


MANUFACTURER CICCUS Desi
TACTURER LICCUS LES
MANUFACTURER 2077 SERIAL NUMBER
FRIAL NUMER
REGISTERED OWNER
STREET ADDRESS
CITY, STATE, ZIP
OPERATOR
STREET ADDRESS
CITY, STATE, ZIP
REGISTERED OWNER
STREET ADDRESS
_CITY, STATE, ZIP
OPERATOR
_STREET ADDRESS
_CITY, STATE, ZIP






I certify that the altimeter, static system, transponder, and altitude reporter test required by FAR's 91.411, 91.413, & 91.217 have been performed and found within the limits of FAR 43 appendices E & F and FEET ON 07/25/06. **TESTED TO 18,000** Transponder: Mfg Garmin P/N 13587-050 Model: GTX-327 S/N 83724945. Encoder: Model ACK P/NA-30 S/N/02644. Altimeter: Mfg Avidyne (PFD) 15222-004S/N 20209246 Mfg United P/N 12731-002 S/N 455223 CDC Quality Assurance_ Cirrus Design Corporation Duluth, MN USA

PC# 338CE






Cirrus Procedure #90502

Name: Peter Flynn

Title: Production Flight Test Pilot



Statements in vive in and the national regulations by the user/instancer before the aneralt may be nown. Computer Generated, GARMIN International Inc. FAA Form 8130-3 (6-01) KADIO & ELECTRONIC CHECKS ERROR OR TYPE OF EQUIPMENT RESULTS TOTAL CHECK CHECKED DATE TIME


Constantion of

Advertised and

-

Maysville KY 41056 606-742-2084 avtech@alltel.net


Avtech Aircraft Maintenance Fleming-Mason Airport (FGX) 7079 Airport Rd N330SR SR22 Serial no. 2077 TCM IO550N42 Engine Serial no. 689851 Date: 8/24//06 Flight Hobbs: 25 Performed the following maintenance/ repairs: Removed defective nav/com 12718-051 serial no. 97134960 from no. two position and installed serviced 12718-051S serial no. 97131087. Repair frayed wiring on right ptt switch. Ground run-up and performed operational inspection, all checks satisfactory.



NEXT CHECK

DUE

A&P 400087835



Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry: Date: 9/5/06 Cirrus SR22 S/N 2077 Flight Hobbs: 37 Performed the following maintenance/ repairs: Replaced auto- pilot altitude transducer 12722-001 S/N0520-34011AA 9Form 8130-3 in records). Perform an airplane run-up and flight test in accordance with Operational/Functional Check in Section CMM 5-30.

m.


AUTHORIZED RVICE CENTER


Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry: Date: 9/12/06 Cirrus SR22 S/N 2077 Flight Hobbs: 26 N330SR Performed the following maintenance/ repairs: Completed Cirrus 50 Hour Demo Service. Tires Visual Inspection for cuts, uneven or excessive wear, and slippage. Tires Inspect for proper tire pressure. Brake System Check system for proper operation. Ice Protection Fluid Tank Fill tank with approved de-ice fluid. Perform an airplane run-up in accordance with Operational/Functional Check in Section CMM 5-30. After completing the Operational Check, perform a walk around to detect fluid leaks or other abnormalities, none noted.


MAINTENANCE RECORD

Avtech

Avtech







SERV



N330SR

co

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net

Engine Entry: Date: 10/2/06 Cirrus SR22 S/N 2077 Flight Hobbs: 95.8 Performed the following maintenance/ repairs: Completed Cirrus 100 Hour Demo Service. Battery Perform Electrolyte Level Check. Tires Visual Inspection for cuts, uneven or excessive wear, and slippage. Tires Inspect for proper tire pressure. Brake System Check system for proper operation. Brake Fluid Reservoir Replenish. Perform an airplane run-up in accordance with Operational/Functional Check in Section CMM 5-30. After completing the Operational Check, perform a walk around to detect fluid leaks or other abnormalities, none

Avtech


MAKE CITUS MODEL SR22 S/N: 22-2077 REG NO 330SR WORK ORDER: 7690-10-2006

Airframe Entries

(2) Removed and replaced LH brake caliper P/N 17122-103 and brake disc P/N 164-02504 with new, LH and RH MLG brake linings (P/N 066-06200) with new Removed and replaced LH and RH MLG tires (Goodyear Flight Custom II, P/N 14075-006) and tubes (Goodyear, P/N 14076-002) with new Inspected wheels and packed wheel bearings. Performed brake break in. Work done IAW CDC SR22 MM 32-41 and 32-42... (3) Bled brake system IAW SR22 M/M 32-42, operational and leak check good.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 10/20/2006





Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone: 218-788-3101

SIGNED: K-6ber 3

Robert Powell Certified Repair Station No. YD5R855Y

· ·/\. I\. TJ.J

Work Order: 7690-10-2006

Printed by EBis 3 (datcomedia.com)

A&P 400087835

DATE: 10/20/2006 A/C TSN: 186.5 HOBBS 186.5

VIQ



DATE OF COMPLETION

> MAKE CITUS MODEL SR22 S/N 22-2077 REG NO 330SR WORK ORDER 7890-11-2006

Airframe Entries

(1) Replaced right wing find nav light bulb P/N 50910-001. Done IAW CDC AMM 33-40 ... (2) Removed remanants of bird from right cowl inlet and baffling. Inspected area IAW CDC AMM 5-20 with no damaged noted ... (4) Replaced pilots 'grab here' placard. P/N 15735-001. Done IAW standard maintenance practices.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R\$55Y.

DATE: 11/20/2006

MAKE CITTUS MODEL SR22 S/N: 22-2077 REG. NO: 330SR WORK ORDER: 7929-11-2006

Airframe Entries

(2) Replaced tail tie down P/N 16678-001 IAW CDC AMM 53-20 (3) Replaced ENVIRO air conditioning compressor assy P/N 21119-304, S/N 210, with new P/N 21119-304, S/N 111, IAW AMM 21-50 and recharged system IAW manufcatures instructions

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 11/27/2006





Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone: 218-788-3101

SIGNED:

Mitch Knase

Certified Repair Station No. YD5R855Y



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone: 218-788-3101

Steve Wilhelmi Certified Repair Station No. YD5R855Y

F.A.R. 43.9 **DESCRIPTION OF WORK PERFORMED** OR APPROVED DATA USED

Printed by EBis 3 (datcomedia.com)

DATE: 11/27/2006 A/C TSN. 266.3 HOBBS: 219

SIGNED: Atas Willen


Printed by EBis 3 (datcomedia.com)


AGENCY & CERTIFICATE NO WORK PERFORMED/RETURNED TO

DATE 11/20/2006 A/C TSN 243.3 HOBBS: 243.3

Work Order: 7890-11-2006

Work Order: 7929-11-2006





DN

AIRCRAFT TIME IN SERVICE

MAKE: Cirrus MODEL: SR22 S/N: 22-2077 REG. NO: 330SR WORK ORDER 8069-12-2006




Airframe Entries

details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 12/18/2006

94200	



was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent





DATE: 12/18/2006 A/C TSN: 266 3 HOBBS: 219

Work Order: 8069-12-2006

Printed by EBis 3 (datcomedia.com)

DRTH	NESS DI DATE & HRS. AT COMP.		FACTORY B TYPE OF A.D. N 1 TIME/RECUR. DAT
A DESCRIPTION OF THE OWNER OWNER OF THE OWNER OF THE OWNER OWNE	or Aug Old	Searched AD'	s through bi-wee





AIRCRAFT TIME IN SERVICE


MAKE CITTUS MODEL SR22 5/11 22-2077 REG NO. 330SR WORK ORDER 8199-01-2007

Airframe Entries

(4) Performed aircraft annual inspection IAW cirrus mm chapter 5-20 and 5-30. FLIGHT METER HOURS 326 2 (7) Researched ADs through bi-weekly issue 2006-26, all ADs are in compliance at this time (21) Serviced aircraft primary battery IAW cirrus mm chapter 24-30... (22) Lubricated flap actuation motor IAW cirrus mm chapter 12-20... (23) Removed moisture from stall warring vacuum switch out to wing port. Performed operational check on ground with satisfactory results I A W. CDC A.M.M. 27-31. (26) Replaced both Main landing gear tires and tubes with new P/N 14075-006 tires, and P/N 14076-002 tubes TAW CDC AMM 32-40 (27) Replaced brake caliper O-rings with four new O-rings P/N 101-34500. TAW CDC AMM 32-42 (28) Install a new P/J 101 connector IAW AVM chapter 77-00-01. Functional check satisfactory. (29) Bled aircraft brake system with approved MiL-H-5606, hydraulic fluid I A W. CDC A M M. 12-10, 32-42 Operational and leak checks good ... (30) Replaced NGL fairing with new P/N 15312-001. IAW CDC AMM 32-20. (33) Updated P.O.H. to most current revision... (34) Repaired puncture mark in L/H forward interior side panel IAW standard maintenance practices (35) Replaced Com 1 P/N 12718-051, S/N 97134965 with hew P/N 12718-051ST, S/N 97124373 (reference FAA form 8130-3 RMA # 2585801) and replaced Com 2 P/N 12718-051, S/N 97131087 with new P/N 12718-051\$T, S/N 97136078 (reference FAA form 8130-3 RMA # 70841) All work was accomplished IAW CDC AMM 34-40 (36) Secured left and right interior bolster panel fabric near kick panels IAW standard maintenance practices... (39) Removed excess adhesive from L/H and R/H flap fuselage torque tube pass through holes IAW standard maintenance practices (40) Removed and replaced inspection hole cover tape on top of vertical stabilizer IAW standard maintenance practices... (41) Replaced NLG rebound bumper with new P/N 13703-001. IAW CDC AMM 32-20. (42) Reapplied new bonding tape at the aft outbd corner of the L/H wingroot fairing per CDC SR-22 AMM 53-50 (43) Replaced Nose wheel bearings with new P/N 214-00400 bearings. IAW CDc AMM 32-41 (44) Replaced safety wire on air conditioning compressor drive pulley botts IAW CDC AMM 20-50 ... (47) CDC pilot performed post annual inspection test flight with satisfactory results. (48) I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 1/16/2007



M.S. THANS

Repair Station No YD5R#55Y 4515 Taylor Circle Duluth, MAN 55811 Phone 218-788-3101

SIGNED: Daniel Runskan

Dave Ruuskanen Certified Repair Station No. YD5R855Y

AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERV **Cirrus Design Factory Service Center**

Work Order: 8199-01-2007 Printed by EBis 3 (datcomedia.com)

DATE 1/19/2007

145 JUNA 3183 1

WA985, 3183, 1

DATE OF COMPLETION

MAKE: Cirrus MODEL: SR22 S/N: 22-2077 REG. NO 330SR WORK ORDER 8210-01-2007

Airframe Entries

(1) Addressed minor exterior cosmetic discrepancies IAW CDC AMM CH 11-20, 12-20, 20-30, 51-20 and standard maintenance practices

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 1/18/2007

MAKE CITUS MODEL SR22 S/N 22-2077 REG. NO 330SR WORK ORDER 8278-01-2007

Airframe Entries

(1) Replaced L/H outboard fuel level sending unit p/n 13467-00,1 s/n 3163 with new unit p/n 13467-001, s/n 3320. Replaced fuel quantity indicator p/n 13557-001, s/n 1150 with new p/n 13557-001, s/n 2562. Performed fuel calibrations and leak checks with satisfactory results. All work was accomplished LAW. CDC A.M.M. 28-40.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 1/23/2007

MAINTENANCE RECORD r A D AD A



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone: 218-788-3101

Mitch Knase Certified Repair Station No. YD5R855Y



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone: 218-788-3101

SIGNED:

Kent Adkins Certified Repair Station No. YD5R855Y


Work Order: 8210-01-2007 Printed by EBis 3 (datcomedia.com)

> Work Order: 8278-01-2007 Printed by EBis 3 (datcomedia.com)

DATE 1/18/2007 AVC TSN 393 1 HOBBS 393.1

SERVICE

DATE: 1/23/2007 A/C TSN: 395.6 HOBBS: 395.6



AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.


Installed Airwolf Air/Oil Separator Kit I/A/W STC SA02268CH and the manufacturer's installation instructions. See FAA Form 337, dated 3 April 2007 for continued airworthiness instructions.


Reattached seal on left half of lower engine cowling as required.


Checked XM Weather functions and status on MFD page. Checked XM installation I/A/W Cirrus Design SB 2X-34-06 R5. Found the 6dB Attenuator not installed. Advised Cirrus Technical Support on findings. Installed new attenuator P/N 51859-002 I/A/W SB Installation Instructions. Checked antenna bonding to airframe. Functional checked XM Weather and radio operations. All checks were good.

Checked # 2 GPS for operations. Found the GPS antennas not installed I/A/W Cirrus Design SB 2X-34-06 R5. Repositioned #1 and #2 GPS antennas. Functional checked good afterwards.

Installed Release 6.2.1 to the MFD I/A/W Avidyne Corp SB # 601-00004-074 service instructions. Functional checked MFD operations. All checks were good. MFD P/N 700-00004-008 S/N 2007256.







Flight Hours:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.


Complied with SB 2X-95-09 R1, CAPS Strap Abrasion Inspection I/A/W accomplishment instructions. Installed CAPS Sheath Kit P/N: 70142-001.


Complied with SB A2X-95-10 R2, CAPS Pick-up Collar Support Replacement VAW accomplishment instructions. Installed CAPS Kit P/N; 70181-001

Troubleshot #1 GPS problem and found antenna had fallen down behind instrument panel, reattached Velcro for GPS Antenna to glareshield. Functional checked #1 GPS with #2 GPS. Both Garmin GNS430 tested I/A/W Cirrus SR22 MM, Chapter 34-40, page 8 and 9, paragraph 5.

Inspected right wheel fairing and found structure not cracked. Cracks in filler and paint only. Install doubler/stiffener in area of bolt hole to prevent further cracking.

Signed:





1

CATE NO.

NED TO SERVICE

MANUFACTURER Cirrus SR22 Model: 2077 S/N: N330SR Reg # 452.9 TAT:

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Complied with SB 2X-27-14R1, Flight Controls Rudder-Aileron Interconnect Modification I/A/W accomplishment instructions. Installed Flight Controls Rudder-Aileron Interconnect Modification Kit P/N: 70187-001.

Complied with SB 2X-52-07R1, Passenger and Crew Doors Cabin Door Rod End Replacement I/A/W accomplishment instructions. Installed Cabin Door, Rod End Replacement Kit P/N: 70186-001.

1 million and the Signed: John T. Gardmer Print: APZZGISISIGSTA Certificate # for

RA	F	T	TI	M	E
SE	R	VI	IC	E	



d/b/a MILLION AIR - RICHMOND


Date	6/20/2007	
W.O.:	M070633	
Hobbs:	551.4	
Flight Hours:	452.9	

DESCRIPTION OF WORK F

OR APPROVED DAT

AIRFRAME LOGBOOK INSERT

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

No.

MANUFACTURER Cirrus Model: SR22 S/N: 2077

Reg #: Date W.O .: ACTT:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Complied with S/B 2X-25-19, Inflatable Restraint Harness Inspection I/A/W accomplishment instructions. No further action required.

Complied with Rev. 2 of SB 2X-27-14, Rudder-Aileron Interconnect Modification by removing the extra washer from the attaching parts securing the forward and aft cable clamps and torque as specified in this service bulletin. No further action required.

Inspected R/H MLG wheel pants and found incorrect bolt installed. Removed incorrect bolt and installed correct bolt P/N: AN4-4A I/A/W Cirrus SR22 MM.

Signed: John T. Guddur Print: APZZLONYTSLOSIA Certificate #


COMMONWEALTH AVIATION SERVICE, INC.


Flight Time:

N330SR 8/24/2007 M070824 500.7 500.7

ENO.

TO SERVI






MANUFACTURER Cirrus Model: SR22 S/N: 2077 Reg #: N330SR

Date 10 W.O.: M ACTT: 50 Flight Hours:

10/1/2007 M070934 507

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.



pumpies bracket and hardware securing oil/air separator to aft engine baffle. condrived crack in left aft engine baffle. Fabricated a doubler from .040" tours auminum for repair of crack. Drilled rivet holes in doubler and L/H aft erone baffle. Secured doubler to L/H engine baffle with new rivets. included bracket and hardware securing oil/air separator.

secured left forward engine baffle with a new screw and washer to prevent the stacking

Cleaned left aft engine isolator mount. Inspected for wear and verified torque. No wear noted and torque is within limits.

Removed #1 battery for servicing. Adjusted electrolyte in all cells and charged. Installed battery.

Complied with SB 2X-27-14 R3, Rudder-Aileron Interconnect Modification, referencing accomplishment instructions. Installed Kit P/N 70197-001. Rudderlaleron interconnect burgee requires replaced. See subsequent entry this work order.

Onlied out and replaced stripped screws in left wing tip as needed.

Removed cracked left and right MLG strut grommets and replaced with new grommets P/N 16937-001.

Removed both cracked upper left and right MLG fairing stand-offs. Installed new upper stand-offs P/N: 13522-001 on left and right MLG referencing Cirrus SR22 MM 32-10.

Removed chaffed heat exchanger tension spring bolts and installed 3 new bolts PIN ANGC-14

Troubleshot roll trim travel out of specs and found rudder/aileron interconnect cungee to be over stretched. (Unable to obtain required alleron deflection while mantaining required roll trim deflection) Removed defective bungee and installed a new rudder/alleron interconnect bungee cord P/N: 12983-001. Performed adjustment/test on rudder/alleron interconnect referencing Cirrus SR22 S8 24-27-14 R3, Dated 10, Oct. 2007. No defects noted at this time.

AIRCRAFT TIME IN SERVICE

ATE NO.

8

ED TO SERVICE

DATEOF

COMPLETION

MAINTENANCE RECORD F.A.R. 43.9

DESCRIFTION OF WORK PERFORMED OR APPROVED DATA USED

Filled gap in COMM antenna with silicone sea int.

Removed cracked lower nose strut rebound umper and installed a new lower nose strut rebound bumper P/N: 18380-001 efere cing Cirrus SR22 MM.

Complied with annual replacement of the brake caliper o-rings P/N M83461/1-222. Reinstalled brake assemblies, bled brakes and serviced brake reservoir referencing SR22 MM Chapter 32-42.

Removed cracked left and right inboard horizontal stab root fairing and cleaned off tape residue. Cleaned new fairings and horizontal stab skin. Primed all areas with tape primer and installed new L/H and R/H horizontal stab root fairings with double sided foam tape as needed. L/H stab root fairing P/N: 15308-001 R/H stab root fairing P/N: 15308-002

Complied with the annual replacement of the induction filter P/N: BA24 referencing Cirrus SR22 MM.

Removed pitted and corroded NLG wheel assembly. from aircraft. Disassembled tire and wheel assembly and inspected tire and tube. Both are good. Installed original serviceable tire and tube on new wheel assembly P/N 40-77 and torqued nuts to 75 inch pounds. Inflated tire to 50 psi. Cleaned and greased bearings with Aeroshell 22 and installed new bearings into wheel assembly. Greased axle and installed wheel assembly onto aircraft. Torque axle nut to 120 inch pounds and safetied referencing Cirrus SR22 MM 32-41 and Cleveland CMM.

Removed left elevator and inspected bushing and hinge pin referencing Cirrus SR22 MM. Play was found to be within limits. Installed left elevator.

John T. Gundner


a the state of the set of the set is the set

Signed:

Print:

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station No. VXWR051W

AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SER



AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Complied with SB 2X-34-24, WAAS Antenna Installation on PFD Equipped Aircraft, referencing accomplishment instructions. Installed Kit's P/N: 70190-002 and 70190-003.

Removed PFD for Release 7 WAAS Upgrade. Installed PFD after Avidyne Corp. installed Release 7 WAAS Upgrade, referencing Cirrus SR22 MM Chapter 31-60, 34-10 and 34-20. Leak check pitot and static system. Leak check good. Performed all setup checks, calibrated and also performed inflight check. All checks were good. PFD P/N: off/on: 700-00006-000 S/N off/on: 20209246. rtant to understand that the existenc

30

S


0


01

ted):

Removed # 1 GNS430W for compliance with Garmin SB 0740 Rev. A.. Installed #1 GNS430W after compliance with Garmin SB 0740 Rev. A was complied with by Garmin International, CRS G6XR582Y, RMA 6296314. The # 1 GNS430W functional checked good referencing Cirrus SB 2X-34-24 instructions. GNS430W P/N: off: 011-000280-10 S/N off: 97136078 P/N on: 011-01060-40 S/N on: 97136078.

Removed # 2 GNS430W for compliance with Garmin SB 0740 Rev. A. Installed #1 GNS430W after compliance with Garmin S/B 0740 Rev. A was complied with by Garmin International, CRS G6XR582Y, RMA 6296314. The # 2 GNS430W functional checked good referencing Cirrus SB 2X-34-24. GNS430W P/N off: 011-00280-10 S/N off: 97124373 P/N on: 011-01060-40 S/N on: 97124373.





AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

The Cirrus Design SR22 S/N: 2077 aircraft was inspected referencing current maintenance rules of the Federal Aviation Regulations for an Annual Inspection using the manufacturer's current inspection guide and is approved for return to service. The following items were serviced, repaired and/or inspected as noted.

Complied with FAR 91.207(d), Inspection of the ELT. No defects noted. ELT batteries due replacement March 2012.

Removed left main tire and wheel assembly from aircraft. Disassembled and discarded old tire. Cleaned and inspected all wheel components - No defects noted. Reassembled with a new tire and original inner tube. Torqued bolts as required and serviced with nitrogen. Performed leak check - No leaks noted. Installed left main tire and wheel assembly on aircraft referencing Cleveland Installed left main tire and wheel assembly on aircraft referencing Cleveland

Wheel and Brake Tech. Guide Rev. J and Cirrus SR22 MM. Tire P/N off: 156E61-3 S/N off: 43010320 P/N on: 070-449-0 S/N on: 7160W00157.

Troubleshot no output from # 2 alternator. All connections and drive spline on alternator good. Removed MCU from aircraft. Removed defective field control module and replaced with a new module P/N 14605-010. Reinstalled MCU. OP's check on # 2 alternator good.

IN SERVICE RATCELELECERT ALECERT Manufacturer: Cirrus Model: SR22 S/N: 2077 Reg #: N330SR

DATE

AIRCRAFT TIME

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.

The Cirrus Design SR22 S/N: 2077 aircraft was inspected referencing current maintenance rules of the Federal Aviation Regulations for an Annual Inspection using the manufacturer's current inspection guide and is approved for return to service. The following items were serviced, repaired and/or inspected as noted.

Complied with FAR 91.207(d) ELT inspection. Functional checked good. Batteries due replacement March 2012. ELT ACK E-01 S/N 055838.

Complied with annual replacement of the brake caliper o-rings P/N M83461/1-222. Reinstalled brake assemblies, bled brakes and serviced brake reservoir with hydraulic fluid.

Complied with the annual replacement of the induction air filter P/N: BA24 referencing Cirrus SR22 MM.

Removed defective fuel vent on left wing outboard panel and installed new vent P/N: 15306-001.

Removed aircraft battery and serviced all cells. Charged battery and reinstalled battery in aircraft.

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND **Cirrus Design Service Center** CRS VXWR051W

> Date 1/28/2009 W.O .: M090120 ACTT: 697.2 Flight Hobbs: 697.2 Hobbs: 850.9

KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

The requirements for AD 2008-03-16 were previously met when SB 2X-27-14 R3 was complied with on Jan. 25, 2008 @ 563.4 flight hobbs.

The requirements of AD 2008-14-13 were met by complying with CDC SB 2X-52-07 R4, Cabin Door Rod End Replacement, referencing accomplishment instructions. Installed kit P/N: 70186-005

Complied with SB 2X-21-03 R1, Air Conditioning Condenser Sealing. referencing eccomplishment instructions. Installed Kit P/N 70220-001. No further action required.

Complied with time change requirement of #2 battery by installing new battery pack P/N: 50979-001.

Complied with time change replacement of TKS filter by installing new filter P/N 15165-009 with new o-rings P/N 15164-092. Serviced TKS system to full with AL-5 TKS fluid and perform leak check. No leaks noted at this time.

Performed 24 month functional check and calibration of the magnetometer referencing Cirrus SR22 AMM.

Removed defective bushing and hinge pin from left elevator (outboard position) and installed new bushing P/N: 50224-001 and new hinge pin P/N: 11621-002 referencing CDC SR22 MM.

Cleaned left lower surface of left wing root fairing where separated from wing. Reapplied bonding tape and edge sealed affected areas as required.

Removed worn left and right brake linings and replaced with new linings P/N 066-06200 referencing CDC SR22 AMM and Cleveland CMM.

Removed defective left aileron bearings and installed new bearings P/N: MS27645-3A referencing CDC SR22 AMM.

Removed 2 defective rivets on left flap and installed new rivets P/N: CR3212-4-2 referencing CDC SR22 AMM.

Removed left and right MLG tire and wheel assemblies from aircraft. Disassembled and discarded old tires. Cleaned and inspected all wheel components - No defects noted. Reassembled with new tires and original inner tubes. Torqued bolts as required. Serviced with nitrogen and performed leak check - No leaks noted. Installed left and right MLG tire and wheel assemblies on aircraft referencing Cirrus SR22 MM. Left tire P/N off/on: 070-449-0 S/N off:7160W00157 S/N on: 7230W00318. Right fire P/N off: 33031 S/N off: B5F40307 P/N on: 070-449-0 S/N on: 7229W00250.

DATE

IN SERVICE

Removed defective NLG wheel fairing mount bracket and installed new bracket P/N: 11799-003.

Resecured/tightened several pitot and static line fittings behind the pilot's instrument panel. Leak checked good referencing CDC SR22 AMM. Removed defective NLG rebound bumper and installed new rebound bumper P/N: 18380-001 referencing CDC SR22 MM.

Removed defective co-pilot's and left passenger's swivel light receptacles and installed new receptacles P/N: 50491-002. Lights op check good.

Signed:

Print

John T. Gurdner for COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station No. VXWR051W



d/b/a MILLION AIR - RICHMOND Cirrus Design Service Center CRS VXWR051W

Manufacturer: Model: S/N: Reg #:

Cirrus SR22 2077 N330SR

Dat W. AC Flig Ho

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.


Removed left MLG tire and wheel assembly from aircraft. Disassembled cleaned and inspected wheel assy. No defects noted. Reassembled with original tire and new tube. Torqued bolts as required referencing the Cleveland 40-414 MM and AWBC MM 0001-3/USA. Serviced tire to proper pressure and performed leak check - No leaks noted. Installed left MLG tire and wheel assembly on aircraft referencing Cirrus SR22 MM. Tube P/N: 097-500-0.

Signed:

Print:

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station No. VXW R051W

e	8/7/2009
0.:	M090813
TT:	740.4
ght Hobbs:	740.4
bbs:	904.0






Manufacturer:	Cirrus	Date	1/28/2009	
Model:	SR22	W.O.:	M090120	
S/N:	2077	ACTT:	697.2	
Reg #:	N330SR	Flight Hobbs:	697.2	
		Hobbs:	850.9	

AVIONICS LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.

The static system and altimeter instrument and automatic altitude reporting system have been tested and found to meet the requirements of FAR 91.411 Part 43 Appendix E. The altimeter was tested to 20,000 feet. PFD P/N: 700-00006-000 S/N: 20209246, encoder P/N: A30 S/N: 102644 and standby altimeter P/N: 5934P S/N: 455223.

The ATC Transponder System was tested and found to meet the requirements of FAR Part 43 Appendix F. ATC Transponder P/N: 011-00-490-00 S/N: 83724945



LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC MULLION ALOR.

Cirrus

SR22

2077

N330SR

882.2

Cirrus Design Service Center CRS VXWR051W

Manufacturer. Model: S/N: Reg # ACTT

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.

Reinstalled co-pilot's map light referencing Cirrus SR22 AMM 25-10.

Removed defective co-pilot's cup holder and installed new cup holder referencing Cirrus SR22 AMM 25-10. P/N: 51179-001.

Removed defective NLG rebound bumper and installed new bumper. Performed NLG inspection. No other defects noted. Work performed referencing Cigrus SR22 AMM 5-50 & 32-20. P/N: 18380-001.

Print

John T. Gurden/

for COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station No. VXWR051W



d/b/a MILLION AIR - RICHMOND Date W.O.:

Hobbs:

8/16/2010 M100826 1073.3 Flight Hobbs: 882.2

5

Manufacturer: Model: - S/N: Reg #: ACTT:

The aircraft and/or component identified above was repaired and inspected in _____ accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.

Removed main aircraft battery and installed new battery referencing Cirrus SR22 AMM 24-10. P/N off/on: G-243 S/N off: G02271074 S/N on: G02480194.

Checked and serviced all tires as required referencing Cirrus SR22 AMM.

Signed:

Print:



d/b/a MILLION AIR - RICHMOND Cirrus Design Service Center CRS VXWR051W Date Cirrus W.O.:

SR22 2077 N330SR 832.5


Hobbs:

AIRFRAME LOGBOOK INSERT

mad R. Young DVN29 DONALD tor

COMMONWEALTH AVIATION SERVIC F.A.A. Approved Repair Station No. VXW

5/5/2010 M100509 1015.3 Flight Hobbs: 832.5






	Cirrus	WR051W Date	6/1/2011
Manufacturer: Model:	SR22	w.o.:	M110528
S/N:	2077	Flight Hob	bs: 960.4
Reg #:	N330SR	Hobbs:	1170.0
TAT:	960.4		

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertiment details of this work order are on file at this repair station.

Removed and replaced nose landing gear rebound bumper with serviceable new bumper (18380-001). REF: AMM 32-20.



John Gardner

Signed:

Print:

AIRCRAFT TIME DATE IN SERVICE DAUGLIGDNI ANIORR'

d/b/a MILLION AIR - RICHMOND **Cirrus Design Service Center** CRS VXWR051W

Manufacturer:	Cirrus
Model:	SR22
S/N:	2077
Reg #:	N330SR
TAT:	925.3

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.


The Cirrus Design SR22 S/N 2077 aircraft was inspected I/A/W current maintenance rules of the Federal Aviation Regulations for an Annual Inspection using the manufacturer's current inspection guide (date June 15, 2010) and is approved for return to service. The following items were serviced, repaired and/or inspected as noted.

C/W SB 2X-32-19 R2 I/A/W inspection instructions per para. 11D, no cracks noted at this time. Installed kit 70238-001 per para. 11F. No further action

Complied with FAR 91.207(d), ELT inspection and functional check with no defects noted. ELT P/N: ACK E-01 S/N 055838. Batteries due replacement Feb. 2013. RCP battery due replacement Feb. 2013.

Complied with annual induction air filter replacement by removing defective air filter assembly and installed new air filter assembly (BA-111). REF: AMM

Complied with annual brake caliper o-ring replacement by removing brake calipers, cleaning and inspecting. Removed o-rings from calipers and replaced with new o-rings (M83461/1-222). Reinstalled calipers. Bled brakes



Date 1/3/2011 W.O .: M101219 Flight Hobbs: 925.3 Hobbs: 1124.6

and the second se	
	V
	V
A A A A A A A A A A A A A A A A A A A	
	1
the second se	
I S LA STATISTICS AND IN STATISTICS	1
F	ł
A AND AN AND AND AND AND AND AND AND AND	2
e)
the state of the s	
C	•
and the second sec	,
and the second second	
R	2
and the second s	
m	1
	•
In	K
W	_
W	e
P	-
R	0
and the second second second	
R	2
Re	7
RE	
	-
and a second second	
Inc	
Ins	2
	1
mi	C
	2
-	.,
RE	
I HAVE AND	-

I.A.N. TJ. I - JI. TUJ

KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

- Complied with 2 year replacement of ice protection system filter by removing and installing new TKS filter (26115-101) and seals (15164-092) as required. REF: AMM 30-05.
- Complied with 24 month magnetometer calibration as required. REF: AMM 34-20.
- Complied with 24 month replacement of # 2 batteries. Installed new batteries P/N 50979-001. Ref. AMM 24-30.
- Complied with 5 year time change requirements for flexible fuel hoses. Installed new hoses P/N's 51276-001, 156F001-6D-0080, 156F005-4S-0140, 156F001-4S-0070 and 156F003-4S-0105. REF: AMM 28-20.
- Complied with 5 year replacement of fuel system drain valve seals by removing left and right inboard fuel panels, removed o-rings and drain valves and installed new mating o-rings (M25988/1-021) and drain valve o-rings (M83248/1-011). Removed left and right outboard fuel panels, removed drain assemblies and installed new assemblies (50141-001). Reinstalled panels and sealed. Removed and replaced gascolator drain valve with new valve (50141-001).REF: AMM 28-10.
- Complied with 5 year time change recommendation for all flexible brake lines. Installed kit P/N 70207-002. Bled brakes and serviced hydraulic
- Complied with 5 year time change on gascolator seals by removing and replacing seals with serviceable new ones. REF: 28-20. O-ring P/N MS29513-137. Seal P/N NAS1523-8B.
- Verified torque of lower engine mount attach fittings. Due again in 500 hour (1425.3 flight hours) or next removal. REF: AMM 71-20.
- Removed and replaced heat exchanger with serviceable inspected heat exchanger (21892-001). Assembly removed from new production aircraft. Component TT 0.0. REF: AMM 78-20.
- Removed defective left muffler and installed serviceable overhauled left nuffler (14836-001). REF: AMM 78-20.
- istalled new handheld extinguisher (RTA400 S/N X-803247). New bottle reight is 520 grams, (1 LB 2.4 oz). Bottle manufacture date is 06-2010.
- esecured (pilots) left front head phone jack. Functionally checked good.
- spected left wing tip light for damage. Found navigation lens gasket issing. Installed new navigation lens gasket (38-0230021-00) as required.

TAIRCRAFT TIME IN SERVICE DATE LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC MILLION ALOR d/b/a MILLION AIR - RICHMOND Cirrus Design Service Center CRS VXWR051W Date

6/30/2011 M110626 W.O .: Flight Hobbs: 961.8 3144 1172.3 2077 Hobbs: N330SR 961.8

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found alworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.

Removed right inboard anti-lice panel (11802-36). Installed new porous ice protection panel (15124-008) on right inboard wing location and installed original stall strips in same location as before. OP's and leak checked good. REF: ANM 30-10 and 57-20.

Performed required post maintenance flight test (after right wing inboard TKS panel replacement) I/A/W Cirrus PS 90502/90500/90504 throughout its nomal range of operation and found the aircraft to be satisfactory. Flight test performed by Brett Schelde, Cirrus Production Flight Test Pilot on July 08.2011.

Nodel

SIN

Reg


TAT

John T. Burdmer COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station No. VXWR051W

INSPECTION RECORD F.A.R. 43.11-91.409

WO#

Pilot: Brett Schelde



EC COMMONWEALTH AVIATION SERVICE, INC. R. MECHCICAL TOMMENT AND AND AND NDO NO. d/b/a MILLION AIR - RICHMOND Cirrus Design Service Center CRS VXWR051W Manufacturer: Cirrus 4/15/2011 Date Model: SR22 W.O.: MH10431

S/N:

Reg #:

TAT:

Signed:

N330SR 958.1

2077

AIRFRAME LOGBOOK INSERT

Flight Hobbs: 958 1

NA


Hobbs:

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service for the work performed. Pertinent details of this work order are on file at this repair station.

Jacked aircraft. Removed left main landing gear fairing and wheel assembly. Disassembled wheel assembly and discarded old tire. Installed new tire (070-449-0 S/N 7230W00230) and reassembled wheel assembly. Torqued and serviced the wheel assembly to proper pressure. Cleaned and repacked the bearings. Reinstalled tire and wheel assembly on aircraft. Down Jacked aircraft. REF: AMM 32-41 and CMM Section 300.



NAME OF PART	PART NUMBER	SERIAL NUMBER	INSTALLATION DATE/HOURS	TIME ON PART AT INSTALL.	LI
			Life Limit	ed Parts SF	222
	P	ART NAME	PARINME	8	
	CA CA	PS Rocket Motor	15047-001	S/N 283	.0
	- C/	APS Parachute	20331-001	S/N_0238	22
		APS Reefing Line itters	5212	LOT TOSO 002-0	
	EI	T Batteries	MN1300	Date Installe	
		MA Controller, AIR	20902-001	1 S/N <u>88</u> Jun	106
		lot Seat Inflator ssy, AAIR	20902-002	2 S/N445I (1038	
	In	o-Pilot Seat flator Assy, AIR	20902-002	2 S/NAASE 102	



N330SR 1-25-12

Maintenance performed:

Completed Annual Inspection I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105. Replaced ELT batteries with new P/N MN1300R4. Next replacement due on March 2017. Complied with annual ELT inspection and functional test I/A/W FAR 91.207 (d) and found satisfactory. Complied with 6 Yr replacement of CAPS reefing line cutters with new kit P/N 25B47-002, Lot No. 1 RRL 0711, VA/W SB 2X-95-12. Due again on July 2017. Complied with SB 2X-32-19 R2 by inspection of upper gusset plate & forward nose gear strut fillet weld and no defects noted at this time. Due every 100 Hrs. Due again @ 1108.3 Hrs Flight Hour Meter. Repaired pilot's and L/H passenger air vents. Replaced missing CAPS handle safety pin with new P/N 25322-001. Replaced L/H brake disc with new P/N 164-02504. Torqued wheel bolts to 150 in/lbs. Replaced air-conditioner compressor drive assy with overhauled P/N 1133180-1. Adjusted belt tension I/A/W Cirrus Repositioned cabin heater shroud and repaired heat tape on R/H lower cowling.

I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

> Cirrus SR22 Hobbs: 1229.5 Hrs

S/N: 2077 Flight Hour Meter: 1008.3 Hrs

unorized Representative

N330SR 9-26-12 Maintenance performed:

I certify that with respect to the work performed this aircraft was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-12-05907.

INSPECTION RECORD F.A.R. 43.11-91.409


Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

> Cirrus SR22 Hobbs: 1319.6 Hrs

Customer reported nose wheel shimmy on landing. Removed nose wheel, cleaned, inspected bearings and regreased. Reinstalled nose wheel and ground checks good. Cleaned stall strip, applied sealing compound and repositioned stall strip to proper location.

Flight Hour Meter: 1080.3 Hrs

S/N: 2077 Authorized Representative




AIKCKAFT TIME

IN SERVICE

DATE

Repaired nose wheel shimmy by removing fork assy. Installed 2 new Belleville washers, P/N 50750-101 and 1 new thrust washer, P/N 50545-001. Re-torqued and set to 25 lbs break torque and re-cotter pinned. Customer performed high

I certify that with respect to the work performed this aircraft was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-12-05950.



Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

> Cirrus SR22 Hobbs: 1322.6 Hrs

SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

S/N: 2077 Flight Hour Meter: 1082.4 Hrs

athorized Representative

N3305R 1-02-13

DATE

MAR

TIME

I certify that the altimeter(s) and static system test required by FAR 91,411 have been performed and found to comply with FAR Part 43, Appendix E. The altimeter(s) have been tested to 20,000 feet.

Pilot's ADC: Standby Altimeter:

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this agency under Work Order #PA-12-05992.

EQUIPMENT CHECKED

TYPE OF

CHECK

Air 88, Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J Montgomery Dr. San Diego, CA 92123

> Cirrus SR22 Hobbs: 1332,4 Hrs

S/N 20609116 S/N 455223

\$ SESECTS COSE RESULTS

Flight Hour Meter: 1088.9 Hrs

NIXICHICK

DUI

I certify that the ATC transponder(s) test and inspection required by FAR 91.413 has been performed and found to comply with FAR Part 43, Appendix F.

#1 Transponder: Altitude Encoder: S/N 83724945 S/N 102644

Authorized Representative

S/N: 2077

CHECKED BY:

SIGNATURE - CERT, NO.

N330SR 1-02-13 Maintenance performed:

AIRCRAFT TIME

DATE

IN SERVICE

expires on March 2017. Complied with SB 2X-32-19 R3 by inspection of upper gusset plate & forward nose gear strut fillet weld and no defects noted at this time. Due every 100 Hrs. Due again @ 1188.9 Hrs Flight Hour Meter. Removed and replaced electronic module assy with new P/N 508358-421, LN 34239260. Replaced R/H main tire with new Michelin tire, P/N 061-501-0, 0293S00256. Replaced R/H wheel bracket with new P/N 17205-002. Replaced R/H pant bracket on nose gear with new P/N 11799-003. Replaced L/H overhead light bulb with new P/N GE400. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy

condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #PA-12-05992. Authorized Representative


F.A.K. 43.11-91.409 **KIND OF INSPECTION - STATUS & DISCREPANCY LIST** SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE


Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123


> Cirrus SR22 Hobbs: 1332.4 Hrs

Completed Annual Inspection using Crownair Aviation Annual / 100 Hour Inspection Checklist, Form CA 105. Complied with annual ELT inspection and functional test I/A/W FAR 91.207 (d) and found satisfactory. ELT battery

S/N: 2077 Flight Hour Meter: 1088.9 Hrs







Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123


> Cirrus SR22 Hobbs: 1355.8 Hrs

Replaced #1 EGT probe with new P/N 16579-002. Ground run indication checks good.

I certify that with respect to the work performed this aircraft was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy for return to service, Details of the repair are on file at this agency under Work Order No. PA-13-06130.

SIGNATURE – CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

Flight Hour Meter: 1105.3 Hrs



N330SR 1-20-14

DATE

Maintenance performed:

TAIRCRAFTTIME

Complied with SA 13-05 Elevator hinge pin inspection, no defects noted at this time. expires on March 2017. Complied with SB 2X-05-02 by replacement of induction duct flapper bolt with new P/N AN3-34A. Due every 500 Hrs or 2 Yrs whichever occurs first. Due again @ 1641.5 Hrs Flight Hour Meter or January 2016. Complied with SB 2X-32-19 R3 by inspection of upper gusset plate & forward nose gear strut fillet weld and no defects noted at this time. Due every 100 Hrs. Due again @ 1241.5 Hrs Flight Hour Meter. Replaced nose tire with new Goodyear tire P/N 301-016-006. Cleaned, inspected and greased nose wheel bearings. Checked operation of the TKS system, show all panels working properly. Replaced left main tire with new Goodyear tire P/N 301-249-006, S/N 31367544. Torqued bolts to 150 in/lbs and Replaced left brake caliper insulator shim with new P/N 068-01100. Charged aircraft battery and serviced cell fluid levels as required. I certify that this **aircraft** has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-14-06401. Authorized Representative

KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

> Cirrus SR22 Hobbs: 1402.9 Hrs

Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105. Complied with annual ELT inspection and functional test I/A/W FAR 91.207 (d) and found satisfactory. ELT battery

Flight Hour Meter: 1141.5 Hrs

S/N: 2077