

Logbooks  
For  
Cirrus Design SR-22

N62CH  
S/N 2180

**ARAPAHOE AERO**

12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386

**SUPPLEMENT TO AIRCRAFT EQUIPMENT LIST AND WEIGHT & BALANCE**

(N) Number: N62CH

Manufacturer: Cirrus Aircraft

Model Number: SR22

AIRCRAFT WEIGHED

Serial Number: 22-2108

EQUIPMENT CHANGE

IN=Installed

RE=Removed

Aircraft Empty per Weight & Balance Dated: <u>29 October 2010</u> ITEM INSTALLED OR REMOVED		WEIGHT	ARM	MOMENT
RE	COMDAT Com/Weather antenna P/N: CI 420-420	<u>-.26</u>	<u>136.20</u>	<u>-35.41</u>
IN	COMDAT WAAS/XM antenna P/N: CI-428-410	<u>.41</u>	<u>136.20</u>	<u>55.84</u>

2424.15

335,115.43

COMPUTED

AS WEIGHED

138.24

Aircraft Empty Weight: 2424.15

Computed Useful Load: 975.85 LBS

Aircraft Empty CG: 138.24

Max Take-Off Weight: 3400.00 LBS

Aircraft Empty Weight Moment: 335,115.43

SEE:  LOG BOOK  FAA 337 FOR DETAILS

Work Order Number: 30795



Scott S. Fisher A&P 3290363

SIGNATURE & CERTIFICATE NUMBER



24 August 2011

Date:



ENG LOGBOOK

# ENGINE MAINTENANCE RECORDS



**1-800-624-6680**

(IN NY 631-298-8330)

**TELEDYNE MATTITUCK SERVICES, INC.**

410 AIRWAY DRIVE, MATTITUCK, NY 11952

### TELEDYNE MATTITUCK SERVICES, INC./ Limited Piston Engine Warranty

Effective 2/5/88, Teledyne Mattituck Services, Inc., (hereinafter called "TMSI"), makes the following warranty to its customer, subject to the limitations, conditions and exclusions set forth below.

**WARRANTY COVERAGE** - For a period of six (6) months after date of delivery to customer, or 240 hours of operation, whichever occurs first, TMSI shall repair or replace, at its option, any aircraft engine accessory or part which is found to be defective, to TMSI's satisfaction, within said warranty period.

For engine warranty after six (6) months from the date of delivery to customer and prior to the expiration of the original manufacturer's recommended time between overhaul ("TBO"), the cost of repair or replacement (including the cost of parts and labor), at TMSI's option, shall be prorated in the following manner. The customer shall pay the net price for a newly rebuilt engine equal to the current list price for the engine divided by the manufacturer's recommended TBO, and then multiplied by the number of hours on the repaired or replaced engine (which shall be deemed the greater of the actual logbook hours, recorded tachometer hours or time at forty (40) hours per month from the date of delivery). Reasonable labor costs associated with the repair of a warranted engine shall be prorated in the same manner on the basis of a flat rate schedule established by TMSI.

After the initial six (6) months from date of delivery or 240 hours of operation, TMSI will not assume any responsibility for the repair or replacement of engine accessories, e.g. magneto, starter, alternator, ignition harness, turbocharger, etc.

Replacement parts supplied for warranted engines still covered by manufacturer's warranty are supplied on an exchange basis. TMSI will pursue warranty claims with the manufacturer on the owner's behalf. Any allowance by the manufacturer will be credited to the operator's account.

The repair or replacement of any part under the foregoing warranty shall not extend the periods of warranty coverage set forth above. TMSI reserves the right to change the price or specifications of any engine or part at any time.

**CONDITIONS AND PROCEDURES FOR OBTAINING WARRANTY WORK** - The foregoing warranty shall be effective only if the engine or component to be serviced is returned to TMSI's facility at customer's expense, together with particulars in writing of the nature of the defect. The customer or his representative should contact TMSI for verification and authorization of warranty prior to return and/or repair. Written authorization must be obtained from TMSI before repairs covered by warranty

can be performed other than by TMSI. In no event shall allowable labor costs exceed local published shop rates. The foregoing warranty shall apply if and only if the engine has been properly installed and maintained in accordance with current approved standards of the FAA and current recommendations of the manufacturer as specified in applicable factory manuals and service bulletins. The performance of recommended inspections and maintenance must be documented by logbook entries which must accompany any engine returned for warranty work. Defects must be discovered within the warranty period and TMSI must be given prompt notice thereof in writing, within ten (10) days after discovery.

**LIMITATION, EXCLUSIONS, AND DISCLAIMERS** - TMSI shall not assume freight charges, transportation or delivery expenses, costs, or airframe repairs, all which are excluded under this warranty. TMSI does not warrant parts, materials or services supplied which are covered by manufacturer's warranty. This warranty shall not apply to any engine which has been subject to misuse, neglect, accident or damage from the elements, or which has been installed, repaired or maintained or altered in any manner which, in the judgement of TMSI, has had an adverse effect on the engine or part. This warranty shall not apply to any engine which has been operated under conditions which exceed the manufacturer's recommendations. This warranty shall not apply to any engine which has been repaired or altered, in any manner other than by TMSI, or its representative.

THE FOREGOING WARRANTY IS IN LIEU OF ALL OTHER WARRANTIES OR REPRESENTATIONS, EXPRESSED OR IMPLIED ARISING BY OPERATION OF LAW OR OTHERWISE, INCLUDING WITHOUT LIMITATION THE WARRANTY OF MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE WHICH WARRANTIES ARE HEREBY EXCLUDED. TMSI liability hereunder shall be limited to the repair or replacement of any engine or part found to be defective within the applicable warranty period as set forth above. IN NO EVENT SHALL TMSI BE LIABLE FOR CONSEQUENTIAL OR INCIDENTAL DAMAGES OR ECONOMIC LOSS OF ANY NATURE WHETHER ARISING IN CONTRACT OR TORT, INCLUDING STRICT LIABILITY ON TORT OR NEGLIGENCE, ON THE PART OF TMSI. The foregoing limitations and exclusion with respect to implied warranties and the exclusion of incidental or consequential damages may not apply in those states which prohibit such limitation or exclusions. This warranty gives customer specific legal rights, and the customer may have other rights which vary from state to state.

Work Order No.

33205

Engine Serial No.

689951



Airway Drive  
Mattituck, N.Y.  
Tel. (631)-298-8330


<b>1. Approving National Aviation Authority/Country:</b>  UNITED STATES	<b>AUTHORIZED RELEASE CERTIFICATE</b> FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	<b>3. Form Tracking Number:</b>  0708091
---	--	--

<b>4. Organization Name and Address:</b> Teledyne Mattituck Services, Inc. Airway Drive Mattituck NY 11952 REPAIR STATION CERTIFICATE NO. T10R507Y	<b>5. Work Order/Contract/Invoice Number:</b> 33205
---	--

6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	Teledyne Continental Aircraft Engine	IO-550-N	TBV by installer	1	689951	Overhauled

**13. Remarks:**  
 This engine has been overhauled to manufacturer's new parts limits by Teledyne Mattituck Services, Inc. on July 8, 2009. Engine disassembled, cleaned and inspected in accordance with manufacturer's instructions. All steel parts magnfluxed. Engine reassembled. All applicable Airworthiness Directives thru biweekly issue 2009-14 are in compliance. Engine overhauled and preserved in accordance with Teledyne Continental Overhaul Manual X30568A, dated 10/00.  
 I certify that this engine has been inspected and tested per FAA Approved Process Specification SP1012C and found to be operating to manufacturer's specifications.  
 Total Engine Time: 1665.5 Hrs. Time since Overhaul: 0 Hrs.

<b>14. Certifies the items identified above were manufactured in conformity to:</b>  <input type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.	<b>19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service</b> <input type="checkbox"/> Other regulation specified in Block 13  Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
---	--

<b>15. Authorized Signature:</b>	<b>16. Approval/Authorization No.:</b>	<b>20. Authorized Signature:</b> 	<b>21. Approval/Certificate No.:</b> T10R507Y
<b>17. Name (Typed or Printed):</b>	<b>18. Date:</b>	<b>22. Name (Typed or Printed):</b> Mahlon P. Russell	<b>23. Date (m/d/y):</b> July 8, 2009

**User/Installer Responsibilities**

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

I N V O I C E  
=====

Teledyne Mattituck Services, Inc.  
Airway Drive  
Mattituck, NY 11952  
(631) 298-8330 305

Inv # : 00000

Date : 07/13/2009

0000 Satsair  
100 Tower Drive  
Hangar #4  
Greenville, SC 29607

Satsair  
100 Tower Drive  
Hangar #4  
Greenville, SC 29607

P O Date : 07/13/2009      Due Date : ASAP      Ship Via :

Qty	Part #	Description
1	CASE-6	Ovh Crankcase - Cont.
1	CSOTH	Tin Plate - Shaft Flange
1	646550A2M	Gasket Set
1	MS9144-01	Gasket - MS9144-01/AMS7283
1	646592A2	Bearing Set
12	642398	Bearing - Connecting Rod
6	654439-2	Hose 2.00 id x 2.50
12	655958	Bolt - Connecting Rod
12	654490	Nut - Connecting Rod
1	641250	Seal Asm - Nose
6	656990	Bolt .3125-24 x .88 long
- 1	EQ7003	Camshaft & Lifter Kit
4	654587-.44	Bolt - .3125-24
2	643626-103	Pin - Crkshsft Cwt
2	643626-104	Pin - Crkshsft Cwt
4	643626-105	Pin - Crkshsft Cwt
8	350998	Bushing - Crankshaft Cwt
16	629104	Ring-Cwt Plate Retaining
16	643629	Plate
16	639193	Bushing - Crksh Cwt
2	641909	Plate - Tab Lock
4	649205	Screw - Hex .31-24 x .41
6	630046	Pin & Plug Asm - Piston
3	652436-1	Clamp Asm
4	655269	Bushing - Magneto Dr
1	CH48109-1	Oil Filter
1	ES48109	Oil Filter
1	MS9970-116	O-Ring .842 od
1	MS9970-117	O-Ring .903 od
1	642892	Gasket -Oil Filler 2.28 od
1	EQ7276	Kit - Maj Ovh Thru Bolt
12	652963	Bushing .875 od x .75 id
6	530658	Bushing
2	646414	Bumper - Rubber Button
2	AS3578-016	O-Ring
1	642892	Gasket -Oil Filler 2.28 od
5	AN737TW82	Clamp 2.00 id - Hose
1	631016	Gear - O.P. Driven
1	631014	Shaft Gear Asm
1	643359	Support-Baffle 5050103-12
1	646868	Support - Baffle
1	632018	Gear
1	646385	Baffle - Support #2 Cyl
1	EQ7248M	Hardware IO-550-G,N
12	RHB32S	Spark Plug
1	10-823674-25	Harness

6x      6x  
657077, 657088



# ENGINE MAINTENANCE RECORDS

Log No. 2

Aircraft Registration No. NG2CH

Engine Manufacturer T.C.M

Model IO-550-N

Serial No. 689951

Date installed on aircraft \_\_\_\_\_

Time Between Overhauls (TBO) \_\_\_\_\_ Hours

If used on multi-engine aircraft:

- |                                |                               |
|--------------------------------|-------------------------------|
| <input type="checkbox"/> Right | <input type="checkbox"/> Left |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |



Teledyne Continental Motors, Inc.  
 Teledyne Mattituck Services  
 410 Airway Drive  
 Mattituck, NY 11952

## ENGINE REPAIR OR OVERHAUL WORK ORDER

FAA REPAIR STATION: T10R507Y

DATE: 8 Jul 09	WORK ORDER: 33205
ENGINE MODEL: 10-550-N	ENGINE SERIAL NUMBER: 689951
DESCRIPTION OF WORK TO BE ACCOMPLISHED:	CORRECTIVE ACTION TAKEN
1. INSPECT ENGINE FOR METAL CONTAMINATION	ENGINE MAJOR OVERHAULED.
2. COMPLY WITH APPLICABLE SERVICE BULLETINS.	COMPLIED WITH, SEE LOG ENTRY AND SERVICE BULLETIN LIST
3. COMPLY WITH APPLICABLE AIRWORTHINESS DIRECTIVES	COMPLIED WITH, SEE LIST THERE ARE NO AIRWORTHINESS DIRECTIVES APPLICABLE AT THIS TIME
4. REPLACE PARTS AS NECESSARY	SEE PARTS LIST
5.	
6.	
7.	

AUTHORIZED SIGNATURE :

*Michael P. Russell*

Compliance	SB	AD	Date	Subject
n/a	SB08-8B		04/10/2009	SLICK SERVICE BULLETIN SB0-08A
c/w	SB08-13		10/14/2008	INDUCTION SYSTEM HOSE AND CLAMP INSTALLATION
n/a	CSB08-9A		10/14/2008	SLICK SERVICE BULLETIN SB03-8A
c/w	MSB96-10A	97-26-17	10/14/2008	CRANKSHAFT ULTRASONIC INSPECTION
c/w	SB97-6A		9/9/2008	MANDATORY REPLACEMENT PARTS
n/a	CSB08-11		7/16/2008	KELLY AEROSPACE POWER SYSTEMS BULLETIN 033
n/a	SB96-11B		7/10/2008	PROPELLER STRIKES AND HYDRAULIC LOCKS
c/w	SID97-3E		6/25/2008	PROCEDURES AND SPECIFICATIONS FOR ADJUSTMENT OF TELEDYNE CONTINENTAL MOTORS (TCM) CONTINOUS FLOW FUEL INJECTION SYSTEMS
c/w	SB08-3		3/25/2008	THROTTLE AND MIXTURE CONTROL ARMS
c/w	SB08-4		3/25/2008	FUEL INJECTION SYSTEM CONTAMINATION
c/w	MSB94-8C		4/25/2007	MAGNETO TO ENGINE TIMING
c/w	SB07-1		3/19/2007	CONNECTING ROD PISTON PIN BUSHING INSTALLATION
n/a	SB663A		2/5/2007	TWO WIRE MAGNETO TACHOMETER BREAKER (CONTACT) POINTS ASSEMBLY PART NUMBER 10-400507
n/a	X-09-06		9/26/2006	ACTIVE SERVICE BULLETIN INDEX
n/a	SIL93-11A		9/20/2006	SERVICE DOCUMENT FORMAT
n/a	SIL06-3		5/1/2006	CRANKSHAFT GEAR RETAINING SCREW
n/a	SB06-1A		4/28/2006	TELEDYNE CONTINENTAL MOTORS (TCM) FUEL SYSTEM FUEL NOZZLE INSPECTION AND REPLACEMENT
n/a	SIL99-2B		10/20/2005	CURRENT LISTING OF SEALANTS, LUBRICANTS & ADHESIVES AUTHORIZED BY TCM
n/a	SB05-9		10/20/2005	SLICK SERVICE BULLETIN SB1-88B
n/a	SB05-8		8/12/2005	IMPROVED CAMSHAFT GEAR P/N 656818
c/w	SID05-7		6/24/2005	TELEDYNE CONTINENTAL MOTORS (TCM) POSITION TUNED FUEL INJECTION NOZZLES
n/a	SB643B		4/12/2005	MAINTENANCE INTERVALS FOR ALL TCM AND BENDIX AIRCRAFT MAGNETOS AND RELATED EQUIPMENT
n/a	SIL642B		3/10/2005	MANUFACTURING NUMBER (SERIAL NUMBER) INTERPRETATION
c/w	SB96-7C		2/9/2005	TORQUE LIMITS
n/a	SB05-2		2/9/2005	OVERSPEED LIMITATIONS
n/a	SIL05-3		2/9/2005	ENGINE SPECIFICATION NUMBERS
n/a	SB04-11		11/2/2004	VALVE GUIDE APPLICATION, INSTALLATION AND REAMING PROCEDURES
n/a	SIL04-12		11/2/2004	TCM AUTHORIZED ENGINE ADJUSTMENTS, COMPONENT REPLACEMENT AND REPOSITIONING OF FITTING ORIENTATION (OEM AND CONVERTERS)
n/a	SIL00-9A		9/10/2004	ENGINE DATA PLATES
n/a	CSB04-5A		8/30/2004	TELEDYNE CONTINENTAL MOTORS IGNITION SYSTEMS CRITICAL SERVICE BULLETIN CSB665A
n/a	SIL00-11B		5/24/2004	RELEASE OF NEW CYLINDER INDUCTION PORT DRAIN CONNECTOR
n/a	SID97-2B		4/19/2004	THIS SERVICE INFORMATION DIRECTIVE (SID) SUMMARIZES INFORMATION PERTINENT TO THE DESIGN, OPERATION, MAINTENANCE AND WARRANTY FOR
n/a	SIL04-2		3/30/2004	CYLINDER BARREL ULTRASONIC INSPECTION
n/a	SIL98-9A		3/28/2003	TIME BETWEEN OVERHAUL PERIODS. (TBO)
n/a	SB03-3		3/28/2003	DIFFERENTIAL PRESSURE TEST AND BORESCOPE INSPECTION PROCEDURES FOR CYLINDERS.
n/a	SIL03-1		1/28/2003	COLD WEATHER OPERATION - ENGINE PREHEATING
n/a	CSB02-2C		12/11/2002	STARTER ADAPTER SHAFT SEAL INSPECTION.
n/a	SB01-3A		12/10/2002	TELEDYNE CONTINENTAL MOTORS P/N 649304A1 AND P/N 649305A1 GEAR-DRIVEN ALTERNATORS.
n/a	SIL02-6A		10/25/2002	PRODUCTION RELEASE OF OPTIONAL INTAKE AND EXHAUST VALVES.
n/a	CSB02-8		9/6/2002	TELEDYNE CONTINENTAL MOTORS IGNITION SYSTEM CRITICAL SERVICE BULLETIN CSB664.
n/a	CSB664		9/6/2002	MAGNETO CAPACITOR P/N 10-400558 REPLACEMENT.
n/a	SIL02-4		4/2/2002	PRODUCTION RELEASE OF NEW LIGHT WEIGHT STARTER MOTORS.
n/a	SB02-3		1/31/2002	MAGNETO TACHOMETER SENSORS.
n/a	MSB00-5D	00-08-51	10/17/2001	CRANKSHAFT MATERIAL INSPECTION.
n/a	CSB01-1		4/25/2001	FUEL PUMP INSPECTION AND SEAL LEAK TEST.
c/w	SIL00-7A		2/5/2001	OIL GAUGE ROD APPLICATION.
n/a	SB00-10		12/19/2000	FUEL PUMP SEAL P/N 649198.
n/a	SB00-4A		3/7/2000	AUSTRALIAN AVGAS CONTAMINATION.
n/a	SB99-8		11/18/1999	ENGINE FUEL INJECTION SYSTEM PRESERVATION.
n/a	SIL661		9/15/1999	BL - PREFIX MARKING ON REBUILT MAGNETOS AND REBUILT D-3000 IGNITION SYSTEMS.
n/a	SIL98-6B		8/23/1999	FUEL INJECTION SYSTEM APPLICATION GUIDE.
n/a	MSB99-3C	99-09-17	7/27/1999	CRANKSHAFT INSPECTION.
c/w	SID97-4C		4/1/1999	CYLINDER BORE AND PISTON FIT SPECIFICATIONS.
c/w	SIL99-1		3/25/1999	ENGINE PRESERVATION FOR ACTIVE AND STORED AIRCRAFT.
n/a	SIL98-5		6/12/1998	PRODUCTION RELEASE OF P/N 654837A1 CAMSHAFT ASSEMBLY.
n/a	SIL98-3A		6/12/1998	PRODUCTION RELEASE OF NEW INTAKE AND EXHAUST VALVE SPRINGS.

n/a	CSB98-1B		6/1/1998	INTAKE AND EXHAUST VALVE INSPECTION.
n/a	SB660		12/5/1997	POSSIBLE MALFUNCTION IN CERTAIN PUSH-TO-START IGNITION/STARTER SWITCHES.
n/a	SB97-15		12/5/1997	TCM IGNITION SYSTEM SERVICE BULLETIN SB660.
n/a	SIL657A		10/9/1997	SUPERSEDURE OF P/N 10-163136 AND 10-361638 COVERS AND OF 10-361637 COVER KIT.
c/w	SB97-11		8/10/1997	INSTALLATION OF SINGLE PIECE ROCKER ASSEMBLY BUSHINGS PART NUMBERS 652129 AND 652963.
c/w	CSB97-10A		7/15/1997	PISTON PIN PLUG WEAR.
n/a	SIL97-1		1/3/1997	AIRWORTHINESS LIMITATIONS.
n/a	SB96-12		9/10/1996	CONTINUED AIRWORTHINESS INSTRUCTIONS FOR TCM CYLINDERS.
n/a	SB658		8/16/1996	DISTRIBUTOR GEAR MAINTENANCE.
c/w	MSB96-10	87-23-08	8/15/1996	CRANKSHAFT ULTRASONIC INSPECTION.
n/a	SID96-6		5/3/1996	TCM IGNITION SYSTEMS SERVICE BULLETIN SB653.
n/a	SB95-7		12/8/1995	MANIFOLD VALVE COVER INSPECTION
n/a	SIL95-5		8/30/1995	HOSE AND TUBING INSTALLATION.
n/a	SB653		5/23/1995	HOT MAGNETO TEST
n/a	SB95-2		4/21/1995	INSPECTION AND MAINTENANCE OF ENGINE CONTROL CABLES AND LINKAGE.
n/a	SIL648		10/18/1994	OPTIONAL CONVERSION TO "SHOWER-OF-SPARKS" IGNITION
n/a	SIL94-5		6/14/1994	MOBIL AV1 OIL
n/a	MSB645	96-12-07	4/4/1994	INSPECTION OF RIVETED IMPULSE COUPLINGS AND STOP PINS
c/w	SB94-2		2/10/1994	OIL FILTER ADAPTER MOUNTING STUD
n/a	SIL640		2/1/1994	NEW SERVICE DOCUMENT FORMAT
c/w	SIL93-15		9/13/1993	GENERAL PRACTICES FOR USE OF LOCK WIRE, TAB WASHERS AND COTTER PINS.
n/a	SIL93-14		8/17/1993	CFC WARNING STATEMENT
c/w	639	96-12-07	3/1/1993	PROPER INSTALLATION OF IMPULSE COUPLINGS
c/w	M93-8		2/19/1993	ROCKER ARM TO ROTOCOIL CLEARANCE
c/w	M93-4		2/12/1993	CRANKSHAFT COUNTERWEIGHTS
n/a	M92-12		8/27/1992	NEW AND REBUILT ALTERNATOR THRU-BOLT TORQUE INSPECTION, P/N's 649304, 649305 (WITH DRIVE COUPLING), 649304R and 649305R (WITH DRIVE COUPLING)
n/a	636		8/1/1992	BENDIX/TCM IGNITION SWITCH INSPECTION
c/w	M92-9		5/29/1992	FLANGED .500 THRU BOLT NUT, P/N 652541
n/a	M92-7		5/26/1992	CRANKCASE CYLINDER DECK STUDS
c/w	M91-9		8/9/1991	CAM AND LIFTER LUBRICATION DURING ENGINE BUILD
n/a	635		5/1/1991	GOLD SEAL HARNESS
n/a	M90-13		7/16/1990	EXHAUST VALVE STEM CORROSION/EROSION
n/a	631		9/1/1989	RECOMMENDED LUBRICANT FOR TAPERED DRIVE ON TCM MAGNETOS
n/a	M89-18		8/10/1989	EXHAUST GAS TEMPERATURE (E.G.T.) RECOMMENDATIONS FOR STANDARD ENGINES ( Leaning Lean )
n/a	M89-7R1		8/4/1989	ENGINE OPERATION AFTER CYLINDER REPLACEMENT AND/OR MAJOR OVERHAUL
n/a	M89-9		4/21/1989	EXCESSIVE CRANKCASE PRESSURES
n/a	M89-5		2/9/1989	ALTERNATOR AND DRIVE COUPLING INSTALLATION
n/a	M88-10	95-21-15	8/24/1988	CONTAMINATED FUELS
n/a	M88-9		8/24/1988	LIGHTNING STRIKES
c/w	M87-23		11/24/1987	CRANKSHAFT COUNTERWEIGHT IDENTIFICATION AT OVERHAUL
n/a	M87-16		8/14/1987	SLICK SERVICE BULLETIN SB1-86A
n/a	M87-15		7/13/1987	ALTERNATOR GROUND STRAP
n/a	M81-25		11/30/1981	EXHAUST FLANGE TO CYLINDER INSTALLATION PROCEDURES
c/w	M76-4		3/12/1976	INSTALLATION INSTRUCTIONS FOR PROPELLER SHAFT OR CRANKSHAFT OIL SEALS
n/a	556C	74-26-09	7/1/1975	SHOULDERED MAGNETO DRIVE SHAFT BUSHING, CHANGE FROM SINTERED IRON TO MACHINED STEEL.
n/a	M74-18	74-08-05	9/16/1974	COMPLIANCE WITH SLICK BULLETIN 1-74
n/a	M71-14	74-18-05	6/21/1971	SLICK SERVICE BULLETIN NO. 1-71
n/a	M70-11		6/22/1970	SLICK ELECTRO BULLETIN 1-70
n/a	M64-18		10/7/1968	FIELD CONVERSION TO TURBOCHARGING OF CONTINENTAL AIRCRAFT ENGINES
Air Worthiness Directives Listings				
n/a		2000-23-21	12/12/2000	CRANKSHAFT MATERIAL INSPECTION
n/a		99-19-01	9/30/1999	TCM ENGINE - CRANKSHAFT ULTRASONIC INSPECTION.
n/a		70-14-07	11/22/1974	TCM ENGINE - FUEL INJECTION PUMP ADJUSTABLE BYPASS NEEDLE

DATE 8 JUL 09

W/O NO. 33205

CUST. SATS AIR

MFG. TCM

# LOG OF AIRCRAFT ENGINE TEST

TELEDYNE MATTITUCK SERVICES Inc.

Mattituck, N.Y., U.S.A

UNITED STATES FEDERAL AVIATION ADMINISTRATION

APPROVED REPAIR STATION NO. T10R507Y


MM ( ) SS ( )  
MH  MISC ( )


Engine Total Time 1665.5 HRS

Model	<u>10-550-N</u>	Starter Serial	<u>4C3190920</u>	Manifold Valve	<u>COBRA400R</u>
Serial No.	<u>689951</u>	Gen/Alt Model		Nozzle Ident	<u>TCM SYS</u>
S.L. Rated H.P. @ R.P.M.	<u>310 @ 2700</u>	Gen/Alt Serial		Mag. Model	<u>10-500556-1 10-500556-1</u>
Fuel Octane	<u>AVGAS 100</u>	Carb. Model	<u>N/A</u>	R.H. Mag Serial	<u>D031A228</u>
Fuel Pump Model	<u>TCM SYS* R649053A5-12</u>	Carb. Serial	<u>N/A</u>	L.H. Mag Serial	<u>D05AA165</u>
Fuel Pump Serial	<u>B09FA101R</u>	Fuel Inj. Model	<u>TCM SYS</u>	Ign Timing	<u>22°</u>
Starter Model	<u>657596</u>	Fuel Inj. Serial	<u>A09FA126R</u>	Spark Plugs	<u>RHB32S</u>

TIME	POWER		OIL SYSTEM			FUEL SYSTEM			ATMOSPHERE					CYLINDER HEAD TEMP								EGT Rk			
	Reading	Min.	RPM	M.P.	Press. PSI	Temp °F	Cons lbs/hr	Flow pph/gph	Nozzle Press	Pump Press	Room °F	Inlet °F	Turbo Press	Case Press	Corr. Bar.	No.1	No.2	No.3	No.4	No.5	No.6		No.7	No.8	
1	3	1000	WARM-UP																						
2	10	1200	10	66/60	130	N/A	16	N/A	12.0	70	N/A	N/A	N/A	30.2	228	220	213	241	215	202	N/A	N/A			870
3	10	1500	14	61/55	165		24		14.8	73				30.2	251	241	235	270	238	224					932
4	10	1800	17	57/54	172		40		18.4	74				30.2	276	260	256	290	248	240					1090
5	10	2000	18.5	56/54	175		60		21.0	77				30.2	282	272	260	295	255	244					1097
6	10	2200	20	56/53	182		80		23.8	78				30.2	312	290	282	317	271	253					1120
7	10	2400	22	54/52	178		98		27.0	79				30.2	337	306	302	337	284	267					1150
8	15	2700	27	54/51	200		150		31.2	84				30.2	364	333	327	377	300	305					1230
9	15	2700	OIL CONSUMPTION RUN			.13 #/HR			PASSED					CRANKCASE Breather Test PAST											
10	3	1000	COOL DOWN			RUN																			

COMPRESSION TEST	77	76	76	75	75	76	N/A	N/A	ENGINE PERFORMANCE TEST					TEST OPERATOR <i>[Signature]</i>					
	80	80	80	80	80	80	80	80	Both Mags R.P.M. 1800										
CYLINDER TYPE	Chrome	Steel	Nitride	Cerminil	TEST # 14 m					R.H.	1720	L.H.	1720	ACCEPTED <i>[Signature]</i>					
		*			CLUB NO. 27					Drop R.H.	80	L.H.	80						
OIL FILTER/SCREEN INSP OK					Idle Speed					Idle Mixture					Fuel Cut Off				

1. Approving National Aviation Authority/Country: FAA/United States		2. <b>AUTHORIZED RELEASE CERTIFICATE</b> FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: SAME AS BLOCK 5	
4. Organization Name and Address: Teledyne Continental Motors 2039 Broad Street Mobile, Alabama 36601				5. Work Order/Contract/Invoice Number: PC #508 0000011875	
6. Item 1	7. Description FUEL INJ. SERVICE KIT	8. Part Number: R-649053A5-12	9. Eligibility: N/A		
10. Quantity: 1	11. Serial/Batch Number: SEE BELOW	12. Status/Work: See Block 13			
13. Remarks: RETURN TO SERVICE, Rebuilt to Original PAH's Specifications  SN's: T/CONT - A09FA126R, F/PMP - B09FA101R, C08RA408R					
14. <input checked="" type="checkbox"/> Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data as in condition for use <input type="checkbox"/> Non-approved design data specified in Block 19.			19. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13  Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
15. Authorized Signature: XXXXXXXXXXXXXXXXXXXX		16. Approval/Authorization No.: XXXXXXXXXX		20. Authorized Signature:  Daniel L. Nicholas	
17. Name (Typed or Printed): XXXXXXXXXXXXXXXXXXXX		18. Date (m/d/y): XXXXXXXXXX		21. Approval/Certificate Number: PC #508	
				22. Name (Typed or Printed): Daniel L. Nicholas	
				23. Date (m/d/y): JUN/24/2009	
<b>User/Installer Responsibilities</b>					
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.</p> <p>Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.</p> <p>Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>					

1. Approving National Aviation Authority/Country: FAA/United States		2. <b>AUTHORIZED RELEASE CERTIFICATE</b> <b>FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG</b>		3. Form Tracking Number: SAME AS BLOCK 5	
4. Organization Name and Address: Teledyne Continental Motors 2039 Broad Street Mobile, Alabama 36601				PC #508 5. Work Order/Contract/Invoice Number: 0000010588	
6. Item 1	7. Description STARTER MOTOR-24V	8. Part Number: 657596	9. Eligibility: N/A		
10. Quantity: 1	11. Serial/Batch Number: 4C3-190920	12. Status/Work: NEW			
13. Remarks:  <p style="text-align: center;">AIRWORTHINESS APPROVAL</p>					
14. Certifies the items identified above were manufactured in conformity to:  <input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.		XXX 13 XXX Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, 25.1301-14, Return to Service, or other regulation specified in Block 13. XXX			
15. Authorized Signature: 		16. Approval/Authorization No.: DMIR#CE-511010		20. Authorized Signature: XXXXXXXXXXXXXXXXXXXXXXX	
17. Name (Typed or Printed): Daniel L. Nicholas		18. Date (m/d/y): JUN/17/2009		21. Approval/Certificate Number: XXXXXXXXXXX	
22. Name (Typed or Printed): XXXXXXXXXXXXXXXXXXXXXXX		23. Date (m/d/y): XXXXXXXXXXX			
<b>User/Installer Responsibilities</b>					
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.</p> <p>Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.</p> <p>Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>					

1. Approving National Aviation Authority/Country: FAA/United States	2.	3. Form Tracking Number: QAA # 55636
--	----	---

## AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

LH

4. Organization Name and Address: Quality Aircraft Accessories Inc. (QYIR334Y) 5746 East Apache Tulsa, OK 74115	Phone: 1-877-833-6948 918-835-6948 Fax: 918-835-2804	5. Work Order/Contract/Invoice Number: INV# 83457
--	--	--

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	MAGNETO	10-500556-1	(VARIOUS)	1	D05AA165	OVERHAUL

13. Remarks:

<input checked="" type="checkbox"/> CSB641 CONDENSOR	<input type="checkbox"/> SB2-80C 500 HR. INSPECTION
<input checked="" type="checkbox"/> MSB644 COIL & ROTOR (AD 94-01-03R2)	<input type="checkbox"/> SB1-98 500 HR. IMPULSE INSPECTION (AD-99-04-04)
<input checked="" type="checkbox"/> MSB645 500 HR. IMPULSE INSPECTION (AD 2005-12-06)	<input type="checkbox"/> SB2-08 BREAKER POINT CAM
	<input type="checkbox"/> SB3-08 CARBON BRUSH

The work identified in Block 12 and described in Block 13 except as otherwise specified was carried out in accordance with EASA 145 and in respect to that work the aircraft component is considered ready for release to service under EASA acceptance Certificate number EASA 145.5982

See Attached Work Order Summary for details. ( 2 ) pages (MECH: KW )

14. Certifies the items identified above were manufactured in conformity to:  <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.	19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13  Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
--	--

15. Authorized Signature:	16. Approval/Authorization No.:	20. Authorized Signature: <i>Ovette Mitchell</i>	21. Approval/Certificate No.: QYIR334Y
17. Name (Typed or Printed):	18. Date (m/d/y):	22. Name (Typed or Printed): OVETTE MITCHELL	23. Date (m/d/y): 05/28/09


### User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



1. Approving National Aviation Authority/Country: FAA/United States		2. <b>AUTHORIZED RELEASE CERTIFICATE</b> FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: QAA # 55637	
4. Organization Name and Address: Quality Aircraft Accessories Inc. (QYIR334Y) 5746 East Apache Tulsa, OK 74115				Phone: 1-877-833-6948 918-835-6948 Fax: 918-835-2804		5. Work Order/Contract/Invoice Number: INV# 83457	
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	MAGNETO	10-500556-1	(VARIOUS)	1	D03IA228	OVERHAUL	
13. Remarks: <input checked="" type="checkbox"/> CSB641 CONDENSOR <input checked="" type="checkbox"/> MSB644 COIL & ROTOR (AD 94-01-03R2) <input checked="" type="checkbox"/> MSB645 500 HR. IMPULSE INSPECTION (AD 2005-12-06) <input type="checkbox"/> SB2-80C 500 HR. INSPECTION <input type="checkbox"/> SB1-98 500 HR. IMPULSE INSPECTION (AD-99-04-04) <input type="checkbox"/> SB2-08 BREAKER POINT CAM <input type="checkbox"/> SB3-08 CARBON BRUSH							
The work identified in Block 12 and described in Block 13 except as otherwise specified was carried out in accordance with EASA 145 and in respect to that work the aircraft component is considered ready for release to service under EASA acceptance Certificate number EASA 145.5982  See Attached Work Order Summary for details. ( 2 ) pages <span style="float:right;">(MECH: KW )</span>							
14. Certifies the items identified above were manufactured in conformity to:  <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13  Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:		20. Authorized Signature: 		21. Approval/Certificate No.: QYIR334Y	
17. Name (Typed or Printed):		18. Date (m/d/y):		22. Name (Typed or Printed): OVETTE MITCHELL		23. Date (m/d/y): 05/28/09	
<b>User/Installer Responsibilities</b>							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.  Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.  Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	---------------------------	------------------------------	---

Engine Model: 10-550-N      Engine S/N: 689951      Engine Time: 1665.5 HRS.

**Teledyne Mattituck Services**

FAA Repair Station T10R507Y  
410 Airway Drive  
Mattituck, New York 11952

This engine was disassembled, cleaned, inspected and repaired as necessary. Parts replaced per the supplied parts list. Engine reassembled and test cell run per Teledyne Mattituck Special Process SP1012C. **Engine Major Overhauled.**

Complied with the following Service Bulletins: SB08-13, MSB96-10A, SB97-6A, SID97-3E, SB08-3, SB08-4, MSB94-8C, SB07-1, SID05-7, SB96-7C, SIL00-7A, SID97-4C, SIL99-1, SB97-11, CSB97-10A, MSB96-10, SB94-2, SIL93-15, C39, M93-8, M93-4, M92-9, M91-9, M87-23, M76-4

Complied with the following AD Notes: NO APPLICABLE AD NOTES AT THIS TIME

This engine is airworthy and returned to service with respect to the work performed.

Work Order: 33205      Authorized Signature: [Signature] 7-8-2009

Form RS-061 Rev (Aug 2008)

**Engine Component Serial Number Summary:**


ITEM	Serial Number	Item	Serial Number
Camshaft	Z09DA117	Left Magneto	D05AA165
Crankshaft	N06FA325	Right Magneto	D031A228
Crankcase	R03DA454	Starter	4C3190920
Connecting Rod	AE06FA627	Manifold Valve	C06HA175
Connecting Rod	AE06FA605	Fuel Pump	B06HA167
Connecting Rod	AE06FA615	Metering Unit	A06HA171
Connecting Rod	AE06FA584	Oil Cooler	7147
Connecting Rod	AE06FA583	Alternator	
Connecting Rod	AE06FAB26	Turbocharger	
Cylinder -1	AC06EC865	Turbocharger	
Cylinder-2	AC06BA099	Turbo Controller	
Cylinder-3	AC06BA068	Turbo Controller	
Cylinder-4	AC06AA715	Overboost Valve	
Cylinder-5	AC06ED109	Wastegate	
Cylinder-6	AC06AB927		

Form RS-062 New (July 2008)


**SUB-TOTALS** this page


**TOTALS**—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

MAKE	TCM	MODEL	10-550-N	SERIAL No./N No.	689951
TOTAL TIME	1665.5 HRS	TACH READING	N/A	DATE	2-MAR-10
REMOVE ROCKER COVERS, ROCKER ARMS, PUSRODS, TUBES AND LIFTERS INSPECT CAM SHAFT FOR CORROSION AND BORESCOPE CYLINDERS. NO ABNORMALTIES FOUND ON EITHER INSPECTION.					
INSTALLED NEWLY REBUILT ALT. PN R649305 SA 009KA083R.					
ENGINE TEST CELL RUN AFTER RE ASSEMBLY. LEAK AND OPERATIONAL CK SATISFACTORY. THIS ENGINE IS AIRWORTHY WITH RESPECT TO THE WORK PERFORMED AND IS APPROVED FOR RETURN TO SERVICE. Ret w/o # 33453					
TELEDYNE MATTITUCK SERVICES, INC. FAA Repair Station T10R507Y W.O. No. 33454 AD 2009-9-07 + AD 2009-24-52 N/A Selected PARTS NOT INSTALLED.					
				 Authorized Signature	

FORM RS-36 REV.(NOV. 2005)

MODEL: SR22  
S/N: 2180  
REG. No: N509SR



DATE: 11-01-2010  
HOBBS: 1936.3  
TACH: 1707.7

Engine S/N 689951

2291  
1936  
355

**Inspections:**

-Complied with Annual Inspection IAW AMM 5-00.

**AD's:**

- AD 2009-16-03 (To Prevent the Separation of the cylinder head) N/A per cylinder manufacture installed.
- AD 2010-11-04 (To Prevent Excessive Hydraulic Lifter wear) N/A per hydraulic lifters PN 657077 and P/N 657088.


**Maintenance Accomplished:**


- Installed Overhauled TCM IO-550-N Engine S/N 689951 with 1,665.5 TET, IAW TCM MM and Cirrus AMM 72-00. For more details on Engine, see work order 19095 task#102.
- Installed Engine mount P/N 16546-001 S/N 3147, IAW AMM 71-00.
- Installed new propeller governor P/N C290D3R/T23 S/N 03-0638, IAW AMM 61-00.
- Cleaned forward face of engine firewall, IAW AMM 20-30.
- Installed Alternator #2 P/N BC410-1 S/N 0231730 after repair with new field wire connectors, IAW AMM 24-00.
- Replaced EGT probes with new P/N 16579-002 on cylinder #1, #3, #5, #2, and #6, IAW AMM 77-00.
- Adjusted oil pressure, idle RPM, and mixture rise, IAW TCM OHM.
- Performed engine ground run and leak check. Prepared aircraft for test flight, IAW AMM 71-00 and AMM 4-00.
- Installed new Vibration Lord Mounts P/N J9613-76, IAW AMM 72-00.
- Installed new Fuel Transducer P/N 15415-001, IAW AMM 72-00.
- Installed new engine hoses P/N 50903-008, IAW AMM 72-00.
- Installed new CHT sensor P/N 16578-001, IAW AMM 72-00.
- Installed new MAP sensor P/N 16235-001, IAW AMM 72-00
- Installed new oil temperature sensor P/N 12634-001, IAW AMM 72-00.

The engine identified above was inspected and repaired in accordance with the current Federal Aviation Regulations and is approved for return to service with only with respect to the work performed. Pertinent details of the work performed are on file at this repair station under Work Order No 19095.

Signed: 

For: **Corporate Flight Management, Inc.** Certified Repair Station **FJTR920D**

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	MODEL: SR22 S/N: 2180 REG. No: N509SR	 276 Doug Warpoole Road Smyrna, TN 37167 615.534.4600		DATE: 1-21-2011 HOBBS: 1975.8 TACH: 1740.7
<b>Engine S/N 689951</b>				
<b>Maintenance Accomplished:</b> -Performed Oil Change IAW AMM 12-00. Drained and removed oil filter, cut open filter, no metal particles found. Serviced With 8 quarts of Phillips X/C 20W50 and oil filter AA48108-2. Run up performed, no leak noted at this time.  The engine identified above was inspected and repaired in accordance with the current Federal Aviation Regulations and is approved for return to service with only with respect to the work performed. Pertinent details of the work performed are on file at this repair station under Work Order №19659. Signed: <i>[Signature]</i> For: <b>Corporate Flight Management, Inc.</b> <b>Certified Repair Station</b> <b>FJTR920D</b> Form CFM 007				

	MODEL: SR22 S/N: 2180 REG. No: N62CH	 276 Doug Warpoole Road Smyrna, TN 37167 615.534.4600		DATE: 5/5/2011 HOBBS: 2016.7 TACH: 1775.4
<b>Engine S/N 689951</b>				
<b>Inspections:</b> -Complied with Annual Inspection IAW AMM 5-00. <b>AD's:</b> -None due at this time. <b>Maintenance Accomplished:</b> -Performed cylinder compression checks. #1) 78/80 #2) 78/80 #3) 76/80 #4) 78/80 #5) 78/80 #6) 76/80 -Removed oil cooler P/N 8000953 S/N 7147 and replaced with new P/N 8000953 S/N 4041018 IAW TCM overhaul manual. -Performed oil change IAW AMM 12-00. Drained and removed oil filter, cut open filter, no metal particles found. Serviced with 8 quarts of Phillips 20W50X/C and oil filter AA48108-2. Run up performed, no leak noted at this time.  The engine identified above was inspected and repaired in accordance with the current Federal Aviation Regulations and is approved for return to service with only with respect to the work performed. Pertinent details of the work performed are on file at this repair station under Work Order №19961. Signed: <i>[Signature]</i> For: <b>Corporate Flight Management, Inc.</b> <b>Certified Repair Station</b> <b>FJTR920D</b> Form CFM 007				

**ARAPAHOE AERO**  
 12760 EAST CONTROL TOWER ROAD; ENGLEWOOD, COLORADO 80112 (303) 799-8386  
 N62CH      Continental      IO-550-N      S/N: 689951      Engine Log Entry  
 14 June 2011      Flight Hobbs: 1810.2      Hobbs Meter: 2067.3  
 Completed 50 hour inspection this date using Cirrus 50 Hour inspection items as a guide. Drained oil and changed engine oil filter. Serviced engine using 7 quarts (Aeroshell 15W-50). Installed, torqued and safetied new Champion CH48108-1 filter. Old filter cut open and inspected - no ferrous contaminates noted. Oil sample taken and submitted. Inspected engine case breather tube for obstructions. Inspected engine exhaust system-no defects noted. Checked lubrication and operation of engine and propeller controls. Post inspection and maintenance engine ground run operational and leak check satisfactory.  
*[Signature]*      L. John Wells A&P 3221132      w/o 30665


**SUB-TOTALS** this page  
**TOTALS**—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	-----------------------	---------------------------	------------------------------	---

**ARAPAHOE AERO**

12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386  
**N62CH Continental IO-550-N(42) S/N: 689951 Total Time: 1823.2**  
**24 August 2011 Flight Hobbs: 1865.4 Hobbs Meter: 2137.0**  
**100 Hour Inspection for Annual** completed this date using the Cirrus Design SR22 Maintenance Manual Inspection Form as a guide. Compression test: #1) 76/80, #2) 74/80, #3) 76/80, #4) 78/80, #5) 76/80, #6) 75/80. Changed oil and filter (Aeroshell 15W-50). Cut oil filter open and inspected, no ferrous contaminants noted. Cleaned, gapped, tested, and rotated spark plugs. Checked timing of magnetos to engine. Inspected fuel injection system for component condition and security. Repositioned #1) cylinder fuel injection line to prevent further chafing on induction tube. Leak checked fuel system. Fabricated and installed center cooling baffle left corner riveted surface doubler repair. Fabricated and installed right rear cooling baffle riveted surface doubler repair. Installed right aft cooling baffle support and reinstalled and torqued upper case through bolt. Installed new aft cooling baffle throttle cable pass through elastic grommet. Installed oil cooler seal between cooler and baffle using high temperature RTV sealant. Rerouted and secured air conditioning compressor hoses, to prevent further chafing on starter. Installed (8) new air compressor rubber coupling drive bushings. Secured air conditioning wiring harness. Secured cabin heat SCEET air induction hose using new cushion type clamp. Washed engine down using solvent. Inspected and pressure tested exhaust system. Inspected induction air filter element. Checked and lubricated throttle, mixture and propeller controls. Installed new engine mount lower right braded grounding strap P/N: MS25083-6BB6. AD's checked through Biweekly 2011-17. Post inspection engine ground run-up, operational check and leak check good. **I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.**

*Scott S. Fisher* **Scott S. Fisher A&P 3290363** w/o 30906

**ARAPAHOE AERO**

12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386  
**N62CH Continental IO-550-N(42) S/N: 689951 Engine Log Entry**  
**28 December 2011 Flight Hobbs: 1931.5 Hobbs Meter: 2220.5**  
 Troubleshoot #2 alternator intermittent operation. Cleaned connection at #2 alternator. Removed MCU cover and inspected MCU. Opened circuit breaker panel and inspected. No issues were found. Reassembled and ~~reinstalled all parts~~ Ground run checks satisfactory.

*Scott S. Fisher* **Scott S. Fisher A&P 3290363** w/o 31423

**ARAPAHOE AERO**

12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386  
**N62CH Continental IO-550-N(42) S/N: 689951 Total Time: 1902.1**  
**19 January 2012 Flight Hobbs: 1944.3 Hobbs Meter: 2236.1**  
**100 Hour Inspection for Annual** completed this date using the Cirrus Design SR22 Maintenance Manual Inspection Form as a guide. Compression test: #1) 70/80, #2) 73/80, #3) 75/80, #4) 75/80, #5) 74/80, #6) 75/80. Changed oil and filter (Aeroshell 15W-50). Cut oil filter open and inspected, no ferrous contaminants noted. Cleaned, gapped, tested, and rotated spark plugs. Checked timing of magnetos to engine. Inspected, grouped and secured left and right magneto ignition wires. Inspected fuel injection system for component condition and security. Leak checked fuel system. Inspected and repositioned aft fuel drain lines to prevent further contact with engine mount weldments. Tightened lower bolts on engine mount weldment to specified torque. Installed new aft right cooling baffle assembly support bracket P/N: 13685-001. Inspected #1) alternator brushes and installed new field electric terminal boot. Washed engine down using solvent. Inspected and pressure tested exhaust system. Installed new induction air filter element. Checked and lubricated throttle, mixture and propeller controls. Adjusted throttle control rod-end to provide full stop-to-stop travel. **Continental AD 2011-25-51E (Starter Adapter Gear Shaft Failure)** effective 12-28-2011, supersedes Emergency AD 2011-25-51, does not apply by installed starter adapter part number, no further action required. AD's checked through Biweekly 2012-01. Post inspection engine ground run-up, operational check and leak check satisfactory. **I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.**

*L. John Wells* **L. John Wells A&P 3221132** w/o 31469

ITEM: 3  
 ORDER: 2494069N/LOT: N/A  
 PN: 10-320467  
 QTY: 1  
 U/M: EA  
 DESC: TERMINAL

2494069

3

OTY: 1  
 U/M: EA

1. Approving National Aviation Authority / Country: FAA / UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number 2494069	
4. Organization Name and Address: Cessna Aircraft Company (PC4) Cessna Parts Distribution Dept. 702 5800 E Pawnee, Wichita, KS 67218				5. Work Order/Contract/Invoice Number 951151		
6. Item	7. Description	8. Part Number	9. Eligibility *	10. Quantity	11. Serial/Batch Number	12. Status/Work
3	TERMINAL	10-320467	N/A	1	N/A	New
13. Remarks: AIRWORTHINESS APPROVAL - PARTS. THIS FORM IS NOT AN EXPORT APPROVAL.  PO# INV-26991						
14. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.			15. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in block 13 Certifies that unless otherwise specified in Block 15, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature: <i>Kenneth E. Wysocki</i>		16. Approval/Authorization No.: ODA-100129-CE		20. Authorized Signature:		21. Approval/Certificate No.:
17. Name (Typed or Printed): KENNETH E. WYSOCKI SR.		18. Date (m/d/y): AUG/27/2009		22. Name (Typed or Printed):		23. Date (m/d/y):
<p align="center"><b>User / Installer Responsibilities</b></p> <p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>						
FAA Form 8130-3 (6-01)			* Installer must cross-check eligibility with applicable technical data.		NSN: 0052-00-012-9005	

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
2 May 12				Hobbs 2314.3 Flight 2012.1 Complied with 50 hr inspection IAW Cirrus SR22 inspection guide. Drained oil and out oil filter, no metal noted. Serviced engine with 7 qts of Amsoil 15w-50 operational and leak check good. Aircraft ok for service. Joshua J. Vanterpool ATP 2817060 - END -
6-20-12	2078.58	413.3	2349.6	Completed a 100 Hour inspection IAW Cirrus M.M. inspection guide and FAR 43 App D. Compression test 1- 74/80 2- 70/80 3- 74/80 4- 74/80 5- 72/80 6- 70/80. Drained oil sump and serviced with 8qts AS. 15w50. Removed and inspected oil filter no metal noted; installed new CH48188-1. Cleaned gapped tested and rotated spark plugs. Installed new induction air filter DA-24. Removed and installed left and right magneto for troubleshooting. Found no defects on either magneto. Trinned and repaired left and right magneto #1 spark plug leads. Swapped left and right magneto p-leads to proper location. AD 12-03-06 AFS Fuel Servo Diaphragm does not apply. part not installed. AD's checked through B-weekly 2012-01. Operational and leak check good. I certify that this engine has been inspected IAW a 100 Hour -7
				<b>SUB-TOTALS</b> this page <span style="float: right;">Cont.</span>
				<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
				inspection and was determined to be in an airworthy condition.
				J. Vanterpool AP2817060 — EVO —
Aspen Flying Club				
13000 E. Control Tower Rd. Box K-16 Englewood, CO 80112				
08/08/12			Cirrus SR22 SN: 2180	N62HC
	Flight: 2096.3	Hobbs: 2408.3	TTIS: 2137.5	SMOH: 472
Complied with a 50 Hour Inspection IAW Cirrus SR22 inspection guide. Drained engine oil, removed filter and cut for inspection. No metal noted. Service engine with 8 qts of Aeroshell 15W50 and installed new oil filter p/n CH40108-1. Operational and leak check good. Aircraft ok for service.				
Josh Vanterpool AP2817060				

**R A S**

**ROCKY MOUNTAIN  
AIRCRAFT SERVICES LLC**

11750 Airport Way Hanger B-12A  
Broomfield CO, 80021

Date: 10-26-2012  
Acraft Reg: N62CH  
Flight Tach: 2125.2  
SMOH: 417.5  
**ENGINE**

Performed an Annual/100 HR inspection in accordance with FAR 43 App (D) and Cirrus checklist. Drained oil and serviced sump with 8 Qts Aeroshell 15w50 oil. Removed old oil filter and cut for inspection, no defects found. Installed torqued and safetied new 48108-1 oil filter. Compressions as follows #1 73 #2 71 #3 74 #4 72 #5 73 #6 71 all over 80 PSI. Removed, cleaned, gapped, tested and reinstalled all spark plugs to 32.5 FT lbs torque using (12) new M674 gaskets. Repositioned and installed missing hardware in exhaust shroud. Cleaned fuel and oil screens as required. Inspected exhaust and intake for leaks, cracks or other defects. None noted at this time. Retorqued all valve covers. Ground run and operational check of all systems are ok at this time. A list of AD's may be found in aircraft records. I certify that this engine has been inspected in accordance with an Annual/100 HR inspection and has been determined to be in airworthy condition and is approved for return to service at this time.-----END-----

Justin C Parrow *Justin C Parrow*

A&P30835861A

				SUB-TOTALS this page
				TOTALS—Carry forward to next page





**ROCKY MOUNTAIN  
AIRCRAFT SERVICES LLC**

11750 Airport Way Hanger B-12A  
Broomfield CO, 80021

Date: 1-16-2014  
Acft Reg: N62CH  
Flight Tach: 2290.8  
SMOH: 583.1  
**ENGINE**

K


Performed an Annual/100 HR inspection in accordance with FAR 43 App (D) and Cirrus checklist. Drained oil and serviced sump with 8 Qts Aeroshell 15w50 oil. Removed old oil filter and cut for inspection, no defects found. Installed torqued and safetied new 48108-1 oil filter. Compressions as follows #1 71 #2 73 #3 72 #4 72 #5 73 #6 76 all over 80 PSI. Removed, cleaned, gapped, tested and reinstalled all spark plugs to 32.5 FT lbs torque using (12) new M674 gaskets. Cleaned fuel and oil screens as required. Removed and cleaned induction tube of dirt and other debris and reinstalled. Inspected exhaust and intake for leaks, cracks or other defects. None noted at this time. Retorqued all valve covers. Ground run and operational check of all systems are ok at this time. A list of AD's may be found in aircraft records. I certify that this engine has been inspected in accordance with an Annual/100 HR inspection and has been determined to be in airworthy condition and is approved for return to service at this time.-----END-----


Justin C Parrow

A&P30835861A


**SUB-TOTALS** this page  
**TOTALS**—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page

**ARAPAHOE AERO**  
 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386  
**N62CH Continental IO-550N(42) S/N: 689951 Engine Log Entry**  
**23 August 2013 Flight Hobbs: 2250.6 Hobbs Meter: 2595.8**  
 Changed engine oil and filter using Shell 15W50 oil. Cut oil filter open and inspected for foreign material, no ferrous contaminants found. Engine run up and leak check good.  
  
 Alberto Pizzato A&P 2522916 w/o 33486


**Calkins Aero Service Inc.**  
 West Houston Airport  
 18000 Groeschke Rd.  
 Houston, TX 77084  
 DATE: 12/13/2014 N62CH HOBBS: 2890.0  
**CHANGED OIL AND FILTER. SERVICED ENGINE WITH 7QTS AEROSHELL 15W50 OIL. WASHED RUN AND LEAK CHECKED OK**  
 Calkins Aero Service Inc.  
 FAA Certified Repair Station  
 No. GK2R849K signed 

ENGINE MODEL: IO-550-N  
 ENGINE S/N: 689951  
 REG. NO: N62CH  
 WORK ORDER:  
 3731-01-2015



**Houston Aviation Center, LLC**  
 12888 Hwy 6 S Ste 113  
 Sugar Land, TX 77498 USA  
 Phone: 281-494-5800


DATE: 2/4/2015  
 A/C TSN: 2527.1  
 ENG TT: 2484.9  
 TSMOH: 819.4  
 FLIGHTTIME: 2527.1

**Engine Entries**

(Flight Meter: 2527.1) Completed a 100 HR/Annual Inspection this date Ref. CDC SR22 AMM 5-20 and CMI IO-550-N Maintenance Manual P/n M-16. Performed a cylinder compression check Ref TCM SB03-3 using differential compression tester with a calibrated orifice value of 42 PSI with results as follows: #1/58, 2/65, 3/62, 4/63, 5/56, 6/64 over 80 PSI. Installed (12) new Tempest spark plugs P/n URHB32E. Drained oil and inspected filter for contaminants (oil sample taken). Installed new oil filter P/n AA48108-2 and serviced engine with 7 Qts. Aeroshell 15W-50. Ran engine and checked for leaks. Inspected and tested Continuous Flow Fuel Injection system per CMI M-16. Inspected intake and exhaust system for leaks. Inspected and cleaned all fuel injectors nozzles and reinstalled nozzles with new o-rings P/n AS3578-010. Purged system and checked for leaks. Checked AD's thru BW 2015-02. Superior Air Parts Investment Cast Cylinder AD 2014-05-29 is N/A by cylinders are not installed.... Removed LH & RH magnetos P/n 10-500556-1, LH S/N DO5AA165, and RH S/N DO3TA228, for 500 hr. inspection/repair. Reinstalled LH & RH magnetos P/n 10-500556-1, LH S/N DO5AA165, and RH S/N DO3TA228, after 500 hr. inspection/repair by Quality Aircraft Accessories CRS No. QYIR334Y, under W/Os 001691 and 001690. Operational check satisfactory.... Installed new oil quick drain P/n S6250.... I certify that this Engine has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.

**Maintenance Release**

The aircraft and/or component(s) on N62CH was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 3731-01-2015.




DATE: 2/4/2015 SIGNED:  Work Order: 3731-01-2015  
 Fouad Hussain, A&P: 3204861 IA Printed by EBIS 3 (datcomedia.com)


**Calkins Aero Service Inc.**  
 West Houston Airport  
 18000 Groeschke Rd.  
 Houston, TX 77084  
 Date: 03/16/15 N62CH HOBBS: 2866.4  
 FLT 2866.4

**Changed oil and filter. Serviced with 7Qts. of Aero Shell 15W50 Wash, run, and leak check-OK.**

**AIRCRAFT AIRWORTHY FOR RETURN TO SERVICE**

Calkins Aero Service Inc.  
 FAA Certified Repair Station  
 No. GK2R849K signed 

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<p><i>Calkins Aero Service Inc.</i>                      West Houston Airport                      18000 Groeschke Rd.                      Houston, TX 77084</p> <p>Date: <u>4/27/15</u> N <u>62CH</u> TACH/HOBBS: <u>2973.1</u></p> <p>Changed oil and filter. Serviced with <u>7</u> QTS <u>AeroShell 15W50</u>                      Wash, run, and leak check-OK.                      AIRCRAFT AIRWORTHY FOR RETURN TO SERVICE                      Calkins Aero Service Inc.                      FAA Certified Repair Station                      No. GK2R849K signed </p>
				<p><i>Calkins Aero Service Inc.</i>                      West Houston Airport                      18000 Groeschke Rd.                      Houston, TX 77084</p> <p>Date: <u>7/1/15</u> N <u>62CH</u> TACH/HOBBS: <u>3016</u></p> <p>Changed oil and filter. Serviced with <u>7</u> QTS <u>AeroShell 15W50</u>                      Wash, run, and leak check-OK.                      AIRCRAFT AIRWORTHY FOR RETURN TO SERVICE                      Calkins Aero Service Inc.                      FAA Certified Repair Station                      No. GK2R849K signed </p>
				<p><i>Calkins Aero Service Inc.</i>                      West Houston Airport                      18000 Groeschke Rd.                      Houston, TX 77084</p> <p>Date: <u>9/18/2015</u> N62CH HOBBS: <u>3062.1</u></p> <p>CHANGED OIL AND FILTER. SERVICED ENGINE WITH 7QTS AEROSHELL 15/50                      OIL. WASH RUN AND LEAK CHECKED OK.                      The aircraft and/or component identified above was repaired and inspected IAW current                      Federal Aviation Regulations and found airworthy for return to service. Pertinent details of                      the repair are on file at this agency under W.O. No. 25171                      Calkins Aero Service Inc.                      FAA Certified Repair Station                      No. GK2R849K signed </p>

MAKE: Cirrus  
 MODEL: SR 22  
 S/N: 2180  
 REG. NO: N62CH  
 WORK ORDER:  
 4134-10-2015



**Houston Aviation Center, LLC**  
 12888 Hwy 6 S Ste 113  
 Sugar Land, TX 77498 USA  
 Phone: 281-494-5800

DATE: 11/11/2015  
 A/C TSN: 2724.6  
 HOBBS: 3086.3

**Airframe Entries**

Installed customer provided drink holder P/n 51179-001.







**Maintenance Release**

The aircraft and/or component(s) on N62CH was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 4134-10-2015.

DATE: 11/11/2015

SIGNED: Elijah Derbecker  
 Elijah Derbecker, A&P: 3757478

Work Order: 4134-10-2015  
 Printed by EBis 3 (datcomedia.com)

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
<b>TOTALS</b> brought forward from previous page				
ENGINE MODEL: IO-550-N ENGINE S/N: 689951 REG. NO: N62CH WORK ORDER: 4134-10-2015		 <b>Houston Aviation Center, LLC</b> 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800		DATE: 11/11/2015 A/C TSN: 2724.6 ENG TT: 2682.4 TSMOH: 1016.9 HOBBS: 3086.3
<b>Engine Entries</b>				
Completed compression check using a differential compression tester with a master orifice value of 43 psi. Compression results are as follows: #1 60/80, #2 64/80, #3 73/80, #4 70/80, #5 70/80 and #6 72/80.... Cleaned all RH cylinder induction port drains and installed new LH cylinder induction drain tub assy. P/n 643584. Operational check satisfactory.... Installed (6) new cylinder head baffling P/n 649243 and (6) new baffling retention springs P/n 632907.... Removed #5 cylinder P/n 658595A1, and installed new #5 cylinder P/n 658595A2, and new intake lifter assembly P/n 658088. Drained oil , installed new oil filter P/n AA48108-2 and serviced engine with 8 Qts. Aeroshell 100 mineral oil. Cleaned and gapped all spark plugs. Performed engine run Ref. TCM SB M-89-7R1. Operational and leak check satisfactory.				
<b>Maintenance Release</b>				
The aircraft and/or component(s) on N62CH was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 4134-10-2015.				
DATE: 11/11/2015		SIGNED: 		Work Order: 4134-10-2015
		Elijah Derbecker, A&P: 3757478		Printed by EBis 3 (datcomedia.com)
ENGINE MODEL: IO-550-N ENGINE S/N: 689951 REG. NO: N62CH WORK ORDER: 4245-01-2016		 <b>Houston Aviation Center, LLC</b> 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800		DATE: 3/8/2016 A/C TSN: 2764.9 ENG TT: 2764.9 TSMOH: 1057.2 FLIGHTTIME: 2764.9
<b>Engine Entries</b>				
(Flight Meter: 2764.9) Completed a 100 HR/Annual Inspection this date Ref. CDC SR22 AMM 5-20 and CMI IO-550-N Maintenance Manual P/n M-16. Performed a cylinder compression check Ref TCM SB03-3 using differential compression tester with a calibrated orifice value of 44 PSI with results as follows: #1/67, 2/68, 3/64, 4/66, 5/71, 6/62 over 80 PSI. Cleaned, gapped and tested spark plugs. Inspected and tested Continuous Flow Fuel Injection system per CMI Overhaul and Maintenance Manual M-16. Inspected intake and exhaust system for leaks. Inspected and cleaned all fuel injectors nozzles and reinstalled nozzles with new o-rings P/n AS3578-010. Purged system and checked for leaks. Checked ADs thru BW 2016-05.... I certify that this Engine has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.				
<b>Maintenance Release</b>				
The aircraft and/or component(s) on N62CH was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 4245-01-2016.				
DATE: 3/8/2016		SIGNED: 		Work Order: 4245-01-2016
		Fouad Hussain, A&P: 3204861 IA		Printed by EBis 3 (datcomedia.com)
				
		DATE: 01-09-2016. ENG: IO-550N.		
		REG. #: N62CH. A/C S#: 4126.		
		HOBBS: 3113.3 FLIGHT: 2751.7 Hrs.		
Drained engine oil, took Blackstone oil sample, removed engine oil filter, inspected oil filter media for contaminants with none found, installed new oil filter Champion P/N:CH48108-1 & safetied, replenished engine with 8 qts of Aeroshell engine oil 15W50 using Cirrus (SR22) A.M.M. as reference for scope of maintenance; Engine components operational & leak checks satisfactory for return to service.				
 ALBERTO W. RINCON-V. A&P #: 3186786.				
<b>ENGINE</b>				

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page

 **TIDAL AVIATION**

DATE: 05-23-2016. ENG: iO-550N(1B).  
REG. #: N62CH. ENG S/N: 689951.  
A/C S#: 1110. FLIGHT: 2798.7 Hrs.


(Hobbs: 3160.4 Hrs) Drained engine oil, took Blackstone oil sample, removed engine oil filter, inspected oil filter media for contaminants with none found, installed new oil filter Champion P/N:CH48108-1 & safetied, replenished engine with 8 qts of Aeroshell engine oil 15W50 using Cirrus (SR22) A.M.M. as reference for scope of maintenance; R/R engine throttle body fuel mixture adjusting screw o-ring with new, adjusted engine idle speed & idle mixture rise to specifications using T.C.M. M-16 M.M. as reference; Details of work performed on file under Tidal Aviation W.O.#:N62CH-20160076; Engine components operational & leak checks satisfactory for return to service.

  
ALBERTO W. RINCON-V.  
A&P #:3186786

 **TIDAL AVIATION**

DATE: 07-08-2016. ENG: iO-550N(1B).  
REG. #: N62CH. ENG S/N: 689951.  
A/C S#: 1110. FLIGHT: 2836.7 Hrs.

(Hobbs: 3198.4 Hrs) (excess travel on engine throttle cable) R/R engine throttle cable with new part provided by aircraft manufacturer using Cirrus (SR22) A.M.M. as reference; Details of work performed on file under Tidal Aviation W.O.#:N62CH-20160096; Engine component operational checks satisfactory for return to service.

  
ALBERTO W. RINCON-V.  
A&P #:3186786

 **TIDAL AVIATION**

DATE: 07-21-2016. ENG: iO-550N(1B).  
REG. #: N62CH. ENG S/N: 689951.  
A/C S#: 1110. FLIGHT: 2846.4 Hrs.

(Hobbs: 3208.1 Hrs) Drained engine oil, took Blackstone oil sample, removed engine oil filter, inspected oil filter media for contaminants with none found, installed new oil filter Champion P/N:CH48108-1 & safetied, replenished engine with 8 qts of Aeroshell W100 SAE50 oil using Cirrus (SR22) A.M.M. & T.C.M. M-16 M.M. as reference for scope of maintenance; Details of work performed on file under Tidal Aviation W.O.#:N62CH-2016121; Engine components operational & leak checks satisfactory for return to service.

*Alejandro Palencia*

ALEJANDRO AGRAZ PALENCIA.  
A&P#:3507228.

 **TIDAL AVIATION**

DATE: 08-12-2016. ENG: iO-550N(1B).  
REG. #: N62CH. ENG S/N: 689951.  
A/C S#: 1110. FLIGHT: 2877.2 Hrs.

(Engine LH magneto check outside allowable limits) R/R Eng. Cyl. #3 bttm. spark plug with new Champion P/N: RHB32E using T.C.M. M-16 M.M. as reference; Details of work performed on file under Tidal Aviation W.O.#:N62CH-20160141; Engine component operational check satisfactory for return to service.

*Alejandro Palencia*  
ALEJANDRO AGRAZ PALENCIA.  
A&P#:3507228.



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
			<b>SUB-TOTALS</b> this page	
			<b>TOTALS</b> —Carry forward to next page	



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
			<b>SUB-TOTALS</b> this page	
			<b>TOTALS</b> —Carry forward to next page	











DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page



DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				<b>TOTALS</b> brought forward from previous page
				<b>SUB-TOTALS</b> this page
				<b>TOTALS</b> —Carry forward to next page





**SERVICE INFORMATION LETTER**

**SIL99-1**

**CONTAINS USEFUL INFORMATION PERTAINING TO THE CONTINENTAL AIRCRAFT ENGINE**

Technical Portions FAA Approved  
Supersedes M91-5

**SUBJECT: ENGINE PRESERVATION FOR ACTIVE AND STORED AIRCRAFT**

**PURPOSE:** Provide current engine preservation information

**COMPLIANCE:** During periods as specified by this document

**MODELS**

**AFFECTED:** All Continental Engine Models

**GENERAL**

There is no practical procedure that will insure corrosion prevention on installed aircraft engines. Susceptibility to corrosion is influenced by geographical location, season and usage. The owner/operator is responsible to recognize the conditions that are conducive to corrosion and take appropriate precautions.

**ENGINE PRESERVATION**

Corrosive attack can occur in engines that are flown only occasionally regardless of geographical location. In coastal areas and areas of high humidity, corrosive attack can occur in as little as two days. The best method of reducing the likelihood of corrosive attack is to fly the aircraft at least once every week for a minimum of one hour.

**NOTE...**

Corrosive attack may reduce engine service life. Of primary concern are cylinders, piston rings, valves, valve guides, camshaft and lifters.

**TEMPORARY STORAGE (Aircraft that are not flown for 30 to 90 days)**

Preparation for storage.

1. Remove oil sump drain plug and drain oil. Replace drain plug, torque and safety. Remove oil filter. Install new oil filter, torque and safety. Service engine to proper sump capacity with oil conforming to MIL-C-6529 Type II.

2. Perform a ground run-up. Perform a pre-flight inspection and correct any discrepancies. Fly the aircraft for one hour at normal operation temperatures.

**WARNING**

To prevent possibility of serious bodily injury or death, before moving the propeller accomplish the following:

- a. Disconnect all spark plug leads.
- b. Verify magneto switches are connected to magnetos, that they are in the "OFF" Position and "P" leads are grounded.
- c. Throttle position "CLOSED."
- d. Mixture control "IDLE-CUT-OFF."
- e. Set brakes and block aircraft wheels. Insure that aircraft tie-downs are installed and verify that the cabin door latch is open.
- f. Do not stand within the arc of the propeller blades while turning the propeller.

ISSUED			REVISED			TELEDYNE CONTINENTAL MOTORS An Allegheny Teledyne Company P.O. Box 90 Mobile AL 36601 • 334-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		1 of 4 SIL99-1	
03	25	99						

**WARNING**

**To prevent possibility of serious bodily injury or death, before moving the propeller accomplish the following:**

3. After flight remove all spark plug leads and remove the top spark plugs. Protect the ignition lead ends with AN-4060 Protectors. Using a common garden sprayer or equivalent, spray atomized preservative oil that meets MIL-P - 46002, Grade 1, at room temperature through upper spark plug hole of each cylinder with the piston at bottom dead center position. Rotate crankshaft as opposite cylinders are sprayed. Stop crankshaft with none of the pistons at top dead center.
4. Re-spray each cylinder. To thoroughly cover all surfaces of the cylinder interior move the nozzle or spray gun from the top to the bottom of the cylinder.
5. Install top spark plugs but do not install spark plug leads.
6. Seal all engine openings exposed to the atmosphere using suitable plugs and covers. Attach a red "REMOVE BEFORE FLIGHT" streamer at each location.
7. Tag each propeller in a conspicuous place with the following notation on the tag: DO NOT TURN PROPELLER - ENGINE PRESERVED - PRESERVATION DATE \_\_\_\_\_.

- a. **Disconnect all spark plug leads.**
- b. **Verify magneto switches are connected to magnetos, that they are in the "OFF" Position and "P" leads are grounded.**
- c. **Throttle position "CLOSED."**
- d. **Mixture control "IDLE-CUT-OFF."**
- e. **Set brakes and block aircraft wheels. Insure that aircraft tie-downs are installed and verify that the cabin door latch is open.**
- f. **Do not stand within the arc of the propeller blades while turning the propeller.**

3. After flight remove all spark plug leads and remove the spark plugs. Protect the ignition lead ends with AN-4060 Protectors. Install protective plugs P/N 22671 in bottom spark plug holes. Using a common garden sprayer or equivalent, spray atomized preservative oil that meets MIL-P-46002, Grade 1, at room temperature through upper spark plug hole of each cylinder with the piston at bottom dead center position. Rotate crankshaft as opposite cylinders are sprayed. Stop crankshaft with none of the pistons at top dead center.
4. Re-spray each cylinder. To thoroughly cover all surfaces of the cylinder interior move the nozzle or spray gun from the top to the bottom of the cylinder.
5. Install dehydrator plugs MS27215-1 or -2 in each of the upper spark plug holes. Make sure each plug is blue in color when installed.


**NOTE...**

If the engine is not returned to flyable status on or before the 90-day expiration, it must be preserved in accordance with "Indefinite Storage" procedures in this document.

**INDEFINITE STORAGE (Aircraft that are not flown for 90 days)**

**PREPARATION FOR STORAGE**

1. Remove oil sump drain plug and drain oil. Replace drain plug, torque and safety. Remove oil filter Install new oil filter torque and safety. Service engine to proper sump capacity with oil conforming to MIL-C-6529 Type II.
2. Perform a ground run-up. Perform a pre-flight inspection and correct any discrepancies. Fly the aircraft for one hour at normal operation temperatures.

ISSUED			REVISED			 <b>TELEDYNE CONTINENTAL MOTORS</b> An Allegheny Teledyne Company P.O. Box 90 Mobile AL 36601 • 334-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		2 of 4 SIL99-1	
03	25	99						

6. Attach a red "REMOVE BEFORE FLIGHT" streamer to each bag of desiccant. Place a bag of desiccant in the exhaust pipes and seal the openings.
7. Seal all engine openings exposed to the atmosphere using suitable plugs and covers.
8. Tag propeller in a conspicuous place with the following notation on the tag: DO NOT TURN PROPELLER - ENGINE PRESERVED - PRESERVATION DATE \_\_\_\_\_.

**INDEFINITE STORAGE INSPECTION PROCEDURES**

1. Aircraft prepared for indefinite storage must have the cylinder dehydrator plugs visually inspected every 15 days. The plugs must be changed as soon as they indicate other than a dark blue color. If the dehydrator plugs have changed color in one-half or more of the cylinders, all desiccant material on the engine must be replaced.
2. The cylinder bores of all engines prepared for indefinite storage must be re-sprayed with corrosion preventive mixture every 90 days.

**RETURNING AN ENGINE TO SERVICE AFTER STORAGE**


1. Remove seals and all desiccant bags.
2. Remove cylinder dehydrators and plugs or spark plugs from upper and lower spark plug holes.
3. Remove oil sump drain plug and drain the corrosion preventive mixture. Replace drain plug, torque and safety. Remove oil filter. Install new oil filter torque and safety. Service the engine with oil in accordance with the manufacturer's instructions.

**WARNING**

**To prevent possibility of serious bodily injury or death, before moving the propeller accomplish the following:**

- a. **Disconnect all spark plug leads.**
- b. **Verify magneto switches are connected to magnetos, that they are in the "OFF" Position and "P" leads are grounded.**
- c. **Throttle position "CLOSED."**
- d. **Mixture control "IDLE-CUT-OFF."**
- e. **Set brakes and block aircraft wheels. Insure that aircraft tie-downs are installed and verify that the cabin door latch is open.**
- f. **Do not stand within the arc of the propeller blades while turning the propeller.**

4. Rotate propeller by hand several revolutions to remove preservative oil.
5. Service and install spark plugs and ignition leads in accordance with the manufacturer's instructions.
6. Service engine and aircraft in accordance with the manufacturer's instructions.
7. Thoroughly clean the aircraft and engine. Perform visual inspection.
8. Correct any discrepancies.
9. Conduct a normal engine start.
10. Perform operational test in accordance with "Operational Inspection," of the applicable Maintenance Manual.
11. Correct any discrepancies.
12. Perform a test flight in accordance with airframe manufacturer's instructions.
13. Correct any discrepancies prior to returning aircraft to service.
14. Change oil and filter after 25 hours of operation.

ISSUED			REVISED			 <b>TELEDYNE CONTINENTAL MOTORS</b> <small>An Allegheny Teledyne Company P.O. Box 90 Mobile AL 36601 • 334-438-3411</small>	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		3 of 4 SIL99-1	
03	25	99						

INTENTIONALLY

LEFT

BLANK

ISSUED			REVISED			 <b>TELEDYNE CONTINENTAL MOTORS</b> An Allegheny Teledyne Company P.O. Box 90 Mobile AL 36601 • 334-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		4 of 4 SIL99-1	
03	25	99						

© 1999, TELEDYNE INDUSTRIES, Inc.



## **CONTINENTAL MOTORS TOP CARE<sup>SM</sup> CYLINDER WARRANTY**

This TopCare Cylinder Warranty provides special warranty coverage for cylinders and related parts shipped from Teledyne Continental Motors' plant on or after August 1, 1999 provided certain eligibility requirements are met. In the event that the eligibility requirements for this TopCare Cylinder Warranty are not met, the terms and conditions of the Teledyne Continental Motors (TCM) Aircraft Engine Part, Component & Accessory Warranty will apply.

- 1. Engines Eligible for TopCare Cylinder Warranty Coverage:** Any TCM aircraft engine meeting the eligibility requirements of Paragraph 2 of this warranty is eligible for coverage.
- 2. Eligibility Requirements:** This Top Care Cylinder Warranty applies only to cylinders and related parts shipped from TCM's plant on or after August 1, 1999. For purposes of this warranty, the cylinder and related parts are defined as the cylinder, cylinder intake and exhaust valves, valve inserts, valve guides, valve springs and their retaining parts, pistons, piston rings and related O-rings and gaskets. To be eligible for TopCare Cylinder Warranty coverage these parts must be installed together and used in combination with each other.

### **Required TopCare Health Check Inspections**

To be eligible for coverage under this TopCare Cylinder Warranty and to maintain that coverage the aircraft must be inspected at a Fixed Base Operator (FBO) facility in accordance with the TopCare Health Check Inspection set forth in the latest revision of TCM Service Information Directive 97-2 (SID 97-2) as follows:

- (A) For new aircraft:** Each new aircraft powered by a TCM engine shipped from TCM's plant on or after August 1, 1999 is covered by this TopCare Cylinder Warranty. To maintain coverage the aircraft must be inspected at least once per year in accordance with the TopCare Health Check inspection set forth in the latest revision of SID 97-2 and any discrepancies corrected at that time.
- (B) For aircraft in service:** For an aircraft in service in which a new or rebuilt aftermarket TCM engine shipped from TCM's plant on or after August 1, 1999 or for an aircraft having an engine in which a new cylinder supplied by TCM on or after August 1, 1999 is installed, the TopCare Health Check Inspection must be performed at time of installation and at least once per year thereafter in accordance with the TopCare Health Check Inspection set forth in the latest revision of SID97-2 and any discrepancies corrected at that time.

### **Enrollment and Documentation Requirements**

Each new aircraft powered by an engine that incorporates cylinders and related parts shipped from TCM's plant on or after August 1, 1999 is covered and no enrollment is required. For other than new aircraft, enrollment under the TopCare Cylinder Warranty must be accomplished by performing the initial TopCare Health Check Inspection at time of engine (or cylinder) installation and correcting any discrepancies at that time. The TopCare Health Checklist Form attached to the latest revision of SID97-2 must be completed, signed by the inspecting mechanic and a copy returned along with the TopCare Cylinder Warranty Enrollment Form attached to the latest revision of SID97-2 to:

Teledyne Continental Motors  
Attn: Warranty Services  
P.O. Box 90  
Mobile, Alabama 36601-0090

To maintain coverage under the TopCare Cylinder Warranty, the TopCare Health Check Inspection must be performed at least once per year and any discrepancies corrected at that time. The TopCare Health Checklist Form must be completed for each inspection, signed by the inspecting mechanic and retained by the owner for submittal to TCM with any claim under the TopCare Cylinder Warranty. Each required

TopCare Health Check Inspection must have been properly performed and documented on the TopCare Health Checklist Form. The TopCare Health Checklist Form for each inspection must be submitted to TCM with any claim under this TopCare Cylinder Warranty. Copies of work orders documenting the performance of the required TopCare Health Inspection and correction of any discrepancies must also be submitted to TCM upon request.

### **3. TopCare Cylinder Warranty Coverage:**

- (A)** For a period of twelve (12) months or one thousand (1000) hours of operation, whichever occurs first, after the warranty activation date, TCM will at its option repair or replace on an exchange basis any cylinder component or related part manufactured or supplied by it which within the applicable twelve (12) month or one thousand (1000) hour period is returned to a representative of TCM authorized to handle the engine in which the cylinder component or related part covered by this warranty is installed and which upon examination by TCM is found to be defective in material or workmanship. For cylinders installed in new or rebuilt engines, the warranty activation date is the date the engine is first operated for any use or the 180<sup>th</sup> day after TCM's invoice date, whichever occurs first. For cylinder components purchased as aftermarket replacement components, the warranty activation date is the date the cylinder is first operated for any use. TCM will pay for reasonable labor costs associated with repairs or replacements under paragraph 3(A) of this warranty and for "troubleshooting" costs associated with identifying the need for such repairs or replacements when coordinated through an authorized TCM representative. The amount of repair or replacement labor costs allowed will be in accordance with the latest revision of the warranty labor allowance schedule, Form X30552, published by TCM. The amount of "troubleshooting" costs allowed will be the reasonable costs under the circumstance of identifying the need for such repairs or replacements, but in no event will the "troubleshooting" costs allowed exceed fifteen percent (15%) of the labor costs associated with such repairs or replacements allowed by TCM. No "troubleshooting" cost allowance will be made where the need for repairs or replacements is identified in the course of overhaul, routine maintenance or on the basis of an obvious defect.
- (B)** After the expiration of the twelve (12) month period described in paragraph 3(A) and before the expiration of an additional twenty-four (24) month period or expiration of one thousand (1000) hours of operation, whichever occurs first, TCM will at its option repair or replace on an exchange basis any cylinder component or related part manufactured and supplied by it which is found to the satisfaction of TCM to be defective in material or workmanship.
- (C)** In the event that TCM elects to repair in the field, rather than replace any cylinder component or related part under paragraph 3(B) of this warranty, TCM will pay labor costs for the repair of the cylinder component or related part only. The amount of repair labor costs allowed will be in accordance with the latest revision of the warranty labor allowance schedule, Form X30522, published by TCM. TCM will not assume any responsibility for labor costs for the removal and/or re-installation of the cylinder component or related part, costs for "troubleshooting" or any other labor costs associated with repairs or replacements under paragraph 3(B) of this warranty.
- (D)** TCM reserves the right at its option to replace any defective cylinder component or related part with either a new or rebuilt cylinder component or related part.
- (E)** Repair or replacement of any cylinder component or related part under this warranty will not extend the period of warranty coverage set forth above.
- (F)** TCM will not assume any responsibility for transportation costs in connection with the repair or replacement of any cylinder component or related part under this warranty, except when such transportation has been expressly authorized by TCM. When authorized, transportation cost reimbursement for cylinder components will be the actual surface freight cost or the currently published UPS surface rate schedule, whichever is less.
- (G)** This warranty applies only to cylinders in which parts manufactured or supplied by TCM or parts manufactured pursuant to an FAA Parts Manufacturer Approval have been used and nothing contained herein should be construed as a warranty by TCM of any cylinder or related part not manufactured or supplied by TCM. TCM accepts no responsibility for the failure of any cylinder or related part which it does not manufacture or supply or damage resulting from such failure.

- (H) This warranty also applies only to cylinders and related parts on which the installation, inspection, maintenance and operating instructions and recommendations contained in the appropriate operator's manual, overhaul manual and applicable service bulletins have been complied with. Performance of recommended inspections and maintenance must be documented by appropriate logbook entries and a copy of the logbook must accompany any cylinder and related part being returned for warranty consideration.
- (I) This warranty does not apply to any cylinder or related part manufactured or supplied by TCM which has been subject to misuse, neglect or accident or which has been installed, repaired, maintained or altered in any way that in the judgment of TCM has adversely affected the condition of the engine or which has been operated beyond factory recommendations (such as, but not limited to RPM, temperature, manifold pressure, fuel flow and proper system adjustment).
- (J) TCM will not be responsible for repair or replacement of cylinder components or parts damaged or worn as a result of corrosion, pre-ignition/detonation, operation with non-calibrated engine gauges, improper fuel system adjustment, non-TCM approved fuel and oil grades or additives and installation of parts, components or accessories that alter the engines' original type design.
- (K) The provisions of this warranty do not apply to normal maintenance service or to the replacement of normal service items. This warranty does not cover any costs related to the performance of the TopCare Health Check Inspection.
- (L) TCM reserves the right to change any part specifications or prices without incurring any responsibility with regard to engines or parts previously sold or replaced.
- (M) THIS WARRANTY IS A WARRANTY TO REPAIR OR REPLACE AND NOT A WARRANTY OF THE CONDITION OR FUTURE PERFORMANCE OF THE PRODUCTS WHICH IT COVERS. THERE ARE NO OTHER WARRANTIES, EXPRESSED OR IMPLIED, SPECIFICALLY, BUT WITHOUT LIMITATION, THERE ARE NO IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. IN NO EVENT WILL TCM BE RESPONSIBLE FOR ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING OUT OF ANY DEFECT IN ANY CYLINDER OR RELATED PART, ARISING OUT OF THE FAILURE OF ANY CYLINDER OR RELATED PART TO OPERATE PROPERLY, OR ARISING OUT OF ANY BREACH OF THE WARRANTY MADE HEREIN. No person is authorized to give any other warranty or to assume any additional obligation or liability on behalf of TCM.



**CONTINENTAL MOTORS**  
Mobile, Alabama 36601





## **CONTINENTAL MOTORS PLATINUM ENGINE WARRANTY**

Each Platinum aircraft engine shipped from Teledyne Continental Motors' plant on or after August 1, 1999 is warranted as follows:

1. (a) For a period of twenty-four (24) months or until expiration of the recommended Time Between Overhaul (TBO) of the engine covered by this warranty, whichever occurs first, after the warranty activation date Teledyne Continental Motors (TCM) will at its option repair or replace on an exchange basis any engine, component or part manufactured or supplied by it which within the applicable twenty-four (24) month or TBO period is returned to a TCM representative authorized to handle the engine covered by this warranty and which upon examination is found to the satisfaction of TCM to be defective in material or workmanship. The warranty activation date is the date the engine is first operated for any use or the 180th day after TCM's invoice date, whichever occurs first.

(b) TCM will pay for reasonable labor costs associated with repairs or replacements under paragraph 1(a) under this warranty and for "troubleshooting" costs associated with identifying the need for such repairs or replacements when coordinated through an authorized TCM representative. The amount of repair and replacement labor costs allowed will be in accordance with the latest revision of the warranty labor allowance schedule, Form X30552, published by TCM. The amount of "troubleshooting" costs allowed will be the reasonable costs under the circumstances of identifying the need for such repairs or replacements, but in no event will the "troubleshooting" costs allowed exceed fifteen percent (15%) of the labor costs associated with such repairs or replacements allowed by TCM. No "troubleshooting" cost allowance will be made where the need for repairs or replacements is identified in the course of overhaul, routine maintenance or on the basis of an obvious defect.

(c) TCM will pay transportation costs in connection with the repair or replacement of any engine, component or part found to the satisfaction of TCM to be defective in material or workmanship under paragraph 1(a) of this warranty. The engine, component or part must be shipped prepaid to the repair facility designated by TCM. Transportation cost reimbursements for engines will be the actual surface freight charge or \$500.00, whichever is less. Engines must be described on the bill of lading as follows: "Internal combustion engine, other than Radial Cyl RVNX \$5.00". Transportation cost reimbursement for components or parts will be the actual surface freight charge for shipment of the component or part or the currently published UPS surface rate schedule, whichever is less.

2. (a) After the expiration of the applicable twenty-four (24) month period described above and before the expiration of an additional thirty-six (36) month period or expiration of the applicable recommended TBO for the engine covered by this warranty, whichever occurs first, TCM will, except as excluded below, at its option repair or replace on an exchange basis any component or part manufactured or supplied by it which is found to the satisfaction of TCM to be defective in material or workmanship. During this period TCM reserves the right at its option to replace the defective component or part with either a new or rebuilt engine or part. During this period TCM will not assume any responsibility for the repair or replacement of engine accessories, i.e. parts which have been purchased by TCM from a manufacturer as a complete and finished unit and included in the assembly of an engine without altering the unit, including, but not limited to Unison® magnetos and harnesses, Precision Airmotive Corporation® carburetors and fuel controls, Electrosystems® starters and alternators and Alliedsignal® and Consolidated Fuel Systems® turbochargers. During this period such engine accessories will be subject to such warranty coverage as may be provided by their manufacturer.

(b) In the event that TCM elects to repair in the field, rather than replace, any component or part under paragraph 2(a) of this warranty, TCM will pay labor costs for the repair of the component or part only. The amount of repair labor costs allowed will be in accordance with the latest revision of the warranty labor allowance schedule, Form X30552, published by TCM. TCM will not assume any

responsibility for labor costs for the removal and/or re-installation of the engine or part, costs associated with "troubleshooting" or any other labor costs associated with repairs or replacements under paragraph 2(a) of this warranty.

(c) TCM will not assume any responsibility for transportation costs associated with repairs or replacements under paragraph 2(a) of this warranty.

3. The coverage under this warranty applicable to cylinder assemblies and related parts shall be subject to the terms, conditions and limitations set forth in the applicable TCM TopCare<sup>SM</sup> Cylinder Warranty.
4. Repair or replacement of any engine or part under this warranty will not extend the period of warranty coverage set forth above.
5. This warranty applies only to engines in which parts manufactured or supplied by TCM or parts manufactured pursuant to an FAA Parts Manufacturer Approval have been used and nothing contained herein should be construed as a warranty by TCM of any engine or part not manufactured or supplied by TCM. TCM accepts no responsibility for the failure of any engine or part which it does not manufacture or supply or damage resulting from such damage.
6. This warranty applies only to engines which have been installed, inspected and maintained in accordance with the instructions for continued airworthiness, including compliance with all applicable service bulletins, issued by TCM, the aircraft manufacturer or any accessory or component manufacturer. Performance of recommended inspections and maintenance must be documented by appropriate logbook entries and the logbook must accompany any engine being returned for warranty consideration.
7. This warranty does not apply to any engine, component or part manufactured or supplied by TCM which (1) has been subject to misuse, neglect or accident; (2) has been installed, repaired, maintained or altered in any way that in the judgment of TCM has adversely affected the condition of the engine; (3) has been operated inconsistent with TCM and aircraft manufacturer recommendations and limitations (such as, but not limited to engine RPM, temperature, manifold pressure, fuel flow and proper system adjustment) or (4) has been changed from its original FAA certificated configuration.
8. TCM will not be responsible for repair or replacement of any engine, component or part damaged or worn as a result of corrosion, pre-ignition/detonation, operation with non-calibrated engine gauges, improper fuel system adjustment, non-TCM approved fuel and oil grades or additives or installation of parts, components or accessories that alter the engine's original type design.
9. The provisions of this warranty do not apply to normal maintenance service (such as engine tune-ups, adjustments, inspections, engine or component overhaul resulting from time between overhaul (TBO) recommendations, etc.) or to the replacement of normal service items (such as spark plugs, filters, hoses, belts, etc.).
10. TCM reserves the right to change any engine or part specifications or prices without incurring any responsibility with regard to engines or parts previously sold or replaced.
11. THIS WARRANTY IS A WARRANTY TO REPAIR OR REPLACE AND NOT A WARRANTY OF THE CONDITION OR FUTURE PERFORMANCE OF THE PRODUCTS WHICH IT COVERS. THERE ARE NO OTHER WARRANTIES, EXPRESSED OR IMPLIED, SPECIFICALLY, BUT WITHOUT LIMITATION, THERE ARE NO IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. IN NO EVENT WILL TCM BE RESPONSIBLE FOR ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING OUT OF ANY DEFECT IN ANY ENGINE OR PART, ARISING OUT OF THE FAILURE OF ANY ENGINE OR PART TO OPERATE PROPERLY, OR ARISING OUT OF ANY BREACH OF THE WARRANTY MADE HEREIN. No person is authorized to give any other warranty or to assume any additional obligation or liability on behalf of TCM.



**CONTINENTAL MOTORS**

Mobile, Alabama 36601

©1999, Teledyne Industries, Inc.

X30683 8/99

Printed in U.S.A.

TCM Engine Model	IO-550N42B
TCM Serial#	689951
Test Document	TH-3215 Rev G
Software Release#	1.98, 05/13/04
Start Time	8/23/06, 10:06:14
Accepted Time	8/23/06, 12:02:00
Cell# & Operator	8, 29274
Sea Level Power	310 HP @ 2700 Prop RPM
Vapor Pressure	0.88 in HG
Temp, Wet Baro	88.18 F, 30.07 in HG

# Teledyne Continental Motors

## Aircraft Engine Standard Acceptance

### Test Log

Test Club#	C5108A
Rqrd Pitch	20° ±.5°
Actual Pitch	20°
Mixture Check	Pass
Alternator Check	PASS

Mag Data	Required	Actual
Eng Speed Both	2100	2102
Eng Speed Right	N/A	2042
Right Mag Drop	150	60
Eng Speed Left	N/A	2046
Left Mag Drop	150	56
Mag Drop Spread	50	4
Fuel Flow (Ref.)	62	70

**Note: Magneto check between Run 2 & 3**

Run Information	Run 1	Run 2	Run 3	Run 4	Run 5	Run 6	Run 7	Run 8
Time Of Day	10:10:48	10:12:02	10:15:38	10:44:35	10:53:28	11:07:15	11:39:43	11:54:51
Run Time Rqd (MM:SS)	01:00	01:00	01:00	10:00	10:00	01:00	10:00	05:00
Run Time	01:00	01:00	01:13	10:00	10:00	01:00	10:00	05:00
Prop Speed Rqd (RPM)	1175-1225	1575-1625	2425-2475	2736-2786	2500-2525	575-625	2500-2525	2502-2527
Prop Speed	1186	1621	2448	2766	2511	611	2511	2513
Manifold Press Rqd (inHg)	N/A	N/A	N/A	26.2-29.2	N/A	18.5 MAX	N/A	N/A
Manifold Press	11.1	13.1	22.4	27.9	23.3	12.4	23.3	23.0
Turbo Dis Press Rqd (inHg)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Turbo Dis Press	29.2	29.2	29.2	29.1	29.1	29.1	29.1	29.1
Fuel Flow Rqd (lb/hr)	N/A	N/A	N/A	154.3-164.3	108.7-124.7	N/A	N/A	N/A
Fuel Flow	21.7	37.1	106.4	159.1	115.0	7.5	113.0	111.4
Nozzle Press Rqd (PSID)	N/A	N/A	N/A	20.9-21.5	12.6-13.8	N/A	N/A	N/A
Nozzle Press	4.9	5.5	12.5	21.5	13.8	4.0	13.6	13.4
Fuel Pump Press Rqd (PSIG)	N/A	N/A	N/A	30.0 REF	N/A	8.0-10.0	N/A	N/A
Fuel Pump Press	15.4	19.2	28.6	32.9	31.0	10.0	30.3	30.3
Fuel Temp Rqd (°F)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Fuel Temp	67	64	61	64	66	71	66	67
Ambient Temp Rqd (°F)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Ambient Temp	88	88	88	91	90	88	90	91
Eng Inlet Oil Temp Rqd (°F)	90-240	120-240	165-240	180-240	165-240	140-240	165-240	165-240
Eng Inlet Oil Temp	109	124	170	190	201	197	170	174
Eng Oil Press Rqd (PSIG)	30.0 MIN	30.0 MIN	30.0 MIN	46.1-57.1	30.0 MIN	13.1 MIN	30.0 MIN	30.0 MIN
Eng Oil Press	51.0	54.9	52.7	49.3	44.5	24.0	53.8	50.0
Min Cylinder Temp Rqd (°F)	150 MIN	175 MIN	250 MIN	250 MIN	250 MIN	N/A	250 MIN	250 MIN
Max Cylinder Temp Rqd (°F)	460 MAX	460 MAX	460 MAX	460 MAX	460 MAX	460 MAX	460 MAX	460 MAX
Cylinder 1 Temp	169	196	323	388	395	254	334	322
Cylinder 2 Temp	184	228	350	418	428	246	333	323
Cylinder 3 Temp	184	216	310	355	354	244	285	281
Cylinder 4 Temp	186	226	322	361	370	258	298	296
Cylinder 5 Temp	186	216	305	360	353	239	306	295
Cylinder 6 Temp	155	185	250	279	280	201	250	250
Collar Press Differential Rqd (PSID)	N/A	N/A	N/A	14.3 MAX	N/A	N/A	N/A	N/A
Collar Press Differential	6.0	3.4	2.2	2.1	1.9	0.9	2.6	2.1



**Teledyne Continental Motors, Inc.**  
A Teledyne Technologies Company

## Engine Component Information Sheet

Printed: 08/23/2006

Serial: 689951	Assembled: 08/22/2006
Spec: I0550N42B	Shipped:
New/Rebuilt: (NEW)	Packed: 08/23/2006

**Customer Name:** CIRRUS DESIGN CORPORATION

**Shipping Address:**

Component	Serial Number	Component	Serial Number
CAMSHAFT	Z06GA159	OIL COOLER	F06-4772-452
CRANKSHAFT	N06FA325	CYLINDER-1	AC06GA361
CRANKCASE	R06EA565	CYLINDER - 2	AC06FA098
CONNROD	AE06FA627	CYLINDER - 3	AC06FC058
CONNROD	AE06FA605	CYLINDER - 4	AC06EC619
CONNROD	AE06FA615	CYLINDER - 5	AC06FC104
CONNROD	AE06FA584	CYLINDER - 6	AC06GA305
CONNROD	AE06FA583	NOZZLE - 1	1234
CONNROD	AE06FA826	NOZZLE - 2	2234
L MAGNETO	D06HA172	NOZZLE - 3	3239
R MAGNETO	D06HA174	NOZZLE - 4	4236
FUEL PUMP	B06HA167	NOZZLE - 5	5236
MANIFOLD VALVE	C06HA175	NOZZLE - 6	6229
METERING UNIT	A06HA171	PSTN WGT	WJ
STARTER	06 144 0032		
ALTERNATOR	006HA099		

**Pack Inspection Stamp**



All of the information provided herein is subject to verification by the user. Teledyne Continental Motors, Inc. makes no representation or warranty concerning the accuracy or completeness of the information and assumes no responsibility with respect thereto.




**Teledyne Continental Motors, Inc.**  
 A Teledyne Technologies Company  
 P.O. Box 90 - Mobile, Alabama 36601  
 www.tcmlink.com

# ENGINE WARRANTY REGISTRATION

This is your **ENGINE WARRANTY/RUST** and **CORROSION AWARENESS PROGRAM REGISTRATION** form. It is essential that it be properly completed and returned to TCM Warranty Department immediately. This will expedite processing of the claim should your engine require repair or replacement as provided in the appropriate warranty policy. The engine owner can register on-line for free product and service information. Visit our web site at [www.tcmlink.com](http://www.tcmlink.com) or contact Customer Service at 1-888-826-5465.

**PLEASE COMPLETE AND RETAIN FOR OWNER'S RECORD**



**Teledyne Continental Motors, Inc.**  
 A Teledyne Technologies Company

OWNER'S NAME \_\_\_\_\_

OWNER'S ADDRESS \_\_\_\_\_

CITY, STATE, ZIP \_\_\_\_\_

COUNTRY \_\_\_\_\_ TELEPHONE \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Engine Model \_\_\_\_\_ Serial # \_\_\_\_\_

Date of Installation \_\_\_\_\_ Tach Time \_\_\_\_\_

Aircraft Model \_\_\_\_\_ Serial # \_\_\_\_\_


Year Manufactured \_\_\_\_\_ Total Airframe Time \_\_\_\_\_

What Engine is being replaced? \_\_\_\_\_

Serial # \_\_\_\_\_ Model \_\_\_\_\_

Hours \_\_\_\_\_

**PLEASE COMPLETE AND RETURN TO TCM IMMEDIATELY TO REGISTER WARRANTY**



**Teledyne Continental Motors, Inc.**  
 A Teledyne Technologies Company

OWNER'S NAME \_\_\_\_\_

OWNER'S ADDRESS \_\_\_\_\_

CITY, STATE, ZIP \_\_\_\_\_

COUNTRY \_\_\_\_\_ TELEPHONE \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Engine Model \_\_\_\_\_ Serial # \_\_\_\_\_

Date of Installation \_\_\_\_\_ Tach Time \_\_\_\_\_

Aircraft Model \_\_\_\_\_ Serial # \_\_\_\_\_

Year Manufactured \_\_\_\_\_ Total Airframe Time \_\_\_\_\_

What Engine is being replaced? \_\_\_\_\_

Serial # \_\_\_\_\_ Model \_\_\_\_\_

Hours \_\_\_\_\_

**Owners Validation Of Engine Preservation For Active And Stored Aircraft.**

I certify that I have read and understand the information provided in the latest revision of TCM service information letter SIL 99-1.

SIGNATURE \_\_\_\_\_

Attn: Warranty Department



NO POSTAGE  
NECESSARY  
IF MAILED  
IN THE  
UNITED STATES

**BUSINESS REPLY MAIL**  
FIRST-CLASS MAIL PERMIT NO. 1369 MOBILE, AL

POSTAGE WILL BE PAID BY ADDRESSEE



**TELEDYNE CONTINENTAL MOTORS  
PO BOX 90  
MOBILE AL 36601-9985**



## SERVICE INFORMATION DIRECTIVE

Compliance Will Enhance Safety, Maintenance or Economy Of  
Operation

SID05-7

Technical Portions FAA  
Approved

**SUBJECT:** Teledyne Continental Motor's (TCM) Position-Tuned  
Fuel Injection Nozzles

**PURPOSE:** To Provide Installation Instructions and Instructions For Continued  
Airworthiness for TCM Position-Tuned Fuel Injection Nozzles

**COMPLIANCE:** At any time TCM Position-Tuned Fuel Injection Nozzles are initially installed  
or when removal is required for service procedures or routine cleaning.

## MODELS


**AFFECTED:** All Fuel Injected Engines

**GENERAL**

TCM fuel nozzles have traditionally been matched to provide equal fuel flow to each cylinder. All nozzles are carefully flow calibrated to give precise metering of fuel flow with respect to fuel pressure. Fuel nozzles are now being produced in additional intermediate sizes, which allow smaller changes to be made in fuel flow. Identification of the new intermediate-flow nozzle is made by combining the flow letter designations of the nozzles one size smaller and one size larger than the new nozzle. (For example: 12D, 12DE, 12E, etc.)


Within the constraints of engine installations and variations in the design of engine induction systems, small differences in airflow can occur within the cylinders on an engine. The variations are small and the resultant changes in air/fuel ratio do not have a significant effect on the power produced in each individual cylinder. TCM's latest engine models, such as the IO-360-ES, IO-550-N, TSIO-520-BE, TSIO-550-B,C and others, feature tuned induction systems which improve the balance of airflow to the cylinders.

The capability exists on ALL engine models to further match the air/fuel ratio between cylinders by carefully modifying the fuel flow between each cylinder in small increments while maintaining the correct total fuel flow. For this purpose TCM has developed "position-tuned" fuel nozzle systems, which match injector flow to each individual cylinder's airflow while maintaining the correct total fuel flow. An automated test method was created to measure and evaluate the fuel flow range between the first and the last cylinder EGT peaks as the mixture was leaned from full rich at cruise operating conditions. Based on the actual fuel flow at each cylinder's peak EGT, individual nozzle flows were changed to align the peaks. The process can yield smaller cylinder-to-cylinder air/fuel ratio variations at selected engine settings. This assures that each cylinder is operating at the same air/fuel ratio in cruise conditions while maintaining acceptable air/fuel ratios at other operating points.

ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		1 of 7	
06	24	2005				SID05-7		

## INSTALLATION INSTRUCTIONS


- 1) In accordance with the airframe manufacturer's instructions, remove cowling and any airframe accessories that may obstruct access to the fuel nozzles.
- 2) Turn the aircraft fuel selector to the off position.
- 3) Loosen and remove the fuel injection lines from the existing fuel nozzles.
- 4) On turbocharged engine models, loosen fuel nozzle sleeve assembly nuts from the upper deck reference tubes and remove the metal washer, the rubber washer and the sleeve assembly from each nozzle. Retain the metal washer and the sleeve assembly for re-use. Discard the rubber washer.
- 5) Loosen and remove the fuel nozzles from each cylinder.




**CAUTION . . .** Never use teflon tape on fluid fittings or fuel nozzles.

**Figure 1. General Antiseize Lubricant Application Typical Fuel Nozzle Shown**


- 6) Remove the TCM Position-Tuned Fuel Nozzles from their packages. Inspect each nozzle for debris to avoid possible nozzle restriction after installation. Visually inspect each nozzle jet orifice to verify that it is open and contains no restriction. If cleaning is required, the Maintenance Instructions contained in this bulletin must be followed.
- 7) Apply a thin film of anti-seize compound, TCM P/N 646943 or Loctite 76732, to the large threaded end of each nozzle assembly. Reference Figure 1 for proper installation of the anti-seize compound to the nozzle assembly.
- 8) Each TCM Position Tuned nozzle is identified as to cylinder position and nozzle size, reference Figure 2 for cylinder arrangement on the engine crankcase and Figure 3 for nozzle position marking.

ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		2 of 7	
06	24	2005				SID05-7		







**Figure 2. Cylinder arrangement as installed on the engine.**




**Figure 3. Nozzle Position Marking**


ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		3 of 7	
06	24	2005				SID05-7		



**FIGURE 4. Typical Turbo-Charged Injector Installation**




**Figure 5. Typical Nozzle Assemblies For Normally-Aspirated Engines**

ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		4 of 7	
06	24	2005					SID05-7	

- 9) Install each nozzle in the fuel nozzle port of the appropriate cylinder finger tight to insure that it does not cross-thread.
- 10) Torque each nozzle to 55-65 inch pounds using a properly calibrated torque wrench.
- 11) For turbo-charged engine models, reinstall nozzle sleeve assemblies ensuring new P/N 630979-9 O-rings are used. Tighten the nut to the upper deck reference tube finger tight to set the seal between the nut and the male connector, then tighten an additional 3/4 to 1 turn. Install a new P/N 640612 rubber washer and the previously retained metal washer on each nozzle, reference figure 4.
- 12) Reinstall each fuel injection line to the appropriate nozzle and tighten to a torque value of 40-45 inch pounds using a properly calibrated torque wrench.

**CAUTION...** Do not apply any type of thread lubricant or sealant to the fuel injection line to nozzle junction.

- 13) Clean each fuel injection line at the location of the identification label application with acetone, reference figure 6. With this area clean and dry, apply an identification label P/N 655303 to each fuel injection line and wrap the label around the fuel injection line to form a flag as indicated in figure 6. An identification label may also be applied to the valve rocker cover in a conspicuous location in addition to the fuel injection line.




**Figure 6. Label Application**

- 14) Turn the aircraft fuel selector to the "ON" position.
- 15) Perform a complete fuel system leak check in accordance with aircraft manufacturer's maintenance instructions prior to engine operation.

**WARNING**

**Over priming can cause a flooded intake resulting in a hydraulic lock condition and subsequent engine damage or failure. If the engine is over primed, or flooded, make sure that all fuel has drained from the intake and cylinders prior to attempting engine start.**

ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		5 of 7	
06	24	2005				SID05-7		

- 16) Perform the engine fuel system verification in accordance with the latest revision of SID97-3.
- 17) Reinstall all airframe-supplied accessories and cowlings in accordance with the airframe manufacturer's instructions.

**MAINTENANCE INSTRUCTIONS**


NOTE . . . This bulletin contains the Manufacturer's Instructions for Continued Airworthiness for Position Tuned Nozzle Assemblies as required by FAR43.13.

All fuel nozzles must be removed annually or every 300 hours, whichever occurs first, for inspection and cleaning as follows:

- 1) In accordance with the airframe manufacturer's instructions, remove cowling and any airframe accessories that may obstruct access to the fuel nozzles.
- 2) Turn the aircraft fuel selector to the off position.
- 3) Loosen and remove the fuel injection lines from the fuel nozzles.
- 4) On turbo-charged engine models, loosen fuel nozzle sleeve assembly nuts from the upper deck reference tubes and remove the metal washer, the rubber washer and the sleeve assembly from each nozzle. Retain the metal washer and the sleeve assembly for re-use. Discard the rubber washer.
- 5) Loosen and remove the fuel nozzles from each cylinder.
- 6) Clean each nozzle by soaking in lacquer thinner, MEK or acetone for several hours. Wipe clean the exterior of the nozzle with a lint-free cloth. Dry the nozzle interior with dry compressed air. Visually inspect the nozzle jet orifice to verify that it is open with no obstructions.
- 7) If the nozzle jet orifice is obstructed and cannot be cleaned by solvent action as noted in step 6 above, the nozzle must be replaced.

***CAUTION . . . Never attempt to clear or clean a nozzle jet orifice restriction by mechanical means. This can damage the orifice and affect the flow rate of the nozzle. Any nozzle which has been cleaned by mechanical means must be replaced.***

- 8) Once each nozzle has been cleaned and inspected, they should be reinstalled in accordance with the following:
- 9) Apply a thin film of anti-seize compound, TCM P/N 646943 or Loctite 76732, to the large threaded end of each nozzle assembly. Reference Figure 1 for proper installation of the anti-seize compound to the nozzle assembly.
- 10) Each TCM Position Tuned nozzle is identified as to cylinder position and nozzle size, reference Figure 2 for cylinder arrangement on the engine crankcase and figure 3 for nozzle position marking.

ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		6 of 7	
06	24	2005				SID05-7		

- 11) Install each nozzle in the fuel nozzle port of the appropriate cylinder finger tight to insure that it does not cross-thread.
- 12) Torque each nozzle to 55-65 inch pounds using a properly calibrated torque wrench.
- 13) For turbo-charged engine models, reinstall nozzle sleeve assemblies ensuring new P/N 630979-9 O-rings are used. Tighten the nut to the upper deck reference tube finger tight to set the seal between the nut and the male connector, then tighten an additional 3/4 to 1 turn. Install a new P/N 640612 rubber washer and the previously retained metal washer on each nozzle, reference figure 4.
- 14) Reinstall each fuel injection line to the appropriate nozzle and tighten to a torque value of 40-45 inch pounds using a properly calibrated torque wrench.


**CAUTION...** *Do not apply any type of thread lubricant or sealant to the fuel injection line to nozzle junction.*

- 15) Turn the aircraft fuel selector to the "ON" position.
- 16) Perform a complete fuel system leak check in accordance with aircraft manufacturer's maintenance instructions prior to engine operation.

**WARNING**

**Over priming can cause a flooded intake resulting in a hydraulic lock condition and subsequent engine damage or failure. If the engine is over primed, or flooded, make sure that all fuel has drained from the intake and cylinders prior to attempting engine start.**

- 17) Perform the engine fuel system verification in accordance with the latest revision of SID97-3.
- 18) Reinstall all airframe-supplied accessories and cowlings in accordance with the airframe manufacturer's instructions.

ISSUED			REVISED			 <b>Teledyne Continental Motors, Inc.</b> <small>A Teledyne Technologies Company</small> P.O. Box 90 Mobile Alabama • 251-438-3411	PAGE NO	REVISION
MO	DAY	YEAR	MO	DAY	YEAR		7 of 7	
06	24	2005				SID05-7		

PROP LOGBOOK

# Aircraft Engine Test Verification

This document verifies that the engine model listed below has satisfactorily completed all testing listed below in accordance with TCM standard engine testing specifications as approved by the FAA.

Engine Model

IO550 N42B

Engine Serial Number

689951

**Testing Completed**

Standard Acceptance Test:

Date of Completion

8-23-06

Test Operator

58  
73




Teledyne Continental Motors, Inc.

Form No 98344

A Teledyne Technologies Company

## **IMPORTANT - Comply with the TopCare<sup>SM</sup> Cylinder Program requirements to be eligible for:**

- **Industry leading warranty**  
- **3 Year / 1000 Hours\***
- **Improved Cylinder Service Life**



### **How to Comply:**

- 1-Have the TopCare Health Check<sup>SM</sup> performed as prescribed in the latest revision of TCM Service Information Directive SID97-2.
- 2-Register by submitting the TopCare Cylinder Warranty Enrollment Form & initial TopCare Health Check form to TCM in accordance with the latest revision of SID97-2.
- 3-Perform the TopCare Health Check on an annual basis to maintain coverage and optimum cylinder service life.

For complete TopCare Program information, go to <http://www.tcmlink.com/topcare/index.html> and download a free copy of the latest revision of TCM Service Information Directive SID97-2. Go to <http://www.tcmlink.com/warranty.html> to obtain a free copy of the TopCare Cylinder Warranty. You can also request this information be mailed to you by contacting the Aviator Services Desk at 1-888-826-5465.

NOTICE: Failure to register in, or failure to meet the eligibility requirements of, the TopCare program will render your cylinder warranty coverage to be the same as the Teledyne Continental Motors (TCM) Aircraft Engine Part, Component & Accessory Warranty which provides 12 Months/500 hours (No Labor).

\*3 Year/1000 Hour Warranty Consists of 1 Year Parts & Labor Coverage. 2nd & 3rd Year Parts Only Coverage.



**CONTINENTAL MOTORS**

TCM NO: CYL0401



**The points of the TopCare Health Check are:**

- Cylinder Differential Compression Check And Trend Monitoring – When made and recorded for trend monitoring purposes you can identify cylinder leakage rates and the source of the leakage. This test can also be used as a gauge to determine wearing of cylinder walls, ring surfaces and valve seats throughout the life of the engine.
- Cylinder Borescope Inspection, As Required – Your technician must examine the cylinder for the presence of rust and overall condition of the cylinder bore and the valve area.
- Oil Consumption Trend Monitoring – A good diagnostic tool that provides the indication of wear, or indication of the need for inspection or service.
- Oil Analysis Trend Monitoring – A tool used to monitor wear material and contaminants in the engine. For those engines with an established oil analysis profile, changes in iron, copper and other tracked materials can alert you to unusual wear trends and contaminants.
- Baffle Condition Inspection – Incorrect and improperly fitting baffles and baffle seals can contribute to premature cylinder removal caused by high cylinder and oil temperatures.
- Induction System Examination – Breathing in unfiltered air contains particulates which are abrasive to the engine, especially to the cylinder walls and ring faces.
- Cowling Inspection and Cowl Flap Operational Check – In addition to baffle conditions, other components that affect airflow through the cowling must be examined.
- Ignition System Inspection – Advanced magneto to engine timing can cause high cylinder head temperatures. Maintain magneto in accordance with published requirements
- Fuel System Setup – Engine operation and cooling are directly related to the correct set-up of the fuel system. Airflow is not enough to cool the engine during high-power operation and additional fuel is required to provide supplemental cooling.
- Verification Of Accuracy Of Engine Instrument Gauges – Use of inaccurate gauges can result in possible cylinder wear due to lean operation, pre-ignition, detonation, loss of power and sever engine damage or sudden engine stoppage.
- Flight Test – Test fly the aircraft with your mechanic after annual inspection. Your knowledge and increased awareness of correct engine operation can significantly influence the service life of your engine's cylinders and other components.

 **TELEDYNE CONTINENTAL MOTORS**

THE OIL PRESSURE ON THIS ENGINE WAS ADJUSTED DURING THE ENGINE ACCEPTANCE TEST AT THE FACTORY. ONLY MINOR ADJUSTMENTS MAY BE NECESSARY TO ASSURE THE PROPER INDICATION ON THE COCKPIT GAUGE.



FACTORY SETTINGS:

RPM 2700 OIL TEMP 190 OIL PRESSURE 49.3  
OIL PRESSURE PICK UP POINT: ENGINE INLET AT  
OIL COOLER

655313



## SENENICH PROPELLER SERVICE, INC.

---

### Propeller Logbook

McCauley	<input type="checkbox"/>
Hartzell	<input checked="" type="checkbox"/>
MT	<input type="checkbox"/>
Sensenich	<input type="checkbox"/>
Dowty	<input type="checkbox"/>
Hamilton Standard	<input type="checkbox"/>

INSTALLING AGENCY PLEASE NOTE:  
Recording of Propeller Total Time Since New (TTSN)  
is Required Per F.A.R. 91.417

Castler Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmore Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

# FAA LOGBOOK REGULATIONS

## 91.417 Maintenance records.

(a) Except for work performed in accordance with §§ 91.411 and 91.413, each registered owner or operator shall keep the following records for the periods specified in paragraph (b) of this section:

(1) Records of the maintenance, preventive maintenance, and alteration and records of the 100-hour annual, progressive, and other required or approved inspections, as appropriate, for each aircraft (including the airframe) and each engine, propeller, rotor, and appliance of an aircraft. The records must include:

(i) A description (or reference to data acceptable to the Administrator) of the work performed; and

(ii) The data of completion of the work performed; and

(iii) The signature, and certificate number of the person approving the aircraft for return to service.

(2) Records containing the following information:

(i) The total time in service of the airframe, each engine, each propeller, and each rotor.

(ii) The current status of life-limited parts of each airframe, engine, propeller, rotor, and appliance.

(iii) The time since last overhaul of all items installed on the aircraft which are required to be overhauled on a specified time basis.

(iv) The current inspection status of the aircraft, including the time since the last inspection required by the inspection program under which the aircraft and its appliances are maintained.

(v) The current status of applicable airworthiness directives (AD) including, for each, the method of compliance, the AD number, and revision date. If the AD involves recurring action, the time and date when the next action is required.

(vi) Copies of the forms prescribed by § 43.9(a) of this chapter for each major alteration to the airframe and currently installed engines, rotors, propellers, and appliances.

(b) The owner or operator shall retain the following records for the periods prescribed:

(1) The records specified in paragraph (a)(1) of this section shall be retained until the work is repeated or superseded by other work or for 1 year after the work is performed.

(2) The records specified in paragraph (a)(2) of this section shall be retained and transferred with the aircraft at the time the aircraft is sold.

(3) A list of defects furnished to a registered owner or operator under § 43.11 of this chapter shall be retained until the defects are repaired and the aircraft is approved for return to service.

**NOTE: Regulations are subject to revision at any date without notice.**

The manufacturers' FAA approved overhaul period for this propeller is 6 years/months or 2400 hours, whichever occurs first.

Limiting factors affecting time between overhaul (TBO)

Corrosion, internal

- Directly proportional to calendar time
- Unseen and potentially catastrophic

Corrosion-erosion, external

- Calendar time and operating environment
- Visible and easily corrected

Wear, Internal/External

- Function of hours in operation and types of flying, i.e., aerobatic much higher wear rates than pleasure.

Seal Life

- Deterioration and loss of resiliency affecting sealing property is proportionate to calendar time in service.
- Wear rates are commensurate to hours flown.

**IT IS STRONGLY RECOMMENDED ALL PROPELLERS MINIMUMLY RECEIVE AN INTERNAL CORROSION INSPECTION AND NEW SEALS AT INTERVALS NOT TO EXCEED SIX YEARS.**

# USE OF LOGBOOK

1. Proper maintenance of this logbook is the owner's responsibility. It is an important record designed for the owner's information and protection.
2. If the propeller is sold or installed on another aircraft, the logbook should be transferred **with the propeller**.
3. It is recommended that maintenance release tags and work orders be attached inside the back cover of this book. If a copy of the work order is not available, the repair station and work order numbers should be referenced in the logbook entry.



Propeller Model PHC-534E-1RF

Blade Model F7693DFB

Hub Serial No. FP4157B

Blade Serial No. 1 K28674

2 K28677

3 K28673

4 \_\_\_\_\_

5 \_\_\_\_\_

6 \_\_\_\_\_




# INSTALLATION HISTORY

Date	Aircraft Model & Registration No.	Engine Serial Number & Position

SOUTH COAST PROPELLER SERVICE, INC.  
 5750 DUROSE DRIVE, BESSEMER, AL 35022  
 205-426-7022  
 REPAIR STATION #S6PR302X

GOVERNOR DISASSEMBLED, CLEANED AND INSPECTED. MAJOR OVERHAULED. MAGNAFLUXED  
 PARTS AS REQUIRED, REASSEMBLED AND TESTED TO MANUFACTURER'S SPECIFICATIONS.

WORK ORDER # SR-6900  
 MODEL # C290D3R/T23  
 SERIAL # 03-0638  
 DATE 09/10/10

  
 JAMES M. GAITHER,  
 GENERAL MANAGER.









# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
<div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="width: 25%;"> <p><b>MODEL:</b> SR22 <b>S/N:</b> 2180 <b>REG. No:</b> N509SR</p> </div> <div style="width: 40%; text-align: center;"> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> <p style="margin: 0;">CORPORATE FLIGHT MANAGEMENT</p> </div> <p style="margin: 5px 0 0 0;">276 Doug Warpoole Road Smyrna, TN 37167 615.534.4600</p> </div> <div style="width: 25%;"> <p><b>DATE:</b> 5/5/2011 <b>HOBBS:</b> 2016.7 <b>TACH:</b> 1775.4</p> </div> </div>				
<b>Propeller S/N FP4157B</b>				
<p><b>Inspection:</b> -Complied with Annual Inspection IAW AMM 5-00.</p> <p><b>AD's:</b> -None due at this time.</p> <p><b>SB's</b> -None due at this time.</p> <p>The propeller identified above was inspected and repaired in accordance with the current Federal Aviation Regulations and is approved for return to service with only with respect to the work performed. Pertinent details of the work performed are on file at this repair station under Work Order №19961.</p>				
<p>Signed:  1196</p> <p>For: <b>Corporate Flight Management, Inc.</b>      <b>Certified Repair Station</b>      <b>FJTR920D</b>      Form CFM 007</p>				

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
			<b>ARAPAHOE AERO</b> 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 <b>N62CH Hartzell PHC-J3YF-1RF/F7693DFB S/N: FP4157B Total Time: 2547.7</b> <b>24 August 2011 Flight Hobbs: 1865.4 SPOH: 157.7 Calendar Time: 0 Years 9 Months</b> <b>100 Hour Inspection for Annual</b> completed this date using the Cirrus Design SR22 Maintenance Manual Inspection Form as a guide. Inspected propeller hub and blades. Dressed leading edges of blades and painted blade faces. AD's checked through Biweekly 2011-17. <b>I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.</b>  Scott S. Fisher A&P 3290363 w/o 30906	
			<b>ARAPAHOE AERO</b> 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 <b>N62CH Hartzell PHC-J3YF-1RF/F7693DFB S/N: FP4157B Total Time: 2626.6</b> <b>19 January 2012 Flight Hobbs: 1944.3 SPOH: 236.6 Calendar Time: 1 Year 2 Months</b> <b>100 Hour Inspection for Annual</b> completed this date using the Cirrus Design SR22 Maintenance Manual Inspection Form as a guide. Inspected propeller hub and blades. Dressed leading edges of blades and painted blade faces. AD's checked through Biweekly 2012-01. <b>I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.</b>  L. John Wells A&P 3221132 w/o 31469	

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
6-19-12	2803.3	413.3	Completed a 100hr inspection IAW Cirrus SR22 MM inspection guide. AD's checked through B-walk 2012-01. I certify that this propeller has been inspected IAW a 100 hour inspection and was determined to be in airworthy condition. J. Vanderpool AP 2817060	— END —



ROCKY MOUNTAIN  
AIRCRAFT SERVICES LLC  
11750 Airport Way Hanger B-12A  
Broomfield CO, 80021

Date: 10-26-2012  
Acraft Reg: N62CH  
Flight Tach: 2125.2  
TSMOH: 417.5  
**PROPELLER**

Performed an Annual/100 HR inspection in accordance with FAR 43 App (D) and Cirrus checklist. Inspected spinner and spinner bulkhead for cracks or defects. None found at this time. Dressed leading edges of propeller blades. Ground run and operational check is satisfactory at this time. A list of AD's may be found in aircraft records I certify that this propeller has been inspected in accordance with an Annual/100 HR inspection and has been determined to be in airworthy condition and is approved for return to service at this time.-----END-----

Justin C Parrow

A&P3083586IA



ROCKY MOUNTAIN  
AIRCRAFT SERVICES LLC

11750 Airport Way Hanger B-12A  
Broomfield CO, 80021

Date: 1-16-2014  
Acft Reg: N62CH  
Flight Tach: 2290.8  
TSMOH: 583.1  
**PROPELLER**

Authorized Signatures

Performed an Annual/100 HR inspection in accordance with FAR 43 App (D) and Cirrus checklist. Inspected spinner and spinner bulkhead for cracks or defects. None found at this time. Dressed leading edges of propeller blades. Ground run and operational check is satisfactory at this time. A list of AD's may be found in aircraft records I certify that this propeller has been inspected in accordance with an Annual/100 HR inspection and has been determined to be in airworthy condition and is approved for return to service at this time.-----END-----

Justin C Parrow

A&P3083586IA

PROP MODEL:  
PHC-J3YF-1RF  
PROP S/N: FP4157B  
REG. NO: N62CH  
WORK ORDER:  
3731-01-2015



**Houston Aviation Center, LLC**

12888 Hwy 6 S Ste 113  
Sugar Land, TX 77498 USA  
Phone: 281-494-5800

DATE: 2/4/2015  
A/C TSN: 2527.1  
PROP TT: 3209.4  
TSPOH: 819.4  
FLIGHTTIME: 2527.1

**Prop Entries**

(Flight Meter: 2527.1) Completed a 100 HR/Annual Inspection this date Ref. CDC SR22 AMM 5-20 and Hartzell Propeller Owner's Manual No. 115N. Inspected and dressed propeller blade leading edges. Checked blade track. Checked AD's thru BW 2015-02.... I certify that this Propeller has been inspected in accordance with a 100 HR/Annual Inspection and was determined to be in Airworthy condition.

**Maintenance Release**

The aircraft and/or component(s) on N62CH was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 3731-01-2015.

DATE: 2/4/2015

SIGNED:

Work Order: 3731-01-2015

Fouad Hussain, A&P: 3204861 IA

Printed by EBis 3 (datcomedia.com)















STAPLE MAINTENANCE RELEASE TAGS AND  
OTHER DATA TO THIS PAGE



**SENENICH PROPELLER SERVICE, INC.**

[www.sensenichpropellers.com](http://www.sensenichpropellers.com)

AD'S

<b>AD NOTES COMPLIANCE RECORD</b>
-----------------------------------

Airframe - Cirrus - SR22

2180

Engine - Teledyne Continental - IO-550-N

Propeller - Hartzell - PHC-J3YF-1

Appliance - Altimeters - United Instruments

Appliance - Ignition Switches - Bendix

Appliance - Magnetos - TCM (formerly Bendix) S-20 series

Appliance - Primary Flight Displays - Avidyne Corporation

Appliance - Safety Belts - AM Safe

Appliance - Transponder - GARMIN GTX 330

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
74-24-13	United Instrument altimeters	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
74-26-09	Bendix magnetos	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
76-07-12	Bendix switches	10/29/10 TAT1707.7	N/A per aircraft manufacture date		X	N/A	Corporate Flight Management FJTR920D
82-20-01	Bendix magnetos	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
86-05-02	United Instruments altimeters	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
87-17-06	AM Safe restraint system	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
88-03-06	Oil filter	10/29/10 TAT1707.7	N/A per engine manufacture date	X		N/A	Corporate Flight Management FJTR920D
91-19-03	Champion oil filter	10/29/10 TAT1707.7	N/A per engine manufacture date	X		N/A	Corporate Flight Management FJTR920D
93-08-17	Incorrect oil pick-up tube	10/29/10 TAT1707.7	N/A per engine manufacture date	X		N/A	Corporate Flight Management FJTR920D
93-10-02	Cylinder valve retainer	10/29/10 TAT1707.7	N/A per engine manufacture date	X		N/A	Corporate Flight Management FJTR920D
94-01-03 R2	Teledyne/Bendix magnetos	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
94-06-09	Teledyne/Bendix magnetos	10/29/10 TAT1707.7	N/A per aircraft manufacture date	X		N/A	Corporate Flight Management FJTR920D
94-17-13	Prop hub failure	10/29/10 TAT1707.7	N/A per propeller manufacture date		X	N/A	Corporate Flight Management FJTR920D
99-19-01	Crankshaft failure	10/29/10 TAT1707.7	N/A per engine manufacture date	X		N/A	Corporate Flight Management FJTR920D
2000-23-21	Fracture of the crankshaft connecting rod journal	10/29/10 TAT1707.7	N/A per engine manufacture date	X		N/A	Corporate Flight Management FJTR920D
2001-07-03	CORRECTION - Prevent propeller failure of the propellers returned to service by BASCO	10/29/10 TAT1707.7	N/A per propeller manufacture date	X		N/A	Corporate Flight Management FJTR920D
2001-25-03	Detect and replace understrength rivets in the elevator and rudder	10/29/10 TAT1707.7	N/A per airframe manufacture date	X		N/A	Corporate Flight Management FJTR920D
2002-21-02	Prevent loss of the self-locking retaining nut on the roll and yaw trim cartridges	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D



AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
2002-24-08	Prevent failure of the CAPS activation system in an emergency situation	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D
2004-08-10	Prevent loss of engine power	10/29/10 TAT1707.7	N/A no ECi cylinder installed	X		N/A	Corporate Flight Management FJTR920D
2005-01-19	Prevent interrogating aircraft from possibly receiving inaccurate replies	10/29/10 TAT1707.7	N/A per Garmin software version installed	X		N/A	Corporate Flight Management FJTR920D
2005-12-06	Prevent failure of the magneto impulse coupling assembly	10/29/10 TAT1707.7	N/A per engine model installed		X	N/A	Corporate Flight Management FJTR920D
2005-14-11	Prevent blade failure that could result in separation of a propeller blade	10/29/10 TAT1707.7	N/A per propeller never been serviced by Southern California Propeller Service of California.	X		N/A	Corporate Flight Management FJTR920D
2006-07-06	To detect, correct, and prevent damage to the fuel line and wire	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D
2006-19-10	To prevent the crew seats from folding forward during emergency landing	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D
2006-21-03	Prevent overheating damage to the brake caliper piston O-ring seals	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D
2007-14-03	To correct pick-up collar support fasteners of the CAPS	4/02/07 TAT237.4	Complied with AD by complying to SBA2X-95-10 with installation of kit P/N 70181-001.	X		N/A	Satair Maintenance Center Richard Bannister A&P 250257611
2007-16-10	To prevent the turbine rotor from separating from the shaft of the turbocharger due to a machining defect in the turbocharger compressor	10/29/10 TAT1707.7	N/A no turbocharger installed on this aircraft	X		N/A	Corporate Flight Management FJTR920D
2007-24-13	To prevent moisture from accumulating along the wing shear web where it may freeze in certain conditions	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D
2007-26-09	To prevent failure of the propeller blade from fatigue cracks in the blade shank radius	10/29/10 TAT1707.7	N/A per propeller blades S/N	X		N/A	Corporate Flight Management FJTR920D
2008-03-16	To prevent the possibility of jamming of the rudder-aileron interconnect system	10/31/07 TAT663.4	Complied with AD by complying with SB 2X-27-14R3 with the installation of kit P/N 70197-001	X		N/A	Satair Maintenance Center Richard Bannister A&P 250257677
2008-06-28	To prevent certain conditions from existing when PFDs display incorrect attitude, altitude, and airspeed information	10/29/10 TAT1707.7	See revision 1	X		N/A	Corporate Flight Management FJTR920D
2008-13-28	To prevent failure of the propeller hub	10/29/10 TAT1707.7	N/A per engine installed		X	N/A	Corporate Flight Management FJTR920D
2008-14-13	To prevent in-flight failure of the cabin door	2/07/08 TAT858.5	Complied with AD by complying with SB 2X-52-07R4 with installation of kit P/N 70186-004.	X		N/A	Satair Maintenance Center Richard Bannister A&P250257611
2009-05-05	To prevent certain conditions from existing when PFDs display incorrect attitude, altitude, and airspeed information	3/30/09 TAT1695.5	CW AD by inspecting PDF S/N 20146037 and complying with Avidyne SB 601-00006-096 paragraph 3.3. "PDF air data system performance verification test". No defects noted per 601-00006-096R1, no further action required.		X	N/A	Satair Maintenance Center, CRS# J4PR714Y Doug K. Bowling
2009-16-03	To prevent the separation of the cylinder head	10/29/10 TAT1707.7	N/A per cylinder manufacture installed		X	N/A	Corporate Flight Management FJTR920D
2009-26-01	To detect and correct anti-ice fluid distribution lines with improperly installed compression fittings	10/29/10 TAT1707.7	N/A per aircraft S/N	X		N/A	Corporate Flight Management FJTR920D

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
2010-11-04	To prevent excessive hydraulic lifter wear	10/29/10 TAT1707.7	N/A per Hydraulic lifters P/N 657077 and P/N 657088		X	N/A	Corporate Flight Management FJTR920D

MISC DOCS



U.S. Department of Transportation  
Federal Aviation Administration

## MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved  
OMB No. 2120-0020  
11/30/2007

Electronic Tracking Number

For FAA Use Only

**INSTRUCTIONS:** Print or type all entries. See Title CFR 43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. 44701). Failure to report can result in a civil penalty for each such violation (49 U.S.C. 46301(a)).

<b>1. Aircraft</b>	Nationality and Registration Mark N509SR	Serial No. 2180	
	Make Cirrus	Model SR22	Series
<b>2. Owner</b>	Name (As shown on registration certificate) Corporate Flight Management	Address (As shown on registration certificate) Address 276 Doug Warpoole Road	
		City <u>Smyrna</u> State <u>TN</u>	Zip <u>37167</u> Country <u>USA</u>

### 3. For FAA Use Only

4. Type		5. Unit Identification			
Repair	Alteration	Unit	Make	Model	Serial No.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	AIRFRAME	_____	(As described in item 1 above)	
<input type="checkbox"/>	<input type="checkbox"/>	POWERPLANT			
<input type="checkbox"/>	<input type="checkbox"/>	PROPELLER			
<input type="checkbox"/>	<input type="checkbox"/>	APPLIANCE	Type _____		
			Manufacturer _____		

### 6. Conformity Statement

<b>A. Agency's Name and Address</b>		<b>B. Kind of Agency</b>	
Name <u>Corporate Flight Management</u>		<input type="checkbox"/> U.S. Certificated Mechanic	<input type="checkbox"/> Manufacturer
Address <u>276 Doug Warpoole rd</u>		<input type="checkbox"/> Foreign Certificated Mechanic	<b>C. Certificate No.</b>
City <u>Smyrna</u> State <u>TN</u>		<input checked="" type="checkbox"/> Certificated Repair Station	<u>FJTR920D</u>
Zip <u>37167</u> Country <u>USA</u>		<input type="checkbox"/> Certificated Maintenance Organization	

**D.** I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.

Extended range fuel per 14 CFR Part 43 App. B <input type="checkbox"/>	Signature/Date of Authorized Individual _____	11/01/2010
--	--	------------

### 7. Approval for Return To Service

Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is  APPROVED  REJECTED

BY	FAA Fit. Standards Inspector	Manufacturer	Maintenance Organization	Person Approved by Canadian Department of Transport
	FAA Designee	<input checked="" type="checkbox"/> Repair Station	Inspection Authorization	Other (Specify)

Certificate or Designation No. FJTR920D	Signature/Date of Authorized Individual _____	11/01/2010
--	--	------------

**NOTICE**

*Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.*

**8. Description of Work Accomplished**

*(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)*

N509SR	11/01/2010
Nationality and Registration Mark	Date

A summary of the repaired done to the aircraft is as follows:

- Repaired damaged AFT floor section by replacing entire AFT floor section between AFT side of spar cover and FS 186 bulkhead per CDC repair deviation # R9793.
- Repaired LH fuselage Station 180 by resin injection as needed then installed repair plied and fully cured area per CDC repair deviation # R9793.
- Repaired RH fuselage Station 180 by resin injection as needed then installed repair plies and fully cured area per CDC repair deviation # R9793.
- Repaired damaged on RH wing and wing cuff at wing Station 165 by removing damaged cuff section, repairing wing leading edge, resin injecting top surface of wing, installing new section on wing cuff and covering replacement section of cuff with repair plies and covering top surface of wing with repair plies per CDC repair deviation # R9793.
- Repaired LH wing cuff leading edge located at Station 150, 164, 174 - 177, 181 - 183 and 195 by installing repair plies per CDC repair deviation # R9793.
- Repaired damage on LH wing lower surface at wing Station 150 by resin injection area and installing repair plies. Repair is fully cured. Work done per CDC repair deviation # R9793.

No Weight and Balance adjustment needed.

Instruction for continued Airworthiness placed in POH.

\*\*\*\*\* NOTHING FOLLOWS \*\*\*\*\*

Additional Sheets Are Attached