AIRCRAFT LOG AF5-1

FBC92813

ENGINE	Teledyne Continental Motors	40-330-2	R
ENGINE			Ľ
PROPELLER	Hartzell Propeller Inc.	PHC J39F-IN	FP5689B
PROPELLER			
ENGINE			
ENGINE			
PROPELLER			
PROPELLER			
ENGINE			
ENGINE			
PROPELLER			
PROPELLER			
ENGINE			
ENGINE			
PROPELLER			

5-08-07		
	THE FOLLOWING SUPPLEMENTAL TYPE CERTIFICATES HAVE BEEN INSTALLED ON THIS AIRCRAFT SA10588SC SE10589SC	
	SA01708SE CDC on 05/08/07. Cirrus Design Corporation Duluth, MN USA	
	PC# 338CE	

Life Limited Parts SR22

PART NAME	PART NUMBER		EXPIRES
CAPS Rocket Motor	21814-001	S/N_3393	03/17
CAPS Parachute	20331-001	S/N_02823	04/17
CAPS Reefing Line Cutters	5212	LOTTOSO6M 003-0039	02/13
Oxygen Bottle Assembly	100N0020- 4	MFG 0//07	01/2022
ELT Battery Pack	452-6504	Date Installed 04/07	08/2011
EMA Controller, AAIR	20902-001	2Feb07-97	2Feb 2014
Pilot Seat Inflator Assy, AAIR	20902-002	S/N AASI 023U 20328	2/1/2014

	5-24-07	 Searched AD's throught issue 2007 - 10 . A compliance at this time 	ll AD's are in	Dank. Bolin	
E Cirrus EL SR22 G3 22-2525 NO 550PK RK ORDER -07-2007		Cirrus Design Factory Service (epair Station No. YD5R855Y 515 Taylor Circle Juluth MN 55811 thone 218-788-3101	Center	DATE 7/19/2007 A/C TSN 64 3 HOBBS 64 3	
furbocharger (P/N 466 04-0003, S/N KFN003 onormalizing System for the reviewed the file on the repaired/inspected in a	304-0003, S/N KCN 51) Work done !A estallation Instruction this aircraft and the accordance with cur	SB No. 26, Issue date 19 July 2007. Removed 101109). Replaced with new Turbochargers, Li- W Kelly Aerospace Power Systems SB No. 26, is 215-9. accompanying discrepancy forms. The aircraft Tent requirements of the Federal Aviation Admit air Station CRS YD5R855Y.	I (P/N 466304-0003, S/N KE Tornado Aljey Turbo MM 21	N00238) and RH (P/N 5-10 and ETI SR22	
TE: 7/19/2007	SIGNI Scott Se	ED: (Printe	Work Order: 9462-07-2007 by EBis 3 (datcomedia.com)	

AIRWORTHINESS DIRECTIVE/FACTORY BULLETIN COMPLIANCE RECORD

A.D./BULL. NUMBER	ITEM AFFECTED	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. 1 TIME/RECUR	NEXT COMP. DATE/HRS./CYCLE	AUTHORIZED SIG CERTIFICAT	NATURE È NO.
PEC WO	KE Cirrus DEL SR22 G3 1 22-2525 G NO 550PK DRK ORDER 19-08-2007	CIRRUS	Cirrus Design Fact Repair Station No YD5R855 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101	1750	enter	DATE 8/15/2007 A/C TSN 104 1 HOBBS 104 1	<i>x x x x x x x x x x</i>
AD	Entries						P
(8)	Researched AD's a	nd Mandatory Service	e Bulletins thru current Bi-We	ekly 2007-16. All AD's	s and MSB's are in comple	ance at this time	
was	repaired/inspected	in accordance with file at this Certified F	current requirements of the Fe Repair Station CRS YD5R855Y	ederal Aviation Admin	airframe, aircraft engine, istration and is approved f	propeller, or appliance identified or return to service. Pertinent	
DA	TE: 8/15/2007	SIG	ENED: Soul &	100		Work Order: 9629-08-2007	
		Jose	eph Sullivan Ified Repair Station No YD5R		Print	ed by EBis 3 (datcomedia.com)	7
	1	1	1 1	STATES IN	NAME OF TAXABLE PARTY.	1	
	S/I RE	AKE Cimus DDEL SR22 G3 N 22-2525 EG NO 550PK ORK ORDER 45-08-2007	Repair 4515 1 CIRRUS Duluth	us Design Fac Station No YD5R855 Taylor Circle I, MN 55811 2 218- 788-3101	tory Service Cen	ter	DATE 8/29/2007 A/C TSN 137 9 HOBBS 137 9
	s	B Entries					
	(4) Complied with SB :	2X-31-02 by installation of hea	at shrink tubing on the	P1051 connector and se	curing as specified	
	l wa	is repaired/inspecte	e on this aircraft and the acco d in accordance with current n file at this Certified Repair S	requirements of the l	ederal Aviation Administr	frame, aircraft engine, propeller, or a ation and is approved for return to se	ppliance identified ervice Pertinent
	D.	ATE: 8/29/2007	SIGNED:	MULH	Ann	WarkO	rder: 9745-08-2007
			Mitch Knase Certified Re	pair Station No YD5	R855Y	Printed by EBis	3 (datcomedia.com)

IIEM UAIL & 1113 AT COMP. AFFECTED

METHOD OF COMPLIANCE I TPE OF A.D.

NEXT COMP. 1 TIME/RECUR. DATE/HRS./CYCLE **AUTHORIZED SIGNATU** CERTIFICATE NO.

MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9774-08-2007



Cirrus Design Factory Service Center

Renair Station No. YD5R855Y 4515 Taylor Circle uluth MN 55811 Phone 218-788-3101

DATE 8/30/2007 A/C TSN 137 9 HOBBS 137 9

AD Entries

(4) Researched AD's and Mandaton's Schools Bulletins thru current Bi-Weekly 2007-17. All AD's and MSB's are in compliance at this time

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance and current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Control Demair Station CRS YD5R855Y

DATE: 8/30/2007

Repair Station No YD5R855Y

Wark Order: 9774-08-2007

Printed by EBis 3 (datcomedia.com)

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9865-09-2007

Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4U10 Taylor Circle Duluth MN 55811 Phone 218-788-3101

DATE 9/17/ AVC TSN HOBBS

SB Entries

(5) Complied with Service Bulletin 2X-28-07 Fuel Check Valve Removal by removing R/H and L/H fuel supply tube/check valve assemblies and installi kit part number 70195-00. IAW the service bulletin instructions. Operational and leak checks good ... (6) Acft is in compliance with A.D. 07-16-10. Ke Aerospace Power Systems Turbo Chargers P/N. 466304-0003 Serial Numbers KEN00238 and KFN00351 are not within effictive range specified in Kr Aerospace Power Systems S.B. No. 26 Rev Bissued July 27, 2007.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identify was repaired/inspected in accordance with current requirements of the Federal Awation Administration and is approved for return to service. Pertiner details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 9/17/2007

SIGNED:

Peterson, Daniel J. Certified Repair Station No YD5R855Y Work Order: 9865-0

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YDERAST

DATE: 11/9/2007

SIGNED:

Work Order: 10240-11-2007

Steven LaMourea
Certified Repair Station No. YD5R855Y

Printed by EBis 3 (datcomedia.com)

L

MAKE Cirrus MODEL SR22 G3 S/N. 22-2525 REG NO 550PK WORK ORDER 10567-01-2008



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3101 DATE 1/8/2008 A/C TSN 281 6 HOBBS 281 6

AD Entries

(2) Researched AD's thru current Bi-Weekly 2008-02. AD 2007-24-13 has been PCW by installing drain holes IAW CDC SB 2X-57-08. All AD's are in compliance at this time.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordunce with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on the afternoon that the contribution of the repair are on the afternoon that the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordunce with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent

DATE: 1/8/2008

SIGNED:

Kari Hagglund

Certified Repair Station No. YD5R855Y

Work Order: 10567-01-2008

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 10752-02-2008



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101 DATE 2/22/2008 A/C TSN: 293 1 HOBBS: 293 1

AD Entries

(2) Researched AD's thru current Bi-Weekly 2008-04. All AD's are in compliance at this time

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 2/22/2008

SIGNED:

Curt Kracke

Certified Repair Station No YD5R855Y

Work Order: 10752-02-2008

AIRWORTHINESS DIRECTIVE/FACTORY BULLETIN COMPLIANCE RECORD

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 11052-04-2008	Cirrus Design Factory Service Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101	DATE: 4/22/2008 A/C TSN 334 5 HOBBS 334 5
CDC SB 2X-52-07R4 Cabir	Door Rod End Replacement, by Installing Improved hardwa (APPENDIX TO AD 2008-06-28 LIMITATIONS REGARDIN	and MSB's are in compliance at this time (8) Complied with re IAW SB Instructions. (10) Complied with AD 2008-06-08 IG AVIDYNE PRIMARY FLIGHT DISPLAYS) in the limitations
was repaired/inspected in a details of repair are on file a	ccordance with current requirements of the Federal Aviation at this Certified Repair Station CRS YD5R855Y	aircraft, airframe, aircraft engine, propeller, or appliance identified a Administration and is approved for return to service. Pertinent
DATE: 4/22/2008	Steven LaMourea Certified Regar Station No YD5R855Y	Work Order: 11052-04-20 Printed by EBis 3 (datcomedia.com
L		
MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO. 550PK WORK ORDER 11219-05-2008	Cirrus Design Factory Servi Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101	ice Center DATE 5/13/20 A/C TSN 364 HOBBS 364
AD Entries		141
(2) Researched AD's and Ma	andatory Service Bulletins thru current Bi-Weekly 2008-10	All AD's and MSB's are in compliance at this time
was repaired/inspected in ac details of repair are on file at	cordance with current requirements of the Federal Awation this Certified Repair Station CRS YD68554	aircraft, airframe, aircraft engine, propeller, or appliance identified a Administration and is approved for return to service. Pertinent
DATE: 5/13/2008	SIGNED:	Work Order: 11219-05-2
		Printed by EBis 3 (datcomedia.

MAKE CITUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 11317-06-2008	Cirrus Design Factory Service Center Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3101	DATE 6/13/2008 A/C TSN 388 6 HOBBS 388 6
SB Entries		
	08-01 by correcting the weight and balance history IAW Service Bulletin instruc 70202-001 IAW SB instructions	ctions (27) Complied with SB2X-57-09 by
 was repaired/inspected in 	this aircraft and the accompanying discrepancy forms. The aircraft, airframe, accordance with current requirements of the Federal Aviation Administration at this Certified Repair Station CRS YD5R855Y SIGNED:	and is approved for return to service. Pertinent
DATE: 6/13/2008	0 0	Work Order: 11317-06-2006
	Joseph Sullivan Certified Repair Station No YD5R855Y	Printed by EBis 3 (datcomedia.com
MAKE: Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER	Cirrus Design Factory Service Center Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101	DATE 6/30/2008 A/C TSN 433 9 HOBBS 433 9
11481-06-2008	· ·	
AD Entries		
AD Entries (2) Researched Airworthine	ss Directives through current bi-weekly 2008-14. All applicable AD's are in co	
AD Entries (2) Researched Airworthine I have reviewed the file on the was repaired/inspected in a	as Directives through current bi-weekly 2008-14. All applicable AD's are in companying discrepancy forms. The aircraft, airframe, accordance with current requirements of the Federal Aviation Administration are this Certified Repair Station CRS YD5R855Y.	aircraft engine, propeller, or appliance identified
AD Entries (2) Researched Airworthine I have reviewed the file on the was repaired/inspected in a	is aircraft and the accompanying discrepancy forms. The aircraft, airframe,	aircraft engine, propeller, or appliance identified

AIRWORTHINESS DIRECTIVE/FACTORY BULLETIN COMPLIANCE RECORD **AUTHORIZED SIGNATURE** TYPE OF A.D. NEXT COMP. DATE & HRS. ITEM METHOD OF A.D./BULL. CERTIFICATE NO. 1 TIME/RECUR. DATE/HRS./CYCLE AT COMP. AFFECTED NUMBER COMPLIANCE DATE 7/27/2008 Cirrus Design Factory Service Center MAKE CITTUS A/C TSN 502 MODEL SR22 G3 HOBBS 502 Repair Station No YD5R855Y S/N 22-2525 4515 Taylor Circle REG NO 550PK Duluth, MN 55811 WORK ORDER Phone 218-788-3101 11665-07-2008 **AD Entries** (2) Researched Airworthiness Directives through current bi-weekly 2008-15. All applicable AD's are in compliance at this time I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y Work Order: 11665-07-2008 SIGNED: 2 DATE: 7/27/2008 Printed by EBis 3 (datcomedia.com) Erick Sjodin Certified Repair Station No YD5R855Y DATE 8/18/2008 Cirrus Design Factory Service Center MAKE CITTUS A/C TSN 524 9 MODEL SR22 G3 Repair Station No YD5R855Y HOBBS 524 9 S/N 22-2525 4515 Taylor Circle REG NO 550PK Duluth, MN 55811 WORK ORDER Phone 218-788-3101 11798-08-2008 **AD Entries** (2) Researched AD's thru current Bi-Weekly 2008-17. AD 2008-14-13, Cabin Door Rod Ends and Hinge, has been P/C/W by CDC SB 2X-52-07R4 on 4-22-08 All AD's are in compliance at this time I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Awation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y Work Order: 11798-08-2008 DATE: 8/18/2008 SIGNED:

PG 52 FOR SB COMPLIANCE RECTED DATES

Karl Hagglund

Certified Repair Station No YD5R855Y

MANUF	ACTURER	MODEL	SERIAL NO.	LOCATION	MAX. ALT.
	I certify	y that the al	timeter, static	system, trai	nsponder,
	and alti	itude reporte	er test require	d by FAR's	91.411,
	91.413	, & 91.217 l	nave been per	formed and	found
	within	the limits of	f FAR 43 app	endices E &	F and
	AC 43				a #
			000 FEI		
	Transp	onder: Mfg	g Garmin I	P/N <u>13587-</u>	<u>050</u>
	_	Model:	GTX-327	S/N 837	28224
7	Encode	er: Model _	ACK_P/N_A	4-30 S/N \	05977
	Altime	ter: Mfg Ay	vidyne		
	68	(PFD)	15222-006 S	N 2007	5087
	Mfg		12731-003 S		
			6	3	
	CDC O	uality Assu	rance	on	05/10/07
	and the second of the second		oration Dulu		
	PC# 33				775000
	1 0,7 0				т т

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 12354-12-2008	Cirrus Design Factory Service Center Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3438	DATE 12/5/2008 A/C TSN 616.5 HOBBS 616.5
AD Entries		
(3) Researched AD's thru	current Bi-Weekly 2008-24 Ali AD's are in compliance at this time	
was repaired/inspected in	this aircraft and the accompanying discrepancy forms. The aircraft, airfraccordance with current requirements of the Federal Aviation Administrate at this Certified Repair Station CRS YD5R855Y	
DATE: 12/5/2008	SIGNED:	Work Order: 12354-12-2008
	Curt Kracke	Printed by EBis 3 (datcomedia.com)
	Certified Repair Station No YD5R855Y	
	I certify that the altimeter, static system, transponder, and alti	
	reporter test required by FAR's 91.411, 91.413, & 91.217 have	
	performed and found within the limits of FAR 43 appendices	s E & F and
	AC 43-6B. Tested To 25,000 Feet Date: 5/15/09	
	Tested To 25,000 Feet Date: 5/15/09 Transponder: Mfg: Garmin P/N: 13587-050 S/N: 837282	224
	Encoder: Model: ACK P/N: A-30 SN: 105977	
	Altimeter: Mfg: Avidyne PFD P/N: 15222-008 S/N: 20051	1247
	Mfg: United P/N: 12731-003 S/N: 46071	
	Signed Date: 5/15/09	
	Signed Date: 5/15/09 Cirrus Design Factory Service Center Corporation Duluth, M	1
	Work Order Number: 12772-05-2009	WII OSA
	CRS # YD5R855Y	
	CIO II I DOILOGO I	14

	Lanes, S	
	and the second	

MAINTENANCE RECOR F.A.R. 43.9

DATE OF COMPLETION

AIRCRAFT TIME IN SERVICE

DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED

MAKE Cimus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9087-05-2007



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101

Airframe Entries

(1) Adjusted fuel flow in one turn and did ground run with the following results, MAP 30.2 F.F. 36.4 GPH with 1 tornado alley maint instructions. Flight test good

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft was repaired/inspected in accordance with current requirements of the Federal Awation Administration and is a details of repair are on file at this Certified Repair Station CRS MD5R856X.

DATE: 5/31/2007

SIGNED:

Mitch Knase
Certified Repair Station No YD5R855Y

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	F.A.R. 43.9 DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERV
MO S/N RE	KE Cirrus DEL SR22 G3 N 22-2525 G NO 550PK DRK ORDER 94-06-2007	Cirrus Design Factory Service Center Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3101	DATE 6/22/2007 A/C TSN 32.5 HOBBS 32.5
Ai	rframe Entries		
the Am L-b har dat Inte Aw Sys DC 178 cha sys 962 Ins Fla sat Aw I ha	pilot floor Arm 140 0 inches in 122 5 inches. One L-band ar land antenna P/N S72-1750-32 mess per Avidyne/Ryan Dwg. 1 ed October 2005, was placed in ernational Corporation Doc. No dyne/Ryan 9900BX Installation stem Installation Guidelines for 1029-01 Revision 12 Dated. Jul 17 Rev C, STC # SA02013CH anges weight and balance data stems operational check satisfact 280912 and installed PS Engine tallation and Operation Manual is should law Avidyne SB 601-0 instactory. (8) Performed airbardyne TAS 620 skywatch system ave reviewed the file on this aircs repaired/inspected in accordance.	System The Processor P/N 70-2420-7 TAS 620 S/N 060109, was in the Transponder Coupler, P/N 70-2040 S/N 051268, was installed in the Interna P/N S72-1750-31L S/N 3086 was installed on the exterior upper L S/N 3107 was installed on the exterior lower surface of the fuselage 029-09 Rev 6 in the center console Arm 115 0 inches. An Awdyne of the aircraft. Installed in the aircraft a copy of the FAA Approved Installed in the aircraft a copy of the FAA Approved Installed Installed in the aircraft a copy of the FAA Approved Installed Inst	the center console just aft of the aircraft encoder, or surface of the fuselage, Arm 157.0 inches. One or SARM 132.0 inches. Fabricated/installed wire TAS Pilots Handbook, P/N 32-2352 Revision 5, attruction for Continued Airworthiness, Ryan ory Systems TAS 600 TAS610 TAS 620 and mational Corporation 9900BX Traffic Advisory attonal Corporation Master Data List Doc. No irrus Ryan TCAD Processor Installation Dwg. aircraft equipment list was revised to reflect these performed and checked satisfactory. Avionics of Garmin GMA340 Audio Panel P/N 12717-050 S/N CDC AMM 23-50 and PMA 8000B System attisfactory. (5) Removed and replaced the MFD by Static leak check IAW CDC AMM 34-10. Checked Flight test satisfactory for functional checked of the
	T. G. 2.2.2001	Joseph Sullivan Certified Repair Station No. YD5R855Y	Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus MODEL: SR22 G3 S/N: 22-2525 REG NO 550PK WORK ORDER: 9270-06-2007



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone: 218- 788-3101

DATE: 6/25/2007 A/C TSN: 34.5

HOBBS: 34.5

Airframe Entries

(1) Removed the PS Engineering audio panel PMA 8000 P/N 050-890-0100 S/N B01099 and installed a PS Engineering audio panel PMA 8000B P/N 050-890-0202 S/N S02980IAW SR22 AMM 23-50 and PMA 8000B System Installation and Operation Manual Doc. P/N 200-890-0100 Rev. 5 Dated July 2006. Functional check satisfactory.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 6/25/2007

SIGNED

Work Order: 9270-06-2007

Taavi Korpi Certified Repair Station No. YD5R855Y

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9629-08-2007	CIRRUS	Cirrus Des Repair Station 1 4515 Taylor Cir Duluth, MN 558 Phone 218-78
Airframe Entries		
(1) FLT TIME 84.4 Hrs particulate inspection on a checks with satisfactory rewith new P/N 15963-201 I Cooling Fan System, IAW FAA Form 337 Dated 14 / these changes (6) Remarked RH wastegate subtransponder antenna cable 3, 2005 Functional checks	drain plug & old filt esults. All work war AVV AMM chapter the following Loan August 2007 Prefer noved alt 1 FCM Pa 1 (9) Removed a pport clamp P/N E	er, no discrepand as accomplished 34-40. Functional Star Drawings Lornied ground ope N 14605-001 and and replaced LH TI-G2-600-109.
 I have reviewed the file on was repaired/inspected in details of repair are on file	accordance music	MILOUR LA HELL
DATE: 8/15/2007		NED: Stock

sign Factory Serv

No YD5R855Y rcle 311 38-3101

0857-001, serviced engine cies noted. Retained oil sk I.A.W. Cirrus SR22 A.M.N l check satisfactory.... (4) S03-0402, and LS01-149\$ erational, function tests. Fit d installed P/N 14605-002 and RH turbo support rod Work accomplished IAW tices and Avidyne/Ryan 9\$ rformed by CDC Test Pilot

discrepancy forms The E ents of the Federal Aviation YD5R855Y

Joseph Sullivan Certified Repair Station No YD5R855Y

MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9774-08-2007



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101

DATE	8/30	/2007
A/C	TSN	137 9
HO	BBS	137 9

Airframe Entries

(2) Removed Ryan TAS 620 Processor P/N 70-2420 S/N 060108 and installed Ryan TAS 620 Processor P/N 70-2420 S/N 060105 IAW Avidyne/ Ryan 9900BX Installation Manual P/N 32-2351 Rev. 04 Dated October 3, 2005 Functional check of the Ryan TAS system satisfactory.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 8/30/2007

SIGNED:

Taaw Korp

Certified Repair Station No YD5R855Y

Work Order: 9774-08-2007

Printed by EBis 3 (datcomedia.com)

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9811-09-2007



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3101

DATE 9/7/2007 A/C TSN 147.9 HOBBS 147 9

Airframe Entries

(1) Accomplished Incoming Aircraft Inspection Checklist IAW RSM Form 21 F1. Airworthiness Directives Current thru Bi-Weekly 2007-18, Service Bulletins Current thru 06 SEP 2007. (2) Replaced upper antenna p/n S72-1750-31L, s/n off 3086, s/r on 3110. Replaced lower antenna p/n S72-1750-32L, s/n off 3107, s/n on 3131 Replaced Ryan processer p/n 70-2420-7TA620, s/n off 060105, s/n on 060108 All work done IAW Avidyne/Ryan 9900BX Installation Manual 32-2351 OPS check on GRD OK... (5) Installed EMI suppressor, PN 51161-001, on cabin hot air valve coupler wiring as per CDC Drawing No. 17404-003.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R955

DATE: 9/7/2007

SIGNED:

Steven LaMourea

Certified Repair Station No. YD5R855Y

Work Order: 9811-09-2007

F.A.R. 43.9

DATE OF MPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
	MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9865-09-2007	Cirrus Design Factory Service Cen Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101	DATE 9/17/2007 A/C TSN 147 9 HOBBS 147 9
	Airframe Entries		And the second s
	(2) Removed Ryan TAS 626 9900BX Installation Manual	0 Processor P/N 70-2420 S/N 060108 and installed Ryan TAS 620 Proc P/N 32-2351 Rev 04 Dated October 3, 2005 Functional check of the R	essor P/N 70-2420 S/N 060105 IAW Avidyne/ Ryan Ryan TAS system satisfactory
	mas repaired inspected in s	this aircraft and the accompanying discrepancy forms. The aircraft, airfraccordance with current requirements of the Federal Aviation Administrate this Certified Repair Station CRS YD5R855Y.	rame, aircraft engine, propeller, or appliance identified tion and is approved for return to service. Pertinent
	DATE: 9/17/2007	SIGNED: Ora Par	Work Order: 9865-09-2007
	500 TO 100 TO 10	Peterson, Daniel J Certified Repair Station No YD5R855Y	Printed by EBis 3 (datcomedia.com)
	-		the transfer of the majority the two
 ,	MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9888-09-2007	Cirrus Design Factory Service Center Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101	DATE 9/19/2007 A/C TSN 156 7 HOBBS 156 7
	Airframe Entries		
	Maintenance Practices Aircra	reheat System Model No TAS100-12CS, S/N 40879 IAW Tanis Installation for Weight and Balance has been Revised for this installation. Ops Check-109 for R/H Tail-Pipe IAW ETI Instructions for Continued Airworthine	k Good (3) Penlaced Support Clams
	was repaired/inspected in acco	aircraft and the accompanying discrepancy forms. The aircraft, airfram rdance with current requirements of the Federal Aviation Administration is Certified Repair Station CRS YD5R855Y.	ne, aircraft engine, propeller, or appliance identified in and is approved for return to service. Pertinent
	DATE: 9/19/2007	SIGNED:	Work Order: 9888-09-2007
		Karl Hagglund Certified Repair Station No. YD5R855Y	Printed by EBis 3 (datcomedia.com)

F.A.R. 43.9

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVI
	MAKE Cimus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 9981-10-2007	Cirrus Design Factory Service Center Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101	DATE 10/10/2007 A/C TSN 156 7 HOBBS 175 2
	new antenna location at F Installation Manual P/N 32 Guidelines for Cirrus SR2 been updated for the mov at the aft ground buss Ali antenna removal IAW repi practices and Avidyne Tra Dated. October 3, 2005, R Dated 12 July 2004, and I have reviewed the file on was repaired/inspected in	Service Bulletin 2X-21-02R1 by installing kit # 70194-001 Fresh air insulating duzed TAS antenna P/N S72-1750-32L S/N 3131 from original antenna location 1/8 159 Installed antenna IAW Avidyne Traffic Advisory Systems TAS 600 TAS 2-2351 Revision 04 Dated October 3, 2005, Ryan International Corporation 990 0/22 Aircraft Revision E Dated 12 July 2004, AC 43 13-18, and FAA form 337 ement of the antenna (8) Added additional antenna grounds to both the top a work completed IAW standard maintenance practices and AQ 43-13. (11) Per air deviation R 8817 and SR-22 AMM 51. (13) Replaced both ends on the Jf affic Advisory Systems TAS 600 TAS610 TAS 620 and Avidyhe/Ryan 9900BX Ryan International Corporation 9900BX Traffic Advisory System Installation Guid AC 43 13-18. This aircraft and the accompanying discrepancy forms. The aircraft, eirframe, a accordance with current requirements of the Federal Aviation Administration and at this Certified Repair Station CRS YD5R855Y. SIGNED: Peterson, Daniel J Certified Repair Station No YD5R855Y.	Installed antenna P/N \$72-1750-32E S/N 4951 In 610 TAS 620 and Avidyne/Ryan \$9008 x 1008 X Traffic Advisory System Installation dated 10 Oct 2007. Weight and balance has and bottom Ryan TAS 620 Antennas all terminate formed repair on lower EH fuselage skin for TAS antenna cable IAW standard maintenance installation Manual P/N 32-2351 Revision 04 delines for Cirrus \$R20/22 Aircraft Revision E

E A D 12 0

DATE (MAKE Cirrus MODEL SR22 G3
	S/N 22-2525 REG NO 550PK WORK ORDER 10103-10-2007
	Airframe Ent



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101

DATE 10/23/2007 A/C TSN: 182 HOBBS 182

NTE	NO		
ED	TO	SER	VIC

Airframe	-ntrice
,u	-1111103

(1) Researched AD's and Mandatory Service Bulletins thru current Bi-Weekly 2007-21. All AD's and MSB's are in compliance at this time. (2) Removed Magnetometer/OAT probe P/N 15222-102, S/N 26631 and replaced with servicable Magnetometer/OAT probe P/N 15222-102S, S/N 26066. Reference FAA form 8130-3 dated 1/17/2007 for airworthiness approval. Work and setup done IAW CDC AMM 34-20. Operational checks good

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aveition Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS 2059855

DATE: 10/23/2007

SIGNED:

Steven LaMourea Certified Repair Station No YD5R855Y Work Order: 10103-10-2007

Printed by EBis 3 (datcomedia.com)

MAKE CITUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 10303-11-2007



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth MN 55811 Phone 218-788-3101

DATE 11/27/2007 A/C TSN 227 2 HOBBS 227 2

Airframe Entries

(3) Removed and replaced R/H lower door latch P/N 21889-001 IAW MM 52-10

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 11/27/2007

Work Order: 10303-11-2007

DATEOF
COMPLETION
COMPLETITION

IN SERVICE

OR APPROVED DATA USED

AGENCY & CERTIFICATE NO.
WORK PERFORMED/RETURNED TO SERV

MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 10567-01-2008



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101 DATE 1/8/2008 A/C TSN 281/6 HOBBS 281/6

Airframe Entries

(3) Removed Avidyne MFD, (P/N 14750-012, S/N 20035147) and Replaced with serviced MFD (P/N 14750-012S, S/N 20017326) IAW CDC SR22 MM 31-60. Ops check good. Updates installed

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Awation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 1/8/2008

SIGNED:

Karl Hagglund
Certified Repair Station No YD5R855Y

Work Order: 10567-01-2008

Printed by EBis 3 (datcomedia.com)

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 10573-01-2008



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218-788-3101 DATE 1/21/2008 A/C TSN 282.4 HOBBS 282.4

Airframe Entries

(21) Performed line sweep number 0801141300 and found that this aircraft has a Cyclone 600 awionics cooling fan installed in a different location that cannot chaffe against the W608 wire bundle. No further action needs to be taken ... (22) Installed SB 2X-34-24 WAAS upgrade IAW service bulletin instructions. (23) Removed GNS-430's p/n 12718-001 s/n's 97137556, GPS1 and s/n 97139323, GPS2 Installed WAAS capable GNS-430's p/n 12718-072, S/N 23404701, GPS1 and, S/N 23404557, GPS2. Set up completed. Removed (2) PN 12744-001 GPS Antennas, SN 59429899 & SN 59429854. Removed XM Antenna PN 16127-002, SN 167346. Installed WAAS GPS/XM Antenna PN 12744-005, SN 216596. Installed WAAS GPS. Antenna PN 12744-004, SN 225668. All work IAW SB 2X-34-24 instructions dated 23 OCT 2007... (24) Performed composite repair for FWD GPS. Antenna installation on upper fuselage. BL0 IAW SB 2X-34-24 and SR-22 AMM 51... (25) Removed PFD, PN 15222-007, SN 20075087. Installed rebuilt PFD, PN 15222-008, SN 20040127. Performed setup and magnetic calibration IAW SR22 AMM 31-60.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 1/21/2008

SIGNED: Don Pale

Work Order: 10573-01-2008 Printed by EBis 3 (datcomedia.com)

Peterson, Daniel J Certified Repair Station No YD5R855Y

F.A.R. 43.9

		F.A.R. 43.9	
DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERV
	MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 10651-01-2008	Cirrus Design Factory Service Center Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3101	DATE 1/23/2008 A/C TSN 284 2 HOBBS 284 2
	Airframe Entries		
	(3) Removed and Replaced LH	and RH Waste Gate Dump Flange (P/N ETI-SR22-109-1), with new, IAW ETI Ins	tallation Instructions Report 22-6460001
	was repaired/inspected in accordetails of repair are on file at the	ircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft endance with current requirements of the Federal Awation Administration and is apply a Certified Repair Station CRS YD5R855Y.	roved for return to service Pertinent Work Order: 10651-01-2008
	DATE: 1/23/2008	SIGNED:	
		Karl Hagglund Certified Repair Station No YD5R855Y	Printed by EBis 3 (datcomedia.com)
-	MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 10752-02-2008	Cirrus Design Factory Service Center Repair Station No YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101	DATE 2/22/2008 A/C TSN 293 1 HOBBS 293 1
	Airframe Entries		
-	check satisfactory IAW SR22 All polished all windows IAW CDC 3 maintenance practices (7) Re AMM 31-60 Leak check and fulcleaned all flight controls as need.	t and static systems, purged pitot and static systems, and found no evidence of pet MM 34-10. Airspeed indicates correct speed according to corresponding pressure SR22 AMM 12-20. (6) Removed and replaced prop. spinner P/N 13978-001. IAW emoved PFD (P/N 15222-008S) (S/N 20040127) and Replaced with new PFD (P/N inctional check satisfactory. (8) Magnetometer calibration was performed. IAW Sided, replace elevator trim CRTRG P/N 15650-002, system checks ok LA W CDC Replaced both LH & RH gap seals. ew P/N (14390-002) IAW CDC AMM 20-30, 5	Inputs up to 200 Knots (5) Buffed and V CDC AMM 61-10 and standard 15222-008) (S/N 20009297) IAW SR22 R22 AMM 34-20 (10) Inspected and MM 27-30 Lubricated all flight controls
<u>-</u>	was repaired/inspected in accor	ircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft endance with current requirements of the Federal Aviation Administration and is approximately continued Repair Station CRS YD5R855Y.	ngine, propeller, or appliance identified roved for return to service. Pertinent
	DATE: 2/22/2008	SIGNED:	Work Order: 10752-02-2008
		Curt Kracke Certified Repair Station No YD5R855Y	Printed by EBis 3 (datcomedia.com)

F.A.R. 43.9

DATE OF COMPLETION AIRCRAFT TIME IN SERVICE DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED AGENCY & CERTIFICA WORK PERFORMED/RETURNE



GRAND FORKS INTERNATIONAL AIRPORT 2467 AIR CARGO DRIVE • GRAND FORKS, ND 58203

Air Frame Logbook Insert

Date: 2/26/2008; Aircraft: 550PK; Type: CIRRUS DESIGN; S/N: 2525; Hobbs: 297.50; Tach: 271.10; Total Time: 271.10; Engine - Type: , S/N:, Time: 271.10; Prop - Type: , S/N:, Time: 271.10; Work Done At - Airframe Time: 271.10,, Engine Time: 271.10, Removed cowl, inspected heat ducting for proper installation and routing, no defects noted, pressurized system to check for leaks, none noted, installed cowl.

Bob Martin A&P471824633

F.A.R. 43.9

MAPE Cirrus MODEL SP22 G3 SNI 22-25-25 SNI 2	F AIRCRAFT TIME ION IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
(3) Removed and replaced vent/blower assembly P/N 20970-003 IAW CDC SR22 AMM chapter 21-20 Cleaned and inspected HVAC ducting IAW standard mantenance practices. Operational check satistactory I have reviewed the file on this arcraft and the accompanying discrepancy forms. The arcraft, arthrame, arcraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Awation Administration and is approved for return to senace. Pertinent details of repair are on file at this Certified Repair Station CRS YDSR855Y DATE: 3/2/2008 SIGNED: Curt Kracle Certified Repair Station No. YDSR855Y MOREL SR22 (33 SN. 22-2555 REC. NO. 550Pk WORK ORDER HOSED SATE 4/22/2008 ACT SN. 334 5 HOSES SATE 11052-04-2008 Airframe Entries (4) Removed and Replaced #2 EGT probe (P/N 16579-002) IAW CDC SR22 AMM 77-20. (9) Performed composite repair on RH A-Piller bonding flange. IAW CDC Repair Devalors/Albration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 8.51-30. (11) Removed DAU PN. 1893-002 SN off1158-002 SN off1158-002 No. 488 IAW CDC MN 77-30. (12) Removed and replaced Mn 47 15088-5 S(SN) Off KR00277, SN on L8N00743). Adusted engine operating parameters IAW TAT Report 215-10. ETI Installation Instructions Report No. 22-6480001 CDC AMM 61-20 and TOM Installed PN 15922-102 SN 98131417 IAW SR22 AMM 34-20 Functional check satisfactory. (10) Performed magnetometer PN 15222-102 SN 98131417 IAW SR22 AMM 34-20 Functional check satisfactory. (10) Performed magnetometer PN 15222-102 SN 28600 and installed Magnetometer PN 15222-102 SN 98131417 IAW SR22 AMM 34-20 Functional check satisfactory. (10) Performed magnetometer calibration IAW CDC SR22 AMM chapter 34-20. (18) Removed and replaced LH MLG Wheel and tire ASSY tire PN 14075-006 tube P/N 14076-002 Wheel Assy PN 17122-101 IAW CDC AMM 32-0. (18) Removed and replaced LH MLG Wheel and tire ASSY tire PN 14075-006 tube P/N 14076-002 Wheel Assy PN 17122-101 IAW CDC AMM 32-0.	MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER	Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811	A/C TSN 293 1
I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YDSR855Y. DATE: 3/2/2008 SIGNED: Curt Kracie Certified Repair Station No. YUGR855Y. Printed by EBis 3 (datcomedia.com) MAKE Cirrus MODEL SR22 G3 SN. 22:2525 REG NO. 550PK WORK ORDER 11052-04-2008 Airframe Entries (4) Removed and Replaced #2 EGT probe (P/N 16579-002) IAW CDC SR22 AMM 77-20. (9) Performed composite repair on RH A-Pitlar bonding flange. IAW CDC Repair Devalor/Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 & 51-30. (11) Removed DAU PN. 10892-002 SN 0ff1156 installed PN 16892-002S SN on 488 IAW CDC MM 77-30. (12) Removed and replaced MAP cortroller PN 470688-5 (SN 0ff KRN00277; SN On LBN00743). Adjusted ergine operating parameters LAW TAI Repoint 215-10, ETI Installation Instructions Report No. 22-6460001 CDC AMM 61-20 and TCM IO-550 Overhaul Manual. All function and spokenick good. (13) Removed Magnetometer PN 1522-102 SN 28066 and installed Magnetometer PN 1522-102 SN 28131417 IAW SR22 AMM 34-20 Functional check satisfactory. (16) Performed magnetometer calibration IAW CDC SR22 AMM chapter 34-20. "(18) Removed and replaced LH MLG Wheel and thre ASSY. the P/N 14075-006 tube P/N 14076-002 Wheel Assy. PN 17122-101 IAW CDC AMM 32-10 I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Poderal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS 1333551	Airframe Entries	P 100 K	
I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y DATE: 3/2/2008 SIGNED: Curt Kraculer Certified Repair Station No. YU5R855Y MakE Cirrus MOCEL SR22 G3 SN 22-2525 REG NO 550PK WORK ORDER AIGHT SEPARATION OF YD5R855Y AIGHT SEPARATIO	(3) Removed and replace standard maintenance ;	ced vent/blower assembly P/N 20970-003 IAW CDC SR22 AMM chapter 21-20 practices. Operational check satisfactory	Cleaned and inspected HVAC ducting IAW
Curt kracie Certified Repair Station No. YtSR855Y MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO. 550PK WORK ORDER 11052-04-2008 Airframe Entries (4) Removed and Replaced #2 EGT probe (P/N 16579-002) IAW CDC SR22 AMM 77-20 (9) Performed composite repair on RH A-Pillar bonding flange IAW CDC Repair Devation/Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 & 51-30 (11) Removed DAU P/N 16692-002 S/N 0f1156 installed P/N 16692-002S S/N on 488 IAW CDC MM 77-30 (12) Removed and replaced MAP controller P/N 470688-5 (S/N 0f1 KFN00277, S/N On LBN00743) Adjusted engine operating parameters IAW TAT Report 215-10, ETI Installation Instructions Report No. 22-6460001 CDC AMM 61-20 and TCM I0-550 Overhauli Manual All function and ops checks good installed Magnetometer P/N 15222-102 S/N 98131417 IAW SR22 AMM 34-20 Functional check satisfactory (16) Performed magnetometer calibration IAW CDC SR22 AMM chapter 34-20 (18) Removed and replaced LH MLG Wheel and thre ASSY thre P/N 14075-006 tube P/N 14076-002 Wheel Assy P/N 17122-101 IAW CDC AMM 32-10 I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Pederal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS 3950557	I have reviewed the file was repaired/inspected	on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, in accordance with current requirements of the Federal Australia.	aircraft engine, propeller, or appliance identified and is approved for return to service. Pertinent
Certified Repair Station No. YEAR855Y MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO. 550PK WORK ORDER 11052-04-2008 Aifframe Entries (4) Removed and Replaced #2 EGT probe (P/N 16579-002) IAW CDC SR22 AMM 77-20 (9) Performed composite repair on RH A-Pillar bonding flange IAW CDC Repair Deviation/Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 8 51-30 (11) Removed DAU PM In 6892-002 S/N off1156 installed P/N 16692-002S S/N on 488 IAW CDC MM 77-30 (12) Removed and replaced MAP controller P/N 47088-5 (S/N Off KFN00277, S/N On LBN00743) Adjusted engine operating parameters IAW TAT Report 215-10, ETI installigation Instructions Report No. 22-8460001 CDC AMM 61-20 and TCM IO-550 Overhault Manual All function and ops checks good (13) Removed Magnetometer P/N 15222-102 S/N 26066 and installed Magnetometer P/N 15222-102 S/N 98131417 IAW SR22 AMM 34-20 Functional check satisfactory (16) Performed magnetometer calibration IAW CDC SR22 AMM chapter 34-20 (18) Removed and replaced LH MLG Wheel and thre ASSY thre P/N 14076-006 tube P/N 14076-002 Wheel Assy P/N 17122-101 IAW CDC AMM 32-10 I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Pederal Awation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS Y 5508594.	DATE: 3/2/2008	SIGNED:	Work Order: 10850-03-2008
MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER T1052-04-2008 Airframe Entries (4) Removed and Replaced #2 EGT probe (P/N 16579-002) IAW CDC SR22 AMM 77-20 (9) Performed composite repair on RH A-Pillar bonding flange IAW CDC Repair Deviation/Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 & 51-30 (11) Removed DAU P/N 16692-002 S/N off1156 installed P/N 16692-002S S/N on 488 IAW CDC MM 77-30 (12) Removed and replaced MAP controller P/N 470888-5 (S/N Off KFN00277, S/N On LEN00743) Adjusted engine operating parameters IAW TAT Report 215-10, ETI Installation Instructions Report No. 22-8460001 CDC AMM 61-20 and TCM I0-550 Overhaul Manual. All function and ops checks good. (13) Removed Magnetometer P/N 15222-102 S/N 26066 and IAW CDC SR22 AMM chapter 34-20 (18) Removed and replaced HM LG Wheel and tire ASSY tire P/N 14075-006 tube P/N 14076-002 Wheel Assy P/N 17122-101 IAW CDC AMM 32-10 I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Paderal Awation Administration and is approved tor return to service. Pertinent details of repair are on file at this Certified Repair Station CRS y 1959559			Printed by EBis 3 (datcomedia.com)
(4) Removed and Replaced #2 EGT probe (P/N 16579-002) IAW CDC SR22 AMM 77-20 (9) Performed composite repair on RH A-Pillar bonding flange IAW CDC Repair Deviation/Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 & 51-30 (11) Removed DAU P/N 16692-002 S/N off1156 installed P/N 16692-002S S/N on 488 IAW CDC MM 77-30 (12) Removed and replaced MAP controller P/N 470688-5 (S/N Off KFN00277, S/N On LBN00743). Adjusted engine operating parameters IAW TAT Report 215-10, ETI Installation Instructions Report No. 22-6460001 CDC AMM 61-20 and TCM I0-550 Overhaul Manual. All function and ops checks good (13) Removed Magnetometer P/N 15222-102 S/N 26066 and installed Magnetometer P/N 15222-102 S/N 98131417 IAW SR22 AMM 34-20. Functional check satisfactory (16) Performed magnetometer calibration IAW CDC SR22 AMM chapter 34-20 (18) Removed and replaced LH MLG Wheel and tire ASSY tire P/N 14075-006 tube P/N 14076-002 Wheel Assy P/N 17122-101 IAW CDC AMM 32-10 I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Awation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS X9598554.	MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER	Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811	A/C TSN 334 5
IAW CDC Repair Deviation/Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 & 51-30 (11) Removed DAU P/N 16692-002 S/N off1156 installed P/N 16692-002S S/N on 488 IAW CDC MM 77-30 (12) Removed and replaced MAP controller P/N 470688-5 (S/N Off KFN00277, S/N On LBN00743) Adjusted engine operating parameters IAW TAT Report 215-10, ETI Installation Instructions Report No. 22-6460001 CDC AMM 61-20 and TCM IO-550 Overhaul Manual. All function and ops checks good. (13) Removed Magnetometer P/N 15222-102 S/N 26066 and installed Magnetometer P/N 15222-102 S/N 98131417 IAW SR22 AMM 34-20 Functional check satisfactory. (16) Performed magnetometer calibration IAW CDC SR22 AMM chapter 34-20. (18) Removed and replaced LH MLG Wheel and tire ASSY tire P/N 14075-006 tube P/N 14076-002 Wheel Assy P/N 17122-101 IAW CDC AMM 32-10. I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Pederal Awation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS VPSP8559	Airframe Entries		
was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS y 5598559	IAW CDC Repair Deviation/ 16692-002 S/N off1156 insta KFN00277, S/N On LBN003 CDC AMM 61-26 and TCM installed Magnetometer P/N IAW CDC SR22 AMM chapt	Alteration for Field Repair No. R9161 dated April 21, 2008 and CDC AMM 51-20 alled P/N 16692-002S S/N on 488 IAW CDC MM 77-30 . (12) Removed and ref743). Adjusted engine operating parameters IAW TAT Report 215-10, ETI Insta IO-550 Overhaul Manual. All function and ops checks good. (13) Removed M 15222-102 S/N 98131417 IAW SR22 AMM 34-20. Functional check satisfactor ter 34-20. (18) Removed and replaced LH MLG Wheel and tire ASSY tire P/N	& 51-30 (11) Removed DAU P/N eplaced MAP controller P/N 470688-5 (S/N Off ellation Instructions Report No. 22-6460001 lagnetometer P/N 15222-102 S/N 26066 and eq (16) Performed magnetometer calibration
	 was repaired/inspected in a 	ccordance with current requirements of the 🗪 deral Aviation Administration and	is approved for return to service. Pertinent
DATE: 4/22/2008 Work Order: 11052-04-2008	DATE: 4/22/2008	SIGNED:	Work Order: 11052-04-2008

MAKE CITUS MODEL SR22 G3 S/N 22-2525	
REG NO 550PK WORK ORDER	

Cirrus Design Factory Service Center

inspection and was determined to be in an airworthy condition

DATE 5/20/2008 A/C TSN 377 9

MODEL 5R22 S/N 22-2525	Repair Station No. YD5R855Y 4515 Taylor Circle	HOBBS 377 9
DEG NO 550PK	Duluth, MN 55811	TIFICATE
WORK ORDER 16-05-2008	Phone 218-788-3101	:TURNED
*		· ·
Airframe Entries		
- 4 VM Weather	/Radio Receiver (P/N 16665-003,S/N 816001264,Rec ID#24) and Replaced	d with new XM Weather/Radio Receiver (P/N
16665-004, S/N 816001836	Rec ID#17,Audio ID#WBRAT0MY,Weather ID# 8XAUR08A) IAW CDC SI	R22 AMM 34-50 Ops check satisfactory at this
time		(Market)
- second/inchected in	this aircraft and the accompanying discrepancy forms. The aircraft, airfram accordance with current requirements of the Federal Aviation Administration at this Certified Repair Station CRS YD R855Y.	me, aircraft engine, propeller, or appliance identified unand is approved for return to service. Pertinent
DATE: 5/20/2008	SIGNED:	Work Order: 11246-05-2008
	Steven LaMourea	Printed by EBis 3 (datcomedia.com)
	Certified Replan Station No YD5R855Y	i into a by Lord o quateoniculationity
		· · · · · · · · · · · · · · · · · · ·
		in year
MAKE Cirrus	Cirrus Design Factory Service Center	DATE 6/13/2008
MODEL SR22 G3	Repair Station No. YD5R855Y	A/C TSN 388 6 HOBBS 388 6
S/N 22-2525 REG NO 550PK	4515 Taylor Circle	
WORK ORDER	Duluth, MN 55811	
11317-06-2008	Phone 218-788-3101	
Airframe Entrie		
		2000 10
(4) Performed aircraft	annual inspection IAW cirrus mm chapter 5-20 and 5-30 (7) Researched (21) Serviced aircraft primary battery IAW cirrus mm chapter 24-30 (ADS through bi-weekly issue 2008-13, all ADS are in
compliance at this time	Complied with FAR 91 207d inspection and operational check of ACK ELT	model ME406. S/N 01318, found serviceable, due each 1
year hattery replacem	ent due ALIG 2011 (24) Complied with Precise Flight built in oxygen syst	tem airworthiness checklist I A.W. STC SA01708SE
instructions (28) Rep	placed landing light lens P/N 17298-001 IAW CDC AMM 71-10 and 33-40	(29) Replaced Brake Caliper O-Rings P/N 101-34500,
IAW CDC AMM 32-42	(30) Bled Brake System IAW CDC AMM 32-42 (32) Serviced O2 syst	tem to 2000 PSI IAW Precise Flight Servicing
Instructions (37) Ins	talled new nut clip P/N 13641-001 on the right upper MLG fairing IAW CDC	C SR22 AMM 32-10 and standard maint practices (38)
Rigged rudder travels I	A W A M M chapter 27-20 OPS check good (39) Replaced VOR/LOC	anterina grommets P/N MS25489-135 IAVV CDC SR22
AMM 34-50 (40) Ins	talled aluminum tape over top inspection hole on vertical stabilizer IAW state with new filter element and o-ring, kit P/N 1742243-05, IAW CDC AMM 28	8-20 Leak checked good (42) Repaired Aff Wheel
Cutout Area Of NLG Fa	aining With A 4 Ply Non-Structural Repair IAW CDC AMM 51-10 And 51-30	0 (43) Repaired Inbd Portion Of Rt MLG Faining, With A
4 Ply Non Structural Re	epair, IAW CDC AMM 51-10 And 51-30 (44) Bonded upper anti-chafe s	spacer on left MLG strut IAW CDC SR22 AMM 32-10 and
standard maint, practic	es (45) Replaced 2 Oxygen bottle clamps (P/N 102N0120-1) IAW Prec	cise Flight STC SA01708SE instructions (46)
Fabricated and installed	d reinforcement gusset for L/H engine intercooler baffle IAW standard mail	intenance practices (47) Replaced starter contactor
boot P/N MS25171-4S	Done IAW CDC AMM 80-10 and standard maintenance practices (48)) Replaced scat tube P/N DXX050684 for right tallpipe
neat jacket IAW standa	ard maintenance practices (49) Resecuted heat shield for on header bet	tween cylinders 1-3 Done lavv lat keport
22.6460004 /E41 Va	afed targue on Engine Woldmont and lower mount attach fittings IAW CD	OC AMM 20-60 (52) Repositioned crankcase breather
22-6460001 (51) Ve	rified torque on Engine Weldment and lower mount attach fittings IAW CD IAW standard maintenance practices (53) Complied with Precise flight	C AMM 20-60 (52) Repositioned crankcase breather

firewall forward for prop TKS ice protection. Done IAW CDC AMM 20-50 (57) I certify that this aircraft has been inspected IAW a 100hr/ Annual

DATE: 6/13/2008	SIGNED: SUCH & LUCY -	Work Order: 11317-06-2008
	Joseph Sullivary Certified Repair Station No. YD5R855Y	Printed by EBis 3 (datcomedia.com)
	. And the state of	Sec. I
MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 11481-06-2008	Cirrus Design Factory Service Cen Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3101	DATE 6/30/2008 A/C TSN 433 9 HOBBS 433.9
Airframe Entries (3) Adjusted L/H door actual	tion linkage IAW CDC SR22 AMM chapter 52-10. Operational check sa	itisfactory.
d the file on th	nis aircraft and the accompanying discrepancy forms. The aircraft, airf accordance with current requirements of the Federal Aviation Administrations. The current requirements of the Federal Aviation Administration CRS YD5R855Y.	ation and is approved for return to service. Pertinent


Production Flight Test accomplished in accordance with Cirrus Procedure #90502 Name: Frank Mathews Signature: Title: Production Flight Test Pilot I find that the aircraft meets the requirements for the -certification requested and have issued an U.S. Standard _Airworthiness Certificate dated The next inspection is due my / 31

_Troy J. McDonald _ODARF-405228-CE MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 11783-08-2008



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth MN 55811 Phone 218-788-3101



Airframe Entries

(3) Removed and Replaced starter adaptor assy, PN 642083-1A2, IAW TAT Installation Instructions and TCM Overhaul Manual. Operational and leak check performed with no discrepancies noted

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 8/15/2008

SIGNED:

Darrel Zimmer David Zimme Certified Penger State

Certified Repair Station No. YD58

Work Order: 11783-08-2008

Printed by EBis 3 (datcomedia.com)

MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 11798-08-2008



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4515 Taylor Circle Duluth MN 55811 Phone 218-788-3101

DATE 8/18/2008 A/C TSN 524 9 HOBBS 524 9

Airframe Entries

(3) Removed and Replaced TIT Probe Assy (P/N ETI-G2-711-1) IAW ETI Installation Instructions Report 22-6460001. Ops check satisfactory at this time

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propelled, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 8/18/2008

SIGNED:

Karl Hagglund

Certified Repair Station No. YD5R855Y

Work Order: 11798-08-2008

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 . REG NO 550PK WORK OPDER 11971-09-2008



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4515 Taylor Circle Duluth, MN 55811 Phone 218- 788-3101 DATE 9/17/2008 A/C TSN 568 1 HOBBS: 568 1

AD Entries

(2) (FLT TIME 541.7 Hrs.) Researched AD's and Mandatory Service Bulletins thru current Bi-Weekly 2008-19. All AD's and MSB's are in compliance at this time

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 9/17/2008

SIGNED:

Steven LaMourge Certified Repair Station No YD5R855Y Work Order: 11971-09-2008

Printed by EBis 3 (datcomedia.com)

MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 12580-02-2009



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4514 Taylor Circle Duluth, MN 55811 Phone: 218- 788-3438 DATE 3/2/2009 A/C TSN 640 1 HOBBS 640 1

AD Entries

(3) (FLT TIME 613.7 Hrs.) Researched AD's and Mandatory Service Bulletins thru current Bi-Weekly 2009-04.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R8555

DATE: 3/2/2009

SIGNED:

Aaron Holmgren
Certified Repair Station No YD5R855Y

Work Order: 12580-02-2009

Cirrus Design Factory Service Center INCONTRACTOR OF THE PROPERTY O

Airframe Entries

(2) Labusted the encoder, and centry that the altimeter, static system, transponder, and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, 91 413, 8 91 217 and altitude reporter test required by FAR's 91 411, (2) Ladjusted the encoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the encoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and attitude reporter test required by FAR's 91.411, 91.413, 8.91.2 Ladjusted the recoder, and certify that the altimeter, static system, transponder, and other properties of the recoder, and certify that the altimeter, static system, transponder, and other properties the recoder, and certify that the altimeter, static system, transponder, and other properties the recoder, and certify that the altimeter, static system, transponder, and other properties the recoder, and the recoder that the altimeter system, transponder, and the recoder that the altimeter system, transponder, and the recoder that the altimeter system is a system of the recoder that the altimeter system is a system of the recoder that the altimeter system is a system of the re The found within the limits of FAP 43 appendices E 8 F and AC with satisfactory results (5) Replaced O2 distribution manifold/dome light assy P/N 102N0230-1 IAW CHT manifold/ Precise Flight Inc. drawing list. 102N0000 Performed leak check with satisfactory results (7) Removed and Replaced J1429 connector assy for #4 (8) Performed fuel Hoisted the Indications are good. (7) Removed and Replaced J1429 connector assy for #4 (8) Performed fuel Hoisted the Indications are good. (8) Performed fuel Hoisted the Indications are g indication with new connector IAW CDC SR22 AWM 77-00-01 and AMM 77-40, operational check of CHT indications are good. (8) Performed fuel Hoisted the Hoisted the Hoisted that Hoisted the Hoisted that Hoisted the Hoisted that Hoisted the Hoisted that Hoi calibration IAW CDC AMM chapter 28-40 OPS check good. (12) Disconnected engine and all attached equipment from engine mount. Hoisted the server are a to facilitate welding. Selected a server of the same material at 120 Disconnected engine and all attached equipment from repair area to facilitate welding. Selected a server of the same material at 120 Disconnected engine and all attached equipment from repair area to facilitate welding. Selected a server of the same material at 120 Disconnected engine and all attached equipment from engine mount. Hoisted the selected a selected as the selected at 120 Disconnected engine and all attached equipment from engine mount. Hoisted the selected as 120 Disconnected engine and all attached equipment from engine mount. Hoisted the selected at 120 Disconnected engine and all attached equipment from repair area to facilitate welding. Selected a selected at 120 Disconnected engine and all attached equipment from repair area to facilitate welding. Selected a selected at 120 Disconnected engine and all attached equipment from repair area to facilitate welding. engine just enough to clear the engine mount and removed the mount from the aircraft. Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to facilitate welding. Selected a 1.30 P/N Removed paint from repair area to fa length of sleet tube sleeve having an inside diameter approximately equal to the outsidediameter of the damaged tube and of the same material 4.1.30 P/N and the sleeve having an inside diameter approximately equal to the outsidediameter of the damaged tube and of the same material 4.1.30 P/N and the sleeve having an inside diameter approximately equal to the outsidediameter of the damaged tube. Cut through the entire length of sleet tube sleeve having an inside diameter approximately equal to the outsidediameter of the damaged tube. Cut through the entire length of sleet tube sleeve having an inside diameter approximately equal to the outsidediameter of the damaged tube. Cut through the entire length of sleet tube sleeve having an inside diameter approximately equal to the outsidediameter of the damaged tube. 50094-083U PO# 94791 RR# 365086, and a wall thickness of 083 Diagonally cut the sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends so that it is sleeve. The sleeve reinforcement at a 30-degree angle on both ends minimum distance of the sleeve from the edge of the chafe damage was 1-1/2 times the diameter of the damaged tube. Cut through the entire lend positioned.

The reinforcement sleeve and repair area is the chafe damage was 1-1/2 times the diameter of the damaged tube. Cut through the entire lend positioned is the sleeve and repair area. The positioned is the sleeve and separated the half-sections of the sleeve. The sleeve is the damaged tube cannot be sleeve and separated the half-sections of the sleeve. The sleeve is the damaged tube controlled the sleeve and separated the half-sections of the sleeve. The sleeve along the length of the two sides and welded both ends of the sleeve. the reinforcement sleeve, and separated the half-sections of the sleeve. Cleaned and prepped reinforcement sleeve to the damaged tube. Added four clamped, and welded the reinforcement sleeve, and separated the half-sections of the sleeve. Cleaned and prepped reinforcement sleeve to the damaged tube. Added four clamped, and welded both ends of the sleeve. Design Comp. Crawling # 16546-001 Design Comp. Stress relieved repair locally as per Circus. clamped, and welded the reinforcement sleeve along the length of the two sides, and welded both ends of the sleeve to the damaged tube Added four # 16546-001 Rev # 16546-001 rosette welds. Inspected welds for repair sleeve, welds check good. Stress relieved repair locally as per Cirrus. Design Corp Drawing # 16546-UU1 Rev. Leak check of repair good. Applied LPS Hard. Leak check of repair good. Leak check of repair good. Leak check of repair good. Applied LPS Hard. Leak check of repair good. Leak check of repair good. Leak check of repair good. Applied LPS Hard. Leak check of repair good. Leak check of repair good. Leak check of repair good. Applied LPS Hard. Leak check of repair good. Leak check of C Pressurized tube through screw hole, applied solution of soapy water to repair, inspected for air leaks applied primer and paint to repair as per coat PN 50869-001 as per Cirrus Design Corp Drawing # 16546-001 Rev C Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled renaired engine mount to aircraft LAW Circus Reference FAA Form 337 Dated 05-19-2009 Reinstalled Reference FAA Form 337 Dated 05-19-2009 out P/N 50869-001 as per Cirrus Design Corp Drawing # 16546-001 RevC Cleaned and prepped repair, applied primer and paint to repair as per Cirrus SR22

Oesign Corp Drawing # 16546-001 Rev C Reference FAA Form 337 Dated 05-19-2009 Reinstalled repaired engine mount to aircraft IAW Cirrus SR22

AMM chapter 71-20 (13) Replaced left wastedate support bracket holf IAW FTI Report 22-6460001 Design Corp Drawing # 16546-001 Rev C Reference FAA Form 337 Dated 05-19-2009 Reinstalled repaired engine mount to aircrait IAVV CITTUS SRC2.

AMM chapter 71-20 (13) Replaced left wastegate support bracket bolt IAW ETI Report 22-6460001 ... (14) Replaced hearings IAVV CD22 AMM 78-10 (15) Replaced left main tire & tithe and renacked hearings IAVV AMM 78-10 (15) Replaced left main tire & tithe and renacked hearings. AMM chapter 71-20 (13) Replaced left wastegate support bracket bolt IAW ETI Report 22-6460001 (14) Replaced all exhaust neader gaskets and enhaust nuts on left and right header assemblies IAW AMM 78-10. (15) Replaced left main tire & tube and repacked bearings IAW SR22 AMM 32-41 (17) Retorqued left and right headers after engine run up IAW AMM ch. 78-10. (10) Penlaced right output to the chaust headers after engine run up IAW AMM ch. 78-10. (10) Penlaced right output to the chaust headers after engine run up IAW AMM ch. 78-10. exhaust nuts on left and right header assemblies IAW AMM 78-10. (15) Replaced left main tire & tube and repacked bearings IAW SKZZ AMM 3Z-4 I.

(17) Retorqued left and right exhaust headers after engine run up IAW AMM ch. 78-10. (19) Replaced right exhaust bonding strap. (20) Replaced SKEET highe from left intercooler to left exhaust head exchanger. DNI DVVDEDERA LAND TAT. (17) Retorqued left and right exhaust headers after engine run up IAW AMM ch. 78-10 ... (19) Replaced right exhaust bonding strap, FN IWISZSUOS-OB AMM 78-20 ... (20) Replaced SKEET tube from left intercooler to left exhaust heat exchanger, PN DXX050564, IAW TAT ICA 215-10 and the stranger of the stran IAW SR22 AMM 78-20 (20) Replaced SKEET tube from left intercooler to left exhaust heat exchanger, PN DXXUDUD04, IAW IAT ICA 213-10 and standard maintenance practices (21) Removed and replaced R/H white nav light bulb p/n 50911-001 with new IAW AMM ch. 33-40, operational check (21) Paramed Map controller DALATOSES, DOS. CALL DALOTAS. Installed MAD controller DALATOSES, DOS. CALL DALOTAS. standard maintenance practices (21) Removed and replaced R/H white nav light build p/H bu911-uu1 witth new IAVV Avviivi CH. 35-40. Work good (22) Removed MAP controller P/N 470688-0005, S/N LEN00233. Work and the standard law TAT Papert 32-6480001 and ETI MPC ASSV DIMC 32-5650001. Operational holds about 15 Papert 32-6480001 and ETI MPC ASSV DIMC 32-5650001. good (22) Removed MAP controller P/N 470688-0005, S/N LBN00743 Installed MAP controller P/N 470688-UUU5, S/N LENUUZ33. (23) Removed MAP accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed satisfactory accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG 22-5650001 Operational leak check performed accomplished IAW TAT Report 22-6460001 Operational leak check performed accomplished IAW TAT Report 22-6460001 Operational leak check performed accomplished IAW TAT Rep accomplished IAW TAT Report 22-6460001 and E11 MPC ASST DWG 22-5050001 Operational reak Check performed satisfactory

controller P/N 470688-0005, S/N LEN00233 Installed MAP controller P/N 470688-0005, S/N LBN00743 Removed master wastegate P/N 470842-0004 controller P/N 470688-0005, S/N LENU0233 Installed MAP controller P/IN 470000-0003, S/N LENU0743 Removed master wastegate 17/N S/N KGN00551 and installed P/N 470842-0004 S/N LJN00264 Work accomplished IAW TAT Report 22-6460001 and ETI MPC ASSY DWG

S/N KGN00551 and installed P/N 470842-0004 S/N LJN00264. Work accomplished IAVV TAT Report 22-5650001 Operational leak check performed satisfactory (24) Performed wastegate linkage retrofit to cable style P/N 22-5650008 IAVV TAT Report The aircraft, airframe, aircraft engine, propeller, or appliance identified Thave reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, aircraft, and aircraft original, projected in Service. Pertinent was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. details of repair are on file at this Certified Repair Station CRS YD5R8553

DATE: 6/4/2009

Mitch Knase Certified Repair Station No YD5R855Y Work Order: 12772-05-2009

MAKE: Cirrus MODEL: SR-22 G3

S/N: 2525

REG. NO: N550PK WORK ORDER:

3053-05-2009

Twin Cities Aviation, Inc.

8891 Airport Rd #A-2 Blaine, Minnesota 55449 USA

Phone: 763-784-9165

DATE: 5/13/2009 A/C TSN:

HOBBS: 667.1

Airframe Entries

Replaced volume knob on Audio panel with new supplied from Avidyne.—Fabricated bracket for MLB antenna under glareshield. New bracktet raises antenna aprox 6 inches to just below glare shield and above glove box. Test satisfactoryl on ground.—Checked operation of TWX 670 lightning sensor. System operatational checks satisfactory with external electrical source. Tested during flight and picked up several strikes near weather compared to datalink info.—Weather working correctly and signal strength good. Replaced batteries in remote. Attempted several times to pair remote to unit while outside. No info displayed. Attempted different unit installation with no change, Removed remote antenna cable from system, no change. Contacted Avidyne, subscription updated for radio and weather. Left aircraft outside to power source to update. After several hours unit would pair and function. Operational check satisfactory on ground.—Test flew aircraft for in flight checks of weather, radio, and lightning. All systems check satisfactory on test flight. Several Mx squawks noted and passed on to owner.—Installed fabricated wire harness from MLX unit com 2 port up to pilot kick panel. Installed two DB9 connectors and wired com 2 to one connector. Fabricated wire harness and installed into second SB9 connector for future GPS signal. Wire ends at MFD connector and is tied back and labeled. Removed MLX/MLB switch behind MFD and spliced in three sections of wire to pilots kickpanel. Reinstalled switch remotely under pilot kickpanel. Reinstalled all interior panels, trim, and seats. All systems check satisfactory.

THIS AIRCRAFT HAS ONE RS232 GPS OUTPUT FROM GPS TO TRANSPONDER. REST ARE 429 BUSS SIGNALS. RADIO RACK REMOVAL IS

MLX com 2 to DB9 connector

- -txd to pin 2
- -rts to pin 3
- -sg to pin 5

Gps DB9 connector to capped ends (GPS input)

REQUIRED FOR GPS SIGNAL COMPLETION.

- pin 2 is blue striped wire
- pin 5 is white wire

DATE: 5/13/2009 Twin Cities Aviation, Inc. A/C TSN: HOBBS: 667.1 MAKE: Cirrus MODEL: SR-22 G3 8891 Airport Rd #A-2 Blaine, Minnesota 55449 USA S/N: 2525 DATE REG. NO: N550PK Phone: 763-784-9165 WORK ORDER: 3061-05-2009 **Airframe Entries** Replaced right brake pads with new 066-6200. The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Work Order: 3061-05-2009 SIGNED: DATE: 5/13/2009 Printed by EBis 3 (datcomedia.com) Jeff Iskierka, A&P: 47004

F.A.R. 43.11-91.409

DATE AIRCRAFT TIME IN SERVICE ASSS Aurord Approach Rd. Duluth, MN 55811 ASSS Aurord Approach Rd. Duluth, MN 55811 ASSS Aurord Approach Rd. Duluth, MN 55811 Date: 8/07/2009; Aircraft: N550PK; Type: SR22; S/N: 2525; Hobbs: 752.1; Total Time: 752.1 Shop Order #: 09-7204 (FLT TIME: 725.7Hrs.) Performed annual inspection on aircraft IAW CDC AMM 5-20 and 5-30. Researched ADs and CDC Mandatory Service Bulletins and Service Advisories thru current bi-weekly 2009-16. Cleaned and lubricated airframe components, as required, IAW CDC AMM 12-20. Inspected tires and brakes IAW CDC AMM 5-20. Replaced brake caliper o-rings (P/N 101-34500) IAW CDC AMM 32-42. Cleaned and packed wheel bearings IAW CDC AMM 32-41. Tested ELT IAW FAR 91.207, tested good. Battery due Aug, 2011. Replaced LH brake linings with 4 each P/N 066-06200. Replaced battery #1 with new Concorde P/N RG24-11M. Replaced #2 batteries with new. Next replacement due August 2011. Removed and replaced TKS filter with new P/N 26115-101. Legrify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in	### PATE INSERVICE ASS Aurport Approach Rd. Duluth, MN 55811	## ASS Airport Approach Rd. Duluth. MN 55811 Sala Part
This aircraft, ariframe, engine, propeller and/or appliance was repaired and/or inspected in accordance with current FAR's and manufacturer's instructions and was found to be airworthy for return to service. Signature:		

MAKE CITTUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 13148-09-2009



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4514 Taylor Circle Duluth, MN 55811 Phone 218-788-3438

DATE 10/8/2009 A/C TSN 845.4 FLIGHTTIME 819 1

SB Entries

(23) Complied with SA09-07 TAT service bulletin SB09-01 inspection for exhaust manifold cracks around turbo mount flange, no discrepancies found. inspection due again at next oil change or 869 1 flight hrs (24) Complied with SA09-08 TAT service instructions S108-01 Rev A, crankcase breather discharge tube, cleaned and inspected, inspection due again at next oil change or 869.1 flight hrs. . (25) Complied with SB2X-32-19R1 (NLG Assy Insp. and reinforcement) by insp of NLG upper gusset plate and FWD nose gear strut fillet weld IAW SB instructions. No evidence of cracking at this time. Re-inspection due again at both points 919.1 flt hours

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 10/8/2009

SIGNED: Clarke 1. 3en

Charles Bernu Certified Repair Station No. YD5R855Y Work Order: 13148-09-2009

Printed by EBis 3 (datcomedia.com)

F.A.R. 43.11-91.409

DATE AIRCRAFT TIME IN SERVICE

KIND OF INSPECTION - STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

MAKE CITUS MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER 13148-09-2009



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4514 Taylor Circle Duluth, MN 55811 Phone. 218- 788-3438 DATE 10/8/2009 A/C TSN 845 4 FLIGHTTIME 819 1

Airframe Entries

(3) Removed the TWX 670 Processor (P/N 700-00033-00 S/N 99060651), TWX 670 Antenna (P/N S72-1715-1 S/N 581-0360), and associated TWX 670 winning and mounting hardware. Removed the MLX 770 Processor (P/N 700-00163-000 S/N M085234997), MLX 770 Antenna (P/N S67-1575-109 S/N 9253), and associated MLX 770 winning and mounting hardware. Removed the MLB 700 Processor (P/N 700-00159-001 S/N M084018475), MLB 700 Antenna (P/N S67-1575-650 S/N 814-0469), MLB 700 Remote Control (P/N URC-10000BA1-R), and associated MLB 700 mounting hardware. All equipment was removed IAW the information and ICA provided by the FAA Form 337, dated 4/20/09 that was submitted for the installation of said equipment, as well as SR22 AMM and SR22 WM. Completed a new FAA Form 337, dated 10/07/09, for the Removal of said equipment. Weight and balance information to be captured under a separate discrepancy. Awonics Functional check satisfactory. (5) Installed WX500 Stormscope system by performing composite repair of antenna location and installing the WX500 Processor (P/N 12745-050 S/N 94366), WX500 antenna (P/N 12745-070 S/N 84026), and WX500 Wire Harness Assembly (P/N 70132-101). Work Performed IAW Cirrus Repair Deviation # R9869, Cirrus SB 2X-34-20, and SR22 AMM 34-40. WX500 Functional checks satisfactory. (8) Addressed all minor exterior cosmetic descrepancies IAW CDC AMM 11-20, 12-20, and 51-20... (21) Removed and replaced LH exhaust tail pipe P/N 22-6150024 and LH tailpipe V-band clamp P/N 11-1100023 IAW TAT Report 22-6460001. (26) Removed and replaced LH wastegate upper and lower support brackets P/N 22-6250006 and bott P/N MS21250-05020 IAW TAT Report 22-6460001. (27) Installed XM Weather/Audio system by re-installing the XM Receiver P/N 16665-004 S/N 816001836 and XM Remote P/N 16665-502 (that were originally removed during the installation of the Avidyner/Ryan ML8700 system on 4/20/09). Maintenance performed IAW SR22 AMM 34-50. XM system functional checks astisfactory. (XM Audio ID WBRATOMY, XM WX ID 8XAUR08A). (28) Updated Weights, Balanc

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 10/8/2009

SIGNED: Charles James

Work Order: 13148-09-2009

Printed by EBis 3 (datcomedia.com)

Charles Bernu Certified Repair Station No YD5R855Y

MAKE Cirrus MODEL SR22 G3 S/N 22-2525 REG NO 550PK WORK ORDER



Cirrus Design Factory Service Center

Repair Station No YD5R855Y 4514 Taylor Circle Duluth, MN 55811 Phone 218-788-3438

DATE 10/9/2009 A/C TSN 846.8 HOBBS 846 8

Airframe Entries

(4) (FLT TIME 820.4) Removed and Replaced Tire and Tube on R/H MLG with 1 ea New P/N 14075-006. Goodyear Flight-Special 15x600x6 Tire and 1 ea New P/N 14076-001 Goodyear 600x6 Tube IAW CDC SR22 AMM 32-40 (5) Accomplished Cirrus Design Service Bulletin SB2x-32-16 Main Landing Gear Axle-Fitting Shim by performing Inspection/Repair and installing Kit P/N 70196-001 per Paragraph E thru H of this SB (7) Reseated the J517 Radio rack Connector "TAWS" and "Autopilot disconnect tone" are now audible. Audio system functional checks satisfactory IAW SR22 AMM 23-50 (9) Removed MFD (P/N 14750-014S S/N 20017326) and installed Serviceable MFD from stock (P/N 14750-014S S/N 20075067) IAW SR22 AMM 31-60 Functional check satisfactory

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y

DATE: 10/9/2009

SIGNED: 342 Joseph Sullivan

Certified Repair Station No YD5R855Y

Work Order: 13163-10-2009

Printed by EBis 3 (datcomedia.com)

N550PK

Cirrus SR22

S/N 2525

Flight Meter 877.6

TKS reported inoperative. Gained access to TKS pump and checked for flow at the test port, no flow. Started to remove TKS lines from the finger strainer back to the primer pump. Eventually heard a noise like air being pushed through on the outlet of the primer pump. Turned system back on and confirmed good flow to all deice panels.

Jeffrey T. Nuttall AP2694634IA

Aero Services, Inc.

133 Municipal Dr.

Nampa, ID 83687

W.O. #7218

	*** ****		
Flight Meter 995	S/N 2525	Cirrus SR22	N550PK
	ound. Exercised flight meter pre rviced brake reservoir with hydrau	er operating with aircraft on the gro faulty TIT probe (Alcor 86245). Ser	5/19/10 Flight meter check good. Replaced
W.O. # 734	Nampa, ID 83687	94634IA 133 Municipal Dr.	Jeffrey 1. Nuttall AP26 Aero Services, Inc.
Flight Meter 1031.	S/N 2525	Cirrus SR22	N550PK
otion), dated 4/10/09. N	ckets), dated 1/20/10. Complied v SB09-01 (Exhaust Manifold Inspe	ated 4/27/09. Complied with TAT S	(Breather Cleanout) da defects noted.
with TAT 5108-01 Rev. ction), dated 4/10/09. N	SB09-01 (Exhaust Manifold Inspe	ated 4/2//09. Compiled with TAT S	(Breather Cleanout) da
w.O. # 737	5809-01 (Exhaust Manifold Inspe	Seed 4/27/09. Compiled with TAT S	defects noted. Jeffrey 1. Nuttall AP26
W.O. # 737	Nampa, ID 83687	S94634IA 133 Municipal Dr. Cirrus SR22 ap control system (flaps reported to 34-A0004-X051). System operations	Jeffrey 1. Nuttall AP26 Aero Services, Inc. N550PK 7/6/2010 Inspected fla

Photo I was a second	2300 (201)			
	N550PK	Cirrus SR22	S/N 2525	Flight Meter 1124.7
DA	reservoirs. Re-tightene gear assembly insp & right main tire and sta 15X6.00-6) and static installed. Removed we slave wastegate spring Checked A.D.s to date installation in accordal 91.207, paragraph (d). with an Annual Inspect	ed loose exhaust heat shields Reinforcement) dated 2/25/1 titic balanced wheel to extend balanced wheel. Removed corn clevis pin and worn safety to eliminate excessive play it is. No A.D.'s applicable at the new with AC43.13-1B, parage The ELT battery pack expiretion and has been determine total time is 1124.7 hours.	and greased wheel bearings. Serve, no defects noted. Complied with 0, by installing NLG repair kit (Cirroll tread life. Replaced left main tire cracked RH turbo heat shield, had by pin in RH wastegate linkage and in linkage. Reattached loose aileror is time. Inspected the aircraft Engraph 12-22. This installation meets 8/2011. "I certify this aircraft has left to be in airworthy condition". Pro-	us P/N 70238-001). Rotated e (Goodyear Flight Special II repair weld repaired, and rereplaced with new. Adjusted trim placard on co-pilot side. nergency Locator Transmitter ets the requirements of FAR been inspected in accordance
<u>-</u>	Aero Services, Inc.	133 Municipal Dr	Nampa, ID 83687	W.O. # 7423
<u> </u>	1			
[
' ——				
,				

INSPECTION RECORD F.A.R. 43.11-91.409

PECTION - STATUS & DISCREPANCY LIST ERSON APPROVING OR DISSAPPROVING		AIRCRAFT TIME IN SERVICE	DATE
DATE: 1/4/2011 A/C TSN: TACH: 1223.5	TDL Aero Enterprises Repair Station No. 7TLR012B 44 MACREADY DRIVE Merced, CA 95340 Phone: 209-722-7300	MAKE: CIRRUS MODEL: SR22 SN: 2525 REG. NO: N550PK WORK ORDER: 00000438	
CHECKS OK AT THIS TIME	USHED TKS PANELS TESTED FUNCTION (Airframe Entries CLEANED AND FLI	
accordance with current FARs rules of the Federal Work Order: 00000438	nponent(s) on N550PK was repaired and inspected in and was found Airworthy for return to service.	Maintenance Release The aircraft and/or com Aviation Regulations a	
Printed by EBis 3 (datcomedia.com)	Chris Palage Certified Repair Station No. 7TLR012B	DATE: 1/4/2011	
	Certilled Mahail Cramer		
	• "		
	1 of 1		
		1	

INSPECTION RECORD F.A.R. 43.11-91.409 KIND OF INSPECTION - STATUS & DISCREPANCY LIST FOR A PROPONING OF DISSAPPROVING AIRCRAFT FOR SERVICE

DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERV	CICE
- P _ ME406 LIT PART _ TSO C1 EXPIRAT		PACK MnO2 REV: A 6304-158 17 DO-227 204)t' MAKE: CIRRUS MODEL: SR22 SN: 2525 REPAIR Station No. 7TLR012B 44 MACREADY DRIVE WORK ORDER: 00000588 Meroed, CA 95340 Phone: 209-722-7300 Airframe Entries	M2011 1313.1
		Removed and replaced #2 alternator field control module Removed and replaced ELT batteries, next expiration Mar 2017 Removed, cleaned and reinstalled all spark plugs.	

Precision Static Testing Livermore, CA	
FAA Certified Repair Station #QJAR856X PHONE: (925) 449-5904 FAX (925) 449-6081 I certify that the altimeter(s) and static system(s) tests required by 14 CFR § 91.411 and transponder tests, including data correspondence, required by § 91.413, have been performed and found to comply with 14 CFR part 43, appendix E and F. Tested to feet. Time: _/\(\frac{1}{2} \	The second secon

MAKE: CIRRUS MODEL: SR22 SA: 2525 REG. NO: N550PK WORK ORDER: 00000842

TDL Aero Enterprises

Repair Station No. 7TLR012B 44 MACREADY DRIVE Merced, CA 95340 Phone: 209-722-7300 DATE: 11/2/2011 AC TSN: 1978-7 HOBBS: 1994-5 1334.7

Airframe Entries

IAW A Annual Inspection, Complied with Cirrus Design maintenance manual Chapter 05-20 for model SR22 AMM dated May 31, 2011. Complied with ELT inspection per 91.207(d), ELT operational check good, ELT battery expires Oct 2016. Complied with Cirrus/Precise Flight instructions for Continued Airworthiness Document 102NMAN0003 rev E, dated March 10, 2010. Complied with 100-500 hour scheduled servicing requirements. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.... Installed new main landing gear upper mushroom faring R/H side.... Removed expired VKS filter, installed new filter.next due 11-2013... Removed expired secondary batteries and installed new secondary batteries.... Complied with service bulletin TAT SB11-04. Removed, inspected, and cleaned turbocharger oil supply inlet screen.... Removed exhaust grounding strap on pilots side and replaced with new grounding strap.... Installed new screws to co-pilots side wing root faring.... Removed 6 inches of disbonded adhesive tape on wing root faring, cleaned surface area applied new adhesive tape to wing root faring.... Removed torn Fwd and Aft bottom cowling closeout rubbers and replaced with new closeout rubbers.... Removed disbonded transfer tape on pilots side main landing gear spacers, cleaned surface area applied new transfer tape to pilots side main landing gear spacers.... Inspected brake line assembly, found loose fitting on co-pilots side main landing gear break line. Cleaned fitting and re-torqued fitting.... Installed new brake shim on co-pilots side brake caliper.... Removed ALT #1 baffle drilled out loose rivets, installed new rivets to ALT #1 baffle.... Pilots side exhaust heat shields Positioned clamps in proper place, tightened clamps into place.... Removed rocker covers and gaskets. cleaned surface areas installed new gaskets on cylinder #2... Removed ripped insulation and aluminum tape from fresh air inlet, installed new aluminum tape to fresh air inlet.... Place RTV on wear marks throughout the duct, fresh air inlet... TKS fluid found on under inspection cover, Inspected pilots side rear belly compartment

1 of 2

for leak. Loose fitting was found and tightened.... Removed loose rivet from pilots side fwd silicone baffle rubber, repositioned rubber installed new rivet.... Replaced RH exhaust stack with new... Removed faded placard from co-pilots side door, cleaned surface area applied new placard to co-pilots side door.

Maintenance Release

The aircraft and/or component(s) on N550PK was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service.

DATE: 11/2/2011

SIGNED:

	entry?		
		1	
		7	
		initial and the same of the sa	
to turbo wastegate controller b	ACTT: 1426 erator AFC0W360 IAW STC SA is typical on left firewall using base. Performed run and leak che d FAA form 337. Item total wei	A02268CH inst supplied braces. Completes	ket mounted _

Installed New 12739-001.

- antema. Cheduck K-ponder operation

doluts Noted.

- and and 48884344674

INSPECTION RECORD F.A.R. 43.11-91.409

Airframe Feb. 1 2013 Complied with Cirrus SR22 Scheduled Inspection Report 100 hr. Items and instructions for continued airworthiness. Replaced engine driven alternator with new ES10024 S/N H-M090307. 500 hour inspection due 1983 ACTT. Replaced left and right turbochargers with overhauled 466304-9003 S/N H-PDR00246 on left and S/N XC000027 on right. Next due 2483 ACTT. Recommended and 3483 ACTT not to exceed. Replaced magneto pressurization filter P/N 1396-2. Next due 1783 ACTI Complied with FAR 91.207 by inspection and function test of ELT. Battery due 10/2016. Replaced 12983-001 aileron/rudder interconnect shock cord. Next due 2/2018. Performed firewall forward replacement of engine oil and fuel hoses including turbo hoses. Next due 2/2023.? Hoses provided by PHT of Tulsa OK. Ref invoice 581517 dated 12/10/12. Performed 5 yr. brake hose replacement with new hoses from PHT of Tulsa OK. dated 12/10/12. Next due 2/2017. Bled brakes and serviced reservoir. Replaced left and right brake cylinder Orings P/N M83461-1-222. Next due 2/2014. Replaced gasculator seals M25988-1-021 and MS29513-137. Replaced ignition harness with new C16-2BSII from skytronics. Serviced anti-ice system with TKS. All AD's complied with to date. I certify that this aircraft has been inspected IAW an Annual Aspection and is determined to be airworthy and is approved for return to service. Ricky E. Townsend A&P488843646IA

INSP

N550PK 3/22/13 airframe

Repaired minor damage to right wingth assembly with new lenses, retainers and Removed left exhaust and replaced #4 cylinder CHT Sensor P/N 16578-001. In left exhaust risers and installed. Ran air

Ricky E. Townsend A&P488843646LA_

INSPECTION RI F.A.R. 43.11-9	
Ref: FAR 91.413 ATC Transponder ATC 327 s/n 83728224 was tested and inspected and complies with FAR Part 43, Appendix F.	ATUS & DISCREPANCY LIST OVING OR DISSAPPROVING AIRCRAFT FOR SERVICE
Signature For Autopilots Central, Inc. Tulsa, Oklahoma FAA CRS CM2R747K	
Work Order # MAI3 - 04055	

Airworthiness. Resealed co-pilots right brake master cylinder with 199-512 Cleveland seal kit. Installed new left and right linings p/n 066-06200. Installed new temp labels On left and right brake actuators 70227-002 kit. Serviced and bled brake system. Complied with the following time limit items: Complied with FAR 91.207 ELT inspection and functional test. Battery due 10/2016. Complied with inflatable restraint electronic control module refurbish. P/N 508358-421 S/N RA14MAR14-41. FAA form 8130-3 on file under work order No.75646-1 at AMSAFE Inc., Pheonix AZ. RS No. PQ1967NM and maintained in aircraft permanent record. Next due 14 yr. Replacement 2/2021 Complied with #2 battery replacement P/N 50979-001 \$\text{ N 18615-001}\ Next due 4/16. No AD's apply at this time. I certify that this aircraft has been inspected IAW an Annual Inspection and is determined to be airworthy and approved for return to service. Ricky E. Townsend A&P488843646IA N550PK Airframe Hours: 1515.5 Removed G-243 Gill Battery S/N G025 4 and in stalled new Concorde RG24-15M ·S/N 40637251. Ricky E. Townsend A&P488843646IA

Complied with SR22 Scheduled inspection Report 100 hr and Instructions for Continued

Removed Primary Flight Display P/N /00-00006-000-Rev 38 S/N 20051247 and installed Modified Primary Flight Display S/N 20604116 and performed configuration and magnometer calibration. Installed new P/N 18603-001 anti-ice fluid strainer and serviced anti-ice reservoir with 2.5 Gal. TK\$406B and leak checked. Requires recertification for IFR flight. Approved for VFR flight duly.

Ricky E. Townsend A&P488843646IA

N550PK airframe

N550PK airframe

N550PK airframe

Removed primary flight display S/N 20604116 due to display. Installed P/N 700-0006-000 S/N 20081246 and performed configuration and Magnometer Calibration IAW 3.6.2

Envision installation manual. VFR flight only

Ricky E. Townsend A&P488843646IA

ATC TRANSPONDER COMPLIANCE

Aircraft Registration # N550PK

The ATC Transponder system ##1—##2 was inspected and tested with approved test equipment and was found to comply with FAR 43, appendix F as required by FAR 91.413.

Tested by: Lichard f. Blakely Date: 6-23-2015

Repairman # 3486824 WO# 13692 R

R.L.S. Rental Company dba Mizzou Aviation 5497 Dennis Weaver Drive, Joplin, MO 64801

CRS# AKCR139C Form MZ1040

ALTIMETER, STATIC SYSTEM & ALTITUDE REPORTING COMPLIANCE

Aircraft Registration # N550PK

The static pressure system, altimeter, and automatic altitude reporting system were tested with approved test equipment and were found to comply with FAR 43, appendices E and F as required by FAR 91.411.

Tested by: Lichar P. Blakely Date: 6-23-2015

Repairman # 3486824

WO# 13692R

R.L.S. Rental Company dba Mizzou Aviation 5497 Dennis Weaver Drive, Joplin, MO 64801

CRS# AKCR139C

Form MZ105

Tested by: Lichel P Blakely Date: 6-23-2015

Repairman # 3481824 WO# 13692 R

R.I.S. Rental Company dba Mizzou Aviation

5497 Dennis Weaver Drive, Joplin, MO 64801

CRS# AKCR139C

Complied with SR22 Scheduled inspection report 100 hr items and instructions for continued airworthiness per Tornado Alley schedule. Replaced #2 battery with new 50979-001. Next due 10/18. Replaced magneto pressurization filter with new P/N1396-2 next due 10/19. Complied with hydrostatic test and regulator overhaul of oxygen bottle P/N 099N0025-1 S/N HPR100293. FAA form 8130-3 On file under WO# 00279 at Precise Flight INC CRS6PCR620B.Next due 5 yr 10/21. Replaced right main tire and tube. Removed and refit left and right exhaust shields. Installed new roll trim placard P/N 12391 at left yoke. Researched airworthiness directives and none apply to airframe at this time. I certify that this aircraft has been inspected IAW an Annual Inspection and is determined to be airworthy and is approved for return to service.

Ricky E. Townsend A&P488843646IA

Complied with SR22 Scheduled Inspection Report 100 hour items and applicable instructions for continued airworthiness. Complied with TAT scheduled maintenance checks 100 and 50 hour items. Complied with FAR91.207 by inspection and test of ELT. Replaced battery pack with new 455-0012 unit. Expires May 2024 Replaced V-band clamps 450 hour requirement with new 11-1100023 clamps. Replaced all hose clamps on engine compartment ducting. Removed electric fuel pump for 10 yr replacement requirement. Installed same unit in overhauled condition IAW SB2X-28-12 R1 and leak test. Placed temporary revision to POH. FAA form 8130-3 on file under wo#029521 at Quality aircraft accessories QYIR334Y. Replaced 2 Tannis heat elements TTP2771-115/50 and spacers with new style connectors. Complied with TAT \$115-02 turbos TAT \$111-01 exhaust slip joints. TAT \$809-01 exhaust manifold inspection. Researched AD's and none apply to the airframe at this time. I certify that this aircraft has been inspected IAW an Annual Inspection and is determined to be airworthy and approved for return to service.

Ricky E. Townsend A&P488843636IA

N550PK

N550PK airframe

Hobbs:

4/2/18

Replaced left and right crew seat inflator assemblies with P/N 191947 S/N 20328 on pilot side and S/N 20453 on co-pilot side. Installation completed with new brackets and wire harness as required for new assembly. Inflator assemblies due replacement IAW Chapter 04-00 12 yrs 4/31/2030. This aircraft has been inspected and has been determined safe for the intended flight in accordance with Special Flight Permit dated April 3 2018.

Ricky E. Townsend A&P488843646IA



Autopilots Central, Inc.

3112 North 74th East Avenue Hangar 23, Tulsa International Airport - Tulsa, OK 74115 (918)836-6418 - Fax (918)832-0136 FAA CRS CM2R747K

Logbook Entry

Work Order:

MA17-05683

Opened: 12/29/2017 Closed: 4/18/2018

Sold To: Hilburn Builders Inc. 2107 E. Kenwood Street Siloam Springs, AR 72761 Acct Number:

(479)381-6846

General Comments:

Hobbs 1593.3 flight 1551.7

S/N: 2525 Type:SR22G3 N550PK Aircraft Number: Prop Time Prop S/N Time Cycles Prop Type S/N Eng# Type

Discrepancy: 1

Problem:

N550PK, s/n 2525 SR22 Parachute and rocket replacement SB 2X-95-18 R◆

Action Taken:

Completed Cirrus SB 2X-95-18R4 GAPS Rocket motor, parachute, shelf and electrical modifications by removing old parachute BRS P/N; 10013B, CDC P/N: 202823. Rocket Assembly P/N:014000-03/J CDC P/N: 21814-001, S/N: 3393 3RS 900 assembly MFG date 03/07. AFT Grain Vulcan Systems VSI Lot 060531-BRS P.0.#10916 TRM-225 Aft grain shift -1. Bulk head grain VSI Lot # 060531-BRS P.O.10916 TRM225 bulk head grain shift -1. Installed Repacked rocket unit P/N: 29500-003 s/n: 2943. Parachute P/N: 25574-004 S/N: 02922R1.AFT Grain 170524-TRM-275-006-001, TRM-275 Aft grain shift -1. Accomplished SB 2X-95-22R2 CAPS Aft Grain Replacement inspection, SB 2X-95-23R1 Aft grain replacement inspection. SPEN-65-24R1 CAPS Rocket shelf ground wire installation. Computed new weight and balance and installed in POH with temporary revision for POH

Part Number	Description	Credit	Quantit	/ Units	Unit Price	Extended
25574-004-INSP	Parachute Assembly	TI		Each	\$	
25574-004-1107	S/N 02922					
	Core Charge	11	1.00	Each	\$	
	Freight		1.00		\$	
29500-403	Assembly, Rocket		1.00	Each	\$	
	S/N: 2943					
	Freight	11	1.00		s	
29705-402	Frangible Link Kit, W/Hardware		1.00	Each	\$	
	Freight		1.00		\$	
50979-001	Battery (13615-001)		2.00	Each	\$	
51168-002U	Anti-Chafe Tape, Flap/Inch		17.00		\$	
70268-002	Kit, Retrofit Elec Ignition			Each	\$	
70271-001	Kit, Retrofit Rocket			Each	\$	
70572-001	Caps Ground Wire Kit, 2X-95-24		1.00	Each	5	
10012-001	Freight		1.00		S	
MS3126F12-10S	Plug		1.00	Each	\$	
NAS1801-08-24	Screw, Hex Head		4.00	Each	\$	

Discrepancy: 2

Problem:

Number 3 EGT INOP. T/S.

Action Taken:

Found number 3 EGT probe bad, replaced probe Operational check OK.

Part Number	Description	Credit	Quantity Units	Unit Price	Extended
16579-002	EGT Sensor (Lgr. Clamp)		1.00 Each	5	
Miscellaneous Cha	rges:				
				Misc Supplies: \$	

SICNATIBE CERT. NO. OF PERSON APPROVING OR DISSAPPROVING KIND OF INSPECTION - STATUS & DISCREPANCY LIST Autopilots Central, Inc. 3112 North 74th East Avenue

SubTotal: Charges: The articles and/or work hereon described is/are certified airworthy, (unless otherwise specified).

Autopilots Central, Inc. FAA CRS CM2R747K Printed: 4/19/2018 Work Order: MA17-05683 Page: 2 of 2