N729AJ

AIRCRAFT LOG AF5-1


weekense Cirrus Design Corp. wood SR22	одногые. <u>МАУ2015</u>
SIRLL NUMBER 4208 RECOSTRATION NUMBER N729A:	T Interest This
SCHILLT ADDRESS OTH, STATE, DP	Inspection Status (Check one) FAR. 91.499 ANNUAL/100 HOUR
STREET ADDRESS	F.A.R. 91.409 PROCRESSIVE
CITY, STATE, ZIP SEGSTERID OWNER STREET ADDRESS	FAR. 135.419 ATCO.
CITY, STATE, ZIP	OTHER DATE ENTERED
STREET ADDRESS	MAINTENANCE RESPONSIBILITY

Searched AD's through bi-weekly issue 20/5-/0. All AD's are in compliance at this time.	(39)
	R.W.

NAME OF PART	PART NUMBER	SERIAL NUMBER	INSTALLATION DATE/WOURS	TIME ON PART AT INSTALL	UL REQUIREMEN LIFE LIMIT REMOVAL ON T.B.O. DATE, WOURS	AGENCY CERT, NO.
1000000		V-1.00	Life Limite	ed Parts SR22		
	_	RT NAME S Rocket Motor	29500-004	100 to 10	EXPIRES	
		PS Parachute	29696-004	SN 0620	04/2025	
		S Reefing Line	27000-004	SNB0616 N	04/2025	
	Cut	ers Line	25347-403	S/N: S/N:	03/2026	
	ELT	Battery Pack	452-6504-1		03/2020	EMERICA N
	EM	A Controller,	20902-001	SN	9/30/2028	
	AAII	2000		A03FEB15-78	-02/2012	
	Asse	gen Bottle. , embly	102N0100-1	MFG Date_Ot/2015	01/2080 -	Foot on Birth Date
	CO	Detector	24660-004	SN 11733	04/2022	
1000		Seat Inflator	20902-002	5N: AASI 1928	03/2025	
	Co-F Inflat	Pliot Seat for Assembly	20902-002	SN: AASI 1828	03/2035	100000000000000000000000000000000000000
				10364	0712000	
					270 11 12 12 12 12	
				2000		
			THE PARTY		2 1 3 3 3 3 3	Contract of the

DATE	MAJOR ALTERATIONS DISCRIPTION OF ALTERATION	
H/16/2015	STC SA01708SE (Fixed Oxygen System) has been installed on this aircraft. Approval for installation has been granted by the STC holder via a Licensing Agreement and the FAA via the Production Certificate / Production Limitation Record. FAA Form 337 not required for this installation.	
	CDC on or 16 /2015 Cirrus Design Corporation Duluth, MN USA PRODUCTION CERTIFICATE NO. 338CE	

		INSPECTION RECORD F.A.R. 43.11-91.409	0
ATE	AIRCRAFT TIME IN SERVICE	KIND OF INCREMENT COMMAND ASSESSMENT OF THE PROPERTY OF THE PR	
May 15	2.7	Production Flight Test accomplished in accordance with Cirrus Procedure #90502. Name: Dan Ryan Date 21 MAY 15 Signature: District Production Flight Test Pilot	
YAY2015	2.7	I find that the aircraft meets the requirements for the certification requested and have issued an U.S. Standard Airworthiness Certificate dated 26 / MAY 2015. The next inspection is due 31 / MAY 2016. David C. Hallfrisch 053841467	



MAINTENANCE RECORD F.A.R. 43.9

DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED

AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE

MAKE: Cirrus Design Corp. MODEL: SR22 S/N: 4208 REG. NO: N729AJ WORK ORDER 17504-10-2015



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y 4961 Airport Road Dulum, MN 55811 Phone: 218-788-3049

DATE 11/9/2015 A/C TSN 28 6 FLIGHTTIME 28 6

Airframe Entries

AIRCRAFT TIME

IN SERVICE

LETTON

(9) Complied with SB2X-28-12R1 in accordance with the service bulletin instructions. Leak and ops checked good (10) Compiled with SB2X-31-08 Removed faulty PDF P.N24655-003 SIN 14Y006546. Replaced with New PIN 24655-003 SIN 14Y006708 reloaded software configuration files: IAW SR22 AMM 31-60. Functions check Satisfactory

(11) Replaced Pilots interior cabin door panel PIN 20348-408, IAW CDC AMM 52-10. Function check good.

(12) Removed and replaced L/H Cabin Door Foam Seal IAW CDC AMM 52-10.
(13) Removed and replaced R/H Cabin Door Foam Seal IAW CDC AMM 52-10.

I have reviewed the file on this aircraft and the accomba was repaired/inspected in accordance with current red. The reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, aircraft engine, propeller or appliance identified details of this work order are on file at this Centified Reduc Station (RS YDSR85).

DATE: 11/9/2015

SIGNED:

Work Order: 17504-10-2015

Gienn Nelson Certified Repair Station No. YD5R855Y

Printed by EBis 3 (datcomedia.com)

MAKE: Circus Design Corp. MODEL SR22 S/N 4208 REG NO N729AJ WORK ORDER 17544-11-2015



Cirrus Design Factory Service Center

Repair Station No. YDSR855Y 4961 Airport Road Dulum, MN 55811 Phone 218-788-3049

FLIGHTTIME 28.6

Airframe Entries

(4) Verified bulance within limits and reinstalled R/H elevator after paint touch-up IAW CDC AMM 55-20 and 51-30. Performed ops. check of elevator horn porous panel IAW CDC AMM 30-00. Ops check good.

I have reviewed the file on this aircraft and the accord soving discrepancy forms. The arcraft airframe, aircraft engine propeller or agginance identified was repaired impected in accordance with current red perfect of the Enderal Aviation Administration and is approved for return to service. Pertners Area of the Sederal Avanon Administration and is approved for return to service. Pertners, Sulpon CRS (DSR), 659 details of this work order are on file at this Certified Re-


DATE: 11/10/2015


SIGNED:


Work Order: 17544-11-2015

Printed by EBis 3 (datcomedia.com)

Gienn Nelson Cestried Repair Station No YD5R855Y









52275

August 23, 2018

N729AJ Aircraft 121.9 Flight Hobbs 163.2 Hobbs

erformed 100 Hour Inspection in accordance with Cirrus SR22 Scheduled Inspection Report and FAR 43 ppendix D. C/W FAR 91.207(d) ELT inspection, next inspection due again by August 2019, battery placement due by March 2020. Installed new air filter element BA-24. C/W tanis I/C/A and Bracket I/C/A W SB2X-32-22 R2 (Nose Gear Gusset Inspection) Inspected and no cracks or any other defects noted. Next due 221.9 flight hobbs or August 2019 whichever occurs first.

W SB2x-28-12R1 (Electric fuel pump inspection) Performed inspection and no leakage from vain seal. detected at this time. Next due 221.9 flight hobbs or August 2019 whichever occurs first.

W SB2x-32-23R1 (Nose Shimmy) Verified nose fork tension and tire pressure. All with in specifications. W SB2x-74-02 (Ignition switch security) Applied thread locker to ignition switch hardware per SB

W SB2x-79-08 (Remote oil Pressure Sensor Installation) Installed Kit #70605-001 per SB. No further action required.

AW SB2x-95-23 R1 (CAPS Aft grain Replacement) Removed and replaced CAPS aft grain with Kit 70596-002 per SB instructions. No further action required.

W SB2x-95-24 R1 (CAPS rocket self ground wire) Installed Kit 70572-001 per SB. No further action required.

certify that this Aircraft has been inspected in accordance with a 100 HR inspection and FAR Part 43 opendix "D" was determined to be in airworthy condition.

> Trevor Moehl 3554241 A&P

pertify that this Aircraft has been inspected in accordance with an Annual inspection and FAR Part 43 opendix "D" was determined to be in airworthy condition.

Mark Roisen 506742944 IA

INSPECTION RECORD F.A.R. 43.11-91.409 DATE Aviation Center. 27 September 2019 N729AJ 152.2 Flt. Hobbs Performed annual inspection in accordance with Cirrus SR22 Scheduled Inspection Report and FAR 43, App. "D". CW FAR 91.207(d) ELT inspection, next inspection due by October 1, 2020. Battery replacement due by March 2020. Installed new air filter element BA-24, CW Tanis ICA and Brackett ICA. Replaced TKS filter, leak checks and ops checks good (next due October 2021). Replaced both #2 batteries; ops checks good (next due October 2021). CW fire extinguisher inspection and weight check, ok. CW SBZX-32-22R2, nose gear gusset inspection: By inspection with no cracks or defects noted. Next due at 252.2 Fit. Hobbs or October 1, 2020, whichever occurs first. CW SB2X-28-12R1, eletric fuel pump inspection: By inspection with no leakage from vain seal detected. Next due at 252.2 Fit. Hobbs or October 1, 2020, whichever occurs first. CW SB2X-32-23R1, nose shimmy: By verification of nose fork tension and tire pressure. Found all within spec. I certify that this Aircraft has been inspected in accordance with an Annual inspection and FAR Part 43 App. "D" and was determined to be in airworthy condition. Mark C Roisen 506742944 Esp





13 October 2020

N729AJ

217.5 Flt. Hobbs

rformed annual inspection in accordance with Cirrus SR22 Scheduled Inspection Report and FAR 43, App. "D". CW R 91.207(d) ELT inspection, installed new 8302 ELT battery, next inspection due by October 1, 2021. Battery lacement due by October 2025. Installed new air filter element BA-24, CM Tanis ICA and Brackett ICA. V fire extinguisher inspection and weight check, ok. O' bottle removed for 5 year hydro test, next due November 1, 5; reinstalled with al lops checks good, no leaks noted. Replaced right tire with P/N 025-501-0 with new 31493-110 o-Replaced line cutters with kit #25347-003 per MM next due August 2026.


C/W SB2X-32-22R2, nose gear gusset inspection: By inspection with no cracks or defects noted. Next due at 317.6 Fit. Hobbs or October 1, 2021, whichever occurs first.

CAW SB2X-28-12R1, eletric fuel pump inspection: By inspection with no leakage from vain seal detected. Next due at 317.6 Fit. Hobbs or October 1, 2021, whichever occurs first.

W SB2X-32-23R1, nose shimmy. By verification of nose fork tension and 35 psi tire pressure. Found all within spec. rtify that this Aircraft has been inspected in accordance with an Annual inspection and FAR Part 43 App. "0" was determined to be in airworthy condition.

506742944 IA

Mark C Roisen Man (



WISCONSIN AVIATION FOUR LAKES, INC.

DESCRIPTION OF WORK DONE:

N729AJ

Complied with Cirrus SB 2X-42-19; update of system software to version 0764.38. Installed new database cards p/n: 010-00474-44 in accordance with Cirrus SB2X-42-12. Performed standby flight display ADC calibration in accordance with Mid Continent MD302 Instructions for Continued Airworthiness. Systems ramp check satisfactory.

----END---

The aircraft component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details are on file at this agency under the following work number.

DATE: 9/3/21 HOBBS: 363.7 WO#: 0518AV SIGNED: 5.7

3606 Corben Ct. - Madison, WI 53704 - CRS No. DBKR124D (608) 268-5006 (608) 268-5038 FAX

MAKE CYLIA DB9C/II Corp MODEL: 8R 22 GT 8 3H: 4200 F.EG. NO. N72NA.; WORK CRIDER: 9353-12-0021

TEA

Parks alseen No. 57C 17/35 2751 N Aspen Real Suss 11C Judg. WH 554 19 Physin MCJ 654 135 CATE: 12/13/2/21 A/C TSN: FUGHT/IME: 311.1

Airframe Entries

Installed new Right MLG Tire, 15 X 6 00 X 5, Michelin AD, Turker G. C.

The arrorat, enfrance, progress, proposition or regulation actives a progress of the Experience of the

DATE: 12/13/2021


SIGNED: Farson Valor State Contract Piepar State No. STORICCE

1Work Order: 9358-12-2021

Printed by EBis 3 (datcomedia com)

Nate: 9/20/2021; Aircraft: N729AJ; Type: CIRRUS SR22; S/N: 4208; Hobbs 0-550 - N68B, S/N: 1011979, Time: 279.0; Prop - Type: PHC-J3YF-1RF, Sincentinued** Illed the left wing TKS inner panel, filled TKS reservoirs (tw). Replaced right with new (MJM). Replaced pilots cup holder p/n 51179-001 with new (tw). Replaced the inductions strut to cowling seal p/n 53361-001(tw). Recured left and right main landing gear strut wire routing grommets with 13 illuminum doubler on the #2 alternator cover flange with AN470-3-3 rivets (tv); Cleaned EMM around the left fuel cap ring for better continuity. Resistance left experiments and cleaned the EMM around filler new ealant, p/n PR2200, to threads of the filler neck ring and re-installed right funds after sealant cured for the right fuel cap ring. Applied aerodynatificated areas on the left and right wings. Installed new fuel placards, p/n 10 cleaned left and right elevator of corrosion at area behind elevator spar at struty). Cleaned, primed, and painted affected area (CRS). Performed ground lefects noted. Will work performed in accordance with approved/current technical data. I centary accordance with an Annual inspection and was determined to be in already and painted affected area (CRS). Performed ground lefects noted. Will work performed in accordance with approved/current technical data. I centary accordance with an Annual inspection and was determined to be in already and painted affected area.	-STATUS & DISCREPANCY LIST
continued** led the left wing TKS inner panel, filled TKS reservoirs (tw). Replaced right left he left wing TKS inner panel, filled TKS reservoirs (tw). Replaced right lith new (MJM). Replaced pilots cup holder p/n 51 179-001 with new (tw). Replaced the induct ose strut to cowling seal p/n 53361-001(tw). ecured left and right main landing gear strut wire routing grommets with 13 luminum doubler on the #2 alternator cover flange with AN470-3-3 rivets (tw). Cleaned EMM around the left fuel cap ring for better continuity. Resistanuel neck. Removed right fuel cap ring and cleaned the EMM around filler neealant, p/n PR2200, to threads of the filler neck ring and re-installed right fuel and 4 ohms after sealant cured for the right fuel cap ring. Applied aerodynant flected areas on the left and right wings. Installed new fuel placards, p/n 17 leaned left and right elevator of corrosion at area behind elevator spar at selevation of corrosion at area behind elevator spar at selevation of the primed, and painted affected area (CRS). Performed ground effects noted. Work performed in accordance with approved/current technical data. I centacordance with an Annual inspection and was determined to be in airwork performed. Will say the selection of the primed and the proved of the primed to be in airwork performed. Wilsconsin Aviation - Madison 3606 Corben Court Madison, WI 53704	
lied the left wing TKS inner panel, filled TKS reservoirs (tw). Replaced right with new (MJM). Replaced pilots cup holder p/n 51.179-001 with new (tw). Re 10902-001 with new. Operational check normal (MJM). Replaced the induct lose strut to cowling seal p/n 53361-001(tw). Recurred left and right main landing gear strut wire routing grommets with 13 illuminum doubler on the #2 alternator cover flange with AN470-3-3 rivets (two): Cleaned EMM around the left fuel cap ring for better continuity. Resistance left. Removed right fuel cap ring and cleaned the EMM around filler new ealant, p/n PR2200, to threads of the filler neck ring and re-installed right fuel and 4 ohms after sealant cured for the right fuel cap ring. Applied aerodynal effected areas on the left and right wings. Installed new fuel placards, p/n 10 illeaned left and right elevator of corrosion at area behind elevator spar at skip. Cleaned, primed, and painted affected area (CRS). Performed ground lefects noted. Wilsconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 Wilsconsin Aviation - Madison 3606 Corben Court Madison, WI 53704	: 279.0; Total Time: 279.0; Engine - Typ /N: FP8600B, Time: 279.0
see strut to cowling seal p/n 53361-001(tw). ecured left and right main landing gear strut wire routing grommets with 13 luminum doubler on the #2 alternator cover flange with AN470-3-3 rivets (two Cleaned EMM around the left fuel cap ring for better continuity. Resistancel neck. Removed right fuel cap ring and cleaned the EMM around filler neck alant, p/n PR2200, to threads of the filler neck ring and re-installed right fuel and 4 ohms after sealant cured for the right fuel cap ring. Applied aerodynal ffected areas on the left and right wings. Installed new fuel placards, p/n 11 leaned left and right elevator of corrosion at area behind elevator spar at skillened left and right elevator of corrosion at area behind elevator spar at skillened, primed, and painted affected area (CRS). Performed ground effects noted. Ill work performed in accordance with approved/current technical data. I ce accordance with an Annual inspection and was determined to be in airwor imothy Woods. P36455541A Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704	eplaced seat belt EMA controller p/n
rected areas on the left and right wings. Installed new fuel placards, p/n 17 leaned left and right elevator of corrosion at area behind elevator spar at set W). Cleaned, primed, and painted affected area (CRS). Performed ground efects noted. It work performed in accordance with approved/current technical data. I ce accordance with an Annual inspection and was determined to be in airwormothy Woods P36455541A Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704	 corrected fuel cap resistance checks be check of less than 10 ohms on the le eck for better bonding. Applied conductive uel cap ring. Resistance check of less
Wisconsin Aviation - Madison 3606 Corben Court Madison, WI 53704 608-268-5003	7366-002 (CRS). everal locations on top and bottom skins
Madison, WI 53704 608-268-5003	rtify that this Aircraft has been inspected thy condition.
9	Visconsin Aviation - Watertowr 741 River Drive Vatertown, WI 53094 20-261-4567

INCDECTION RECORD Date: 9/20/2021; Aircraft: N729AJ; Type: CIRRUS SR22, S/N: 4208; Hobbs: 279.0; Total Time: 279.0; Engine - Type: IO-550 - N68B, S/N: 1011979, Time: 279.0, Prop. - Type: PHC-J3YF-1RF, S/N: FP8600B, Time: 279.0 Fit 279.0 Hobbs: 363.7. ***Airframe*** Completed an Annual inspection in accordance with FAR 43, Appendix D (tw). AD 17-16-01 (10/24/2017) Quality standards - Ameri-King ELTs, not applicable by manufacture, Artex ELT-1000 installed (sey). AD 20-19-06 (11/03/20) McCauley propeller governor idler gear bearing unapproved variant, not applicable by date of manufacture and not overhauled during date/time frame (sey). Cirrus Mandatory SB2X-32-25 (12/11/2020) Oleo strut production number, not applicable by production number 0417-18 installed (sey). Complied with Cirrus Mandatory SB 2X-34-29R1 (08/24/2020) Pitot and TKS Line Routing Inspection. Rib routing was correct. Tied pitot and TKS lines to keep separate (tw). Complied with Instructions for continued airworthiness for Brackett Filter Assembly, no defects noted (tw). Complied with Instructions for continued airworthiness for Tanis Engine pre-heater, no defects noted (tw). Complied with the six year fire extinguisher inspection thru Summit Fire Protection service, Madison, WI (tw). Inspected and tested ELT in accordance with FAR 91.207(d), no defects noted, next due AUG2022. 15-Digit HEX ID: ADC6499C643E3A1. Country Code: 366. ELT battery due JAN2027 (tw). Replaced left and right brake linings with new using kit p/n 31392-105 (tw). Replaced left and right fuel cap seals using overhaul kit p/n 300 (tw). Bled the left wing TKS inner panel, filled TKS reservoirs (tw). Replaced right wing outboard static wick p/n 33266-001 with new (MJM). Replaced pilots cup holder p/n 51179-001 with new (bw). Replaced seat belt EMA controller p/n 20902-001 with new. Operational check normal (MJM). Replaced the induction air filter BA24 (tw). Replaced the nose strut to cowling seal p/n 53361-001(tw). "continued" Wisconsin Aviation - Madison Wisconsin Aviation - Watertown 3606 Corben Court 1741 River Drive Madison, WI 53704 Watertown, WI 53094 608-268-5003 920-261-4567



INSPECTION RECORD F.A.R. 43.11-91.409 KIND OF INSPECTION-STATUS & DISCREPANCY LIST - CERT, NO, OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE AIRCRAFT TIME IN SERVICE DATE Quality Aviation, Inc. 3401 W. Trunk Hwy 21 N Faribault, MN 55021 Di 1-866-865-1777 Co N729JA Aircraft Log book entry. Cirrus SR22 S/N 4208 ma Date: 03/07/2022 Hobbs: 432.2 Aircraft TT: 333.1 FLT Hobbs: 333.1 * [Replaced the left main tire with, P/N Michelin 15X6.0-6 025-501-0 * Replaced both the right and left nose wheel pant brackets with new, P/N 11799-004. The nose landing gear fork rotation tension was adjusted per MM 32-20. Gerald L. Serres A&P IA 3496061 Fall J Ic ain


	CHECKED	CHECK	EXPROPER OR RESULTS	NEXT CHECK.	ORECKED SY:
-			A 6		SIGNATURE CERT, N
	N729AJ	9 FEB 2023 HOBE	BS: 0514.2 WO# A1	0490 PAGE 1-1	
Inst	alled Garmin Flig	ht Stream 210 PN:	011-03257-40 SN: 3R	010646164040	
,	re age and TTO\SI	to 150 Installation !	Manual PN: 190-0170	0-00 Rev H Dated Au	g1
-	or residu operati	on and no problem	s found.		
	200	000			
SIGN	oforna	mad	DATE: 09	-FEB- ZO	23
					-
	APG Avionic	cs CRS#N1OR037B - 4	8150 Skylane Way, Pun	ta Gorda FL 33982	
		+1 (941) 637-6530	http://www.avionix.o	om	

QUALITY AVIATION INC. Certified Repair Station No. 4QIR152 ALT TEST DATA PER 14 CFR 91.411 IAW 14 CFR 43, APP.E

CIN	OMER NA	UME: Jano	en Stotts		, inches	L4CHK4	3. APP	.E	
N NO	729A		DAT	E: 09/08	/2022				
W.O.	NO.: QAI	1102	INSP	INSP. BY: Gerald L. Serres					
ALT S	N: 20611	1957	Mod	MODEL GOCZAA					
	TABLE	1				YABLE			
ALT	TOL	IND		TEST TOL MO		ann.			
-1000	20	-3020	CM						
0	20	-20	arrs	MYSTERISS 100			RM.		
500	20	480	100000	TST 50%	75		-		
1000	20	500		200 FEET AND			-		
1500	25	1500	5 30 00	ACTO ACTO				1000	
2000	30	2020		30 1140					
3000	30	3020		TABLE I		T		ie IV	
4000	15	4040	ALT	TO	1000	1	1000	SCALE	-
6000	40	6000	1000	70	MA	HG	ALY	DIF	TOL
\$000	60	8020	2000	70	AGA	-28,10	1727	,	-500
10000	80	10020	3000	70	MA	-24.50	3,5401	0	-150
12000	90	12020	5000	70	AGA .	29.00	863	3	360
14000	100	3-6020	10000	80	ALA.	29.50	392		820
16000	110	16030	15000	90	NA.	29.92	0	0	1220
18000	120	18020	20000	100		30.50	530	9	1760
20000	130	20020	25000	1000	MA	30.90	893	7	2120
22000	140		30000	140	AGA	30.99	974	6	2200
25000	155		15000	160					
10000	180		40000	180					
15000	205		50000	250		Revisions		form	

			-	FEVE
FO	IRON	IC	CH	ECKS

ERROR OR	NEXT CHECK	ONECOS
Date: 09/08/2022	DUE	SIGNATURE -
VO#: QA1102		
bbs: 459.0		
J ACTT: 356.0		
tests required by 14 , including data been performed		
ppendices E and F.		
dentified above was repaired ederal Aviation Administration Pertinent details of the		
ty Aviation, Inc. FAA Certified		
Form 1-1		



AJRCRAFT TIME IN SERVICE

KIND OF INSPECTION-STATUS & DISCREPANCY LIST CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE





APG Aviation - Maintenance & Repair 28000 Airport Rd. A-17 Punta Gorda, FL 33982 Tel: 941-575-8605 - Fax: 941-575-8734 - ga@avionix.com

10-16-2023 N729A) CIRRUS SR22 ASN 4208 HM 571.9 FLT 444.1 ENG 444.5

CW THE 100hr INSPECTION IAW CIRRUS SR22 AMM INSPECTION CHECKLIST CH 05-20. INSPECT ELT IAW FAR 91.207d. BATTERY DATE 01-2027. LUBRICATE AIRFRAME, CW 2 YEAR MAGNETOMETER CALIBRATION, CW SA21-16 CAPS INSPECTION/CHECK, TESTED AMSAFE INFLATABLE RESTRAINT SYTEM USING SDT 508987-401. REPLACE ACFT MAIN BATTERY WITH NEW RG24-11M SN 41316886. VERIFIED EMA COMTROLLER DOM A0721 WITH A REPLACEMENT DATE OF 07-2028. SERVICE MLG WHEELS AND BRAKES. SERVICE NLG WHEEL ASSY. INSPECT NLG CASTER TENSION TO BE WITHIN LIMITS. REPLACE NLG FAIRING STRUT SEAL 533614-001U. REPLACE LANDING LIGHT 24946-002. REPAIR TKS WIRING AT #2 METERING PUMP, PURGED LEFT ELEVATOR TIP TKS PANEL, T/S TKS TANK SENSOR ERRONEOUS INDICATION, CND AT THIS TIME, REPLACE LEFT LOWER DOOR ROTARY LATCH 21889-001. ADJUST DOORS FOR PROPER CLOSURE IAW SR22 AMM, CW SB2X-25-30 CRIEW SEAT BREAK-OVER BOLT ADJUSTMENT. CW SB2X-32-26 NLG STRUT ASSY INSPECTION. NO DEFECTS NOTED. NEXT INSPECTION DUE 494.1 FLT HM. OPERATIONAL CHECK SATISFACTORY.

THIS AIRFRAME/AIRCRAFT HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AS PER CIRRUS SR22 AMM CH 05-20 AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. MAINTENANCE CARRIED OUT IAW CURRENT FAA REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED. ADS THROUGH BI-WEEKLY 2023-20.

ZURIEL ORYVAR

TTAF 444.1 FE

TTAF 444.1 FLT