AIRCRAFT LOG AF5-1

AEROTRONICS

SECTION SEQUENCE DESCRIPTION OF SECTION PAGE NUMBER 1st SECTION AIRCRAFT DESCRIPTION INSTALLED EQUIPMENT 2nd SECTION MAJOR ALTERATIONS 3rd SECTION LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS 4th SECTION 5th SECTION AIRWORTHINESS DIRECTIVE OR FACTORY BULLETIN COMPLIANCE RECORD 9 ALTIMETER & STATIC SYSTEM CHECKS [FAR 91.411] 6th SECTION 7th SECTION RADIO AND ELECTRONIC CHECKS 19 MAINTENANCE RECORD [FAR 43.9] 29 8th SECTION INSPECTION RECORD [FAR 43.11-91.409] 43 9th SECTION **Aero Products Corporation**

Copyright 1975 All Rights Reserved

AIRCRAFT DESCRIPTION

		10	100	S
	DATE OF MFG. NOU, 02	3.00	59105	be sent
SERIAL NUMBER		4	M	due
REGISTERED OWNER	Inspection Status [Check one]	3	INGS,	tement n past
STREET ADDRESS	F.A.R. 91.409 ANNUAL/100 HOUR	A		sta pt o
CITY, STATE, ZIP			CE BI	Вхсе
OPERATOR	F.A.R. 91.409 PROGRESSIVE		M	
STREET ADDRESS		1	TION P	5
CITY, STATE, ZIP		F	M	
REGISTERED OWNER		ND TO	651 A\	
STREET ADDRESS	F.A.R. 135.419 A.T.C.O.	BRA	-	$\boldsymbol{\exists}$
CITY, STATE, ZIP		9	S, INC.	Ш
OPERATOR			S	8
Or LINATOR	OTHER		S	2
STREET ADDRESS			TH	OF OF
CITY, STATE, ZIP	DATE ENTERED		AERO	CEIPT
	MAINTENANCE RESPONSIBILITY		1.	RE
			T TO	NOM
			EM	DUE (
			1 ==	

INSTALLED EQUIPMENT

	INSTALLED EQUIT	IVILIAI			7 [(0)
ITEM	MANUFACTURER	MODEL	SERIAL NO.	5	9165	sent
ENGINE	Teledyne Continental	IO550N	R 686399	-1/2	/T 5	vill be
ENGINE			R L	74	38, 1	ast d
PROPELLER	Hartzell	PHC-J34F-IRF	FPZ006B	*	ĮŽ Į	t on p
PROPELLER						Nos
ENGINE					ACE	
ENGINE					N PL	Щ
PROPELLER				AL	ATIO	4
PROPELLER				TOT 0	1 AVI	
ENGINE				RANC	165	3
ENGINE				. 5	NG.	
PROPELLER					IICS,	OICE
PROPELLER					8	N H
ENGINE					5	PT 0
ENGINE					AE	RECE
PROPELLER					Ü	PON
PROPELLER					EMI	UE U
] =	
						3

2/2/2

	INSTALLED EQU	IIDAAFAIT	MAJOR ALTERATIONS MAJOR ALTERATION	2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -
ITEM	MANUFACTURER		MAJON PALTERATION DESCRIPTION OF ALTERATION	一
ENGINE		MODEL		
ENGINE		DATE		可量を参
PROPELLER		R		班 老美
PROPELLER				3
ENGINE				
ENGINE				- 4 E
PROPELLER				
PROPELLER				3 2 2
ENGINE				3 4
ENGINE				级 级
PROPELLER				
PROPELLER				EPOTRO F.
ENGINE				
ENGINE				i i i
PROPELLER				ES
PROPELLER				
				- 21

MAJOR ALTERATIO	NS ,	LIFEL	IMITED PAI	RTS OR OVER	HAUL R	EQUIREME	NTS	2 S T 1 S S
DATE DESCRIPTION OF ALTER		AME OF PART NUMBER	SERIAL INSTA	HOURS AT INSTALL.	OR T.B.O.	REMOVAL DATE/HOURS	AGENCY CERT. NO.	1 59 P
DATE DESCRIPTION OF ALTER		PART NA CAPS Rocket N CAPS Parach CAPS Reefing Cutters ELT Batterie Turn Coordinator/R Computer Batter	Life Limited ME PART NUMB Iotor 12582-104 ute 15046-002 Line 5212 MN1300 MN1604 ries	ER S/N 00 6 7 6 0 S/N 00 6 7 3 09 Tosoo E 2003 - 0 LOT Date Installed 0 / 2 0 0 2 0 Date Installed	EXPIRES 9/20/2 9/20/2 0/2009 U/A	Replaced Line ch	AGENCY CERT. NO.	REMIT TO: AEROTRONICS, INC. 1651 AVIATION PLACE BILLINGS, MT 59105 Due upon receipt of invoice NVOICE exception past due accounts
								d So d

A.D./BULL.		DATE & HRS.	METHOD OF	TYPE OF A.D.	NEXT COMP. DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.				F.A	.R. 91.41		DECHECK I	APPRO	1/9
NUMBER	AFFECTED	AT COMP.	COMPLIANCE	1 TIME/RECUR.	DATE/HRS./CICLL	D. D.	ATE M	ANUFACTURER	MODEL	SERIAL NO.	LOCATION	MAX. ALT.	RECHECK REQUIRED	AGENCY C	- 3
							I an 9 w A T T T T T T CD Cirr	certify that the nd altitude report 1.413, & 91.2 within the limit AC 43-6A. ESTED TO_ ransponder: I	e altimeter orter test in 17 have be sof FAR 4 17,500 Mfg Gar GTX-327 ACK United	required by Freen preformed 43 appendices FEET 0 min P/N 13 S/N 337 P/N A-30 P/N 12731 S/N 43-83	n, transpond AR's 91.411 I and found SE & F and N 10/15/03 3587-050 1154/ S/N 8083 -001 on 10/15	er,			GRAND TOTAL GRAND TOTAL

	LATION TIME ON PART LIFE LIMIT REMOVAL AGENCY					VUKIIII	NE33 DII	KECIIVE/	FACIORY BULLETIN	COMPLIANCE RECOR
E/HOURS	AT INSTALL.	OR T.B.O.	DATE/HOURS	AGENCY CERT. NO.	A.D./BULL. NUMBER	AFFECTED	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. NEXT COMP. 1 TIME/RECUR. DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.
					2002-23		11/19/02 35 hrs	weekly	d AD's through bissue 2002-23. All e in compliance at this	Supy (SUPV)

				ECTRONIC C	HECKS					RADIO & E	LECTRONIC	CHECKS	CHECKED BY: SIGNATURE — CERT. NO.	1
DATE	TOTAL	EQUIPMENT	TYPE OF CHECK	RESULTS	NEXT CHECK DUE	CHECKED BY: SIGNATURE — CERT. NO.	DATE	TOTAL TIME	EQUIPMENT	TYPE OF CHECK	RESULTS	DUE	SIGNATORE	=
				11 1										7
	5	cont	inured in	1300Ch	4									
														IN TOTA
														GRAN
					*									

		MAINTENANCE RECORD					
2		F.A.R. 43.9				MAINTENANCE RECOF	RD -
DATE OF COMPLETION .	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	WORK PERFORMED/RETURNED 101			F.A.R. 43.9	
CONTILLING	INSERVICE		TALKS STATE	DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SE
		MODEL: SR22 HOBBS TIME: 27.8S/N:037	75				
	cirri cirri PN: Dec	maintenance practices. Lubricated cabin air serus mm. Ch. 12. Repaired multiple minor cosmetic discrettus MM. CH. 51. Installed stormscope system, the presented in the presentation of th	selector IAW epancies IAW processor box 0-3 dated 17 ned for further	Model:	N437C : Cirrus SR22 #: 0375 Order #: 17857	Aviation Services	Hobbs: 75.4 Tach: Total Time: Date: 1/29/03
	on the store of th	formation. Equipment list and weight and balance update ormscope system. Removed and replaced baggage door sea 2 IAW cirrus MM. CH.25. The work identified above was performed in accordance with the current guilation and was found to be airworth for retent to service. Pertinent det agency under. 10#:121402-02 SIGNED Design Factory Service Center, CRS# YD5R855Y, 4515 Taylor Circle, Dulled Control of the con	ted to include all PN: 50210-		baggage door drain h	FAA Repair Station ACOR030C	

Reg #: N437C Model: Cirrus SR22 Serial #: 0375

Work Order #: A8462

Aviation Services

Hobbs:

Tach:

Total Time: 49.1


Date: 3/26/03

Removed autopilot computer p/n 13560-001S, s/n 4687 AE/AE. Installed new warranty exchange autopilot computer p/n 13560-001S, s/n 5041 AG/AE. Ops checks normal.

> For: Air Care, Inc. FAA Repair Station

> > AC0R030C

RWI AIRPORT ROCKY MOUNT, NC 27804 PP.REPAIR STATION NO.ACOROSOC



HAWTHORNE		MARKALL VA 22E02			
		(757) 857-3413	Reference W		
Aircraft #	N437C		Total Time	203.2	
Make:	Cirrus		Hobbs	203.2	
Model:	SR-22		S/N:	0375	

- Complied with Cirrus Service Bulletin 2X-30-01 "Replacement of wing proportioning unit and bracket" by removing old valve p/n PU300EN126 s/n AST021C274 and installed new valve p/n PU300EN126 s/n AST03C621 on right side. Left side p/n off PU300EW126 s/n AST021C371 and installed p/n AST300EW126 s/n AST03C859. No problem noted with either bracket.
- Complied with Cirrus Service Bulletin 2X-71-05 Induction assembly support bracket installation kit # 70051-001.
 - Complied with Cirrus Service Bulletin 2X-57-03 "Wing tip shear pin engagement" for proper pin engagement, No Problem Noted.
 - Complied with Cirrus Service Bulletin 2X-30-02 "Ice protection slinger tube inspection" Slinger tube found to be aligned correctly, no further action taken.
 - Complied with Cirrus Service Bulletin 2X-57-04 "Outboard Aileron Hinge Inspection" No Problems Noted.
 - Removed and replaced pilots push to talk switch with new p/n 50339-001. Operational checks good. Checked aileron rigging per Cirrus SR22 maintenance manual Chapter 27-10-04. Rigging checks
 - good. Bent fixed trim tab and advised customer to check on next flight. Removed and replaced right forward engine baffle with new p/n 13669-003.
 - Removed and replaced right position light with new p/n 34-0428070-64 and right nav light bulb p/n 7512-24. Operational checks good.
 - Complied with Cirrus Service Bulletin 2X-24-02 R1 by installing parts listed in kit 70057-002. Alternator wire has ample clearance and will not chafe .

The maintenance operations described above were performed and inspected in accordance with the applicable rules of 14CFR part 43, and with respect to the work performed, this aircraft is approved for return to service.

Date: 07-08-03



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

SR22

Date

10/21/2003

S/N:

0375

W.O.:

M031012

Reg #:

N437C

HOBBS: Landings: 263.3

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

The Cirrus SR22 S/N 0375 aircraft was inspected I/A/W current maintenance rules of the Federal Aviation Regulations for an Annual Inspection union the manufacturer'e Inche-41-

COMPLETION

AIRCI

SERVICE

DESCRIPTION OF

APPROVED DATA

PERFORMED TA USED

WORK PERFORM

& CERTIFICATE NO. ED/RETURNED TO SERVICE

CERTIFICATE

Approving National Avigition

2

Authority/Country:

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

Reg #:

S/N:

SR22

0375

N437C

Date

10/29/2003

W.O.:

M031029

ACTT: Landings:

278.7

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed defective alternate air bracket P/N 15196-001 and installed new serviceable bracket P/N 15196-002 I/A/W SR-22 MM Chapter 71.

Checked data programming of Sandel H S I and reprogrammed. Checked the # 1 and # 2 GPS receivers programming and reprogrammed. Checked the ATC Transponder programming and reprogrammed to accept GPS and encoder Interface Information. Functions checked H S I, GPS and Altitude information output and inputs. All system and message error checked good afterwards.

Ran aircraft. Leaned fuel for temp increase. Brought back rich. Ran aircraft at 2,000 RPM. No defects noted.

1 EGT 1260 CHT 274

2 EGT 1290 CHT 288

#3 EGT 1295 CHT 288

4 EGT 1350 CHT 270 # 5 EGT 1315 CHT 288

6 EGT 1360 CHT 296

Signed:

AP226987565IA

Print:

REMIT TO:

John T. Gardner for

COMMONWEALTH AVIATION SERVICE, INC.

GRAND TOTAL

AEROTRONICS, INC. 1651 AVIATION PLACE


BILLINGS, MT

MAINTENANCE RECORD .9

ns of

DUE UPON RECEIPT OF INVOICE

No statement will be sent except on past due accounts



ns of

DUE UPON RECEIPT OF INVOICE

INVOICE

No statement will be sent except on past due accounts

DATE OF COMPLETION

AIRCRAFT TIME IN SERVICE

DESCRIPTION OF WI OR APPROVED

1/12/2004

M040110

313,2

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC TO BE ALOR

dole MILLION AIR - RICHMOND

MANUFACTURER CITUS

SRZ

Date

W.O.

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft ancifor component identified above was repaired and inspected accordance with current Federal Aviation Regulations and was found airwork for return to service. Pertinent details of the repair are on file at this agency.

Investigated leak on right hand brake and found worn o-rings on the brake cylinder assembly piston. Replaced both o-rings with new MS28775-222 orings and reinstalled brake cylinder assembly. Bled system and reserviced braine reservoir. Stains operates normally.

APZZLAY 7565 IA

John T. Guidner

COMMONWEALTH AVIATION SERVICE, INC.

LOGBOOK BITTIV

COMMONWEALTH AVIATION SERVICE

THE DELLE LANDING TO BE SERVICE OF THE PARTY OF THE PARTY

dow MILLION AIR - RICHMOND

MANUFACTURER Cirrus

1/21/2004 M040117

314.6

Landings

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

inspected wear mark in left flap and found that it was just in the paint and had not gone into the skin. Also determined that the Chaff tape was installed on the left flap skin was not put in the correct location to be effective as compared the right flap skin. After conversation with oustomer, it was agreed to removed the chaff tape on the left flap. Touched up the painted area and put chaff tape at the same location as the right. When chaff tape was removed, portions of the paint on the left flap skin came off. This was because the surface did not have any primer. The left flap was removed and the painted area on the upper surface of the flap behind the seam line was blended at the area where the paint lifted and scuffed the remaining portion. Masked the flap as needed.

Primed and painted the flap skin to match original paint. Installed chaff tape at location to match right flap. Reinstalled left flap. Removed both flap torque tubes to investigate play and found movement at all connections. Reinstalled torque tubes and tightened all connections as needed to remove play at flaps.

APZZL987565IA

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

MAINTENANCE RECORD

F.A.R. 43.9

SHOW THEFT THE TH' SERVICE

MAN Mode S/N Reg 4

GENET & CERTIFICATE NO. WHERE PERFORMED/RETURNED TO SERVICE

DESCRIPTION OF WORK PERFORMENT OR APPROVED DATA LISED

Plens Annual Street

Mödel: Capping	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SER	LAIRC	MAINTENANCE RECO F.A.R. 43.9 DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE WORK PERFORMED/RETURNED TO SERVICE
Work Order #: 18567	Aviation Services RON SYSTEM	Hobbs: 387.0 Tach: Total Time: Date: 5/27/04	Reg #: N437C Model: Cirrus Serial #: 0375	SR22 Aviation Services 18630	Date: 7/9/04
NO FURTHER ACTION TAK	RON SYSTEM AND FLAP SYSTEM. AD EN. FOR FURTHER DETAILS SEE WO# For: Air Care, Inc. FAA Repair Station ACOR030C	JUSTED R/H FLAP AS NEEDED. 18567 ON FILE THIS STATION. AIR CARE, INC. RWI AIRPORT ROCKY MOUNT, NC 27804 APP.REPAIR STATION NO ACCRESSE	O1 by replacing stars SB 2X-55-10 by in 08R1 by visual ins	eR1 by visual inspection of selector valve extension. Four stalling kit p/n 70067-001. C/W SB 2X-95-07 by installing arter p/n 656181B24U s/n 04-89-0007. C/W SB 2X-34-00 estalling kit p/n 70070-001. C/W SB 2X-24-03 by installing pection. No defects noted. Installed kit p/n 70071-001. C/S instructions. Adjusted L/H flap as needed. Ground rand details see WO# 18630 on file this station	ing sealant on MCU. C/W SB 2X-32- C/W SB A2X-25-08 by adjusting both aircraft and systems ops checked
				FAA Repair Station ACOR030C	ROCKY HOUNT, N.C. 27801 PAA APP. REPAIR STATION NO. ACCROSOC
			8/1/04	SB 2X-95-08 corrected replacement dute Time contras Holk	REMIT TO:

INSPECTION RECORD

F.A.R. 43.11-91.409

KIND OF INSPECTION - STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE BILLINGS, MT Production Flight Test accomplished in accordance with Cirrus Procedure #90502. Name: Rory Papenfuss Date: 19 Novoz

Signature: Magnetine

Title: Production Flight Test Pilot

DMIR410073CE

I find that the aircraft meets the requirements for the certification requested and have issued a Standard Airworthiness Certificate dated 11/19/02. The next inspection is due_11 / 30 / 03 Jeffrey K. Holter

AGENCY & CERTIFICATE NO.
WORK PERFORMED/RETURNED TO SERVIO AIRCRAFT TIME IN SERVICE DATE

11/19/02

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Landings:

W.O.:

10/1/2004

505.9 HOBBS

M040938

AIRFRAME LOGBOOK INSERT

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND

AIRCRAFT TIME

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed upper cowling. Removed aircraft battery. Installed a serviceable new battery after servicing and charging. Reinstalled upper cowling. Performed operational check of the charging system. System checks good. P/N off/on G-243. S/N off G02051612. S/N on G02157736.

Removed cracked left inboard flap fairing from flap hinge fitting. Installed a serviceable new flap hinge fairing P/N 15065-004 I/A/W SR22 MM.

DATE OF

MANUFACTURER Cirrus

SR22

0375

follow AP226987565IA

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

AIRFRAME LOGBOOK INSERT

W.O.:

Landings:

10/11/2004

M014014

514.2

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed cracked right wing inboard flap fairing and installed serviceable new fairing P/N 15065-001 I/A/W Cirrus SR22 MM.

AP22LAY7565TA John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

AEROTRONIC 2 REMIT Due up

No stater

INSPECTION RECORD

F.A.R. 43.11-91.409

AIRCRAFT TIME KIND OF INSPECTION - STATUS & DISCREPANCY LIST DATE SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE IN SERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

N437C

ACTT:

Landings:

APZZ6987S65IA

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworth for return to service. Pertinent details of the repair are on file at this agency.

AIRFRAME LOGBOOK INSERT

Removed cracked right wing inboard flap fairing and installed serviceable new fairing P/N 15065-001 I/A/W Cirrus SR22 MM.

John Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

Date

W.O.:

ACTT:

Landings:

9/18/2004

M040917

499.2

MANUFACTURER Cirrus

Model: S/N:

10/11/2004 Reg #:

M041014

514.2

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Did not comply with SB 2X-25-09 - seat belt anti-rotation tab at this time. Kit is not available at this time.

Complied with SB 2X-25-05 R1, Release of Am-Safe Mandatory SB's.

Complied with SB 2X-25-06 R1 - Crew Seat Recline Lock Installation.

- AP276987565IA John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

INSPECTION RECORD F.A.R. 43.11-91.409

KIND OF INSPECTION - STATUS & DISCRE SIGNATURE - CERT. NO. OF PERSON APPROVING OR DIS AIRCRAFT TIME INSERVICE

11/8/2004

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC INCOMOR AND TOURS d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

M041104 531.0 ACTT:

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Auto-pilot system ground checked good. Removed auto-pilot computer. Installed serviceable repaired auto-pilot computer. The auto-pilot system tested good. P/N off/on 01192-34-61T-30. S/N on 5041.

DATE

Signed: Schill AP226987565IA John T. Gerduer

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station



ROTRONIC

REMI DUE L

KIND OF INSPECTION NO. OF PERSON APPROVING & DISCREPANCY LIST OR DISSAPPROVING AIRCRAFT FOR

SERVICE

DATE

AIRCRAFT TIME IN SERVICE

SIGNATURE

CERT. NO. OF PERSON APPROVING OR DISSAPPROVING

AIRCRAFT FOR SERVICE

RECOR

DATE

AIRCRAFT TIME IN SERVICE

SIGNATURE

CERT.

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

S/N:

Reg #:

SR22

N437C

0375

Date W.O.:

ACTT:

10/27/2004

M041029 519.6

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

The Cirrus SR22 S/N 0375 aircraft was inspected I/A/W current maintenance rules of the Federal Aviation Regulations for an Annual Inspection using the manufacturer's inspection guide and is approved for return to service.

Removed life vests S/N's B42315, B42204, B42260 and B42240 for inspection. Renstalled life preservers after inspection.

Touched up paint on lower engine cowling as required.

Removed nose tire and wheel assembly from aircraft. Inflated nose tire to max pressure and placed in water tank for several minutes. No leaks were detected. Deflated tire to recommended tire pressure I/A/W Cirrus MM Chapter 12 Servicing. Reinstalled tire and wheel assembly I/A/W Cirrus MM Chapter 32.

Adjusted left flap rod one half turn down as requested I/A/W Cirrus MM Chapter 27.

Serviced battery fluid as required.

Installed missing muffler heater shroud attach hardware as required.

Removed induction air filter and replaced with new filter P/N BA24.

Secured left hand and right hand MLG brace anchor nutplates with structural adhesive.

Installed 7 Rubber anchor nuts P/N 50803-001 on left hand wing upper fairing I/A/W Cirrus MM.

Installed 3 Rubber anchor nuts P/N 50803-001 on right hand wing for the upper fairing I/A/W Cirrus MM.

Repaired several eroded areas on left hand and right hand wings at leading edge with structural adhesive. Primed, painted and applied erosion tape to repaired areas.

Tensioned the aileron control cables to the correct tensions I/A/W the Cirrus MM Chapter 27-10.

Tensioned the elevator control cables to the correct tensions I/A/W Cirrus MM Chapter 27-30. OP's check OK at this time.

Removed cabin headliner. Tightened right hand cabin door lower pin receptacle screw. Reinstalled cabin headliner. Checks good I/A/W Cirrus MM 52-10.

Removed loose rivet from lowest point of rudder trim tab and installed new rivet P/N CR3212-4-2. All rivets now tight.

Replaced elevator trim cartridge rod end with a new rod end P/N 11314-003. Verified rigging of elevator trim cartridge I/A/W Cirrus SR22 MM.

Removed and replaced the rubber grommet on the left MLG strut with new grommet P/N 10209-001 I/A/W Cirrus MM Chapter 32-10.

Complied with SB 2X-28-03, Installation Of Fuel Selector Valve Extension Shaft Sleeve, I/A/W accomplishment instructions. No further action required.

Complied with SB 2X-25-09, Installation of Seat Lap Belt Anti-Rotation Clips I/A/W accomplishment instructions.

Removed alcohol filter and installed new filter P/N 15165-009 as required.

Removed outside air temp gage / clock battery and installed new battery as required.

AP226987565IA

Signed:

Print:

John T. Gardner COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

FREIGHT

GRAND TOTAL

BILLINGS, MT 59105

No statement will be sent

except on past due accounts

DUE UPON RECEIPT OF INVOICE

REMIT TO:

AEROTRONICS, INC. 1651 AVIATION PLACE

INSPECTION RECORD F.A.R. 43.11-91.409

DATE

AIRCRAFT TIME IN SERVICE

KIND OF INSPECTION - STATUS & DISCREPANCY LIST

SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model

S/N:

Reg #

SR22

0375

N437C

W.O.: ACTT:

Date

Landings:

12/1/2004

AV041115

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Ground checked the auto-pilot system. Checked the auto-pilot input configuration and connection at the flight guidance programmer computer. System ground checked good.

Checked # 1 and # 2 VOR calibration and found the # 2 VOR was off. Calibrated the # 2 VOR I/A/W Cirrus MM Chapter 34-40.

LUMIN APZZG9875G5JA John T. Gardner

> COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Circus

Model: S/N:

Reg #:

SR22 0375

N437C

Date W.O.:

561.1

12/27/2004

M041222

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Adjusted alternate air door as required.

Complied with SB 2X-25-07, Dual Inertia Reel Seat Belt Installation I/A/W accomplishment instructions. No further action required.

Signed:

APZZ6987565IA

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

John T. Gardner

INSPECTION RECORD F.A.R. 43.11-91.409

KIND OF INSPECTION - STATUS & DISCREPANCY LIST AIRCRAFT TIME SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE DATE IN SERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

S/N:

Reg #:

SR22

0375

N437C

2/8/2005 Date AV050205 W.O.:

590.5 ACTT:


Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed weather controller boxes. Removed pilot's and co-pilot's seats. Displaced and removed panels to gain access for installation of convenience power kit. Installed components for convenience power. Reinstalled all removed panels and components.

Signed:



John T. Gardger

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model: S/N:

SR22

2/22/2005 Date AV050221 W.O.:

Reg #:

N437C

600.6

Landings:

ACTT:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed HS I to shop for repair. Removed and replaced projection lamp with new long life lamp P/N 90122-B I/A/W service letter instructions for Sandel Model SN3708 H.S.I. Reinstalled H.S.I in aircraft. Performed functional checks to all HS I functions. All checks were good. Zeroed lamp hour meter in HSI. New lamp hours is 0.0 hours with TAT of 600.6 Hours.

APZZL'ISTSGSTA

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

John T. Gardner

INSPECTION RECORD 1.11-91.409

> PECTION - STATUS & DISCREPANCY LIST RSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE



LOGBOOK ENTRY

MANUFACTURER Circus

SR22

0375

N437C

W.O.: ACTT:

Date

633.4 Landings:

4/14/2005

M050414

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed brake gear plates and inspected brakes. Found all seals leaking on both brake assemblies and all brake linings worn. Measured brake discs. Left disc measure at 0.367" and right disc measured at 0.352". Minimum allowable thickness is 0.327". Removed left and right brake assemblies and inspected all brake components. Installed 1 new o-ring P/N MS28775-222 on left brake. Removed all brake linings and replaced with new linings P/N 066-10500 I/A/W Cleveland CMM. Installed brakes on left and right MLG wheels. Bled brakes VA/W Cirrus SR22 MM 30-52. Right brake continued to leak statically. Removed right brake and replaced o-ring on lower cylinder. Reassembled right brake and installed. Bled brakes I/A/W Cirrus SR22 MM. Reinstalled brake access plates and engine cowling.

AP2ZG187SGSIA John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC.

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Circus

S/N:

5/6/2005

Reg #:

W.O.: ACTT:

Date

AV050507

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed and replaced batteries in # 2 battery pack with new batteries P/N 50979-0001. OP's checked good afterwards.

APZZGGY7565IA John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

F.A.R. 43.11-91 KIND OF INSPECTIO AIRCRAFT TIME SIGNATURE - CERT. NO. OF PERSON IN SERVICE DATE LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC IN SOMOBLE LEGISLE AND HORSE d/b/a MILLION AIR - RICHMOND MANUFACTURER Cirrus 6/17/2005 Date SR22 AV050520 W.O.: 0375 675.7 ACTT: N437C Landings: AIRFRAME LOGBOOK INSERT The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency. Contacted Cirrus Design technical support concerning the auto-pilot intermittently disengaging. Per their instructions checked connector # 521 and turn and bank connector for pin tension wire connection and pin security. Also checked connector # 550. All checked good. Checked the auto-pilot system and the system checked I/A/W Cirrus MM at this time. Per technical support's instructions removed turn coordinator unit and replaced with serviceable turn coordinator. The system checked I/A/W Cirrus MM. P/N off 12733-001 S/N 13825G. P/N on 12733-001S S/N 13943G.

INSPECTION REC

APZZCANISCSIA John T. Gredner

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

ANC

SERVICE

7 G

AIRCRAFT TIME

SIGNATURE

NG OR DISSAPPROVING

AIRCRAFT FOR SERVICE

AIRCRAFT TIME IN SERVICE

SIGNATURE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC.



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

S/N:

Reg #:

SR22

0375 N437C Date

10/26/2005 M051020

W.O.:

830.2 ACTT:

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

The Cirrus SR22 S/N 0375 aircraft was inspected I/A/W current maintenance

rules of the Federal Aviation Regulations for an Annual Inspection using the manufacturer's inspection guide and is approved for return to service.

AD 2005-17-19C crew seat modifications previously complied with during incorporation of SB 2X-25-06 and SB 2X-25-08. No further action required.

Inspected brake pads and o-rings. Found pads to be well within limits at this time and no leaks were noted around brake pukes. Customer advised. No further action taken.

Replaced Sandel Projection lamp with new lamp P/N 3308-00BL S/N 4359 I/A/W Sandel Installation Manual. Reset lamp hours to zero.

Removed old sealant from left strut fairing stand off and cleaned surface. Reattached stand off back onto strut using Scotchweld 2216 Epoxy.

SB 2X-57-06R1.

Removed old broken inboard flap fairings and installed new style fairings I/A/W

Removed old sealant from passenger cup holder and floor pan in cabin. Reattached cup holder using Scotchweld 2216 epoxy.

Tightened elevator trim cartridge rod end as required.

Inspected Interconnect between pilot's and co-pilot's stick. Tightened interconnect bolts.

Removed broken clamp on the de-ice line adjacent to the # 5 cylinder and replaced with new clamp.

Repositioned alternate air duct lever to prevent chaffing into cowling and air induction tube.

Repositioned prop de-ice nozzles to prevent chaffing on the spinner.

Removed old induction air filter and replaced with new filter P/N BA-24.

Removed defective muffler heat exchanger and replaced with new heat exchanger P/N 14837-001 I/A/W SR22 MM Chapter 78-20.

Removed defective left muffler and replaced with new muffler P/N 14836-001 I/A/W SR22 MM Chapter 78-20.

Removed right main landing gear strut. Removed upper strut fitting and installed a new upper strut fitting and main bolt. Reinstalled strut. Bled brakes I/A/W Cirrus SR22 MM.

Removed defective right strut lower brake line and replaced with new brake line P/N 50555-072. See previous entry this work order for bleeding brakes.

Removed right MLG's lower strut fitting and brake assembly. Removed right strut grommet and installed a new grommet I/A/W Cirrus MM. Reinstalled brake assembly and lower strut fitting.

Tightened NLG's left tow pin as required.

Removed NLG tire and wheel assembly. Disassembled, realigned inner tube and reassembled. Installed tire and wheel assembly I/A/W Cirrus SR22 MM. Inflated tire as required.

Complied with SB 2X-57-05 R1, Attach Fittings Aileron Hinge Bearing and Gap Instructions I/A/W accomplishment Instructions.

Cut and sanded off delaminated area on right MLG lower inboard wheel fairing. Fiberglassed from inside only. Repaired by replacing 2 Inner glass plies.

Signed:

Prin

APZZUGY7565TA John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

STATUS & DISCREPANCY LIS

APPROVING OR

DISSAPPROVING

AIRCRAFT FOR

REMIT TO: AEROTRONICS, INC. 1651 AVIATION PLACE BILLINGS, MT 59105

AIRCRAFT TIME IN SERVICE

KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE - CERT. NO. OF PERSON APPROVING OF DISCAPPROVING AIRCRAFT FOR CERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC. AND THE PROPERTY AND TH

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

S/N:

Rea #:

N437C

W.O.: ACTT:

Date

M051207 866.8

12/2/2005

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Complied with SB 2X-28-04 R1, Distribution Fuel Line Chafing, I/A/W accomplishment instructions. No further action required on this SB.

Removed plug connection from oil pressure sender and cleaned. Reinstalled connector. Ran engine. Oil pressure Indications are normal at this time.

AP27697565IA John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC TO TO THE STREET AND THE STREET AND

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

Reg#:

SR22

N437C

Date 12/27/2005 W.O.:

M051226 8.688

ACTT:

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed interior seats and panels to gain access to circuit board and relays. Troubleshot and found up directional relay intermittent. Removed defective relay and replaced with serviceable relay P/N 0-332-209-204. OP's check OK. Reinstalled all panels and seats. All work done I/A/W Cirrus Design SR22 MM and wiring manual.

Removed upper cowling and removed defective oil pressure sensor. Installed new sensor P/N 12635-002. Oil pressure gauge OP's check good on ground run. Reinstalled upper cowling.

APZZEGYTSESIA

Signed:

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC IMACNOEL, ELECTRICITATION AND HORSE d/b/a MILLION AIR - RICHMOND

2/22/2006 MANUFACTURER CITUS Date M060244 W.O.: 960.5 0375 ACTT: N437C

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed nose tire and wheel assembly. Disassembled tire and wheel assembly and discarded old tire and inner tube. Cleaned and inspected all wheel components. No defects noted. Reassembled with a new tire and inner tube. Balanced as required. Torqued and inflated I/A/W Cirrus SR22 MM and wheel placards. Installed tire and wheel assembly on aircraft. Tire P/N off 505C66-5 S/N 20820771. Tire P/N on 070-312-0 S/N 3172W00357.

s-annual-John T. Gariner AFZZG987SGSTA

> COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC IN MORE AND MORE d/b/a MILLION AIR - RICHMOND

CRS VXWR051W 3/14/2006 MANUFACTURER CIMUS Date AV060306 W.O.:

983.1 0375 ACTT: N437C Landings:

OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Installed Garmin Terrain update P/N 011-00280-10 S/N 97111773 Into # 2 GNS430 COM/NAV/GPS I/A/W Service Bulletin 0532.

F.A.R. 43.11-91.409

John T. Gardener

- Alli Lillellen

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station No. VXWR051W

INSPECTION RECORD F.A.R. 43.11-91.409

AIRCRAFT TIME DATE IN SERVICE

KIND OF INSPECTION - STATUS & DISCREPANCY LIST

Reg#:

SIGNATURE - CERT. NO. OF PERSON ADDROVING OR DISCARDOOUTING AIRCRAFT FOR CEDVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

S/N:

Reg #:

SR22 0375

N437C

W.O.:

Date

M051207 ACTT:

866.8 Landings:

12/2/2005

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Complied with SB 2X-28-04 R1, Distribution Fuel Line Chafing, I/A/W accomplishment instructions. No further action required on this SB.

Removed plug connection from oil pressure sender and cleaned. Reinstalled connector. Ran engine. Oil pressure indications are normal at this time.

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

APZZUYYTSGSIA

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC.

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

0375

SR22

N437C

Date W.O.: ACTT:

M051226 889.8

12/27/2005

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed interior seats and panels to gain access to circuit board and relays. Troubleshot and found up directional relay intermittent. Removed defective relay and replaced with serviceable relay P/N 0-332-209-204. OP's check OK Reinstalled all panels and seats. All work done I/A/W Cirrus Design SR22 MM and wiring manual.

Removed upper cowling and removed defective oil pressure sensor. Installed new sensor P/N 12635-002. Oil pressure gauge OP's check good on ground run. Reinstalled upper cowling.

APZZENYTSESTA

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

INSPECTION RECORD F.A.R. 43.11-91.409

*** INSPECTION - STATUS & DISCREPANCY LIST

Model

Reg #:

S/N:

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus SR22

Model S/N: Reg#:

0375 N437C

AIDCDAFT TILIF

W.O.: ACTT:

960.5 Landings:

2/22/2006

M060244

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed nose tire and wheel assembly. Disassembled tire and wheel assembly and discarded old tire and inner tube. Cleaned and inspected all wheel components. No defects noted. Reassembled with a new tire and inner tube. Balanced as required. Torqued and inflated I/A/W Cirrus SR22 MM and wheel placards. Installed tire and wheel assembly on aircraft. Tire P/N off 505C66-5 S/N 20820771. Tire P/N on 070-312-0 S/N 3172W00357.

John T. Garaner

Certificate #

AFZZG987SGSTA

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC.

OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

d/b/a MILLION AIR - RICHMOND CRS VXWR051W

Date

W.O.:

ACTT:

MANUFACTURER Cirrus

SR22 0375

N437C

AV060306 983.1

3/14/2006

Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Installed Garmin Terrain update P/N 011-00280-10 S/N 97111773 into # 2 GNS430 COM/NAV/GPS I/A/W Service Bulletin 0532.

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station No. VXWR051W

Aut	ing National Aviation hority/Country: JNITED STATES		ED RELEASI 8130-3, AIRWORTHINI		ICATE	racking Number: 0202-660005-11752
	zation Name and Address:	COMANT INDUSTR	RIES INC. EE ROAD FULLERTON C	A 92833	5. Work of Number:	rder/Contract/Invoice 016473
6. Item:	7 Description:	8. Part Number				
1000	XM SATELLITE/VHF COMBINATION ANTENN	CI 2480-206	TSO ARTICLE N		116630	NEW
13. Remar	FOR DOMESTIC SHIP TSO C37d, C38d DWG. CI 2480-206 REV					
4. Certifies		re manufactured in conformity are in a condition for safe operations	ation.	nd described in Block	herwise specified in block 13, the 13 was accomplished in accordant 43 and in respect to that wor	dance with Title 14, Code of
15. Author	rized Signature:		oval/Authorization N 20. Auth	orized Signature:		21. Approval/Certificate No.:
	Hem A.	Morky DMIR-6	360005-NM		N/A	N/A
17. Name	(Typed or Printed): Kevin A. Norton	18. Date Feb/02/		e (Typed or Printed):	N/A	23. Date (m/d/y):
Where the specified is of the court	e user/installer performs work in n Block 1, it is essential that the ntry specified in Block 1. nts in Block 14 and 19 do not co	onstitute installation certification by the user/installer before the a	egulations of an airworthiness her airworthiness authority act. In all cases, aircraft mainten	authority different that cepts parts/componer	an the airworthiness authority of others/assemblies from the airworth of the direction and installation certification	iness authority

3. Form Tracking Number: 1. Approving National Aviation Authority/Country: AUTHORIZED RELEASE CERTIFICATE RMA: 8894-001 FAA/UNITED STATES FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG 5. Work Order/Invoice Number: 4. Organization Name and Address: 626 Heads Up Technologies, Inc. 2033 Chenault Dr. #100 Carrollton, TX 75006 Eligibility:* 12. Status/Work: Serial/Batch Number: Description: 6. Item: Part Number: 9. 10. Quantity: REPAIRED 816000482 XM BLUETOOTH DATA XMD076A-01 NA RECEIVER 13. Remarks: Work performed as described on RMA work order or shop order number(s) stated in Block 3 in accordance with Heads Up Technologies FAA Approved Repair Station Manual No. HUT-22, Rev 6.0 Dated 06/15/04. Customer P.O. (if provided) is stated in Block 5. USER PART NUMBER(S): 16665-002 Certifies that the work specified in Block 12/13 was carried out in accordance with European Aviation Safety Agency (EASA) Part-145 and in respect to that work the aircraft component is considered ready for release to service under EASA Approval Certificate No. EASA.145.5433. INSTALLER NOTES: The serial number format of the above listed parts may have changed for improved tracking purposes. Please update your records, as required. 14. Certifies the items identified above were manufactured in conformity to: 14 CFR 43.9 Return to Service M Other regulation specified in Block 13 Approved design data and are in condition for safe operation. Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Non-approved design data specified in Block 13. Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 15. Authorized Signature: 16. Approval/Authorization No.: 21. Approval/Certificate No.: 20. Authorized Signature: 'lelert HU9R459J 17. Name (Typed or Printed): 18. Date: 22. Name (Typed or Printed): 23. Date (m/d/y): Charlie Moster John Header User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

national regulations by the user/installer before the aircraft may be flown.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the

AEROTRONICS, INC. 1651 AVIATION PLACE DUE UPON RECEIPT OF INVOICE

REMIT TO:

ins of

BILLINGS, MT 59105 No statement will be sent except on past due accounts AIRCRAFT TIME

IN SERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in

accordance with current Federal Aviation Regulations and was found airworthy

defective sensor and installed a new sensor Part # 12635-002. Aircraft started

for return to service. Pertinent details of the repair are on file at this agency.

Removed upper cowling to gain access to oil pressure sensor. Removed

normal and ran okay. Checked for oil leaks around sensor, none noticed.

John T. Gardner

APZZLYNISUSIA

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

W.O.:

ACTT:

Landings:

4/18/2006

M060430

1011.4

MECHOEL ELECTION AND MORE

DATE

MANUFACTURER Cirrus

Installed upper cowling.

0375

N437C

2

REMIT 2

KIND OF INSPEC COMMONWEALTH AVIATION SERVICE, INC. SIGNATURE - CERT. NO. OF PERS THE BUILDING AND TORK

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

Reg #:

5/4/2006 AV060503

Landings:

AIRFRAME LOGBOOK INSERT

Checked TCAD antenna bonding and installed new bonding straps to aircraft bonding straps between TCAD processor and aircraft ground.

TCAD tested good on ground.

Reinstalled GPS unit. Functional check good.

John T. Gardner

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

AIRCRAFT TIME IN SERVICE

LOGBOOK ENTRY

WACHCEL, BLEEDING AN HOER

COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in

for return to service. Pertinent details of the repair are on file at this agency.

Installed Airwolf Air/Oil Separator Kit I/A/W STC SA02268CH and the

COMMONWEALTH AVIATION SERVICE, INC.

F.A.A. Approved Repair Station

accordance with current Federal Aviation Regulations and was found airworthy

Date

W.O.:

ACTT:

Landings:

5/5/2006

M060506

1024.1

DATE

MANUFACTURER Cirrus

0375

N437C

Complied with all soap sample on aircraft engine.

John T. Gardner

APZZUMYTSUSTA

manufacturer's installation instructions.

W.O.:

ACTT:

1024.1

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

ground. Removed ATC transponder antenna. Cleaned bonding area between the transponder antenna and the aircraft ground plane. Checked continuity between TCAD bonding area and aircraft ground. Both TCAD antennas checked good to ground. Reinstalled ATC transponder antenna. Fabricated

Reinstalled serviceable TCAD processor P/N 70-2420-7TAS600 S/N 060307 after functional check by manufacturer. Functional checked TCAD system

Removed # 2 GPS unit. Removed and replaced display unit with new.

ALIZICALISCSIA

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC. IN HELECULAR DESIGNATIONS

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

SR22 Model: 0375 S/N:

Reg #:

KIND OF INSPECTION - STATUS & DISCREPANCY LIST

SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

N437C

AV060616 1069.2 Hobbs

6/22/2006

Landings:

Date

W.O.:

ACTT:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Removed HS I to avionics shop. Removed defective HS I display lamp and replaced with a new lamp P/N 90122-B. Reinstalled H S I in aircraft. Reset lamp hour meter VA/W Sandel Model SN3308 H S I Display Installation Manual post installation section. Functional checked pilot's HS I afterwards. OP's checked good. HS I P/N off/on SN3308-00-BL S/N 4359.

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

John T. Gardner

APZZLAYTSGSIA

INSPECTION RECORD F.A.R. 43.11-91.409

DATE	AIRCRAFT TIME IN SERVICE	Later a	PECTION - STATUS & DISCREPANCY ERSON APPROVING OR DISSAPPROV	LIST
				ING AIRCRAFT FOR SERVICE
	LOGBOOK COMMONWEALTH AVIA		LOGBO	OK ENTRY
	OCILICADA	ANDORR'	TO MONTHE HOLD	EVIATION SERVICE, INC
-	- 10 VE	7	Sept.	
	d/b/a MILLION AIR	R - RICHMOND	d/b/a MILLION	AIR - RICHMOND
MANUFA Model: S/N: Reg #:	SR22 0375 N437C	Date 6/23/2006 W.O.: M060624 ACTT: 1069.2	MANUFACTURER Cirrus Model: SR22 S/N: 0375 Reg #: N437C	Date 8/1,7/2006 W.O.: M060829 ACTT: 1101.3
	AIRFRAME LOGE	Landings:	AIRFRAME L	Landings: OGBOOK INSERT
accordar	nce with current Federal Aviation	above was repaired and inspected in Regulations and was found airworthy the repair are on file at this agency.	accordance with current Federal Av	ified above was repaired and inspected iation Regulations and was found airwoils of the repair are on file at this agence
Remove		oft side skirt mount brackets. Installed	Complied with SB 2X-77-02 R1, Er EGT wire harness I/A/W Accomplis	ngine Sensor Modification for all CHT ar hment Instructions.
Signed:	2-allimill			nsor with a new serviceable sensor. Of 's checks good. P/N off: 14554-001 P/
Print:	John T. Gun	and the state of t	Signed:	
Certifica	10 #		Print John T. G	
	F.A.A. Approved		Certificate #APZZCC18	TSUSTA
				oved Repair Station

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC MEDICAL PLANTINGS.

AIRFRAME LOGBOOK INSERT

INSPECTION RECORD F.A.R. 43.11-91.409

KIND OF INSPECTION - STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC MECHUEL EL ECCENT AN HORR d/b/a MILLION AIR - RICHMOND

AIRCRAFT TIME IN SERVICE

DATE

MANUFACTURER CIMUS 8/21/2006 M060839 Model: W.O .: 0375 1101.4 ACTT: N437C Reg #. Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Installed a new door strut P/N 12545-001 on the right side VA/W 52-10 of the Cirrus SR22 MM.

John T. Gardger APZZUG87565IA

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

BILLINGS, MT 59
No statement will be sexcept on past due acc

AEROTRONICS,

DUE



HEADSUPTECHNOLOGIES

2033 Chennault, Suite 100 · Carrollton TX 75006.5097 telephone: (972)-407-1131 fax: (972)407-1758

Work Order - Final

Work Order / RMA Number: **HUC-125 Print Date:**

00000008894-001

12/8/06

FAA Approved Repair Station #HU9R459J

Page 1 of

Customer Information:

Ship To:

Million Air 400 Portugee Rd. Ship to Attn: ?

Purchase Date:

Customer #: 000000002233

Net 30 Terms:

Sandston, VA 23250

Customer PO #: 626

Product Information:

Part Number: Costomer Part #:

XMD076A-01

Description: XM BLUETOOTH DATA RECEIVER

Requested Activity Repair

Serial Number:

16665-002 816000482

Received Rev: C

Shipped Rev: C

(1) 15 To 10

Comments: Connection fault, antenna jack loose.

TD Overnight Description of Unit Upon Arrival:

Description

Comments

CAPPLG Missing the plug cap.

Activation=02/17/06

Unit was shipped without proper ESD packaging. **ESD**

Initial Findings:

Code

Description Code

Comments

Inspect By Date

NOANT No antenna signal. Has no signal on both Audio and Weather recievers.

12/8/06

RODRIG

Cause / Hidden Damage:

Code MALBOARD Description

Found malfunctioning board.

Work Performed / Parts Record:

ART

	Qty:	Item Number	Item Description	
	1.00	RODRIGUEZ	Technician Labor - GR	
_		Notes/Desc.:	Replaced splitter board due to malfunction.	Bench and vibe testing performed.

1.00 XMSP-43-1

XM Radio Active Splitter (1-3)

Notes/Desc.: PO# 10038 Rev. D

Signature:

Date:

Tested OK:

2-8-06

Serial Number Tag:

Assembly Q.C. Inspector

Repair Technician

ESD Caution Sticker:

The unit described above has been inspected in accordance with current FAA Regulations and is approved for return to service.

K12 Inspedtor

COD :

Inspection Stamps: Warranty Seal:

Additional Documents:

HUT Document: HUC-125(9/19/2002)

Order #: 8894

Date: 12/11/2006 Weigh: 4.0

30.79 Total

0.00

34.33

Svcs: STANDARD OVERNIGHT

TRCK: 6653 8545 7023

DATE

IN SERVICE

SIGNATURE

NO.

OF PERSON

APPRO

VING OR DISSAPPROVING

AIRCRAFT FOR SERVICE



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

Model:

SR22

Date

S/N: Reg#:

0375 N437C W.O.:

10/23/2006 M061032 1138.7

ACTT: 11 Landings:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

The Cirrus Design SR22 S/N 0375 aircraft was inspected I/A/W current maintenance rules of the Federal Aviation Regulations for an Annual Inspection using the manufacturer's inspection guide and is approved for return to service.

Requirements of AD 2006-21-03 have previously been met by the following

actions: 1) The brake piston o-rings were changed at the last annual inspection I/A/W Section 32-42 of the SR22 MM, 2) SB 2X-32-14 R1 was complied with on 22 March 2006, 3) The owner had previously inserted Rev. 6 in the the AFM. No further action required.

Removed old induction filter and replaced with a new filter P/N BA-24 I/A/W Cirrus SR22 MM.

Complied with AD 2006-19-10 by 1) complying with SB 2X-25-17 R1, installed kit P/N 70130-001 for para. (e)(1), 2) Para. (e)(2) requirements were previously complied with by complying with SB 2X-25-06 R1 on 18 Sept. 2004. Inspected seat to confirm they meet the 2X-25-06 R4 requirements. No further action required.

Requirements for AD 2006-07-06 were met when Cirrus Design SB 2X-28-04 R1 was complied with on 12/2/2005. No further action required.

Complied with annual ELT Inspection I/A/W FAR 91.207(d). OP's check OK. Battery replacement due March 2009.

accomplishment Instructions. Modified left and right side torque tube assemblies. Installed kit P/N 70124-001.

Complied with SB 2X-27-12 R1, Flight Control System Freeplay, VAW

Complied with SB 2X-24-06, SR22 Wiring and Alternator Inspection, I/A/W accomplishment instructions. Installed Kit P/N's 70131-001 and 70162-001.


Complied with SB 2X-52-04 R1, Cabin Door Strut Modification, I/A/W accomplishment instructions. Installed Kit P/N 70151-001.

YTÇ	PART NUMBER		DESCRIPTION	J. J. J. SAM	TOTAL
				6.0844	
		Manager 1			
	Asses and the second			Arrest and	2011
		Action			4
		-			
		1			-
8					1
				7	
		Park Hills		1	1
		The			

CORRECTIVE ACTION: -		
PERFORMED	PITOT STATIC	CERTIFICATION
, cit ::		

I certify that the altimeter, automatic pressure altitude reporting system and static system test required by FAR Part 91.411 and 91.217 have been performed and comply with Appendix E of Part 43. Tested to 20 K feet. A/C Time: 2015.5 Reg.#: N 1871.

Signature: Change dated: 5/15/11
Aerotronics of Assoula Inc. CRS NH2D031L



RATE	TOTAL PARTS/SS
HOURS	TOTAL EQUIPMENT
1 47000 /HB.	LABOR
MASTER ALTIMETER	3 RECERTIFICATION \$210.00
MASTER	25,00
	GRAND TOTAL
DENNIT TO: AEROTRONICS,	INC. 1651 AVIATION PLACE BILLINGS, MT 59105
REIVIT	SIECHVGS, MT 59105

ns of DUE UPON RECEIPT OF INVOICE

aircraft

mount

lent, or

e upon e event

nade

CTORY

INVOICE

No statement will be sent except on past due accounts

		1	R. 91.411	MAX. AL	T. F	ECHECK EQUIRED	APPROVED AGENCY CE	BY:				RADIO & EL				
BER SI CTURER	MODEL	SERIAL NO.	LOCATION			Lyomas	CI CI	RT. NO. DAT	TOTA	L EQUII	PMENT CKED	TYPE OF CHECK	ERROR OR RESULTS	NEXT CHECK DUE	SIGNATURE — CERT.	NO.
10.0ty 11. Serial/Batch Number 12. Status/Work:	1 T42267B Repaired		Sooo ***** 70 KD Soos	07 1 000 1 07 0008 1 000 1 000 1 000 1 000 1 000 1 00 1 00 1 00 1 00 1 00 1 0	1 3	Removed airspend mind static system. System tested I/Avv melium 1900 Leak tested pilot and static system. System tested I/Avv melium 142267B. Leak tested pilot and static system. System tested I/Avv melium 142267B.	Signed: Signed: Print COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station No. VXWR051W		MANUFACTI Model: S/N: Reg #: The aircraft an accordance wi for return to se The Static Sys System have be Appendix E. The SIN 428209. E. The ATC Trans FAR 43 Appen Signed: Print: Print: Appendix	COMMONWE Alb/a MIL CH CH CH CH CH CH CH CH CH C	LION AIR - RICE S VXWR051W Aviation Regula tails of the reparation of the reparatio	TRY IN SERVICE, INC CHMOND Date 10/18/2006 W.O.: AV061010 ACTT: 1138.7 Landings: NSERT was repaired and inspected in ations and was found airworthy air are on file at this agency. comatic Altitude Reporting requirements of FAR Part 43 and Landing requirements of FAR Part 43 and Landing requirements of FAR Part 43 and found to comply with 400490-00 S/N 83711541.	MANU Model: S/N: Reg #: The airc accorda for return troubles system of function signed: Signed: Print:	LOGBO COMMONWEALTH A A/b/a MILLION A FACTURER Cirrus SR22 0375 N437C AIRFRAME LOC Traft and/or component identified ince with current Federal Aviation in to service. Pertinent details of shot XM weather system and very was inop. Called XM and reactive ally checked good afterwards.	Date 12/5/2007 W.O.: AV071205 ACTT: 1460.2 Flight Hours: BBOOK INSERT above was repaired and inspected in Regulations and was found airworthy the repair are on file at this agency. Iffied customer complaint that the rated XM weather system. System	

INSPECTION RECORD E.A.R. 43.11-91.409

REMEDIATE THEFTER THEM STATUS & DISCREPANCY LIST ARRESTATE TRAFF MONATURE - CERT, NO. OF PERSON APPROVING UND THOSAPPROVING AMERICANT FOR SERVICE TEREST in service 書きる書

F.A.R. 43.11-91.409

271772000

AMOTOTIT

1396.5

CHECK SET TAKE

SP's steel goes.

LIGHTOOK TENTING

TO MERCHANISM TO A WORLTHON RESIDENCE HER

MENTAL SCHOOL STATE THE SAME SAME

TERRENN NEXT BRANCH BRANCHERS

This along all another companions identified obesits your expained and respected it.

percentages with content Florent Stateters Plagutations and was found amountly.

the relative to contrate. Plantager contains of this report are on the of this report.

Countment Traffic Street, System: Tightment connector (1 on top 1707)

COMMISSION DESIGNATION DESIGNATION OF THE PROPERTY OF THE PROP

P. S. Aspenned Physics Stations

personal. Traffic Hollands Statement Character 100/W TAS-600 intendessors Manual

PERCYING UR DISSAPPROVING AIRCRAFT FOR SERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE INC.



HINE MILLION AIR - RICHMONEY

MANUFACTURER CONS

This is

19722 1986

W.O: AV070614

NASTO 339(6)

Flight Hours:

AURPRAME LOGGOOK INSERT

The annual mater component identified above use repaired and inspected in appoint in appoint of the appoint and inspected in the appoint of the appoint on on the other agency.

Dataserough & 1 (1995) and #2-0995 spatence with Scotchi-Weld (1991) Sporty.
Adhesive ascrequentili-Punctional checked note (1995 systems MANE CITUS)
(manys-0905) 1886 Chapter (1610) Punctional checked profit:

Elen E Chritice

repeate


-

NECTO ISLA

(ref

CAMBROKENEGAS, THE AVEATHON SERVICES, INC.

F.A.A. Appended Perput Stations



INSPECTION RECORD F.A.R. 43.11-91.409

KIND OF INSPECTION - STATUS & DISCREPANCY LIST

PPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE

LOGBOOK ENTRY

COMMONWEALTH AVIATION SERVICE, INC



d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

AV070717 1326.8

7/17/2007

Flight Hours:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Troubleshot Traffic Advisory System. Tightened connector J1 on top TAS antenna. Traffic Advisory System checked I/A/W TAS600 Installation Manual.

Reseated HSI in rack. The HSI system snecked good.

N437C

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC

d/b/a MILLION AIR - RICHMOND

MANUFACTURER Cirrus

8/15/2007 AV070814

Flight Hours:

AIRFRAME LOGBOOK INSERT

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Resecuted # 1 GPS and # 2 GPS antenna with Scotch- Weld 3501 Epoxy Adhesive as required. Functional checked both GPS systems I/A/W Cirrus Design SR22 MM. Chapter 34-40. Functional checked good.

John T Gurdner

APZZG18784SIA

COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station

INSPECTION RECORD

INSPECTION RECORD

DATE AIRCRAFT TI		F.A.R. 43.11-91.409 KIND OF INSPECTION - STATUS & DISCREPANCY LIST IN SERVICE SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT F	FOR S
LOGBOOK ENTRY COMMONWEALTH AVIATION SERVICE, INC ANAMILLION AIR - RICHMOND	MANUFACTURER Onus MANUFACTURER Onus SN	LOGBOCK ENTRY CCMACNWEALTH AVAITON SERVICE, INC BY AMILLION AIR - RICHMOND CRS VXWRSSW MANUFACTURER Curus Model: SR22 Date 10/31/2007 SR: 0375 W.O.: AV071021 Reg 8: N437C ACTT: 1425.5 Flight Hours: AIRFRAME LOGBOCK INSERT The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Avaiton Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency. Functional checked and adjusted blind encoder referencing the Curus SR22 MM, chapter 34-10. The airmeter and ATC Transpender checked good afterwards and met the requirements of FAR Part 43 Appendix E and F. Signed: JEAN T. Curviner COMMONWEALTH AVAITON SERVICE, INC. FAA: Approved Repair Station NO, VXWR051W	

INSPECTION RECUKU

OR SERVICE

F.A.R. 43.11-91.409

aircraft was removed from jacks.

u .		Locaco			INSPECT	
		LOGBOO		110	FPERSO	Secured loose prop control rod end at governor as needed. Installed a new
	700 000	COMMONWEALTH AV			9	cotter pin P/N; MS24665-132.
2		題(個人個人題(個))		EAL.		Removed L/H front baffle from aircraft. Removed cracked area and trimmed
N.		1000		~		worn edge of baffle and blended. Reinstalled L/H front baffle
		dh/- MILLION A	IR - RICHMOND			
		GDIA MILLION A	IK - KICHMOND	1485	Par T	Repaired exhaust leak at left muffler by cleaning clamps and flanges. Secured -
	MANUEACT	URER Cirrus		9.381	4 (46)	clamps referencing Cirrus SR22 MM 32-20. No leaks noted on run up.
	Model:	SR22	Date	11/5/2007		Removed cracked right front baffle. Stop drilled crack. Fabricated a
	S/N:	0375		M071044		reinforcement patch using .040" 2024-T3 Aluminum and installed patch using
-	•		W.O.:	1425.5		17 ea. rivets P/N: MS20470AD3-3 per AC 43-13.1B. Reinstalled right baffle
	Reg #:	N437C	ACTT:		1000	per Cirrus SR22 AMM.
-			Flight Hou	irs:	1007	D
						Removed #3 EGT probe and cleaned off exhaust deposits. Reinstailed #3
·	_	AIRFRAME LO	GBOOK INSERT			EGT probe and secured as required.
	P. 2011				-11	Removed induction filter and replaced with a new filter P/N BA24 referencing
		and/or component identifie			7	Cirrus SR22 MM.
		with current Federal Aviati		0.50	-	
	for return to	service. Pertinent details	of the repair are on file	e at this agency.		Removed deteriorated boot on battery terminal and replaced with a new boot
						P/N: MS25171-4S.
	The Cirrus I	Design SR22 S/N: 0375 ai	reraft was inspected t	eferencing current		
_		rules of the Federal Aviat			-	Complied with SB 2X-53-03, Tail Tie-Down Assembly Replacement referencing
		anufacturer's current inspe				the accomplishment instructions. Installed a new Tail Tie-Down Assembly Kit
-		e following items were serv				P/N: 70120-001.
				V V VVV VVV		
		th FAR 91.207(d), Inspect				Cleaned and lubricated prop governor cable and throttle cable. Throttle OP's
	The state of the s	8 new Duracell D-Cell ba	tteries. No defects no	led. ELT batteries	-	check good.
	due replacer	ment March 2012.				
	Secured los	ose interior light rheostats of	o holeter nanel as re-	ruited		Repaired cracks on upper fuselage skin between door frames by filling cracks,
	Secured loc	se interior light meostats c	or boster parer as rec	Juli 60.		sanded, primed, painted and blended paint as required and polished.
fit-	Troubleshot	and found several defective	e sockets at the fuel f	low indicator	-	
		Removed defective connec				Removed nose wheel and tire assembly from aircraft. Disassembled nose
-		a. P/N: 200333-1, 3 ea. P/				wheel assembly. Removed defective bearing cup and installed a new bearing
	OP's checke	ed good afterwards.				cup P/N: 214-00300. Cleaned, inspected and reassembled wheel halves.
-						Serviced tire to 40 psi. Installed a new bearing cone P/N: 214-00400 and a
	to the second of	th SB 2X-27-14 R3, Rudde				serviceable bearing cone and lubed wheel bearings with Aeroshell 22 grease
		he accomplishment instruc		er-Alleron		referencing Cleveland Wheel and Brake MM AWBC MM 0001-7 section 300.
	Interconnect	Modification Kit P/N: 7019	7-001.			Reinstalled nose wheel assembly onto aircraft.
	Complied with	h SR 2Y 27 12 Floo Activ	ntor Mounting Course	Dainforcement		Removed left MLG aide fitting and strut clamp. Removed defective strut
-	THE RESERVE OF THE PARTY OF THE	th SB 2X-27-13, Flap Actua he accomplishment instruc				grommet and replaced with a new grommet P/N 10209-001. Reinstalled strut
		forcement Kit P/N: 70185-				clamp and ade fitting and torqued as required. Performed final torque after

INSPECTION RECUKU

Removed worn bolt in right strut upper fitting and installed a new bolt P/N: NAS6207-64 referencing Cirrus SR22 MM 32-10, Performed final torque after aircraft was removed from jacks.	O. OF P	Removed binding L/H inboard alleron hinge bearing and installed a new bearing P/N: MS27645-3A. OP's checked good afterwards.	E
to 1	254	Removed defective wellnut in baggage area and installed a new wellnut P/N; E- 632	4
Removed both cracked left and right MLG upper fairing stand-offs. Installed new upper stand-offs P/N: 13522-001 on left and right MLG and removed right MLG wheel skirt stand off bracket and replaced with a new bracket P/N 17205-002 referencing Cirrus SR22 MM 32-10 and 20-60.	7 -	Removed broken exhaust spring on L/H exhaust outboard side and installed a new exhaust spring P/N; 50442-001 referencing Cirrus SR22 MM.	4,
Removed worn lower NLG rebound bumper and installed a new lower NLG rebound bumper P/N: 13703-001 I/A/W Cirrus SR22 MM 32-20.		Removed broken propeller de-ice line and fabricated a new line using the same material. Installed new fabricated propeller de-ice line and performed OP's check/leak check. OP's check good and no leaks noted referencing Cirrus	
Removed #1 Alternator for 500 hour inspection. Installed serviceable overhauled original alternator P/N: 646843 S/N: 002HA028 with new gasket P/N: 629436C referencing Cirrus SR22 MM that was overhauled by Quality Aircraft Accessories, Inc., W.O.# 59196. OP's check good.		Inspected # 5 EGT sensor and found wires chaffed and grounding. Removed defective # 5 EGT sensor and installed a new # 5 EGT sensor P/N: 165579-	
Complied with 5 year replacement of all flexible fuel lines referencing Cirrus SR22 MM. Replacement due again on or before 31 Oct. 2012. Leak check good.		Removed brake assemblies from aircraft. Removed o-rings in left and right brake and replaced with new o-rings P/N M83461/1-222. Reinstalled brake assemblies, bled brakes and service brake reservoir referencing SR22 MM	-
Complied with 5 year replacement of the gascolator seals, P/N's: MS29513- 137 and NAS1523-8Y. Leak check good. All work done referencing Cirrus SR22 MM 28-20.		Chapter 32-42	-
Complied with 5 year replacement of all fuel drain valve seals. Defueled aircraft. Removed left and right fuel panels on collector tank. Removed drain valves I/AW Cirrus Design SR22 MM 28-10. Installed new o-rings, 2 ea. P/N: M83248/1-011 and 2 ea. M83248/1-020. Removed left and right wing fuel drain valves and replaced with new valves P/N: 50141-001. Removed	-	Print: John T. Gardger APZZG9875GSIA	
gascolator drain valve and replaced with a new valve P/N: 50242-001. Refueled aircraft. All drains and collector panels leak check OK.		COMMONWEALTH AVIATION SERVICE, INC. F.A.A. Approved Repair Station	_
Complied with 5 year replacement of brake system flexible lines referencing Cirrus Design SR22 MM Chapter 32. Bled all brake lines. OP's and leak checks good."		3. F-445	
Adjusted pilot's seat shoulder harness pass through on the seat cover. Pilot's shoulder harness retracts normally.	NA MA		
Adjusted alleron cable system rigging to obtain neutral chord position. Found roll trim cartridge and rudder-alleron interconnect bungee to be weakened.			
Removed defective roll trim cartridge and installed a new roll trim cartridge P/N: 15660-001 and replaced weakened bungee cord with a new bungee cord P/N: 12983-001. Performed roll trim cartridge adjustment/test and inspection and	-		

checked rudder-alleron adjustment referencing Cirrus SR22 MM chapter 27-10

and 27-20. OP's checked good afterwards.

INSPECTION RECORD F.A.R. 43.11-91.409

DATE	AIRCRAFT TIME IN SERVICE	SIC	GNATURE – CERT. NO.	OF PERSON APPROV	ING OR DISSAPPI	ROVING AIRCRAI	T FOR SERVICE
	COMMONWEALTH AND COMMONW	IR - RICHMOND	INC		COMMONWEALTH	AVIATION SERVICE, I	NC RR*
MANUFA	CTURER Cirrus			MANUFACT	URER Cirrus		
Model:	SR22	Date	11/9/2007	Model:	SR22	Date	11/13/2007
S/N:	0375	W.O.:	M071117	S/N:	0375	W.O.:	M071123
Reg#:	N437C	ACTT:	1430.9	Reg #:	N437C	ACTT:	1435.7
		Flight Hou	rs:			Flight Hour	s:
	AIRFRAME LOG	BOOK INSERT			AIRFRAME LO	OGBOOK INSERT	
accordanc	t and/or component identified with current Federal Aviation service. Pertinent details of	Regulations and w	as found airworthy	accordance v	ind/or component identification with current Federal Aviation Pertinent details	tion Regulations and wa	s found airworthy
itself and o	nt and found #1 and #6 EGT ne against a CHT probe. Rer ea new probes P/N: 16579-00	moved #1 and #6 E	GT probe and	new#6 CHT	CHT probe and tested. probe P/N: 14880-001 vieck good on ground run	with 2 ea new connector	
check goox	at this time.						
Cleaned ca engine sen	nnon plug at the firewall for er sor not transmitting message	ngine sensors. Cou on MFD at this time.	ild not duplicate	Signed:	John T. Gre	1000	
Signed:	& acumentant			Print: Certificate #_	APZZLG875C		
Print:	John T. Gran				COMMONWEALTH A	VIATION SERVICE, IN ed Repair Station	IC.
Certificate fi	COMMONWEALTH AVIA	TION SERVICE, IN	IC.				

MECHOELEC HOURS AND HOURS

This logbook closed out on 6 Dec. 2007. Refer to logbook # 2 for future entries.

AP226987565 IA

F.A.A. Approved Repair Station Contincate # AP22&975&577A Contincate # AP22&977A Continuation # AP22&97A Co	PORT BOX 10 Read By: Date Out: 5 A/C S/N: A/C
Certifies the items identified above were manufactured in conformity to: 19. # # # # # # # # # # # # # # # # # #	HWAY 10 WEST - AIF LA, MT 59808 1-7830 FAX (406) 728 npaul @ aerotronics.col npaul @ aerotronics.col npaul @ aerotronics.col Reg N Repairable by the part agrees to pay Attomeys and subject to what and subject to what and subject to what agrees to pay Attomeys and Repairable tag is Rejected tag iss
15. Authorized Signature: 16. Approval/Authorization No.: 20. A Gaw percuey Auss of united solutions and united solutions are solved as a solution solution solution solution solution solutions and united solutions are solved as a solution solution solution solution solution solutions are solved as a solution solution solution solution solution solution solution solutions are solved as a solution sol	State/Zip: MYT SSSULA, (406) 728-78 (406) 72
User/Installer It is important to understand that the existence of this document alone does not automatically (PO: Check CC#: PO: RAILS E. RAILS MUST BE FILL CARB. CARB. RAILS MUST BE FILL CARB. CARB. RAILS MUST BE FILL CARB. CARB. CARB. RAILS MUST BE FILL CARB.
Statements in Blocks 14 and 19 do not co astitute installation certification. In all cases, aircraft national regulations by the user/installer before the aircraft may be flown. *Installer must cross-check eligibility with product of the aircraft may be flown.	HODDS: 2018 S. A CERTIFIED STA INAMA 150 INA

Approving National Aviation 3. System Tracking Ref. No. AUTHORIZED RELEASE CERTIFICATE Authority/Country: RMA 11337785 FAA/UNITED STATES FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG Certificate No. G6XR582Y GARMIN International 1200 E 151st Olathe, KS 66062 4. Organization: 5. Work Order Contract/Invoice Number: RMA 11337785 7. Description: 6. Item: 12. Status/Work: 10. Quantity: 11. Serial/Batch Number: 9. Eligibility: * 8. Part Number: GNS430W.Blk REPAIRED 23401810 011-01060-00 N/A Confirmed Problem. Repaired the NAV board to correct return issue. Repaired the COM board to fix unrelated problem found during testing. Updated software to latest version and aligned unit to optimum performance. Master cleared unit to restore factory default settings. Unit passes its ATE tests and is operating within normal limits. Unit acquired satellites. OK to Return to service. The Main and GPS software is at the latest revision. This unit complies with Garmin's Service Bulletins No. 0740, 0808 and 0818. It is the responsibility of the installer to verify that the manuals and addendum in the aircraft are at the correct revision. It is also the responsibility of the Installer to verify that the installation complies with the Service Bulletins listed above. If this unit is part of a dual unit installation Garmin recommends that both units have the same software levels. It is the responsibility of the installer to assess the installation compatibility. This "Certifies that the work specified in block 12/13 was carried out in accordance with EASA Part-145 and in respect to that work the component is ready for release to service under EASA Part-145 Approval Number. EASA.145.5534". The work that was performed on this unit was done to meet the requirements of all sections of the maintenance manual part number 190-00364-00 Rev-R, Revision Date 9/24/2008. All repaired or replaced GARMIN units have a 90-day warranty or the continuation of the original factory warranty from the original purchase date, whichever is longer. 14. Certifies the items identified above were manufactured in conformity to: Other regulations specified in Block 13 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in block 13, the work identified in Block 12 and Approved design data and are in condition for safe operation described in Block 13 was accomplished in accordance with Title 14, code of Federal Non-approved design data specified in block 13 Regulations, part 43 and in respect to that work, the items are approved for return to service. 15. Authorized Signature 16. Approval/Authorization No.: 21. Approval/Certificate No.: 20. Authorized Signature: N/A N/A G6XR582Y 17. Name (Typed or Printed 18. Date (m/d/y) 22 Name (Typed or Printed) Date (m/d/y) NIA N/A Paige E. Bartz 11/14/2008 User/Installer Responsibilities It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the