AIRCRAFT LOG AF5-1

AIRCRAFT DESCRIPTION

MANUFACTURER Cirrus De	REGISTRATION NUMBER N 9140	DATE OF MFG.
SERIAL NUMBER 1104	REGISTRATION NUMBER N 9140	
REGISTERED OWNER		Inspection Status (Check one)
CITY, STATE, ZIP		F.A.R. 91.409 ANNUAL/100 HOUR
OPERATOR		F.A.R. 91.409 PROGRESSIVE
STREET ADDRESS		F.S.A. 91.409 PROGRESSIVE
CITY, STATE, ZIP		
REGISTERED OWNERSTREET ADDRESS		F.A.R. 135.419 A.T.C.O.
CITY, STATE, ZIP		OTHER
OPERATOR		DATE ENTERED
STREET ADDRESS		MAINTENANCE RESPONSIBILITY
CITY, STATE, ZIP'		
N. W.		
7		

INSTALLED EQUIPMENT

ITEM	4.348 K-10	MANUFACTURER	MODEL	SERIAL NO.
ENGINE	TCM :	TO-360-ES (6)		R 35728/
ENGINE			seed to the	R L
PROPELLER	Hartzell	BHC-JZYF-IBF/F7	694	EF230B
PROPELLER				
ENGINE			in the second	
ENGINE				
PROPELLER				
PROPELLER		and the second s		- V
ENGINE	December 2011			
ENGINE			Name and at factor with	
PROPELLER		Million again, a sea mais de marchanna agus an tha	and the second free to the second of	1
PROPELLER		a Sun Safara-in-war reso awate Jano Samuel 1955	and the second control of the second	
ENGINE	record for the Contract of the	Control (Control Control Control (Control Control Cont		
ENGINE				Marie Committee
PROPELLER		A STATE OF THE PARTY OF THE PAR		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
PROPELLER			ng a grand the respectation is to	description of the second of t

AIRWORTHINESS DIRECTIVE/FACTORY BULLETIN COMPLIANCE RECORD

A.D./BULL. NUMBER	ITEM AFFECTED	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. 1 TIME/RECUR.	NEXT COMP. DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.
2x-95-10A	CAPPS	5-5-07	Installed kits	Itime		AP 2834035
x-27-c/R2		478.4		Itime		AP2831582
4008-11-18		8-26-68	58 2 x-78-07R1	Becon	740.9	APTRIGIES CHIPRE
2x-53-03	Tie down	7-9-08		Itime		APT82918 Chelle
2x-27-14	13 6	5-16-08 555.7	Kit 70197-001	Isine	VII.	AP2831582
40 2008-0	3-16	555.7	SB 2x-27-14R3	1 time		
					,	

N914D

Airframe Log

AirCenter Santa Fe

121 Aviation Dr. • Bldg. 3005 • Santa Fe, NM 87507

Date:5/5/07	Make:	Cirrus	Model: SR-20	S/N: 1104
Tach:	Hobbs:	403.6	TTAF:	

CM/ SB A2X-95-10R1, CAPS PICK-UP COLLAR SUPPORT REPLACEMENT, BY INSTALL OF KIT P/N 70181-002.

C/W SB 2X-95-09R1, CAPS STRAP ABRASION INSPECTION, BY INSTALL OF KIT P/N 70142-001.

Arturo Torres A&P2834035

Work accomplished at Santa Fe Jet Center, Inc. Reference work order #6136

Au	ving National Aviation thority/Country: A/United States	AUTHORIZI	ED RELEA	SE CE	RTIF	CAT			CA25648
	zation Name and Address: yne Corporation		ead Lincoln,		VALTAG			mber:	der/Contract/Invoice
6. Item: 7. Description: 8. Part Number: 9. Eligibility: * 10. Quantity: 11. Serial/Batch Number: 12.									Status/Work:
1	MFD	700-00004-008	TSO Article	N/A	1	20	127185		Rebuilt
		meets approved TS		9. ☑ 14 CFR 4					n specified in Block 13
	approved design data and are son-approved design data spec	in a condition for safe operation. cified in Block 13.		and described	l in Block 13 s lations, part	was accom	plished in accorda	nce with	lentified in Block 12 Title 14, Code of ms are approved for
15. Author	ized Signature:	16. Approval/A	authorization No.: 20	O. Authorized Sig	nature:	15	2		oval/Certificate No.: PT1042NE
17. Name (Typed or Printed):	18. Date (m/d/y	22	Name (Typed o	11 11 11 11 11 11	TRA		3. Date (m/d/y): 9/28/2007
			User/Installer Resp	ponsibilities					
Where the Block 1, it i Block 1.	user/installer performs work in s essential that the user/installe in Blocks 14 and 19 do not con	stence of this document alone does n accordance with the national reg er ensures that his/her airworthine nstitute installation certification. In perfore the aircraft may be flown.	ulations of an airworthi ess authority accepts par	ness authority dif rts/components/as	Terent than the semblies from	e airworth the airwo	hiness authority of orthiness authority	of the co	ountry specified in

Lubbock Aero 6304 N. Cedar Ave. Lubbock, TX 79403

		Lubbe	JCK, 1 × 79403	A RESIDENCE OF THE PARTY OF THE			
DATE OF	4. ARCHAELTE		PERCEPTION	NOW FUT DOMESTIC		WORK PERFORMED/RETURNED TO SERVICE	
COMPLETION	The state of the s	Make: Cirrus		s/n: 1104	Maria Maria		
	Date: 12-08-2007	Model: SR20	TT: 496.5	Hobbs: 496.5			
	Installed JPI E						
	and installation				And the second s		
				# SA01285SE a			
				 A. Installed Re 			
	preheat systen	n Hotstrip oil s	sump heater p/	n 08-00688 IAW			
	installation inst		337 or W&B ch	ange needed.			
	Chad R Burns	AP2829180					
3-17-	18 HoBBS	32.9 Rm	wed ong	we Okiven	Vacuum	Pump 1/2 21500	
	SWIA	7 5056 t	INS TALLE	0 6.4. HICC	SN 127/2	By Howy Sero. Seit Al 2148062	
	Pm +0	distel	Roquin Ton		Sene	Seit All 2148062	
						8	
							*

HOLLY AERO, INC.

WORK ORDER

PART NAME: AIRBORNE DRY AIR PUMP	W.O. #
PN 211ce SN 12712	INV. #_ 20060830
WORK ACCOMPLISHED: Overhauled epaired in a Process Specifications # H7YR030Y-1009 REV. A. The following components were inspected and installe INSPECTION: CODE: INSPECTION: Front Housing Rear Housing Stator Rotor Drive	ccordance with FAA approved
3/19	
8237	external Spline Dr. 5
	ther
Results of Final Test at 4000 RPM PRESSURE:	nei
FLOW 1/4 SCFM VACUUM:	IN.HG
TECHNICIAN MANUEL MISPEC	etor
MAINTENAN	CE RELEASE/
The appliance identified above was overlawith current regulations of the Federal Arreturn to service.	pauled/repaired and inspected in accordance viation Administration and is approved for
Holly Aero, Inc. (Cert. # H7YR030Y)	RTIFICATE # <u>2581082</u>
190 PR 7538 Hawkins, TX 75765	
	Form # HAI 201

MAINTENANCE RECORD F.A.R. 43.9 DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED MAINILIU F.A.R. 43.9

F.A.R. 43.9

DESCRIPTION OF WORK PERFORMED
OR APPROVED DATA USED

	De.		. 43.9				n. 43.3	
DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK OR APPROVED DAT		WORK PERFORMED/RETIRED TO SERVICE	DATE OF	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK TO OR APPROVED DAT	ERFORMED A USED
		Lubbock Ae 6304 N. Cedar Lubbock, TX 79	ro Ave. 4403		COMPLEXION		ABILENE AERO I 2850 AIRPORT BI ABILENE, TX. 79 (915) 677-260	NC. VD. 502
	Reg #: 914D Date: 05-02-20	Make: Cirrus 008 Model: SR-22	S/N: 1104 HOBBS: 542.3			N #: 914D Date: 06-02-200	S/N: 1104 08 TAC/HM: 586.1	W/O #: 14389
	left main w SB 2X-78-0 stud missir condition a	wheel. Serviced to corre 07 R1 heater exchange ng, heater exchanger fo at this time.	r inspection, found one			Re-installed	repaired GNS-430 S/N //M. Installed 5.3 softward.	re in #2 GNS-430, Op SSTR469E
2029)	Matthew VV	Abilene Aer 2850 Airport Abilene TX, 7	Blvd			Reg #: 914D	6304 N. Ceda Lubbock, TX 7 Make: Cirrus 108 Model: SR-20	
	Reg #: N914 I	D Make: Cirrus	S/N: SR20 IT: 555.7 Meter: 555.7			Installed E Complied	LT shield p/n 18389-0 with SB 2X-53-03 tail	001 at this time. tie down assembly a
	Modification	2X-27-14 R3 Rudder-Ail on by installing Kit P/N	leron Interconnect			- hande I	ew tail tie down bump	
		K at this time.			*	Matthew V	Villiams A&P 269968	30

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WO OR APPROVED D		AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE	
		ABILENE AERO 2850 AIRPORT ABILENE, TX. 7 (915) 677-26	BLVD. 79602		_
	N #: 914D Date: 06-02-20	S/N: 1104 008 TAC/HM: 566.1	W/O #: 14389		
	good IAW M	d repaired GNS-430 S/N M/M. Installed 5.3 softwa bod. FOR RETURN TO SERVICE G	are in #2 GNS-430, Op -		-
		Lubbock Aero 6304 N. Cedar A Lubbock, TX 794	Ave.		•
	Reg #: 914D Date: 07-09-2008	Make: Cirrus 8 Model: SR-20	S/N: 1104 HOBBS: 587.5		ŧ
	Installed EL Complied wi	T shield p/n 18389-001 with SB 2X-53-03 tail tie w tail tie down bumper	1 at this time. down assembly and		•
	Matthew Wi	illiams A&P 2699680			,
					1
					į

Lubbock Aero 6304 N. Cedar Ave. Lubbock. TX 79403

DATE OF COMPLETION	AIRCRA IN SE	TICK TO THE TOTAL TO THE T	ODALT	ock, TX 7	A Editor	A Control of the Cont	AGENCY & CERTIFICATE NO. ORK PERFORMED/RETURNED TO SERVICE
		N#: 914D Date: 08-26-2008	Make: Cirrus Model: SR20	TT:_		1104 obs: 640.9	
		Removed Co 40097163 and SB 2X-78-07	ncord main aird d installed s/n 4 R1 by pressuriz S AP2829180	raft bat 024995	54. C/W AD 08	3-11-18 IAW	
		The second secon		- The same of the	- Francisco	and the second s	•
					A Service March		
				1 1	1.1		
			. American	1	11.		
			A L				The state of the s
			- 12 13 47 14				
The same							

		Lubbock Ae 6304 N. Cedar Lubbock, TX 7	ero r Ave.				MAINTENANCE RECORD F.A.R. 43.9				
ATE OF APLETION	IN SE			AGENCY & CERTIFICATE NO. ORK PERFORMED/RETURNED TO SERVICE	DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	TIME DESCRIPTION OF WORK PERFORMED VICE OR APPROVED DATA USED		AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVI		
	Remove 400971 SB 2X-7	ed Concord main aircraft be and installed s/n 40249	Pattery p/n RG24-15M s/n 954. C/W AD 08-11-18 IAW n of exhaust, no leaks noted.			Date 08-29-08 Tach: 643.7 INSTALLED SE PRECISE FLIGI MARK L MARRUJO	Make: CIRRUS Hobbs: N/A MI-PORTABLE OXYG HT ENGINEERING DR	GERVICES Model-SR20 TT AF: EN SYSTEM PER ST RAWVING LIST 003N00	Airframe Log # 87507 S/N-1104 C NO. SA01232SE AND 1000.	EJUNELU 10 JENNI	
				*							
				¥							

10-17-2008 Cirrus SR20 N914D Hobbs: 666.5 hrs Removed VSI, directional gyro, and S-Tec. Installed Aspen Avionics EFD	DATE OF COMPLETION
1000 PRO Primary Flight Display in accordance with Aspen Avionics	_
Installation Manual No. A-01-26-00, Rev C dated 3/28/2008. Airplane	_ A
Flight Manual Supplement Document No. A-01-175-00, Rev B dated 3-17-	IN SERV
2008 and per Aspen STC# SA10822SC.	TIME
I certify that the work performed on the aircraft has been performed	_
satisfactorily and per current Federal Aviation Administration Regulations	
and is approved for return to service only for the work performed.	
Drilet -	
Mike Pippen	DESCRIP
A&P462634580IA	OR APP
	ROVE
10-17-2008 Cirrus SR20 N914D Hobbs: 666.5 hrs	ORK I
Removed Garmin GNS430 and shipped to Garmin International for WAAS	A USED
upgrade. Reinstalled WAAS modified 430W and function tested. The	MED
430W modification falls under STC# SA01933LA.	
Reference Work Order No. 14123 and FAA 337	
Dated 10.17.08 for complete details on the work performed. I certify that	
the work performed on the aircraft has been performed satisfactorily and per	+
current Federal Aviation Administration Regulations and is approved for	
return to service only for the work performed.	WOR
muy.	X PER
Pippen-York Inc.	FORM
FAA C.R.S. FMZR327K	& CER
	TURN
	ED TO
	5 9

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED			
10/18/08	No. Barba	Test flight of Aspen Avinney	E		
	666.8	All Functions check out as &	int:		
		Tom Woodruft 4426 76 504	5		



Sama Fe NA121: Aviation Dr. • Bldg 4002 • Santa Fe NM 87507

N914D Airframe Log

Date:11-10-08	Make: Cirrus	Model: SR-20	S/N: 1104
Tach:N/A	Hobbs:0690.5	TTAF:0690.5	


INSTALLED NEW NOSE LANDING GEAR PUCKS, P/N 11879-006. INSTALLED NEW RIGHT MLG TIRE, P/N 15X600.6-6 PLY.

Daniel Gowe A/P 558904411 I/A


Work accomplished at Santa Fe Aero Services, LLC. Reference work order #661

		1.4.11. 73.3	
DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
12-1-08	Hobbs: 6	92.9. Darked anciety, Nem	med wheels, duakes o
	bearings,	cleaned and inspected, repache	of anhel bearings and
	reinstall	ed wheels I heares onto aire	of Replaced in filler
	with nee	a Mosperted averall hatter	Seunced brake very
	Checked o	Il unteres a Extent lights. An	finealed agreaft as
	Re Am	m. Remed Cleared inspected a	reinstalled phel straines
	and down	asser. Replaced bolt for me.	governor cable at quadrant
	Replaced	hald for mittere cable at &	wel rump. adjusted a tighters
	atternator	helt. MW AD 2008-11-18	7-2-08, Exhaust &
	heat Eve	Ranges revormed vessino	Check of heat Exthense
	ZAW-S	B-2X-78-07 RI Service b	ulletin checked of this
	date.	Clu) FAR 91-207 (d), ELY	- wisna vispection &
	onerat	that check clu annual	class of extable pino
	Volle	unsual inspectors a weigh	cheel of bottle litates
	left in	ain til on wheel asses of	lue to lucas on outer exet
	of this	I Replaced OAT / Clock &	sattley Dul lucy 24 month
	Ref Cared	Tun a bank indicator batteries	and livery year
	1	analder Math AND 252682	
	A STATE OF THE PARTY OF THE PAR		

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
D	ATE 12-1-09	TOTAL TIME TO DATE . 692	2.9
10	ERTIFY THA	THIS ABOUTE AND THE SEEN I	NSPECTED
.IN	ACCORDAN	, , ,	
A	D WAS DET	ERMINED TO BE IN AIRWORTHY	
C	NOITION.	Circles Shuth 2826872	- IA
	socket at WX50 on Avidyne and Performed ramp Reference Work on the work performed Administration I the work perform	connection in stormscope processor wiring with new 0 processor J2 pin 17to correct stormscope failure markets of stormscope. Order No. 14166 dated 12-11-2008 for complete deformed. I certify that the work performed on the airc satisfactorily and per current Federal Aviation Regulations and is approved for return to service on the deformed. A Flying Machine Co.	etailseraft has
	FAA C.R.S. FM		



DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORM OR APPROVED DATA USED	MED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
			ANY LATER	
I C	ERTIFY THAT THE A	ALTIMETER SYSTEMS, ALTITUDE T, AND STATIC SYSTEM TESTS		
REC	QUIRED BY FAR 91.4	11 AND THE ATC TRANSPONDER ED BY FAR 91.413 HAVE BEEN		F-3471
PEF	REFORMED. A/C HOUR	METER 762.0 . ALTIMETERS; TESTED TO	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
AU1	TOMATIC PRESSURE F	REPORTING SYSTEM, TYPE 14-30		, of a tent 2 to 1 has 25 historial
ATC	XPDR #. 1 GTX	430 STESTED TO 20,000	0	
	NATURE	14269 DATE 4-30-2009		
	55 Frederi	EN-YORK, INC. 55 Airport Road icksburg, TX 78624 CRS FMZR327K		bbock Aero
			6304	N. Cedar Ave. ock, TX 79413
			Make: Cirrus	Model: SR20
		N#: 914D Date: 08/25/09	S/N: 1104	Hobbs: 779.2
		Elt p/n 455-6 shielded wire 91.207(d) by	614 Rev H, s/r	cket. Installed new bracket New In 188-12949 Installed 4 cond. Temote switch to ELT. C/W FAR Id op's check of ELT no defects
		Chad R. But	ns AP2829180	



LUBBOCK AERO

6304 N. Cedar Ave., Lubbock, TX 79403

Date: 01-11-10 N#: 914D Make: Cirrus Model: SR20

S/N: 1104 Hobbs: 805.8 ATT: 805.8

C/W Annual inspection IAW FAR 43 appendix D.

C/W AD 2008-11-18 (7-07-08) by inspection of engine exhaust/ heat exchanger IAW SB 2X-78-07R1.

C/W SB 2X-32-18 R4 by inspection of nose landing gear, no defects noted.

C/W SB 2X-27-15 by replacement of stall warning horn.

C/W SB 2X-05-01 by installing a secondary yellow temperature sticker on the brake caliper.

C/W SB 2X-71-10 R2 by installation of oil breather line insulation sleeve.

C/W 12 month replacement of turn and bank batteries.

C/W 12 month fire bottle weigh. Weight is within limits.

C/W 12 month Concorde battery capacitance check. Battery checked within limits.

C/W FAR 91.207(d) by inspection and op's check of ELT no defects noted, ops check normal, battery due 07-2015.

Checked brake reservoir fluid level and serviced as required. --Inspected and serviced tires. --Removed, cleaned, inspected, packed and re-installed wheel bearings. --Removed screen, inspected, cleaned, re-installed fuel bowl and leak check. --Ops check interior and exterior lights. --Removed muffler shroud, inspected and reinstalled shroud. --Replaced vacuum filter. --Checked cable tensions, surface travels and lubed flight controls. --Inspected all placards interior and exterior.

Replaced power lever, washers, and bushings.

I certify that this aircraft has been inspected IAW an annual inspection and was determined to be in airworthy

condition,

Gene Seitz AP21480627A

-3	0-2009	ALTIME	TER SCALE ERROR		
NO.	.5934D-3		SERIAL NO.	4140	48
100		ALTI	METER PRESSURE		
FT)	INDICATOR READ- INGS AT + 25 ° C	TEST PT (FT)	INDICATOR READ- INGS AT + 25 ° C	TEST PT (FT)	INDICATOR READ- INGS AT + 25 ° C
00	0	8,000	+25	30,000	(
0	+10	10,000	+20	35,000	
100	+5	12,000	+30	40,000	
>00	+10	14,000	+40	45,000	
1500	+15	16,000 -	+40	50,000	
2000	+20	18,000	450	55,000	
3000	125	20,000	+50	60,000	
4000	120	22,000		70,000	/
6000	120	25,000		80,000	/

PIPPEN-YORK INC. dba A FLYING MACHINE COMPANY GILLESPIE COUNTY AIRPORT FREDERICKSBURG, TX. 78624 FAA C.R.S. FMZR327K 830-997-8205

ACCEPTED OR SERVICEABLE

Cust Name LUCODRVFF	A/C N# N914D
Equip M-M UMTED 5	8340-3 SN414048
Tech MIKE PIPPE	was repaired and inspected in accordance with
current Regulations of the Federal Av	viation Administration and is approved for return air are on file at this repair station under
Work Order No 14269	Date 4-30-2009
Signed Marpi	Cert No A\$10442634580

PIPPEN-YORK INC. dba A FLYING MACHINE COMPANY FILLESPIE COUNTY AIRPORT FREDERICKSBURG, TX. 78624 AA C.R.S. FMZR327K 830-997-8205

ACCEPTED OR SERVICEABLE

Series Print	ust Name WOODRUFF	A/C N# N914D
		SN 68788
	프랑스 (1994)	Inspector MICE PIPPEN repaired and inspected in accordance with
ı	irrent Regulations of the Federal Aviation	Administration and is approved for return
-	ork Order No. 14269	하는 사람들은 사람들이 가는 것이 되었다면 하는 것이 없는 것이 없다면
-	。	Date 4-30-2005
	aned MilePy	Cert No. A\$P462634580

DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
		commence the later from the company	
timeles successive successive services	and the second s		
Commence of which the property	And the second section of the second section is the second section of the second section of the second section of the second section s		
Application of the Control of the Co		N914D HOURS:810.1	and the second second second second
		00 PFD S/N 1976-A Version 1.1 software to the	
		software in accordance with SB2009-04 Rev A	
		0822SC amendment Rev 2.	
		 14525 dated 1-18-2010 for complete details or ify that the work performed on the aircraft has 	
	the set with the control of the cont	rily and per current Federal Aviation	
		is and is approved for return to service only for	
	ne work performed.		
er en marin marin men	mixers.		and the first of the first of the same of
N	like Pipper A&P 46263	4580 IA	
man-prime control	630	ubbock Aero 4 N. Cedar Ave. bbock, TX 79403	
2.			
	N914D S/N: 1104 05-25-2010 Model: SR20	Make: Cirrus Hobbs: 829.2	
Insta	lled new main aircra	aft battery Gill G-243, S/N-	
G02	505306.		
	1		
_ //	under Mark	7	
Krne	old Hertel A&P 2826	822	
And	Ju Herter Adr 2020		
man are	(,)		

INSPECTION RECORD F.A.R. 43.11-91.409

T TIME RVICE	KIND OF INSPECTION-STATUS & DISCREPANCY LIS SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING A							
	N#: 914D Date: 11-09-2007	Make: Cirrus Model: SR20	TT: 489.3	s/n: 1104 Hobbs: 489.3				
	Cleaned and packed wheel bearingsReplaced bearings and races on LT MLG wheelC/W FAR 91.207 ELT inspection & op's check normal, replaced battery new date Mar. 2011Cleaned Fuel strainer bowl and screenLubed aircraft,serviced batteryI certify that this aircraft has							
	been inspected IAW an annual inspection and was determined to be in airworthy condition. Charles Burns AP2829180IA							
		Lubboc 6304 N. C Lubbock,	edar Ave.					
N#: 9 Date:	14D Make 12-21-2010 S/N:	e: Cirrus 1104 h	lobbs: 866.4	Model: SR22				
Rer reins	noved Rosen Stalled factory	Sun Visor sys sun visors.	tem, STC SA	0185SE and				

MAINTENANCE RECORD F.A.R. 43.9				INSPECTION RECORD F.A.R. 43.11-91.409			
DATE OF OMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE	DATE	AIRCRAFT TIME KIND OF INSPECTION-STATUS & DISCREPANCY LIST		
					A	N#: 914D Make: Cirrus s/n: 1104 Date: 11-09-2007 Model: SR20 TT: 489.3 Hobbs: 489.3	
	The supplied on			1		Cleaned and packed wheel bearingsReplaced bearings and races on LT MLG wheelC/W FAR 91.207 ELT	
		20 N914D HOURS:810.1 000 PFD S/N 1976-A Version 1.1 software to the		4		nspection & op's check normal, replaced battery new date	
S	software version 2.0 TSO	Software in accordance with SB2009-04 Rev A		1		Mar. 2011Cleaned Fuel strainer bowl and screenLubed aircraft,serviced batteryI certify that this aircraft has	
		10822SC amendment Rev 2. No. 14525 dated 1-18-2010 for complete details on		1		been inspected IAW an annual inspection and was	
th	the work performed. I cert	ertify that the work performed on the aircraft has	1	A	4	determined to be in airworthy condition.	
b	een performed satisfacto	torily and per current Federal Aviation ons and is approved for return to service only for	The state of the s		Chal Burns AP2829180IA		
ť	the work performed.	is and is approved for return in the control of the				- Olida N Bullio M 2020 100 M	
7	Mike Pipper A&P 46263	24580 14			4		
	like rippon ricci reaco	74360 IA	and the same of th			Lubbock Aero 6304 N. Cedar Ave. Lubbock, TX 79413	
	630	Lubbock Aero 304 N. Cedar Ave. abbock, TX 79403					
					N#: 914E	Make: Cirrus Model: SR22	
	#: N914D S/N: 1104 : 05-25-2010 Model: SR20	Make: Cirrus 0 Hobbs: 829.2		Removed Rosen Sun Visor system, STC SA0185SE and			
		raft battery Gill G-243, S/N-			reinstalled factory sun visors.		
	2505306.			Gary N. King AP3544414			
= 6	unalds that	4					
Arr	nold Hertel A&P 2826	ô822				A STATE OF THE PARTY OF THE PAR	
	//						

Weight and Balance Report

Lubbock Aero 6304 N. Cedar Lubbock, TX 79403 Ph. 806-747-5101

Cirrus Make

Serial#

Model

SR20

1104

Reg.#

N914D

Date of scale calibration:

Feb. 2010

Aircraft gross weight:

3,000.00

Airent		14/-	
Aircraft	as	we	gnea

All clait as Weighed									
Weight Point	Scale Reading	Tare	Net Weight	Arm	Moment				
Left	893.00 0.0		893.00	157.50	140,647.50				
Right	849.00	0.00	849.00	157.50	133,717.50				
Nose	363.00	0.00	363.00	67.50	24,502.50				
Total As Weighed			2,105.00	141.98	298,867.50				

Weight Adjustments

Description	Weight	Arm	Moment
Total Corrected Empty Weight	2,105.00	141.98	298,867.50

Corrected Empty Weight:

2,105.00

Center of Gravity:

141.98

Useful Load:

895

Aircraft Mechanic

2826822 A&P

2/17/2011

Title

Cert. Number

Date

LUBBOCK AERO.

6304 N. Cedar Ave., Lubbock, TX 79403

Date: 02/18/11 N#: 914D Make: Cirrus Model: SR20

S/N: 1104 Hobbs: 870.0 ATT: 870.0

C/W Annual inspection IAW FAR 43 appendix D.

C/W AD 2008-11-18 (7-07-08) by inspection of engine exhaust/ heat exchanger IAW SB 2X-78-07R1. No defects noted.

C/W SB 2X-32-18R4 by visual inspection only, no cracks or defects found at this time.

C/W 12 month Turn and Bank battery replacement. Next due: 02-2012.

C/W 12 month Fire extinguisher weigh and inspection. Weight 26 oz.

C/W FAR 91.207(d) by inspection and op's check of ELT no defects noted, ops check normal, battery due 7-2015.

C/W Battery capacitance check. Battery was found to be at 88 percent.

Checked brake reservoir fluid level and serviced. --Inspected and serviced tires as required. --Removed, cleaned, inspected, packed and re-installed wheel bearings. --Removed screen, inspected, cleaned, re-installed fuel bowl and leak check. --Ops check interior and exterior lights. --Removed muffler shroud, inspected and reinstalled shroud. --Replaced instrument vacuum filter and Vacuum regulator filter. --Checked cable tensions, surface travels and lubed flight controls. --Inspected all placards interior and exterior.

Replaced left MLG tire and tube with Goodyear Flight custom III 15X6-6.00, s/n: 02517635.

Resealed right brake caliper.

Replaced 1 left MLG wheel bearing and race.

Preformed weight and balance. See updated w&b sheet.

I certify that this aircraft has been inspected IAW an annual inspection and was determined to be in airworthy

condition.

Arnold Hertel AP2826822IA

INSPECTION RECORD F.A.R. 43.11-91.409

AIRCRAFT TIME	KIND OF INSPECTION-STATUS & SIGNATURE — CERT, NO. OF PERSON APPROVING OR	DISCREPANCY LIST DISAPPROVING AIRCRAFT FOR SERVICE
LOG ID# 1121	cs 6002 N. Cedar ave. Lubbock, TX 79403-9971 GG7	
date and foun Inspected P/N:	and static system tests and inspections required to comply with FAR 43 Appendix E. 910-00001-001 S/N:6265 (pilot) and P/N: 5934D-3 onder test and inspection required by FAR 91.413 was appendix F. Test included Transponder Factor test and inspections are on file at this repaire for recertification is May 12, 2013. Anthony J. Rumpel Date	S/N: 414048 (standby)
Reg #: N914D S/ Date: 06-02-2011 M	Lubbock Aero 6304 N. Cedar Ave. Lubbock, TX 79403 N: 1104 Make: Cirrus Iodel: SR20 Hobbs: 871.6	
Complied with C	Cirrus SB 2X-52-04R2, Passenger and or Strut Modification by installing Catcher pe 1, Rt. and Lt. hand, rod end kits. (P/N	
Inda Heriel A	WH/ &P 2826822	

		AIRCRAFT TIME	INSPECTION RECORD F.A.R. 43.11 –91.409 KIND OF INSPECTION-STATUS & DISCREPANCY LIST		INSPECTION RECORD F.A.R. 43.11-91.409					
_	DATE	IN SERVICE	SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE	DATE	AIRCRAFT TIME IN SERVICE		NSPECTION-STATUS & DISCREPANCY LIST CRSON APPROVING OR DISAPPROVING AIRCRAFT FOR SE	FRVICE		
=	6/6/11 871.6 Romand Nose wheel point to report charle. Part repaired and repained Town whosher yell 76 50 49 6/6/11 871.6 27/7/1/12 wheel point after repaire. Chy Mh Herrospo				MAKE Cirrus MODEL SR20 S/N 1104 REG NO N914D WORK ORDER 1132	Clear Star Aviation Repair Station No. 5CSR009B 4765 Fronk Luke Dr	DATE 519/2011 AC TSN 873.9 HOBBS: 873.9	1974-53 N		
Ē	616/11	871.6			11386-001 and e 2X-27-16 R1, by	ss 88 2X-57-05 R2 by installing kit P/N 70105-001 afte outboard P/N 11775-902 alleron hinges. Complied- rinstalling kit P/N 70255-002. Found AD 2007-14-0 10R1 Installed new R/H wing tip light lens retainer	with SB 2X-25-05 R2. Complied with SB 3 previously complied with by compliance			
Weig_ eft					seal Adjusted the reinstalled with resolution of the sound in the seal of the	ne nose wheel axle and fork tension. Removed both new double-sided tape. Installed new standby vacual dorilled small cracks in LIH side and RyH front baffl LIH aft baffle fwd of oil cooler. Installed new prop preplaced the governor rod end attach washer. Rem the landing light attachment nut plates and reinstall	h wing root fairings, cleaned, preped, and um outlet hose using P/N le. Fabricated doubler from .040 2024–T3 jovernor cable anchorage clip P/N oved landing light from the L/H forward led. Installed vacuum manifold P/N			
tal A			Lubbock Aero 6304 N. Cedar Ave. Lubbock, TX 79413		01/28/2011 Ren and reinstalled	6-2 after overhaul performed by Aero Accessories, moved induction assembly, secured the induction as Adjusted cabin door handle actuation roll pins to the pins to keep them for falling out. Replaced both en- ge.	essembly aft mount bracket with new rivets e correct height, reinstalled handles and			
			N#: 914D Make: Cirrus Model: SR20 Date: 07-06-2010 S/N: 1104 Hobbs: 840.1		Pertinent details of	repair are on file at this Certified Repair Station 5CSR009	OB.			
			Removed Gill G243 battery and installed Concord RG24		DATE: 6/16/2011	SIGNED Signed	Work Order 113257			
al Cc			-15M sealed battery.			Daw, Isaiah Certified Repair Station No. 5CSR009B	Printed by EBis 3 (datcomedia.com)	Link		
1			Chad R. Burns AP2829180							
- Virginia										
								77.7.7		

	INSPECTION RECORD F.A.R. 43.11-91.409						INSPECTION RECORD		
DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTI SIGNATURE — CERT. NO. OF PERSON A	ON-STATUS & DISCREPANCY LIST APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE	_	DATE	AIRCRAFT TIME IN SERVICE	N914D Hobbs; 906.7		
6-17-11	control shafts.	Phone: 672-267-2376 ries p governor and throttle control cables at both ends as we Installed new Teflon guide washers P/N 50823-001 and of repair are on file at this Certified Repair Station 5CSR009B.			9-15-11	In Se	Replace prop governor support bracket P/N 658017 and check cable rigging. Replace intra-cylinder baffle supports at left forward position and right rear. Replace pilot side push to talk switch P/N 50339-001. C/W Cirrus SB2X-76-03 by installation of new control quadrant P/N 70060-002, check rigging and install interior. The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. 57541 FAA Approved Repair Station No. B2ER1441 Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020 Serial # 1104 Fight Time: 920.3 Serial # 40449974. Serial # 40449974. Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020		

	AIRCRAFT TIME	INSPECTION RECORD F.A.R. 43.11 –91.409 KIND OF INSPECTION-STATUS & DISCREPANCY LIST	INSPECTION RECORD F.A.R. 43.11-91.409				
DATE	IN SERVICE	SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE	AIRCRAFT TIME IN SERVICE AIRCRAFT TIME IN SERVICE KIND OF INSPECTION-STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE				
Piq.		N914D Cirrus SR20 S/N 1104 Hobbs; 934.7 Removed the following equipment: Garmin GNC-420 GPS/Com S/N 97200109, Garmin GI-102A CDI S/N J201069, Garmin GA-56 antenna S/N 59052309 Installed the following equipment: Garmin GNS-430W WAAS GPS/Nav/Com S/N 23431957 IAW STC# SA01933LA-D, Garmin GA-35 WAAS GPS antenna S/N 57926 IAW STC# SA0195SE, Garmin GI-106A CDI S/N F10-10373 IAW Mid-Continent installation manual #8017702 Rev C. File FAA Form 337. Weight and balance updated. Update #1 Garmin GNS430W main software to version 3.30 IAW Garmin SB 0918 Rev A. Add AFMS #190-00356-03 Rev B to the aircraft records. Add Software Version 3.30 upgrade supplement #190-00356-34 Rev B to the GNS-430W Pilot's Guide. Update the Aspen EFD-1000 PFD software to version 2.2.3 IAW Aspen SB2010-10. Software #302-00007-006 installed and added AFMS#900-0008-001 Rev n to the aircraft records. Added Pilot Guide Errata#091-00014-001 and Pilot Guide Addendum #091-00017-001 To the Pilot's Guide. The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. A56906 Bated: 10-27-11 FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020	N914D Hobbs; 952.4 Aircraft TT; 952.4 AIRFRAME CW FAR91.207(d) (406 ELT) inspection, battery replacement next due July 2015. C/W AD2008-11-18 exhaust system inspection. C/W Crrus SB 2X-32-18R4 nose gear leg inspection. Replace loose rivets on top cowing by oil door and touch up paint. Install new engine air filter P/N Ba-24. Install new fuel bowl gasket P/N NAS1523-8B. Repair air box by installation of nut plates and rivet into place and reinstall. Install three new 9 volt batteries for Turn & Bank Indicator. Tighten up baggage coor lock cylinder nut. Apply sealant around GPS antenna on top of aircraft. Repair air/oil separator b welding small hole and reinstall by cylinder #2. The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. 57869 Dated: 3-15-12 I CERTIFY THAT THIS AIRC/AS+ HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL TYPE INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. A.D. SUMMARY TO 2012-014 CHECKED. OPERATIONAL CHECK SATISFACTORY. SIGNATURE: FORM A WEAPA TOTAL TIME: 950.4 JACH: 952.4 DATE OF INSPECTION: 3155/2				

AIRCRAFT TIME INSERVICE SIGNATURE CERT. NO. OF PERSON APPROVING A RICRAFT FOR SERVICE 1001.1 AND CONSETT PAIN AVER SCRUE SIGNATURE SIGNATURE TO BE SIGNATURE SIGNATURE SIGNATURE TO BE SIGNATURE TO BE SERVICE 1001.1 AND CONSETT PAIN AVER SCRUE SIGNATURE SIGNATURE SIGNATURE INSERVICE N 9140 Cirrus SR20 AIRTRAME: Installed repaired engine fror YYBR641. Continental 1036 Aircraft Maintenance Manual Aircraft Maintenance Manual Service Order No. 58090 N 9140 Cirrus SR20 Removed Comant CI1125, Serial # 384827. Replaced ReSS antenna cable from the Splitter to the #1 GR6430W Nav. Tested the VOR & ICS on both the #1 and #2 430Ws. Removed Garmin GM340 audio panel for factory repair. Serial # 96255296. Garmin replaced the board and returned. Reinstalled the Audio Panel in accordance with the Garmin Installation Manual # 190-00149-01. See attached FAA 8130 fir detaults, Tested, satisfactory.	CTION RECORD 43.11–91.409
N 914D Cirrus SR20 AIRFRAME: In Stalled repaired engine from YYBR664L. Continental IO36 Aircraft Maintenance Manual Service Order No. S8990 N 914D Cirrus SR20 Aircraft Maintenance Manual Service Order No. S8990 Cirrus SR20 Removed Comant CI1125, Serial # 10092337. Installed new splitter, CI-1125, Serial # 384827. Replaced RGS8 antenna cable from the Splitter to the #1 GR4390W No. Tested the VOR &ICS on both the #1 and #2 430ws. Removed Garmin GM340 audio panel for factory repair. Serial # 96255296. Garmin replaced the board and returned. Reinstalled the Audio Panel in a coordance with the Garmin Installation Manual # 190-00149-01. See attached FAA 8130 fir detaults, Tested, satisfactory.	KIND OF INSPECTION-STATUS & DISCREPANCY LIST — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE
Service Order No. A57094 Dated: 7/24/2012d Siened: FAA Approved Repair Station No. BZER144J Joshart Enterprises and Aircraft Services, Inc. Ga tesee County Airport Batavia, N.Y. 14020	Serial # 1104 Flight Time: 1008.2 Poplar Grove Airmotive FAA CRS # -ES, Serial # 357281 following Cirrus occedures. Dated: 19/08/2012

Approving National Aviation Authority/Country: FAA/UNITED STATES	AUTHORIZED RELI	EASE CERT	CIFICATE OVAL TAG	3. System Tracking Ref. No. RMA 44714901
4. Organization: GARMIN International 1200 E 15	1st Olathe, KS 66062 Certificate No. G63	(R582'r		5. Work Order Contract/Invoice Number:
	Part Number: 9, Eligibility: * 011-00401-10 N/A	10. Quantity:	11. Serial/Batch Number: 96255296	RMA 44714901 12. Status/Work: REPAIRED
installer to assess installation compatibility. This unit complies with MOD 1 per Garmin's Service Bulletin Northis unit complies with MOD 3 per Garmin's Service Bulletin Northis unit complies with MOD 5 per Garmin's Service Bulletin Northis unit complies with MOD 5 per Garmin's Service Bulletin Northis unit complies with MOD 6 per Garmin's Service Bulletin Northis unit complies with MOD 7 per Garmin's Service Bulletin Northis unit complies with MOD 8 per Garmin's S	o. 0208B o. 0209 o. 0210 o. 0212 o. 0213 o. 0221 out in accordance with EASA Part-145 and in respect to the	7 Rev- 2, revision Date of	//2001.	
All renaited or replaced GARA	AIN units have a 90-day warranty or the continuation	on of the original factors	warranty from the original purch	ase date, whichever is longer.
4. Certifies the items identified above were manufactured in the provided design data and are in condition for safe Non-approved design data specified in block 13	actured in conformity to:	19. 14 CFR 43 Certifies that unlead Block 13 was according to the control of the	3.9 Return to Service ess otherwise specified in block 1	Other regulations specified in Block 13 3, the work identified in Block 12 and described in itle 14, code of Federal Regulations, part 43 and in
5. Authorized Signature N / A	16. Approval/Authorization No.: N / A	20. Authorized Signa	ture:	21. Approval/Certificate No. G6XR582Y
7. Name (Typed or Printed	18. Date (m/d/y)	22. Name (Typed or I	Printed)	23. Date (m/d/y)
N / A	N / A User/Installe	er Responsibilities	Stephen E. Abels	Jul 20 2012
It is important to understand that the existence of this D. Where the user/installer performs work in accordance we the user/installer ensures that his/her airworthiness authors are the user/installer ensures that his/her airworthiness are the	with the national regulations of an airworthiness authority accepts parts/components/assemblies from the	ority different than the air Airworthiness Authority	irworthiness authority of the country of the country specified in block	1.

DATE	AIRCRAFT TIM	E	F.A.R. 43	WHEN OF MICH	CTION CTATUE	DISCREPANCY LIST DISAPPROVING AIRCRAFT FOR SERVICE		AIRCRAFT TIME	F.A.R. 43.11 – 91.409 KIND OF INSPECTION-STATUS & DISCREPANCY LIST
DAIC	I MAN T		N914D SR-20 S/N 1104 H	lobbs: 1010.			2 2 2 s 1 3	1032.9 4LL	SIGNATURE—CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE SIM ADRA DB 2011—03, yddetad Agra
Boshart Enter Genesee coun Batavia, NY 14 Repair Station	ty Airport 1020	ER144J	Tested in Compliance w Part 43 Appendix E Para	rith Igraph (A,B)		0504 100003-001 ed and	213.17		EPD-1000 Dorel* 120507 Solme to Verse 2.2.1 Part 302-0007-009. Asper \$900-00007-001 Rank A.F.M. 3. Address To flight manual. Asper
	Reading #2	Tolerance +/-(feet)	HYSTERESIS/TE	Reading	NCES Tolerence	deral pe.			091-00017-001 P.L. Gide Add. add to the Aspe
-1000 -15 0 -15	- -15	20	Case leak Test	-97	(feet) 100	jer	-		Post Inhan gentled Apr Efform Housing IAN SB.
500 -3 1000 -15	0	20	Hysteresis Test First TP50% of Max	4/2	75				TOST Trability Grand Gree CE.
1500 -(o 2000 -10 3000 -(1			Hystereis Test First TP40% of max	57	75		-		100
4000 -8 6000 -13	16	35 40	After Effect Kollsman Winde	5 10	30	ion No. B2ER144J	1		CR3 # BZER1445
8000 -14 10000 -10 12000 -15		80	Pressure Setting in Reading	1/	Altitude Difference				
14000 -/(16000 -/7 18000	17	100	28.10 -1730 -	1737	-1727 -1340	Part 43 Appendix F			
20000 22000 25000		120 130 140	29.00 - SCO - 29.50 - 3% -	402	-863 -392	3 Appendix E			
30000		155 180	30.50 530 30.90 SGa	512	0 531 893	with Part			
150 90 150 90		205 230 255		772 boshe1	974	10			

INSPECTION RECORD F.A.R. 43.11-91.409

1010.7	N914D SR-20 S/N 1104 Hobbs; 1010.7 Remove Aspen EFD-1000 display P/N 910-00001-001 S/N 6265 Software Version 2.23. Install Aspen EFD-1000 display P/N 910-00001-001 S/N 120504 Software Version 2.23 IAW Aspen Installation Manual #900-00003-001 Rev AJ and Aspen Instructions for continued airworthiness.
	The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. A57180 Dated: 10-17-12
	FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020
1032.9	Boshart Enterprises Inc. East Saile Drive, Batavia, N.Y. 14020 Repair Station No. B2ER144J Aircraft N 9190 W/O No. A57253 Transponder Model 674-327 S/N 83702395 Has been tested IAW Part 91.413 para. a, b, c and found to comply with Part 43 Appendix F.
	Encoder Model A-30 S/N 68788 Altimeter Model EFO-1000 S/N 120504 #1 PFO Has been tested IAW Part 91.411 para a and found to comply with Part 43 Appendix E. 59340-3 414047 #2 House Aircraft Static System has been tested IAW Part 91.411 and found to comply with Part 33.1325 para 21 Signed #31C1417 Date 2/2013 Aircraft Tach/Hobbs Time 1032.9 House
	/032.9

INSPECTION RECORD F.A.R. 43.11-91.409	1		INSPECTION RECORD F.A.R. 43.11-91.409
DATE IN SERVICE	4	AIRCRAFT TIME	KIND OF INSPECTION-STATUS & DISCREPANCY LIST
N914D Hobbs; 1032.8 Aircraft TT; 1032.8 AIRRAME CWF FARS) 207(d) ELT inspection and operation test, perform 406 signal test , ID# ADCC40CA54002F1. Replace parachute reef line cutters per Cirrus airworthiness limitations, replacement next due 2/2019. Jack up aircraft, remove fairings. Grease wheel bearings and service brakes. Replace six well nuts the attach gear strut fairings. Replace vacuum regulator filter P/N B3-5-1. C/M SB 2X-32-18r4 nose gear gusset plate inspection per para (D)(1-6). C/M AD2008-11-18 by pressure test per SB 2X78-07r1, no defects noted. Remove and clean fuel bowl filter. The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. 60182 Dated: 2/22/13 I CERTIFY THAT THIS AVCAGH HAS BEEN INSPECTED IN ACCORDANCE WITH AUGUST TYPE INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. A.D. SUMMARY TO 13 - 6.3 CHECKED. OPERATIONAL CHECK SATISFACTORY. SIGNATURE:	-	SB 2X-78-0 DUE 7/2015 SB 2X-78-0 ON RT WITH INOW TURN OF A HERNET TWO NEW C RUDDET A HE FUT Proper S ELT REMOTE OF TIRC SOUXS G	
FOR REPAIR STATION BEET 1441 TOTAL TIME: 1032.8 TACH; 1032.8		1/	PIN BA-240 Justilles New DZUS FIGTENER BOTTON left
DATE OF INSPECTION: 2/22/13	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	The second secon	FD PIN 53-150 END - Jones K Mercail -
		2156 07 11	CRS# 82ER144J —
			1.
			- aver

INSPECTION RECORD Boshart Enterprises Inc. Tested in Compliance with F.A.R. 43.11-91.409 Genesee county Airport Part 43 Appendix E Paragraph (A,B) KIND OF INSPECTION-STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE Batavia, NY 14020 AIRCRAFT TIME AIRCRAFT TIME Repair Station Number B2ER144J DATE IN SERVICE DATE HYSTERESIS/TEST TOLERANCES Test I CERTIFY THAT THIS AIRCOAP+ HAS BEEN INSPECTED Tolerance +/-Altitude in Reading (feet) IN ACCORDANCE WITH AN ANNUAL TYPE INSPECTION Feet AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. -1000 -12 110 20 Case leak Test 100 A.D. SUMMARY TO 2014-02 CHECKED. 0 20 +8 -17 Hysteresis Test 500 20 40 OPERATIONAL CHECK SATISFACTORY. -13 75 First TP...50% of Max 1000 20 +12 -10 1500 110 25 Hystereis Test 75 SIGNATURE: 30 First TP..40% of max 2000 120 FOR REPAIR STATION BZER144J 30 3000 45 -10 After Effect 30 0 TOTAL TIME: 1110.2 TACH: 1110.2 35 4000 +17 N914D Hobbs; 1155.6 DATE OF INSPECTION: 3/4/2014 Kollsman Window Calibration 6000 14 +30 AIRFRAME 60 Pressure 8000 125 0 Install new EGT probe on #4 position P/N M-111 and check operation. 10000 80 Setting in Difference -15 1115 90 12000 In./Hg. 28.10 (feet) The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal -10 112 14000 100 -172 -1727 10 0 110 28.50 16000 -1340 Aviation Administration and is approved for return to service. -23 -1350 29.00 -863 Pertinent details of the repair are on file at this station under 18000 -27 120 Service Order No. ,60881 / Dated: 9-10-14 20000 130 29.50 -392 -10 -400 22000 140 29.92 -0- (ref) 0 Jones K Nerrich 25000 155 30.50 30 531 FAA Approved Repair Station No. B2ER144J 30000 180 30.90 900 893 Boshart Enterprises and Aircraft Services, Inc. 35000 205 30.99 1 990 974 Genesee County Airport Batavia, N.Y. 14020 40000 230 45000 255 W/O No. ASTRY Date: 2/2/15

DATE								
AIRFRAME CW FARS1.207(d) EIT battery replace C/W AD2008-11-18 nose gear inspectior install new Concord install three new em Next due 3/2016. In install new vacuum Reseal stainless ste Service compass wi Install two lower sec Jack up aircraft, rem Rotate right main ge The aircraft and/c inspected in accord Aviation Administr Pertinent details co Service Order N FAA Approved Rej Boshart Enterprise	ment next due 11/2019, ELT exhaust heat exchanger per per A-O) (1-6). Per G-24-11M Concorde bat ergency turn coordinator 9 vistall new engine air filter P/oump hoses. Clean air/oil siel heat shields on belly of air hfluid and reinstall. tions of door seal on pilot ar ove wheels and grease who are time and torque botts to 15 or component identified a dance with current regulation and is approved for fithe repair are on file air	olt batteries, replacement N BA-24. sparator. craft. d co-pilot doors. ele bearings. io in lbs. bove was repaired and attons of the Federal return to service. this station under: 3/2/15 IN ACCORDA AND WAS DI A.D. SUMMA OPERATION. SIGNATURE: FOR REPAIR TOTAL TIME:	ACR ELECTRONICS. Inc. ARTEX PRODUCTS - CAGE Code: 60253 Fort Lauderdale, FL 33312 ME406 LITHIUM BATTERY PACK MnO2 PART NO: 452-6499 REV: E TSO C126 S.N.:356442-09 EXPIRATION DATE: NOV/2019 DO-227 ENV CAT DIXBC[204][204]XRXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	9/11/15 [1/12]15				

INSPECTION RECORD

FAR 4311-01 400

INSPECTION RECORD FAR 43 11-01 400

N914D Hobbs; 1230.8

Update both GNS-430W software #1 S/N 97101428 and #2 S/N 23431957. C/W Garmin SB 1315 Rev A, update GPS software to version 5.0. C/W Garmin SB 1474 Rev A, update main software to version 5.20. Add AFMS #190-00356-03 Rev E and ICA # 190-00356-65 Rev D to the aircraft records.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. A57881 Dated: 9-11-15

FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020

N914D Hobbs; 1239.0 AIRFRAME

Rebuild pllot side right master cylinder using new MS28775-012, MS28775-006, and MS775-113 o-rings. Pressure bleed brakes with 5606 hydraulic fluid. Operational check satisfactory.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No./ 61364 Dated: 11-12-15

FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020

6		INSPECTION F.A.R. 43.11	-91.409					INSPECTION RECORD F.A.R. 43.11–91.409
D	ATF AIRCRAFT TIME	CICNATIRE - CERT NO	D OF INSPECTION-STATUS & DISC OF PERSON APPROVING OR DISA	APPROVING AIRCRAFT FO	R SERVICE	DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION—STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE
	PR	Aviation S		716-633- FAX 716-839- NIAGARA INTERNATIONAL 50 NORTH AIRPORT DRIVE FFALO NEW YORK 14225 1	L AIRPORT	12/16/15		N914D Hobbs; 1242.8 Aircraft TT; 1242.8 AIRFRAME Install a new lower cowl seal P/N 53722-063U using 1300L adhesive. Remover right caliper, install two new MS28775-222 o rings and new caliper cylinder P/N 061-01800 and reinstall caliper. Bleed brakes
5	Registration Number	Serial Number	Hobbs Time	Cycles	Date			and service system with mil spec 5606 hydraulic fluid.
0	N914D	1104	1218.6	-	20 July 2015			The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal
	Taxi Light INOP -Removed and replaced lamp Right Wing position light(ree, -Removed and replaced lamp Right Wing Aft Position light -Removed and replaced RH v IAW SR20 AMM 33-40-02. (C) The aircraft and/or component F.A.A. regulations and was form on file at this (repaigagency y fix	ar) INOP. o with new. Lamp tested. It keeps blowing bulbs. white NAV light socket. P. Ops check good.	No defects noted at t	his time. 'eramic insulato	or broken on oldu	\$ 1000		Pertinent details of the repair are on file at this station under Service Order No. 61401 Dated: 12-16-15 FAA Approved Repair Station No. B2ER1441 Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020
	Signed	Certificate	Number CRS BIOR 4	73C.				

INSPECTION RECORD **INSPECTION RECORD** F.A.R. 43.11-91.409 F.A.R. 43.11-91.409 KIND OF INSPECTION-STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE AIRCRAFT TIME IN SERVICE KIND OF INSPECTION-STATUS & DISCREPANCY LIST DATE SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE N914D 3/16/16 N914D Tach; 1259.0 Hobbs 1259.0 5/20/16 Hobbs; 1248.6 AIRFRAME TT: 1248.6 C/W FAR91.207d ELT inspection and operation test. Battery due Boshart Enterprises Inc. Tested in Compliance with 11/2019. C/W AD2008-11-18 inspection and pressure test of Genesee county Airport Part 43 Appendix E Paragraph (A,B) exhaust system per para.(e) using guidelines in SB2x-78-07r1. Replace induction filter p/n BA-24. Jack up aircraft. Clean and Batavia, NY 14020 EFD1000 Repair Station Number B2ER144J grease wheel bearings. Replace right main tire. Replace inbd.
brake linings on both sides p/n 066-10500. Service brake reservoir.
Inspect prop governor rod end. Replace bolt and install cotter Test HYSTERESIS/TEST TOLERANCES in: Altitude in Reading Tolerence (feet) Reading Feet (feet) PE Wei -20 20 -1000 The aircraft and/or component identified above was repaired and Case leak Test -85 100 Left -20 20 inspected in accordance with current regulations of the Federal Hysteresis Test 500 -20 20 Right Aviation Administration and is approved for return to service. 0 75 FA 1000 -20 20 First TP...50% of Max Pertinent details of the repair are on file at this station under Vose A -20 25 Hystereis Test 1500 Service Order No. 61465 Bo Dated: 3-16-16 0 75 First TP..40% of max G 2000 -25 30 11 Solut 3000 -25 30 30 After Effect 0 FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Inc. B 4000 -25 35 3/9/12 Kollsman Window Calibration 6000 -20 40 -15 60 8000 Genesee County Airport Batavia, N.Y. 14020 Pressure Difference Reading 10000 -10 80 Setting in I CERTIFY THAT THIS Armost HAS BEEN INSPECTED 12000 -10 90 (feet) In./Hg. 28.10 tal C. IN ACCORDANCE WITH LAUGUE TYPE INSPECTION 14000 -5 100 -1735 -1727 AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. 16000 -5 110 28.50 -1350 -1340 18000 120 29.00 -865 -863 A.D. SUMMARY TO 16-14 CHECKED. 20000 130 29.50 -390 -392 OPERATIONAL CHECK SATISFACTORY. -0- (ref) 22000 140 29.92 0 25000 155 30.50 520 531 SIGNATURE: 880 30000 180 30,90 893 FOR REPAIR STATION BEER144J 205 970 35000 30.99 974 TOTAL TIME: DY (TACH HASE 124X 6 40000 230 45000 255 DATE OF INSPECTION: 3/16/16 50000 280 W/O No. A58166 Date 3/9/2017

⊇14D Tach; 1259.0 Hobbs 1259.0 ■RFRAME
Lepainted lower cowling, nose strut fairing, and nose wheel pant With Nason BC/CC. Installed all new CamLoc fasteners in cowling. Applied new stripes on cowling and nose wheel pant. Installed Anti erosion tape on nose wheel pant.
The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.
Pertinent details of the repair are on file at this station under Service Order No. 61538 Dated: 5/20/2016
FAA Approved Repair Station No. B2ER144J
Boshart Enterprises and Aircraft Services, Inc.
Genesee County Airport Batavia, N.Y. 14020
Boshart Enterprises Inc. East Saile Drive, Batavia, N.Y. 14020 Repair Station No. B2ER144J
Aircraft N 9140 W/O No. A 58166
Transponder Model GT X-327 S/N 83702395 Has been tested IAW Part 91.413 para. a, b, c and found to comply with Part 43 Appendix F.
Encoder Model A-30 S/N 68788
Altimeter Model <u>EFO 1000</u> S/N 120504 Has been tested IAW Part 91.411 para a and found to comply with Part 43 Appendix E.
Aircraft Static System has been tested IAW Part 91.411 and found to comply with Part 23.1325 para 2I
Signed Date 3/9/17 Aircraft Tach/Hobbs Time 1315.3 Form BOSHE 10
Aircraft Tach/Hobbs Time 1315.3

		F.A.R. 43.11-91.409					ONI DECO			_
DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION-STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE		AIRCRAFT TIME IN SERVICE	Boshart Ente			Tested in Complian Part 43 Appendix I		.B)
3/10/12	1	N914D Hobbs: 1314.7 ACTT: 1314.7	3 G LA		Batavia, NY		2ER144J	St	tandby Altim	eter
	7	AIRFRAME	315)14		Test			HYSTE	RESIS/TEST TO	LERANCES
		C/W FAR 91.207(d) ELT Inspection, battery due for replacement 11/2019, ELT remote battery due for replacement 3/2019.			Altitude in Feet	Reading	Tolerance +/-(feet)		Re	ading Tolerer
		C/W AD 2008-11-18 Exhaust System Pressurization per visual inspection IAW Cirrus SB 2x-78-07R1.			-1000	-10 -10	20	Case leak Test		-85 100
		C/W Cirrus SB 2x-32-18R4 Nose Gear Inspection. Installed new induction air filter			500	-10	20	Hysteresis Test	First	
	F	P/N BA24. Fabricated and installed baffle patch on forward right side baffle,			1000	0	20	TP50% of Max		5 75
		riveted in place. Replaced missing rivets on oil cooler baffle. Installed new right hand Whelen		8	1500	-5	25	Hystereis Test		-
	/ V	strobe light bulb P/N 36-0050705-00. Tightened door lock in baggage door.			2000	0	30	First TP40% of	max	10 75
	-	Installed new fire extinguisher P/N 12533-004.			s 3000	5	30	After Effect		5 30
		Raised aircraft on jacks, cleaned and repacked all wheel bearings.			4000	15	35			
		Service brake reservoir with 5606 hydraulic fluid. Remove, left and right main wheel pant brackets, weld cracks, prime, paint			6000	10	40	Koll	Isman Window	
		and reinstall brackets. Inspect fuel bowl and fuel servo finger screen.		h	8000	15	60	Pressure		Altitud
					10000	5	80	Setting in	Reading	
		Service Order No. 61868 / Date 3/10/2017			12000	5	90	In./Hg.		(feet)
		III Ye Caplant			14000	10	100	28.10	-1735	-1
		FAA Approved Repair Station No. B2ER1443			16000	5	110	28.50	-1345	-1
		Boshart Enterprises and Aircraft Services, Inc.	Additional and the second		18000		120	29.00	-870	-4
	-	Genesee County Airport Batavia, N.Y. 14020	7		20000		130	29.50	-405	-
					22000	I said Said	140	29.92	-0- (ref)	
	THE STREET, I'M				25000		155	30.50	530	
					30000		180	30.90	890 970	
			7	1 32	35000		205	30.99	970	
					40000		230 255			boshe11
		A second			45000				A58166 D	ate 3/9
					50000		280	W/O No.	A30100 D	ite di
					4					
									W. The	

INSPECTION RECORD F.A.R. 43.11-91.409

DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION-STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE
31914		Boshart Enterprises Inc. East Saile Drive, Batavia, N.Y. 14020 Repair Station No. B2ER144J Aircraft N 9/40 W/O No. 458/66 Transponder Model S/N Has been tested IAW Part 91.413 para a, b, c and found to comply with Part 43 Appendix F. Encoder Model S/N Altimeter Model 593400-3 S/N 4/4048 Has been tested IAW Part 91.411 para a and found to comply with Part 43 Appendix E. Aircraft Static System has been tested IAW Part 91.411 and found to comply with Part 23.1325 para 21 Signed Date 3/9/17 Aircraft Tach/Hobbs Time 1315. 3 6rm BOSHE 10

AND OF INSPECTION-STATUS & DISCREPANCY LIST IN SERVICE SIGNATURE—CERT. NO. OF PERSON APPROVING ORIGINATE FOR SERVICE DATE ARCHIT INSE SIGNATURE—CERT. NO. OF PERSON APPROVING ORIGINATE FOR SERVICE SIGNATURE OF PERSON APPROVING ORIGINATE FOR SERVICE SIGNATURE OF PERSON APPROVING ORIGINATE FOR SERVICE SIGNATURE OF PERSON APPROVING ORIGINAT	INSPECTION RECORD F.A.R. 43.11–91.409			INSPECTION RECORES.A.R. 43.11-91.40	
PRIOR Aviation Sewite Int. Registration Number Model Serial Number Total Time Date N914D Cirrus SR 20 1104 1317.8 04/24/2017 1. Nose tire flat. C/A Inspected nose tire and tube assy, and found small pin hole in tube. Removed and replaced tube assy with new. Serviced and reinstalled wheel assy on A/C IAW Cirrus SR-20 AMM 32-20. No other discrepancies noted. The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this standour component identified above was repaired and inspected in accordance with current explaints of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this standour component identified above was repaired and inspected in accordance with current F.A.A. regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this repair agency under Work Order # 025390 Dated 04/24/2017 Signed Administration and inspected in accordance with current place of the repair are on file at this repair agency under Work Order # 025390 Dated 04/24/2017 Signed Administration and sapproved for return to service. Pertinent details of the repair are on file at this repair agency under Work Order # 025390 Dated 04/24/2017	AIRCRAFT TIME KIND OF INSPECTION-STATUS & DISCREPANI DATE IN SERVICE SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROV	INC AIRCRAFT FOR SERVICE		KIND OF INSPECT	ION-STATUS & DISCREPANCY LIST
Registration Number Model Serial Number Total Time Date N914D Cirrus SR 20 1104 (317.8 04/24/2017 1. Nose tire flat. C/A Inspected nose tire and tube assy, and found small pin hole in tube. Removed and replaced tube assy with new. Serviced and reinstalled wheel assy on A/C IAW Cirrus SR-20 AMM 32-20. No other discrepancies noted. The aircraft and/or component identified above was repaired and inspected in accordance with current equals of the repair are on file at this station under Service. Pertinent details of the repair are on file at this repair agency under Work Order # 025390 Dated 04/24/2017 Signed Aman Component identified above was repaired and inspected in accordance with current file. CRSBIOR473C	1/24/17		7 0	Hobbs; 1348.5 Diagnose issue with tachometer. Found tach	Airframe
N914D Cirrus SR 20 1104 1317.8 04/24/2017 1. Nose tire flat. C/A Inspected nose tire and tube assy. and found small pin hole in tube. Removed and replaced tube assy with new. Serviced and reinstalled wheel assy on A/C IAW Cirrus SR-20 AMM 32-20. No other discrepancies noted. The aircraft and/or component identified above was repaired and inspected in accordance with current F.A.A. regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this repair agency under Work Order # 025390 Dated 04/24/2017 Signed Amade CRSBIOR473C	Aviation Service Inc.			Install cowl The aircraft and/or component identified ab inspected in accordance with current regular Aviation Administration and is approved for Pertinent details of the repair are on file at the component of the aircraft and aircraft an	ove was repaired and tions of the Federal return to service. his station under
F.A.A. regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this repair agency under Work Order # 025390 Dated 04/24/2017 Signed CRSBIOR473C	Nose tire flat. C/A Inspected nose tire and tube assy, and found small pin he replaced tube assy with new. Serviced and reinstalled wheel assy on A/C IAW	ole in tube. Removed and		FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Ir	
Prior Aviation/Service Inc. 50 N. Airport Drive Buffalo NY 14225	F.A.A. regulations and was found airworthy for return to service. Pertinent details on file at this repair agency under Work Order # 025390 Dated 04/24/2017	the contract of the contract o			

	INSPECTION RECORD F.A.R. 43.11-91.409		INSPECTION RECORD F.A.R. 43.11-91.409				
DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION-STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE	DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION-STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE		
824/17		N914D AIRFRAME Complied with Aspen Avionics Service Bulletin No. SB2016-05: MAP Version 2.9 amd IOP version 2.1 Software Update Notice. Complied with Aspen Avionics Tech Note No. TN2015-01 Rev D: Instructions for enabling Angle of Attack in a Level C PFD, MFD or EBD with software version 2.8 or later. Complied with Aspen Avionics Tech Note No. TN2011-10 Rev C: Instructions for unlocking Evolution Synthetic Vision in a PFD, EBD Or MFD with software version 2.8.3 or later. The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No. A58252 Dated: 8/24/2017 FAFApproved Repair Station No. BZER144J Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020	3)(3)18		N914D Hobbs: 1380.0 AIRFRAME Removed Garmin GTX-327 Transporder, s/n 83702395 and ACK A-30 Altitude Encoder s/n 68788. Installed Garmin GTX-345 ADS-B In/Out Panel Mounted Transponder s/n 568009797. Installed Garmin Altitude Encoder, s/n 376004713. Interfaced transponder to GNS-430W for GPS, Traffic, Weather and Heading Data. Interfaced encoder to GTX-345 and GNS-430W for altitude data. All work done in accordance with Garmin Installation Manual No. 190-00734-10 and Garmin STC No. SA01714WI. Filed FAA Form 337. Updated Aircraft Flight Manual Supplement. Service Order No. A58352 Dated: 3/12/18 DATE: SAMPTOVED REPAIR STATION SERIL411 Boshart Enterprises and Aircraft Services, Inc. Genesee County Airport Batavia, N.Y. 14020		

Hobbs: 1378.8; ACTT: 1378.8; AIRFRAME CON FAR 91 207(c) ELT inspection. Battery due for replacement 11/2019. Remote battery due 11/2019. CON AD 2006.1-11.6 Enhancist Result Exchanger per SB 2x-76-07R1. Results Strip 11/20 Remote battery due 11/2019. CON AD 2006.1-11.6 Enhancist Result Exchanger per SB 2x-76-07R1. Results Strip 11/20 Remote battery due 11/2019. Aircraft TI 14/31.7 TI 14/31.7 TI 14/31.7 Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Installed new 6V batteries for stand by turn coordinatoristal warning. Next due 3/2019 gg 14/78 ACTT. Inst		INSPECTION RECORD	INSPECTION NES
A.D. SUMMARY TO 2018-05 CHECKED. FA Apploid Repair Station No. BZER1443	Hobbs: 1379.8; ACTT: 1379.8; ARFRAME CW FAR 91.207(d) ELT Inspection. Battery due for repi Remote battery due 11/2019. CW AD 2008.1-1-18 Exhaust Heat Exchanger per SB 2) Next due 3/2019 @ 1479.8 ACTT. CW Cirrus SB 2x-32-18R4 Nose Gear Inspection. Next @ 1479.8 ACTT. Installed new 9V batteries for stand by turn coordinator/s Next due 3/2019 @ 1479.8 ACTT. Installed new clock AA battery. Next due 3/2019 @ 1479. Lubnicated all flight controls and pulleys. Raise aircraft of inspect all wheel bearings. Checked brake disks and brake linings. Installed new G 15x6.00-6 and tube on left main wheel. Serviced brake reservoirs with 5606 hydraulic fluid. Inspected and cleaned fuel bowl screen. Installed new E Fabricated baffle patch for aft inght side baffle, riveted in Removed MCU cover, and inspect for corrosion. Reinst Service Order No. 62220 Date 3. FAA Approved Repair Station No. B2ER144J Boshart Enterprises and Aircraft Services, Inc.	acement 11/2019. 2-78-07R1. due 3/2019 stall warning. 2-8 ACTT. In jacks, bood Year Flight Special II 2-24 induction air filter. place. all cover. 2-16/2018 I CERTIFY THAT THIS Accord Type INSPECTED IN ACCORDANCE WITH A TOQUEL TYPE INSPECTION	## SIGNATURE — CERT. NO. OF PEI N914D Hobbs; 1432.2 TT; 1432.9 C/W FAR 91.207d ELT inspection and operation test. Replace landing light with new Whelen P36P2L LED bulb. Replace induction filter p/n gA-24. Jack up aircraft. Clean and grease wheel bearings. Replace right tire with new GDYR 15x6:00x6. Clean and inspect wheel assembly, torque bolts to 150 in/lb. Clean and lubricate engine controls. C/W AD2008-11-18 exhaust system inspection. Replace reef line cutters p/n 25347-002. Manufacture date 8/2018. Replace vacuum regulator filter AB-3-5-1 and instrument filter D9-18-1. Replace turn coordinator Back up batteries. Replace clock battery. Install new alternator p/n E5-4024LP s/n H-5021621. I certify that this aircraft has been inspected in accordance with an annual type inspection and was found to be in airworthy condition. AD summary checked thru 19-05 The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviston Administration and is approved for return to service. Pertinent details of the regair arp on file at this station under
Genesee County Airport Batavia, N.Y. 14020	Serviced brake reservoirs with 5606 hydraulic fluid. Inspected and bleaned fuel bowl screen. Installed new E Fabricated baffle patch for aft inght side baffle, inveted in Removed MCU cover, and inspect for corrosion. Reinst Service Order No. 62220 Date 3. FAA Approved Repair Station No. 62ER144J Boshart Enterprises and Aircraft Services, Inc.	I CERTIFY THAT THIS ACCORD HAS BEEN INSPECTED IN ACCORDANCE WITH AS DOUGL TYPE INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	I certify that this aircraft has been inspected in accordance with an annual type inspection and was found to be in airworthy condition. AD summary checked thru 19-05 The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this station under Service Order No.,62564 FAA Apployed Repair Station No. BZER1441 Boshart Interprises and Aircraft Services. Inc.

The second second second second