N 1459 V

AIRCRAFT TECHNICAL RECORD

Section 1. AIRFRAME LOG



Section 1: Airframe Log

Section	AIR TIME			LANDINGS / CYCLES	
DATE	DAILY TOTAL	TOTA		DAILY	TOTAL
/ /		HOURS			

DETAILS OF TASK (INSPECTION, REPAIRS & REPLACEMENT)

Caldwell Aviation

Columbus, MS 39701 4717 S. Frontage Road

662-361-8701

Tach: 4146.6 N1459V AFTT: 4146.6 August 9, 2019 August 9, 2019

Art 11: 4146.6

Inspected aircraft in accordance with Cessna 172M Checklist and FAR 43, Appendix "D". Lubed in Inspected aircraft in accordance with Costal Area bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through accordance with Lube chart. Installed a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's through a new bracket induction filter BA-6108. Researched AD's a new bracket induction filter BA-6108. Researched AD's a new bracket induction filter BA-6108 accordance with Lube chart. Instance a management of the sails and Pin). I certify this aircraft has been inspected in 2019-07. Complied with AD 11-10-07 (Start and address of the first and an accordance with a 100 hr/ANNUAL inspection and determined to be in airworthy condition.

Robert S. Caldwell, III A&P 3256723, I.A.



MAINTENANCE ENTRY Sept 19, 2019 CESSNA 172M, N1459V S/N 17263596

ITEMS REMOVED: Garmin GTX327 Transponder P/N 011-00490-00.

ITEMS INSTALLED: Garmin GTX345 w/out GPS P/N 011-03302-00, Rami transponder antenna P/N AV-74.

MAJOR ALTERATION: A Garmin GTX345 transponder whout GPS was installed in the same location as the removed GTX327 and interfaced to the GNX30W, newly installed transponder antenna and Alditude Encoder. The GTX345 was installed using new RG-142 transponder coax and circuit the GNX30W, newly installed anapponder antenna and Alditude Encoder. The GTX345 was installed using new RG-142 transponder coax and circuit related to the GTX345 was connected to the avionics buss using a new 3 amp resettable circuit breaker labeled Xponder installed in the same breaker. Power to the GTX345 was connected to the avionics buss using a new 3 amp resettable circuit breaker labeled Xponder installed in the same breaker.

breaker. Power to the GTXJ43 was connected to the aviounce outs using a new a suppresentation of the same location as the removed 5 amp circuit breaker.

The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X was installed under the guidelines and in reference to Garmin GTXJXX transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X was installed under the guidelines and fin reference to Garmin GTXJXX transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X was installed under the guidelines and fin reference to Garmin GTXJXX transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 23 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder Part 24 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder PART 24 AML STC DM PN: 190-00734-10
The Garmin GTXJ4X transponder PAR

of 14 CFR section 9/227.
The newly installed transponder was evaluated and tested using IFR ATC6000 equipment and found to be within the parameters of the IM Operation Performance Ground Check. Satisfactorily performed tests and inspections as required by FAR 91.413, Part 43 Appendix F and Altitude Reporting Cornellation Test per FAR Part 43 Appendix E (c). Satisfactorily performed ADS-B Checks.

MINOR ALTERATION: A Rami AV-74 transponder antenna was installed below the copilot floor board under the guidelines of and in reference to the RAMI installation instructions Doe #27-801-02, Rev D Dec 2018.

Updated GNS-300W from 5.20 to 5.4 Main, 5.0GPS. AFMS updated to Doe #190-00356-03 Rev F. Final ground checks satisfactory. Updated GNS-300W from 5.20 to 5.4 Main, 5.0GPS. AFMS updated to Doe #190-00356-03 Rev F. Final ground checks satisfactory.

MINOR REPAIR: Found all pilot instrument panel shock mounts cracked or broken. Replaced all 10 pilot side panel shock mounts.

See FAA Form 337 dated Sept 19, 2019.

See F.A. FURM 301 UNION SEPERATOR.

The work described above has been inspected and found airworthy for return to service.

Weight and balance/upplemental equipment list updated.

Page 1 of 1



Maintenance Entry

September 19, 2019 N1459V Cessna 172 sn 17263596

Repaired 2500ft/min static leak. Tightened several fittings and staic drain bottle. Foundak rate satisfactory at 37ft/min @2000ft. Found Ki209 and GI-106A lighting inop. Found lighting wires disconnected from lighting dimmer bus. Connected to dimming circuit. Replaced all pilot instrument panel shock mounts due to being cracked or broken. Updated GNS430W software from 5.20 main/5.0 GPS to 5.40 min/5.0 GPS. AFMS updated to Doc #190-00356-03 Rev F.

Final systems ground checks satisfactory.

The work described above has been inspected and found airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order #011583.

4265172

Signed for Carpenter Avionics, Inc. Repair Station RH4R492M



Maintenance Entry

sn 17263596 September 19, 2019 N1459V Cessna 172

I certify that the altimeter

United Instruments Pneumatic Altimeter- P/N- 5934PA-3 S/N- 426375

has been tested, inspected and found to comply with Appendix E, para. b of FAR 43. The altimeter was tested to a maximum of 18,000 feet.

I certify that the ATC transponder

Garmin GTX345 P/N- 011-03302-00 S/N- 3EG029418

has been tested inspected and found to comply with Appendix F of Far 43. The altitude reporting correspondence checks required have been performed to 18,000 feet. This aircraft meets criteria outlined in FAR, part 43 Appendix E, para. c. I certify that the static system was tested and inspected and found to comply with Appendix E para. a of FAR43. The work described above has been inspected and found airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order #011583

4265172 Signed for Carpenter Avionics, Inc. Repair Station RH4R492M

Caldwell Aviation

Columbus, MS 39701 4717 S. Frontage Road

662-361-8701

AFTT: 4153.2

Removed and installed Whelen A490TCCF Strobe Power Supply PN 01-0770006-09. Replaced (1) Lord Cowl Mount Bushing PN J-7444-1. Removed and installed new NDM Oil Cooler PN 20002A. Operational check

performed satisfactory.

Robert S. Caldwell, III A&P 3256723, I.A.

LICENCE: AME OF AMO/ACA

NAME/ SIGNATURE

Caldwell Aviation

Columbus, MS 39701 4717 S. Frontage Road

662-361-8701

AFTT: 4161.1 Hobbs: 2869.9 Tach: 4161.1 N1459V Inspected aircraft in accordance with Cessna 172M Checklist and FAR 43, Appendix "D". Lubed in accordance November 27, 2020 with Lube chart. Installed a new bracket induction filter BA-6108. Installed McFarlane Mixture Control Cable PN MC600-72. Installed 8 ft. Scat Hose. Installed Merl ELT Battery BP-1010 Exp 12-22. Installed Lord Cowl Mount Bushing PN J-7444-14. Researched AD's through 2020-11. AD 2020-18-01 does not apply to this model number. Complied with AD 11-10-07 (Seat Rails and Pin). I certify this aircraft has been inspected in accordance with a

100 hr / ANNUAL inspection and determined to be in airworthy condition

Robert S. Caldwell, III A&P 3256723, J.A.

Caldwell Aviation

4717 S. Frontage Road Columbus, MS 39701

662-361-8701

Tach: 4162.7-Hobbs: 2871.8 AFTT: 4162.7 November 27, 2020 N1459V In accordance with 43.9 or 43.11, this aircraft was flown for 1.6 hours for initial engine oreak-in and test flight.

Operational check performed satisfactory.

Thomas Glyn Hilton, A&P 3093102