

The Standard AIRCRAFT LOG

ASA-SA-2

Aircraft Record General Information

Bookte

BEECH Model P35 Manufacturer. Registration Number N9774 Y 7159 Serial 4-2-1963 **Date of Manufacture** Engine(s) currently installed: Manufacturer TCM Model I 0-470-N Serial 94508 -2 - NR Manufacturer. Model . Serial Propeller(s) currently installed: Manufacturer. Model **HUB Model** Serial Serial Blade Model Serial Serial Serial Blade Model **Serial** Serial Serial

EAR 0/2- ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR 20 /2 DATE	TACH TIME
Re re sy Pi co	placement flowstem, P/N 92 placem, P/N 92 placem, P/N 92 placement in the placement of the	oum direct pating ins 20-00003- n was don the instathe proce 854-007' ELT from installed	trument par -010 in new ne IAW STO allation mare dures conta 7 Sonalert in baggage a with an exto	235 S/N D-7159 N9774Y ACTT- 5,144.8 hrs and Motorola ADF equipment. Installed owner supplied PMA'd nel. Installed an Aspen EFD1000 PRO, primary flight display (PFD) y panel, and relocated remaining flight instruments in panel. The C 10822SC, see 337 for further details. All ground checks were nuals called out in the 337 documents. This equipment is to be ained in the flight manual supplement and Aspen operation manual. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude alert. In front panel that is interfaced to the PFD for altitude aler	8-18-12 5/4/13	ches nn-
	aniel Blackw	50% or Battery Proper i Presend Battery	more of its for corrosion installation ce of sufficion expiration I	battery useful time remaining. on and expiration date. and operation of controls and crash sensor. ent signal radiated from its antenna. Date May 2017	Re of	April 29, emoved 872536 aniel Bi

Repairs and Alterations ng and Certificate Number of ges for other specific entries.)

ACTT- 5,144.8 hrs

wner supplied PMA'd rimary flight display (PFD) ruments in panel. The II ground checks were is equipment is to be Aspen operation manual. for altitude alert. aggage wall. New 406 pilot control panel in or:

r.

YEAR 20 12 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries
8-18-12	A.		5147.5	or TACH PERFORMED STATIC SYSTEM
	heck ,	su.	FAR S	23.1325. System Leak CHK @ 45
m	N- < 100	OAM	AX. K	TN FOR SERVICE LAW FORD
-11.11.0	CIACO			AFF201345951 2484880 Rm
14113	5/96.2	3		
-		1	Stolle	I over how feet Left Hight mos notos
		9,7	fee ou	
-		phy	10-16	3060-1 5/N 927010 + 10-16300
		5/	1811.	2040. Toss offecheck
				Day.
				AND TO VENER
Ар	ril 29, 2013		Beech P35	S/N D-7159 N9774Y ACTT- 5,196 hrs

CIT2538. Audio panel is interfaced to both nav/com radios and provides 4-place headset connections.

Daniel Blackwell 3289766 A&P

YEAR 20 DATE

rind Alterations ficate Number of r specific entries.)	YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
8/12/	- WW			10.1	March Janes - DANE - All Control of the San San
re on order 0.13 d's AND S/B			The air identifi in accordance Federa Regula airwor #85-2	Repair	or component vas inspected the current administration was found arn to service. Pertinent details of the repair are on file at this agency under work order No. 024701 Date 2 MAY 2013 Signed Law Eleman for Columbia Aircraft Services, Inc Ricomplying PA

DATE	HECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)
6/8/13	5203.47		5203.47	and Clemed Fre) systems. Flight Control System
	/	*		Installed one D9-14-5 FIHER C/W91,007
	-280-7			bolley expires May 2017/AD 76-07-12R1
				15333,47. ADS9-35-32 100 home Fitty
				94-120-04/R2 100 box 1/to 1 inspection
				AD 2007 0808 IMPORTAGE 530347.
				Lordy cone, excled Cocche com the
				demed bely of necept. 109501
				The for inspection @ 5218,65 pc 177

YEAR 20 DATE

1/10/13

1/23/13

	_
airs and Alterations	5
d Certificate Number of	
or other specific entries.)	
date Checkon	1
sht Control Syst	1
7 1 1	

date Checkog

sht Control System

lud, freenessman

k. C/W 9/, 0007

find. EUT

) 76-07-12R1

W, Next due

1-20 home Fifty

308, 47. ND

1 insportion

99/24-10

H dure 53-347

M/25-21-10

NO95-21-10

NO95-21-10

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
100	y 20 V	4	Icetif that this aircreast has been
			losperted in occordance inth annual
(Lezna)		(12 h)	ingportan and uns determined to be
		363.5	alkosty and 15 applied for Return
	1		to Samiles .
	10 1/2		6/8/13. nett 5203. 47 (Clay 11) 239 751
5224	57		Installed New 10-400572
			150 Jun Coppertors IN LOST & Right
			monato oftenion Charles Satisti
			(La 14939932)
40.0	- 0		1111, 125 95004-71
5230	29		Installed Naw 33 - 1300 121)
			Right axhoust To pipe. // / moderarys
			a de la companya del la companya de
		men	TIME SERVICE

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)
8/29/13	5241.6	0		Logard inflingporton par 5/B2360
				MITES 1501/- ~ hoavess,
		NTY AIRPORT , PA 15122 8400 R026K	to version 5.	June 3, 2014 10 I.A.W. SB 1401.
(W/O #5867	Villiam R Derric	ckson		PITTSBURGH AIR RADIO INC. ALLEGHENY COUNTY AIRPORT WEST MIFFLIN, PA 15122 412-469-8400 F.A.A. AZ1R026K
<u> </u>			E 1/	A/C Reg. # 97747 Date:
		8		Jor Af

A/C Reg. # 9775

THE FOLLOWING TEST THE STATIC SYSTEM TEST REQUIRED BY I ALTIMETER WAS TEST

ACTT: 45333

THE FOLLOWING PERFORMED: THE 91.413 LA.W. APPE pairs and Alterations
and Certificate Number of
for other specific entries.)


25/3360

5/024/199045

ANDRIVSUS

58686

AVE BEEN PERFORMED: BY FAR 91.411 LA.W. PUTER WAS TESTED TO



Inspections. Tests. Repairs and Alterations icate Number of Aligned the Aspen EFD-1000 Air Data I.A.W. Aspen Avionics Document #991-00023-001 Revision B. (W/O #58686) specific entries.)

	AECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
704	5222.7		5302.76	Com Insportance ploted this data
7119	7			The second wheekal + land + light o
				Knows & Lpndry Spine System Inspirent and
				Service broke Fland. Instrilled 1/ 19-193
				FINE C/W912078) inspectant of ELT, Bally
				Open miles w/ J. Clothan in put
				15 5m 2 hpage 10 76-57-12/ NOTONOSTANDE
				C/W poster raportorest the pottores 1 dd 18
ā				C/W polone, Agporton of the I wanted
	Name of the last			Chr haster water 1802 Western All
				C/Wholer proportion of up of the contraction has all
				Q 5422 76 pex th) 200 PS 500 Ray
			- D	Lather 650x 86 pg Fisht a fin
				wheel less toppened tepped of
				habit chole pin 334 0131 37.
				Hard gene The working & hard of

YEAR RECORDING TACH TIME

1-29-16, BEEC REMOVED EX INSTALLED P ACCORDANC AIRCRAFT WI RANDALL CH

Repairs and Alterations ng and Certificate Number of ages for other specific entries.)
Lord this data known Flight stem Important
miled 1/ 19-14-5 miled
100 + de 5422.76. 100 + de 5422.76. 100 + de 5422.76.
experien metidia
Replaced hatt
+ ence oftents Lingtilde - 1813/00
DESCRIPTION OF PERSONS ASSESSED.

to bett
on words
mothers!
2 and 15
WILLIAM)
1 1 1 1 1 1

1-29-15, BEECHCRAFT, M/N P35, S/N D-7159, TACH READS 5384.43
REMOVED EXISTING GENERATOR, VOLTAGE REGULATOR AND RELATED COMPONANTS AS NECESSARY.
INSTALLED PLANE POWER ALTERNATOR CONVERSION KIT NUMBER SAL 12-70C, S/N A2-143410, IN
ACCORDANCE WITH STC# SA10682SC. SEE FAA FORM 337 DATED 1-29-15 FOR PERTINANT DETAILS.
AIRCRAFT WEIGHT AND BALANCE AND EQUIPMENT REVISED.

RANDALL CHARLES A&P 2857342 IA

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1/11/13	5	3 N		This Directly the Been Inspected and the Been Lound Safe for The Intended Flight in Accordance with Special Flight Poonts
				Been Lound Safe for The Intended Plight in
<u> </u>	1			Detro 7/17/15
				Coner / Maler
			N.	D-09 563064190
3770		1		
				у.

YEAR 20 DATE RECORDI TACH TIME

MAKE Beechcraft R MODEL P35 S/N D-7159 REG NO 97 WORK ORDI

Airframe

Annual Inspe Revised 35-5 inspection, bi due at 5/30/2 Document I-1 hours, perfor right cowling Exhaust syste system Tailp repaired with removed and (a)(2)(v) and (b), and (c), g clate 6/27/200 around the te Fight, Inc. St Presses Flight 2007-08-08 E territing geer

safetiest. Co Lorenge and of teamings, rec-tides on whee in par Balf doubles patch disable patch completed by

Charles March Control 1	
airs and Alterations d Certificate Number of or other specific entries.)	
and they dod Flight in	١
Aala 1190	١
	1
	۱

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (<i>See</i> back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	--

MAKE: Beechcraft-Raytheon

MODEL: P35 S/N: D-7159 REG. NO: 9774Y WORK ORDER: 15127



Mangon Aircraft, Inc.

501 Sky Ranch Drive Petaluma, CA 94954-3908 Phone: (707) 765-1848 DATE: 12 February, 2016 A/C TSN: 5394.44 TACH: 5394.44

Airframe Entries

Annual Inspection requirements of, FAR 91.409 (a) (1), completed using Beechcraft / Raytheon Service Manual 35-590096B, Reissue, Nov.15, 1960, Revised 35-590096B20, Dtd. Sep. 03, 2001, 100 hour inspection guide. See following corrected discrepancies.... ELT completed with FAR 91.207 (d), inspection, battery expiration, and impact signal testing. See AC43-13-1B, Sec. 12-22, a. thru f. Next test date due at 2/28/17 and battery replacement due at 5/30/2017.... Engine air filter Brackett air filter assembly installed I/A/W continued airworthiness requirements instructions per Brackett Air filter Document I-194.... Battery complied with Manufacture capacitance check for annual certification. Removed battery, cleaned, inspected, charged for two hours, performed capacitance test, recharged to specifications, serviced and installed. Battery passed at 100%. Due again 07/2016.... Dzus fastener for right cowling forward position installed with new locking collar.... Dzus fastener for left cowling forward position reinstalled with new locking collar... Exhaust system oil deflector/heat shield positioned correctly.... Exhaust stack Lt. side cylinders #2, 4 & 6 removed and replaced. Holes drilled for EGT system. Tailpipe connected at ball joint and safetied. Tailpipe secured at firewall with brackets, clamps, hangers and all hardware safetied... Firewall hole repaired with a stainless steel doubler patch installed on cabin side for pilot's side near tail pipe exhaust hanger support brackets.... Vacuum central filter removed and replaced I/A/W Airborne Service Letter 59A.... Airworthiness Directive records for all components brought up to date I/A/W FAR 91.417 (a)(2)(v) and made part of this aircraft's records.... A.D. 76-07-12 R1 Eff. date 08/30/1977. Bendix Ignition Switch, grounding complied with Para. 1., (a), (b), and (c), grounding function was satisfactory. Due again in 100 hrs. at 5494.44 hrs.... A.D. 89-05-02 eff. date 03/24/1989 Raytheon/Beechcraft elevator control fittings inspection complied with by visual inspection. No defects or cracks found. Inspection due again at 5494.44 hrs.... A.D. 94-20-04 R1 eff. date 6/27/2003 Raytheon/Beechcraft V-tail structural inspection complied with para (d)(3),(i),(ii),(iii) of A.D. Visually inspected the fuselage skin and around the bulkhead fuselage stations FS 256.9 and FS 272 for damage. No damage or cracks found.... A.D. 99-24-10 eff. date 01/14/2000 Precise Flight, Inc. Standby vacuum system 12 month inspection of control cable, and 24 month inspection of shuttle valve complied with by inspection I/A/W Procise Flight, Inc. Instructions for Continued Airworthiness, no defects found. Para (b) (1) next due at 2/2016 and Para. (b) (2) next due at 2/2018.... A.D. 2007-08-08 Eff. 05/25/2007. Raytheon/Beechcraft Landing gear uplock roller lubrication complied with by inspection and lubricating left and right main landing gear rollers.... Nose gear door push pull control rod ends adjusted to remove excessive play and re-safetied. Gear swung though 3X times normal operation... Tail pipe hanger firewall brackets Lt. inboard and outboard removed and replaced.... Grommets for tail pipe brackets removed and replaced ... Tail pipe hanger firewall brackets Rt. outboard and inboard removed and riveted in place. Tail pipe and muffler installed, clamps tightened and safetted.... Cowl flap Rt. push pull control lower rod end jam nut re-tightened.... Brake linings and discs Rt. & Lt. main wheels removed and replaced. Linings and discs conditioned IAW Cleveland conditioning procedures.... Right Main tire assembly removed. Disassembled wheel assembly. Inner tube, bearings, races, and wheel halves, cleaned & inspected. Repacked bearings with Aeroshell 22. Replaced tire with new and installed tire and original inner tube on wheel halves, torqued nuts to 150 in. lbs. per manufacturer. Installed wheel assembly on axle, torqued to 40 in. lbs. and safetied. Serviced tire to 10 psi Haffle Lt. front governor access panel attach points repaired with doubler patch and riveted in place.... Baffle Lt. rear cracks and hole covered with about ler patch and riveted in place.... Inter-cylinder baffle for cylinders #2 & 4 removed and replaced.... Baffle Rt. rear support bracket repaired with a deadler patch inter-cylinder baffle for cylinders #1 & 3 removed and replaced.... Alternator belt tensioned to specifications and safetied. All work Transplated VAVV Beechcraft Service Manual and Plane Power installation instructions. Operational check satisfactory.... Nose section pan for wheel well

CONTINUED >


YEAR 20 DATE	Rt. side crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Doubler patch installed on inside of wheel well Nose section pan for wheel well Lt. side crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Doubler patch installed on inside of wheel well Steering idler arm bushing removed and replaced. Hardware removed and replaced to access bushing removal. Safeties installed as needed Nose section center pan for wheel removed and replaced. Hardware removed and replaced to access bushing removal. Safeties installed as needed Nose section center pan for wheel well. Lt. side near Lt. side pan crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Nose wheel steering strut disconnected to provide access well Lt. side near Lt. side pan crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Nose wheel steering strut disconnected to provide access well Lt. side near Lt. side pan crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Nose wheel steering strut disconnected to provide access well Lt. side near Lt. side pan crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Nose wheel steering strut disconnected to provide access well Lt. side near Lt. side pan crack repaired in accordance w/ AC 43.13-1B, Chap. 4, Sec. 4. Nose wheel steering strut disconnected to provide access well Lt. side pan crack repaired man gear Rt. door lightning holes cleaned and installed 2 Ceconite covers Up lock roller on left gear adjusted removed and replaced Inboard main gear Rt. door lightning holes cleaned and installed 2 Ceconite covers Up lock roller on left gear adjusted removed and replaced Inboard main gear Rt. door lightning holes cleaned and installed 2 Ceconite covers Up lock roller on left gear adjusted	ions or of ries.)	YEAR 20 DATE	T/	ECORD ACH ME
	removed and replaced Inboard main gear Rt. door lightning holes cleaned and installed 2 Ceconite covers Up lick roller of the gear adjusted to .015". Gear swung through 3X times normal operation. Operational checked good Air intake plenum removed and replaced. Support box aft of plenum removed to install plenum assembly. Cowl flap push pull control rod removed for access. Plenum installed onto box assembly and plenum plenum removed to installed plenum assembly installed. Flexible duct, used serviceable, installed from plenum to servo. Drain line installed Drilled assembly installed rivets in left and right nose bowl flange Fuel pump fresh air Scat duct relocated to aft engine baffle left. Blast tube hole on tunnel repaired and installed rivets in left and riveted in place Nose section row of damaged rivets removed and replaced Engine compartment flexible fluid carrying with fabricated patch and riveted in place Nose section row of damaged rivets removed and sent for overhaul. Re-installed governor after overhaul replaced. Controls rigged for stop to stop operation and safetied Propeller governor removed and sent for overhaul. Re-installed governor after overhaul by CRS #S5UR963. Control rigged for stop to stop operation and safetied. No leaks noted. Ops check good Ignition switch jumper wire removed from right magneto lug on switch and starter vibrator box removed.		E	Reg #	N9
	AIRCRAFT GROUND OPERATED, ALL SYSTEMS CHECKED NORMAL. I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH THE REQUIRMENTS OF A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. DATE: 12 February, 2016 SIGNED: Michael Tillman, A&P: 2845176 IA Printed by EBis 3 (datcomedia.com		E	Keg #	*d c R R b
			E		8
			E.		SSCA


Description of Inspections, Tests, Repairs and TODAY'S TOTAL RECORDING TEAR Entries must be endorsed with Name, Rating and Certificate Num FLIGHT TIME IN TACH 29 Technician or Repair Facility. (See back pages for other specific entries SERVICE TIME DATE Airframe Log Entry Serial # D-7159 Model P35 Reg # N9774Y MFG Beechcraft Hr Meter 5435 Tach 5435 TT 5435 Researched AD's thru 2017-02 (summary provided) AD89-05-02 complied with by inspection, satisfactory, next due 5535, AD94-20-04R2 complied with by inspection, satisfactory, next due 5535, AD97-14-15 complied with by installation of serviceable handle, due next removal, AD07-08-08 complied with by inspection / lubrication, satisfactory, next due 5535, AD76-07-12 complied with by functional test, satisfactory, next due 5535, AD78-05-06 DNA, AD99-24-10 complied with by inspection, satisfactory, next due 2/2018 Updated POH as needed, removed non-applicable supplements, added missing supplements for Aspen EFD, Garmin 530W, McCauley propeller Removed landing gear motor for 500 hour inspection by Aircraft Systems (WO# 51933) Rigged cowl flaps IAW Beech MM, re-located air oil separator outlet duct to allow closure Trimmed and fitted nose gear doors and RH outer gear door as needed Replaced tail nav bulb GE93 Replaced all brake hoses; 111417-4S0140 hose assy (2ea), 111502-4S0124 hose assy (2ea), 111417-4S0100 hose assy (2ea), 111417-4S0106 hose assy (2ea), bleed system with 5606 fluid IAW Beech MM Inspected ELT IAW FAR 91.207 (d), satisfactory, replaced Lithium batteries, next due 2/2021 Rigged V tail IAW Beech MM, adjusted primary cable length, rigged elevator cable tensions, rigged rudder cable tensions, rigged tab cable tensions (bell-crank to horn), loosened LH lower tab clevis bolt as needed. Test flew aircraft, adjusted tabs for RH adverse yaw IAW Beech MM, re-test flew satisfactory Replaced RH upper wing bolt cover clip 35-105005-4, re-painted both RH covers with wing walk as needed Re-attached fuel strainer door drain tube by welding, GTAW method IAW AC43.13 Replaced inner cabin door handle with owner supplied serviceable spare to comply with AD97-14-15 Tightened all 4 ruddervator hinge bolts as needed Replaced all 3 nose gear retract rod end bearings 2ea ADNE5-323, 1ea HML6-M Replaced 49-00003-001 Aspen battery (next due 2/2020) Tightened up nose wheel steering as needed, added zerk to steering idler, replaced bushing A-779, added idler shims, replaced yoke shim washer, re-installed 2 bolts in correct orientations as needed Re-installed canvas uplock covers on correct sides Landing gear rigging; tightened LH lower drag link bolt, tightened LH rear main gear trunnion bolt, tightened LH inner gear door linkage, tightened RH lower drag link bolt, tightened RH inner gear door linkage, tightened lower & upper nose gear drag link bolts, replaced nut on nose upper drag link with required castellated type, tightened LH nose gear trunnion bolt, adjusted nose gear up force and down deflection, adjusted both dynamic brake switches, adjusted RH outer gear door closure and nose gear door closures, adjusted LH uplock clearance, system inspected IAW Beech MM Re-applied red paint on emergency exit window pins per AD84-09-01 Riemoved all spark plug type CHT probes on GEM and replaced with 5ea serviceable bayonet probes as it should be and 1ea Insight CHT adapter probe PRB-2856 laced battery box drain hose with tygon as needed, capacity tested main ships ed 2mg 4-11541 flag roller bearings on RH flag, 1ea MS25083-2BB6 bonding m and Tea broken actuating bracket screw as needed, tightened screws on LH side


cast struts with 5506 fluid and nitrogen IAW Beech MM, RH would not service, re-

Cleaned extensively in rear fuselage, cleaned under floorboards
 Adjusted engine controls as needed


ed RH strut as needed, replaced seals and scraper 504271







rs and Alterations Certificate Number of 20. other specific entries.) Dai	R RECORDING	TODAY'S	TOTAL TIME IN	Description of Inspections, Te	atting and Certificate Number of bages for other specific entries.)
			Aircraft Mainten		
	%	Work O	rder Number: 30	erial Number: D-7159 166 Date: 02/08/2019	
7	Perform 91.41 Performed te Appendix E a	ete required		91.413 in accordance with paragraph (c) t 43.	
	Transponder Altimeter(s), 91,411 have b		P/N- A' orting equipment d in accordance	T-150 S/N- 43351 t and Static system required by 14CFR Part with 14CFR Part 43 Appendix E.	
	Aspen EFD10 Standby Alti The aircraft 1/A/W currer	meter -	P/N- 22	100-00001-001 S/N- 11535 2-977 S/N- 5057 this WO 3066 were repaired and inspected pproved for return to service.	
	OutRight Av 10078 Airpo Conroe, TX CRS # 80AR	ionics, LLC. rt Road 77303	John		



epairs and Alterations and Certificate Number of	YEAR RECORDING TODAY'S TOTAL Description of Inspections. Tes	sts, Repairs and Alterations
ther specific entries.)	DAI Reg # N9774Y MFG Beechcraft Model P35 Serial # D-7159 Tach 5457 TT 5457 Hr Meter 5457	ng and Certificate Number of ges for other specific entries.)
(a) (b)	Researched AD's thru 2020-10 (summary provided) AD89-05-02 complied with by inspection, satisfactory, next due 5557, AD94-20-04R2 complied with by inspection, satisfactory, next due 5557, AD07-08-08 complied with by inspection / lubrication, satisfactory, next due 5557, AD76-07-12 complied with by functional test, satisfactory, next due 5557, AD99-24-10 complied with by inspection, satisfactory, next due 5/2021, AD19-23-10 complied with by inspection, satisfactory Inspected ELT IAW FAR 91.207 (d), satisfactory, batteries next due 11/2023	
	Landing gear rigging; tightened RH uplock cable tension, tightened LH inner gear door linkage, system inspected IAW Beech MM, satisfactory Capacity tested main ship battery satisfactory Serviced struts with 5606 fluid and nitrogen IAW Beech MM Lubricated airframe with LPS 2 and Aeroshell 5 as required Inspected airframe IAW 100 hour checklist per Beech MM	e
	" Cleaned wing bolts & bath tub fittings and treated with corrosion X as needed Replaced nose tire 500-5 4 ply Michelin Air & 500-5 tube Replaced Aspen battery 409-00003-001, next due 5/2023 Replaced inst air filter D9-14-5	
	I certify this aircraft was inspected in accordance with an Annual inspection and is determined to be in airworthy condition. Beturned to service this date. Signature: Date: 5/12/2020 David Beaver AP 3097750 IA 8320 Thora Lane, #F-1, Spring, TX 77379, 713 851-8960	
)
-		

YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and Co Technician or Repair Facility. (See back pages for or	ertificate Number of
	di vo pi te P	TEC 50 PO rove in both oltage over tch servo a ested good a ITCH SERV isassemble	RPOISES: To directions. H 3 volts. Remond adjusted bafter repair. /O HAS HIGH d and refurbis and alignment.	Executive AutoPilots DEDICATED TO EXCELLENCE 5839 FREEPORT BLVD, SACRAMENTO, CA 95822 SN: D-7159 TACH: 5494.3 DATE: 11/03/2020 ested the system and verified the servo engaged and looked up test set to pitch servo and found the starting oved Servo for testing and repair. Reinstalled repaired oridle cable to 15 inlbs. STEC 50 system ground function H START UP VOLTAGE: Tested and verified discrepancy. Sehed drive motor. Reassembled servo and performed Servo tested good after repair. W.O. 16329	

RECOR TACH TIME

> Cle Chi 32 god

YEAR 20___ DATE

i, Repairs and Alterations ing and Certificate Number of ages for other specific entries.)	YEAR 20 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
			So	noma CENTER	Sonoma Jet Center 6000 Flightline Dr. Santa Rosa, Ca. 95403
nd ting red notion epancy. ed 16329		Cleaned Checke	d and test	ted all bottom is with high te right at 18 dec	774Y; Type: Beechcraft; S/N: D-7159; Tach: 5500.59 In plugs and top right side, run-up performed no change. In plugs and tester all good, checked mag timing found left at agrees, timed both mags to 20 degrees run-up and ops checks Application of the company of

epairs and Alterations	ons, Tests, Re	of Inspection	Descriptio	TOTAL TIME IN	TODAY'S FLIGHT	RECORDING TACH	DATE	
epairs and Alterations and Certificate Number of or other specific entries.)	4346 23 AML STC INSTALLED NEW N 23820961. WEIGHT	2742 CR493Y Hobbs Tach Work Order No.	STAL AVIONICS, 146 Entrance Driving Aunfels, TX 78130 EARLY STATION YOUR SATED REPAIR STATION YOU DANIED AND JANUARY 1, 2020 A	PONDER. SB TRANSPONDE O, REV 14, DATE OF OUT GARMIN OF	N GTX 345 ADS No. 190-00734-1 SON 44336. SEN' SELIGIBLE. identified above pproved for return th manufacturer's Number: 4346			YEAR 20 DATE


	WEIGHT Wation Lionally the		Rating and Cel
			d Certificate Number of or other specific entries.)
111111	11111	000	/ Y 1 1 1 1 1 1 1 1 1
	AVIONICSLLC	N: 9779	
1746EntranceDi NewBraunfels,T		<i>-</i>	
(830)626-3838 FAARepairStation	onYVCR493Y	FAR 91.413	1 1
	tion are filed under Repair Sta	ation Work Order No: 43	16
	Reporting System Tested To:		
No. 1 Transponder: M	Hodel: GTX 345 SINJE	G041426 Tested On: 3-2	8-221
	lodel: NA S/N		LA -
91.413 have been pe to be in Airworthy co	Transponder reporting equiperformed in accordance with ndition and approve these sy	FAR43, Appendix F. I found	ed by FAR these systems
PAACERTIFIED	Signature: () REPAIR STATION W	CR493Y	
		Form# C	
			ian in
CRYSTAL	AVIONICSLLC	N: 977	44
1746EntranceDr. NewBraunfels,Te		Date: 3-28	2021
(830)626-3838 FAA Repair Statio		FAR 91.411	
Details of this inspect	ion are filed under Repair Sta	ation Work Order No: 430	16
System Tested To:		. X 1	09 FT
Pilot's Altimiter: F	P/N: <u>EFD1000</u> S/N 11 P/N: <u>22-979-02</u> S/N 50	535 Tested To: 290	09 FT
#2 Pilot's Altimeter. P	N: 22-979-02 SIN 50	757 Tested To: 20,0	09 FT .
	neter & Altitude reporting equeriormed in accordance with lition and Approve these systems.	AR43, Appendix E. I found	
be in Airworty Condit		75 400V	
be in Airworty Condit	Signature: DREPAIRSTATIONYV	CR493Y Forms	# CA-08 · V2.0 · 1/15/09

ENGINE

YEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Re Entries must be endorsed with Name, Rating Technician or Repair Facility. (See back pages
W	IPAÎRE, IN	C.		
DECEMBE	R 13, 2021		N9774Y	TACH: 550.24
THE AIRI IDENTIFIE CURRENT APPROVE FILE AT T W/O NO. 3	System function checked ABOVE WAS REGULATIONS TO FOR RETURN THIS REPAIR STA	ME, AIRC S REPAIRE OF THE F TO SERVICE TION UNDE	RAFT ENGINE ED AND INSPI FEDERAL AVIA E. PERTINENT ER	I-0 S/N 621. Received from repair and E, PROPELLER, OR APPLIANCE ECTED IN ACCORDANCE WITH TION ADMINISTRATION AND IS DETAILS OF THE REPAIR ARE ON DATE December 13, 2021 PHONE 651.451.1205



Engines Are Our ONLY Busine 21 CREATIVE PL. • MONTROSE, ČO (970) 249-0232 • 800-575-9929 • FAX (97



ENGINE

YEAR 20 _____

RECORDING TACH TIME TODAY'S FLIGHT

TOTAL TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Sierra Hotel Aero, Inc.1690 Aeronca Ln, So St Paul, MN 55075 May 23, 2022 N9774Y S/N D-7159 TACH 5558.03

Replaced PN 409-00003-001 Aspen Avionics Battery, SN 193000068. Lower transponder antenna was loose, installed 2 each AN970 washers and re-installed. Hole found in cowling LH side. Fabricated and installed 2 inch .040 2024T3 doubler and filler plate 2024T3, 032 referencing AC43.13 1b fig 4-16 and painted, repair was determined to be minor. Tightened loose avionics and autopilot switches. Replace Bracket filter element BA7112. Replaced Nose Strut valve core 302DN and Serviced Nose Strut Ref Service Manual 12-20-00. ELT Battery due 11/2023. Replaced C2200-L4 Compass, Airpath SN AS-20393 and compass housing 730A, accomplished Compass Swing.

Complied with all applicable ADs ref AD report this date.

For	N	30	60	E	120	150
Steer	0	31	62	80	118	147
For	S	210	240	W	300	330
Steer	181	211	241	270	301	330

I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

Christopher D. Gardner A&P 3045762 IA



Engines Are Our ONLY Business 21 CREATIVE PL. • MONTROSE, ĆO 81401 (970) 249-0232 • 800-575-9929 • FAX (970) 249-4155

Description of Inspections, Tests. RECORDING TODAY'S TOTAL YEAR Entries must be endorsed with Name, Ratin TACH FLIGHT TIME IN 20 Technician or Repair Facility. (See back page TIME SERVICE DATE MIPAÎRE, INC. JULY 25, 2022 N9774Y TACH: 5567.04 Gained access and cleaned pitch servo motor brush contacts. System function check good. THE AIRCRAFT AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER W/O NO. 79809 DATE July 25, 2022 SIGNED -GREG REIMERS FOR WIPAIRE, INC. CRS RJWR390K PHONE 651.451.1205 IPAIRE, INC. AUGUST 5, 2022 N9774Y TACH: 5568.41 Gained access and checked integrity of altitude hold sensor and fittings. Tightened bridal cable tension to 15 pounds. System function check good. THE AIRCRAFT AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER W/O NO. 79796 DATE August 5, 2022 CRS RJWR390K PHONE 651.451.1205

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				, Inc.1690 Aeronca Ln, So St Paul, MN 55075
		June (08, 2023 NS	9774Y S/N D-7159 TACH 5589.6 TT 5589.6
PN Repl	T-8071-3. Servaced RH and LH	iced Nose I Brake lini	Strut with nit	de. Replaced worn section of engine baffle seal material RH side trogen per BONANZA SERIES MAINTENANCE MANUAL 12-20-00. 4400 Linings (8 each). Replaced RH tire and tube, Tire PN AB3L4 cket filter element BA7112. Checked ELT per 91.207d ELT Battery due 11/2023.
				in accordance with an annual inspection and was determined to be
Chris	topher D. Gardr	ner A&P 30	045762 IA	

N



JUNE 13, 2023

N9774Y

TACH: 5589.68

Replumbed static system to all instruments and encoders.

The aircraft altimeter, static system, transponder, and altitude reporter have been tested to 20,000 feet in accordance with FAR's 91.411, 91.413, & 91.217 and were found to be within the limits of FAR 43, appendices E & F.

Aspen EFD 1000 S/N 11535 Altimeter P/N 22-979-02 S/N 5057 Encoder P/N 0900-4099-01 S/N 01769 Transponder GTX-345 S/N 3EG041426

THE AIRCRAFT AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER

W/O NO. 80236

DATE June 13, 2023

SIGNED

GREG REIMERS FOR WIPAIRE, INC. CRS RJWR390K PI

PHONE 651.451.1205