N729AJ

# ENGINE LOG BOOK



Publication ELB-01

**NOV 2013** 

N729 AJ

Service Information:

Considerable Motors Information Confidence of the most current engine Instructions for Continued Service confidence of the most current engine Instructions for Continued Service confidence on the Confidence of the most current engine Instructions for Continued Service Confidence on the Confidence on the Confidence on the Continued Service Continued Service on the Confidence on the Continued Service Co Consult the Continental Motors web site at confinential reclaims are not or engine instance on the most current engine instructions for Continued Airworthiness useful information for Continued Airworthiness useful and service documents that may be persistent to your engine model.

If Internet access is not available, contact our Customer Service: Department at 1-888-826-5465 Toll free in the United States or 1-251-436-8299 International

# **Engine Returns**

Raturn engines for core credit with this log book to: Continental Motors, Inc. 2039 Broad Street Mobile, AL 36615 USA

Return engines for overhaul with this log book to: Continental Motors, Inc. **Factory Service Center** 8600 County Road 32 Fairhope, Alabama 36532 USA

> USE ONLY FUEL SPECIFIED IN OPERATOR'S MANUAL OR TYPE CERTICATE DATA SHEET **USE OF AUTOMOTIVE FUEL IS PROHIBITED**



# Continental Motors


FAA PRODUCTION CERTIFICATE NO. 508

log book Printed:03/31/2015: prior to the informa-

Test Daten3/27/2015

This engine model 10550N68B, serial number 1011979 was manufactured by Continental Motors, Inc. in accordance with approved design data and the applicable requirements of 14 CFR, Part 21. The approved design data for this engine incorporates all changes required by applicable FAA Airworthiness Directives and Continental Motors Service

Form 6012-03 (Roy Sept 2014) CONTINENTAL MOTORS, INC.



This document verifies that the engine model listed below has satisfactorily completed all testing listed below in accordance with CM standard engine testing specifications as approved by the FAA.

Engine Model

10550 N 68 B

Engine Serial Number

1011979

**Testing Completed** 

Standard Acceptance Test:

Date of Completion

MAR 2 6 2015 Test Operator



unt of "troubleshooting" costs allowed will presentative. The amount of repair and rs or replacements under paragraph 1(a)

te need for such repairs or replacements. he latest revision of the warranty labor identifying the need for such repairs or

tified in the course of overhaul, routine

No "troubleshooting" cost allowance will fifteen percent (15%) of the labor costs



Form No 98344

Continental Motors, Inc.

nufactured or supplied by CMI or parts if have been used and nothing contained to or part not manufactured or supplied by

inty will not extend the period of warranty

engine or part with either a new or rebuilt

repair or replacement of any engine, active in material or workmanship under at must be shipped prepaid to the repair nt for engines will be the actual surface described on the bill of lading as follows: shipment of the component or part or the Transportation cost reimbursement for

e thirty-six (36) month period described rkmanship. The warranty activation date warranty and which upon examreplacement of the starter or alternators. e date, whichever occurs first. After the omplete and finished unit and included in coverage as may be provided by their expiration of the initial twenty-four (24)



9 Record removal and ess Directives,

September 17, 2015

Engine

Engine

Flight Hobbs 20.6

preformed 25 hour inspection IAW circus 25 hour inspection checklist

Preformed compression 1;71 2;76 3;72 4;64 5;70 6;68. Drained oil and removed filter, took and sent black stone oil sample. Cut open filter and no defects noted at this time. Serviced engine with 6 0ts of Aeroshell 1000 oil and one chall-108-1 filter. Removed and inspected gascolator fuel bowl and no defects noted at this time. Cleaned engine and ran aircraft, all leak and operation checks were satisfactory

Brendan Carcone

3745796 A&P

CHEMP MODEL TO TOO IN THOMAS AND TOTAL TO THOSE NO NOTICE LANGUAGE WORK CHOOSE LATER NO JOHN



Cirrus Design Factory Service Center

Repair Station Fax. HOSPOSOV MRT August Staat Childle, MR 550111 Phone 216-708-3049

Engine Entries

(14) Changed engine oil and Star, Temporal AA48100-2, PA 5087-501. Serviced origins with 5 quarts of ACROSHELL 100 engine oil. Parliamed particulate impedition on old Star, should satisfactory. Performed operational and leaf offects. Cyl's and leaf-other good. All work was accomplished LAW. Circle SR22 AA4M, 12-10.

DATE 11/9/2015

BONED

Printed by Ellin 3 (detowned a rom)

Aviation Center

May 20, 2016

N729AJ

52.1 Hobbs

Performed Cylinder compression test #1: 70, #2: 71, #4: 68, #5: 69, #6: 72.

Oil and filter changed. Serviced with 7 quarts Philips 20-50w and CH48108-1 oil filter. Took and sent Blackstone oil earniple. Added cam guard oil additive.

I certify that that timpine has been impected in accordance with an 100 Hour Inspection and FAR 43. Appendix "D" was found to be in an airworthy condition.

Byendan J. Cercone 6.

3745798 A&P

Avation Center

December 2, 2016

N729AJ

82.3 Flight Hobbs

Performed 50 hour inspection IAW cirrus 50 hour inspection checklat.

Drained oil and removed filter, took blackstone oil sample. Serviced engine with 7 Quarts of Phillips 20w-50 oil with Camguard oil additive and one AA48108-2 filter. Cleaned engine and ran aircraft, all leak and oil with Camguard oil additive and one AA48108-2 filter. Cleaned engine and ran aircraft, all leak and Mark Roisen Mark operation checks are satisfactory at this time

Avation Conter -

MAY 10, 2017

N729AJ

89.1 Flight Hobbs

Compression test: #1: 71, #2: 72, #3: 72, #4: 68, #5: 71, #6: 72

Oil and filter changed. Oil sample taken. Serviced engine with 7 quarts of Aeroshell 20W-50W and CH48108-1 oil filter. Added Camquard oil additive. Cleaned and gaped spark plugs. Engine washed, run-up

leak check OK. t certify that this Engine has been inspected in accordance with a 100 hour inspection and FAR Part 43.

Appendix "D" was determined to be in airworthy condition.

Trever Moehl 3554241 A&P - HE M

1 3

Time Since Last Engine Service and Maintenance Record **Total Time** Overhaul Daf and Aviation Center - William tives. 108.2 Flight Hobbs Carried fd N729AJ February 27, 2018 041 145.4 Hobbs Engine Drained oil and removed filter, took Blackstone oil sample. Serviced engine with 7 Quarts of Phillips 20w-50 oil with Camquard oil additive and one CH48108-1 filter. Cleaned engine and ran aircraft, all leak and Carried operation checks are satisfactory at this time. 3554241 A&P Aviation Conter Town August 23, 2018 121.9 Flight Hobbs N729AJ 163.2 Hobbs Engine Compression test: #1: 69, #2: 71, #3:68, #4:60, #5:70, #6: 70 Oil and filter changed. Oil sample taken. Serviced engine with 7 quarts of Aeroshell 20W-50W and CH48108-1 oil filter. Added Camquard oil additive. Cleaned and gaped spark plugs. CAW S82x-79-08 (Remote oil Pressure Sensor Installation). Installed Kit #70605-001 per SB. No further Engine washed, run-up leak check OK.
I wertify that this Engine has been inspected in accordance with a 100 hour inspection and FAR Part 43.
Appendix "D" was determined to be in elimority condition.

Mark Roisen

Mark Roisen Mark Roisen Mari C Rovi Avation Center Drained oil and removed filter. Serviced engine with (7) gts. Phillips 20W50 cil., Camguard oil additive and replaced oil filter (CH48108-2). Washed engine, ran up aircraft and leak checked, all ok at this time.

Mark C Roiseen

S06742944 A&P Mar In C Roise() 14 May 2019 N729AJ Aviation Center Taxan 27 September 2019 N729AJ 152.2 Fit. Hobbs Compression test: 1[74], 2[74], 3[75], 4[05], 5[75], 5[72]. Oil and filter changed. Serviced engine with 7 cls. Aeroshell snatyris. Cleaned and gapped spark plags; repeated liver coal aluminum tape and coal challe strips as needed. Was 1 careful filter strongers and less choosed cis, all operational checks in spec.

1 careful filter this snatyrise has been inspected in accombined with a 160 fir, inspection and EAP Part 43. Annual was determined to be in sinventity condition. Mark C Roisen Male C 372

D ..... Aviation Center\_ Date 27 April 2020 N729AJ 172.7 Fit. Hobbs
Engline 247.2 Hobbs
Engline 247.2 Hobbs
Drained oil and removed filter. Serviced engine with (7) qts. Philips 20W50 oil. Computed oil additive and replaced oil filter (C1468108-2). Washed engine, ran up aircraft and leak checked, all oil at this time.

Mark C Roisen
506742944 A&P // W1 C // CPCC 04/27/200 Carried forward -·········· > Aviation Center - ---13 October 2020 NT2SAJ 217.5 Fit. Hobbs

Compression test: 1(74), 2(72), 1(72), 4(62), 5(74), 5(72). Ot and fifter changed. Serviced engine with 7 ds. Aeroshell analysis. Cleaned and gapped speck plags, repeired lower over sharinum tope and over clude siting as readed. Soft AD 2020-16-11, cylinder impection and tile casting marks as required, replaced points in right mag and nationed both mags to repodifications. Washell engine and load check did siting as readed. I conflict that this engine has been inspected in accordance with a 100 hr. Inspection and FAR Part 43 App. "D" and was determined to be in airworthy condition. Mark C Roisen Marc Roise \*\*\* \*\*\*\*\* Aviation Center - Torre 3 16 December 2020 N729AJ 227,9 Fit, Hobbs Replaced left and right magnetos with new, PN 10-500556-1, SN's I-11445 and I-11437. All ops checks good. Mark C Robsen Marc Roin Aviation Center - Taxan 10 March 2021
Engine 320.4 Hobbs
Desired oil and removed filter. Serviced engine with (7) gts. Phillips 20W50 oil, Camguard oil additive and replaced oil filter (CH48108-2). Washed engine, ran up aircraft and leak checked, all oik at this time.

March 2021

March 2021

Engine 320.4 Hobbs

Desired oil and removed filter. Serviced engine with (7) gts. Phillips 20W50 oil, Camguard oil additive and replaced oil filter (CH48108-2). Washed engine, ran up aircraft and leak checked, all oik at this time.

March 2021 Date: 9/20/2021; Aircraft: N729AJ; Type: CRRIUS SR22; SN: 4208; Holbid: 279.0; Total Time: 279.0; Engine - Type: 10-550 - N65B, SN: 1011979; Time: 279.0; SMCH: 279.0
""Engine Work"" ISO-500 - NSSE, DAY: 1011979, Time: 279.0, SMCH 279.0

"Engine Work"

Completed an Annual inspection, in accordance with FAR 43, Appendix D.

Changed oil and filter pin AAS108-2, took sample, out filter, no metal noted, serviced engine with #fots, 204/50

Phillips and 1 pint Campaurd PhN K-245-100ALS. Compression test as follows: #1/17 /80, #2/65 /80, 80) 67/80, 84) 50/80, #5/7080, Missaer prifice 43/80. Cleaned, papped and tested spark plugs. Checked mag to engine timing. Checked engine control travels and lutricated. Ground run for ops and leak on normal. All work performed in accordance with appropriate control technical data. I certify that this engine has been inspected in accordance with an Annual inspection and was determined to be in armorthy consister.
Timothy Woods furthy fellowed Wisconsin Aviation - Madison ☐ Wisconsin Aviation - Watertown 3606 Corben Court 1741 River Drive Madison, WI 53704 Watertown, WI 53094 608-268-5003 920-261-4567 3

(4)

Э

mass R	Total Time Hours Min		Overhaul		Engine Service and Maintenance Record			
Date					Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins			
Carried forward	1	-	690	100				
	(	9	8	28000 Anye	H. Maintenance & Reper H. Rd. JA 17 Pures Gunds, Ft, 30982 5-9025 - Fax: 641-475-6734 - sautherinns com			
	CW 05-1 M.00 20WANC FUE TIM PLU OPE EXON RIG COR SRIZ FLO INT: COX SPO AD2 SAT THE CIR ARR REC THE ZU	THE 100/20 AND C 44/80. C 44/80. C 44/80. C 44/80. C 45/50 AND C 5A/FETY L INJECTION CLE G URHS. RATION. INTERWED C 5A/FETY C	INSPEC AT M-O. ( PIANGED FILTER A NEW FILT ORS. SER AN, GAP, 2E. LUBR SER 1508 BAFFLE I INSTALL REPLACE DER ASSI VE FAILUR DER ASSI VE FAILUR DER ASSI VE FAILUR DER ASSI VE COMOUTING COMOUTING NEW AND INCOME.	TION TAY COMPRESS OIL AND AA9108-2 FER. ADD VICE GAS AND ROT ICATE NE ENGINE I 0-001. RE 5471-007 OF REMO E #4 EGT Y FOUND I ESS NA SI FAINING 8 -SEGHEN C NOT THE EN INSPEE H 05-20, 100N. MAII S APPROVA	22 ASN 4208 HM 571.9 FLT 444.1 ENG 444.5  V CIRRUS SR22 AMM INSPECTION CHECKLIST CH SIONS OVER 80: 1)70 2)64 3)73 4)73 5)68 6)68.  FILTER, SERVICED WITH BQTS PHILLIPS XC  LOUT AND INSPECT FILTER, INSTALL, TORIQUE, IPL CAMGUARD, AVLAB SAMPLE TAKEN, SERVICE KOLATOR, INSPECT MAGNETO TO ENGINE ATE SPARK PLUGS, REPLACE 1ee FAILED SPARK KYLIRE CABLE AND QUADRANT CAM FOR PRIOPER MANIFOLD DRAIN 25939-002. REPLACE #1 FPLACE #4 EXHAUST RISER 15073-001. REPLACE  AREPLACE A/C DRIVE GARLIOC SEAL 25102. TE-MOUNT OIL PRESSURE SENSOR IAW SENSOR 24585-001. AD2020-16-11 CROSS POW 10-13-2020 217.5 FLT HM. AD2023-02-12 ISPECT PARTS NOT INSTALLED, AD2023-09-09 T V-BAND CLAMPS NA BY INSTALLATION. STALLED, OPERATIONAL AND LEAK CHECK  COTED IAW AN ANNUAL INSPECTION AS PER CAT M-O, AND WAS FOUND TO BE IN AN VIENANCE CARRIED OUT IAW CURRENT FAA HOD FOR RETURN TO SERVICE WITH RESPECT TO DRIROUGH BI-WEEKLY 2023-20.  TTE 444.1 FLT			
				-				
The state of								
	13/							
9600 11 11 15	1000	100						
	1000							
10-10-10-10-10-10-10-10-10-10-10-10-10-1					A CONTRACTOR OF THE PARTY OF TH			
NAME OF THE OWNER,		10000	1 10 2751	N MEET	<b>新港市市市市市市市市市市市市市市市市市市市市市市市市市市市市市市市</b>			
1		1	1	0000	THE RESERVE THE PROPERTY OF THE PARTY OF THE			
	10000	1000	1000	933				
		0 1000	100	1000	THE RESERVE THE PROPERTY OF THE PARTY OF THE			
No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other party of the Concession, Name of				NO DECEMBER	THE RESIDENCE OF THE PARTY OF T			
The state of the s				THE RES	TO A THE RESIDENCE OF THE PARTY			

## Elite Aircraft Services

Date

Carried forward -

501 W. Hangar St. Slove Falls 50

605-809-5304

DATE I	MARK SECTION	TACH/HORSE	BHON/CHOUS	RESERVACE	SERVI WINNESS
12/15/801	Cross 9603	Hight; 305.3 Hotel; 400		N72544	400
Engine Model TOW ID-100-III	Engine 5/4 3003879				

- Displace oil. Spreyued, cut, and impected of filter for contamination. Note found. Installed move filter gift-CHRISOR-1 and implemented of with 7-quarts of Pfillips XC 20WSG.

Quality Aviation, Inc. 5-801 W. Trunk Hwy 21 Faribank, MN 53021 1-866-865-1777

N729AJ Engine Log book entry. Continental Motors IO-550-N S/N 1011979 Date: 09/21/2022 Hobbs: 459.0 Engine TT: 356.0

Complied with a Annual inspection in accordance with 14 CFR 43, Appendix D using the Cirrus Design SR-22 service marrial as a guide.

- Compression check #1 71.00 #2 66/00 #3 70/00 #4 Replaced/00 #5 72/00 #6 62/00.
   The #4 cylinder was removed and repaired by Horizon Aircraft Engine Services (CRS# YZ8R163C), reference their W/O 34891 for repair details. The repaired cylinder was installed per Continental Motors Standard Practice maintenance manual, M-0 10-6.1. The engine was ground ran, functional and leak checked and was found to be
- \* The left muffler was replaced with a new FAA/PMA muffler P/N A 14836-001 from Aeruspace Welding
- Complied with Continental Motors service bulletin SID97-3G (effective 10/21/2015) fuel system functional test and impection. The fael pressure checked per Continernal Motors Standard Practice Maintenance manual Table 6-4. I centify that this aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Gorald L. Secres ARP IA 3490061 Fell Hung





N729AJ ENGINE LOG DATE (2-17-23 ENG 399.6 PLT 366.2 HOBBS \$14.5

DRAINED OIL, R/R OIL FILTER AMBIOS-2, SAFTIED. INSPECTED OLD FILTER. DOKAMED OIL, NO RO FOLKEL RAMBIOS-2, SWITTEN INSPECTIO CLD RELIGIOREM POR METHAL, NORE FOLKED. SERVICED ENGINE WITH PRILLIPS X/C 20W/SO. COLLECTED AVIAB OIL SAMPLE. REMOVED STARTER C24ST) AND INSTALLED NEW STARTER R.13464 S. PI. H-WOS2672. LIPDATED WEIGHT AND BALANCE/CQUIPMENT LIST. OPERATIONAL AND LEAK CHECK SATISFACTORY, MAINTENANCE CARRIED OUT LIW CURRENT FAA REQUILATIONS AND IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK

30HN MCCORHACK AE 47580823

mass R	Total Time Hours Min		Overhaul		Engine Service and Maintenance Record			
Date					Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins			
Carried forward	1	-	690	100				
	(	9	8	28000 Anye	H. Maintenance & Reper H. Rd. JA 17 Pures Gunds, Ft, 30982 5-9025 - Fax: 641-475-6734 - sautherinns com			
	CW 05-1 M.00 20WANC FUE TIM PLU OPE EXON RIG COR SRIZ FLO INT: COX SPO AD2 SAT THE CIR ARR REC THE ZU	THE 100/20 AND C 44/80. C 44/80. C 44/80. C 44/80. C 45/50 AND C 5A/FETY L INJECTION CLE G URHS. RATION. INTERWED C 5A/FETY C	INSPEC AT M-O. ( PIANGED FILTER A NEW FILT ORS. SER AN, GAP, 2E. LUBR SER 1508 BAFFLE I INSTALL REPLACE DER ASSI VE FAILUR DER ASSI VE FAILUR DER ASSI VE FAILUR DER ASSI VE COMOUTING COMOUTING NEW AND INCOME.	TION TAY COMPRESS OIL AND AA9108-2 FER. ADD VICE GAS AND ROT ICATE NE ENGINE I 0-001. RE 5471-007 OF REMO E #4 EGT Y FOUND I ESS NA SI FAINING 8 -SEGHEN C NOT THE EN INSPEE H 05-20, 100N. MAII S APPROVA	22 ASN 4208 HM 571.9 FLT 444.1 ENG 444.5  V CIRRUS SR22 AMM INSPECTION CHECKLIST CH SIONS OVER 80: 1)70 2)64 3)73 4)73 5)68 6)68.  FILTER, SERVICED WITH BQTS PHILLIPS XC  LOUT AND INSPECT FILTER, INSTALL, TORIQUE, IPL CAMGUARD, AVLAB SAMPLE TAKEN, SERVICE KOLATOR, INSPECT MAGNETO TO ENGINE ATE SPARK PLUGS, REPLACE 1ee FAILED SPARK KYLIRE CABLE AND QUADRANT CAM FOR PRIOPER MANIFOLD DRAIN 25939-002. REPLACE #1 FPLACE #4 EXHAUST RISER 15073-001. REPLACE  AREPLACE A/C DRIVE GARLIOC SEAL 25102. TE-MOUNT OIL PRESSURE SENSOR IAW SENSOR 24585-001. AD2020-16-11 CROSS POW 10-13-2020 217.5 FLT HM. AD2023-02-12 ISPECT PARTS NOT INSTALLED, AD2023-09-09 T V-BAND CLAMPS NA BY INSTALLATION. STALLED, OPERATIONAL AND LEAK CHECK  COTED IAW AN ANNUAL INSPECTION AS PER CAT M-O, AND WAS FOUND TO BE IN AN VIENANCE CARRIED OUT IAW CURRENT FAA HOD FOR RETURN TO SERVICE WITH RESPECT TO DRIROUGH BI-WEEKLY 2023-20.  TTE 444.1 FLT			
				-				
The state of								
	13/							
9600 11 11 15	1000	100						
	1000							
10-10-10-10-10-10-10-10-10-10-10-10-10-1					A CONTRACTOR OF THE PARTY OF TH			
NAME OF THE OWNER,		10000	1 10 2751	N MEET	<b>新港市市市市市市市市市市市市市市市市市市市市市市市市市市市市市市市</b>			
1		1	1	0000	THE RESERVE THE PROPERTY OF THE PARTY OF THE			
	10000	1000	1000	933				
		0 1000	100	1000	THE RESERVE THE PROPERTY OF THE PARTY OF THE			
No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other party of the Concession, Name of				NO DECEMBER	THE RESIDENCE OF THE PARTY OF T			
The state of the s				THE RES	TO A THE RESIDENCE OF THE PARTY			

## Elite Aircraft Services

Date

Carried forward -

501 W. Hangar St. Slove Falls 50

605-809-5304

DATE I	MARK SECTION	TACH/HORSE	BHON/CHOUS	RESERVACE	SERVI WINNESS
12/15/801	Cross 9603	Hight; 305.3 Hotel; 400		N72544	400
Engine Model TOW ID-100-III	Engine 5/4 3003879				

- Displace oil. Spreyued, cut, and impected of filter for contamination. Note found. Installed move filter gift-CHRISOR-1 and implemented of with 7-quarts of Pfillips XC 20WSG.

Quality Aviation, Inc. 5-801 W. Trunk Hwy 21 Faribank, MN 53021 1-866-865-1777

N729AJ Engine Log book entry. Continental Motors IO-550-N S/N 1011979 Date: 09/21/2022 Hobbs: 459.0 Engine TT: 356.0

Complied with a Annual inspection in accordance with 14 CFR 43, Appendix D using the Cirrus Design SR-22 service marrial as a guide.

- Compression check #1 71.00 #2 66/00 #3 70/00 #4 Replaced/00 #5 72/00 #6 62/00.
   The #4 cylinder was removed and repaired by Horizon Aircraft Engine Services (CRS# YZ8R163C), reference their W/O 34891 for repair details. The repaired cylinder was installed per Continental Motors Standard Practice maintenance manual, M-0 10-6.1. The engine was ground ran, functional and leak checked and was found to be
- \* The left muffler was replaced with a new FAA/PMA muffler P/N A 14836-001 from Aeruspace Welding
- Complied with Continental Motors service bulletin SID97-3G (effective 10/21/2015) fuel system functional test and impection. The fael pressure checked per Continernal Motors Standard Practice Maintenance manual Table 6-4. I centify that this aircraft has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Gorald L. Secres ARP IA 3490061 Fell Hung





N729AJ ENGINE LOG DATE (2-17-23 ENG 399.6 PLT 366.2 HOBBS \$14.5

DRAINED OIL, R/R OIL FILTER AMBIOS-2, SAFTIED. INSPECTED OLD FILTER. DOKAMED OIL, NO RO FOLKEL RAMBIOS-2, SWITTEN INSPECTIO CLD RELIGIOREM POR METHAL, NORE FOLKED. SERVICED ENGINE WITH PRILLIPS X/C 20W/SO. COLLECTED AVIAB OIL SAMPLE. REMOVED STARTER C24ST) AND INSTALLED NEW STARTER R.13464 S. PI. H-WOS2672. LIPDATED WEIGHT AND BALANCE/CQUIPMENT LIST. OPERATIONAL AND LEAK CHECK SATISFACTORY, MAINTENANCE CARRIED OUT LIW CURRENT FAA REQUILATIONS AND IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK

30HN MCCORHACK AE 47580823