ALTIMETER & STATIC SYSTEM CHECKS F.A.R. 91.411

74						_ RECHECK APP					
TE	MANUFACTURER	MODEL	SERIAL NO.	LOCATION	MAX. ALT.	REQUIRED	AGENCY	CERT			
	MAKE: Cirrus MODEL: SR22T S/N: 1168 REG. NO: N238MP WORK ORDER: 200875 MAKE: Cirrus All Clear Star Aviation Clear Star Aviation All Clear Star Aviat										
	Avianias Entries	Phone: 972-	-267-2376								
	Avionics Entries										
	The test and inspections required by 14 CFR 91.411, 91.217 have been performed and the equipment listed below has been found to meet the requirements of 14 CFR 43, Appendix E.										
	Garmin ADC #1 P/N GI	Garmin ADC #1 P/N GDC74A S/N 20620909. Certified to 25K feet.									
	Garmin ADC #2 P/N GDC74A S/N 20620955. Certified to 25K feet.										
	Standby ALT. P/N MD302 S/N G15-10909 Certified to 25K feet.										
	The tests and inspections required by 14 CFR 91.413 have been performed and the equipment listed below has been found to meet the requirements of 14 CFR 43, Appendix F. Transponder Garmin P/N GTX 33ES S/N 89130145Certified to 25K feet.										
	This aircraft/component is d Station 5CSR009B.		e in airworthy condition	is ok for return to service	e. Pertinent details of		s Certified Repair				
	DATE: 12122017		aker, Doug			Printed by EBis 3					
		Certifi	ied Repair Statio Lyb.	5CSR009B			(
Part I				· And the	tus						
					127						
-							1				
							1	-			

RADIO & ELECTRONIC CHECKS

RADIO & ELECTRONIC CHECKS

	ME I	EQUIPMENT CHECKED	TYPE OF CHECK		ERROR OR RESULTS	NEXT CI DU		CHECKED E SIGNATURE — C	
altimeter at th	2160 Colu CRS cale errors determent time this altim	Ohio State University O.W. Case Rd. Hgr. Jumbus, Ohio 43235 ## IKBR028F mined by the use of the second of the seco	a master		altimeter at t	216 Colorador CRS cale errors detended time this altir	Ohio State University O.W. Case Rd. Hgr umbus, Ohio 43235 # IKBR028F mined by the use of neter is calibrated for cale corrections for	f a master	
cale Corrections f	or: N238MP Indicator	Altimeter Serial: 2		-	Scale Corrections	for: N238MP	Altimeter Serial: 0	G15-10909 MD SB	_
Test Points	Error	Test Points	Indicator Error	Section 1	Test Points	Indicator Error	Test Points	Indicator Error	
-1000	-5	14,000	-25	ASS	-1000	0	14,000	-10	
0	-5	16,000	-25		0	0	16,000	-10	_
500	-5	18,000	-25	AND Y	500	0	18,000	-15	
1,000	-10	20,000	-25		1,000	0	20,000	-20	_
1,500	-10	22,000	-30		1,500	0	22,000	-25	
2,000	-10	25,000	-30		2,000	-5	25,000	-35	_
3,000	-10	30,000	XXXX	7	3,000	-5	30,000	xxxx	
4,000	-10	35,000	XXXX	Control of the Contro	4,000	0	35,000	xxxx	_
6,000	-15	40,000	XXXX		6,000	0	40,000	XXXX	
8,000	-20	45,000	XXXX	and the same of th	8,000	0	45,000	XXXX	_
10,000	-20	50,000	XXXX		10,000	-5	50,000	XXXX	
12,000	-20	and the second second second	1	7	12,000	-10	35,000		_
01/31/2020	Technician: Cl	parles Jenkins		7					
01/31/2020	Totaliolat. Ci				Date: 01/31/2020	Technician:	Charles Jenkins		
43									

RADIO & ELECTRONIC CHECKS

TE	TOTAL TIME	EQUIP	MENT KED	TYPE OF CHECK			ERROR OR RESULTS	NE	CT CHECK DUE	C SIGNAT	HECKED BY: TURE — CERT. NO.
	2460 (Leban FAA F #8WC		Rd. 15036	orrection	942 V258MP			ree Rd. nio 45036 Sta. C meter Co	Date 8-2 W.O. No 52 Tech A/C Reg. No A Orrection	238MP Card	n 14 —
	A		Error	Alt	Error	11.	Alt	Error	Alt	Error	with -
	-10	00	-20	10,000	-10		-1000	-70	10,000	0	955 -
	0) -	-20	12,000	-40		0	-20	12,000	0	
	50		0	14,000	-20		500	+20	14,000	-60	
	1,0	00 _	-20	16,000	0		1,000	0	16,000	-40	_
	1,5	00 -	-20	18,000	-30		1,500	-/0	18,000	+30	-
	2,0		20	20,000	-10		2,000	0	20,000	440	-
	3,0	00	6	22,000	-20		3,000	410	22,000	140	-
	4,0	00 -	126	25,000	0	-	4,000	+30	25,000	+60	
- 4	6,0	00	-20	30,000	7		6,000	0	30,000	フ	
	8.0	00	0	35,000	1		8,000	+10	35,000	1] [

F.A.R. 43.9

N_	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK PERFORMED OR APPROVED DATA USED	AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SERVICE
	wo: WO_1732	Flightlogix · 4510 Airport Road · Cincinnati, OH 45226 ·	Airframe page 1 of 1
	N238MP Flight: 438.7	Cirrus, S/N: 1168 ACTT: 438.7	April 28, 2023
	 Remounted bat Installed new R 105 - BERINGE Installed new L 105 - BERINGE Installed new lo 32-42 Installed - BACK STOP, I Performed a ha Installed new no - PANT BRACK 	udder bottom IAW Cirrus SR22T AMM 55-40 Inst	BM-AIK1 Installation Instructions. 1. Installed (1 PACK) P/N 31392- 1. Installed (1 PACK) P/N 31392- 2 missing IAW Cirrus SR22T AMM (E ASSY, Installed P/N 31392-109) 50-03. No defects noted. 22-20. Installed (2) P/N 11799-004
	9. Installed new L 18138-003 - AC	H wheel pant access panel IAW Cirrus SR22T AN CESS PANEL, MHG LH ce run up and leak checks good.	MM 32-10 Installed (1 EACH) P/N
fo		ork performed, this airframe is approved for return Flightlogix under work order: WO_1732.	n to service. Details of work per-

Scanned with CamScanner

INSPECTION RECORD F.A.R. 43.11-91.409

DATE	AIRCRAFT TIME IN SERVICE	SIGNATURE — CE	KIND OF INSPECTION-STA RT. NO. OF PERSON APPROV
	DEDOOT		
	REPORT of 400 MHz ELT testin		
Report date: 1/27/2020		Date of testing: 1/1/020u	
	ELT IDENTIFICATION		
ELT Wodel	Nux.	a, has a remain a management of the second	
ELT Serial '40'	251-08533		
ER lessos date:	1/28/2015		
The second secon	Full Message: FFFEDOD6E324	CCA064Fu893362CF000000u0	
	Massage Format: Long		
and the second second second second second	User protocols or User-location	protocols	A STATE OF
	Beacon Identifier: ADC64959-4	OCIJED1	
EL I MESSAGE CONTE	NTS Country code. United States of	America (366)	
227 ///2007/02 00/1/1	Aircraft Registration Marking: N	(Z36MP	
	121.5kt-tz radio-lucating transf	ninor: Yes	
	Eracided postion data is provid	led by external source	@ 45 ME
	Latriude North 120 degraes J	minutes	
	't ongstude' East O angrees O m	unules	
	GENERAL ELT PARAMET	ERS	
Frequency of 406MHz channel,	KIN 406/39 89	Place and the second se	
Prwei bvel in aliamtiz chaniei			
and the second s	ADDITIONAL ELT PARAME	TUDO	N ASSESSED
a distribution of the second	4.19.7	The same control of the sa	
Total transmission time, ms Unmindulated carrier time, ins	439.7	All the same of the same strength backet by	
Phase(+), degrees:	21	And the state of t	
Phane(-), de grues	6	and the second s	
and the second s			ENGINES .
Such to the return of the second	VISUAL ELT PARAMETE	RS	
4US Nin Led		Yes	
State of Marang		Good	
Date of next testing, 1/2021	Ballufies fe	placement dute: 125021	/
fracts are carried out by curific		University Airport Repair Station #IABR028F, Gabe Rd. Columbus, Ohio 432:55	
NOTES -	and appropriate and the second and the	the first of the first of the second of the	
	Radioenginger (Signature, Postion, Hant		

INSPECTION RECO F.A.R. 43.11-91.4

DATE	AIRCRAFT TIME IN SERVICE	SIGNATURE	KIND OF INSP — CERT. NO. OF PERS
		REPORT of 406 MHz ELT testing	
	Report date: 3/2/2021	Date of testing: 03/02/2021	A section of the sect
	Ĩ.	ELT IDENTIFICATION	
-	ELT Model: 1 45554 CON FROM FLAN AND THE PARK	A3-08-2749-1	
	ELT Serial No.	251-08533	
	Elt Issue date	9/3/2015	
		Full Message: FFFED056E620729800130D08A1D0 Message Format Short	To the second
and the state of t	Continue to respect and to a respect to the continue of the co	User protocols or User-location protocols	Date: 10
	ELT MESSAGE CONTENTS	Beacon Identifier: ADCC40E53000261	
		Country code: United States of America (396)	Aircraft
**	and the state of the property of the state o	Beacon Serial Number: 14663 Cospas Sarsat Certificate: 152	Tach Ti
		121.5MHz radio-locating transmitter. Yes	1 ach 1)
			Aircr
The reserve to the	The second secon	ENERAL ELT PARAMETERS	- And the state of
	Frequency of 406MHz channel, kHz	406036.44	1.
	Power level in 406MHz channel, dBm	26.8	
	ADO	DITIONAL ELT PARAMETERS	2.
	Total transmission time, ms.	443 1	
-	Unmodulated carrier time, ms:	443.1	
	Phase(+), degrees Phase(-), degrees	45	
- Commence	Secure of the second recommendation of the second s	VISUAL ELT PARAMETERS	3.
	406 MHz Led	Yes	
	State of Marking	Good	
	Date of next testing: 3/31/2022		A CONTRACTOR OF THE PARTY OF TH
	Tests are carried out by certified company	The Ohio State University Airport, 2160 West Case Rd Columbus, Ohio 43235 Tel/Fax: 614-292-5033	
	NOTES	The second secon	The airc
		11112	in acco
- I wante	Radioenginee	(Signature Fosten, Name)	airworth
		(Sanot	this age
A STATE OF THE STATE OF		the control of the company of the region of the control of the con	Signatu
			3.8
		Commence of the control of the contr	
		그는 보호로 하는데 그래요 그는 그리고 있다.	

INSPECTION RECURD F.A.R. 43.11-91.409

wo: WO 1985 Airframe · page 1 of 1 Flightlogix · 4510 Airport Road · Cincinnati, OH 45226 · 513-321-1200 **N238MP** Cirrus SR22T, S/N: 1168 November 17, 2023 ACTT: 492.6 Hobbs: 597.7 Flight: 492.6 1. Due to #4 CHT probe Red'X on MFD found heat damage to #4 CHT probe and airframe connector P155. Installed new probe and repaired damaged connector IAW Cirrus SR22T WM 20-10-00 and AMM 77-20. Ops check good. 2. Due to heat damage found on #2 CHT probe replaced probe IAW Cirrus SR22T AMM 77-20. Ops check good. 3. Due to heat damage on #6 CHT probe wiring harness SECH2328-22 repaired wiring IAW Cirrus SR22T WM 20-10-00. Ops check good. 4. Pilot reported annunciation message "using ADC2". Swapped #1 P/N 24651-001 & S/N 20620909 and #2 P/N 24651-001 and S/N 20620955 GDC 74A air data computers locations for troubleshooting purposes IAW Cirrus Perspective Line Maintenance Manual 190-00920-00 Rev J 4.1.2 & 5.4.5. With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Flightlogix under work order: WO 1985. Dave Stewart A&P IA 3501524

Scanned with CamScanner