N9923Y AD COMPLIANCE RECORD AND RECURRING AD LIST





FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author, By
Manufacturer	Category	Model	*L		Part	
Cessna Aircraft	Airframe	T210N			Serial	#: 21064641
71-09-07 R1 11/26/1986	TO PREVENT EXHAUST GASES FROM ENTERING THE CABIN		SEE RECURRING LIST	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
CATP	CATP			GATP	Signature:	
71-21-01 1/1/1971	Superseded by 72-07-09		****	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
72-07-09 10/17/1974	TO DETECT CRACKS AND BOLT LOOSENESS WHICH COULD LEAD TO INFLIGHT SEPARATION OF THE FIN AND THE RUDDER		DNA SERIAL NUMBER	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature	
77-06-02 1/1/1977	Superseded by 78-07-01		****	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
®ATP	©ATP			ØATP	Signature	
77-16-05 8/11/1977	TO PREVENT MALFUNCTION OF THE P/N C291503-0101 OR P/N 1216100-1 FUEL SELECTOR VALVE		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	GATP			ØATP	Signature:	
78-07-01 4/6/1978	TO PRECLUDE ENGINE OIL PUMP FAILURE DUE TO CONTAMINATION BY THE TURBOCHARGER THRUST BEARING ANTI-ROTATION.		DNA SERIAL NUMBER	Once		1 S & S AVIATION CO 2 MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	CONTD. @ATP			ØATP	Signature	





FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By
Manufacturer	Category	Model	ale and a second se		Part	
Cessna Aircraft	Airframe	T210N			Serial	#: 21064641
78-26-09 1/1/1978	Superseded by 79-10-14		XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
ØATP	©ATP			©ATP	Signature:	
78-26-12 1/4/1979	TO DETECT BINDING OF FUEL QUANTITY TRANSMITTER FLOAT ARMS AND ASSURE PROPER OPERATION OF THE FUEL, CONTD.		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			SATP	Signature.	
79-10-14 R1 5/30/1988	TO PROVIDE AN ALTERNATE SOURCE OF FUEL TANK VENTING IN CASE OF FUEL TANK VENT OBSTRUCTION BY FOREIGN MATERIAL, CONTD.		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
79-15-01 7/26/1979	TO PROVIDE INSTRUCTIONS FOR RECOGNITION OF FUEL SYSTEM VAPOR BLOCKAGE AND OPERATING PROCEDURES TO RESTORE, CONTD.		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
79-25-07 12/13/1979	TO PRECLUDE THE POSSIBILITY OF ELECTRICAL OR ELECTRONIC COMPONENT DAMAGE OR AN IN-FLIGHT FIRE. CONTD.		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature	
80-07-01 3/28/1980	TO PRECLUDE FAILURE OF THE ENGINE OIL PRESSURE AND SCAVENGE PUMP DRIVE SHAFT AND RESULTING OIL PRESSURE. CONTD.		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
SATP	©ATP			©ATP	Signature.	

Content Revision: 12/2	8/2007 File ID: N99				stration N992			
FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. B		
Manufacturer	Category	Model			Part	#:		
Cessna Aircraft	Airframe	T210N			Serial	#: 21064641		
80-21-03 10/2/1980	TO PREVENT LOSS OF ROLL AXIS FLIGHT CONTROL		DNA NOT INSTALLED	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND		
CATP	©ATP			CATP	Signature:			
82-06-10 4/15/1982	TO PREVENT LOSS OF VACUUM- DRIVEN-ATTITUDE INSTRUMENTS RESULTING FROM FAILURE OF THE SINGLE AIRBORNE, CONTD		PCW	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND		
©ATP	©ATP			©ATP	Signature:			
85-02-07 3/6/1985	TO ELIMINATE THE POSSIBILITY OF LOSS OF THE FUEL SELECTOR ROLL PIN INSTALLATION		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND		
CATP	©ATP			©ATP	Signature:			
86-19-11 10/4/1986	TO ELIMINATE THE POSSIBILITY OF ENGINE POWER REDUCTION DUE TO CONTAMINATED FUEL		COMPLIED WITH 11-1-86 TOTAL 713.1 SEE LOG ENDORSEMENT	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND		
©ATP	©ATP			©ATP	Signature			
87-20-03 R2 9/24/1990	TO ASSURE PROPER ENGAGEMENT OF THE SEAT LOCKING MECHANISM AND TO PRECLUDE INADVERTENT SEAT SLIPPAGE		SEE RECURRING LIST	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND		
©ATP	GATP			©ATP	Signature			
88-22-07 11/24/1988	TO PREVENT POWER LOSS OR FIRE DUE TO FAILURE OF CERTAIN AEROQUIP 601 HOSE ASSEMBLIES		PCW SEE LOG ENDØRSEMENT DATED 12-12-88	Once		1.S & S AVIATION CO 2. MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND		
GATP	©ATP		· · ·	GATP	Signature			

Content Revision 12/2 FAA AD Number Effective Date	8/2007 File ID: N99 Description	Complied Date	Amendment Number Method of Compliance/Applicability	Once or	Next Due Date	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. B
Ellective Date	Description	Time	method of compliance applicating	Recur	Time	a contraction of the
Manufacturer	Category	Model			Part	
Cessna Aircraft	Airframe	T210N			Serial	#: 21064641
88-25-04 12/26/1988	TO PRECLUDE MAGNETO MOISTURE CONTAMINATION. WHICH COULD RESULT IN DUAL MAGNETO FAILURE, ENGINE, CONTD.		DNA NOT PRESSURIZED	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature	
91-22-01 11/4/1991	TO PREVENT FUEL LEAKAGE CAUSED BY DAMAGED FUEL LINES, WHICH COULD RESULT IN AN IN-FLIGHT FIRE		DNA SERIAL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
GATP	©ATP			CATP	Signature	
92-26-04 SUS 1/22/1993	Superseded by 94-12-08		****	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	GATP			©ATP	Signature:	
93-13-09 8/13/1993	TO PREVENT AIR INDUCTION HOSE FAILURE, WHICH COULD RESULT IN LOSS OF ENGINE POWER		DNA NOT INSTALLED	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
94-12-08 7/22/1994	TO PREVENT LOSS OF ENGINE POWER CAUSED BY INADVERTENT FUEL LOSS OR INADEQUATE FUEL SERVICING		DNA NOT INSTALLED	Once		1.S & S AVIATION CO 2 MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature	
96-12-22 7/31/1996	TO PREVENT LOSS OF ENGINE OIL CAUSED BY LOOSE OR SEPARATED OIL FILTER ADAPTERS, WHICH COULD RESULT IN ENGINE, CONTD		SEE Recuiring Lost	Recur		1. S&S AVIATION 2. MECHANIC/IA 3. 256295713 A&P IA 4. JIMMY L. GARLAND
CATP	CATP			MATP	Signature	



(hinaca Directivo Compli



Content Revision: 12/28	3/2007 File ID: N99	23Y	Air	craft Regis	stration: N992:	3Y
FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By
Manufacturer	Category	Model			Part	#:
Cessna Aircraft	Airframe	T210N			Serial	#: 21064641
98-05-14 R1 9/22/1998	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS,CONTD.		PCW COPY INSERTED IN FLIGHT MANUAL	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
2000-06-01 5/5/2000	To prevent foreign material from entering the fuel system and engine, which could result in loss of engine power,contd.		PCW HAS CORRECT STANDPIPE	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
2002-07-01 5/13/2002	To detect and replace structurally deficient horizontal stabilizer attachment brackets		DNA AFFECTED PARTS NOT INSTALLED	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	




C

¢

FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By
Manufacturer	Category	Model			Part	
Teledyne Continental 00-00-01 1/22/2001	Engine Important for Cessna Oil Filter Adapter Assemblies listed in AD 96-12-22	TSIO-520-R	DNA NOT INSTALLED	Once	Serial	#: 294000-R 1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
GATP	©ATP			©ATP	Signature:	-A-
77-05-04 3/11/1977	TO PREVENT CRANKSHAFT FAILURE		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
(CATP	©ATP	1		GATP	Signature:	
79-05-09 3/12/1979	TO PREVENT THE POSSIBLE LOSS OF OIL PRESSURE INDICATION		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713.A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	1
80-01-04 1/25/1980	TO PREVENT FAILURE OF CYLINDER HOLDDOWN FLANGES		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			GATP	Signature:	
80-22-05 10/24/1980	TO PREVENT CRANKSHAFT FRONT OIL SEAL BEING DISLODGED FROM THE ENGINE CRANKCASE		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L, GARLAND
©ATP	©ATP			©ATP	Signature:	
81-24-06 11/23/1981	TO PREVENT POSSIBLE FUEL LEAKAGE AND POTENTIAL FIRE HAZARD		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
	©ATP		inted 1/2/2008 9:46:19AM		1	a 6 of 11







PAA AM M	2007 File ID: N99				stration N992	
FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Nun 2. Cert. Type 4. Author. B
Manufacturer	Category	Model			Part	#:
eledyne Continental	Engine	TSIO-520-R			Serial	#: 294000-R
94-14-12 L 6/23/1994	Superseded by 95-21-15		XXXXXXXXXXXXX	Once		1 S & S AVIATION CO 2 MECHANIC/IA 3 256295713 A&P IA 4. JIMMY L. GARLAND
GATP	CATP			©ATP	Signature	
95-21-15 11/28/1995	TO PREVENT DETONATION DUE TO LOW OCTANE, WHICH CAN RESULT IN SEVERE ENGINE DAMAGE AND SUBSEQUENT FAILURE		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			GATP	Signature:	
	TO PREVENT LOSS OF ENGINE OIL CAUSED BY LOOSE OR SEPARATED OIL FILTER ADAPTERS, WHICH COULD RESULT IN ENGINE, CONTD.		SEE RECURRING LIST	Recur		1.S&S AVIATION 2.MECHANIC/IA 3.256295713 A&P IA 4.JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
	TO PREVENT CRANKSHAFT FAILURE AND SUBSEQUENT ENGINE FAILURE		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4.JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature.	
1/15/1998	TO PREVENT EXHAUST ROLLER ROCKER ARM FAILURE, WHICH CAN RESULT IN BENT PUSH RODS, RUPTURED ROCKER ARM,CONTD.		DNA NOT INSTALLED	Once		1. S&S AVIATION 2. MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature	
1/15/1998 (TO PREVENT EXHAUST ROLLER ROCKER ARM FAILURE, WHICH CAN RESULT IN BENT PUSH RODS, RUPTURED ROCKER ARM,CONTD.		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Once		1 S & S AVIATION CO 2 MECHANIC/IA 3 256295713 A&P IA 4 JIMMY L, GARLAND
@ATP	©ATP			CATP	Signature:	





FAA AD Number Effective Date	B/2007 File ID: N99 Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	stration. N9923 Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By
Manufacturer	Category	Model			Part	
Teledyne Continental	Engîne	TSIO-520-R			Serial	#: 294000-R
99-09-17 L 4/22/1999	Superseded by 99-19-01		COMPLIED WITH AT TCM AT REBUILD 09-10-98	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
99-19-01 9/30/1999	To prevent crankshaft failure due to crankshaft cheek cracks, which could result in total engine power loss,contd.		COMPLIED WITH 05-25-05 AT TACH 1027.7	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
2000-08-51 E 4/28/2000	Superseded by 2000-23-21		****	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
2000-23-21 12/12/2000	To prevent crankshaft connecting rod journal fracture, which could result in total engine power,contd.		DNA SERAIL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
2004-08-10 5/5/2004	To prevent loss of engine power due to cracks in the cylinder head & possible engine failure caused,contd.		DNA AFFECTED CYLINDERS NOT INSTALLED	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature:	
2007-04-19 R1 5/7/2007	To prevent cylinder separation that can lead to engine failure, possible engine compartment fire, and, contd.		DNA NOT INSTALLED	Once		1. S&S AVIATION 2. MECHANIC/IA 3. 256295713 A&P IA 4. JIMMY L. GARLAND
©ATP	©ATP			©ATP	Signature	





Content Revision: 12/28	/2007 File ID: N9		1		stration: N992:		
FAA AD Number Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By	
Manufacturer	Category	Model			Part		
McCauley	Propeller	D3A34C402			Serial #: 815993		
77-26-03 6/7/1978	TO PREVENT POSSIBLE BLADE PITCH CONTROL FAILURES		DNA SERAIL NUMBER	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND	
©ATP	©ATP			©ATP	Signature:	1	
82-27-02 R1 2/22/1983	TO PREVENT POSSIBLE PROPELLER BLADE SHANK FAILURE		DNA SERIAL NUMBER	Once		1. S & S AVIATION CO 2. MECHANIC/IA 3. 256295713 A&P IA 4. JIMMY L. GARLAND	
©ATP	©ATP			©ATP	Signature:		
2003-13-17 7/18/2003	To detect unsafe conditions that could result in separation of a propeller blade & loss of control,contd.		DNA OVERHAUL FACILITY	Once		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND	
©ATP	©ATP			©ATP	Signature:		
2005-14-11 8/17/2005	To prevent blade failure that could result in separation of a propeller blade and loss of control of the airplane		DNA OVERHAUL FACILITY	Once		1. S&S AVIATION 2. MECHANIC/IA 3. 256295713 A&P IA 4. JIMMY L. GARLAND	
©ATP	©ATP			©ATP	Signature:		
2006-24-07 1/3/2007	To detect potentially unsafe conditions that could result in a propeller blade separating from the hub,contd.		DNA OVERHAUL FACILITY	Once	-	1.S&S AVIATION 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND	
©ATP	©ATP			©ATP	Signature:		
Manufacturer	Category	Model			Part	: #:	
ACS Products Company	Ignition Switches	IGNITION SW	VITCHES		Seria	#:	
93-05-06 4/29/1993	TO PREVENT FAILURE OF IGNITION SWITCHES		COMPLIED WITH AT 2112.7 DUE AGAIN AT 4112.7	Recur	4112.7	1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND	
©ATP	©ATP			©ATP	Signature.		
	©ATP		nted 1/2/2008 9:46-19AM			10 of 11	



din.

FAA AD Number Effective Date	8/2007 File ID: N9	923Y	Air Air Compliance Re	craft Regis	tration: N9923	
Effective Date	Description	Complied Date Time	Amendment Number Method of Compliance/Applicability	Once or Recur	Next Due Date Time	1. Facility 3, Cert. Num. 2. Cert. Type 4. Author. By
anufacturer	Category	Model			Part	#:
duction Air Filters	Air Filter	PAPER INDU	CTION AIRFILTER		Serial	#:
84-26-02 1/29/1985	TO PREVENT POSSIBLE ENGINE POWER LOSS OR STOPPAGE CAUSED BY ENGINE INGESTION OF FRAGMENTS, CONTD.		SEE RECURRING LIST	Recur		1.S & S AVIATION CO 2.MECHANIC/IA 3.256295713 A&P IA 4. JIMMY L. GARLAND
MATP	©ATP			GATP	Signature:	

N9923Y

12/07/2010

AD NOTES COMPLIANCE RECORD

Airframe - Cessna - T210N

Engine - Teledyne Continental - TSIO-520-R

Propeller - McCauley - D3A34C402

64641
294000R
815993

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
69-08-11	Fuel boost pump		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
71-09-07 R1	Exhaust manifold heat exchanger		INSPECT		×	EV 50 HRS	ADVANTAGE AIRCRAFT CRS Q2AR596N
72-07-09 R1	Cracks, bolts in fin and rudder		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
74-18-05	Slick magnetos		N/A BY MODEL	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
75-05-07	King Radio nav systems		N/A DATE OF MANUFACTURE	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
77-05-04	Crankshaft failure	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
77-16-05	Fuel selector valve		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
77-26-03	D3A34C		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
78-07-01	Engine oli pump		N/A BY S/N	x			ADVANTAGE
78-26-12	Fuel quantity system		N/A BY S/N	x			ADVANTAGE AIRCRAFT
79-05-09	Oil pressure relief valve	9/10/98	COMPLIED WITH AT O/H	x			CRS Q2AR598N ADVANTAGE AIRCRAFT CRS Q2AR598N
79-08-03	Electrical system		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
79-10-14 R1	Fuel tank venting		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
79-15-01	Fuel flow distribution		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS 02AR598N
79-25-07	Alternator ground		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
80-01-04	Cylinder holddown flanges	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
80-06-05	Slick magnetos		N/A BY MODEL	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
80-07-01	Oil pressure		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS 02AR598N
80-21-03	Roll axis flight control		N/A EQUIPMENT NOT INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
80-22-06	Crankshaft front oil seal	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
81-16-05	Slick magnetos		N/A BY MODEL	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
81-24-06	Fuel pump	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N

Page 2			N9923Y				12/07/2010
AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
82-06-10	Vacuum-driven instruments		N/A EQUIPMENT NOT INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
82-27-02 R1	Propeller blade shank failure	6/11/91 @1683	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
84-10-01 R1	Bladder fuel cells		N/A BY S/N	×			ADVANTAGE AIRCRAFT CRS Q2AR598N
84-26-02	Paper induction air filters		REPLACE FILTER		x	EV 500 HRS	ADVANTAGE AIRCRAFT CRS Q2AR598N
85-02-07	Fuel selector		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
86-13-04 R3	Cylinder assemblies		N/A BY MANUFACTURER	×			ADVANTAGE AIRCRAFT CRS Q2AR598N
86-19-11	Contaminated fuel	11/1/86 @713	INSERT POH PROCEDURES	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
87-20-03 R2	Seat tracks		INSPECT SEAT LOCKS		x	EV ANNUAL	ADVANTAGE AIRCRAFT CRS Q2AR598N
87-23-08	Crankshaft fatigue cracks		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
88-03-06	Oil filter		N/A DATE OF MANUFACTURE	×			ADVANTAGE AIRCRAFT CRS Q2AR598N
88-22-07	Hose assemblies	12/12/88 @1174	INSP	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
88-25-04	AFM/POH changes-magneto		N/A NO PRESSURIZED MAGS	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
91-19-03	Champion oil filter		N/A DATE OF MANUFACTURE	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
91-22-01	Fuel line chaffing		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
92-26-04	Fuel loss		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
93-05-06	ACS ignition switches	2/9/94 @ 2112.7	DIODE INSTALLED REINSP / LUBE		x	EV 2000 HRS	ADVANTAGE AIRCRAFT CRS Q2AR598N
93-08-17	Incorrect oil pick-up tube	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
93-10-02	Cylinder valve retainer	9/10/98	COMPLIED WITH AT O/H	×			ADVANTAGE AIRCRAFT CRS Q2AR598N
93-13-09	Intercooler installation		N/A NO STC INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
94-12-08	Preflight procedures	11/3/09 @3976	INSERT POH PROCEDURES CALBRATE FUEL QTY INSTALL RAISED FUEL CAPS	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
94-14-12	Low octane detonation		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
95-21-15	Engine teardown and analytical inspect.	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
96-12-22	Oil filter adapter		N/A NOT INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
97-26-17	CORRECTION - Crankshaft fatigue cracks	9/10/98	COMPLIED WITH AT O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR596N
PL98-01-08	Exhaust roller rocker arms		N/A NO STC INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR596N

Page 3			N9923Y				12/07/2010
AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
98-05-14	AFM revision	12/7/98 @964	INSERT COPY OF AD IN AFM	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
98-05-14 R1	AFM revision	12/7/98 @964	INSERT COPY OF AD IN AFM	x		A.	ADVANTAGE AIRCRAFT CRS Q2AR598N
98-14-03	AlliedSignal ATC transponders		N/A BY S/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
PL99-09-17	Crankshaft failure		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
99-19-01	Crankshaft failure	5/25/99 @118.4	INSP TCM SB 99-3	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
99-23-22 R2	Traffic Alert Collision Avoidance System (TCAS II) advisories		N/A EQUIPMENT NOT INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2000-06-01	Prevent foreign material from entering the fuel system	11/3/09 @3976	INSP FUEL STRAINER	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
PL2000-08-51	Crankshaft connecting rod journal fracture		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2000-23-21	Fracture of the crankshaft connecting rod journal	9/8/98 O/H	N/A BY CRANKSHAFT S/N K169313N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2001-23-17	Prevent external noise to the GNS 430 units course deviation indicator (CDI)		N/A 430W INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2002-07-01	CORRECTION - Detect and replace structurally deficient horizontal stabilizer attachment brackets	11/3/09 @3976	N/A NO RECORD OF PART REPLACEMENT	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2003-13-17	Detect unsafe conditions that could result in separation of a propeller blade		N/A NO REWORK BY T&W PROP	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2004-08-10	Prevent loss of engine power		N/A NO STC INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2004-19-01	CORRECTION - Prevent slippage of the pilot/co-pilot shoulder harness		N/A EQUIPMENT NOT INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2005-14-11	Prevent blade failure that could result in separation of a propeller blade		N/A NO REWORK BY SO. CAL. PROP	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2005-18-20	Prevent Goodrich "FASTprop" propeller de-icers from detaching from the propeller blade		N/A BY BOOT P/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2005-26-10	To prevent loss of engine power due to cracks in the cylinder assemblies		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2006-24-07	To detect unsafe conditions that could result in a propeller blade separating from the hub and loss of control of the airplane		N/A NO REWORK BY CSE AVIATION	×			ADVANTAGE AIRCRAFT CRS Q2AR598N
2007-04-19	To prevent cylinder separation that can lead to engine failure		N/A TCM CYLINDERS INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2007-04-19R1	To prevent cylinder separation that can lead to engine failure		N/A TCM CYLINDERS INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2008-10-02	To prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators		N/A BY VALVE P/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2008-26-10	Prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators	11/3/09 @3976	N/A BY VALVE P/N	x			ADVANTAGE AIRCRAFT CRS Q2AR598N
2009-16-03	To prevent the separation of the cylinder head	11/3/09 @3976	N/A BY MODEL	x			ADVANTAGE AIRCRAFT CRS Q2AR598N

rage 4		Naazot					12/01/2010		
AD#	Applicable S.B. #& Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number		
2009-19-07	Correction - To prevent loss of engine power due to cracks in the cylinder head, possible engine failure, and fire in the engine compartment		N/A NO NEW CYLINDERS INSTALLED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N		
2009-24-51	To address rapid wear on the face of hydraulic lifters		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR598N		
2009-24-52	To address rapid wear on the face of hydraulic lifters		SUPERCEEDED	x			ADVANTAGE AIRCRAFT CRS Q2AR596N		
2010-11-04	To prevent excessive hydraulic lifter wear		N/A NO RECORD OF SUSPECT LIFTER INSTALLATION POST O/H	x			ADVANTAGE AIRCRAFT CRS Q2AR598N		

N9923Y	S/N 20164641
AD96-12-22	OIL FILTER ADAPTER

Description	Date of Compliance	Hour Meter at Compliance	Method of Compliance	Next Due Compliance	Signature
INSPECT OIL FILTER ADAPTER FOR LOOSENESS AND TORQUE STRIPE	12-01-07	HOBBS 1934.0	VISUAL INSPECTION	NEXT OIL CHANGE	J. GARLAND 256295713A&P
				_	
				_	

N9923Y	S/N 20164641
AD71-09-07	EXHAUST INSPECTION

	Description		Date of Compliance	Hour Meter at Compliance	Method of Compliance	Next Due Compliance	Signature
EXHAUST HEAT EXCHANGER PRESSURE TEST(DUE 50 HOURS)		PRESSURE	11-08-05	HOBBS 1735.5	REPLACED INDUCTION AIR FILTER I synatic & Ressure test	HOBBS 1785.5	J. GARLAND 256295713A&P
15	1.4	12	12-18-06	1860.8	Troppediou + Provo Test of Heat Expansion	1910.8	la \$19860.At
10	11	11	12-01-07	Holdos 1860.8 Held Tach 1134.0	11 11	1984.0	Colump P

INSPEC 190

N9923Y	S/N 21064641
AD87-20-03R2	SEATS AND RAILS

Description INSPECTION OF SEATS AND RAILS. DUE ANNUALLY		Date of Hour Meter at Compliance Compliance		Meth	Method of Compliance			Signature	
		11-08-05	TACH 1735.5	INSPECTION OF SEATS AND RAILS		11/06	J. GARLAND 256295713 A&P		
11	15	1.5	12-18-06	1860-8	0	i.V.	11	12-07	23191860 AN
11	11	11	12-01-07	700L 1934.0	<i>t</i> i	11	11	12.08 -	256245713 PM

N9923Y	S/N 20164641
AD84-26-02	PAPER AIR FILTER

Description	Date of Compliance	Hour Meter at Compliance	Method of Compliance	Next Due Compliance	Signature
PAPER AIR FILTER REPLACEMENT (DUE 500 HOURS)	11-08-05	HOBBS 1735.5	REPLACED INDUCTION AIR FILTER	HOBBS 2235.5	J. GARLAND 256295713A&P

	And the first state	337 Statu	IS
Aircraft Reg	istration No. N99237	1	Aircraft S/N 21064641
Date of 337	Further Continuous Airworthiness Requirements	Approved By	Description
3-12-82	Yes No		STEC 60-2 whele the my lactely
5-27-15	Yes No 😡		WX-10A STREAMING Invit
1-24-50	Yes No 🖸		Paging First sparsey Union Just
2-10-89	Yes No K		KLSSE HSI LASHI
8-6-70	Yes No D		KW 89 685 Jastal
9-22-03	Yes No 🔁		Renne Branc / App SHO See Varm Looks
4-16-97	Yes No 1		Trues homen brokill
11-6-97	Yes No		WXICH REMARE / WX \$50 Instill
11-9-05	Yes No		3PI FS450 Rel flow
1-29-09	Yes No		Garmin 430W Install
1-12-12	Yes No		JPI 830 Jav-11
9-11-12	Yes No		Equil injustre lastill
1-17-13	Yes No		STATS ASTAN 250 00- Pas, 601 Bt, 6mt3
	YOU NOT		GARGEN ADD 454 (D ACK E- OF BLT
	Yes No		
	Yes No		
	Yes No		

adlog minutes	Airci Mak		IND. N992	n Status		nor Lor L	WPUCABLE ARM	
	1	DUE AT	-	C	OMPLIED W	пн	CS ORTH	
TYPE OF INSPECTION	HOURS	CYCLEN	DATE	HOURS	OVELUIA	DATE	NESS	
ANNUAL 2013	-		1-31-13	4Mt 3/2193.L	-	4-22-13		
O ALTIMETER 91.411			8-31-14					
O TRANSPORDER 914	second se		5 31-14					
Or O2 Tank Hydrodent	-	-	12-12	12-292		12-202		
or Turbo on that check us	due 5200 TIS		1-25-13	2191.3		1-15-13		
O Turba eatlet while in		3400 Adds				11		
- Expanst 71-9-7	2241.34		-	715.3/21934		4-22-13		8
ALS Smitch 93-5-6	- GIYIATIS	374T Hele	the second s			4-22-13		
- Cent Rolls 2011-10-0			1-31-13	243.6				
An FILTER Report 5426-		-	Para	2246.4		4-22-13	ARTENAR	
And Fritzen Instrumed	2237.4	-	1-21-13	-		9-24-1-		
On Tonk Hydrolest	-	-	12-31-15					
ANNUAL 2014			4-30-14	2011		12-3-13		
Exhaut 71-9-7	2243.6.4	-	4-30-14	2246,4		14-2-12		
Sont miles 2011-10-9	2243.6	-	10-27-07	3976.875		10/24/04		
Propellar Resp.1			10-11-01	-1 70-4	1	14124757		
Propulse Recol				-			ENGINE	
A. F. Her Replement 5-1-24	2 2746.4					-		
Elawer 71-9-7	2346.4							

-	TREGISTRA		adl	adNote				
	T SERIAL NO 210N RCRAFT		Exhaust Ga	s Ente	ering C	abin		
				1				
DATE	TOTAL TIME AT COMPL.	TACH OR RECORDING METER TIME AT COMPL.	METHOD OF COMPLIANCE	NEXT CO TOTAL TIME	MPL. DUE AT	AUTHORIZED SIGNATURE & NUMBE		
1-25-13	4195.7	2191.3			2241.3	RABornhart 31249944AD		
4-22-13	4198.3	2193.6			2243.6	CJohn Colorea CRS LCI R24		
12-3-13	-1251.1	2246.4			2296.4	Milan Journevic 1,4 3144117		

AIRC	99237 RAFT REGIST 106964	RATION NO.	e	dNot	84-26-2 R AD NUMBER				
AIRG	RAFT SERIAL	NO	Induc	tion Air	Filters				
If multi-eng	ine: 🛛 Left	□ Right □ Fi	ont 🛛 Rear	-					
DATE	TOTAL TIME AT COMPL.	TACH OR RECORDING METER TIME AT COMPL.	METHOD OF COMPLIANCE	NEXT COMPL TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	AUTHORIZED SIGNATURE & NUMBER			
11/8/05	3777.5	1735.5	Replace of new		2235.5	Lest # 256245713 ADIA			
12-3-13		2246.4	AFLY#3 Replace when		2746.4	Milus Saraunic A3164117AP			
-							-		
					1		T ·		


AIRCR.	AFT REGISTR	ATION NO.	a	93-5-6 R AD NUMBER		
	AFT SERIAL N	0	lgn	ition Sw	vitch	
DATE	TOTAL TIME AT COMPL.	TACH OR RECORDING METER TIME AT COMPL.	METHOD OF COMPLIANCE	NEXT COMPL TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	AUTHORIZED SIGNATURE & NUMBER
2/9/44	2112.7		Dude AFray			
1/11/12	4141.8		Inspection H3	6141.8		AP 268 9017 1A

a stadel	Serial Numbers		the second s
Cessna Model	and a survey of the survey of	through	15079405
150	15074428	and the statement of th	A1500734
And and a state of the state of	14 4 5 6 6 9 0 6	through	

(b) Within 100 flight hours after the effective date of this AD, or at the next annual inspection, whichever occurs first, inspect the ignition switch installation to determine if a diode or other surge suppresser is installed on the starter solenoid. If one is not installed, prior to further installed on the starter solenoid if one is not installed, prior to further

-

1	N9923Y AIRCRAFT REGISTRATION NO. 21064641 AIRCRAFT SERIAL NO. T210N			a Seat Rails	2011-10-9 R AD NUMBER				
-		ARCRAFT							
	DATE	TOTAL TIME AT COMPL	TACH OR RECORDING METER TIME AT COMPL	METHOD OF COMPLIANCE	NEXT COMPL TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	-	URE & NUMBER	-
Ī	11/12	4141.8	2137.4	Inspection AFLuget		2237.4 JAV/2013	AP 2689017	14	+
4	1-14-13	4148.3	2143.6	P	22436 -	7	O John (dalmin	LLIRZYIK	-
									1
F									-
-									



	RATION NO.	ad	81-24-6 AD NU		
			ntal Er	ngine	
	t 🗌 Right 🗍	Front Rear Engine Mode			
TOTAL TIME AT COMPL	TACH OR RECORDING METER TIME AT COMPL	METHOD OF COMPLIANCE	TOTAL	DATE, TACH, OR RECORDING	AUTHORIZED SIGNATURE & NUMBER
		dweott		METERTIME	
		Engine hay # 1			
		0 0			
					- The second second
	TSERIAL N LION RCRAFT ne: Left TOTAL TIME	TOTAL TACH OR	TOTAL TACH OR TIME AT AT AT AT AT AT AT AT AT AT	T SERIAL NO. CONTINENTAL Engine Model/Serial No:_ TOTAL TACH OR TIME RECORDING METER TIME AT COMPL AT COMPL	0644641 PT SERIAL NO. CONTINENT Continental Engine CRAFT ne: Left Right Front Record of the series Total TACH OR AT METHOD OF COMPLIANCE Time Record of the series AT OMPL AT COMPL METHOD OF COMPLIANCE Time Record of the series AT METHOD OF COMPLIANCE Time Record of the series

	SY ISTRATION NO.		82-27-2	
AIRCRAFT SER T210, TYPE AIRCRAF	IAL NO.	M	IcCauley Propeller	
A DECOMPANY AND A DECOMPANY				
	Left 🗌 Right 🗌 Fro		Propeller Model/Serial No.	
	Left Right Fro	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NU
COMPLIANCE	TOTAL TIME AT	TACH OR RECORDING METER TIME		AUTHORIZED SIGNATURE & NI
COMPLIANCE DATE	TOTAL TIME AT	TACH OR RECORDING METER TIME	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & N

Amendment 39-4521 as amended by Amendment 39-4564. Applies to the following McCauley Accessory Division C200, C300, and C400 series constant speed propellers with blade
 B120667 thru B120686
 96DCA-10

 B120687 thru B120929
 96DHB-16E

 B121663 thru B121262
 90DCB-8 and 90DHB-16E

 B121450 thru B121489
 90DCB-8

AIRCRAFT	4237 REGISTRATION NO		adNote	86-5-2 N/I
	ION	U	nited Instruments A	ltimeter
COMPLIANCE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER

Amendment 39-5317. Applies to altimeter Part Numbers 5934, 5934A, 5934M, 5934AM, 5934PA, 5934PA, 5934PA, 5934PA, 5934PAD, 5934PAD, 5934PAD, and 5934PAD with the following serial numbers:

6C461 thru 6C999 7C000 thru 7C999 8C000 thru 8C999 9C000 thru 9C999 0D000 thru 0D999 1D000 thru 1D999 2D000 thru 2D869 NOTE 1: This AD is applicable to pressure sensitive © 1988-2012 AeroTech Publications, Inc., All rights reserved

NOTE 2: It is recommended but not required by this A that the above check for synchronized movement accomplished each time the altimeter barometric pressu dial is adjusted.

(b) Regardless of the results of the check specified paragraph (a) of this AD, on or before July 1, 1986, for affected altimeters installed in an aircraft, remove t altimeter and return it to United Instruments, Inc. at t above address. Replacement altimeters must serviceable units.

(c) For all affected altimeters not installed in an aircraption to further use but no later than July 1, 1986, return t

AIRCR	AFT REGIST	TRATION NO.	ad	AD NU					
AIRCR	06464 AFT SERIAL 210N	NO	Contine	ntal Er	ngine				
If multi-engin	ne: 🗌 Left	Right	Front 🗌 Rear Engine Mode						
DATE TOTAL TIME AT COMPL		TACH OR RECORDING METER TIME AT COMPL	METHOD OF COMPLIANCE	TOTAL TIME	MP. DUE AT DATE, TACH, OR RECORDING METER TIME	NG			
9/10/48			JW @ OH						
			Engile Log # 1						
Amendment 39-53 39-5850, Applies I P/N's 643985, 640 649169, 649169Cl any cylinder rewo after January 1, 1 following Teledyn New ENC	GINES SERL	d by Amendment 3 amblies (part numb 846652, 646652CF these numbers will above part numbers 485 total hours on Motors (TCM) Engl AL NUMBERS 68 hru 807070	9-5555, is further amended by Amendment er (P/N) stamped on flange of cylinder) with , 646657, 646657CP, 649162, 649162CP, h all "A" dash numbers as a suffix, and also , either of which were manufactured on or r less installed on, but not limited to, the nes:	These 6 Aero C 33, 35, 36 210, 310	-L 242 -MB 236 -M 233 IO-550-B 249	©1986 AeroTech Publications Inc., All rights 1045, 224046 1834 thru 242896, 242899 1383 thru 236400, 266000 thru 266017, 266019 1728 thru 235787, 235789 thru 235793 104 thru 249122 In, but are not limited to, the following airplanes: 685; AISI F, 20 Pegaso; Ambrosini MF-15; Beagles B206 18, 58P, 58TC; Bellanca Viking 300; Cessna 185, 186, 19, 401, 402, 404, 411, 414, 421; Fletchar FU-24A; Janco melak; Piper PA-46; Prinair DeHavilland Heron; Proce Vindecker Eagle; Yeoman Cropmaster 285.			

N 99237 ACRAFT REGISTRATION N 21064691 ACRAFT SERIAL NO.

TZION

Quick-Drain Installation

adNote

DD OF COMPLIANCE	METHO	RECORDING METER TIME AT COMPLIANCE	TOTAL TIME AT COMPLIANCE	DATE	
Insersts	POH		-713.1	1/1/80	
		METHOD OF COMPLIANCE PoH Lase-sta	AT COMPLIANCE	TOTAL TIME AT RECORDING COMPLIANCE AT COMPLIANCE METHOD OF COMPLIANCE	

Amendment 39-5407. Applies to Models R172 thru R172K. FR172E thru FR172K, 177 thru 177B and 177RG, F177RG, 185 thru 185E, A185E, A185F, A188, A188A, A188B, T188C, 205 and 205A, 206, U206, U206A thru U206G, TU206A thru TU206G, P206, P206A thru P206E, TP206A thru TP206E, 207 and 207A, T207 and T207A, 210B thru 210R, T210F thru T210R, P210N and P210R (all Serial Numbers (S/N)) airplanes equipped with fuel reservoir(s) certified in any category.

Compliance required within 100 hours time-in-service or at the next annual inspection, whichever comes first after the effective date of this AD, unless already accomplished. To eliminate the possibility of engine power reduction due

to contaminated fuel, accomplish the following: A. On Cessna Models R172, R172E thru R172H, (S/Ns

A. On Cessna Models R172, R172E thru R1721, (SNS R172-0001 thru R1720625) FR172E thru FR172] (S/Ns FR17200001 thru FR17200530) 177 thru 177A (S/Ns 17700001 thru 17702123) Model 177RG (S/Ns 177RG0001 thru 177RG0592) F177RG (S/Ns F177RG0001 thru F177RG0122) 177RG0592) thru 210L and T210L (S/Ns 21058819 thru 210H, 210J, 210K, 210L, 210M, 210N, 210R, T210F, T210G, T210H, T210J, T210K, T210L, T210M, T210N, T210R (S/Ns 21057841 and on) P210N and P210R (S/Ns P21000001 and on) airplanes, attach the information that is included in the appendix to this AD (entitled PILOT OPERATING PROCEDURES — PREFLIGHT FUEL SYSTEM CHECK) to the airplane documents.

86-19-11

C. An equivalent means of compliance with this AD may be used if approved by the Manager, Aircraft Certification Office. FAA, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209.

All persons affected by this directive may obtain copies of the document(s) referred to herein upon request to Cessna Aircraft Company, Piston Aircraft Marketing Division, Post Office Box 1521, Wichita, Kansas 67201; or FAA, Office of the Regional Counsel, Room 1558, 601 East 12th Street, Kansas City, Missouri 64106.

MAJOR REPAIR

Ro

This amendment becomes effective October 4, 1986. APPENDIX

LIO 64441 AIRCRAFT SERIAL NO. T 210N TYPE AIRCRAFT If multi-engine: Left Right Front Record Dire Compliance TOTAL TIME AT Record Dire METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER 9/10/98 Uw Email Email Email Email Bare Compliance METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER Total Time Method Email Method	N99237 AIRCRAFT REGISTRATION NO.			adNote	88-3-6 N AD NUMBER	
If multi-engine: Left Right Front Rear Engine Model/Serial No: COMPLIANCE TOTAL TIME AT COMPLIANCE TACH OR HETER TIME AT COMPLIANCE METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER 7/10/98 Uwe Oth	AIRCRAFT SERI	AL NO.	Coi	ntinental Oil Filters		
COMPLIANCE TOTAL TIME AT COMPLIANCE RECORDING METER TIME AT COMPLIANCE METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER 9/10/98 0/we 0/t			ont 🗌 Rear Er	ngine Model/Serial No:	1	-
9/10/98 Uwe off -	COMPLIANCE		TACH OR RECORDING METER TIME	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER	-
Enjine huy #1	9/10/98		1 0	OH		-
			Enjine	hoy #1		-

Amendment 39-5888. Applies to IO-360, TSIO-360, O-470, IO-470, TSIO-470, IO-520, TSIO-520, GTSIO-520 and IO-550 series engines equipped with oil filters.

Compliance is required at the next oil change or within 10 flight hours, whichever occurs first, unless already accomplished.

To prevent possible loss of engine oil and subsequent engine failure, accomplish the follow-

ing: (a) Determine if oil filter TCM P/N 649309 or can be accomplished.

(d) Upon request, an equivalent means of compliance with the requirements of this priority letter AD may be approved by the Manager, Atlanta Aircraft Certification Office, FAA, 1669 Phoenix Parkway, Suite 210C, Atlanta, GA 30349.

(e) Upon submission of substantiating data by an owner or operator, through an FAA maintenance inspector, the Manager, Atlanta Aircraft Certification Office, may adjust the compliance time specified in this AD.

Notes: (1) TCM Service Bulletin No. M88-4, dated

MAJOR

AIRCRAFT REGIN	STRATION NO		adNote	AD NUMBER
AIRCRAFT SERIA T210 N TYPE AIRCRAFT	NU NO	Aero	quip Hose Assemb	lies
COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
2/12/88	1174.4	NAFI	Taspecton	
		AAFL	oy#1	

Amendment 39-6050. Applies to all TP206, TU206, T207, T210 and P210 Series airplanes (all serial numbers) certificated in any category.

Nganzy

Compliance required within the next 75 hours time in service after the effective date of this AD, unless already accomplished.

To prevent power loss or fire due to failure of certain Aeroquip 601 hose assemblies, accomplish the following:

that a Model 601 hose was installed between April 1984, and May, 1988, replace the suspect hoses as follows:

88.22.7

@1988 AeroTech Publications Inc., All rights reserved

(i) Prior to further flight replace the waste gate supply hose assembly, Aeroquip P/N 601000-4-0310 or the hose identified as Cessna S1236-4-0310 supplied by sources other than Cessna, or as identified above with an Aeroquip P/N AE3663162E0310 hose or equivalent in accordance with Cessna Service Bulletin SEB 88-5, one or with an Aeroquin 601000TZICN

Champion Oil Filter

adNote

If multi-engine: Left Right Front Rear Engine Model/Serial No:

COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	ROHOR RECORDING WEITER HIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
efet				
9/10/98			C/w e off	
			Fine hon #1	

Amendment 39-8030.

Applicability: TCM Models IO-360, L/TSIO-360, IO-346, L/I/O-470, TSIO-470, IO-520, L/TSIO-520, 8-285, IO-550, and GTSIO-520 series engines, which are installed on, but not limited on, but not limited to, certain Beech Bonanza models C33, E33, F33, S35, V35, A36, 36, A36TC, and B36TC; Musketeer model A23, Baron models C55, D55, F55, 58 and 58TC series airplanes; and on certain Cessna models R172K, 180 (Serial Numbers (S/N) 53087 and up), 182 (S/N 67042 and up), F182 (S/N 00130 and up), 185 (S/N 03852 and up), 188 (S/N 03474 and up), T188 (S/N 03474 and up), 206 (S/N 05030 and up), 207 (S/N 05227 and up), T207 (S/N 05227 and up), 210 (S/N 63373-63375 and up), T210 (S/N 63373-63375 and up), P210 (S/N 278 and up), T303, 310, 320, P337, T337, exterior. Remove any filter bearing any of the

91-19-3

following date codes prior to further flight: Date Codes: All three-digit date codes with "9" as the third-digit, or date codes 3J8, 4J8, 1K8, 2K8, 3K8, 4K8, 2L8, 1M8, 3M8, 1A0, or 2A0.

(c) Filters identified with any of the date codes listed in paragraph 9(b) of this AD are not serviceable and cannot be returned to service.

(d) Replace any removed filter with Champion filter P/N CH48108 or CH48109 having date codes other than those listed in paragraph 9(b) of the AD, or with any other FAA approved filter that is eligible for the applicable engines.

(e) Aircraft may be ferried in accordance with the provisions of FAR 21.197 and 21.199 to a base where the AD can be accomplished.

MAJOR REPA

(f) Upon submission of substantiating data by an

210646 AIRCRAFT SERI	AL NO.		adNote	93-8-17 AD NUMB
T 2/0ハ TYPE AIRCRAFT nulti-engine: 匚			Engine Model/Serial No:	
COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
10/98			c/we off	
			Fingin Lig #1	
				©1993 AeroTech Publications Inc., All rights reser
Applicability CM) rebuilt	9-8565. Docket : Teledyne (and overhaule SIO-520, and I	Continental d Model O-4	Motors proved alterna 70, IO- this airworth	ation concerning the existence of ative methods of compliance w iness directive, if any, may the Certification Office.

To prevent an engine failure, accomplish the following: (a) Within the next 50 hours time in service after the effective date of this AD, inspect engines for an

JOR REPAIR & I FORMS (FAA FO following service bulletin: Document No. Pages Revision Date TCM M91-10 1-3 1 Nover November 27, 1991

AIRCRAFT REGISTRATION NO.	adNote		
21064641 AIRCRAFT SERIAL NO. T210N	TCM (Bendix) Mag	ineto	
TYPE AIRCRAFT	ar Magneto Position/Mod /Serial No: LFT. RT		-
DATE COMPLIANCE RE	TACH OR ECORDING ETER TIME COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER	
9/10/48	C/WE Off Regime Lug #1		

Amendment 39-8895. Docket 94-ANE-12.

Applicability: Teledyne Continental Motors (TCM) (formerly Bendix) magnetos new and rebuilt TCM Model SC-20, Part Number (P/N) 10-500XXX-X series; Model SC-200, P/N 10-600XXX-X series; and Model S-1200, P/N 10-349XXX-X series, magnetos with Serial Numbers (S/N) J2793XXX(R) through J3193XXX(R), K0193XXX(R) through K3093XXX(R) and L0193XXX(R) through L2293XXX(R) inclusive, with capacitor, P/N 10-349276, with date code 93-40 or 93-42. In addition, all TCM Model SC-20, P/N 10-500XXX-X series; SC-200, P/N 10-600XXX-X series; and S-1200, P/N 10-349XXX-X series, magnetos that have capacitor, P/N 10-349276, identified with date code 93-40 or 93-42, installed after October 27, 1993. Also, any TCM or Bendix magneto regardless of serial number that was fitted after October 27, 1993, with capacitors P/N 10-349276, sold as individual replacement parts with date code 93-40 or 93-42. These magnetos are installed on but not limited to reciprocating engine powered Beech, Cessna, Maule, Mooney, Piper, and Robinson aircraft. NOTE: The "X" represents numbers in the that have no significance in determining applicability:

date code other than 93-40 or 93-42, and metal stamp the letter "E" in accordance with the Identification paragraph of TCM CSB641, dated February 1, 1994, to show compliance with this AD.

(b) Prior to installation, inspect uninstalled capacitor, P/N 10-349276, and replace, if necessary, with a serviceable part, in accordance with the Detailed Instruction, paragraph 2.1 of TCM CSB641, dated February 1, 1994. NOTE: TCM Critical Service Bulletin CSB94-1 dated February 1, 1994, and Lycoming Service Bulletin 517 dated February 25, 1994, refers to this subject.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta Aircraft Certification Office. NOTE: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Atlanta Aircraft Certification Office.

(d) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the aircraft to a location where the MAJOR REPAIR & A FORMS IFAA FOR

AD NUMBER		adNote		STRATION NO.	N907 AIRCRAFT REGIN
		Fuel System		AL NO.	AIRCRAFT SERU T 210 TYPE AIRCRAFT
					TTPE AIRGRAFT
RE & NUMBER	AUTHORIZED SIGNATU	METHOD OF COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	TOTAL TIME AT COMPLIANCE	COMPLIANCE
	ton FAACRS	POHV Fal quert while		3976.8	11/3/09
	QLAR 5981	railed folcups indellal			
/	U AMA SISI				
/	U ANA S ISI				

92-26-04, Amendment 39-8431.

Applicability: The following model and serial number airplanes, certificated in any category.

Model 210G through 210R, and T210G through T210R P210N, and P210R

Serial Numbers 21058819 through 21065009, and

T210-0198 through T210-0454 P21000001 through P21000874

Compliance: Required within the next 12 calendar months after the effective date of this AD, unless already accomplished.

To prevent loss of engine power caused by inadvertent fuel loss or

inadequate fuel servicing, accomplish the following: (a) Incorporate the PILOT OPERATING PROCEDURES -PREFLIGHT (a) Incorporate the PILOT OPERATING PROCEDURES -PREFLIGHT

SLOWLY DURING LAST 5 GALLONS. RECHECK FOR FULL AFTER 2 MINUTES."

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

NOTE: Information concerning the existence of approved alternative

96-12-22 R AD NUMBER		Note	ad		9237 TREGISTRAT	AIRCRAF
	apters	lter Ada	Oil Fil		HON	AIRCRAF
		del/Serial No:_	Front Rear Engine Mo	Right	ine: 🗌 Left [If Multi-eng
AUTHORIZED SIGNATURE & NUMBER	DUE AT DATE, TACH, OR RECORDING METER TIME	NEXT COMPL TOTAL TIME	METHOD OF COMPLIANCE	TACH OR RECORDING METER TIME AT COMPL	TOTAL TIME AT COMPL	DATE
		ed	NA NA Instill			
		1 7				

1250417-(all dash numbers), 1250418-(all dash numbers), 1250921-(all dash numbers), and 1250922-(all dash numbers), installed on, but not limited to, the following: (1) Cessna Models 100, 200, 300, and 400 Series airplanes (all serial numbers), certificated in any category, that are equipped with at least one Teledyne Continental Motors (TCM) engine.

value is within the limits of 50 through 60 foot pounds. (3) If evidence of oil leakage is found or the torque is not within the 50 through 60-foot pound limit, prior to further flight, remove the adapter and filter assembly, and: (1) Inspect the threads of the adapter assembly and engine for signs of damaged or cracked threads; and

AIRCRAF	CEYEYI TSERIAL NO 210N		Continental/F	Rolls-Ro	oyce Eng	gine
TYPE AI	RCRAFT					
DATE	TOTAL TIME	TACH OR RECORDING METER TIME AT COMPL	METHOD OF COMPLIANCE	ODEL/SERIAL NO: NEXT COMPL TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	AUTHORIZED SIGNATURE & NUMBER
9/10/98			c/we of			
-			Engine hog #1			
						10 1966 AwoTech Publications, Inc., All rights reserved
a state of the sta	- AA 5775		E-08. Supersedes AD 87-23-08. al Motors (TCM) 10-360, LTSIO	crankshaft	in accordance	e 1996 AwoTech Publications, Inc., All rights reserved conduct an ultrasonic inspection of the with the procedures specified in TCM 10, dated August 15, 1996, and, if necessary,

LIO-520, LTSIO-520 and TSIO-520 series reciprocating engines with

serial number of 901203H and lower; and Rolls-Royce, plc IO-360 and

senal number or 301203H and lower, and Holis-Hoyce, pic 10-360 and TSIO-360 series reciprocating engines with any serial number. These engines are installed on but not limited to the following aircraft: Raytheon (formerly Beech) models 95-C55, 95-C55A, D55, D55A, E55, E55A, 58, 58A, 58P, 58PA, 58TC, 58TCA, S35, V35, V35A, V35B, E33A, E33C, 35-C33A, 36, A36, F33A, F33C and A36TC; Bellanca model 17-30A; 35-C33A, 36, A36, F33A, F33C and A36TC; Bellanca model 17-30A;

Cessna models 172XP, A185, A188, T188C, 206, T206, 207, T207, 210,

Cessna models 17207, A167, A16

(c) The ultrasonic inspection of the crankshaft must be performed by a non-destructive test (NDT) ultrasonic (UT) Level II inspector who is qualified under the guidelines established by the American Society of Nondestructive Testing or MIL-STD-410 or FAA-approved equivalent, or must be trained by TCM personnel or their designated representative on how to accomplish and conduct this inspection procedure. The person approving the engine for return to service is required to verify that the UT inspection was accomplished in accordance with the requirements of this paragraph.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office. Operators FORMS (FAA

21064 AIRCRAFT SERIA T 210, TYPE AIRCRAFT	L NO.		Continental Er	ngine]
f multi-engine: [] Le	ft 🛛 Right 🗋 F	ront 🗌 Rear	Engine	/odel/Serial	-
COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER	-
			NA NO STC		

Teledyne Continental Motors with STC SE8594SW: Priority Letter issued on December 23, 1997. Docket No. 97-ANE-48-AD.

Applicability: Teledyne Continental Motors (TCM) IO-520-A, -B, -BA, -C, -CB, -D, -E, -F, -K, -L, -M, -MB, -J; TSIO-520-A, -B, -D, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -R, -T, -U, -UB, -AF, -CE, -VB, -WB, -NB, -LB, -KB, -JB, -EB, -DB, -BB; O-470-B, -G, -K, -L, -M, -P, -R, -S, -U; IO-470-C, -D, -E, -F, -G, -H, -L, -M, -N, -P, -R, -S, -U; IO-470-C, -D, -E, -F, -G, -H, -L, -M, -N, -P, -R, -S, -U; and IO-550-B, -C, and -G series reciprocating engines, with Performance Engineering exhaust roller rocker arms, Part Number (P/N) PE92E, installed, in accordance with Supplemental Type Certificate (STC) SE8594SW. These engines are installed on but not limited to Cessna 180, 182, 185, 206, 207, 210, 310, 335, 340, 401, 402, 414; Raytheon (Beech) 33, 35, 36, 55, 58; Bellanca 17-30; New Piper PA-46; Fletcher FU-24A aircraft. roughness, and possible engine failure, accomplish the following:

(a) Within 25 hours time in service after the effective date of this AD, remove from service all Performance Engineering exhaust roller rocker arms, P/N PE92E, and replace with serviceable parts, as follows:

(1) For IO-520, TSIO-520, O-470, IO-470, and all IO-550 series engines except the IO-550-G, replace with serviceable TCM exhaust roller rocker arms, P/N 652130.

(2) For IO-550-G series engines, replace with serviceable TCM exhaust roller rocker arms, P/N 652966.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Special Certification Office. Operators shall submit their requests through an appropriate FAA FORMS (FAA)

FOF

T210N	1		AFM Limitation	
	OTAL TIME AT	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
17/48 9	64.0		Added puyes to APM	

adNote

Amendment 39-10773; Docket No. 97-CE-62-AD; Revises AD 98-05-14, Amendment 39-10375.

9234

IRCRAFT REGISTRATION NO 211 1 1 1 1 1

Applicability: Models T210N (serial numbers 21063641 through 21064897), P210N (serial numbers P21000386 through P21000834), and

21064997), P210N (serial numbers P21000386 through P21000834), and P210R (all serial numbers) airplanes; certificated in any category. NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions not been eliminated, the request should include specific proposed actions

to address it. Compliance: Required as indicated in the body of this AD, unless

already accomplished. To minimize the potential hazards associated with operating the airplane in severe icing conditions by providing more clearly defined "THE FOLLOWING WEATHER CONDITIONS MAY BE CONDUCIVE TO SEVERE IN-FLIGHT ICING:

98-5-14 Rev. 1 N

Visible rain at temperatures below 0 degrees Celsius ambient air temperature.

· Droplets that splash or splatter on impact at temperatures below 0 degrees Celsius ambient air temperature.

PROCEDURES FOR EXITING THE SEVERE ICING ENVIRONMENT: +

These procedures are applicable to all flight phases from takeoff to landing. Monitor the ambient air temperature. While severe icing may form at temperatures as cold as -18 degrees Celsius, increased vigilance is warranted at temperatures around freezing with visible moisture present. If the visual cues specified in the Limitations Section of the AFM for

identifying severe icing conditions are observed, accomplish the following: Immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the severe icing conditions in order to avoid extended exposure to flight conditions more severe than those for which the airplane has been certificated.

Avoid abrupt and excessive maneuvering that may exacerbate control difficulties,

· Do not engage the autopilot.

If the autopilot is engaged, hold the control wheel firmly and

FORM

98-14-3 N AD NUMBER		adNote		GISTRATION NO	_	
AlliedSignal KT-76A Transponder				21064641 AIRCRAFT SERIAL NO. T 210 N TYPE AIRCRAFT		
	AUTHORIZED SI	METHOD OF COMPLIANCE	TACH OR RECORDING METER TIME	TOTAL TIME AT COMPLIANCE	COMPLIANCE DATE	
SIGNATURE & NUMBER						
SIGNATURE & NUMBER		NA by SN#	AT COMPLIANCE	964.0	12/7/48	
SIGNATURE & NUMBER		NA by SN#		964.0	12/7/48	

Amendment 39-10637; Docket No. 97-CE-30-AD.

Applicability: AlliedSignal KT 76A Air Traffic Control (ATC) transponders; part number (P/N) 066-1062-00/10/02; serial numbers 93,000 through 109,999, as installed on, but not limited to the following airplanes (all serial numbers), certificated in any category:

Cessna Aircraft Company: 172, 182, R182, T182, 206,

P206, U206, TP206, 210, T210, P210, 310, E310, T310, and

421 series airplanes. Twin Commander Aircraft Company: 500, 520, 560, 680, 681, 685, 690, 695, and 720 series airplanes.

The New Piper Aircraft Corporation: PA-31, PA-32,

and PA-34 series airplanes. Raytheon Aircraft Company: E33, F33, G33, 35, J35, K35, L35, K35, M35, P35, S35, V35, 36, A26, B36, D55, E55,

56, A56, 58, 58A, 95, B95, D95, and E95 series airplanes.

Mooney Aircraft Corporation: M20 series airplanes. McDonnell Douglas Helicopter Company: Model 500N .

(a) Replace the two resistor network modules, RM401 a RM402, with new glass-coated parts in accordance with the MODIFICATION PROCEDURE section of AlliedSignal Service Bulletin SB KT 76A-7, dated July 1996. When accomplished, this replacement is referred to as Mod 7.

(b) As of the effective date of this AD, no person may install an AlliedSignal KT 76A ATC transponder; part number (P/N) 066-1062-00/10/02; serial numbers 93,000 through 109,999, in an aircraft without first incorporating Mod 7 as specified in paragraph (a) of this AD.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of

FORMS

the compliance time that provides an equivalent level of safety may be approved by the Manager, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Mid-Continent

N94237 AIRCRAFT REGISTRATION N 21064641 AIRCRAFT SERIAL NO. T210 N TYPE AIRCRAFT	adNote	98-21-21 Rev. 1 N/M AD NUMBER	
21-21, Amendment 39-10844. Applicability: Electric infla accordance with the applicable or through field approval, that a following aircraft: AeroTech Note: The a Airworthiness Directive (AD) original AD from the FAA has this adNote™ for easier read! NOTE 1: This AD applies preceding applicability provision seals installed, regardless of will	table door seals, installed either in supplemental type certificate (STC) re installed on, but not limited to, the applicability provision for this that was in this location in the been moved to the reverse side of ing. to each airplane identified in the that has the affected inflatable door atternative mettra and (b) of this one of these co- original equipment (c) One of alternative mettra and (b) of this one of these co- original equipment (c) One of these co-	AUTHORIZED SIGNATURE & NUMBER AUTHORIZED SIGNATURE & NUMBER December 2012 Annotation and a served Destantive difference between this AD and AD 98-21- dition of the alternative method of compliance aragraph (c) of this AD. his AD only applies to those aircraft equipped with the also has the option of removing all provisions of the Bob sories inflatable door seals. With this in mind, the also has the option of removing all provisions of the Bob sories inflatable door seals or an FAA-approved is of a different design than the referenced Bob Fields minatable door seals. The following actions may be accomplished as an od of compliance to the requirements of paragraphs (a) AD. No further action is required by this AD as long as figurations remains incorporated on the aircraft. The following acting system in accordance with the ob Fields Acrocessories Service Bulletin No. BFA-001, Date	ADI RECURING ADDITIONAL

	AIRCRAFT RI	EGISTRATION NO.		ad	Note	98-23-1 N/M AD NUMBER
	AIRCRAFT SI			Vac. Pum	o Cou	pling
	TYPE AIRCR		Front II Poor		Engine Mod	del/Serial
	COMPLIANCE	Left Right TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME	METHOD OF COMP		AUTHORIZED SIGNATURE & NUMBER
			AT COMPLIANCE	NA RAP	to br	nnd
						e 1998 AeroTech Publications, Inc., All rights reserved
	kits, and couplin 1, that: 1. Have a	ty: The following hg kits, with flexib date code resem nufacture date of talled in, but no , certificated in a AD:	bling a clockfa either "12/97" o t limited to, th any category,	t number (P/N) B1-19- ce on the coupling and or "5-6/98"; and he following aircraft or that are listed in the	flexible P/N 35(No. 48, (b) availabl only;	later, replace any affected flexible coupling with P/N B1-7-3 coupling (part of Parker Hannifin flexible coupling kit, Airborne 0) in accordance with Parker Hannifin Airborne Service Letter dated October 20, 1998. If parts have been ordered from Parker Hannifin, but are not ble, accomplish the following: (1) Operate the aircraft in visual flight rules (VFR) conditions (2) Operate the aircraft during daytime hours only; and (3) When parts become available, replace the coupling prior flight
	Item Dry Air Pump Dry Air Pump Dry Air Pump	Part Numbe 211CC 211CC-9 E211CC	1AP1 throu 11AN543 th and 2AP11	igh 2AP5 hrough 11AN642 hrough 7AP442	(c) any air conver	her flight. As of the effective date of this AD, no person shall install, on ircraft or engine, any of the affected Airborne dry air pumps, rsion kits, and coupling kits, with part number (P/N) B1-19-1 the coupling that has a date code resembling a clockface on the ng and indicating a manufacture date of either "12/97" or "5-
5	Dry Air Pump Dry Air Pump Dry Air Pump	212CW E212CW 215CC	1AP1 throu 12AN719 t	igh 7AP286 igh 7AP492 hrough 12AN940 through 9AP3510	6/98". (d) as aut) The owner/operator holding at least a private pilot certificate thorized by section 43.7 of the Federal Aviation Regulations (14
	Dry Air Pump Dry Air Pump	215CC-9 216CW	2AP1 throu	igh 7AP95 hrough 12AN660 through 10AP2695	the ex	43.7) may check the maintenance records to determine which with a stalled kisting dry air pump, conversion kit, or coupling kit was installed odified since January 1, 1998. If the dry air pump, conversion kit, pulling kit was not installed or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled or modified since January 1, 1998, the maintenance of the stalled stalled or modified since January 1, 1998, the maintenance of the stalled stall

21064	GISTRATION NO.		adNote	AD NUMBE
T210	N		Continental Eng	ine
	Left DRight	E Front E Rear	Engine Model/Serial	
DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
-128/99		11814 TS	of 1027,7 Tuch	
			Engre has HI	
	A CONTRACTOR OF		- 1 -11	

Amendment 39-11290. Docket No. 99-NE-28-AD. Supersedes AD 99-09-17. Issued August 30, 1999.

Applicability: Teledyne Continental Motors (TCM) O-470, IO-470, TSIO-470, IO-520, TSIO-520, LTSIO-520, IO-550, TSIO-550, TSIOL-550, series new and rebuilt engines manufactured between January 1, 1998, and December 31, 1998, listed by serial number (S/N) in TCM Mandatory Service Bulletin (MSB) 99-3C, dated July 27, 1999. Also, GTSIO-520 series engines, listed by S/N in TCM Critical Service Bulletin (CSB) 99-6A dated July 21, 1999. This airworthiness directive (AD) is also applicable to any other TCM O-470, IO-470, TSIO-470, IO-520, TSIO-520, LTSIO-520, IO-550, TSIO-550, TSIOL-550, and GTSIO-520 series engines that were overhauled by facilities other than TCM, and that have had replacement crankshafts installed that were sold individually by TCM and were manufactured or rebuilt between January 1, 1998, and December 31, 1998.

Note 1: Engine S/Ns can be found in logbooks or other

Note 3: The engines and crankshafts that are the subject of this AD were manufactured or rebuilt by TCM during 1998. The dates that engines and crankshafts were delivered, however, may not coincide with their dates of manufacture. For the engines identified in paragraphs (a) and (b) of this AD, TCM has already determined which engines have either a new or rebuilt suspect crankshaft installed, and identified those engines by engine S/N. Only for those engines identified in paragraphs (c) and (d) of this AD does crankshaft serial number play a role in determining the need for visual and UT inspections.

Note 4: The engine S/Ns listed in TCM MSB 99-3C and TCM CSB 99-6A contain only the numerical portion of the S/N. Rebuilt engines will have the letter "R" at the end of the six digit numerical portion. This letter "R" should be disregarded and only the six digit numerical sequence should be used for determination of applicability. Only TCM is authorized to rebuild TCM engines and they have not approved any other agency to perform that function.

(1) If a crack is found, replace the crankshaft with a

FORMS (F

2100	HE41		adNote	9
	10 N		Fuel Filter Stand	dpipe
TYPE AIRCR.	AFT			
COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
11/3/09	3976.8	1972.4	Mansure	CRS Q2AR 598 N
			AF log #3	
			0	

Amendment 39-11641; Docket No. 97-CE-114-AD.

Applicability: All serial numbers of the following airplane models, certificated in any category, including those manufactured in France that

have a capital "F" or "FR" prefix on the model number: Models 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L A150M, A-150L, A-A150L, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FA150M, FRA150L, FRA150M, 152, A152, F152, FA152, 172F, 172G, 172H, 172I, 172K, 172L, 172M, 172N, 172P, 172Q, R172E (T41), R172F (T41), R172G (T41), R172H (T41), R172J, R172K, 172RG, F172F, F172G, F172H, F172K, F172L, F172M, F172N, F172P, FR172E, FR172F, FR172G, FR172H, FR172J, FR172K, 177, 177A, 177B, 177RG, F177RG, 180H, 180J, 180K, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R/T182, 182R, R182, R182/TR182, A182J, A182K, A182L, A182N, F182P, F182Q, FR182, 185D, 185E, A185E, A185F, 188, A188, 188A, A188A, 188B, A188B, T188C, A-A188B, U206, U206A, TU206A, U206B/TU206B, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, TP206A, P206A, P206. U206G/TU206G, P206E/TP206E, 207/T207 P206D/TP206D, 207A/T207A, 210E, 210F, 210G, 210H, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N/T210N, T210F, T210G, T210H, T210J, P210N,

(b) If the standpipe does not measure a maximum length of 1.68 inches, prior to further flight, replace the filter strainer top assembly in accordance with the ACCOMPLISHMENT INSTRUCTIONS section in Cessna Single Engine SB No. SEB97-9, dated November 17, 1997; or Cessna Multi-engine SB No. MEB97-12, dated November 17, 1997, whichever is applicable.

(c) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may check the maintenance records to determine whether a Cessna part number (P/N) 0756005-2 top assembly, Cessna P/N 0756005-8 fuel strainer assembly, or a Cessna P/N 0756005-9 fuel strainer assembly was installed after December 12, 1996. Those parts that were shipped between December 12, 1996, and September 5, 1997, may have been manufactured with an internal tube installed to a depth less than specified and may become loose and dislodge from the strainer top assembly. If, by checking the maintenance records, the owner/operator can make an absolute determination that one of these parts is not installed or was installed prior to December 12, 1996, the requirements of paragraphs (a) and (b) of this AD do not apply. The owner/operator must make an entry into the aircraft records showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

FORMS (F

N992 AIRCRAFT REC AIRCRAFT SEP T 210 TYPE AIRCRAFT	DISTRATION NO. 1641 Nial No.	Te	adNote	2000-23-21 N/M AD NUMBER	
If multi-engine:		Front [] Rear	Engine	Model/Serial	
COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER	_
9/8/48		AT COMPLETING	c/we off		_
11			NA by SN Ft		
	-				
				© 2000 AeroTech Publications, Inc., All rights reserved	
2000-08-51. Dock Applicability This Airword Motors (TCM) IO 520, TSIO-520, reciprocating engi crankshaft that wa listed by engine at Bulletin (MSB) 00 Note 1: The	et 2000-NE-16-Al hiness Directive (/ .360, TSIO-360, L LTSIO-520, IO- nes that were as s manufactured be d crankshaft serial 5C, dated Octobe engines and crank.	AD) is applicable TSIO-360, O-470 550, TSIO-350 ssembled, rebuilt, tween April 1, 19 I number (SN) in r 10, 2000. shafts that are the	to Teledyne Continental h 10-470, TSIO-470, 10- and TSIOL-550 series (iii) or overhauled using a bit used. C TCM Mandatory Service October 10 (2) A subject of this AD were (iii)	Jse the specialized tools and equipment provided by TCM as listed in fTCM MSB 00-5C, dated October 10, 2000. You may use each rotobroach bit to obtain up to six core samples. e rotobroach after the sixth core sample, or before if the rotobroach tt with the maximum torque applied. Maintain a record of each core sample obtained with each rotobroach ontact TCM to obtain additional rotobroach bits. Do not exceed the torque limits specified in TCM MSB 00-5C, dated 0, 2000, when obtaining the core sample. After obtaining the results of the core sample evaluation, disposition the as follows: If TCM notifies you that the crankshaft is not serviceable, replace the with a serviceable crankshaft of the same part number before further	ADA REQUIRING ADDITIONAL COMPLIANCE


AIRCRAFT R 240 AIRCRAFT S	M9923Y AIRCRAFT REGISTRATION NO. 24021064641 AIRCRAFT SERIAL NO. T210N		adN Garmin G		2001-23-17 N AD NUMBER		
COMPLIANCE		TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIA		AUTHORIZED SIGNATUR	RE & NUMBER	-
			NA GNS 430		© 2001 AeroTec	h Publications, Inc., All rights reserved	-
applies to the (a)(1) of this A units are ins certificated in of this AD: (1) GNS	airplanes are GNS 430 unit AD and are inst talled in, but any category a 430 Units, pa	affected by is that are sp talled on aircr not limited f and presented art number (this AD? This AD	96300394, 96300451, 96300506, 96300585, 96300585, 96300628, 96300734, 96300734, 96300786, 96300846, 96300916,	96300484, 96300485, 9 96300513, 96300522, 9 96300587, 96300618, 9 96300641, 96300653, 96300756, 96300766, 96300766, 96300808, 96300831, 96300866, 96300870,	96300429, 96300437, 96300489, 96300504, 96300549, 96300563, 96300621, 96300624, 96300664, 96300713, 96300781, 96300785, 96300837, 96300842, 96300872, 96300899, 96300929, 96300941,	ADS REQUIRING ADDID

N997 AIRCRAFT RE 21044			adNote	
AIRCRAFT SE T210 TYPE AIRCRA			Horizontal Stabili Attach Brackets	
COMPLIANCE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
11/3/09	3976.8	AT COMPLIANCE	NA Not inshilled	FAA ERS QZARS98N
	20 12605: Do	cket No. 200	1-CE-42-AD (a) W	6 2002 AeroTech Publications, Inc. Al rights reserved
Amendment		cket No. 200	AD affec numbers	hat airplanes are affected by this AD? This its the following airplane models and seria that are certificated in any category:
ſ	Model		AD affec numbers Seri	hat airplanes are affected by this AD? This ts the following airplane models and seria
P206C an	Model d TP206C	P20	AD affec numbers Seri 6-0420 through P206-0519	hat airplanes are affected by this AD? This ts the following airplane models and seria that are certificated in any category:
P206C and P206D and	Model d TP206C d TP206D	P20	AD affec numbers Seri 6-0420 through P206-0519 6-0520 through P206-0603	hat airplanes are affected by this AD? This its the following airplane models and seria that are certificated in any category: al numbers
P206C and P206D and P206E and	Model d TP206C d TP206D d TP206E	P20 P20 P20 P20 U20	AD affec numbers Seri 6-0420 through P206-0519 6-0520 through P206-0603 600604 through P20600647, and 6-0915 through U206-1234	hat airplanes are affected by this AD? This its the following airplane models and seria that are certificated in any category: al numbers d P206-0001
P206C and P206D and P206E and U206C and	Model d TP206C d TP206D d TP206E d TU206C	P20 P20 P20 U20 U20	AD affec numbers 5eri 6-0420 through P206-0519 6-0520 through P206-0603 600604 through P20600647, and 6-0915 through U206-1234 6-1235 through U206-1444, U20	hat airplanes are affected by this AD? This its the following airplane models and seria that are certificated in any category: al numbers d P206-0001
P206C and P206D and P206E and U206C and U206D and	Model d TP206C d TP206D d TP206E d TU206C d TU206D	P20 P20 P20 U20 U20 U20	AD affec numbers Seri 6-0420 through P206-0519 6-0520 through P206-0603 600604 through P20600647, and 6-0915 through U206-1234 6-1235 through U206-1444, U20 601588 through 20601700	hat airplanes are affected by this AD? This its the following airplane models and seria that are certificated in any category: al numbers d P206-0001 0601445 through U20601587
P206C and P206D and P206E and U206C and U206D and	Model d TP206C d TP206D d TP206E d TU206C d TU206D d TU206D d TU206E	P20 P20 P20 P20 U20 U20 U20 U20 U20	AD affec numbers Seri 6-0420 through P206-0519 6-0520 through P206-0603 600604 through P20600647, and 6-0915 through U206-1234 6-1235 through U206-1444, U20 601588 through 20601700	hat airplanes are affected by this AD? This its the following airplane models and seria that are certificated in any category: al numbers d P206-0001 0601445 through U20601587 d U20602590 through U20603521

TYPE AIRCRAFT TOTAL TIME AT TACH OR RECORDER METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER DATE RECOMPLIANCE METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER DATE NA MO STC NA MO STC	N992 AIRCRAFT REGIS AURCRAFT SERIA T210,	64641 RIAL NO	adNote Brackett Air Filter	2002-26-3 N/M AD NUMBER
DATE COMPLIANCE RECORDEND METER TIME ATCOMPLIANCE METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER AUTHORIZED SIGNATURE & NUMBER METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER AUTHORIZED SIGNATURE & NUMBER METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER AUTHORIZED SIGNATURE & NUMBER METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER Brackett Aircraft Company: Amendment 39-12988; Docket 0.2002 Aerotech Publications, Inc., All rights reserved Brackett Aircraft Company: Amendment 39-12988; Docket following aircraft that are certificated in any category and incorporate Supplemental Type Certificate (STC) No. (a) What airplanes are affected by this AD? This AD (a) What airplanes are affected by this AD? This AD AUTHORIZED SUPPLEMENTAL Type Certificate (STC) No.				
Brackett Aircraft Company: Amendment 39-12988; Docket No. 2002-CE-38-AD. (a) What airplanes are affected by this AD? This AD (a) What airplanes are affected by this AD? This AD	The subscription of the second second	COMPLIANCE RECORDERO METER TIME	METHOD OF COMPLIANCE AUTHO	ORIZED SIGNATURE & NUMBER
Brackett Aircraft Company: Amendment 39-12988; Docket No. 2002-CE-38-AD. (a) What airplanes are affected by this AD? This AD (b) What airplanes are affected by this AD? This AD (c) Direct circles access air filter assemblies, part			IA NO STC	
Brackett Aircraft Company: Amendment 39-12988; Docket No. 2002-CE-38-AD. (a) What airplanes are affected by this AD? This AD (b) Brackett single screen air filter assemblies, part				
Brackett Aircraft Company: Amendment 39-12988; Docket No. 2002-CE-38-AD. (a) What airplanes are affected by this AD? This AD (b) What airplanes are affected by this AD? This AD (b) What airplanes are affected by this AD? This AD				
Cessna Model Serial Nos.	No. 2002-CE-38- (a) What air	8-AD. hiplanes are affected by this	AD? This AD SA71GL: ssemblies, part	are certificated in any category and

1/9423-						2003-13-17 N/M	
AIRCRAFT REGISTR	ATION NO.		adN	ote		AD NUMBER	
2106464 AIRCRAFT SERIAL N T210N TYPE AIRCRAFT	0.		T and W Pro	opeller	Inc.		
	e n Right D		r Propeller Model:		Serial No.:		1
DATE		TACH OR RECORDING METER TIME	TACH OR METHOD OF COMPLIANCE AUTHORIZ			D SIGNATURE & NUMBER	_
		AT COMPLIANCE	NA NO wor	+ bo	TIW		-
						2003 AeroTech Publications, Inc., All rights reserved	
AD. Effective Date (a) This airworth 2003. Affected Ads (b) None. Applicability: (c) McCauley Propeller Company, Inc., and	This AD a Systems, S Raytheon A	any, Inc., an 39-13219. Do we (AD) beco applies to Ha Sensenich Pr Aircraft Com returned to hat have a pro	cket No. 2003-NE- 13- mes effective July 18, artzell Propeller, Inc., opeller Manufacturing pany (formerly Beech service by T and W peller hub serial number	(i) Cr (ii) C (iii) Y (iv) S (v) B (vi) corrosion, (vii) (viii) (x) (x) (x) (x) (x)	pect for the following acks, orrosion, vicks, icratches, lade minimum dimer Chemical conversio Lack of chemical co Lack of paint on int Bolts incorrectly toro neorrect parts, Lecorrect mstallation	isions, n coat or paint or both applied o nversion coating, ernal surfaces, jued,	Ner Ner

AIRCRAFT	4234 REGISTRATION NO. 64641 SERIAL NO 10 M	_	dNote Cylinders	2004-8-10 N/M AD NUMBER
	Left Right Fron	t 🛙 Rear Engine	Model/Serial No:	
COMPLIANCE	COMPLIANCE RECO METE	CH OR DRDING METHOD OF COL IR TIME APLIANCE	MPLIANCE	AUTHORIZED SIGNATURE & NUMBER
		NA no S	TC	
				© 2004 AeroTech Publications, Inc., All rights reserved
Effective Date (a) This airw Affected Ads (b) None. Applicability (c) This AD NB, -VB, and -W	applies to Teledyne Contin B engines that are modified facturer and model	comes effective May 5, 2004. ental Motors (TCM) TSIO- 520- l by supplemental type certificate Table 1List of Airplane Engine model 1-520-C	325 HP or greater, (th IV, and VII reciproca model 520 and 53 reciprocating engine These engines are ins following Table 1:	turer and model Engine model



adNote

Hartzell Propeller, Inc., McCauley Propeller Systems, and Sensenich Propeller Manufacturing Company, Inc. Propellers: Amendment 39-14188. Docket No. 2003-NE-53-AD.

Effective Date

194237

AIRCRAFT REGISTRATION NO

(a) This airworthiness directive (AD) becomes effective August 17, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the Hartzell Propeller, Inc., McCauley Propeller Systems, and Sensenich Propeller Manufacturing Company, Inc. propeller models last returned to service by Southern California Propeller Service of Inglewood, CA., listed in the following Table 1:

are issuing this AD to prevent blade failure that could result in separation of a propeller blade and loss of control of the airplane. Compliance

2005-14-11 N/M

AD NUMBER

(h) You are responsible for having the actions required by this AD performed within 10 hours time-in-service after the effective date of this AD.

Required Actions

(i) Perform the actions specified in paragraph (j) of this AD on propeller models listed in Table 1 of this AD. You can find information on performing the actions in the applicable propeller manufacturer's service documentation.

(i) Perform the following actions:

(1) Disassemble,

			2006-3-8 N/M AD NUMBER
	AIRCRAFT REGISTRATION NO.	adNote	
	TYPE AIRCRAFT	Aero Advantage	ac. Pump
	If multi-engine: 🛛 Left 🗇 Right 🗇 Front 🗇	Rear Mfg./ Part I	ło.:
	COMPLIANCE TOTAL TIME AT TACH OF DATE COMPLIANCE METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
	AT COMPLA	Brand	
	Amendment 39-14472; Docket No. FAA-2005- 2005-CE-05-AD. When Does This AD Become Effective? (a) This AD becomes effective on March IO What Other ADs Are Affected by This Actio (b) None.	0, 2006. to, tt 1? SA1	e 2006 AeroTech Publications, Inc., All rights reserved t Airplanes Are Affected by This AD? c) This AD affects ADV200 series (part numbers (P/Ns) 211CC and ADV212CW) vacuum pumps installed on, but not limited e following aircraft that are certificated in any category. These vacuum ss can be installed under supplemental type certificate number 0126SC, through field approval, or other methods:
	Make		4-19-2, 14-19-3, 17-30, 17-31, 17-31TC, 17-30A, 17-31A, and 17-31ATC.
	Alexandria Aircraft, LLC Alliance Aircraft Group, LLC	7AC, 7E	JSAF U10D). CA, 7GC, 7GCA, 7GCAA, 7GCB, 7GCBC, 7HC, 7KC, 7KCAB, 8GCBC, and
-	American Champion Aircraft Corp	172P, 1 182M, 182N, 1 82N, 1 A152, 2	 IA, 172B, 172C, 172D, 172E, 172F, 172G, 172H, 172I, 172K, 172L, 172M, 172N, 172Q, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182P, 182Q, 182R, R182, T182, TR182, 172RG, R172E, R172F, R172H, R172J, 152, 10, 210-5 (205), 210-5A (205A), 210A, 210B, 210C, 210D, 210E, 210F, 210G, 10J, 210K, 210H, 2210M, 1210M, T210N, T210A, T210N, 10J, 210K, 210H, 210H, 180E, 180G, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 5A, 185B, 185C, 185D, 185E, 180, 180A, 180B, 180C, 207A, T207, T207A, 177RC

	GISTRATION NO.		adNot		AD NUMBER
	ON		Oxford Aviation	n Limited	
If multi-engine:	Left Right	□ Front □ Real	r Propeller Model:	Serial No.:	1
COMPLIANCE DATE	TOTAL TIME AT COMPLIANCE	TACH OR RECORDING METER TIME AT COMPLIANCE	METHOD OF COMPLIANCE	AUTHORIZE	D SIGNATURE & NUMBER
			NA no work		
					ublications, Inc., All rights reserved
AD. Effective Date (a) This airwo Affected Ads (b) None. Applicability (c) This AD a McCauley Propelle action (PN) and	rthiness directive (AD pplies to Hartzell Proj rr Systems (formerly serial number (SN) lis) becomes effective . peller Inc. (formerly Cessna Aircraft Co. ted in Table 1 or Ta	January 3, 2007. TRW Hartzell Propeller) and) propellers that have a part to d ble 2 of this AD, serviced by	(e) You are responsible for having compliance times specified unless th (f) For propellers listed by SN in November 2003, or overhauled by ber 2003, no further action is requi Propellers Listed by SN in Table (g) Before further flight, perform a termine if the propeller was involv (h) If the propeller was involv	the actions required by this AD performed within e actions have already been done. Table 1 or Table 2 overhauled or repaired by CSE y an FAA- approved propeller repair facility after red. 1 or Table 2 a document search of airplane and propeller records

charter businesses. Aerotech Note: Tables 1 & 2 that were in this position of the original Airworthiness Directive have been moved to facilitate compilation of this adNoteTM.

Unsafe Condition (d) This AD results from findings that CSE Aviation failed to perform some specific (d) This AD results from findings that CSE Aviation failed to perform some specific inspections and repairs. We are issuing this AD to detect potentially unsafe conditions that inspections and repairs. We are issuing from the hub and loss of control of the airplane.

ground strike, use the compliance schedule in the following Table 3 to perform the requirements specified in paragraph (j) or paragraph (k) of this AD as applicable.

<form><form><form><form><text><text><text><text></text></text></text></text></form></form></form></form>
OCMPLIANCE TOTAL TIME AT TACH OR METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER DATE COMPLIANCE AT COMPLIANCE AUTHORIZED SIGNATURE & NUMBER Image: An operation of the state o
Control COMPLIANCE RECORDING METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER DATE COMPLIANCE METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER I/I/II/IZ MATERIAN MATERIAN Authoritat I/I/II/IZ MATERIAN MATERIAN AUTHORIZED SIGNATURE & NUMBER I/I/II/IZ MATERIAN MATERIAN Authoritat Accodence 39-15005 Docket No FAA-2006-25948, Discourse Identifier 2006-NE-52-AD. Environmental Society Contents Identifier 2006-NE-52-AD. Clearies Date • This AD revises AD 2007-04-18. Sector Autor Society AD 2007-04-18. ************************************
Image: Provide and Prov
Amendment 39-15005 Docket No FAA-2006-29948, Directorate Identifier 2006-NE-32-AD. In an investiment 39-15005 Docket No FAA-2006-29948, Directorate Identifier 2006-NE-32-AD. In an investiment 39-15005 Docket No FAA-2006-29948, Directorate Identifier 2006-NE-32-AD. In an investiment 39-15005 Docket No FAA-2006-29948, Directorate Identifier 2006-NE-32-AD. Interview Advance Identifier 2006-NE-32-AD. Interview Advance Identifier 2007-04-33. Interview Advance Identifier 2005, part numbers (PhNs), SA470000-A, SA470000-A, SA470000-AD, SA55000-AD,
(b) This AD revises AD 2007-04-19. Applicability (c)-This AD applies to Superior Air Parts, Inc. (SAP), cylinder assemblies, manufactured between April 2005 and November 2005, part numbers (PNs): SA47000L-AI, SA4700L-AI, SA470L-AI, SA4
Applicability 0-330 -ABCDE.H (c).Tills AD applies to Superior Air Parts, Inc. (SAP), cylinder assemblies, manufactured 0-330 -ABCDE.H between April 2005 and November 2005, part numbers (PNis): SA47000-A1, SA47000-A1, SA47000-A1, SA47000-A1, SA47000-A1, SA52000-A20P, Installed -BDE. 0-100 AdDir.SAA70005-A1, SAA70005-A20P, SA470005-A21P, SA52000-A1, SA52000-A20P, Installed -ABCDE.H 0-100 -BDE. SA52000-A21P, SA52000-A22P, SA52000-A1, and SA55000-A20P, Installed -ABCDE.H 0-100 -BDE. No cylinder assemblies may be installed in the TCM engine models listed in the following Table 1 0-100 -ABCDE.H 0.100
(c) This AD applies to Superior Air Plats, Inc. (SAP), cylinder assemblies, manufactured 10-320 -8, -0, -8 between April 2005 and November 2005, part numbers, (PNs): SA47000L-AI, SA47000L- LiO-320 -8 ADJP, SA470005-AI, SA470005-A20P, SA47005-A20P, installed LiO-320 -8 Sa52000-A21P, SA52000-A22P, SA52000-A23P, SA55000-A20P, installed ADD-320 -8, -0, -8 in Teledyse Continental Motors (TCM) 470, 520, and 550 series reciprocating engines. These 0-360 -8, -0, -8 PN cylinder assemblies may be installed in the TCM engine models listed in the following 10-360 -8, -4. Table 1 LO-360 -A -8
A20F, SA470005-A1, SA470005-A20F, SA52000-A1, SA52000-A10F, A0-320 -A, -8, -6 SA52000-A21F, SA52000-A21F, SA52000-A1, and SA55000-A1, and SA55000-A10F, installed -A, -8, -6 in Teledyne Continental Motors (TCM) 470, 520, and 550 series reciprocating engines. These -A, -8, -6, -6 PN oplinder assemblies may be assailed in the TCM engine models insted in the following 10-360 -A, -8, -6, -0, -F, -0, -J Table 1 -0.360 -A, -8, -4, -0, -7 -0.360
SA52000-A21P, SA52000-A22P, SA52000-A23P, SA55000-A1, and SA55000-A20P, installed in Teledyne Continental Motors (TCM) 470, 520, and 550 series reciprocating magnes. These P:N cylinder assemblies may be installed in the TCM engine models listed in the following Table 1: D-360 -A. 8CDFQJ LO-360 -A. 8CDFQJ
PN cylinder assemblies may be sestailed in the TCM engine models listed in the following Table 1 Control Cont
Table 1. L0-360 -A
Engine Model H0-360 -C
O-4%
10-520 - A & BA C C B D & F J K L M B& MB 10-540 - A C D - M - T - M - W
T385-320 - AF. 8, 88, C, CE, D, DB, E, EB, G, H, L, IB, M, N, NB, AE(0.546 -D

21064641 AIRCRAFT SERIAL NO. T210N TYPE AIRCRAFT		
TTPE AINGRAFT	ternate Static Sou	urce Valve
COMPLIANCE TOTAL TIME DATE COMPLIANT	 METHOD OF COMPLIANCE	AUTHORIZED SIGNATURE & NUMBER
11/3/09 3976.1	NA by Value PN	CRS Q2AR598N
		© 2008 AeroTech Publications, Inc., All rights res
Amendment 39-15508; D dentifier 2008-CE-025-AD. Effective Date (a) This AD becomes eff Affected ADs (b) None.	2088 Note 1	



2008-26-10 corr. N/M AD NUMBER

Alternate Static Source Valve

TOTAL TIME AT COMPLIANCE TACH OR RECORDING METHOD OF COMPLIANCE **AUTHORIZED SIGNATURE & NUMBER** COMPLIANCE DATE METER TIME AT COMPLIANCE 11/3/04 Value FN CRS Q2AR598N NA

Amendment 39-15776; Docket No. FAA-2008-1328; Directorate Identifier 2008-CE-066-AD.

Effective Date

(a) This AD becomes effective on January 5, 2009.

N99231

TZION **TYPE AIRCRAFT**

AIRCRAFT REGISTRATION NO

1064641 AIRCRAFT SERIAL NO

Affected ADs

(b) This AD relates to AD 98-01-01, Amendment 39-10287 and AD 2008-10-02, Amendment 39-15508. These ADs can be found on the Internet at the following Web site: http://rgl.faa.gov/.

Applicability

(c) This AD applies to all serial numbers (S/Ns) of the airplanes listed in Table 1 of this AD, certificated in any category, that:

(1) Were initially delivered from the manufacturer between January 1, 1993, and March 31, 2008, unless the modification/rework required in AD 2008-10-02 has been done and you remain in compliance with that AD; or

number (P/N) 2013142-18 installed as a replacement part

© 2010 AeroTech Publications, Inc., All rights reserved

Note 1: The affected part was shipped from Cessna Parts Distribution (CPD) between January 1, 1993, and March 31, 2008.

Note 2: P/N 2013142-18 replaced P/Ns 2013142-9, -13, and -17,

Aerotech Note: Table 1 has been moved from this location in the Original FAA version of this Airworthiness Directive to page 3 to facilitate compilation of this adNote™.

Unsafe Condition

(d) This AD is the result of reports of improper installation of the part number identification placard on the alternate static air source selector valve. We are issuing this AD to prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators, which could cause the pilot to react to incorrect flight information and possibly result in loss of control. Compliance

(a) To address this problem you must do the following, unless already done.

	F 21064 RAFT SERIAL T 210 N AIRCRAFT	NO	Conti	inental	Engine	
If multi-en	gine: 🗆 Left	□ Right □ F	ront 🗆 Rear Engine M	odel:	Ser	rial No:
DATE	TOTAL TIME AT COMPL.	TACH OR RECORDING METER TIME AT COMPL	METHOD OF COMPLIANCE	TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	AUTHORIZED SIGNATURE & NUMBER
1/11/12	-		NA ER Lylindes			
-						
						© 2009. AeroTech publications, Inc., All rights reserved

(c) This AO applies to Teledyne Continential Motions (TCM) 10-320, T50-320, and IO-550 series reciprocating engines with SAP investment cast cylinder assemblies, part numbers (P/Ns) SA52000-A1, SA52000-A20P, SA52000-A21P, SA52000-A22P, SA52000-A23P, SA55000-A1, or SA55000-A20P, Installed. These engines are installed on, but not limited to, the airplanes listed in Table 1 of the APP in the A (For TCM 10-520, TSIO-520, and 10-550 series reciprocating engines with SAP investment cast cylinder assemblies, P/Ns SA52000- A1, SA52000-A20P, SA52000-A21P, SA52000-A22P, SA52000-A23P, SA55000- A1, or SA55000-A20P, replace the SAP cylinder head assembly at the first TBO after the effective date of this AD. Engines that were already overhauled may continue in service

FORMS (


	N9923 CRAFT REGIST 210646 CRAFT SERIAL	RATION NO.	-	dNot		2009-19-7 N/ ad NUM
TYP	T 210N		Conti	nental	Engine	
If multi-er	ngine: 🗆 Left	CRight CF	ront 🛛 Rear Engine Mo	odel:	Sei	rial No:
DATE	TOTAL TIME AT COMPL.	TACH OR RECORDING METER TIME AT COMPL.	METHOD OF COMPLIANCE	TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	AUTHORIZED SIGNATURE & NUMBER
1/11/12	_		NA 1223 Lylindy			
-						
-						
Amondma	of 39-16023 Do	ket No. FAA-	2009-0367; Directorate Identifier 2009-	(2)	For EQ3 cylinders w	© 2009 AeroTech publications, Inc., All rights reserved with fewer than 400 hours total time of operation

-					-	-	
				-	2010-7-8 N/M		
	AINCRAFT REGISTRAT	TON NO.	adNote	el "	AD NUMBER		
						1	
	AIRCRAFT SERIAL NO	Kol	ly Aerospace Tur	bochargers		-	
		Rei	ly Aerospace Tu	boonargoro			
	TYPE AIRCRAFT						
1 9 1 2	If multi-engine: U Left	D Right D Front D Rea	r Turbocharger Model/Ser	ial No			
	COMPLIANCE TOTAL TIME AT TACH DATE COMPLIANCE RECORD METER		METHOD OF COMPLIANCE	AUTHORIZED SIGNA	TURE & NUMBER	-	
	5/30/12 2	11 2145.3	INA S man.	AP 3182126			
	5/30/12 7	ch'	ant intilled				
				0.2010 Aero7	ecn Publications, inc., All rights veserved		
			to the second second				
		3. Docket No. FAA-20		ability This AD applies to certain seri	al numbers (S/Ns) of Kelly		
	Identifier 2009-NE-41 Effective Date		Aeros	nace Energy Systems, LLC (KAES	() rebuilt turbochargers listed	8 1 18	
	Ellective Date	ness directive (AD) become	mes effective April 19, by par	rt number (P/N) in the followin of S/Ns are listed in Table III	g Table I of this AD. The		
	(a) This airworthi			ns, LLC Service Bulletin (SB) No	0. 039 A. dated February 10.	82 1 12	
	(a) This airworth: 2010.			12) Pro Dervice Serieur family of	the set of the second se		
	2010. Affected ADs		2010.				
	2010.		2010.	-bochargers Affected			
	2010. Affected ADs (b) None.		e 1-Part Numbers of Rebuilt Tur	bochargers Affected 9019 406610-9020	406610-9021	LINE LINE	
	2010. Affected ADs (b) None. 406610-9005	406610-9015	e 1-Part Numbers of Rebuilt Tur	9019 406610-9020 9029 406610-9030	406610-9032	L TOOLUCE	
	2010. Affected ADs (b) None. 406610-9005 406610-9025	406610-9015 406610-9026	e 1-Part Numbers of Rebuilt Tur 406610-9018 406610- 406610-9028 406610- 408610-9021 409170-	9019 406610-9020 9029 406610-9030 9001 409680-9011	406610-9032 465680-9001	ANGETTON	
	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001	406610-9015 406610-9026 406990-9004	action action<	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002	406610-9032 465680-9001 465292-9004	Television (
5	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465680-9004	406610-9015 406610-9026 406990-9004 465680-9005	at -Part Numbers of Rebuilt Tur 406610-9018 406610- 406610-9028 406610- 408610-9021 406910- 465930-9002 465930- 46681-9001 46642-	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002	406610-9032 465680-9001 465292-9004 466642-9005	Table Party of the second seco	
	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 4655880-9004 465398-9002	406610-9015 406610-9026 406990-9004 465680-9005 407540-9003	at -Part Numbers of Rebuilt Tur 406610-9018 406610- 406610-9028 406610- 408610-9021 406910- 405930-9002 465930- 46681-9001 466642- 600573-9000* 600574-	9019 406610-5020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001*	406610-9032 465680-9001 465292-9004 466642-9005 600575-9002*	Transmission of the second sec	
51	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465680-9004 465398-9002 466304-9003	406610-9015 406610-9026 406990-9004 465680-9005 407540-9003 600572-9000* 600700-9001*	e 1-Part Numbers of Rebuilt Tur 406610-9018 406610- 406610-9028 406610- 408610-9001 409170- 465930-9002 4655930- 466881-9001 466642-	9019 406610-5020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001*	406610-9032 465680-9001 465292-9004 466642-9005	ANOLISIA I I I I I I I I I I I I I I I I I I	
51	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465388-9002 465398-9002 466304-9003 600576-9000*	406610-9015 406610-9026 406900-9004 465580-9005 407540-9003 600572-9000* 600700-9001* id: max base a CF prefix.	el-Part Numbers of Rebuilt Tur 406610-9018 406610- 406610-9028 406610- 406610-9001 409170- 465930-9002 465930- 466881-9001 466642- 600573-9000* 600803- 600803-9001* 600803-	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001* 9002* N/A	406610-9032 465680-9001 465292-9004 466642-9005 600575-9002* N/A	ADORTHOWN MAJO	
	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465680-9004 465398-9002 466304-9003 600576-9000* * P/Ns with an aster	406610-9015 406610-9026 406900-9005 405580-9005 407540-9003 600572-9000* 600700-9001* isk may have a CF prefix.	e 1-Part Numbers of Rebuilt Tur 406610-9018 406610- 408610-9028 406610- 408610-9001 409170- 465930-9002 465930- 466881-9001 466642- 600573-9000* 600574- 600803-9001* 600803- but not limited to, the (1)	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001* 9002* N/A	406610-9032 465680-9001 4655292-9004 466642-9005 600575-9002* N/A fication Office, has the authority	ADORTICINAL ANAZ	
	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465680-9004 465398-9002 466304-9003 600576-9000* * P/Ns with an aster These rebuilt turbu	406610-9015 406610-9026 406900-9004 465680-9005 407540-9003 600572-9000* 600700-9001* isk may have a CF prefix. ochargers are installed on, et in Table IV of Kelly Av	e 1-Part Numbers of Rebuilt Tur 406610-9018 406610- 408610-9028 406610- 408610-9001 409170- 465930-9002 465930- 466881-9001 466642- 600573-9000* 600574- 600803-9001* 600803- but not limited to, the (1)	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001* 9002* N/A	406610-9032 465680-9001 4655292-9004 466642-9005 600575-9002* N/A fication Office, has the authority	ADOTTONIL MAJOR REP ANCE	
	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465680-9004 465398-9002 466304-9003 600576-9000* * P/Ns with an aster These rebuilt turbu	406610-9015 406610-9026 406900-9004 465680-9005 407540-9003 600572-9000* 600700-9001* isk may have a CF prefix. ochargers are installed on, et in Table IV of Kelly Av	e 1-Part Numbers of Rebuilt Tur 406610-9018 406610- 408610-9028 406610- 408610-9001 409170- 465930-9002 465930- 466881-9001 466642- 600573-9000* 600574- 600803-9001* 600803- but not limited to, the (1)	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001* 9002* N/A	406610-9032 465680-9001 4655292-9004 466642-9005 600575-9002* N/A fication Office, has the authority	MAJOR REP ANCE	
	2010. Affected ADs (b) None. 406610-9005 406610-9025 407810-9001 465680-9004 465398-9002 466304-9003 600576-9000* * P/Ns with an aster These rebuilt turbo engines and aircraft lisis LLC SB No. 039 A, data	406610-9015 406610-9026 406900-9004 465680-9005 407540-9003 600572-9000* 600700-9001* isk may have a CF prefix. ochargers are installed on, et in Table IV of Kelly Av	e 1-Part Numbers of Rebuilt Tur 406610-9018 406610- 406610-9028 406610- 408610-9001 409170- 465930-9002 465930- 466881-9001 466642- 600573-9000* 6600574- 600803-9001* 600803- but not limited to, the rospace Energy Systems, to app the pro Specie	9019 406610-9020 9029 406610-9030 9001 409680-9011 9003 465292-9002 9001 466642-9002 9001* 600575-9001* 9002* N/A	406610-9032 465680-9001 465292-9004 466642-9005 600575-9002* N/A ification Office, has the authority ce for this AD if requested using	MAJOR REPAIR & ALTE	

AIRCRAFT REGISTRATION NO.	
21064641	
AIRCRAFT SERIAL NO. Teledyne Continental Engine	
T210N TYPE AIRCRAFT	000000
If multi-engine: Left Right Front Rear Engine Model/Serial No:	
COMPLIANCE TOTAL TIME AT COMPLIANCE TOTAL TIME AT COMPLIANCE METHOD OF COMPLIANCE AUTHORIZED SIGNATURE & NUMBER	MUNUUM
NA au lither propriet since Ott 1998	
© 2010 AeroTech Publications, Inc., All rights reserved	
Amendment 39-16309. Docket No. FAA-2009- 1156; Directorate Identifier 2009-NE-38-AD. Effective Date (a) This airworthiness directive (AD) becomes effective June 16, 2010. Affected ADs (b) This AD <u>supersedes</u> AD 2009-24-52. Applicability (c) This AD <u>supersedes</u> AD 2009-24-52. Applicability (c) This AD applies to all Teledyne Continental Motors (TCM) 240. 346. 360, 470, 520, and 550 series and Rolls-Royce Motors, Ltd (R-RM) 10-240-A reciprocating engines with hydraulic lifters, part numbers (P/Ns) 657913, 657915, or 657916, installed. These engines are installed on, but not limited to, general aviation airplanes.	
 engines are installed on, but not limited to, general a failed in applicability of this AD to (d) This AD results from TCM reporting another occurrence of rapid wear on the face of hydraulic lifters, P/Ns 657913, 657915, and 657916, and from the need to expand the applicability of this AD to to the TCM 346 series engines and the R-RM 10-240-A (l) Contact Anthony Holton, Aerospace Engineer, Atlanta (l) Contact Anthony Holton, Data Direction 1701	AUMAIA

anthony holton@faa.gov; telephone (404) 474-5567; fax (404) 474-

AIRCRAFT REGISTRATION NO		Technologies	2011-13-3 N/M AD NUMBER]
TYPE AIRCRAFT	Turboci	largers		
lf multi-engine: 🛛 Left 🗈 Rig	aht □ Front □ Rear Turbocharg	er Model/Serial No:		8
COMPLIANCE TOTAL TIME A DATE COMPLIANCE	ALL	ANCE AUTHORIZED S	IGNATURE & NUMBER	_
5/30/12	MA by mastacta	~		-
			AeroTech Publications, Inc., All rights reserved	
and Teledyne Continental Mi Engines: Amendment 39-16726 Identifier 2011-NE-03-AD. Effective Date (a) This AD is effective July I Affected ADs (b) None. Applicability (c) This AD applies to the reciprocating engines listed in, bh following Hartzell Engine Tecl TA3601, TAO401, TAO402, T THO867, and TEO659, installed: (1) Newly manufactured t series) before serial number H-N	he Lycoming Engines and TCM turbocharged put not limited to, Table I of this AD, with the chnologies, LLC (HET) turbocharger models (A0411, TA0413, T1879, T18A21, T18A44, turbochargers (otherwise known as the -0000 N1L00003, or rebuilt (otherwise known as the -	 (g) Unless already done, disassemble, affected by this AD as follows: Turbochargers With Between 0 and 10 (1) For affected turbochargers incluthours TIS on the effective date of this A turbocharger, clean the CHRA center turbocharger. Turbochargers With More Than 10 Ho (2) For affected turbochargers inclut TIS but less than 50 hours TIS on the effethours TIS, disassemble the turbocharger, and reassemble the turbocharger. (3) Use paragraphs 1 through 10 HOUSING section of Hartzell Engine TA, dated December 22, 2010, to othe cl. (4) The reference to Step 16 in proceedings. 	clean, and reassemble the turbochargers Hours TIS ding overhauls, with between 0 and 10 D, before further flight, disassemble the housing cavity, and reassemble the ars TIS But Less Than 50 Hours TIS ding overhauls, with more than 10 hours citive date of this AD, within the next 10 clean the CHRA center housing cavity, 0 of the CLEANING CHRA CENTER chnologies, LLC SB No. 040, Revision	ADY REDUKTIVAS AUDITIONAL COMPLUMICE FORMS (FAA FORM 337)



Lower Wing Spar Caps

COMPLIANCE DATE			
5/30/12	~ 4150	 Inspection SBL ST-DI	AP 3182126
			e 2012 Aeroliset Publications, Inc. 43 spris monores

adNote

Amendment 39-17053; Docket No. FAA-2012-0534; Directorate Identifier 2012-CE-015-AD

(a) Effective Date

N99234

TZION

ARCRAL'T REGISTRATION NO 2106464 RAFT SERIAL NO

This AD is effective June 5, 2012.

- (b) Affected ADs
 - Nore

(c) Applicability

This AD applies to the following Cessna model airplanes listed in paragraphs (c)(1) through (c)(13) of

this AD, certificated in any category (1) 210G: Serial numbers (S/Ns) 21058819 through

- 21058936 (2) T210G: S/Ns T210-0198 through T210-0307,
 - (3) 210H; S/Ns 21058937 through 21059061,
 - (4) T210H. S/Ns T210-0308 through T210-0392,

 - (5) 210.J: S/Ns 21059062 through 21059199, (6) T210J: S/Ns 21058140, and T210-0393 through T210-

(7) 210K and T210K: S/Na 21059200 through 21059502, 0454. (8) 210L and T210L: S/Ns 21059503 through 21061041,

(8) 210L and through 21061573, and 21061043 through 21061574 through

this AD), do the following in accordance with Cessna Single Engine Service Letter SEL-57-01, Revision 1, dated May 9, 2012:

(i) Before further flight after June 5, 2012 (the effective date of this AD), do an external visual inspection of the outer skin underneath the main spar cap fitting between wing station (WS) 25.25 and WS 45.00 for cracks.

(ii) If no cracks are found during the inspection required in paragraph (g)(1)(i) of this AD, within the next 5 hours TIS after June 5, 2012 (the effective date of this AD), do an internal visual inspection of the wing lower main spar caps between WS 25.25 and WS 45.00 for cracks.

(2) For airplanes with 5,000 hours TIS or more, but less than 10,000 hours TIS as of June 5, 2012 (the effective date of this AD), within the next 25 hours TIS after June 5, 2012 (the effective date of this AD), do an internal visual inspection of the wing lower main spar caps between WS 25.25 and WS 45.00 for cracks in accordance with Cessna Single Engine Service Letter FORMS (FAA FORM 337)


adlog		Applicable Airworthiness Directives	ID Hos Page Nos Contec	276/345	
AD NOMINE IN	Inn		and the second division of the second divisio	the PER STATISTICS	1000
		ENGINETATE TELO-520-R	-		-
		Tota sta to			C
	-	PROPELLERIATE DIAIACADI			-
	-	and the second s	State of the state		T
		MADNETOLATI Bendix 'S' Series	1000		F
	- 20020		2. 10100		L
71-09-0781	(n)	EXHAUST DAS ENTERING CADIN	1985 P. 1988		
76-07-1281	1491	RENDIX IONITION SWITCH	12-12-12-12-12-12-12-12-12-12-12-12-12-1		
77-05-04	100	CONTINENTAL ENGINE	Part Barris		
91-24-06	348	CONTINENTM. ENGINE	1000		
82-13-01	K	RENDIX MADNETO			
02-20-01	M	BENDIX MAGNETO	-		
02-27-0281	M	RECALLEY PROPELLER	20 24216		
64-26-02	(P)	INDUCTION AIR FILTERS	The state of the		
86-01-06	1164	AIRBORNE DRY AIR FUMP			
R6-05-02	1115	UNITED INSTRUMENTS ALTIMETER	74 2 123		
94-13-04R3	Jun	CONTINENTAL ENGINE	10000		
86-19-11	K	FUEL RESERVOIR OUICE DRAINS	100 100 100 100 100 100 100 100 100 100		
87-17-05	N	AN-SAF SEAT BELT ASSEMBLIES	and the state		
08-03-06	N	CONTINENTAL OIL FILTERS	and the loss		
88-22-07	N	AEROQUIP HOSE ASSEMBLIES	-		
91-19-03	15	CHAMPION OIL FILTER	S. Contraction		
93-05-04	(R)	IGNITION SHITCH			
93-08-17	M	CONTINENTAL ENGINE	180 184.000		
93-10-02	X	CONTINENTAL ENGINE	Mar Call		
93-13-09	K	AIR INDUCTION HOSE FAILURE	12 11250		
94-01-03R2	N	BENDIX MAGNETO	73-07	-04	
24 06 02	The	TCH (BENDIX) MAGNETO	A	Contraction of the second	
PA-12-09	K	FUEL SYSTEM	92-24	-04	
26-12-22	K	OIL FILTER ADAPTERS			
97-26-17	K	CONTINENTAL/ROLLS-ROYCE ENGINE	87-23	-08	
01-00	W	CONTINENTAL ENGINE	and the state	1. 2. 1. 2. 1.	
-05-14R1	peri	AFR LIMITATION	the sources		
5-14-02	W	ALLIEDSTONAL ET-764 TRANSPONDEN		2 18- 7 4 B	
8-21-21R1	SHE	INFLATABLE DOOR SEALS		and the second	
	1 1	MAC, FLIMP COUFLIND		and the state	

Append Act Desired and active there is a subscription of the second o

dlog Model		Airworthiness Directives	ID No: 27838 Page No: 2 Date: 12/18/
AD NUMBER	TYPE-	SUBJECT	Supersedes AD Numb
		ENGINE(s): TSIO-520-R	
		PROPELLER(s): D3A34C402	
		MAGNETO(s): Bendix 'S' Series	
99-19-01	N	CONTINENTAL ENGINE	99-09-17
2000-06-01	W	FUEL FILTER STANDPIPE	The second second
2000-23-21	DHM	TELEDYNE CONTINENTAL ENGINE	2000-08-51
2001-23-17	W	GARMIN GNS 430	
2002-07-01	MM	HORIZONTAL STABILIZER ATTACH BRACKETS	
2002-26-03	NIM	BRACKETT AIR FILTER	
2003-13-17	NM	T AND W PROPELLER INC.	
2004-08-10	NH	ECI CYLINDERS	
2005-14-11	MM	SOUTHERN CALIFORNIA PROPELLER SERVICE	
2006-03-08	NM	AERO ADVANTAGE VAC. PUMP	
2006-24-07	MIL	OXFORD AVIATION LIMITED	
2007-04-19R1	I DY	SUPERIOR CYLINDERS	
2008-10-02	DHM	ALTERNATE STATIC SOURCE VALVE	
2008-26-100	DHM	ALTERNATE STATIC SOURCE VALVE	
2009-16-03	NR	CONTINENTAL ENGINE	
2009-19-07	DIR	CONTINENTAL ENGINE	1
2010-07-08	MM	KELLY AEROSPACE TURBOCHARGERS	
2010-11-04	NM	TELEDYNE CONTINENTAL ENGINE	2009-24-52
2011-10-09	R	SEAT RAILS & SEAT ASSEMBLIES	87-20-03R2
2011-13-03	DIM	HARTZELL ENG. TECHNOLOGIES TURBOCHARGER	K\$
2012-10-04	Prist	LOWER WING SPAR CAPS	
2012-10-52	N	HARTZELL ENG. TECHNOLOGIES TURBOCHARGER	R
		The second s	
			1
		P. STR. C.S. Contraction of the Street of the Street	
		The second s	
	1		
	1		
and the second s			and the second second second

"Type of AD (acting subscribers - this designation appears in the upper right corner of each adNote page): "Type of AD (acting subscribers - this designation appears in the upper right corner of each adNote page): N-Non-Repetitive. R - Repetitive. NM - Non-Repetitive, but has more than one compliance requirement. N-Non-Repetitive. Repetitive or Non-Repetitive, depending on the method of compliance.

0



If multi-engi	ine: 🗆 Left I	Right Fr	ont 🗆 Rear Engine Mo	odel:	Se	erial No:
DATE	TOTAL TIME AT COMPL.	TACH OR RECORDING METER TIME AT COMPL.	METHOD OF COMPLIANCE	NEXT COMPL TOTAL TIME	DUE AT DATE, TACH, OR RECORDING METER TIME	AUTHORIZED S
3/28/14			MA- Cont. Glulos			
						© 2014 AeroTech pu

AD.



Continental Engine

Amendment 39-17801; Docket No. FAA-2007-0051; Directorate Identifier 2007-NE-37-


* *

* * .*

publications, Inc., All rights reserved

(ii) To check the cylinder, apply a 2-percent scapy water solution to the side of the leaking cylinder.

(iii) If you see air bubbles, indicating air leakage, on the side of the cylinder head,



SIGNATURE & NUMBER

Applicable	
Airworthiness Directives	

THE dlog aircra Aircra Mateou syst	AFT ENANCE RDKEEPING EM	Applicable Airworthiness Directives	ID No: Page No:	27838 1
Mode	1: T2	10N, S/N: 21064641, Tail No: N9923Y	Date:	12/18/13
AD NUMBER	TYPE*	SUBJECT	Supersed	es AD Number N
		ENGINE(s): TSIO-520-R		
		PROPELLER(s): D3A34C402		
	-	MAGNETO(s): Bendix 'S' Series		
71-09-07R1	3	EXHAUST GAS ENTERING CABIN		
76-07-12R1	NE	BENDIX IGNITION SWITCH		
77-05-04	, NŔ	CONTINENTAL ENGINE		
81-24-06	NE	CONTINENTAL ENGINE		······
32-13-01	R	BENDIX MAGNETO		
32-20-01	N	BENDIX MAGNETO		
32-27-02R1	N	McCAULEY PROPELLER		
34-26-02	(\hat{R})	INDUCTION AIR FILTERS		
36-01-06	Nix	AIRBORNE DRY AIR PUMP		
86-05-02	MM	UNITED INSTRUMENTS ALTIMETER		
36-13-04R3	NR	CONTINENTAL ENGINE		
86-19-11	.*	FUEL RESERVOIR QUICK DRAINS		
37-17-06	N	AM-SAF SEAT BELT ASSEMBLIES		
38-03-06	.N	CONTINENTAL OIL FILTERS		
38-22-07	N	AEROQUIP HOSE ASSEMBLIES		
91-19-03	N	CHAMPION OIL FILTER		
23-05-06	Ŕ	IGNITION SWITCH		
23-08-17	N	CONTINENTAL ENGINE		
23-10-02	_D+*	CONTINENTAL ENGINE		
23-13-09	X	AIR INDUCTION HOSE FAILURE		
94-01-03R2	N	BENDIX MAGNETO	73-07	'-04
94-06-09	N	TCM (BENDIX) MAGNETO		
94-12-08	M	FUEL SYSTEM	92-26	04
96-12-22	F	OIL FILTER ADAPTERS		
97-26-17	Ŕ	CONTINENTAL/ROLLS-ROYCE ENGINE	87-23	-08
28-01-08	N	CONTINENTAL ENGINE		•
28-05-14R1	DAM	AFM LIMITATION		
/8-14-03	M	ALLIEDSIGNAL KT-76A TRANSPONDER		
98-21-21R1	JYM	INFLATABLE DOOR SEALS		
	WM	VAC. PUMP COUPLING		

FAX NO: (631) 765-9359

TEL: (631) 765-9375

TEL: (800) 235-6444

Other Ander Beich Price to

N-Non-Repetitive. R-- Repetitive. NM--Non-Repetitive, but has more than one compliance requirement. NR-Can be either Repetitive or Non-Repetitive, depending on the method of compliance.

Applicable	
Airworthiness Directives	

	: T2	10N, S/N: 21064641, Tail No: N9923Y	Date:	12/18/1	3
AD NUMBER	TYPE*	SUBJECT	Supersedes	s AD Number	N
		ENGINE(s): TSI0-520-R		·····	1
		PROPELLER(s): D3A34C402			+
		MAGNETO(s): Bendix (S' Series			
					+
99-19-01	N	CONTINENTAL ENGINE	99-09-	-17	
2000-06-01	N	FUEL FILTER STANDPIPE			
2000-23-21	<u>DH</u> M	TELEDYNE CONTINENTAL ENGINE	2000-0	08-51	
2001-23-17	M.	GARMIN GNS 430			
2002-07-01	NM	HORIZONTAL STABILIZER ATTACH BRACKETS			
2002-26-03	NIT	BRACKETT AIR FILTER			
2003-13-17	NM	T AND W PROPELLER INC.			
2004-08-10	NM	ECI CYLINDERS			
2005-14-11	, MM	SOUTHERN CALIFORNIA PROPELLER SERVICE			
2006-03-08	NPT	AERO ADVANTAGE VAC. PUMP			
2006-24-07	DAM	OXFORD AVIATION LIMITED	<u></u>		
2007-04-19R1	N	SUPERIOR CYLINDERS			
2008-10-02	NM	ALTERNATE STATIC SOURCE VALVE			
2008-26-100	juhri -	ALTERNATE STATIC SOURCE VALVE			
2009-16-03	NR	CONTINENTAL ENGINE			
2009-19-07	NE	CONTINENTAL ENGINE			
2010-07-08	MM	KELLY AEROSPACE TURBOCHARGERS			
2010-11-04	NM	TELEDYNE CONTINENTAL ENGINE	2009-2	24-52	
2011-10-09	(12)	SEAT RAILS & SEAT ASSEMBLIES	87-20-		
2011-13-03	Jura	HARTZELL ENG. TECHNOLOGIES TURBOCHARGERS			·
2012-10-04	, MM	LOWER WING SPAR CAPS			
2012-10-52	tu	HARTZELL ENG. TECHNOLOGIES TURBOCHARGER			
111-5-24	NP.	and the second			

FAX NO: (631) 765-9359

TEL: (631) 765-9375 TEL: (800) 235-6444

*Type of AD (*adlog* subscribers—this designation appears in the upper right corner of each *adNote* page): N—Non-Repetitive. R—Repetitive. NM—Non-Repetitive, but has more than one compliance requirement. NR—Can be either Repetitive or Non-Repetitive, depending on the method of compliance.

	adlog Ancenation	ANCE KEEPING	Applicable Airworthiness Directives	ID No: 27838 Page No: 1 Date,12/20/2019	-
	Model:	1210	N, S/N: 21064641, Tail No: N9923Y	Supersedes AD Number	1000
	AD NUMBER	TYPE*	SUBJECT	Supersedes / 12 / 14	T
			ENGINE: TSIO-520-R		T
			PROPELLER: D3A34C402		T
			MAGNETO: BENDIX-S		
	71-09-07R1	B	EXHAUST GAS ENTERING CABIN		
	76-07-12R1	NR	BENDIX IGNITION SWITCH		
	77-05-04	NR	CONTINENTAL ENGINE		
359	81-24-06	NR	CONTINENTAL ENGINE		
2-9	82-13-01	NR	BENDIX MAGNETO		
176	82-20-01	X	BENDIX MAGNETO		
531)	82-27-02R1	M	MCCAULEY PROPELLER		
0: (84-26-02	R	INDUCTION AIR FILTERS		
FAX NO: (631) 765-9359	86-01-06	NAT	AIRBORNE DRY AIR PUMP		
FA	86-05-02	NM	UNITED INSTRUMENTS ALTIMETER		T
	86-13-04R3	R	CONTINENTAL ENGINE		
	86-19-11	N/	QUICK-DRAIN INSTALLATION		T
	87-17-06	N	AM-SAF SEAT BELT ASSEMBLIES		T
	88-03-06	N	CONTINENTAL OIL FILTERS	61-03-02	
	88-22-07	X	AEROQUIP HOSE ASSEMBLIES		
919	91-19-03	N	CHAMPION OIL FILTER	1159-11-12	T
IEL: (631) 765-93	93-05-06 (R)	IGNITION SWITCH	1 12-19-10-11	T
76	93-08-17	N	CONTINENTAL ENGINE		
331)	93-10-02	N	CONTINENTAL ENGINE		
	93-13-09	×	AIR INDUCTION HOSE FAILURE		
-	94-01-03R2	N	BENDIX MAGNETO	73-07-04	
_	94-06-09	X	TCM (BENDIX) MAGNETO		
3444	94-12-08	N	FUEL SYSTEM	92-26-04	
(800) 235-6444	96-12-22	₿∕	OIL FILTER ADAPTERS		T
0) 2	97-26-17	₿⁄	CONTINENTAL/ROLLS-ROYCE ENGINE	87-23-08	t
(800	98-01-08	W	CONTINENTAL ENGINE		
TEL	98-05-14R1	NHM	AFM LIMITATION		1
F	98-14-03	X	ALLIEDSIGNAL KT-76A TRANSPONDER		+
	98-21-21R1	MM	INFLATABLE DOOR SEALS		
	98-23-01	N	VAC. PUMP COUPLING		
	99-19-01	N	CONTINENTAL ENGINE	99-09-17	+
		1		00 00 II	

*Type of AD (*adlog* subscribers—this designation appears in the upper right corner of each *adNote* page): N—Non-Repetitive. R—Repetitive. NM—Non-Repetitive, but has more than one compliance requirement. NR—Can be either Repetitive or Non-Repetitive, depending on the method of compliance.

**Not applicab



J/Á

adlog	ENANCE IDKEEPING	Applicable Airworthiness Directives	ID No: 27838 Page No: 2	
Model:	T210	N, S/N: 21064641, Tail No: N9923Y	Date12/20/2019	1
AD NUMBER	TYPE*		Supersedes AD Number	1
		ENGINE: TSIO-520-R		
	10 10 10 10	PROPELLER: D3A34C402		
		MAGNETO: BENDIX-S		
2000-06-01	N	FUEL FILTER STANDPIPE		100
2000-23-21	NM	TELEDYNE CONTINENTAL ENGINE	2000-08-51	
2001-23-17	N	GARMIN GNS 430		
2002-07-01	NM	HORIZONTAL STABILIZER ATTACH BRACKETS	1 10 March 10	
2002-26-03	NM	BRACKETT AIR FILTER		
2003-13-17	NM	T AND W PROPELLER INC.		
2004-08-10	NM	ECI CYLINDERS	2005-26-10	T
2005-14-11	NM	SOUTHERN CALIFORNIA PROPELLER SERVICE		T
2006-03-08	-NM	AERO ADVANTAGE VAC. PUMP		I
2006-24-07	NM	OXFORD AVIATION LIMITED		İ
2007-04-19R1	N	SUPERIOR CYLINDERS		I
2008-10-02	MAL	ALTERNATE STATIC SOURCE VALVE	State State	İ
2008-26-100	NM	ALTERNATE STATIC SOURCE VALVE		İ
2009-19-07	ł√R	CONTINENTAL ENGINE		İ
2010-07-08	TVM	KELLY AEROSPACE TURBOCHARGERS	11. 11. 11. 11. 11	İ
2010-11-04	NM	TELEDYNE CONTINENTAL ENGINE	2009-24-52	İ
2011-10-09	(R)	SEAT RAILS & SEAT ASSEMBLIES	87-20-03R2	İ
2011-13-03	MM	HARTZELL ENG. TECHNOLOGIES TURBOCHARGERS		
2012-10-04	NHM	LOWER WING SPAR CAPS		1
2012-10-52	×	HARTZELL ENG. TECHNOLOGIES TURBOCHARGER		1
2014-05-29	AR	CONTINENTAL ENGINE	2009-16-03	t
2016-16-12	NHM	ECi CYLINDERS		t
2017-04-06	MM	UNITED ALTIMETER		t
				ł
				ł
		Part Carl Line and the second s		t
			R. C. Barris	
			2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

N—Non-Repetitive. R—Repetitive. NM—Non-Repetitive, but has more than one compliance requirement. NR—Can be either Repetitive or Non-Repetitive, depending on the method of compliance.