N210PF

ANFRAME LOB # 4



AIRFRAME MAINTENANCE RECORDS



AIRFRAME MAINTENANCE RECORDS

					Log No. AF-4				
Aircraft Registration No									
Aircraft Mfg	DOSSNA	_ Model	210N	_ Serial No	121000018				
(Turbo Norm)									
Engine Mfg.	TCM	_ Model	D-55D-P	_ Serial No	1009768				
Engine Mfg.		_ Model		_ Serial No	. /				
	2				,				
Propeller Mfg.	artze11	_ Model _ H C	·J3YF, IRF	Serial No	JN,3388				
Hub Design No	HC, J	34F.	Hub Serial No)	JN.338B				
Blade Design No.	F806	83	Blade Serial N	No's. L 28	8708				
				L 29	3710				
				L 29	8711				
Propeller Mfg		_ Model		_ Serial No					
Hub Design No	-		Hub Serial No),					
Blade Design No.			Blade Serial N	No's					



AEROTECH PUBLICATIONS INC.

(All applicable information must be filled in)

www.adlog.com P.O. Box 1359 / Southold, NY 11971-0965 (631) 765-9375 1-800-235-6444

FAX: (631) 765-9359

NOTE; Add 15,2 TO TACK FOR AIC TT.

	Page No.	1F4-2							
	DATE	TOTAL TIME IN SERVICE	TACH -OR- RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK					
		5	TOTAL brought forward from previous page						
MAY	1 0 2017	3758.2	2743.0	New (#4) Dirfyame Log Instinted old Log (#3) Full (closed out & Placed IN Historical Logs Section (Front Pouch, 3 Rmg Zipper Folio/ Lobs)					
				Swink Aircraft Services 3332 Whitlow Creek Dr #R# 43677 Bishop, GA 30621					
MAY	1 0 2017	3758.2	3743.0	10 May 2017 N210PFP210N, sn# P21000018Tach; 3743.0A/C TT: 3758.2 hrs					
				 Replaced all 4 aileron rod end bearings #S1819-4 (crank to aileron) (L/H & R/H) with new parts (excessive play), checked aileron rigging and adjusted to correct for witness hole exposure on L/H side (detected pre replacement) 					
				2. Installed new # RA-D-18-1 central vacuum filter					
8				3. Installed new # P131364 Donaldson paper air filter (eng inlet air) (see AD#84-26-02, repl @ 500 hr intervals)					
				4. Installed new "Ram Acft" pn# 1396-2 magneto press ait filter.					
				5. Installed 2 new # ARB3-5-1 vacuum filters (regulator)					
				6. Replaced cabin fire extinguisher (empty) with new (H3R avn) 1.25 lb Halon 1211, pn#(amerex# A344)					
				7. Airworthiness Directices thru issue # 2017-10 complied, see A.D. report dated May 10, 2017					
				2 (SP)					
				7. (A.D. s, continued)					
			-	(a) AD# 81-23-03 (R2) exhaust system integrity, inspected and found "inconnel" exhaust components installedas long as all exhaust components (stacks, risers,crossover & collector) are retained as "inconnel parts" (not replaced with ANY stainless steel parts)the repetitive requirements for inspection per this A.D. are N/A					
				A.D. are N/A (b) AD# 11-10-09 seat track wear and seat pin engagement, insp per A.D. "G"(1) thru (10)each 100 hrs/annually, complied with, NO defects. (c) AD# 84-26-02 paper induction air filters, complied with by installing new "Donaldson" pn# P131364 element (ea 500 hrs)					
		<u>(</u>		(c) AD# 84-26-02 paper induction air filters, complied with by installing new "Donaldson" pn# P131364 element (ea 500 hrs)					
MAY I	1 0 2017			(d) AD# 93-05-06 ACS/ Gerdes ignition switches insp/test. P/C/W 6-12 @3358 A/C TT (parts a & b) kit # A3770 installed and lubed) repetitive portion not due until 5358. hrs TT.					
MAI [1 0 2017	5	SUB-TOTA						
		3758.7	TOTAL-Car	ry forward to next page Swink Aircraft Services					

3332 Whitlow Creek Dr Richan GA 30621

(antmued

