


Priebe Propeller Shop, Inc.



**3861 Co. Rd. 140
Findlay, Ohio 45840
1-800-553-7767**

Propeller Log Book

Owner Name Gary Todd

Address _____

Propeller Make Sensenich

Propeller Model 76EM855-0-60

Blade Model -

Hub Serial No. 13647K

Blade Serial No. 1 -

2 -

3 -

4 -

PITCH RANGE

High - Low -

Feather - Reverse -

Maximum Hours or Service Life between overhaul recommended by Mfg. 1000 Hrs. or -

years interval between overhauls. _____

SERVICEABLE

PROPELLER SENSENICH
UNIT MAKE

76EM8S5-0-60 13647K
MODEL SERIAL NUMBER

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repair are on file at this repair station under:

OWNER GARY TODD

WORK ORDER NO. 9646

DATE 5-7-91

Michael W. Baird
SIGNED FOR

Priebe Prop Shop, Inc.
3861 Co. Rd. 140
Findlay, Ohio 45840
419-299-3562
800-553-7767
FAX 419-299-3244
FAA Repair Station No. IC5R930M

PROPELLER LOG BOOK



*SENSE***NICH** PROPELLER MFG. CO.
Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

PROPELLER MAINTENANCE RECORD

PROPELLER MODEL 76EM855-060

PROPELLER SERIAL NUMBER 31243K

TABLE OF PROPELLER ATTACHING BOLT WRENCH TORQUE
Sensenich Metal Propellers (the proper torque is also shown on Blade Information Decal)

PROPELLER SERIES**	BOLT DIA. (Inches)	RECOMMENDED WRENCH TORQUE		
		In.-lb.	ft.-lb.	n.-m.
69CK, M69CK (6 bolts) 72CK (6 bolts) 74CK, M74CK (6 bolts) 76AK, M76AK (6 bolts) 76AM6, M76AM (6 bolts) 74DM6, M74DM (6 bolts) * 74DR, M74DR (8 bolts)	3/8 (0.375)	280-300	23-25	32-34
74DM7 (6 bolts)	7/16 (0.4375)	480-540	40-45	54-61
72CC (6 bolts) 74DC, M74DC (6 bolts) 76EM8, M76EMM (6 bolts) * 80BM8, M80BMM (6 bolts)	1/2 (0.500)	720-780	60-65	81-88

*Not in production

**These are the basic propeller models. Spacer addition does not affect recommended wrench torque.

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
3/26/97	1695.2	Installed New Prop	Clyde J. Malone AP 402606620

Date 08-09-99 Propeller Total Time 66.40

Tach ~~Time~~ Time 1761.6 Propeller Time Since ~~xxxxx~~ ^{New} 66.40

REPLACE PROPELLER FROM 60" TO 58" SPECS, CHECK BLADE TRACKING, AND CHECK
STATIC BALANCE. REMOVAL & INSTALLATION OF PROPELLER. DYNAMIC BALANCE

PROPELLER CHECKED, NO ADJUSTMENT NECESSARY. VIBRATION READING BELOW .2 IPS

Work Performed By Tiffin Aire Inc.
 Repair Station #DTXR341D. Work Order Invoice # 14371 Signature [Signature]

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

TACH TIME	DESCRIPTION OF WORK	SIGNATURE
	<p>Tail# N7977W TTAF: 3939.0 TSMOH:227.3 Date: 07/10/13 Tach:1841.3 Performed annual inspection on this propeller IAW FAR 43 Appendix "D" I certify that this propeller has been inspected IAW and annual inspection and found to be in airworthy condition at this time.</p>	

Buckeye Aviation LLC

Name: Matthew Akers Signature: 

Certificate #: 2705782 A&P IA

SERVICEABLE

PROPELLER	SENSENICH
UNIT	MAKE
76EM855-0-58	31243K
MODEL	SERIAL NO.

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repair are on file at this repair station under:

OWNER HUNTER J. WARREN

WORK ORDER NO. 14371

DATE AUGUST 9, 1999


SIGNED FOR

Tiffin Aire, Inc.
1778 West State Route 224
Tiffin, Ohio 44883
419-447-4263
800-553-7767 or 800-458-2487
FAX 419-447-4042
F.A.A. Certified Repair Station
Number DTXR341D