

S/N FP6560B

N624CP



EAST COAST PROPELLER SERVICE INC.

PROPELLER LOGBOOK #2

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model PHC-J3YF-1

Blade Design F7392-1

Diameter _____

Hub Ser. No. FP6560B

Blade Ser. Nos.

No. 1 K69711

No. 2 K69716

No. 3 K69718

No. 4 _____

No. 5 _____

PITCH RANGE

High 35.0° Low 13.9°

Feather ✓ Reverse ✓

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

MAINTENANCE RELEASE

Make Hartzell

Model PHC-13YF-1RF F7392-1

Serial No. FP 6560B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-10195 and complies with Airworthiness Directives and Service Bulletins listed here.

No AD's Applicable @ this time.

Service Bulletin: 161-136R1

Manual No. 113BR41, 133CR30
202A & latest revisions
Total Time Brought forward Total Time Since O/H -0-
Date 4-18-14 Signed [Signature]

EAST COAST PROPELLER SERVICE INC.

MAINTENANCE RELEASE

Make Hartzell

Model PHC-13YF-1RF

Serial No. FP 6560B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-10569 and complies with Airworthiness Directives and Service Bulletins listed here.

Removed and replaced mounting studs. Torque checked studs.

Manual No. 113BR41
Brought forward
Total Time Brought forward Total Time Since O/H Brought forward
Date 6-5-14 Signed [Signature]

EAST COAST PROPELLER SERVICE INC.

JOHNSON AIRCRAFT MAINTENANCE

SEPTEMBER 2, 2015

N624CP CIRRUS SR20 S/N 1947 HOBBS 967.1 PROPTT 967.1 PROP TSMOH 114.0 FLIGHT HOBBS 905.4

Performed an annual inspection. This propeller installed on the aircraft identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Agency and Hartzell Manual and is approved for return to service. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Dennis E. Johnson 9-2-2015
AP2105411801A Dennis E. Johnson Date

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		<p>PROP MODEL: PHC-J3YF-1RF PROP S/N: FP6560B REG. NO: N624CP WORK ORDER: 0549</p> <p>Dedicated Aircraft Work 698 CR 1143 Tyler, TX 75704 Phone: 972-834-2476</p> <p>DATE: 10/6/2016 A/C TSN: 1028.3 PROP TT: 1028.3 FLIGHTTIME: 1028.3</p> <p>Prop Entries Performed propeller 100HR/annual inspection in accordance with FAR 43 Appendix D using the Cirrus AMM 5-20 and 5-30 as a guide. Researched AD's through biweekly release 2016-20. Lubricated the propeller hub.... Dressed the propeller blades.</p> <p>I certify this propeller has been inspected in accordance with a 100 hour/annual inspection and was determined to be in airworthy condition.</p> <p>DATE: 10/6/2016 SIGNED: <i>Isaiah Daw</i> Work Order: 0549 Isaiah Daw, IA: 2594100 Printed by EBis 3 (datcomedia.com)</p>	

DESCRIPTION OF ALL OPERATIONS

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP6560B
REG. NO: N624CP
WORK ORDER: 0617

Dedicated Aircraft Work 698 CR 1143
Tyler, TX 75704
Phone: 972-834-2476

DATE: 11/17/2017
A/C TSN: 1217
PROP TT: 1217
FLIGHTTIME: 1217

Prop Entries

Performed propeller 100HR/annual inspection in accordance with FAR 43 Appendix D using the Cirrus AMM 5-20 and 5-30 as a guide. Researched AD's through biweekly release 2017-22. Lubricated the propeller hub.

I certify this propeller has been inspected in accordance with a 100 hour/annual inspection and was determined to be in airworthy condition.

DATE: 11/7/2017

SIGNED: *Isaiah Daw*

Work Order: 0617

Isaiah Daw, IA: 2594100

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP6560B
REG. NO: N624CP
WORK ORDER: 0666

Dedicated Aircraft Work 698 CR 1143
Tyler, TX 75704
Phone: 972-834-2476

DATE: 1/17/2019
A/C TSN: 1327.2
PROP TT: 1327.2
FLIGHTTIME: 1327.2

Prop Entries

Performed propeller 100HR/annual inspection in accordance with FAR 43 Appendix D using the Cirrus AMM 5-20 and 5-30 as a guide. Researched AD's through biweekly release 2018-24. Lubricated the propeller hub.

I certify this propeller has been inspected in accordance with a 100 hour/annual inspection and was determined to be in airworthy condition.

DATE: 1/17/2019

SIGNED: *Isaiah Daw*

Work Order: 0666

Isaiah Daw, A&P: 2594100

Printed by EBis 3 (datcomedia.com)

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model PHC-J3YF-1

Blade Design F7392-1

Diameter _____

Hub Ser. No. FP6560B

Blade Ser. Nos.

No. 1 K69711

No. 2 K69716

No. 3 K69718

No. 4 _____

No. 5 _____

PITCH RANGE

High 35.0° Low 13.9°

Feather ✓ Reverse ✓

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

MAINTENANCE RELEASE

Make Hartzell

Model PHC-J3YF-1RF F7392-1

Serial No. FP 6560B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found air-worthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-10495 and complies with Airworthiness Directives and Service Bulletins listed here.

No AD's Applicable @ this time.

Service Bulletin: 161-136R1

Manual No. 113BR41, 133CR30

Total Time Brought forward

Total Time Since O/H -0-

Date 4-18-14

Signed [Signature]

EAST COAST PROPELLER SERVICE INC.

MAINTENANCE RELEASE

Make Hartzell

Model PHC-J3YF-1RF

Serial No. FP 6560B

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and was found air-worthy for return to service for work performed. Pertinent details of the repair are on file at this agency under Work Order No. ER-10569 and complies with Airworthiness Directives and Service Bulletins listed here.

Removed and replaced mounting studs. Torque checked studs.

Manual No. 113BR41

Total Time Brought forward

Total Time Since O/H Brought forward

Date 6-5-14

Signed [Signature]

EAST COAST PROPELLER SERVICE INC.