

MAINTENANCE RECORD

DATE	TOTAL IN SI
19__	HOURS

Associated Aero Service Inc

P. O. Box 1310 • Bethany, OK 73008 • (405) 789-5474 • FAA CRS SSWR186K

1-20-97

N4248C

Removed and replaced engine, replaced propeller McCauley B2D34C214. Replaced damaged components including lower center and forward belly skins, left and right lower cowling, keel assy and left and right cowl flaps. Details contained in Associated Aero Service Work Order No. 2151.

Sam Birchett

Sam Birchett IA2231949

RESIZED SIGNATURE,
CERTIFICATE TYPE
& NUMBER