

Transport Transports Canada

Note: The being provided of applicable Amountainess Directives for the specific registration mark is based solely on airhams, engine and projecter model installation information on record with Transport Canada. Miscellameous equipment ACs are not inscholed. It is required search to determine applicability of equipment ACs is required.

THE DATA FELDS FOR LATED WITH DATA FROM THE CHORNING DOCUMENT, ARE PROVIDED FOR REFERENCE ONLY REFER TO THE ORIGINAL DOCUMENT VARIED DETERMINING HECESSARY ACTION FOR YOUR PRODUCT ALL MARK COSTS.

HANK COSTS.

AND COSTS. SE22

CONTROLLED ON CONTRIBUTAL, 10-550-N

Provider HARTZELL, PROJNY-18F

rives	Pertaini	ing to Aircraft	Model: CIRRUS, SR22	Service Hutetin or Reference	Repeat Insp.?
Prod	Chu Al	D Number	PLJ 59,67855	SB 2X-30-08	REFER TO
A	US 20	09-26-01 D 🕾 /	ANTI-ICE FLUID LINE SEPARATION	601-00006-096, REVISION 1	REFER TO
A			PRIMARY FLIGHT DISPLAY (PFD) ALTITUDE AND AIRSPEED INFORMATION	SB 2X-52-07 R4	REFER TO
A	US 20	08-14-130日	N-FLIGHT CABIN DOOR SEPARATION	CIRRUS SB 2X-27-14R3	REFER TO
A	US 20	08-03-16 🗅 📆	JAMMING OF THE RUDDER-AILERON INTERCONNECT SYSTEM.	SERVICE BULLETIN 2X-57-08	REFER TO
A	US 20	07-24-13 0 10	INSTALL A DRAIN HOLE IN THE LEFT AND RIGHT OUTBOARD WING TIPS	SB A2X-95-10 R2; SB A2X-95-10 R1	REFER TO
A	US 20	007-14-03 🗅 🖫	CIRRUS AIRPLANE PARACHUTE SYSTEM (CAPS) ACTIVATION	SB 2X-32-13 R1	REFER TO
A			OVERHEATING DAMAGE TO THE BRAKE CALIPER PISTON O-RING SEALS.	2X-25-06 R4	REFER TO
A	US 20	006-19-10 🗅 📆	CREW SEAT SECURITY TO DETECT, CORRECT, AND PREVENT DAMAGE TO THE FUEL LINE AND WIRE BUNDLES, WHICH COULD TO DETECT, CORRECT, AND PREVENT DAMAGE TO THE FUEL LINE AND WIRE BUNDLES, WHICH COULD	SB 2X-28- 04 R1	REFER T
A			RESULT IN FUEL LEARN STATE OF THE POEM OF	SUPERCEDED BY 2006-19-10	NO REFER T
A	US 20	005-17-19	CREW SEATS - FOLDING FORWARD DURING EMERGENCY DATASETS OF THE STANDARD OF INACCURATE REPLIES DUE TO SUPRESSION FROM GTX 330/330D MODE S RECEPTION OF INACCURATE REPLIES DUE TO SUPRESSION FROM GTX 330/330D MODE S RECEPTION OF INACCURATE REPLIES DUE TO SUPRESSION FROM GTX 330/330D MODE S	REFER TO AD	AD REFER T
A		阿尔尼亚州市市	TRANSPONDERS SR20 AND SR22 - MODIFICATION OF CAPS SYSTEM	22-95-03/-04/-05R1	AD
A			SR20/2 - ROLL + YAWTRIM CARTIDGES RETAINING NUT	A22-27-03	REFER
A	US 2	002-21-02	TO SEASON AND THE CONTROL OF THE CON	22-95-01	REFER
A	US 2	002-05-05 D	CIRRUS AIRCRAFT PARACHUTE SYSTEMS(CAPS)	22-55-03	REFER
A	US 2	001-25-03	INSPECT/REPLACE UNDERSTRENGTH RIVETS PINMS20470A4		

				CONTINENTAL IO-550-N		
ectives	Perte	nining to Engi	ne M	odel:TELEDYNE CONTINENTAL, IO-550-N	Service Bulletin or Reference	Repeat Insp.2
Down !	Ctry	Transfer Bar		AD NOSS	REFER TO AD	NO TO
			DIE	NON-CONFORMANCE OF MAINTENANCE ON PISTON ENGINES		REFER TO
E		CF-90-03R2	01	EXHAUST TYPE COCKPIT/CABIN HEATERS (MOFF) INSTESS IN THE		NO
_	-	022	100	ENGINES OVERHAULED BY PROVENCE AERO MAINTENANCE	REFER TO F-2005-023	REFER TO
		F-2005-023		CANCELLATION NOTICE - AD SUPERSEDED BY F-2005-023	REFER TO F-2003-020	AD REFER TO
E	FR	F-2001-139R1				AD
Meli	119	2016-16-12		ATA -72 ENGINES - CRACKED AND LEAKING ALUMINUM CYLINDER HEADS AND		REFER T
	00			CYLINDER HEAD SEPARATIONS STCSE09773SC - STCSE4985NM - SEPARATION OF THE CYLINDER HEAD	SIL98-9C REV.C	AD
E	US	2014-05-29			MSB11-4B, DATED APRIL 4, 2012	REFER T
	-		1000	STCSE10589SC - FRACTURES IN STARTER ADAPTER GEAR SHAFTS	MSB11-4B, DATED APRIC 4, 2012	AD
E	US	2012-10-13	DE	510521000000-11010-01-2	S SECTION AND ADDRESS OF THE PARTY OF THE PA	REFER T
E .	LIC '	2012-03-06	DEF	FAILED FUEL SERVO DIAPHRAGM		REFER
-	03	2012 05 00	-		CMI MSB NO.MSB11-4	AD
E	US	2011-25-51		SUPERSEDED BY FAA AD 2012-10-13	TCM MANDATORY SERVICE BULLETIN (MSB) NO.	REFER
				HYDRAULIC LIFTERS, PART NUMBERS 657913, 657915, OR 657916	MCDOO RA	AD
E	US	2010-11-04	DE	HYDRAULIC LIFTERS, FART HOMESTIC	TCM MANDATORY SERVICE BULLETIN MSB09-08	REFER
INE	- TIO	2009-24-52	9 HO ES	AD SUPERSEDED BY AD 2010-11-04	1CM MARIONI OTT	REFER
	US	2003-24 32			MSB09-8	AD
E	US	2009-24-51		SUPERSEDED BY FAA AD 2009-24-52	ON THE OWN INDER ASSEMBLIES	REFER
			accum to	SUPERSEDED BY FAA AD 2014-05-29	SUPERIOR AIR PARTS (SAP) CYLINDER ASSEMBLIES	AD
E	US	2009-16-03			PRECISION AIRMOTIVE LLC MSB NO. PRS-107 REVISION 4	REFER
	2 200	2009-02-03	0.5	PRECISION AIRMOTIVE & BENDIX FUEL INJECTION SERVO, HAVING A SERVO	PRECISION AIRMOTTE	
E	US	2009-02-03	LI	PLUG GASKET, PART NUMBER (PM) 3000000	MSB 342	REFER
HE	IIIS	2008-14-07	MESS S	SUPERSEDED BY 2011-26-04		REFER
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		AE
E	US	2008-08-14		SUPERSEDED BY FAA AD 2009-02-03	KELLY AEROSPACE POWER SYSTEMS SERVICE	REFE
			-	KELLY AEROSPACE POWER SYSTEMS TURBOCHARGERS	BULLETINS NO.026, REVISION B & NO. 027	AI
E	US	2007-16-10	19	RECEI ACTOSI AGE I	SUPERIOR AIR PARTS B06-01, REV. E	REFE
A SECON	LIC	2007-04-19	21 05	CYLINDER SEPARATION	Out at the second secon	REFE
E	03	2007-04-25			S.I. NO. 04-1 R1	KEFE
ME	US	2004-08-10	01	FAILURES OF CYLINDER HEADS MARKETED BY ECI	HE RESIDENCE AND ASSESSMENT OF THE PARTY OF	N
			西西!	CRANKSHAFT FAILURE	TCM MSB 00-5C	REFE
E		2000-23-21	D		MSB 99-3C AND CSB 99-6A	A
E	US	99-19-01	0	CRANKSHAFT NDT INSPECTION	THE RESERVE THE PARTY OF THE PA	REF