THE AIRCRAFT MAINTENANCE MAINTENANCE RECORDKEEPING SYSTEM



PROPELLER MAINTENANCE RECORDS



PROPELLER MAINTENANCE RECORDS

	Law Ma
Aircraft Registration No. N4449	Log No
Propeller Manufacturer Hartzell	ere Como design
Hub Model BHC-J2YF-1BF	_
Blade Design No. F7694	_
Hub Serial No. EF 268B	_
Blade Serial No's. 1	
3	_
4	
Pitch Range: High35,0 Low	
Governor Manufacturer	,A
Model No	
Date installed on aircraft $\frac{3/19/2007}{2400}$ Time Between Overhauls (TBO) $\frac{2400}{100}$ Ho	OVERHAULED 7-7-14) urs 6 YEARS,
If used on multi-engine aircraft: Right Left Front Rear	

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

www.adlog.com PO BOX 1359 / SOUTHOLD, NY 11971-0965 (631) 765-9375

1-800-235-6444 FAX: (631) 765-9359

	TOTAL	TOTAL	TACH OR			
DATE	TIME IN SERVICE	TIME SINCE OVERHAUL	RECORDING METER TIME		TION OF WORK PERFORMED— CATE NO. OF PERSON PERFORM	NG WORK
				TOTALS brought forward from	om previous page	
	Prop E	N: 1: N44YP 1: RDER: 177 :ntries ted an Annual Ins	DVANCE IRCRAFT spection using the	Sub Airport Road Suite D Lititz, PA 17543 Phone: 717-735-5179	A. PR	E: 3/19/2007 C TSN: 933 OP TT: 933 TSPOH: 0.1 100BBS: 933
				ted IAW an Annual Inspection and was found	to be in Airworthy condition.	- Control Control
	DATE: 3	3/19/2007	SIGNE	D: WWH WWW. t. IA/3124994		Order: 177
			RDarnnar	1, 17/3124994	Printed by EBis 3 (datcom	nedia.com)
	A 3 7 3 7 1			1000		
	į į	PROP MODEL: BHCJ2YF-1BF PROP S/N: EF268B REG. NO: N44YP WORK ORDER: 572	Advanced 500 Airport Roa Lititz, PA 17543 Phone: 717-735		DATE: 3/28/2008 A/C TSN: 1129.1 PROP TT: 1129.1 TSPOH: 136.1 HOBBS: 665.9	
		Prop Entries Completed an Ar	nnual Inspection	using the Ornus AMM check list ch. 5-2	20 Dressed all propeller blades	
	The second second second		7	en inspected IAW an Ann (at Inspection and v	vas found to be in Airworthy condition.	
		DATE: 3/28/2008	SIGN		Work Order: 572	
	a,		Richa	ard A. Barylaar II, IA: 3124994	Printed by EBis 3 (datcomedia.com)	
		1				,
	* §	PROP MODEL: BHC-J2YF-1BF PROP S/N: EF268B REG. NO: N44YP	Advance 500 Airport R Lititz, PA 175		DATE: 4/3/2009 A/C TSN: 1288.3 PROP TT: 1288.3 TSPOH: 295.3	
		WORK ORDER: 895	Phone: 717-7		HOBBS: 794	
				n using the Cirrus AMM check list ch. 5 nru 09-07-END-	5-20 Dressed all prop blades and	
		I certify that this P	ROPELLER has b	een inspected IAW an Annua Inspection and	was found to be in Airworthy condition.	
		DATE: 4/3/2009		SNED: MA 3124994	Work Order: 895 Printed by EBis 3 (datcomedia.com)	
	1		****			
				SUB-TOTALS this page		Ĭ.
				TOTALS-Carry forward to		

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME		PTION OF WORK PERFORM FICATE NO. OF PERSON PE		
	Prop Mod BHC-J2Y N44YP		971 Heilr	e Aerospace, LLC man Road sville, PA 17754 5-0064	Date: 4-30-10 A/C TSN: 1513.6 Hobbs: 968		
	Prop Ent	ries			-		
				sing the Cirrus AMM check ed hub. All A.D.s current thro			
	_		airworthy co	PELLER has been inspected IAW an Annual Inspection and airworthy condition.			
	Date: <u>4-3</u>	<u>0-2010</u>	Signed:	FIR 74 20653	> 3 T.A		
				77,000) VM.		
2-15-10	TACH: 1675, 8	HOBBS: 1085. 2	Completed HUB WITH	A 100 HR INSPECTION IFAL AEROSHELL 6 GREASE, PER 1	L CIÈRRUS AMM : DRESSED MANUFACTURE'S' RECOMME	ALL PROD blades 45 NOATION 5. EMGRICA	
	Prop Mo BHC-J2' N44YP		971 He Montou	ote Aerospace, LLO ilman Road ursville, PA 17754 35-0064	Date: 4-30-		
	Prop En						
	Complet Dressed						
	-			nas been inspected IAW an A condition.	-		
	Date: <u>4-</u>	<u>30-2011</u>	Signed: _	Condition. Guit H. Cypic A.	HP3420653IA.		
				•	1		
					V. Andrews		

Page N	O.

	TOTALS brought forward from previous page	*****
	SENSENICH PROPELLER SERVICE, INC. DATE: 4-7-12 CRS: QV9R194N Hobbs/IIII 1876-0 A/C Reg: V41/P Hub Model: BHC-JZYF-IBF Hub SIN: EF268B Propeller TTSN: Propeller TTSO:	Shirt S
	Summary of work performed Dinamic Talance Propeller IAW. Chadasick Holanoth Smooth Propeller IAW. Chadasick Holanoth Smooth Propeller IAW. Hartzell mancal # 115NR 66. Starting TPS: 69 at 2600 pm. Removed 17.6grams of static balance weight, & installed 19.0grams of Static balance weight 180° away to obtain. 03 TPS: at 2600 pm. Encl.	
,	Pertinent details of this repair or provinced are on file at this repair station under work order # 235 78 Signed for Sensenich Propeller Service, Inc., 519 E. Airport Rd. Lititz, PA 17543 "Finis signature constitutes approval for return to service of this aircraft ONLY FOR THE WORK WE HAVE PERFORMED. We have not performed nor been authorized to perform any in spection of this aircraft nor have we review and or been authorized to review the maintanance records, including Part 39 compilance.	
	Prop Model: Coyote Aerospace, LLC Date: 5-1-12 BHC-J2YF-1BF 971 Heilman Road A/C TSN: 1949.2 N44YP Montoursville, PA 17754 Hobbs: 1292.0 (570) 435-0064 Hobbs: 1292.0	
	Prop Entries Completed an Annual Inspection using the Cirrus AMM check list, chapter 5-20 Dressed all prop blades and serviced hub. All A.D.s current thru 12-08.	
	I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in an airworthy condition. Signed:	
	Hartzell Prop Model: Coyote Aerospace, LLC Date: 7-15-13 BHC-J2YF-1BF 971 Heilman Road A/C TSN: 2112.4 s/n: EF268B Montoursville, PA 17754 Maint. Hobbs: 1421.5 (570) 435-0064	
	Prop Entries Completed an Annual Inspection using the Cirrus AMM check list, chapter 5-20 Dressed all prop blades and serviced hub. All A.D.s current thru 13-08. I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in an airworthy condition.	
	Signed:	

Р	Don't M		2YF-1BF	Dannelatia	HADTZELL DDODELLED	Savial No. EE249D
-	Part No	AND RESIDENCE AN	ED (describe)	Description:	HARTZELL PROPELLER	Serial No: EF268B
	was L	1 KDLVIK	ED (describe)		and a supplicate of the problem over the first term of the first term of the problem of the prob	
		⊠ ove	RHAULED pe	er the following de	ocuments (include revision levels):	
		Man	uals 113B R	41, 133C R30, 20	2A Vol. 1 R47, Vol. 2 R29, Vol. 3 R	34, Vol. 7 R36, Vol. 10 R32
			_	THRU 61-306 R		
,			ice Letters		1-267, 61-278, 61-329	
1			ice Instructions ice Advisories		12A	
	The fo			ctives have been c	omplied with:	
	1110 10		0111111000 2 1100	Method		Recurs at:
	A.D.			Compli	ance:	Date or Hours
-	N/A					
_	T'	Yana Maura	HODE	3S: 2256.2	Time Since Overhaul/Major:	-0-
	The it	Since New:			auled (as indicated) and inspected in	
	FAA.	aculations on	d are approved	for return to serv	ice. Pertinent details of this repair o	r overhaul are on file at
			nder work orde		ec. Termient details of this repair of	2
				Signed	- 1 Vlan Kush	^
	Date	July 17, 20	014		pair Station #QV9I(194N	
					H PROPELLER SERVICE, INC.	
		004				
	FORM	004		519 Eas	t Airport Road, Lititz, PA 17543	
						N .
, Antion						
					Sen	senich Propeller Service
					Rec	pair Station #QV9R194N
					,	
					CHILDREN CO.	The second secon
					SENSENICH PROPE	LLER SERVICE, INC.
				,	lobbs/1528.7	A/C Reg:CRS: QV9R194N
					ropeller TTSN: 2256. 2	Hub S/N:
					Topener Flore.	Propeller TTSO:
					Summary of	f work performed
						installad Overhayled
					11 -A1 H	trell approved data
			-	+	frepeller IAW. Her	
					Opps& leak checked	gast Inamic
				1	11 1 Poste	IAW Chadesick 11
					Folanced 199	11 or & thetell
				-	Holaush Smooth tro	peller
					data. Starting Its	39 at 2500 kgm.
					data. Staffing 215	the spinner Bulkhard.
					Installed 19 grans in	The Spinner
				:	Francis 115 .01 at	200 kgm. Ind -
		÷			0	
			-			is repair station under work order#125872 th Propeller Service, Inc., 519 E. Airport Rd. Lititz, PA 17543
				-	, , ,	of this aircraft ONLY FOR THE WORK WE HAVE PERFORMED.
						any inspection of this aircraft nor have we reviewed or been
					thorized to review the maintenance records, including P	art 39 compliance.
		AACT 4T	- 227A	2		
8	-8-14	MAINT	- 22 10	12	ANTI DIANCE A. M.	ALABANTA INCOME THAT
	- ' ' '	MHINT	10005-1547	3.5	OPELLEIZ BLADES, AND	COMPONEN IS INSPECTED THE
				AN	INVAL INSPECTION,	COMPONENTS INSPECTED IAW MI EMIH Upin ALP 3420653IA.
					SUB-TOTALS this page	
			1		OTALS- Carry forward to next p	nage
					- In a Culty lotward to liext	ago .

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			100000000000000000000000000000000000000	TOTALS brought forward from previous page
				,
			Hartzel paint to I certify	ntries eted an Annual Inspection using the Cirrus AMM check list, chapter 5-20 and l maint manual: Dressed all prop blades and serviced hub. Reapplied flat black orear surface. All A.D.s current thru 15-20. That this PROPELLER has been inspected IAW an Annual Inspection and and to be in an airworthy condition.
			Signed	Eint lipin A+P 3420653 IA. Date: 10-30-15
	,			•
	Tail No: Date: 11 Flt Hobb I certify determinapplicab List in lo I certify accordan	N44YP/Har /4/16 Wo es: 1815.3 that this pro- ned to be in le airworth gbook. Per all work do nce with cur	ork Order: M Hobbs: 26 opeller has h an airworth iness directi formed groune to the air crent regula	2YF-1BF/Serial: EF268B 24.3 PROP TT:2624.3 Prop TSO: 368.1 and an annual inspection IAW FAR43 Appendix D and was been reviewed and complied with. In and run up, all applicable leak and ops checks good. It is approved to the Federal Aviation Administration and was found with respect to the work performed.
	DE	V. 111		, Steven D. Reifeis A&P35055351A
12	845 Seve Tail No: I Date: 11,	ern Ave. Tan N44YP/Har	rk Order: M	2YF-1BF/Serial: EF268B 427 4 MAINTENANCE
	determit	ied to be in le airworth gbook. Lub	an airworth iness directi	nad an annual inspection IAW FAR43 Appendix D and was ny condition and is approved for return for service. All ives through 11/14/17 have been reviewed and complied with. r hub. Performed ground run up, all applicable leak and ops

Steven D. Reifeis A&P3505535IA



AVERY PV119G

519 East Airport Road Lititz, PA 17543

Propeller Logbook

- **X** - - -

Hamilton Standard

Sensenich

McCauley Hartzell

INSTALLING AGENCY PLEASE NOTE: Recording of Propeller Total Time Since New (TTSN) is Required Per F.A.R. 91,417

EF368B

Lee Gilmer Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

INVOICE

Invoice Number: L23575

> Invoice Date: Apr 4, 2012

Page: 1

.O.D. Due Date 4/4/12 Amount

275.00

unt





SENSENICH PROPELLER SERVICE, INC. 519 East Airport Road Lititz, PA 17543 (717) 560-3711 * (800) 462-3412 Fax: (717) 560-4354 seuseni:hpropellers.com

INVOICE

Invoice Number:

L23575

Invoice Date:

Apr 4, 2012

FAA Certified Repair Station# QV9R194N

JET AERO LLC 97! HEILMAN ROAD MONTOURSVILLE, PA 17754

Ship to:

Page: 1

(412) 496-9984

Cı	stomer ID	Customer PO	Payment Terms	3	
JETAERO Sales Rep ID			C.O.D.		
		Shipping Method	Ship Date	Due Date	
Kat	therine Wright	Hangar		4/4/12	
Quantity	Item	Description	Unit Price	Amount	
	8 10	N44YP SR20	775.00	275.00	
1.00	S 10	Dynamic Balance	275.00	275.00	
Check/Cred	iit Memo No:	DNII Maso a Carox	Subtotal Sales Tax al Invoice Amount	275.0 16.5 291.5	
		Val.	TOTAL	291.5	