



OWNER NAME Bruce Brewn

ADDRESS 5350 Tyler Lane

Meridian MS 39301

PROPELLER MODEL Hatzell HC - J3YF - 1RF

BLADE MODEL _____

HUB SERIAL NO. JN3388

BLADE SERIAL NO.

1 _____

2 _____

3 _____

4 _____

3

TS

Regulations 1

Book/ Contents 2

Information 3

History 4 - 10

Bulletins 11 - 12

Release Tags 13

2

N210PF



SOUTH COAST PROPELLER SERVICE, INC.



FAA Approved Repair Station
S6PR302X

1-866-875-6377
205-426-7022
FAX 205-426-7026


5750 Durose Drive
Bessemer, AL 35022

PROPELLER LOGBOOK

www.southcoastpropellerservice.com



MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
			LAKE Texoma <small>EST. 1978</small> 3604 Airport Drive Denison, Texas 75020 Propeller	
			Date: 06-28-2013 Prop Model: HC-J3YF-1RF Prop S/N: JN3388 PTT: 0.0	Aircraft: P210N Reg: N210PF TT:3540.1 PTC: 0
			Removed and installed new Hartzell propeller assembly for ferry flight , P/N HC-J3YF-1RF , S/N JN3388 IAW Cessna Service manual section 14. Performed engine run and propeller ops checked good. B Foytik 06-28-2013	
			The above described article has been inspected and repaired in accordance with current Regulations of the Federal Aviation Agency and is approved for return to service with respect to work performed. Pertinent details of repairs and inspections are on file under the W/O 13-01893.	
			 A&P 3677115 For: Lake Texoma Jet Center, LLC	

Note: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11& 12.

Date	Total Prop Time
1-20-13	68.

Note: Enter Comp

ORY

MAINTENANCE & SERVICE HISTORY



Authorized Signatures
Repairman & Station
Certificate Numbers

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
1-20-19	68.4	68.4	Remove Prop Due to low power Prop Strike	3110932 <i>John P...</i>

HC-J3YF-1RF, S/N
propeller ops

accordance with
proved for return
s of repairs and

nter, LLC

illettins on Pages 11& 12.

Note: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11& 12.

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number APW5830	
4. Organization Name and Address: Aircraft Propeller Works, Inc. 506 Charlotte Road Auburndale, FL 33823				5. Work Order/Contract/Invoice Number APW5830		
6. Item:	7. Description:	8. Part Number:	9. Eligibility:	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	Aircraft Propeller	HC-J3YF-1RF F8068	N/A	1	JN338B	Repair
13. Remarks: This Hartzell Propeller resealed, leading edge cleaned up, blades repainted and static balanced in accordance with Hartzell manuals 202A, 113B and 133C. Approved for return to service. Continue time.						
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13			19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signatures:		16. Approval Authorization No:		20. Authorized Signatures:		21. Approval/Certificate No:
						T4ZR741Y
17. Name (Typed or Printed):		18. Date (m/d/yy):		22. Name (Typed or Printed):		23. Date (m/d/yy):
				Arthur J Michaud		3/6/2014
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.						
FAA Form 8130-3 (8-01)			*Installer must cross-check eligibility with applicable technical data			NSN: 0052-00-012-9005

WORK HISTORY

Number of Work	Authorized Signatures Repairman & Station Certificate Numbers
----------------	---

Date	Total


Inspected this propeller (Hartzell Model NoP.HC-J3YF-1RF/F8068, S/N JN3388B) ON A/C REG. #N210PF IAW Vitaeo Aviation STC # SA2918CH REV.F,APP.A and the Manufacturer's Instructions in the Owner's Manual. Propeller leak checked good and functioned as designed. End

AP 2961799

Note: Enter Compliance with Air Applicable TFR and Factory Service Bulletins

Note: Enter

SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
			Vitatoe Aviation LLC Pickaway County Airport 28181 McCrady Rd. Circleville, Ohio 43113	
Date: 3-1-2014	Tach: 3549.6	TTAF: 3549.6	TSNEW : 9.8	A/C REG. # N210PF
Installed this propeller (Hartzell Model NoP.HC-J3YF-1RF/F8068, S/N JN3388B) ON A/C REG. #N210PF IAW Vitatoe Aviation STC # SA2918CH REV.F, APP.A and the Manufacturer's Instructions in the Owner's Manual. Propeller leak checked good and functioned as designed. End				
				 AP 2961799

Note: Enter Compliance with All Applicable FAA, EASA, & Factory Service Bulletins

Date	Total

Note: Enter

RY

Authorized Signatures
Repairman & Station
Certificate Numbers

Date	Total

1210PF

C REG. #N210PF IAW Vitaeo
ner's Manual. Propeller leak

2961799

Note: Enter

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 21956	
4. Organization Name and Address: Tiffin Aire, Inc. 1778 West U.S. 224 Tiffin, Ohio 44883 (DTXR341D)				5. Work Order/Contract/Invoice Number: W.O.# 21956		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	HARTZELL PROPELLER	HC-J3YF-1RF	1	JN338B	OVERHAUL	
<p>12. Remarks:</p> <p>COMPLETELY OVERHAUL PROPELLER DUE TO FOREIGN OBJECT STRIKE AND INSTALLED NEW DE-ICE BOOTS IN ACCORDANCE WITH HARTZELL SERVICE MANUALS LISTED ON BACK SIDE OF THIS FORM. COMPLIED WITH SERVICE BULLETIN: 1361 / SERVICE INSTRUCTION: 152A / SERVICE LETTERS: 260R22, 177, 189R2, 217, 229R2, 244, 265R2, 267, 278, 61YR6. BLADE MODEL NUMBER: F8068B / BLADE SERIAL NUMBERS: L28708, L28710, L28711. PROPELLER TOTAL TIME SINCE NEW: 68.9 PROPELLER TOTAL TIME SINCE OVERHAUL: 0.0 PROPELLER TIME BETWEEN OVERHAULS: 72 CALENDAR MONTHS OR 2400 HOURS WHICHEVER OCCURS FIRST.</p>						
13a. Certifies the items identified above were manufactured in conformity to:				14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12		
<input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.				Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval/Authorization No.:	14b. Authorized Signature:		14c. Approval/Certificate No.:	
			<i>Todd C. Perry</i>		DTXR341D	
13d. Name (Typed or Printed):		13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):		14e. Date (dd/mmm/yyyy):	
			Todd C. Perry		09/Feb/2015	
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.						
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

FAA Form 8130-3 (02-14)

NSN: 0052-00-012-9005

7



MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
------	----------------------	---------------------	---------------------	---

Date	To
23 June 2016	

Vitaoe Aviation LLC
 Pickaway County Airport
 28181 McCrady Rd.
 Circleville, Ohio 43113

Date: 8 June 2015 TACH: 363.1 TTA#: 4004 TSNEW : 68.9 Tail N210PF

Removed Prop for a unpowered prop strike inspection by Tiffin Aire INC .See wo 21956 And 8130 for details. Reinstalled prop, Performed an annual inspection on this prop IAW FAR 43 APP. D. and using Vitaoe STC # SA02918CH and Hartzell's Owner/User manual as a guide. AD's researched through current bi-weekly 2015-11. See AD compliance log. I certify this propeller was found to be in an airworthy condition at the time of inspection---END-----

John B...
 AP 3110932 IA

1 of 1

PROP MODEL:
 HC-J3YF-1RF
 PROP S/N: JN3388B
 REG. NO: 210PF
 WORK ORDER: 7206



Tennessee Aircraft Services, Inc.

2313 Technology Center Drive
 Jackson, TN 38301
 Phone: 731-424-7227

DATE: 13 June, 2016
 A/C TSN: 4026
 PROP TT: 151.8
 TACH: 4010.8

Prop Entries

- Performed Annual / 100 hour inspection with reference to FAA CFR 43 Appendix D.
- Adjusted propeller governor max RPM stop to decrease 3/4 turns as required. Request flight check to confirm results.
- Dressed propeller nick and painted as required.
- Work performed by Joe Norris and Doug Kail.

I certify this aircraft has been inspected in accordance with an Annual Inspection and found airworthy.

No
 8

DATE: 13 June, 2016

SIGNED: *Joe A. Norris*
 Joe Norris, IA: 3466262

Work Order: 7206

Printed by EBis 3 (datcomedia.com)

& 12.

Note: Enter

MAINTENANCE & SERVICE HISTORY



Authorized Signatures
Repairman & Station
Certificate Numbers

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
23 June 2016	193	84.1	Removed propeller, taken for inspection at South Coast Propeller. Propeller return spring replaced. Propeller reinstalled IAW Cessna Service Manual, rev 2, dated 3 June 1996 with propeller bolt torque 700 in-lbs. Bruce Brown AQP 3207478 Bruce Brown	

Tail N210PF

performed an annual inspection on this
through current bi-weekly 2015-11. See

13 June, 2016
A/C TSN: 4026
ROP TT: 151.8
TACH: 4010.8

& 12.

Note: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11 & 12.

Order: 7206
media.com)