

HARTZE

PROPELLER LOGBOOK

PROPELLER MODEL PHC-334F-1RF

PROPELLER S/N FP8968B

LOGBOOK #

PROPELLER MAINTENANCE RECORD

Position ONE

PITCH RANGE

Propeller Model PHC-J34F-1RF

High/Feather _____

Propeller S/N FP8968B

Start Lock _____

Blade Design F7693DFB

Low _____

Blade S/N's

Reverse _____

No. 1 L75043

No. 2 L75045

Aircraft Manufacturer Cirrus Design Corp

No. 3 L75046

Aircraft Model SR22

No. 4 _____


S/N 4450

No. 5 _____

Registration N1GT

No. 6 _____

Spinner Assembly Part No. _____



FLIGHTLEVEL
N O R W O O D

Propeller Log Entry

| | | |
|----------------|-----------------------------------|--------------------|
| Name: SRJ LLC | Tail # N1GT | Flight Time: 150.7 |
| W.O.: 9946 | Model : PHC-J3YF-1RF/F 7693DFB | Hobbs:183.6 |
| Date: 3/8/2018 | S/N: FP8968B | |

Checked Bi-Weekly ADs through 2018-05. Lubed propeller.

I certify that this propeller was inspected I/A/W FAR 43 Appendix D for a 100 hour Inspection and was determined to be in airworthy condition.

Signature: _____

A&P 38401436

Lance Drew

FlightLevel Norwood LLC - Maintenance
209 Access Rd., Norwood, MA 02062

Propeller
TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspection

Propeller



Columbia Air Services-BHB, LLC
112 Caruso Drive (Hancock County) Bar Harbor Airport – Trenton, ME 04605
CRS#ZKGR483J

N1GT SR22

Date 4/4/2019 Hobbs 375.7 Flight 320.4
Propeller FP8968B

I certify that this Propeller has been inspected I.A.W. an Annual Inspection and was determined to be in airworthy condition and no defects noted. Inspected using FAR 43 appx "D" as a guide. Greased hub and dressed blades. Run-up and leak checked. See AD list for AD's.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance Identified Above was Repaired and Inspected in Accordance with current Regulations of FAA and

is Approved for return to Service. Pertinent details of the repair are on file at This Repair Station under RO # 4925

Date: 4/4/2019

Signed:

Columbia Air Services – BHB, LLC

112 Caruso Drive Trenton, ME 04605 FAA Certified Repair Station # ZKGR483J

PROP MODEL:
PROP S/N:
REG. NO: N21GT
WORK ORDER: 6573



Nassau Flyers

1300 New Hwy
Farmingdale, NY 11735
Phone: 631-454-0626

DATE: 4/21/2020
A/C TSN: 461.9
PROP TT: 461.9
TACH: 461.9

Prop Entries

- Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-02 and 05-30.
- *Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.
- Serviced propeller hub with Aeroshell #6 grease.

Maintenance Release

This aircraft, engine, propeller or component(s) on N21GT were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 4/21/2020

SIGNED:

Sean McFadden, A&P: 3647763

Work Order: 6573

Printed by EBis 3 (datcomedia.com)

PROP MODEL: PHC-J3YF-1RF
PROP S/N: FP8968B
REG. NO: N21GT
WORK ORDER: 6828



Nassau Flyers

1300 New Hwy
Farmingdale, NY 11735
Phone: 631-454-0626

DATE: 6/1/2021
A/C TSN: 509.3
PROP TT: 509.3
TACH: 509.3

Prop Entries

- Performed a 100 hour inspection of propeller per Cirrus AMM and Cirrus inspection checklists, Chaps 05-02 and 05-30.
- *Removed propeller spinner and serviced/dressed/painted propeller as need, then reinstalled spinner.

Maintenance Release

This aircraft, engine, propeller or component(s) on N21GT were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 6/1/2021

SIGNED:

Darion McFadden, A&P: 4138120

Work Order: 6828

Printed by EBis 3 (datcomedia.com)

