



# PROPELLER OWNER'S MANUAL

**HARTZELL**



**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL PAC-J341F-IN/N7605B

PROPELLER S/N NJ403B

LOGBOOK # \_\_\_\_\_



## PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model PHC-I3YIF-IN

Propeller S/N NJ403B

Blade Design N7605B

Blade S/N's

No. 1 A4385

No. 2 A4384

No. 3 A4381

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Inner Assembly Part No. \_\_\_\_\_

PITCH RANGE

High/Feather \_\_\_\_\_

Start Lock \_\_\_\_\_

Low \_\_\_\_\_

Reverse \_\_\_\_\_

Aircraft Manufacturer CIRRUS DESIGN CORP.

Aircraft Model SR-22T

S/N 0066

Registration N88BA

Safety: Avoiding









4510 Airport Rd.  
Cincinnati OH 45226  
(513) 321-1200



**N88BA S/N: NJ403B Date: 12/23/2011 Propeller Flight: 139.8 TSN: 139.8**

Inspected propeller I/A/W an **Annual** inspection per Cirrus SR22 AMM rev. B1 Chapter 5-20 and Hartzell POM no.145 rev 5 Oct/08. The following work was accomplished at this time:

1. Lubricated propeller

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 406901563IA



4510 Airport Rd.  
Cincinnati OH 45226  
(513) 321-1200



**N88BA S/N: NJ403B Date: 2/1/2013 Propeller Flight: 254.7 TSN: 254.7**

Inspected propeller I/A/W an **Annual** inspection per Cirrus SR22 AMM rev. B1 Chapter 5-20 and Hartzell POM no.145 rev 5 Oct/08. The following work was accomplished at this time:

1. Lubricated propeller

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 406901563IA





4510 Airport Rd.  
Cincinnati OH 45226  
(513) 321-1200



**N88BA S/N: NJ403B Date: 3/28/2014 Propeller Flight: 323.5 TSN: 323.5**

Inspected propeller I/A/W an **Annual** inspection per Cirrus SR22 AMM Chapter 5-20 and  
Hartzell POM no.145 rev 5 Oct/08. The following work was accomplished at this time:

1. Lubricated propeller

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA  
and is approved for return to service.

Greg Herrmann 406901563IA