



PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF/F7693DFB

PROPELLER S/N ~~XXXXXXXXXXXX~~ FP 10481B

LOGBOOK # _____

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date

Propeller
TSN TSO A/C
Hrs

wo. WO_270

Propeller - page 1 of 1



Warbird Factory - 743 ALBANY SHAKER ROAD - Latham, NY 12110 - 5186331155

N814LT
HOBBS: 3940.0

S/N 3568

HARTZELL, PHC-J3YF-1RF, S/N: FP7368B


TACH: 3102.0 **3120.0**

January 09, 2026

INSTALLED NEW PROPELLER P/N PHC-J3YF-1RF/F7693DFB ASSY. S/N FP10481B IAW SR22 AMM 61-10 WITH SERVICEABLE GOVERNOR P/N D-20309-22 S/N 220455. ADJUSTED GOVERNOR STOP AS REQUIRED. OPERATIONS AND LEAK CHECK OK.

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Warbird Factory under work order: WO_270.

Michael Berti A&P 4051217



wo: WO_442

Propeller - page 1 of 1



Warbird Factory - 743 ALBANY SHAKER ROAD - Latham, NY 12110 - 5186331155

N814LT

HOBBS: 3965.1

HARTZELL, PHC-J3YF-1RF, S/N: FP7368B

PTSN: 0.0

TACH: 3120.3

February 23, 2026

PTSN: 0.0

1. PERFORMED PROPELLER 100 HOUR INSPECTION IAW SR22 AMM CHAPTER 5-20. NO DEFECTS NOTED AT THIS TIME.
2. ADJUSTED PROP GOVERNOR TO ALLOW POWER LEVER TO TRAVEL PROPER DISTANCE. PERFORMED FULL STATIC POWER RUN TO 2680 RPM. OPS CHECK SATISFACTORY. SAFTEY WIRED PROP GOVORNER ADJUSTMENT SCREW. IAW CIRRUS SR 22 AMM CHAPTER 61-20, SECTION 2, STEPS 3(A) - 3(J).

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Warbird Factory under work order: WO_442.

Andres Morales IA 3859420

A handwritten signature in black ink, appearing to read "Andres Morales", written over a horizontal line.