


MAINTENANCE & SERVICE HISTORY



Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
23 June 2016	193	84.1	Removed propeller, taken for inspection at Southcoast Propeller. Propeller return spring replaced. Propeller reinstalled IAW Cessna Service Manual, rev 2, dated 3 June 1996 with propeller bolt torque 700 in-lbs. Bruce Brown AIP 3207478 Bruce Brown	Inspection at Southcoast Propeller replaced. Propeller Manual, rev 2, dated 3 June 1996 with propeller bolt torque 700 in-lbs.
5 May 2017	218.4	150.0	NAIDPF Tach: 3743.0	/A/C TSN: 3758.2
Complied with 100 hr/ANNUAL inspection of propeller assembly Approved for Return to Service For Time to Continue SEE A.D. Report Dated 10 MAY 2017 (16 PAGES)			ASSY	 1975936 AIP

Note: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11 & 12.