WISCONSIN AVIATION

SERVICE BULLETIN COMPLIANCE RECORD

Aircraft, Engine, Propeller

N456AK

Cirrus SR20, S/N 1979

Bulletin Number	Rev. Date	Subject	Date & Hours at Compliance		One Time	Re-occurring	Next Due	
			ACTT	Date			ACTT	Date
2x-05-01	3/11/2009	Brake O-ring replacement schedule	212.7	5/10/10	X		N/A	N/A
2x-21-05	2/17/2012	Cabin Air Coupler Actuator Rigging	367.3	5/25/12	X		N/A	N/A
2x-27-16R1	5/6/2011	Flap Actuator Mod	367.3	5/25/12	X		N/A	N/A
2x-27-17R1	6/3/2013	Electronic Flap Relay Installation	367.3	4/1/16	X		N/A	N/A
2x-32-19R3	***6/26/2012***	***NLG Inspection / Re-enforcement***	***608.5***	***5/1/17***		***X***	***708.5***	***N/A***
2x-52-08	3/3/2016	Catcher/Diverter & Gas Strut Replacement	567.1	4/5/16	X		N/A	N/A
2x-57- 10	8/12/2008	Aileron trailing edge insp.	63.6	10/3/08	X		N/A	N/A
2x-57-13R2	7/31/2012	Lower Landing Gear Attach Bracket Torque	521.4	3/16/15	X		N/A	N/A
2x-71- 04R5	5/24/2007	Winterization kit	63.6	10/8/08	X		N/A	N/A
2x-71- 10R2	3/25/2009	Oil breather line sleeve	123.3	5/8/09	X		N/A	N/A
2x-74-01	11/15/2011	Fine Wire Spark Plugs	367.3	5/25/12	X		N/A	N/A
2x-95-18R4	8/31/2013	CAPS rkt mtr replacment	655.7	12/15/17	X		N/A	N/A
2x-95-24	10/10/2017	Caps rkt shlf grnd wire	655.7	12/15/17	X		N/A	N/A

This form is intended to be a listing of service bulletins, letters and instructions as they relate to this airframe and/or appliance, and is not intended to be a return to service.
See appropriate log book for sign-off.