

Base Coat Colors: SNOW WHITE CMO850102

Use compatible primer and clear per AMM and SW product data sheets

North America 1.888.888.5593 International 316.733.7576 www.swaerospace.com 415 E. Commerce Street Andover, KS (USA) 67002

AIRCRAFT DESCRIPTION
MANUFACTURER CIRRUS DESIGN CORP MODEL SR20 DATE OF MFG. OCT 2019
regial MINARER 2518 REGISTRATION NUMBER N87VB
REGISTERED OWNER Inspection Status (Check one)
STREET ADDRESS
CITY, STATE, ZIP
OPERATOR F.A.R. 91,409 PROGRESSIVE
STREET ADDRESS
CITY, STATE, ZIP
REGISTERED OWNER F.A.R. 135.419 A.T.C.O.
STREET ADDRESSOTHER
ALVE SUFFERE
Orthodox
STREET ADDRESS
(III, SIAIC) AT

		INSTALLED EQL	JIPMENT	
	ITEM	MANUFACTURER	MODEL	SERIAL NO.
	ENGINE	LYCOMING ENGINES	IO-390-(3B6	n 1 - 921- Car
	ENGINE	Les May Craditors	10-390-(386	R
	PROPELLER	HARTZEN PROPENER, INC		
	PROPELLER	TINCIZE PEOPETER, INC	HC-E3YR- IRF	FM 2319B
	ENGINE	Aller		
	ENGINE			
	PROPELLER	1		
· ·	PROPELLER			
	ENGINE			
	-			
	ENGINE			
	PROPELLER			
	PROPELLER			n <sub>e</sub>
	ENGINE			
	ENGINE		-	
	PROPELLER			
	PROPELLER			
			-	
			1/1	
			1	

	MAJOR ALTERATIONS	NAME OF	PART SER	AL INSTAL	RTS OR OVER	LIFELIMIT	REMOVAL	AGENCY
DATE	DESCRIPTION OF ALTERATION	PART	NUMBER NUM	BER DATE/	HOURS AT INSTALL	OR T.B.O.	DATE/HOURS	CERT. NO
			L	Tife Time!	ed Parts SR20			
			II <b>-</b>					
			CAPS Rocket Motor	29500-005	The state of the parameters of the state of	EXPIRES		
			T CATS ROCKET MISSIST	29300-003	SN 3685	09/2029		
	A 15 - 10		CAPS Parachute	25337-005	s/N 001043	/		
			CAPS Reefing Line Cutters	26707-001	S/N:/57/3 S/N:/57/5	06/2025		
	//		ELT Battery Pack	452-6504-1	**	01-2026		
			EMA Controller, AAIR	20902-001	404 Jun 18-9		1-	
			CO Detector	24660-002	sn100934	04-2024		
			Pilot Seat Inflator Assembly	20902-005	Z7/8/7830Z9	02/2029		
			Co-Pilot Seat Inflator Assembly	20902-005	Z7/8/783028	02/2029		
		-						

	1.0	F LIMITI	FD PARTS	OR OVERH	IAUL REO	UIREMENT	S							MPLIANCE RECORD
NAME OF	PART	SERIAL	INSTALLATION	TIME ON PART	LIFE LIMIT OR T.B.O.	REMOVAL DATE/HOURS	AGENCY CERT, NO.	A.D./BULL. NUMBER	ITEM AFFECTED	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. 1 TIME/RECUR.	NEXT COMP. DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.
PART	NUMBER	NUMBER	DATE/HOURS	AT INSTALL	OR I.B.O.	DATE/HOURS	CEMPTO			10/09/2019 1.5HRS	Searched A	D's through b	n-weekly	Whod Thoushor (82.6)
										10/09/2019 1.5485	compliance	at this time.		
										1.5485	All mandatory Corporation M	Service Bulle	tins that apply to	o Cirrus Design have been bable at this time.
											CDC MF	on/o 0	9 2019.	
											Cirrus Design C PC# 338CE	orporation Dui	uun, MN USA	i,
·														
		•												

	AIRWOR	THINESS D	IRECTIVE/F	ACTORY B	ULLETIN COMP	LIANCE RECORD	ALTIMETER & STATIC SYSTEM CHECKS F.A.R. 91.411								
A.D./BULL. NUMBER	ITEM AFFECTED	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. 1 TIME/RECUR.	NEXT COMP. DATE/HRS./CYCLE	AUTHORIZED SIGNATURE CERTIFICATE NO.	DATE	MANUFACTURER	MODEL	SERIAL NO.	LOCATION	MAX. ALT.	RECHECK REQUIRED	APPROVE AGENCY	D BY: CERT. NO.
							\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		reporter test been perforn E & F and TESTED	the altimeter, s required by FA ned and found v AC 43-6C. TO 18,000  der: MfgC  Model: GTZ  S: Model _GS  S/NX/00  S: Model _GS  S/NX/00	R's 91.411, 91 within the limit  FEET  Garmin P/N  X-345R S/N	1.413, & 91.2 1.5 of FAR 43 : ON_9~11- 1_36745-00 N_3EH025	17 have		
									Altimeter	S/N <u>3k400</u> :: Mfg <u>UNI</u> S/N <u>5)U</u>	red_P/N	12731-003	-	*c	
									<ul> <li>CDC Oua</li> </ul>	lity Assuranc sign Corpora	e CDG		- <u>                                     </u>		
,															

.00

# ALTIMETER & STATIC SYSTEM CHECKS F.A.R. 91.411

				1.11. 91.71		RECHECK	APPRO	OVED BY:
MANUF	ACTURER	MODEL	SERIAL NO.	LOCATION	MAX. ALT.	REQUIRED	AGENCY	CERT. NO.
MANUF	FAA Cer L.I. Mac. 631-585- ALTIME Initials Initials	ISLIP AVIO  USE Repair Station  Arthur Airport Rouk  3543  FER(S) REMOVED A  #1 S/N 3  #3 S/N 5  UNITIST RECER  ALTIMETERS W  ALTIMETER TE  AND FOUND TO  INTEGRATION  THIS DATE ANI  IF MAPKE!  ATC TRANSPOTTIS DATE ANI  #1 make/model  #2 make/model	SERIAL NO.  FIJIRIAL KOUKUMIA, NY  ND REINSTALLED KY CO 3 3 0 6  J 6 77 6  THE TESTS AND INSPECTION OF COMPLY WITH FAR RESSURE ALTITUDE. TESTS AND INSPECT OF FOUND TO COMPLY. ALSO COMPLIES WITH FALL OF THE STAND INSPECT OF THE STAND TO COMPLY. ALSO COMPLIES WITH FALL OF THE STAND INSPECT OF THE STAND I	#2 S/N 3 #4 S/N BELE TAGGED SEE A O FEE S REQUIRED BY 91, 411 PART 43, APPENDIX E FQUIPMENT AND AT 10NS REQUIRED BY WITH FAR 91,217 PECTIONS REQUIRE R 43, APPENDIX F. X - 3 4 S R PECTIONS REQUIRE	MAX. ALT.  TENANCE R  DATE:  N#  A/C S/N  TTACHED TEST SHE  I. WERE PERFORMEI PARA a,b,d.  C. TRANSPONDERS FAR 91.413 & 91.413 APP. E PARA, c,d.	ECORD 21-0CT-202 N\$7VB 25 S	AGENCY	


MAKE Cirrus Design Corp DATE 2/11/2020 A/C TSN 95 9 Nassau Flyers Nassau MODEL Sr22 1300 New Hwy Farmingdale, NY 11735 S/N 2518 TACH 95.9 FLYERSX REG NO N87VB WORK ORDER: 6512 **IECKED BY:** URE - CERT. NO. Phone 631-454-0626 Airframe Entries Serviced NLG oleo strut with nitrogen and fluid to proper levels per CAMM, no defects noted. Removed damaged governor control cable bracket and replaced with new. Removed damaged governor control cable clip and replaced with new Removed induction "Y" duct assembly, cleared of all debris, re-installed, and safetied. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times. DATE: 2/11/2020 SIGNED Work Order: 6512 Darion McFadden A&P 4138120 Printed by EBis 3 (datcomedia.com) DATE 4/9/2020 A/C TSN: 140.5 MAKE: Cirrus Design Corp Nassau Flyers NASSAU MODEL Sr20 1300 New Hwy TACH 1405 S/N 2518 REG NO N87VB FLYERSX Farmingdale, NY 11735 Phone 631-454-0626 WORK ORDER: 6571 Airframe Entries Removed top engine cowling, prepped, primed, painted to match and reinstalled cowling on aircraft. This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times. SIGNED: Work Order: 6571 DATE: 4/9/2020 Sean McFadden, A&P 3647763 Printed by EBis 3 (datcomedia.com)

DATE: 11/20/2020 A/C TSN: 404.1 MAKE: Cirrus Design Corp MODEL: Sr20 Nassau Flyers :0 5 5 NASSAU TACH: 404:1 1300 New Hwy S/N: 2518 FLYERS Farmingdale, NY 11735 Phone: 631-454-0626 REG. NO. N87VB WORK ORDER: 6705 Airframe Entries Removed loaner ELT batteries and replaced with new (Expires: 1/2027), Performed operational check of same, no defects noted. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times Work Order: 6705 DATE: 11/20/2020 SIGNED: Printed by EBis 3 (datcomedia.com) Darion McFadden, A&P: 4138120 ı) MAKE Cirrus Design Corp Nassau Flyers DATE 12/18/2020 A/C TSN 449 3 6 2 6 2 Nassau MODEL: Sr20 S/N: 2518 1300 New Hwy Farmingdale, NY 11735 TACH: 449 3 FLYERS REG NO N87VB WORK ORDER: 6724 Phone 631-454-0626 Airframe Entries · Removed snapped left cabin door latch cable and replaced with new. Removed bent LH interior door handle and replaced with new Performed an operational check of the same, no defects noted. · Removed bent LH interior door handle axle and replaced with new. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times m) DATE: 12/18/2020 SIGNED: Work Order: 6724 Mohammed Farhanuddin, A&P 4183289 Printed by EBis 3 (datcomedia.com)

MAKE, Cirrus Design Corp MCDEL, Sr20 Nassau Flyers DATE 5/19/2020 A/C TSN: 180.5 TACH: 180.5 Nassau S/N 2518 REG NO N87VB WORK ORDER 6588 1300 New Hwy Farmingdale NY 11735 Phone 631-454-0626 FLYERS Airframe Entries Installed new inspection cover under LH horizontal stabilizer where previously missing. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times DATE: 5/19/2020 SIGNED: Work Order: 6588 Darion McFadden, A&P: 4138120 Printed by EBis 3 (datcomedia.com) MAKE, Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK OF DER: 6685 DATE 10/9/2020 A/C TSN 376 2 TACH 376 2 Nassau Flyers Nassau 1300 New Hwy Farmingdale NY 11735 Phone 631-454-0626 FLYERS Airframe Entries Removed peeling nose strut fairing seal trim and replaced with new Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times. DATE: 10/9/2020 SIGNED: Work Order: 6685 Darion McFadden, A&P, 4138120 Printed by EBis 3 (datcomedia\_com)

D/ COM	MAKE: Cirrus Design Cor MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6894	rp	NASSAU FLYERS X	Nassau Flyers 1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626	DATE: 8/10/2021 A/C TSN: 736.4 TACH: 736.4
	Airframe Entries Removed erratic CH	IT probe and replaced w	ith new Performed a	an operational check of sam	ie, no defects noted
	manufacturers recommer	ndations and was found to be	e in airworthy condition.	This aircraft, engine, propeller of	urrent Federal Aviation Regulations and or component(s) is approved for return to
	DATE: 8/10/2021	k performed and described : SIGNED:	Dis date and time	11-11	Work Order: 6894
F_		Darion McFado	den, A&P: 4138120		Printed by EBis 3 (datcomedia.com
	MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6909		FLYERS A 1300	SSAU Flyers D New Hwy ningdale, NY 11735 ne, 631-454-0626	DATE: 8/27/2021 A/C TSN: 770.6 TACH: 770.6
=	Airframe Entries  Serviced low NLG oleo str Replaced cracked NLG wl Installed new NLG wheel f Installed new NLG wheel	neel fairing forward cap fairing stripes	with new, Prepped/p	nd pressure. rimed/painted to match.	¥.
7	Maintenance Release  This aircraft, engine, propeller or manufacturers recommendation service regarding the work performance.	s and was found to be in ain	worthy condition. This a	ted in accordance with current ligraft, engine, propeller or comp	ederal Aviation Regulations and expendit of the second for return to
		SIGNED:			Work Order: 6909

DATE 5/27/2021 Nassau Flyers MAKE Cirrus Design Corp NASSAU A/C TSN 640 MODEL: Sr20 1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626 TACH 640 S/N 2518 FLYERSX REG NO N87VB WORK ORDER 6838 **Airframe Entries** Replaced missing Right aileron gap seal with new. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times Work Order: 6838 SIGNED: DATE: 5/27/2021 Printed by EBis 3 (datcomedia.com) Sean McFadden, A&P. 3647763 DATE 7/13/2021 A/C TSN 684.3 TACH 684.3 MAKE Cirrus Design Corp MODEL Sr20 Nassau Flyers NASSAU 1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626 FLYERSX S/N 2518 REG NO N87VB WORK ORDER 6872 Airframe Entries Removed and replaced broken static wick on right wingtip Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this pate and times Work Order 6872 SIGNED DATE: 7/13/2021 Printed by EBis 3 (datcomedia com) Mohammed Farhanuddin, A&P 4183289



MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6987



#### Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 12/16/2021 A/C TSN: 932 2 TACH: 932 2

۸	inf	<b>F</b> 2	m	n 1	=n	tri	90

Maintenance Release

- · Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-25.
- \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due
- \*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.
- \*Serviced gascolator IAW Cirrus AMM 28-20.
- \*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.
- \*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.
- \*C/WICA Concorde Sealed Battery, no defects noted.
- \*C/W FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 01/2027.
- Replaced both #2 batteries with new (P/N: 50979-001). Performed an operational check of same, no defects noted.
- Replaced muffler with new (P/N: 21878-001).
- Removed worn LMLG and RMLG brake linings and replaced with new (P/N: 31392-105).
- Removed worn LMLG tire and replaced with new (P/N: 14075-010).
- Performed cosmetic re-seal on worn baggage window seal (P/N: 51206-001).
- Replaced broken LH front cup holder with new (P/N: 51179-001).
- Repaired broken RH front cup holder.
- Updated FS510 firmware from version 2,33 to version 2.71, performed operational check of same, no defects noted
- Troubleshot engine not starting, found ignition booster fuse burnt and ignition booster inoperative. Replaced fuse and booster with new (P/N: 35133-001; S/N off: 19066815, S/N on: 21028921). Performed an operational check on run-up, no defects noted.

This aircraft, engine, propeller manufacturers recommendation service regarding the work per	or component(s) on N87VB were repaired an ons and was found to be in airworthy condition formed and described above, this date and to	nd inspected in accordance wi n. This aircraft, engine, propell mes	th current Federal Aviation Regulations and ter or component(s) is approved for return to
DATE: 12/16/2021	SIGNED A	M(b)	Work Order: 6987
	John Magnowski, ASP 3273394		Printed by EBis 3 (datcomedia.com)

	MAKE Cirrus Design Corp MODEL, Sr20 S/N: 2518	NASSAU FLYERS×	Nassau Flyers 1300 New Hwy	DATE: 1/16/2022 A/C TSN: 949 9 TACH: 949 9	
	REG NO N87VB WORK ORDER 7008		Farmingdale, NY 11735 Phone: 631-454-0626		
7=-	Airframe Entries				
v~·,	Removed worn RMLG wh	eel assembly and replaced with service	able spare for repositioning		
V*1	Maintenance Release				
v= <u>,</u>	manufacturers recommendation	r component(s) on N87VB were repaired and is and was found to be in alloworthy condition ormed and described above, this date and time	This aircraft engine propeller or	rent Federal Aviation Regulations and component(s) is approved for return to	
,-,	DATE: 1/16/2022	SIGNED: DE M	///	Work Order: 7008	
,u,	-	Darion McFadden, A&P 4138120		Printed by EBis 3 (datcomedia.com)	
,				*	
, Y	MAKE, Cirrus Design Corp MODEL, Sr20	NASSAU	Nassau Flyers	DATE_1/27/2022 A/C TSN_960 2	
٧٠,	S/N 2518 REG NO N87VB WORK ORDER 7014	FLYERS	1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626	TACH 960 2	
H	Airframe Entries				
, <u>.</u>	⊴ Replaced missing LH ail	eron gap seal with new.			
y-t)	Maintenance Release				
<i></i>	manufacturers recommendation	or component(s) on N87VB were repaired and ons and was found to be in airworthy condition formed and described above, this date and time	This aircraft, engine propeller of	urrent Federal Aviation Regulations and r component(s) is approved for return to	
~~	DATE: 1/27/2022	SIGNED:		Work Order: 7014	
·/,	E	Mohammed Farhanuddin, A&P: 41832	289	Printed by EBis 3 (datcomedia.com)	
	8				
<b>₩</b> /^—	- 1	+			
H					
V-1					
***~					

m,

# MAINTENANCE RECORD F.A.R. 43.9

MAKE Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG NO: N87VB WORK ORDER: 7066



#### Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 4/1/2022 A/C TSN: 1026.5 TACH: 1026.5

Δ	irframo	Entries
	ııııaıııe	cillies

- Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2022-07
- \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.
- \*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.
- \*Serviced gascolator IAW Cirrus AMM 28-20.
- \*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.
- \*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.
- \*C/W ICA Concorde Sealed Battery, no defects noted.
- \*C/W FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 01/2027.
- C/W Cirrus SA21-06, Release of Beringer Service Bulletin SB-019, Brake Backstop Replacement EA-00X and EA-004X, by replacing both MLG backstops with new (P/N: 31392-109).
- Replaced LH main axle due to fairing thread damage (P/N: 31491-001).
- Removed worn LMLG and RMLG brake linings and replaced with new (P/N: 31392-105).
- Removed worn RMLG tire and replaced with new (P/N: 14075-010).
- Removed nose fork assembly, cleaned and re-installed with new grease and hardware. Set nose fork to proper tension per CAMM.
- Removed cracked fuel flow sensor assy and replaced with new (P/N: 15415-003; S/N off: 222437, S/N on: 233554). Ops check OK.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to

DATE: 4/1/2022 SIGNED

John Maghowski, ASP 32/3394

Work Order: 7066

	MAKE: Cirrus Design Corp MODEL: Sr20 SN: 2518 REG NO: N87VB WORK ORDER: 7004  Airframe Entries  NASSAU FLYERS 1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626	DATE: 1/12/2022 A/C TSN: 948 TACH: 948
<u> </u>	<ul> <li>Troubleshot pilot report, "both cup holders will not close." Found pilot and co-pilot cup hotherefore repaired both. OK for service.</li> <li>Troubleshot pilot report, "pilot side seatbelt twisted," and untwisted twisted pilot side seatbelt.</li> </ul>	
	Maintenance Release  This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance we manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, proper service regarding the work performed and described above, this date and times.	vith current Federal Aviation Regulations and eller or component(s) is approved for return to
# <del></del>	DATE: 1/12/2022 SIGNED:	Work Order: 7004
	Mohammed Farhanuddin, A&P. 4183289	Printed by EBis 3 (datcomedia.com)
	MAKE: Cirrus Design Corp MODEL: 5r20 S/N: 2518 REG. NO: N87VB WORK ORDER: 7066  Nassau Flyers 1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626	DATE 4/1/2022 A/C TSN 1026 5 TACH 1026 5
	Airframe Entries  I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy c/w all AD's due this inspection.	inspected in accordance with an Annual condition. AD's checked through this date,
	Maintenance Release	1
W	This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance of manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, proper service regarding the work performed and described above, this date and times	with current Federal Aviation Regulations and eller or component(s) is approved for return to
V-1,	DATE: 4/1/2022 SIGNED	Work Order: 7066
	John Magyowski, TA 3273394	Printed by EBis 3 (datcomedia.com)
V-,		

Mili

INSPECTION RECORD F.A.R. 43.11-91.409

ICATE NO. RNED TO SERVICE

KIND OF INSPECTION-STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE AIRCRAFT TIME IN SERVICE DATE CIRRUS OCT 19 Production Flight Test accomplished in accordance with Cirrus Procedure #90500. Name: Chad Friedrich Title: Production Flight Test Pilot 2\_\_\_\_\_Date: 80ct 19 Signature: \_\_( DCT/2019 I find that the aircraft meets the requirements for the certification requested and have issued an U.S. Standard Airworthiness Certificate dated 09 / OCT / 2019. The next inspection is due 31 /oct /2020. Aaron S. Knudsen 293766879

DATE: 10/25/2019 MAKE: Cirrus Design Corp Nassau Flyers A/C TSN: 22 1 MODEL Sr20 TACH: 22 1 1300 New Hwy S/N: 2518 Farmingdale, NY 11735 Phone 631-454-0626 REG. NO: N87VB WORK ORDER: 6427 Airframe Entries Performed a 25 hour inspection of airframe per Cirrus AMM and Cirrus inspection checklists, Chaps 05-02 and 05-30 \*Serviced fuel gascolator no defects noted Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times Work Order: 6427 DATE: 10/25/2019 SIGNED: Printed by EBis 3 (datcomedia com) Darion McFadden A&P 4138120 DATE: 11/29/2019 Nassau Flyers MAKE: Cirrus Design Corp MODEL Sr20 A/C TSN 523 TACH 52.3 1300 New Hwy S/N. 2518 Farmingdale, NY 11735 Phone: 631-454-0626 REG NO N87VB WORK ORDER 6455 Airframe Entries Performed a 50 hour inspection of airframe per Cirrus AMM and Cirrus inspection checklists. Chaps 05-02 and 05-30 \*Serviced airframe interior and exterior including lights, batteries, struts, tires brakes, fluids and screens Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times Work Order: 6455 DATE 11/29/2019 SIGNED: Jasmit Singh, A&P. 4099112 Printed by EBis 3 (datcomedia com)

MAKE: Cirrus Design Corp MODEL: Sr22 S/N: 2518 REG. NO: N87VB WORK ORDER: 6512



## Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 2/11/2020 A/C TSN: 95 9 TACH: 95 9

#### Airframe Entries

Performed a 100 hour inspection of airframe per Cirrus AMM and Cirrus inspection checklists, Chaps 05-02 and 05-30

\*Serviced airframe interior and exterior including lights, batteries, struts, tires brakes, fluids and screens

\*C/W ICA Concorde Sealed Battery, no defects noted

\*C/W FAR 91 207 ELT Inspection, no defects noted. ELT Battery expiration date 1/2026

Removed worn LMLG and RMLG brake linings and replaced with new

Removed worn LMLG and RMLG tires and replaced with new

Re-attached both LMLG and RMLG fairings grommets to strut

Disassembled, cleaned, inspected, reassembled NLG fork assembly and set tension per CAMM.

Removed worn "Rescue" placard from co-pilot door and replaced with new.

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 2/11/2020

SIGNED: John Daniel III. A&P 4208140

Work Order: 6512

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL: Sr22 S/N: 2518 REG. NO: N87VB WORK ORDER: 6512



## Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 2/11/2020 A/C TSN: 95.9 TACH: 95.9

### **Airframe Entries**

I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection.

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 2/11/2020

SIGNED

Work Order: 6512

Sean McFadden, IA: 3647763

MAKE Cirrus Design Corp MCDEL Sr20 DATE: 4/2/2020 A/C TSN: 140.5 Nassau Flyers NASSAU S/N 2518 REG NO N87VB 1300 New Hwy Farmingdale, NY 11735 TACH 1405 FLYERSX WORK ORDER: 6570 Phone 631-454-0626 Airframe Entries \*Performed airframe 50 Hrl inspection IAW Cirrus AMM 5-201 \*Serviced gascolator IAW Cirrus AMM 28-20 \*Serviced brake fluid reservoir IAW Cirrus AMM 12-10. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times. DATE: 4/2/2020 SIGNED: Work Order: 6570 Sean McFadden, A&P. 3647763 Printed by EBis 3 (datcomedia.com) MAKE, Cirrus Design Corp DATE: 6/18/2020 Nassau Flyers MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER 6598 A/C TSN 196 1 TACH 196 1 1300 New Hwy Farmingdale NY 11735 Phone 631-454-0626 Airframe Entries \* I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection. Maintenance Release This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times on. This aircraft, engine propeller or component(s) is approved for return to DATE: 6/18/2020 SIGNED: Work Order: 6598 Sean McFadden, IA: 3647763 Printed by EBis 3 (datcomedia.com)

# INSPECTION RECORD F.A.R. 43.11-91.409

MAKE Cirrus Design Corp MODEL: \$r20 SIN: 2518 REG. NO: N87VB WORK ORDER: 6598  Airframe Entries  Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-11.  Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.  Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.  Serviced gascolator IAW Cirrus AMM 28-20.  Serviced gascolator IAW Cirrus AMM 12-10.  *Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  *C/W Cirrus SB2X-91-02 Airplane Wiring, Backshell Strain Relief, by inspection. No defects noted.  *Removed worn LMLG and RMLG brake linings and replaced with new.  Removed worn RMLG tire and replaced with new.  Maintenance Release  This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times  **DATE: 6/18/2020**  **Work Order: 6598**	MODEL \$720 \$7/N. 2518 REG. NO. N87VB WORK ORDER. 6598  Airframe Entries  Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-11.  *Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.  *Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.  *Serviced gascolator IAW Cirrus AMM 28-20.  *Serviced brake fluid reservoir IAW Cirrus AMM 12-10.  *Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  *C/W Cirrus SB2X-91-02 Airplane Wiring, Backshell Strain Relief, by inspection. No defects noted.  *Removed worn LMLG and RMLG brake linings and replaced with new.  *Maintenance Release  This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.	MODEL Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6598  Airframe Entries  Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-11.  Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.  Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.  Serviced gascolator IAW Cirrus AMM 28-20.  Serviced brake fluid reservoir IAW Cirrus AMM 12-10.  Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.  *C/M FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 1/2026.  C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  C/W Cirrus SB2X-91-02 Airplane Wiring, Backshell Strain Relief, by inspection. No defects noted.  Removed worn LMLG and RMLG brake linings and replaced with new.  Removed worn RMLG tire and replaced with new.  Maintenance Release  This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times  DATE: 6/18/2020  SIGNED:  Work Order: 6598		IRCRAFT TIME IN SERVICE	SIGNATURE -	KIND OF INSPECTION-STATUS & DIS - CERT. NO. OF PERSON APPROVING OR DIS	
Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-11.  *Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.  *Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.  *Serviced gascolator IAW Cirrus AMM 28-20.  *Serviced brake fluid reservoir IAW Cirrus AMM 12-10.  *Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 1/2026.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kill.  *C/W Cirrus SB2X-91-02 Airplane Wiring, Backshell Strain Relief, by inspection. No defects noted.  *Removed worn LMLG and RMLG brake linings and replaced with new.  *Removed worn RMLG tire and replaced with new.  *Maintenance Release  This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.	Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-11.  *Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.  *Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.  *Serviced gascolator IAW Cirrus AMM 28-20.  *Serviced brake fluid reservoir IAW Cirrus AMM 12-10.  *Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  *C/W Cirrus SB2X-91-02 Airplane Wiring, Backshell Strain Relief, by inspection. No defects noted.  *Removed worn LMLG and RMLG brake linings and replaced with new.  *Removed worn RMLG tire and replaced with new.  *Maintenance Release  This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.  **DATE: 6/18/2020**  **Service daircraft records aircraft engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.  **DATE: 6/18/2020**  **Service daircraft records aircraft engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.	Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-11.  *Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.  *Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.  *Serviced gascolator IAW Cirrus AMM 28-20.  *Serviced brake fluid reservoir IAW Cirrus AMM 12-10.  *Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W ICA Concorde Sealed Battery, no defects noted.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  *C/W Cirrus SB2X-71-32R1, Engine Driven Fuel Pump Heat Shroud Removal, by removal of heat shroud and installation of kil.  *C/W Cirrus SB2X-91-02 Airplane Wiring, Backshell Strain Relief, by inspection. No defects noted.  *Removed worn LMLG and RMLG brake linings and replaced with new.  *Removed worn RMLG tire and replaced with new.  *Maintenance Release  This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.  **DATE: 6/18/2020**  **Serviced pascellation and the work performed and described above, this date and times.**  **Work Order: 6598**	MODEL SI SINI 2518 REG. NO. I WORK OR	20 N87VB DER: 6598		1300 New Hwy Farmingdale, NY 11735	A/C TSN 196.1
This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.	This aircraft engine propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.  DATE: 6/18/2020 SIGNED: Work Order: 6598	This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.  DATE: 6/18/2020  SIGNED:  Work Order: 6598	*Research *Performe *Serviced *Serviced *Lubricate *C/W ICA *C/W FAR • C/W Cirr • C/W Cirr	ned aircraft records for applied airframe 100 hour inspect gascolator IAW Cirrus AMM brake fluid reservoir IAW Concorde Sealed Battery, r 8 91.207 ELT Inspection, no us SB2X-71-32R1, Engine tus SB2X-91-02 Airplane Widworn LMLG and RMLG br	cable Cirrus Mandatory S ion IAW Cirrus AMM 5-2 128-20. irrus AMM 12-10. 12-20 lubrication schedul to defects noted. defects noted. ELT Batte Driven Fuel Pump Heat S iring, Backshell Strain Re take linings and replaced	Service Bulletins that are due.  6.  e.  ery expiration date 1/2026, Shroud Removal, by removal of heat sl lief, by inspection. No defects noted.	
	Darion McFadden, A&P, 4138120 Printed by EBis 3 (datcomedia.com)	Darion McFadden, A&P 4138120 Printed by EBis 3 (datcomedia.com)	-	e Release	c(s) on N87VB were repaired	and inspected in accordance with current Fe	deral Aviation Regulations and

MAKE: Cirrus Design Corp MODEL Sr20 S/N. 2518 REG NO N87VB WORK ORDER: 6614



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 6/30/2020 A/C TSN: 247.4 TACH: 247.4

#### Airframe Entries

- · Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-13.
- \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.
- \*Performed airframe 50 Hr. inspection IAW Cirrus AMM 5-20.
- \*Serviced gascolator IAW Cirrus AMM 28-20.
- \*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.
- · C/W Cirrus SB2X-76-04, Power Control Hard Contact Between Elevator and Throttle Cables, by installation of adel clamps.
- Removed worn LMLG tire and replaced with new.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 6/30/2020

SIGNED:

Work Order: 6614

Darion McFadden, A&P, 4138120

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG NO: N87VB WORK ORDER: 6642



Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 8/25/2020 A/C TSN 296 4 TACH: 296.4

#### Airframe Entries

· I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition, AD's checked through this date, c/w all AD's due this inspection.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times

DATE: 8/25/2020

SIGNED:

Work Order: 6642

Sean McFadden, IA 3647763

# **INSPECTION RECORD**

F.A.R. 43.11-91.409 KIND OF INSPECTION-STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE AIRCRAFT TIME IN SERVICE DATE DATE: 8/25/2020 MAKE: Cirrus Design Corp MODEL Sr20 Nassau Flyers NASSAU A/C TSN: 296 4 1300 New Hwy Farmingdale, NY 11735 TACH: 296.4 REG NO: N87VB WORK ORDER: 6642 Phone 631-454-0626 **Airframe Entries** Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-16.
\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.
\*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.
\*Serviced gascolator IAW Cirrus AMM 28-20.
\*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.
\*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule. \*C/W ICA Concorde Sealed Battery, no defects noted. \*C/W FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 1/2026. Removed worn LMLG and RMLG brake linings and replaced with new. Removed cracked vertical heat shield from #4 exhaust stack and replaced with new Re-attached peeling LMLG grommets to gear leg, no further defects noted. Removed worn RMLG tire and replaced with new. Removed cracked induction plenum and replaced with new Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times. SIGNED: Work Order: 6642 DATE: 8/25/2020 Darion McFadden, A&P 4138120 Printed by EBis 3 (datcomedia.com)

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER 6675



# Nassau Flyers

1300 New Hwy Farmingdale NY 11735 Phone 631-454-0626 DATE 9/21/2020 A/C TSN: 351.6 TACH: 351.6

#### **Airframe Entries**

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due

Sean McFadden, A&P, 3647763

\*Performed airframe 50 Hr. inspection IAW Cirrus AMM 5-20.

\*Serviced gascolator IAW Cirrus AMM 28-20

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Maintenance Releas

This aircraft, engine propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 9/21/2020

SIGNED:

Work Order: 6675

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6701 NASSAU FLYERS

## Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 11/17/2020 A/C TSN: 396.1 TACH: 396.1

#### **Airframe Entries**

I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above. This date and times

DATE: 11/17/2020

SIGNED:

Work Order: 6701

Sean McFadden, IA 3647763

# INSPECTION RECORD F.A.R. 43.11-91.409

MAKE: Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER: 6701



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 11/17/2020 A/C TSN: 396.1 TACH: 396.1

#### Airframe Entries

- Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-23.
- \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.
- \*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.
- \*Serviced gascolator IAW Cirrus AMM 28-20.
- \*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.
- \*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.
- \*C/W ICA Concorde Sealed Battery, no defects noted.
- \*C/W FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 01/2026.
- C/W Cirrus SB2X-53-10, Alternate Cabin Door Seal Installation, by installation of new door seal. No defects noted
- Removed dead ELT battery pack and installed loaner from N238RS. Performed operational check of same, no defects noted.

  Removed worn LMLG and RMLG brake linings and replaced with new.
- Removed worn LMLG tire and replaced with new.
- Replaced fraying left upper engine mount ground strap with new.
- \* Removed corroded rudder bellcrank rod end and replaced with new, using new hardware.
- · Removed cracked induction plenum and replaced with new
- Removed pealing nose strut fairing seal trim and replaced with new.
- Removed worn cowl seal tape from lower left cowling and replaced with new.
- Removed nose fork assembly, cleaned and re-installed with new grease and hardware.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 11/17/2020

SIGNED:

Work Order: 6701

Mohammed Farhanuddin, A&P, 4183289

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG NO N87VB WORK ORDER: 6721



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phonel 631-454-0626 DATE 12/11/2020 A/C TSN 443 6 TACH 443 6

# Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-25,

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 50 Hr. inspection IAW Cirrus AMM 5-20.
\*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

· Removed and replaced broken clamp.

· Removed worn cowl seal tape from lower right cowling and replaced with new.

Maintenance Release

This aircraft engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times

DATE: 12/11/2020

SIGNED:

Work Order: 6721

Mohammed Farhanuddin, A&P: 4183289

Printed by EBis 3 (datcomedia.com)

MAKE Cirrus Design Corp MODEL: Sr20 S/N 2518 REG NO N87VB WORK ORDER: 6731



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 1/6/2021 A/C TSN 462.9 TACH 462.9

# Airframe Entries

· I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date

DATE: 1/6/2021

SIGNED:

Sean McFadden, IA 3647763

Work Order: 6731

# INSPECTION RECORD F.A.R. 43.11-91.409

MAKE Cirrus Design Corp MODEL Sr20 S/N: 2518 REG NO N87VB WORK ORDER 6731



## Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 1/6/2021 A/C TSN 462.9 TACH 4629

#### Airframe Entries

- Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2020-26.
- \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.
- \*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20.
  \*Serviced gascolator IAW Cirrus AMM 28-20.
- \*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.
- \*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.
- \*C/W ICA Concorde Sealed Battery, no defects noted,
- \*C/W FAR 91,207 ELT Inspection, no defects noted. ELT Battery expiration date 1/2027.
- \* C/W Cirrus SB2X-32-25, Oleo Strut Production Number Inspection, by inspection. Oleo strut does not need to be replaced by production number (0719-2).
- C/w 500 hour inspection on alternator #1 by replacing worn brush holder assembly.
- C/w 500 hour inspection on alternator #2 by replacing worn brush holder assembly
- Replaced both expired #2 batteries (P/N: 50979-001) with new. Performed an operational check of same, no defects noted.
- Removed worn LMLG tire and replaced with new.
- Removed worn RMLG tire and replaced with new.
- Removed worn LMLG and RMLG brake linings and replaced with new.
- Removed worn NLG tire and replaced with new and serviced to proper inflation pressure,
- Removed both cracked NLG wheel pant brackets and replaced with new.
- Removed nose fork assembly, cleaned and re-installed with new grease and belleville washers.
- Adjusted LH cabin door actuation assembly. Performed operational check, no defects noted
- Removed cracked induction plenum assembly and replaced with new.
- Removed damaged propeller governor control cable and replaced with new,

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times

DATE: 1/6/2021

SIGNED:

Work Order: 6731

Mohammed Farhanuddin, A&P 4183289

MAKE: Cirrus Design Corp MODEL Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6762



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626

DATE: 2/22/2021 A/C TSN: 510.4 TACH: 510,4

#### Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-04.

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 50 Hr. inspection IAW Cirrus AMM 5-20.
\*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Removed cracked induction plenum and replaced with new

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this data and times.

DATE: 2/22/2021

SIGNED:

Work Order: 6762

Mohammed Farhanuddin, A&P: 4183289

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL Sr20 S/N: 2518 REG NO N87VB WORK ORDER 6792



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone, 631-454-0626 DATE: 3/24/2021 A/C TSN: 556.3 TACH: 556.3

#### **Airframe Entries**

Toertify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection.

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, his date and times

DATE: 3/24/2021

SIGNED:

Work Order: 6792

Sean McFadden, IA: 3647763

DATE	AIRCRAFT TIME IN SERVICE	SIGNATURE — CE	KIND OF INSPECTION-STATUS & RT. NO. OF PERSON APPROVING O	DISCREPANCY LIST R DISAPPROVING AIRCRAFT FOR SERVICE
M( S/I RE W(	AKE Cirrus Design Corp DDEL: Sr20 N: 2518 EG. NO: N87VB ORK ORDER: 6792 irframe Entries	NASSAU FLYERS X	Nassau Flyers 1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626	DATE: 3/24/2021 A/C TSN: 556,3 TACH: 556,3
*R *P *S *S *L	Researched aircraft records for ap tesearched aircraft records for ap terformed airframe 100 hour inspe erviced gascolator IAW Cirrus AM erviced brake fluid reservoir IAW ubricated aircraft IAW Cirrus AMN WICA Concorde Sealed Battery Removed ELT 1000 due to firing fa	plicable Cirrus Mandatory Servection IAW Cirrus AMM 5-20.  JM 28-20. Cirrus AMM 12-10.  JM 12-20 lubrication schedule.  JM 10-00 no defects noted.	ice Bulletins that are due.	
F.A - F - F - F - F	AR 91.207 ELT Inspection, no defi- Removed worn LMLG brake lining Removed worn RMLG brake lining Removed worn RMLG tire and rep Removed cracked induction plenu Removed nose fork assembly, clean AMM.	ects noted. New ELT Battery e is and replaced with new. g and replaced with new. placed with new. m and replaced with new.	opiration date 01/2027.	
F.4 - F. - F. - F. - C.4 - Ma - Th.	AR 91.207 ELT Inspection, no defi Removed worn LMLG brake lining Removed worn RMLG brake lining Removed worn RMLG tire and rep Removed cracked induction plenu Removed nose fork assembly, clea	ects noted, New ELT Battery e is and replaced with new, g and replaced with new, laced with new, m and replaced with new, aned and re-installed with new ent(s) on N87VB were repaired and s found to be in airworthy condition.	grease and hardware. Set nos  inspected in accordance with curren This aircraft, engine, propeller or cor	se fork to proper tension per
FA F	AR 91.207 ELT Inspection, no deficemoved worn LMLG brake lining Removed worn RMLG brake lining Removed worn RMLG tire and represented with the same set of the	ects noted, New ELT Battery e is and replaced with new, g and replaced with new, laced with new, m and replaced with new, aned and re-installed with new ent(s) on N87VB were repaired and s found to be in airworthy condition.	grease and hardware. Set nos  inspected in accordance with curren This aircraft, engine, propeller or cor	se fork to proper tension per

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER: 6823



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626

DATE: 5/10/2021 A/C TSN 603 5 TACH 603 5

#### Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly.

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 50 Hr. inspection IAW Cirrus AMM 5-20.

\*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Installed RMLG outboard fairing attach screw where previously missing.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 5/10/2021

SIGNED

Work Order: 6823

Sean McFadden, A&P 3647763

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL: Sr20 S/N 2518 REG. NO: N87VB WORK ORDER: 6846



#### Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE 6/17/2021 A/C TSN 656.8 TACH 656.8

#### Airframe Entries

I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date. c/w all AD's due this inspection.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 6/17/2021

SIGNED

Work Order: 6846

Sean McFadden, IA: 3647763

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6846



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 6/17/2021 A/C TSN: 656.8 TACH: 656.8

#### Airframe Entries

· Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-12,

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20. \*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.

\*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule.

\*C/W ICA Concorde Sealed Battery, no defects noted.

\*C/W FAR 91.207 ELT Inspection, no defects noted. ELT Battery expiration date 01/2027.

· Removed worn LMLG and RMLG brake linings and replaced with new

· Removed worn LMLG tire and replaced with new.

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 6/17/2021 SIGNED: Mohammed Farhanuddin, A&P: 4183289 Work Order: 6846

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER 6882



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 7/23/2021 A/C TSN: 698.5 TACH: 698.5

### Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-15

Researched aircraft records for applicable Airworthness Directives through current bi-week Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due Performed airframe 50 hr inspection IAW Cirrus AMM 5-20. Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Removed cracked LH aft engine baffle and replaced with new Removed and replaced cracked LH side aft baffle with new

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N37VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE 7/23/2021

SIGNED

Work Order | 6882

Mohammed Farhanuddin, A&PI 4183289

Printed by EBis 3 (datcomedia com)

MAKE Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG NO N87VB WORK ORDER 6898



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626

DATE 8/18/2021 A/C TSN 752.4 TACH 752.4

# Airframe Entries

I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 8/18/2021

SIGNED

Sean McFadden, IA 3647763

Work Order 6898

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG NO N87VB WORK ORDER: 6898



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626

DATE 8/18/2021 A/C TSN: 752 4 TACH 752 4

#### Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-16

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20

\*Serviced gascolator IAW Cirrus AMM 28-20

\*Serviced brake fluid reservoir IAW Cirrus AMM 12-10.

\*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule

\*C/W FAR 91 207 ELT Inspection, no defects noted.

\*C/W FAR 91 207 ELT Inspection, no defects noted.

\*C/W FAR 91 207 ELT Inspection, no defects noted. ELT Battery expiration date 01/2027.

Removed worn LMLG and RMLG brake linings and replaced with new.

Removed worn RMLG tire and replaced with new

Removed worn cowl seal tape from top cowling and replaced with new

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 8/18/2021

SIGNED

9

Work Order 6898

Printed by EBis 3 (datcomedia com)

DATE: 9/16/2021 A/C TSN: 801.8 TACH: 801.8

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 6924



## Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

#### **Airframe Entries**

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-19.

\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 50 hr inspection IAW Cirrus AMM 5-20.

\*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 9/16/2021

SIGNED: 矣

Work Order: 6924

Darion McFadden, A&P: 4138120

# **INSPECTION RECORD**

F.A.R. 43.11-91.409 KIND OF INSPECTION-STATUS & **DISCREPANCY** LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE AIRCRAFT TIME DATE MAKE Cirrus Design Corp MODEL Sr20 S/N: 2518 REG NO: N87VB DATE: 10/12/2021 A/C TSN 838 7 TACH: 838 7 Nassau Flyers NASSAU 1300 New Hwy Farmingdale, NY 11735 Phone, 631-454-0626 FLYERSX WORK ORDER 6939 Airframe Entries Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-21. \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due \*Performed airframe 100 hour inspection IAW Cirrus AMM 5-20 \*Serviced gascolator IAW Cirrus AMM 28-20. \*Serviced brake fluid reservoir IAW Cirrus AMM 12-10. \*Lubricated aircraft IAW Cirrus AMM 12-20 lubrication schedule \*C/W ICA Concorde Sealed Battery, no defects noted. \*C/W FAR 91 207 ELT Inspection, no defects noted, ELT Battery expiration date 01/2027. C/W Cirrus SB2X-42-22R1, Perspective+ S/W Update v2647 N8, by updating and configuring software. Performed operational check of same no defects noted C/W GMU44 Magnetometer Calibration Check, no defects noted. Removed worn LMLG and RMLG brake linings and replaced with new. Replaced cracked Induction plenum assembly with new.
Replaced broken left cabin door exterior door handle with new and performed an operational check of same, no defects noted. Removed damaged cylinder #3 exhaust header and replaced with new Removed worn exhaust tailpipe and replaced with new Removed worn cowl seal tape from right cowling and replaced with new Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times. SIGNED Mohammed Farhanuddin, A&P 4183289 Printed by EBis 3 (datcomedia com)

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER: 6939



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE 10/12/2021 A/C TSN: 838 7 TACH: 838 7

#### Airframe Entries

I certify that this Aircraft (including airframe, engine, propeller and appliance) has been inspected in accordance with an Annual inspection as outlined in FAR 43 Appendix D, and was determined to be in an airworthy condition. AD's checked through this date, c/w all AD's due this inspection.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 10/12/2021

SIGNED

Sean McFadden, IA: 3647763

Work Order: 6939

Printed by EBis 3 (datcomedia.com)

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER 6970



### Nassau Flyers

1300 New Hwy Farmingdale NY 11735 Phone 631-454-0626

DATE 11/12/2021 A/C TSN 890 9 TACH 890 9

#### Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2021-23 \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due

\*Performed airframe 50 hr inspection IAW Cirrus AMM 5-20.

\*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. The service regarding the work performed and described above, this pute and times (aff, engine, propeller or component(s) is approved for return to

DATE: 11/12/2021

Work Order: 6970

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER, 7011



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626

DATE 1/21/2022 A/C TSN 950 6 TACH 950 6

# Airframe Entries

· Removed worn LMLG tire and replaced with new.

Removed loaner RMLG wheel and re-installed original with new tire.

Replaced inoperable pitot tube with new (P/N: 20919-001; S/N off: AS07193665, S/N on: AS10213714), Performed an operational Replaced inoperable pitot tube with new (P/N: 20919-001; S/N off: AS07193665, S/N on: AS10213714). check of the same, no defects noted.

Performed pitot system leak check, no defects noted

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 1/21/2022

SIGNED:

Work Order: 7011

Darion McFadden, A&P: 4138120

Printed by EBis 3 (datcomedia.com)

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO N87VB WORK ORDER 7031



### Nassau Flyers

1300 New Hwy 1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626 DATE 2/21/2022 A/C TSN 970 3 TACH 970 3

### Airframe Entries

Removed worn rudder bell crank rod end bearing and replaced with new (P/N 11315-004).

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 2/21/2022

SIGNED:

Darion McFadden, A&P, 4138120

Work Order: 7031

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 7038



#### Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 2/25/2022 A/C TSN: 977.8 TACH: 977.8

#### Airframe Entries

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2022-04. \*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 50 hr inspection IAW Cirrus AMM 5-20.

\*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10.

Removed cylinder #2 exhaust headers due to slippage and chaffing into alt air tube, cleaned, applied anti-size, and reinstalled away from alt air tube.

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N67VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times

DATE: 2/25/2022

SIGNED:

Work Order: 7038

Mohammed Farhanuddin, A&P: 4183289

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 7036



#### Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone; 631-454-0626

DATE: 2/23/2022 A/C TSN: 973.2 TACH: 973.2

#### Airframe Entries

Removed flat spotted LMLG tire and replaced with new.

Removed worn wheel clips from both MLG and replaced with new, using new hardware.
Removed damaged right wing tip. Prepped, painted, installed new wing tip on right wing.

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times

DATE: 2/23/2022

SIGNED:

Mohammed Farhanuddin, A&P 4183289

Work Order: 7036

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG NO: N87VB WORK ORDER: 7050



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 3/7/2022 A/C TSN 1000.6 TACH: 1000.6

### Airframe Entries

Replaced missing RMLG wheel pant bolt.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times.

DATE: 3/7/2022

SIGNED:

de

Work Order: 7050

Mohammed Farhanuddin, A&P: 4183289

Printed by EBis 3 (datcomedia.com)

MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO: N87VB WORK ORDER: 7055



#### Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626 DATE: 3/15/2022 A/C TSN: 1003 6 TACH 1003 6 

#### Airframe Entries

Replaced cracked RMLG wheel fairing with new, installed aerotect protective decals.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times

DATE: 3/15/2022

SIGNED:

Work Order: 7055

John Magnovski, A&P, 3273394

MAKE Cirrus Design Corp MODEL Sr20 S/N 2518 REG NO: N87VB WORK ORDER 7082



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone: 631-454-0626

DATE: 4/22/2022 A/C TSN 1045 7 TACH 1045 7

### Airframe Entries

Reinstalled exhaust spring to bracket after found hanging off.

Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above this date and times

DATE: 4/22/2022

SIGNED:

Work Order: 7082

Mohammed Farhanuddin, A&P, 4183289

Printed by EBis 3 (datcomedia com)

MAKE: Cirrus Design Corp MODEL Sr20 S/N: 2518 REG. NO. N87VB WORK ORDER: 7120



# Nassau Flyers

1300 New Hwy Farmingdale, NY 11735 Phone 631-454-0626

DATE: 6/7/2022 A/C TSN: 1081 6 TACH: 1081 6 

### **Airframe Entries**

Researched aircraft records for applicable Airworthiness Directives through current bi-weekly 2022-12.
\*Researched aircraft records for applicable Cirrus Mandatory Service Bulletins that are due.

\*Performed airframe 50 hr inspection IAW Cirrus AMM 5-20. \*Serviced gascolator IAW Cirrus AMM 28-20.

\*Serviced all tires to proper inflation pressures IAW Cirrus AMM 12-10

#### Maintenance Release

This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and descriped above, this date and times

DATE: 6/7/2022

SIGNE

3273394

Work Order: 7120

DATE 6/21/2022 A/C TSN 1089 6 TACH 1089 6 MAKE: Cirrus Design Corp MODEL: Sr20 S/N: 2518 REG. NO. N87VB WORK ORDER: 7137 Nassau Flyers NASSAU 1300 New Hwy Farmingdale, NY 11735 Phone, 631-454-0626 FLYERSX DATE Airframe Entries · T/S pilot reports, "rudder bolt loose," found loose rudder rod end bolt loose, \*Tightened loose rudder rod end bolt and secured using new hardware. Maintenance Release This aircraft, engine, propeller or component(s) on N87VB were repaired and inspected in accordance with current Federal Aviation Regulations and manufacturers recommendations and was found to be in airworthy condition. This aircraft, engine, propeller or component(s) is approved for return to service regarding the work performed and described above, this date and times Work Order: 7137 SIGNED: DATE: 6/21/2022 Printed by EBis 3 (datcomedia com) Mohammed Farhanuddin, A&P 4183289