

wo: WO\_562

Airframe Annual - page 2 of 2



Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

18. Re attached Pilot door seal when B pillar tape applied.

I certify that this AIRFRAME has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation under work order: WO\_562.

Jeff Pleiman A/P I/A 3304319

wo: WO\_562

Avionics - page 1 of 1



Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

**N647MD**

HOBBS: 1094.1

**CIRRUS DESIGN CORP, SR20, S/N: 1772**  
TACH: 876.1

**November 27, 2024**

1. C/W AVIDYNE 10.3.1.2 IFD UPDATE I/A/W SB 601-00182-034. IFD 1&2.
2. Trouble shoot ADSB FAULT, on IFD 550 FREE FLIGHT RANGER BOX not compatible with past IFD SW UPDATE : cnfg RANGER ,ADSB out to CAP WX TR 34000 AND GPS IN ADAB+G 34000 as not to conflict with IFD 550 RS232 in/out put.

With respect to the work performed, this avionics is approved for return to service. Details of work performed are on file with Steel Aviation under work order: WO\_562.

Danny Potter A/P I/A 3176242

wo: WO\_163

Airframe - page 1 of 1



The Armory at Airboss · 3N060 Powis Rd · West Chicago, IL 60185 · 8474140697

**N647MD**

FLIGHT: 889.1

**Cirrus, SR20, S/N: 1772**

HOBBS: 1113.8

**March 19, 2025**

Removed Battery #2 p/n 50979-001. Installed 2 new each battery #2 p/n 50979-001. Operational check performed with no issues noted.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with The Armory at Airboss under work order: WO\_163.

Christophe Merani Mechanic AP3435422IA