MAINTENANCE RECORD F.A.R. 43.9

DATE OF

March 13, 2009 N184PG S/N 1965 FLT Time 148.0

O SERVICE

Complied with AD2009-05-05 by checking s/n of PFD. s/n 20055118 did not match any affected s/n's in AD list.-END-

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Detail(s) are on file under work order 5085.

Paulle, Il

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

DATE OF COMPLET

June 3, 2009 N184PG S/N 1965 Hobbs Time 228.7 FLT Time 176.9

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order **5210**.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

MAINTENANCE RECORD F.A.R. 43.9

DATE OF	i Milli 43.9			
COMPLETION	July 7, 2009 N184PG S/N 1965 FLT and Total Time 202.7 Hobbs Time 261.6			
	Completed annual inspection this date. Lubed airframe. Complied with 91.207(d)1-4 ELT inspection/ check. No defects found, operational check good. ELT battery due change 9/2012. Next ELT inspection/ check due 7/2010. Complied with AD2006-21-03 brake caliper 0-rings, by installing new o-rings and temp stickers. Next due at 302.7 FLT Time. AD's good thru 2009-11END			
	The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5251. Paul W. Enlow Repair Station MYNR748K			
	MONTGOMERY AVIATION, INC. 11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487			
	Certified Repair Station No. MYNR748K			

F.A.R. 43.9

DATE (

September 3, 2009 N184PG S/N 1965 FLT Time 255.2 Hobbs Time 322.3

Installed new o-rings and temp. label on RH brake caliper. Installed new brake linings on RH brakes. Serviced RH brakes. Leak check good. Tightened flap switch handle set screws.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order-5326.

Paul W. Dan

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

EXPERIENCE PRESIDENCE SEE SHOW

10 569

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5432.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

DATE (

June 17, 2010 N184PG S/N 1965 FLT and Airframe Total Time 395.5 Hobbs Time 492.2

Completed Annual Inspection this date. Installed repaired #2 GPS. Operational check good. Installed new engine air filter. Resecured magneto wire harness from firewall. Complied with 91.207(d)1-4 ELT inspection/ check, no defects found. ELT battery due replacement Aug. 2012. Next ELT insp./ check due June 2011. AD's good thru 2010-10------END-------END-------

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5720.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC. NO.

TO SEE

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

August 31, 2010 N184PG S/N 1965 Flight Time 449.2

Installed new high temp. o-rings in left and right brake calipers. Installed new blue and yellow temperature labels. Seviced brake reservoir. Bled brakes. Leak check good.-----END------

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5858.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

September 13, 2010 N184PG S/N 1965 Flight Time 449.6

Installed two new flap relays. Operational check good.-----END-----

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5879.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

September 30, 2010 N184PG S/N 1965 FLT Time 452.5

Resealed left and right copilots master cylinder. Pressure bled brakes from the calipers. Leak check good. Operational check good.-----END------

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 5907.

Paul W. Enlow

Repair Station MYNR748K



MONTGOMERY

11329 East State Road 32 Zionsville, IN 46077 317 - 769 - 4487

	THE THE	KIND OF INSPECTION	
DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION-STATUS & DISCREPANCY LIST SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE	
	7.4	TON SERVICE	
1210/10/		Production Flight Test accomplished in accordance with Cirrus Procedure #90500.	
		Name: Nate Alm Date 12 APR 08	
		Signature:	
		Title: Production Flight Test Pilot	
happ door	4.5 Hrs	I find that the aircraft meets the requirements for the certification requested and have issued an U.S. Standard Airworthiness Certificate dated APR 22 2008 The next inspection is due APR / 30 / 2009.	
		TZ IMDSS	
		Troy J. McDonald	
		ODARF-405228-CE	

DATE

March 1, 2011 N184PG SR-20 S/N 1965 FLT and AF/TT 493.7 Hobbs Time 602.5

Completed 100HR per Cirrus Ch. 5 Scheduled Maintenance Report. Installed #2 batteries. Next replacement due 3/2013. Installed new brake linings on Left and Right calipers. Installed new PTT switch in pilots control stick. Repaired and touched up paint on lower RH engine cowling. Complied with 91.207(d)1-4 ELT insp./ check, no defects found. ELT batteries due replacement 8/2012. Next ELT insp./ check due 3/2012. Complied with SB2X-32-19R2 nose gear assy. insp., no defects found. Next insp. due at 593.7 FLT Time. Complied with SB2X-71-10R2 oil breather line support by installing support kit. No further action required. Run-up and operational checks good. AD's good thru 2011-03.------END-------

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 6098.

Paul W. Enlow

Repair Station MYNR748K

MONTGOMERY AVIATION, INC.

11329 East State Road 32 Zionsville, IN 46077 317-769-4487

INSPECTION RECORD F.A.R. 43.11-91.409

AIRCRAFT TIME IN SERVICE KIND OF INSPECTION-STATUS & DISCREPANCY LIST
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE

MAKE Cirrus MODEL SR20 SN 1965 REG NO N184PG WORK ORDER: 28630-05-2011



Commander Aero, Inc.

Repair Station No. GA5R-876M 10570 Springboro Pike Miamisburg, Ohio 45342 USA Phone: 888-881-5580 DATE: 6/7/2011 A/C TSN: 541 FLIGHTTIME: 541

Airframe Entries

(1) Complied with 100 Hour Airframe Inspection.... (4) Serviced and charged battery as required.... (7) Complied with FAR Part 91.207 on ELT. Battery expires Aug 2012.... (8) Rotated nose and right main tire on rim and balanced all 3 tires.... (10) Installed new entry step pads.... (11) Replaced and sealed two feet of double sided tape on upper side of copilot's wing fillet fairing.... (12) Installed new close out tape on top of vertical stabilizer.... (13) Repaired crack in filler and painted lower inside flange of Co-Pilots door.... (14) Installed new lower latch in pilot's side door.... (15) Shimmed both rudder pedal torque tubes on copilot's side.... (26) Complied with Cirrus Mandatory SB 2X-32-19 R2 Nose Landing Gear Assembly Inspection and Reinforcement.... (27) Checked AD's thru 11-11.

I certify that this aircraft was inspected in accordance with an annual inspection and found to be airworthy.

The aircraft and/or component(s) on N184PG was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 28630-05-2011.

DATE: 6/7/2011

SIGNED: Work Order: 28630-05-2011

Kromer, Gary
Certified Repair Station No. GA5R-876M

Work Order: 28630-05-2011

Printed by EBis 3 (datcomedia.com)

June 5, 2012 N184PG S/N 1965 Flight Time 603.0 AFTT

100hr/Annual Inspection Completed This Date. Inspected IAW Cirrus Inspection Report ATA 05-20. ELT Inspected IAW 14CFR 91.207d, OK, New ELT battery dated 8/19 installed.

Lubed per lube chart items due. Installed new air filter element. Installed new boots on "P" leads. Charged #1 & #2 batteries serviced #1 battery with water at end of charge. Loosened nose wheel steering friction 1 flat and re cotter pinned pull test is at 25 pounds. Found heater control hanging up at heat/defrost position, wire hanging up on screw head by firewall, bent wire to clear screw head Ops check normal. Post run /leak check IAW 05-30 normal.

ADs checked thru BW 2012-10 no ADs due at this time.

See AD list for full details.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service.

Details are op file under work order 6801

Ed Hobelman

MYNR748K

11329 East State Road 32 Zionsville, IN 46077 317-769-4487

DATE


January 11, 2013 N184PG M/N SR20 S/N 1965 FLT Time 616.7

Installed new fuel bowl drain valve. Leak check good.-----END-----

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 7128.

Paul W. Enlow

Repair Station MYNR748K



11329 East State Road 32 Zionsville, IN 46077 317-769-4487


July 17, 2013 N184PG M/N SR20 S/N 1965 FLT and Airframe Total Time 617.0 Hobbs Time 726.3

Annual inspection completed this date I/A/W Cirrus SR20 Ch. 5 Scheduled Inspection Report. Lubed airframe and flight controls. Installed new #2 aircraft batteries. Next due change 7/2015. Fabricated and installed serviceable battery drain tube. Complied with 91.207(d)1-4 ELT insp./check, no defects found. ELT battery due replacement 9/2019. Next ELT insp./check due 7/2014. Complied with SB2X-57-13R2 lower landing gear attach bracket torque, by checking run-out torque and retorque lower landing gear attach bolts. No further action required. Verified SB2X-27-16R2 is recemended since previous service bulletin was not performed. Inspected actuator and torque tube. No defects found. Run-up and operational checks good. AD's good thru 2013-13.------END-------

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order **7387**.

Paul W. Enlow

Repair Station MYNR748K



11329 East State Road 32 Zionsville, IN 46077 317-769-4487

INSPECTION RECORD F.A.R. 43.11-91.409

July 30, 2014 s/n 1265 N184PG Flight Time 643.3

Performed 91.411 and 91.413 checks in accordance with F.A.R. 43, Appendix E, Appendix F and SR20 M/M 34-30- I. Altimeters tested to 20,000 feet

Pilot's Altimeter: Avidyne PFD, s/n 20055118 Test Date 7/30/14

STBY Altimeter: United, s/n 467388 Test Date 7/30/14


Encoder: ACK A30, s/n 112125

Transponder: GTX327, s/n 83732326

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service.

Details are on file under work order 7904

Ed War -- Polishalla



329 East State Road Zionsville, IN 460 317-769-44

ation No. MYNRZ

Altimeter United	d S/N 467388	3
st Equipment	Tolerance	Aircraft
1000	20	-1020
0	20	-15
500	20	485
,000	20	980
,500	25	1485
2,000	30	2000
,000	30	3015
,000	35	4005
,000	40	5985
3,000	60	7980
),000	80	9950
2,000	90	11970
4,000	100	13935
6,000	110	15970
8,000	120	17980
0,000	130	20010
2,000	140	
5,000	155	
0,000	180	
5,000	205	
The second secon		

I Certify that the altimeter and static

Altimeter PF	FD S/N 20055118		
Test Equipme	ent Tolerance	Aircraft	
-1000	20	-985	
0	20	10	
500	20	495	
1,000	20	1000	
1,500	25	1490	
2,000	30	2000	
3,000	30	3015	
4,000	35	3990	
6,000	40	5980	
8,000	60	7980	
10,000	80	9975	
12,000	90	12000	
14,000	100	13970	
16,000	110	16000	
18,000	120	17980	
20,000	130	20000	
22,000	140		
25,000	155		
30,000	180		
35,000	205		

I Certify that the altimeter and static System tests required by FAR 91.411 have been performed. The Altimeter was tested to 20,000 Feet 7/39/14 W. O. 7904

Certified

August 15, 2014 N184PG M/N SR20 S/N 1965 FLT and Airframe Total Time 643.3 Hobbs Time 752.9

Annual inspection completed I/A/W Cirrus SR20 AMM Ch.5 Scheduled Inspection Report. Installed new engine air filter. Serviced, charged and installed new Gill G243 battery s/n G0289736. Installed new line cutters s/n 6684 and 6712 with mfr date of 7/14. Line cutters due replacement 7/2020. Installed new tach generator s/n 1965. Verified tach reading with tru tach.Complied with 91.207(d)1-4 ELT insp./check, no defects found. ELT battery due replacement 8/2019. Next ELT insp./check due 7/2015. Complied with SB2X-32-19R3 nose landing gear assy. insp. No defects found. Reinforcement bolt previously installed. Next due insp. at 743.3 FLT Time. Run-up and operational checks good. Reviewed AD's thru 2014-07-28.----END----

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service. Details are on file under work order 7904.

Paul W. Enlow

Repair Station MYNR748K

MONTGOMERY Aviation, Inc.

11329 East State Road 32 Zionsville, IN 46077 317-769-4487

MIE

May 7, 2015 N184PG M/N SR20 S/N 1965 FLT Time 662.2

Removed pilots broken visor and installed new visor from Rosen.

The maintenance operation(s) described above were inspected in accordance with current regulations and with respect to work performed, the aircraft and/or component was found airworthy and is approved for return to service.

Details are on file under work order 8226.

Paul W. Enlow

MYNR748K



11329 East State Road 32 Zionsville, IN 46077 317-769-4487