



CONTINENTAL MOTORS

## **Service Information**

Service Bulletins and Technical Publications are available on a direct mail basis from the factory. Orders must be prepaid. Send for order form or call 334-438-3411, publications department, for information.

## **Engine Returns**

All returned engines are to be shipped with this log book Directly to:

Teledyne Continental Motors Abbeville Industrial Park Suite 159 Abbeville, AL 36310

## USE ONLY FUEL CONFORMING TO ASTM D910 USE OF AUTOMOTIVE GAS IS NOT APPROVED.

This engine model <u>TO550N78</u> , Serial Number <u>686237</u>
was manufactured on by Teledyne Continental
Motors in accordance with approved design data and the applicable requirements of
Part 21 of the Federal Aviation Regulation The approved design data for this engine
incorporates all changes required by applicable Airworthiness Directives and Teledyne
Continental Motors Service Bulletins.

TELEDYNE CONTINENTAL MOTORS
A TELEDYNE TECHNOLOGIES COMPANY

Date	Total	Time		Since verhaul	Engine Service	ce and Maintenance Record s, Airworthiness Directives, Special Inspections
	Hrs.	Min.	Hrs.	Min.	Modifications and Service	Pa Rullatine
-30-02	0	3			Serviced Engi Straight Mine	ral Oil on 4/30/02 by MFG
05-28-02	25	9			REMOVED + R	EPLACED CHT PROSE P/N
					12637-001 5	CORRUS AMM CH. 77-20.
					OPS V GOOD.	Pertinent details are on file at this agency under  Work Order:  Date OS 350  Signature  Cirrus Design Factory Service Center Duluth, MN Repair Station Cert. No. YD5R855Y
ਦ			(			Tiopal Guitor Control
			-			
INSTAL ENGINE OI	1).	1//	) ama	lit	S OF EXXON ELITE 20W50. I	INSTALLATION INSTRUCTIONS. CHANGED LEAK CHECKED OKEND-
d sprong tandelig darin ab anggano an cara aga a	85				Annual State	
Reg #: Nº		22	dynagolicians) adminy is foreward.		AIR CARE INC.	Hobbs: 82.5 Tach:
Serial #: 0	0227		-		Aviation Services	Total Time:
	and compression from the		il filter. I	nspected	oil filter and no metal not	ted. Oil analysis sample taken. Installed a —
CH48108 of Washed engages see WO# 1	gine. Gr	ound ra	n acft, sy	ine with stems op	8qts Aeroshell 100. Repla 's checked normal and no	ced CHT probe, installed p/n 12637-001. Leaps noted at this time. For further details
		-			FAA Repair Station AC0R030C	AIR-CARE, INC.  RVI AIRPORT 2780 T  ROCKY MOUNT, N.C. NCOROSOC  FAA APP. REPAIR STATION NO. NCOROSOC
		}				
		-				
	+					

SOUTHEAST AERO SERVICES, INC. 800-692-2091 CIRRUS SR22 S/N 0227 N927CD 26 November 2002 Total Time: 144,5 **TCM IO-550-N** s/n 686237 Drained engine oil and obtained sample for analysis. Removed oil filter and inspected with no defects noted. Installed new oil filter. 2. Serviced engine with 8 qts Aeroshell 15W-50. 3. Removed and replaced #2 alternator shaft garloc seal. Removed and replaced CHT probe with new. 5. Engine ground runs completed with no defects noted. Engine approved for return to service. John Strohl A&P2669139 SOUTHEAST AERO SERVICES, INC. 800-692-2091 **CIRRUS SR22 S/N 0227 N927CD** 28 January 2003 Total Time: 166.7 **TCM IO-550-N** s/n 686237 1. Completed installation of Avidyne EMAX engine monitoring probes and harness. Removed and replaced air/oil separator modified rocker cover with correctly modified unit. Engine ground operational tests completed with satisfactory results. Adjusted propeller governor forward stop to achieve 2650 RPM on static Run up. Engine approved for return to service. James T. Markey A&P154623664 SOUTHEAST AERO SERVICES, INC. 800-692-2091 CIRRUS SR22 S/N 0227 N927CD 5 February 2003 Total Time: 171.5 **TCM IO-550-N** s/n 686237 1. Removed and replaced #6 CHT probe with new. Installed additional wire length to increase service loop. Adjusted propeller governor to obtain 2700 in flight. Engine approved for return to service. John Strohl A&P2669139 **SOUTHEAST AERO SERVICES, INC. 800-692-2091** CIRRUS SR22 S/N 0227 N927CD 25 April 2003 Total Time: 213.8 **TCM IO-550-N** s/n 686237 1. Drained engine oil and obtained sample for analysis. 2. Removed oil filter and inspected with no defects noted. Installed new oil filter. 3. Serviced engine with 8 qts Aeroshell 15W-50. Removed and replaced #2 alternator shaft garloc seal, left rear accessory shaft garloc seal, and all associated

Engine approved for return to service.

James T. Markey A&P154623664

gaskets including adapter plates.

5. Engine ground runs completed with no defects noted.

Reg #: N927CD
Model:Cirrus SR22
Serial #:0227
Work Order #:17992



Hobbs:233.3

Tach:

Total Time:233.3

Date: 5/19/03

Performed 100 hour inspection using Cirrus SR22 scheduled inspection report as a guide. Oil and filter was not changed due to low amount of time since oil change. C/W TCM CSB664 magneto capacitor replacement NA by magneto s/n and capacitor p/n. Replaced induction filter assembly p/n BA-111. Replaced spark plugs p/n RHB32E. Replaced rivet in RH rear baffle. Replaced #2 alternator drive garlock seal p/n 25102. Replaced oil cooler. Installed new cooler p/n 654585 s/n D03-2147-238. Ground run acft. Systems ops check normal. No leaks noted at this time. For further details see WO# 17992 on file this station.

Compression CHECK: For Sar Care, Inc.

# 1) 7/80 142) 69/80

# 3) 69/80 # 4) 70/80

# 5) 70/80 # 6) 64/80

1 CERTIFY THAT THIS ENGINE MAS
BEEN INSPECTED IN ACCORDANCE WITH A

100 LOVE INSPECTION AND APPROVED
FOR RETURN TO SERVICE.

BATE 5-19-03 TIME IN SERVICE 2333

SICHE

AIR CARE INC. SA 24
MAI ASSPORT
BOOKY MOUNT, NC 27802
LA MYROYED REPAIR
STREETED NO. ACORDOOC

Airways, Inc. 520 Airport Rd Lititz, Pennsylvania 17543 LOG ID# 487 25-July-2003 WO# 3807 REF# 3807 HOBBS 271.8 N927CD S/N 0227 CIRRUS SR22

Pg 1/1

4256264

-ENGINE LOG-CHANGED THE ENGINE OIL AND FILTER, SERVICED WITH 7 QTS OF A/S 15W50. PERFORMED AN OIL ANALYSIS. CUT OPEN FILTER AND INSPECTED, CHECKED GOOD. PULLED AND CLEANED THE #1,2 & 6 FUEL INJECTORS. PERFORMED A GROUND RUN UP AND LEAK CHECK. CHECKED GOOD.-END-

Signed A&P 2699478 James J. Mazzante

Airways, Inc. 520 Airport Rd Lititz, Pennsylvania 17543 LOG ID# 651 10-November-2003 WO# 3974 REF# 3974 HOBBS 347.0 N927CD S/N 0227 CIRRUS SR22

Pg 1/1

-ENGINE LOG-CHANGED THE ENGINE OIL AND REPLACED FILTER, SERVICED WITH 8 QTS OF A/S 15W50. PERFORMED AN OIL ANALYSIS. CUT OPEN FILTER AND INSPECTED, CHECKED OK. RUN UP AND LEAK CHECKED GOOD. REPLACED THE #4 OEM EGT PROBE.-END-

Signed A&P 2699478

Mazzante

	Hrs.	Min.	Hrs.	Min.	Modifications and Servi	ce Bulletins
Reg #: N927CD Model: Cirrus SR22 Serial #: 0227 Work Order #: 18306			4),	4R CARE INC. Aviation Services	Hobbs: 366.6 Tach: 366.6 Total Time: Date: 12/1/03	
lue to low t	ime since Removed a hell 15W:	oil chand ins 50. St	ange. Ca spected of op drille	hecked o oil filter. d crack i	No metal noted Installed	n report as a guide. Oil was not changed 2) 72/80 #3) 70/80 #4) 68/80 #5) 69/80 new filter p/n CH48108. Serviced with 1 files. Ground ran acft. Systems op's check certify that this engine has been inspected in accordance with a inspection and approved for return to service.  Date 14/63 Time in service 366.6
						AIR CARE, INC. RMI AIRPORT ROCKY MOUNT, NC 27802 C.A.A. APPROVED REPAIR STATION MO. ACORDIDO
ک <i>ی-ک</i>	3973				0.1 3 Filter	- 00mmmy 13539
	4				- 1	