



CONTINENTAL

A E R O S P A C E T E C H N O L O G I E S

**ENGINE
LOG
BOOK**



Edmonds Aviation LLC · 3001 Earhart Drive · Jonesboro, AR 72401 · (870) 819-3569

N725AA

Flight Hours: 24.3

Continental, IO-550-N, S/N: 1048687**June 24, 2025**

TSN: 24.3

Total: 31.4

1. C/W 25 Hour Inspection of engine in reference to Cirrus AMM Chapter 5, Continental M-0 and Continental M-16.
2. Performed borescope inspection in reference to Continental M-0 Manual.
3. Drained oil and collected sample for review. Inspected oil filter, no discrepancies noted. Installed new oil filter. Serviced engine with 7qts Phillips X/C 20W-50. Installed P/N AA48108-2 - Tempest Oil Filter, Installed (7 quart) P/N 1045457 - Phillips X/C Aviation Oil SAE 20W-50.

Technicians who worked on items listed above: Tupelo Thompson, Timothy Rowe

Maintenance Release: With reference to above mentioned work performed IAW current FARs and Manufacturer Maintenance Manual, I certify this engine is approved for return to service at this time. Details of work performed are on file with Edmonds Aviation LLC under work order: JBR-25-1106.

Ernie Haycraft A&P 3857829



Edmonds Aviation LLC · 3001 Earhart Drive · Jonesboro, AR 72401 · (870) 819-3569

N725AA

Flight Hours: 55.9

Continental, IO-550-N, S/N: 1048687**October 20, 2025**

TSN: 55.9

Total: 69.8

1. C/W 50 Hour Inspection/Service Interval in reference to Cirrus AMM Chapter 5 and Continental M-0 Manual.
2. Drained engine oil and serviced with 7qts Phillips X/C 20W-50. Replaced oil filter with new AA48108-2. Performed particulate inspection on filter, no discrepancies noted. Run up and leak checks performed with no discrepancies. Work performed in reference to Cirrus AMM Chapter 12 and Continental M-0 Manual. Installed P/N BS-KT-OIL - Oil Sample Kit, Blackstone.

Technicians who worked on items listed above: Tupelo Thompson, Blayne Ray

Maintenance Release: With reference to above mentioned work performed IAW current FARs and Manufacturer Maintenance Manual, I certify this engine is approved for return to service at this time. Details of work performed are on file with Edmonds Aviation LLC under work order: JBR-25-1185.

Jonathan Edmonds A&P 3568491