

CONTINENTAL

A E R O S P A C E T E C H N O L O G I E S

ENGINE LOG BOOK

Service Information

Consult the Continental web site at <http://www.continental.aero> for engine related news or announcements. The web site contains useful information for Continental engine owners, including service information and illustrated parts catalogs.

If Internet access is not available, contact our Customer Service Department at:
1-888-826-5465 Toll free in the United States or 1-251-436-8299 for International customers

Warranty Information

This product is covered by Continental Aerospace Technologies™ product warranty. To read or download a copy for your records, please visit the Product Warranty page on our web site at: <http://www.continental.aero/services/warranty.aspx> or scan the QR Code to the right to navigate to the page:



Instructions for Continued Airworthiness

For complete access to the engine Instructions for Continued Airworthiness, Illustrated Parts Catalogs, Service Documents, Technical Briefs, company news, and upcoming events, please take a few moments to register the serial number of your engine on our web site: <http://www.continental.aero/services/owner-registration.aspx> or scan the QR Code to the right to navigate to the page:



Engine Returns

Return engines for core credit with this log book to:

Continental Aerospace Technologies
2039 Broad Street
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:

Continental Services
Factory Service Center
8600 County Road 32
Fairhope, Alabama 36532 USA

**USE ONLY FUEL SPECIFIED IN OPERATOR'S
MANUAL OR TYPE CERTIFICATE DATA SHEET
USE OF AUTOMOTIVE FUEL IS PROHIBITED**



Continental Motors

FAA PRODUCTION CERTIFICATE NO. 508

Printed: 05/27/2022

Test Date: 05/27/2022

This engine model I0550N68B, serial number 1043585 was manufactured by Continental Motors, Inc. in accordance with approved design data and the applicable requirements of 14 CFR, Part 21. The approved design data for this engine incorporates all changes required by applicable FAA Airworthiness Directives and Continental Motors Service Bulletins.

Thomas Howard

CONTINENTAL MOTORS, INC.

Form 6012-03 (Rev Sept 2014)

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hours	Min	Hours	Min	

wo: WO_123 Engine Change/Annual

Engine - page 1 of 3



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N444JH
HOBBS: 3652.3

Continental , IO-550-N68B, S/N: 1043585
TACH: 3055.4

December 01, 2022

1. Installed Factory new engine. Replaced associated parts and components as listed. Installed (2) P/N AN7-33A - BOLT, REAR ENGINE MOUNT, Installed (4) P/N AN7-40A - Bolt, Installed P/N 26377-001 - Heat Shield, Engine Isolator, LH, Installed P/N 26378-001 - Heat Shield, Engine Isolator, RH, Installed P/N 15415-001 - Fuel Flow Sensor Assembly, SR22, Installed (4) P/N 51324-001 - Barrel Nut, Installed P/N 15074-001 - SR22, IO550N, #6, Installed P/N 15073-001 - SR22, IO550N, #4, Installed P/N 15072-001 - SR22, IO550N, #2, Installed (4) P/N 20166-001 - COUPLER, EXHAUST, 2 Per Tailpipe, Installed P/N 15080-001 - SR22, IO550N, #1, Installed P/N 15069-001 - SR22, IO550N, #3, Installed P/N 15070-003 - SR22, IO550N, #5, Installed (2) P/N 15077-003 - Weldment, Tailpipe SR22 Black, Installed P/N AE3663161B0120 - HOSE, TYPE D, ENG TO OIL PRESS SENDER, Installed P/N AE3663163G0100 - HOSE, TYPE D, RETURN FROM FUEL PUMP, Installed P/N AE3663163H0137 - HOSE, TYPE D, FIREWALL TO BOOST PUMP, Installed P/N AE3663161E0070 - HOSE, TYPE D, BAFFLE TO XDUCER, Installed P/N AE3663162E0106 - HOSE, TYPE D, XDUCER TO METERING BLOCK, Installed P/N 1133180-4 - Drive Shaft, Hub & Mounting Bracket Assy, A/C, Installed P/N 19815-016 - MCU To Alternator 2, Shielded, Installed P/N 19815-004 - MCU To Alternator 1, Shielded, Installed P/N 19815-020 - MCU To Battery, Installed P/N 19815-030 - MCU To Starter, Installed (2) P/N AN5-24 - Bolt, Installed (6) P/N 96301-01 - BARRY MOUNT, Installed P/N 24761-002 - OIL TEMP PROBE W/Din Style Connector, Installed P/N 13929-001 - MCU AND ENGINE GROUNDING STRAP, Installed P/N 50152-002 - SPRING CLAMP, 9/16 HOSE, FUEL DRAIN, Installed P/N SCEET-10 X 27 WITH CUFFS - SCEET DUCT, 2.5 DIA X 27 W/SEALED ENDS, Installed P/N SCEET-10 X14" WITH CUFFS - SCEET DUCT, 2.5 DIA. X 14 W/SEALED ENDS, Installed (2) P/N SCEET-10 X 12.5 WITH CUFFS - SCEET DUCT, 2.5 DIA. X 12.5 W/SEALED ENDS, Installed P/N 20153-002 - Collector, Exhaust, SR22, Installed P/N 18892-003 - NACA Duct To Mixing Box, Installed (12) P/N RG-632459 - REAL, PREMIUM VALVE COVER GASKET, IO 550.

wo: WO_123 Engine Change/Annual

Engine - page 2 of 3



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

2. Replaced engine perimeter baffles as listed: Installed P/N 15471-007 - Side, RH, Black Anodize, Installed P/N 15487-009 - Front, RH, Black Anodize, Installed P/N 15480-005 - Spinner, Black Anodize, Installed P/N 15490-003 - Baffle, Spinner, Black, Installed P/N 17547-007 - Assembly, Alternator 2 Enclosure, Black, Installed P/N 15488-002 - Assembly, Baffle, Aft, Cylinder, Right.
3. R&R engine drain collector assy. with new: Installed P/N 26939-002 - Weldment, Manifold, Drain, Fuel.
4. R&R all control rod ends with new. Installed (3) P/N 11314-003 - Rod End, Female.
5. Alt #1 new with FACTORY NEW ENGINE from Continental S/N H-W041290.
6. Alternator #2 NEW Installed P/N ES-7024-14 - ALTERNATOR, HARTZELL, 70 AMP S/N: H-W071930.
7. Alt #1 500 hour inspection due in 500 hours @ 3555.4.
8. Alt #2 500 hour inspection due in 500 hours @ 3555.4.
9. Fuel boost pump Installed P/N 5217-00-3 - DUKES FUEL PUMP (OVERHAULED) S/N: 1552.
10. Induction air filter Installed P/N 50207-200 - Brackett Replacement Filter Element, BA-24.
11. 500 hour engine mount torqued to spec. I/A/W Cirrus AMM. Next due @ 3555.4.
12. 500hr. magneto inspection C/W by new magnetos installed with new engine, S/N L/H- D22DA131, R/H- D22DA154.
13. New muffler and heat exchanger Installed P/N 21892-002 - Weldment, Muffler, SR22, Inconel Flame Cone, Installed P/N 14836-002 - Heat Exchanger, SR22, Inconel Flame Cone.
14. New Prop Governor Installed P/N C290D3-R/T23 - PROP GOV. S/N: 220580.
15. Installed Reiff pre heater IAW Reiff installation instructions. Installed P/N SL6 - REIFF PRE HEATER, STANDARD, IO 550.
16. Reinstalled same engine mount weldment s/n 090666 after inspection and refinishing by AWI see form 8130 number 210677 dated 8/21/2022.

Continued on next page

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record
	Hours	Min	Hours	Min	
Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins					
Carried forward →					

wo: WO_123 Engine Change/Annual

Engine - page 3 of 3



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

With respect to the work performed, this Engine is approved for return to service. Details of work performed are on file with Steel Aviation, Inc. under work order: WO_123 Engine Change/Annual.

Brad Helman A&P 3939968

Brad Helman

end

wo: WO_123 Engine Change/Annual

Engine Annual - page 1 of 1



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N444JH

HOBBS: 3652.3

Continental, IO-550-N68B, S/N: 1043585

TACH: 3055.4

December 01, 2022

1. C/W Annual Inspection in accordance with FAR 43 Appendix D using Cirrus AMM as a guide.
2. Serviced engine: Installed (8) P/N Mineral SAE20W50 - Oil.

I certify that this ENGINE has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation, Inc. under work order: WO_123 Engine Change/Annual.

Make: Continental
Model: IO550N68
Serial No: 1043585



Date: 1/30/2023
Flight Time: 3110.7
Total Time: 55.2

Continental Services, 8600 County Road 32, Fairhope, AL 36532 251-990-5080 FAA Repair Station No. 9CER853B
The work performed as described below has been inspected in accordance with current regulations of the Federal Aviation Administration and found to be in airworthy condition with respect to the work performed.

Work Performed: COMPLETED A COMPRESSION CHECK AND BORESCOPE INSPECTION IN ACCORDANCE WITH CONTINENTAL MOTORS STANDARD PRACTICE MAINTENANCE MANUAL M-0. COMPRESSION CHECK / 80 PSI: #1-67, #2-72, #3-72, #4-70, #5-72 AND #6-74, WITH A MASTER ORIFICE VALUE OF 42 PSI. CYLINDER COMPRESSION AND BORESCOPE RESULTS INDICATE CYLINDERS MEET CONDITIONS FOR CONTINUED SERVICE. LIGHT POOLING NOTED, PARTICULARLY IN #S 1 AND 4. STRONG NEAR NEW X HATCH PATTERN NOTED IN 1-5, #6 HAS SOME EVIDENCE OF PATTERN WEAR/GLAZING AT THE TOP. #4 EXHAUST/#6 INTAKE SHOW SIGNS OF LIGHT VALVE GUIDE OIL. OIL WAS CHANGED TO AEROSHELL 100 MINERAL OIL. DRAINED OIL AND COLLECTED SAMPLE FOR OWNER TO ARRANGE FOR ANALYSIS. INSTALLED NEW OIL FILTER. CUT AND INSPECTED OLD FILTER NOTING NORMAL INDICATIONS. SERVICED ENGINE WITH 7 QUARTS AEROSHELL 100 MINERAL OIL. WASHED ENGINE. PERFORMED GROUND OPERATIONAL AND LEAK CHECKS. RECOMMEND ADDITIONAL BREAK IN FOR 25 HOURS/CONTINUED MONITORING.-----END-----

Authorized Signature for Repair Station 9CER853B:

Details of the work performed are on file under Work Order No. AC-11287

Don Budick

Date	Total Time		Time Since Last Overhaul
	Hours	Min	
Carried forward →			

wo: WO_134

Steel Aviation, Inc.

N444JH

HOBBS: 3669.7

Continental

TACH

1. Drained oil and took oil sample.
2. Removed oil filter. Cut open oil filter.

With respect to the work performed, this Engine is approved for return to service. Details of work performed are on file with Steel Aviation, Inc. under work order: WO_134 Engine Change/Annual.

Jeff Pleiman A/P I/A 3304319

N305KD

Hobbs

Drained oil hot. Removed oil filter, W100. R/R all spark plugs (Champion)

N305KD

Hobbs

Performed engine ground run, 10 minutes. Tempest AA

ENGINE MODEL
ENGINE S/N
REG. NO. N305KD
WORK ORDER
KTK13090-09-2023

Engine Entries

- (2) Removed all spark plugs. Cleaned spark plug sockets.
- work accomplished IAW SR22 AMM
- (3) Cleaned fuel injectors IAW Con

I have reviewed the file on this aircraft and was repaired/inspected in accordance with details of this work order are on file at the

DATE: 9/15/2023

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record
	Hours	Min	Hours	Min	
Carried forward →					Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins

wo: WO_123 Engine Change/Annual

Engine - page 3 of 3



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

With respect to the work performed, this Engine is approved for return to service. Details of work performed are on file with Steel Aviation, Inc. under work order: WO_123 Engine Change/Annual.

Brad Helman A&P 3939968

Brad Helman

end

wo: WO_123 Engine Change/Annual

Engine Annual - page 1 of 1



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N444JH
HOBBS: 3652.3

Continental, IO-550-N68B, S/N: 1043585
TACH: 3055.4

December 01, 2022

1. C/W Annual Inspection in accordance with FAR 43 Appendix D using Cirrus AMM as a guide.
2. Serviced engine: Installed (8) P/N Mineral SAE20W50 - Oil.

I certify that this ENGINE has been inspected in accordance with an (annual) inspection and was determined to be in airworthy condition. Details of work performed are on file with Steel Aviation, Inc. under work order: WO_123 Engine Change/Annual.

Jeff Pleiman A/P I/A 3304319

Jeff Pleiman

wo: WO_189

Engine - page 1 of 1



Steel Aviation · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N444JH
HOBBS: 3725.1

Cont., IO550N 68B, S/N: 1043585
TACH: 3117.3

March 13, 2023

1. C/W AD 2023-04-08 IAW Continental Aero Space Technologies MSB 23-01a. No Defects Found.
2. Cleaned #4 CHT connector, reconnected and checked operation. Ops checked good.
3. Replaced Rear baffles with (2) and L/H side baffle with new. Installed P/N 15473-010 - Rear LH, Black, Installed P/N 15475-006 - Side, LH, Black Anodize, Installed P/N 15469-013 - Assy, Baffle, Rear, RH, Black Anodize.
4. Checked Mag timing. Found to be at 25 Deg BTC. Adjusted R and L mags to 22 deg BTC.

With respect to the work performed, this Engine is approved for return to service. Details of work performed are on file with Steel Aviation under work order: WO_189.

Brad Helman A&P 3939968

Brad Helman

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hours	Min	Hours	Min	
Carried forward →					

wo: WO_134

Engine · page 1 of 1



Steel Aviation, Inc. · 53 North Street Ext · Phillipsburg, Ohio 45354 · 937 332 7587

N444JH
HOBBS: 3669.7Continental, IO-550-N68B, S/N: 1043585
TACH: 3070.5

December 07, 2022

1. Drained oil and took oil sample. Serviced engine. Installed (7) P/N Aeroshell W100 Plus - Oil.
2. Removed oil filter. Cut open oil filter no defects noted at this time. Installed P/N AA48108-2 - Oil Filter.

With respect to the work performed, this Engine is approved for return to service. Details of work performed are on file with Steel Aviation, Inc. under work order: WO_134.

Jeff Pleiman A/P I/A 3304319



Lore Aviation Services LLC

Date: 6/29/2023

500 Airport BLVD Hangar 1

Lake Charles, LA 70607

Phone: (337)912-4496

N305KD

Hobbs: 3872

Tach: 3234

Drained oil hot. Removed oil filter, cut open, and inspected. Installed new Tempest AA48108-2 oil filter. Added 7 qts Aeroshell W100. R/R all spark plugs (Champion RHB32E Qty. 12) Performed leak check with satisfactory results.

END

Christopher Lore

A&P 3458101



Lore Aviation Services LLC

Date: 7/24/2023

500 Airport BLVD Hangar 1

Lake Charles, LA 70607

Phone: (337)912-4496

N305KD

Hobbs: 3924.6

Tach: 3286.3

Performed engine ground run and op's check. Drained oil hot. Removed oil filter, cut open, and inspected. Installed new Tempest AA48108-2 filter, torqued, and safetied. Added 7 quarts of Aeroshell W100

END

Christopher Lore

A&P 3458101

ENGINE MODEL
ENGINE S/N
REG NO N305KD
WORK ORDER
KTKI3090-09-2023



Cirrus McKinney Service Center

Repair Station No CDCR140E
1500 Industrial Blvd
Hangar #19
McKinney TX 75069
Phone 469 215 4452

DATE 9/15/2023
A/C TSN 3318
ENG TT 3318
TSMOH
HOBBS 3963.9

Engine Entries

- (2) Removed all spark plugs. Cleaned, gapped and tested spark plugs. No defects found. Rotated and installed spark plugs. All work accomplished IAW SR22 AMM 74-20. Ops check good.
- (3) Cleaned fuel injectors IAW Continental MM M-0. Leak and ops checks good.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of this work order are on file at this Certified Repair Station CRS# CDCR140E

DATE: 9/15/2023


SIGNED:

Charles Gazaway
Certified Repair Station No CDCR140E

Work Order: KTKI3090-09-2023

Printed by EBis 3 (datamedia.com)

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record
	Hours	Min	Hours	Min	
					Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins

Carr	October 24, 2023 Flight Recorder 3328.2 TSN 273 (5/27/2022) Oil Change. Drained oil (hot), sampled (see Blackstone Report this date), replaced with seven (7) quarts of Aeroshell W100+ R/R oil filter 108. Opened old filter and found normal debris. Note: Pre-oiled adapter cavity, installed/torqued new Tempest™ AA48108-2 dry and safetied. Motored engine for pre-oil until pressure noted. Two (2) minute engine run for leak check. Ok. Subsequent test flight	N444JH Engine
		 Glenr. Carter A&P 2686734

ENGINE MODEL
ENGINE S/N
REG NO N444JH
WORK ORDER
KTKI3303-01-2024

 **CIRRUS** Cirrus McKinney Service Center

Repair Station No CDCR140E
1500 Industrial Blvd
Hangar #19
McKinney, TX 75069
Phone 469 215 4452


DATE 2/7/2024
A/C TSN 3354 5
ENG TT 3354 5
TSMOH
HOBBS 4010 2

Engine Entries

- (3) Performed annual engine inspection IAW SR22 AMM 05-20 inspection checklist. Compression check results: 1) 64/80 2) 69/80 3) 74/80 4) 73/80 5) 74/80 6) 73/80. Master orifice reading: 44. Replaced induction air filter element, PN 50207-200.
(11) Changed engine oil and filter, performed Oil Filter Particle Inspection and serviced engine with 8 quarts of Aeroshell W100 IAW SR22 AMM 12-10. Leak check good. No particles in filter found.
(12) Performed engine setup per Continental Motors Manual M-16. Post setup operational and leak check performed with no discrepancies.
(24) Adjusted idle mixture rise IAW SR22 AMM 5-30.
(46) Replaced 2 failed spark plugs with new P/N:URHB32E. Work completed IAW SR22 AMM 74-20.
(63) I certify that this engine has been inspected IAW an annual inspection and was determined to be in an airworthy condition.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of this work order are on file at this Certified Repair Station CRS# CDCR140E


DATE: 2/7/2024


SIGNED: 




Work Order: KTKI3303-01-2024

Alex Coats
Certified Repair Station No. CDCR140E

Printed by EBis 3 (datcomedia.com)

 Lore Aviation Services LLC		Date: 5/23/2024 500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337)912-4496
Engine		
N444JH	Hobbs: 4058.8	Tach: 3394.7
Performed engine ground run, Drained oil hot, Removed oil filter, cut open, inspected, Installed new Tempest Filter (PN AA48108-2) Owner Supplied, Date Stamped, Torqued, Safetied, Added 6 qts of Aeroshell W100 Owner Supplied, Performed engine ground run & leak check with satisfactory results. R/R Spark plugs with new PN:URHB32E (owner supplied) Retrieved oil sample.		
END		
 Christopher Lore A&P 3458101		

 Lore Aviation Services LLC		Date: 8/24/2024 500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337)912-4496
Engine		
N444JH	Hobbs: 4150.5	Tach: 3474.1
Performed engine ground run, Drained oil hot, Removed oil filter, cut open, inspected, Installed new Tempest Filter (PN AA48108-2), Date Stamped, Torqued, Safetied, Added 6 qts of Aeroshell W100, Performed engine ground run & leak check with satisfactory results. Removed, cleaned, gapped, tested, and reinstalled previously removed spark plugs.		
END		
 Christopher Lore A&P 3458101		

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hours	Min	Hours	Min	
	 Lore Aviation Services LLC				Date: 10/18/2024 500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337)912-4496
	Engine N444JH Hobbs: 4215.3 Tach: 3530.4				
	Performed engine ground run, Drained oil hot, Removed oil filter, cut open, inspected, Installed new Tempest Filter (PN AA48108-2), Date Stamped, Torqued, Safetied, Added 7 qts of Aeroshell W100 and 11oz of Cam Guard, Performed engine ground run & leak check with satisfactory results.				
	END  Christopher Lore A&P 3458101				
	 Lore Aviation Services LLC				Date: 3/9/2025 500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337) 912-4496
	Engine N444JH Hobbs: 4332.6 Tach: 3626.4 TSNEW: 571				
	Compressions #1 74.3/80 #2 74/80 #3 76.5/80 #4 74/80 #5 72/80 #6 75/80				
	Performed <u>Annual inspection</u> IAW CFR 43 appendix D, with reference to Continental inspection checklist. Performed pre-inspection ground run and op's check. Drained oil hot. Removed filter, cut open, and inspected. Borescoped engine. Installed new oil filter (PN: AA48108-2) torqued, dated and safetied. Added 7 quarts of Aeroshell W100. Removed, cleaned, inspected, gapped, tested, rotated and reinstalled spark plugs. R/R induction air filter (PN: BA-24). R/R magnetos with new units (PNs: 10-500556-1, SNs: LH(D24IC685) & RH(D24IC694)) and timed per engine data tag. Performed engine ground run/leak check with satisfactory results. Complied with all AD's, see AD compliance record.				
	I certify that this engine has been inspected IAW an Annual Inspection and was found to be in airworthy condition. END  Christopher Lore A&P 3458101 IA				
	 Lore Aviation Services LLC				Date: 8/19/2025 500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337)912-4496
	Engine N444JH Hobbs: 4523.7 Tach: 3790.3				
	Performed engine ground run, Drained oil hot, retrieved oil sample, Removed oil filter, cut open, inspected, Installed new Tempest Filter (PN AA48108-2), Date Stamped, Torqued, Safetied, Added 6 qts of Aeroshell W100 Plus, Performed engine ground run & leak check with satisfactory results.				
	END  Christopher Lore A&P 3458101				
	 Lore Aviation Services LLC				Date: 7/21/2025 500 Airport BLVD Hangar 1 Lake Charles, LA 70607 Phone: (337)912-4496
	Engine N444JH Hobbs: 4465.8 Tach: 3739.6				
	Performed engine ground run, Drained oil hot, Removed oil filter, cut open, inspected, Installed new Tempest Filter (PN AA48108-2), Date Stamped, Torqued, Safetied, Added 6 qts of Aeroshell W100, Performed engine ground run & leak check with satisfactory results.				
	END  Christopher Lore A&P 3458101				