AIRCRAFT TECHNICAL RECORD

Section 3. ENGINE LOG #



/Country	ng Competent Authority y ro Control GmbH Austria	2.	AUTHOR	ISED RELEAS EASA FOR	E CERTIFIC	ATE			3. Form Tracking Number AE028198
4. Organisa	ation Name and Address:			Austro Engine Rudolf Diesel Stra Wiener Neustac	GmbH				5. Work Order / Contract / Invoice ES191601
6. Item	7. Description		8. Pa	rt No.	9. Qt	·.	10. Serial No.		11. Status/Work
1	E4PC Engine		E4PC	-00-000-000 Is s.: 004		1	E4P-C	-00265	New
Item 1: Th	The engine complies with the Engine conforms to EAS uel hose assy P/N: A24119-es that the items identified all approved design data and approved design data are	A TCDS E.200 Issue 01 (EASA Form1: 220 	10; Damper assy P/N: D44-7306-30-00_1 (832) acc. DAI-Drawing D44-7306-00-00 its ed in comformity to:	14a	Part-14s	i.A.50 Release to nerwise specified 12, was accomp	o Service in block 12, the worlished in accordance	k identified in bl with Part-145 a	on specified in block 12 lock 11 and in
	non-approved design da	a specified in block 12	2	respe	ect to that work the	items are consid	dered ready for reles		te/ Approval Ref. Number
13b. Author	rised Signature	7.0	13c. Approval / Autorisation Number AT.21G.0010	14b. /	Authorised Signate	ire			
13d. Name		la	13e. Date (dd mmm yyyy) 1 2 JUN 2019	14d. N	Name			14e. Date (do	mmm yyyy)
This certifica	TALLER RESPONSIBILITIES ate does not automatically con	nstitute authority to inst	all the item(s). Where the user/installer per ensures that his/her airworthiness authorit s must contain an installation certification is	forms work in accord y accepts items from ssued in accordance	dance with regulat the airworthiness with the national	ions of an airwor authority specif regulations by th	thiness authority dif- ied in block 1. State e user/installer befo	errent than the ments in blocks re the aircraft m	airworthiness 13a and 14a do not constitute lay be flown.

EASA Form 1 - 21 Issue 2

Freigabe: 24 Aug. 2010 / M. Nemec

Section 3A: Engine Service and Maintenance Log



DIAMOND AIRCRAFT INDUSTRIES INC. D.O.T. APPROVED MANUFACTURER #161-93

Registration: AC Serial Number: LH Engine Serial Number: RH Engine Serial Number LH Prop Serial Number: RH Prop Serial Number: Airframe Total Time:

N502LA 62.C022 E4P-C-00265 E4P-C-00266 190626 190628

LH Total Time Engine Brought forward from Production Test Flight Journey Log (DAI - Form Q-224): 47 HRs

No STC's incorporated

Bi-weekly AWD check carried out to current revision 2020-04 all applicable AD's complied with, see

The work described above was carried out IAW the applicable Standard of Airworthiness.

Q 8 Inspector

FEB 2 6 2020

(Intentionally left blank below this point)

ENGINE MODEL: AE330 ENGINE S/N (L): E4P-C-00265 REG. NO: N502LA WORK ORDER: 0129



SIGNED: /

Aircraft Service

Premier Aircraft Sales, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

A/C TSN X : ENG TT L: % :

Left Engine Entries

DATE: 8/6/2020

 Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra Inspected gearbox chip collector

*	Chad Cox, License: AP3	782800
		8 U.S. 12
ENGINE MODEL: AE330 ENGINE S/N (L) E4P-C-00265 REG. NO N502LA WORK ORDER 0250	Premier	Premier Aircraft Service, Inc. 3804 Falcon Way W

DATE: 4/15/2021 A/C TSN: 1871 ENG TT L; 1871 FLIGHTTIME 1871

Work Order: 0129

Printed by EBis 3 (datcomedia.com

Left Engine Entries

Performed 100 Hour Inspection using DA62 AMM as a guide
 Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra
 Inspected gearbox chip collector

Replaced #1 top exhaust nut

and the engine has been inch.		
rap	od IAW an Annual Inspection and was detailed	
DATE: MARIE	ed IAW an Annual Inspection and was determined to be in airworthy condit	tion
DATE: 4/15/2021	Condition of the condition	lion

Seastead, License: AP3492477 IA

Work Order: 0250

Printed by EBis 3 (datcomedia.com)



ENGINE MODEL AE330 ENGINE S/N (L) E4P-C-00265 REG NO N502LA WORK ORDER: 0562



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 5/11/2022 A/C TSN: 274.5 ENG TT (L): 274.5 FLIGHTTIME: 274.5

Left Engine Entries

- Performed 100 Hour Inspection using DA62 AMM as a guide
- Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra
- Inspected gearbox chip collector
- Performed 300hr gearoil and filter change
- Performed 300hr Injector Cover Zonal Inspection Performed 300hr Alternator Inspection
 Performed 300hr TVD Inspection

I certify this engine has been inspected in a	coordance with an Annual Inspection and was determined to be in clausethy and the
The state of the s	cordance with an Annual Inspection and was determined to be in signed by an attitude

Chad Cox, License: AP3782800 IA

DATE: 5/11/2022

SIGNED:

Work Order: 0562

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE330 ENGINE S/N (L): E4P-C-00265 REG NO N502LA WORK ORDER: 0575



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 5/11/2022 A/C TSN: 274.5 ENG TT (L): 274.5 FLIGHTTIME: 274.5

Left Engine Entries

- MSB-E4-029 Installed BPA restrictor
- Replaced turbo and head drain gaskets
- Replaced oil filter housing return o-ring
- Replaced turbocharger with new E4C-00-410-000-BHY

Chad Cox, License:		Work Order:
		Printed by EBis 3 (datcomedia
	* ***	

	DON DAVIS	
	HAIHTION	
	Going your way every day since 1957	
	Left Engine Logbook Entry	
Date: 11-30-2022	Aircraft: N502LA	SN: 62C022
TSMOH: 377.2	TTAF: 377.2	Tach: 377.2
0 1 1 1 1001		
complied with 100 hour inspection of	on the engines per Austro Engines Mai	ntenance manual chapter 5 requirements.
this date. Oil and filter changed usin	g Aeroshell Diesel Liltra and 100 have	literate manual chapter 5 requirements.
rearboy filter and replaced seed as	g Aeroshell Diesel Ultra and 100 hour	Kit p/n E4A-52-000-KIT. Cleaned the
som box illici aliu ichiaccu geallicix i	on with shell shires so tax ME 75W/	7/1 Tigal 1
engine was inspected in accordance	with an 100 hour inspection and was de	etermined to be in airworthy condition.
/	/	etermined to be in all worthy condition.
<i>F1</i>	111	
//.		
/1/	MILL	_ A&P3296474IA
	/ /-	
CHARTER AIRCRA	T MANAGEMENT PULL OPPAR	IOD DD O
CHARTER - AIRCRA	FT MANAGEMENT - FULL SERV	ICE FBO - MAINTENANCE
	TO STATE OF THE ST	
	Hwy 136 West - Henderson, KY 42420 - Telepl	
	TO STATE OF THE ST	
	TO STATE OF THE ST	

Section 3A: Engine Service and Maintenance Log Going your way every day since 1957 Aircraft Logbook Entry (MED Aircraft: N502LA Date: 2-16-2023 TTAF: 391.7 SN: 62.C022 TSMOH: 391.7 Annual inspection completed this date. AD's checked thru CD2023-02. I certify that this aircraft has been inspected with an Annual inspection and was determined to be in airworthy condition. _A&P3296474IA - FULL SERVICE FBO - MAINTENANCE **CHARTER** AIRCRAFT MANAGEMENT Don Davis Aviation, Inc - 2154 Hwy 136 West - Henderson, KY 42420 - Telephone 270 826 6000 - Fax 270 826 6040 MAKE. DIAMOND MODEL DA62 Aero City Maintenance 2901 East Spring St. Suite A LONG BEACH, California 90806 W/O # 4608 DATE 09-27-2024 A/C Tach. 570.9 ENG TT - L 570.9 REG. NO: N502LA SN - L: E4P-C-00265 Complied with 100Hr/Annaul inspection using Diamond aircraft chapter 5 maintenance manual and FAR part 43 appendix D as a guide. Engine oil Complied with 100Hr/Annaul inspection using Diamond aircraft chapter 5 maintenance manual and FAR part 45 appendix 0 as a guide Engine oil drained, oil filter removed and inspected with no defects noted, service engine oil with Shell Diesel Ultra and 100hr service kit PN: E4A-52-000-KIT. All applicable Airworthiness Directives have been researched through bi-weekly issue 2024-18 Performed LH engine 300/600 hour inspection and servicing as required using Austro E4.08.04R31 MM as a guide. Replaced LH engine flywheel PN. Performed LH engine 300/600 hour inspection and servicing as required using Austro E4.08.04R31 MM as a guide. Replaced LH engine flywheel PN. E4PB-73-000-000-KIT SN: 08215 (old SN: 03254) and wastegate circlip for 600 hour replacement using Austro E4.08.04R31 MM as a guide. Replaced High pressure pump PN: E4A-30-000-BHY SN: 23-10-12-02-01519 (old SN: 12-04-02-06-00021) due to 600hr life limit using Austro E4.08.04R31 MM as a Replaced LH oil inlet drain and injector cover drain seals using Austro MM Ch. 79 as a guide. Operation/leak check good... Replaced LH engine exhaust shock mount PN: 597205 due to break using Diamond DA62 AMM Ch. 78-10 as a guide. I certify that this Aircraft has been inspected in accordance with Annual inspection checklish and was DATE: 09-27-2024 SIGNED: Jonathan Shea WORK ORDER: 4608 Cert: AP 3823821 IA Printed by EBIS (EBISCloud.com) THIS PAGE PREVIOUS TOTALS TOTALS SINCE NEW CARRY FORWARD to Top