


ENGINE LOG BOOK/



CONTINENTAL MOTORS

Aircraft Engine Test Verification

This document verifies that the engine model listed below has satisfactorily completed all testing listed below in accordance with TCM standard engine testing specifications as approved by the FAA.

Engine Model

0470R4ZB

Engine Serial Number 466802

Testing Completed

Standard Acceptance Test:

Date of Completion 8-14-01 Test Operator



Form No 98344

CONTINENTAL MOTORS

AvTecH • 7079 Airport Rd. • Fleming-Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084 N52590 8/25/01 Tach 1174 TTE 0.0

Completed ANNUAL inspection this date, utilizing Cessna Service Manual and FAR 43.9App. D. Installed NEW Factory engine, installed with new alt belt, engine mounts, gaskets, seals and hoses as applicable. Installed prop with new nuts and seal. Installed CH48110 filter, filled with 12qt's Aeroshell 100 mineral oil. Replaced air filter {BA8103-1}. Inspect exhaust, heat exchange and baffles. Check mag timing. Dress prop, inspect spinner. Checked and complied with AD's to date, see report. Lubed all controls, ground run-up, test flew and performed op's and leak check, all checks satisfactory. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

Brian Coleman A&P 400087835IA

₹AvTecH • 7079 Airport Rd. • Fleming-Mason Airport • Maysville, Ky. 41056 • (606) 742-2084

1/9/02 N52590 Tach 1202 TTE 28

Change engine oil/filter, installed cp48110 filter, serviced with 12qt's Aeroshell 15W50. Ground run-up, performed on's check all checks satisfactory.

Brian Coleman 400087835

₹AvTecH • 7079 Airport Rd. • Fleming-Mason Airport • Maysville, Ky. 41056 • (606) 742-2084

4/24/02 N52590 Tach 1219

Replaced fuel line from strainer to carb with new (111F418D0120) ref (S1167-8-0120). Ground run-up, performed op's check all checks satisfactory.

Brian Coleman A&P400087835

	Total Time		Time Since Last Overhau	Engine Service and Maintenance Recor
	Hrs.	Min.	Hrs. Min.	Installations, Inspections, Airworthiness Directives, Special Inspection Modifications and Service Bulletins
N52590 9/16/0 Completed Ann lest: {Hot} 1~80 metal found],insexhaust, heat ex date, see report.	D2 Tach 1 ual inspec D/#72) 2~ stalled CF change ar Washed (ERTIFY 1	231 TT ction this 80/72) 3 148110 find baffles engine, lu	E 57 date, utilizing Co ~ 80/74) 4~ 80/7 ilter, filled with 1 s. Check mag tim ubed all controls,	Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084 essna Service Manual and FAR 43.9App. D. Performed cyl. comparison 4) 5~80/74) 6~80/75). Changed engine oil/ filter and inspect filter,[no 2qt's Aeroshell 15W50 oil. Replaced air filter {BA8103-1}. Inspect sing. Dress prop, inspect spinner. Checked and complied with AD's to ground run-up, and performed op's and leak check, all checks BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL AIRWORTHY CONDITION.
*******	*****	**** ***	A STATE OF THE PARTY OF THE PAR	Brian Coleman 4000878351A
A	vTecH	d • 7 <u>079</u> .	Airport Rd. • Flem	ning-Mason Airport • Maysville, Ky. 41056 • (606) 742-2084
Change engine (MCC299506-	e oil/filter -0102). G	round rui	d CH48110 filter, n-up, performed of	serviced with 12qt's Aeroshell 15W50. Installed new prop cable op's check all checks satisfactory. Brian Coleman 400087835 D***********************************
		· · · · · · · · · · · · · · · · · · ·		
N52590 9/19 Completed Al comparison to inspect filter, TCM Top Ca exhaust, heat Airworthy Di	7079 A 9/03 Tac nnual inspest: {Hot} [no metal re checklif exchange rectives to	hometer bection the 1~80/75 I found], it st (rear of and baff to date, seems, satisfied	• Fleming-Masor: 1283 Total Tinis date, utilizing (2 × 80/67) 3 × 80 nstalled CH4811 of log). Replaced cles. Check magner report. Washed factory, LCERTI	Pus Design Authorized Service Center/ Member TCM Link (Alirport (FGX) • Maysville, Ky. 41056 • (606) 742-2084 The Engine: 109 Cessna Service Manual and FAR 43.9Appendix D. Performed cylinder (0/70) 4~80/70) 5~80/68) 6~80/72). Changed engine oil/ filter and (0 filter, filled with 12qt's Aeroshell 15W50 oil. Complied with SID97-2 (air filter {BA8103-1}. Rescaled forward feft oil galley plug. Inspect (eto timing. Dress prop, inspect spinner. Checked and complied with (engine, lubed all controls, ground run-up, and performed operational (FY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE (TERMINED TO BE IN AIRWORTHY CONDITION)
			1/2	·
Brian Colema	an 400087			
	ı	l	•	ning-Mason Airport • Maysville, Ky. 41056 • (606) 742-2084

_ ___

Date	Tota	Time	;	Since verhaul	Engine Service and Maintenance Record
	Hrs.	Min.	Hrs.	Min.	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
6/1/04 N52590 Ta	ich 1337 filter, inst	alled CH			son Airport • Maysville, Ky. 41056 • (606) 742-2084 iced with 12qt's Aeroshell 15W50. Ground run-up. performed op's Brian Coleman A&P400087835
N52590 10/ Completed A comparison t Changed eng 15W50 oil. C exhaust, heat Airworthy Di and leak chec	15/04 Tannual insect: {Hot ine oil/ file omplied exchange rectives tan in the control of the con	achomete pection the 1~80/68 Iter and in with SID and baff to date, seecks satis	er: 1358 his date, a solution of the control of the	Total Tim Itilizing Co 8) 3~80/6 er.[no me 4 Top Can ck magnete Washed er	s Design Authorized Service Center/ Member TCM Link Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084 te Engine: 184 essna Service Manual and FAR 43.9Appendix D. Performed cylinder 58) 4~80/68) 5~80/74) 6~80/69). Clean and gap sparkplugs. tal found], installed CH48110-1 filter, filled with 12qt's Aeroshell e checklist (rear of log). Replaced air filter {BA8103-1}. Inspect of timing. Dress prop. inspect spinner. Checked and complied with 12qt's Aeroshell engine, lubed all controls, ground run-up, and performed operational THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE ERMINED TO BE IN AIRWORTHY CONDITION Brian Coleman 4000878351A
N52590 2/1/05 Changed engine	7079 Airp Tachon oil/ filte laced oil	ort Rd. • Fineter: 13' r and insponential r and insponential	F <i>leming-N</i> 76 pect filter, m with ne	<u>lason Airp</u> [no metal w. Installe	found], installed ES48110 filter, filled with 12qt's Aeroshell ed Tanis engine pre heater TAS100-12. Ground run-up, and sfactory. Brian Coleman A&P400087835
N52590 6/9/0: Changed engin	<u>7079 Airp</u> 5 Tach or e oil/ filte	oort Rd. • neter: 14 or and ins	<i>Fleming-l</i> 04 pect filter	<i>Mason Ain</i> .[no meta	I found].installed CH48110-1 filter, filled with 12qt's Aeroshell and leak checks, all checks satisfactory. Brian Coleman A&P400087835

Total Time Time Since Date Last Overhaul Hrs. Min. Hrs. Min.

Engine Service and Maintenance Record

Installations, Inspections, Airworthiness Directives, Special Inspections. Modifications and Service Bulletins

AvTecH · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd. • Fleming-Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084

N52590 11/7/05 Tachometer: 1438 Total Time Engine: 264 Completed Annual inspection this date, utilizing Cessna Service Manual and FAR 43.9Appendix D. Performed cylinder comparison test: {Hot} 1~80/68) 2~ 80/65) 3~ 80/74) 4~ 80/70) 5~ 80/65) 6~ 80/70). Clean and gap sparkplugs. Changed engine oil/ filter and inspect filter, [no metal found], installed CH48110-1 filter, filled with 12qt's Aeroshell 15W50 oil. Complied with SID97-2 TCM Top Care checklist (rear of log). Replaced air filter {BA8103-1}. Inspect exhaust, heat exchange and baffles. Adjust alternator belt tension. Replace egt probe with new MM-111. Repair crack left rear baffle. Insulate carb probe leads. Check magneto timing. Dress prop, inspect spinner. Checked and complied with Airworthy Directives to date, see report. Washed engine, lubed all controls, ground run-up, and performed operational and leak checks, all checks satisfactory, I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION

400087835/A

AvTecH · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd. • Fleming-Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084

N52590 11/14//05

Completed the following maintenance/ repairs: Replaced alt battery terminal with new. Replaced one cowling Lord mount.. Ground runup, and performed operational and leak checks, all checks satisfactory.

AvTecH · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd. • Fleming-Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084

N52590 12/15/06 Tachometer: 1449 Total Time Engine: 275 Completed the following maintenance/repairs: Changed engine oil/ filter and inspect filter.[no metal found].installed CH48110-1 filter, filled with 12qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and

leak checks, all checks satisfactory. A&-P400087835

AvTecH · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd. • Fleming-Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084

N52590 5/9/06 Tachometer: 1460

Completed the following maintenance/ repairs: Replaced vacuum pump with o/h unit 216CW serial no 51651. Ground run-up. and performed operational and leak checks, all checks satisfactory.

AvTecH · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd. • Fleming-Mason Airport (FGX) • Maysville, Ky. 41056 • (606) 742-2084

N52590 6/9/06 Tachometer: 1468

Completed the following maintenance/ repairs: Replaced propeller governor with overhauled unit serial number 753709 (release in records). Ground run-up, and performed operational and leak checks, all checks satisfactory.

A&P400087835

Date Total T' UNIT GOVERNOR MODEL C29003/T1 T.S.O. Modified C
Hrs. S. New L. 753709
Serial No's. Serial No's. Serial No's. Serial No's. Serial No's. The Aircraft and or component identified above was repaired and inspected in accordance of the current Federal Air Regulations and was found airworthy for return to service. Pertinent detail the repair are on file at this agency under Work Order No. May - 23 - 20 Signed A S PROPELLER SHOP, INC- CERT. NO. MQ5R05 6220 G-ROW OAKLAND COUNTY INT. AIRPORT, WATERFORD, MICHIGAN 4:
AvTech · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd. · Fleming-Mason Airport (FGX) · Maysville, Ky. 41056 · (606) 742-2084 N52590 6/16/06 Old Tachometer: 1469 NEW TACH: 0.0 Total Time Engine: 295 Completed the following maintenance/ repairs: Replaced tachometer with new D1-112-5023 serial no. 26074. Ground run-up, and performed operational and leak checks, all checks satisfactory. A&P400087835
AvTecH · Aircraft Maintenance and Repair / Cirrus Design Authorized Service Center 7079 Airport Rd · Fleming-Mason Airport (FGX) · Maysville, Ky. 41056 · (606) 742-2084 N52590 7/19/06 Tachometer: 10 Total Time Engine: 305 Completed the following maintenance/ repairs: Changed engine 64/ filter and inspect filter. [no metal found].installed CH48110-1 filter, filled with 12qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and leak checks, all checks satisfactory. A&P400087835
Avtech Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry N52590: TCM 0470R42 S/N 466802 Date: 11/29/06 Tach 37 TTE: 332 Performed the following maintenance/ repairs: Completed Annual inspection this date, utilizing Cessna Service Manual and FAR 43.9Appendix D. Performed cylinder comparison test: {Hot} 1~80/66) 2~80/66) 3~80/67) 4~80/72) 5~80/62) 6~80/64). Clean and gap sparkplugs. Changed engine oil/ filter and inspect filter.[no metal found].installed AA48110 filter, filled with 12qt's Aeroshell 15W50 oil. Complied with SID97-2 TCM Top Care checklist. Replaced air filter {BA8103-1}. Replaced carb temp probe with new 0550209-1. Inspect exhaust, heat exchange and baffles. Check magneto timing. Dress prop. inspect spinner, replaced forward bulkhead and shim to fit Checked and complied with Airworthy Directives to date, see report. Lubed all controls, ground run-up, and performed operational and leak checks, all checks satisfactory. I CERTIEY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL. INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. 4000878351A

Date	Ť	otal Time	Time Si		Г <u>— — — — — — — — — — — — — — — — — — — </u>	
	·	Olai Tiiris	Last Over		Engine Service and Maintenance Reco	rd
	Hr	s. Min.	Hrs.	Min.	Installations, Inspections, Airworthiness Directives, Special Inspectio Modifications and Service Bulletins	ns,
Brought Forwa	ard —	-			modified the Service Bulletins	
	NvTecH.	AiranaG M	factors and			
N52500 45	7079	Airport Rd. •	<u>aintenance :</u> Fleming-Masc	<u>and Re</u> on Airpo	epair / Cirrus Design Authorized Service Center ort (FGX) • Maysville, Ky. 41056 • (606) 742-2084	
i in Compicied i	he following	maintenance	ronaium Ch	gait. M		
tilled with 12 checks, all cl	lqt's Aerosh recks satisfa	iell 15W50 oil. actory.	. Comply with A	AD 96-1	ne oil/ filter and inspect filter,[no metal found].installed AA48110 filter, 2-22 by inspection. Ground run-up, and performed operational and leak	
		-				
					A&P400087835 —	
	1	1 1	1	1		
2	} AvTec⊦	l · Aircraft	Maintenanc	e and	Repair / Cirrus Design Authorized Service Center	
N52590 9	<u>707</u> 9/19/07 Ta	9 Airport Rd.	• <i>Fleming-Ma</i> .9 Total Time I	son Air	port (FGX) · Maysville, Ky. 41056 · (606) 742-2084	_
[1] Compicted	the followi	mg maintenan	ce/renaire: Ch	cugine:	300.7	
checks, all	checks sati	stactory,	oil. Comply with	h AD 96	igine on/ filter and inspect filter.[no metal found].installed AA48110 filter, i-12-22 by inspection. Ground run-up, and performed operational and leak	
					<i>fb C</i>	
<u> </u>	1				A&P400087835	
	(] -
	in us					-
├─ ─	<u>Flemir</u>	ng-Mason Ai	rport (FGX) 7	7079 Air	Avtech rport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net	-
		TCM	0470P-42	E / N. 4	66002 Det 45/49/	-
Perfori 43.9Ai	ned the foll ppendix D 4	owing mainter	nance/ repairs: (Complete	66802 Date: 12/19/07 Tach 99 TTE: 394 66 Annual inspection this date, utilizing Cessna Service Manual and FAR	
l lap val	ves install n	ew ring set an	d oasters Pool	an test. T	100, 1~60/68) 2~ 80/22) 3~ 80/62) 4~ 80/66) 5~ 80/60) 6~ 80/63). R&r cylinder 2	ļ -
Replac	ed complete	exhaust syste	m with new nas	o neada	Complete With 31797-2 TCW Top Care checklist. Replaced air filter {BA8103-11	_
to date.	see report.	Lubed all con	trole Ground ru	II) (II) 04	a ward bunknead and saim to fit. Checked and complied with Airworthy Directives	
DETE	THIS ENC RMINED T	GINE HAS BI FO BE IN AH	EEN INSPECT RWORTHY C o	ED IN.	ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS	
					4000878351.4	
		,				_
				<u> </u>		
CIRRUS					<u> </u>	
					Avtech	
- <u>F/e</u>	<u>ming-Mas</u>	on Airport (i	FGX) 7079 Ai	<i>rport R</i>	AVIECTI 2d. Maysville, KY 41056 606-742-2084 avtech@alltel.net 2 Entry N52590;	
Performed the	following n	TCM (9470R-42 5	/N 46	6802 Date: 5/21/08 Tach 113	
with 12qt's Ae	roshell 15W	50 oil., Groun	epans. Changed ld run-up, and p	erforme	6802 Date: 5/21/08 Tach 113 oil/ filter and inspect filter.[no metal found].installed AA48110 filter. filled d operational and leak checks, all checks satisfactory.	\neg
- [•		A&P400087835	\neg
	1					ᅱ
	1		1	1		

Total Time Time Since Date **Engine Service and Maintenance Record** Last Overhaul Installations. Inspections, Airworthiness Directives, Special Inspections, Hrs. Min. Hrs. Min. Modifications and Service Bulletins Brought Forward Avtech Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry N52590: TCM 0470R-42 S/N 466802 Date: 7/14/08 Tach 120 Performed the following maintenance/repairs: Installed the JPI EGT-701 engine temperature and fuel flow monitoring system. Installed as per STC SA2586NM R 6/17/1999, STC SA00432SE 12/16/2000, J REF FAA FORM 337 THIS DATEJ. Ground run-up and performed operational checks, all checks satisfactory Ground run-up, and performed operational and leak checks, all checks satisfactory, A&P 400087835 Avtech Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry N52590: TCM 0470R-42 S/N 466802 Date: 11/4/08 Tach 134 Performed the following maintenance/ repairs: Changed engine oil/ filter and inspect filter.[no metal found] installed AA48110 filter. filled with 12qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and leak cheeks, all checks satisfactory. Avtech Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry N52590: TCM 0470R-42 S/N 466802 Date: 1/5/09 Tach 138 TTE: 433 Performed the following maintenance/repairs: Completed Annual inspection this date, utilizing Cessna Service Manual and FAR 43.9 Appendix D. Performed exhinder comparison test: {Hot} 1~80/64) 2~80/53) 3~80/56) 4~80/66) 5~80/59) 6~80/64). Complied with SID97-2 TCM Top Care checklist. Replaced air filter [BA8103-1] Inspect exhaust, heat exchange and baffles. Check magneto timing, Dress prop. inspect spinner. Checked and complied with Airworthy Directives to date, see report. Lubed all controls, Ground run-up, and performed operational and leak checks, all checks satisfactory. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. 4000878351.4 Avtech Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@alltel.net Engine Entry N52590: TCM 0470R-42 S/N 466802 Date: 3/12/09 Tach 142 Performed the following maintenance repairs. Changed engine oil: filter and inspect filter.] no metal found], installed AA48110 filter, filled with 12qt's Acroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and leak checks, all checks satisfactory .1&P400087835

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net Engine Entry N52590:

TCM 0470R-42 S/N 466802 Date: 11/3/10 Tach 202

Performed the following maintenance/repairs: Changed engine oil/ filter and inspect filter.] no metal found], installed AA48110-2 filter, filled with 12qt's Acroshelf 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and leak checks, all checks satisfactory.





Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net Engine Entry N52590:

TCM 0470R-42 S/N 466802 Date: 3/15/11 Tach 209 TTE: 504

Performed the following maintenance/repairs: Completed Annual inspection this date, utilizing Cessna Service Manual and FAR 43 9Appendix D. Performed cyfinder comparison test: {Hot} 1~80/55) 2~80/28) 3~80/56) 4~80/64) 5~80/58) 6~80/64). Removed cylinder 2 reinstalled cylinder 2 after overhaul 8130-3 in records installed with new gaskets and seals. Changed engine oil/lilter installed A V18110-2 filter and serviced with 12 qt's Aeroshell 15W50. Complied with SID97-2 TCM Top Care checklist. Replaced air filter [BA8103-1]. R&R factory cht probe clean unit and connections. Inspect exhaust, beat exchange and baffles. Check magneto timing. Dress prop. inspect spinner. Checked and complied with Airworthy Directives to date, see renort. Lubed all controls. Ground run-up, and performed operational and leak cheeks, all cheeks satisfactory. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

40008783514

ord

tions.



Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net **Engine Entry N52590:**

TCM 0470R-42 S/N 466802 Date: 8/4/11 Tach 225

Performed the following maintenance/repairs: Changed engine oil/filter and inspect filter. [no metal found],installed AA48110-2 filter. tilled with 12qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and leak checks, all checks satisfactory



Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net Engine Entry N52590:

TCM 0470R-42 S/N 466802 Date: 1/4/12 Tach 246

Performed the following maintenance/repairs: Changed engine oil/filter and inspect filter. no metal found installed AA48110-2 filter. filled with £2qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection, Ground run-up, and performed operational and leak checks, all checks satisfactory

BA___1&P3498105



DETERMINED TO BE IN AIRWORTHY CONDITION.

Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net Engine Entry N52590:

TCM 0470R-42 S/N 466802 Date: 4/16/12 Tach 252 TTE: 547

Performed the following maintenance/repairs: Completed Annual inspection this date, utilizing Cessna Service Manual and FAR 43.9 Appendix D. Performed cylinder comparison test. [Hot] 1:80/61) 2:80/65) 3:80/56) 4:80/62) 5:80/62) 6:80/60). Complied with SID97-2 1CM Top Care checklist. Replaced air filter {BA8103-1}. Inspect exhaust, heat exchange and halfles. Check magneto timing. Dress prop. inspect spinner. Checked and complied with Airworthy Directives to date. AD96-12-22 by inspection next due ann or filter removal, see report. Lubed all controls, Ground run-up, and performed operational and leak checks, all checks satisfactory. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS

34981057.1

Date	Total	Time	1	Since verhaul	Engine Service and Maintenance Record
	Hrs.	Min.	Hrs.	Min.	Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
Brought Forward	410000000000000000000000000000000000000	->			



Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net **Engine Entry N52590:**

TCM 0470R-42 S/N 466802 Date: 7/17/12 Tach 258

Performed the following maintenance/ repairs: Changed engine oil/ filter and inspect filter. no metal found installed AA48110-2 filter. filled with 12qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up, and performed operational and leak cheeks, all cheeks satisfactory.

Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net

Engine Entry N52590: TCM 0470R-42 S/N 466802 Date: 5-7-13 Tach 285 TTE: 580

Performed the following maintenance/ repairs: Completed Annual inspection this date, utilizing Cessna Service Manual and FAR 43,9Appendix D. Performed cylinder comparison test: {Hot} 1~80/6) 2~80/60) 3~80/60) 4~80/64) 5~80/62) 6~80/60). Complied with SID97-2 TCM Top Care checklist. Replaced air filter {BA8103-1}. Cleaned gap sparkplugs. Inspect exhaust, heat exchange and baffles. Check magneto timing. Dress prop. inspect spinner. Checked and complied with Airworthy Directives to date. AD96-12-22 by inspection next due ann or filter removal, see report. Lubed all controls. Ground run-up, and performed operational and leak checks, all checks satisfactory. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION

AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

3498105*L*4

Δ	1/1	P	~	h

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net Airframe N52590:

Cessna 182P S/N 18262692 Date: 10/18/13 Tach 291.5

Performed the following maintenance/ repairs: Replaced alternator with o/h unit Doff10300J s/n 5085167 and new voltage regulator DgR6-1, and noise suppressor S1915-1.FAA 8130-3 in records. Ground run-up and performed operational checks, all checks satisfactory.

A&P 3498105

Avtech

Fleming-Mason Airport (FGX) 7079 Airport Rd. Maysville, KY 41056 606-742-2084 avtech@windstream.net

Engine Entry N52590:

TCM 0470R-42 S/N 466802 Date: 2-25-14 Tach_302

Performed the following maintenance/ repairs: Changed engine oil/ filter and inspect filter,[no metal found],installed AA48110-2 filter, filled with 12qt's Aeroshell 15W50 oil. Comply with AD 96-12-22 by inspection. Ground run-up,

and performed operational and leak checks, all checks satisfactory.

Avtech Fleming-Mason 606-742-2084 Engine Entry N	Airport (ยพทเตรเก	eam.net		ysville, KY 41056	
TCM 0470R-42 Performed the f date, utilizing C comparison test 80/56) 5~ 80/5 plugs. Inspect of prop, inspect so Directives to dai all controls. Gro satisfactory. I C ACCORDANCE W AIRWORTHY CO	S/N 4666 ollowing essna Sec., master 8) 6~80 exhaust, inner, pate, AD96 und run-ERTIFY T	mainten ervice Ma orfice 30 0/56). Re heat exc aint blade -12-22 n up, and i HAT THI ANNIJAI	e: 5-21-1 ance/ rep nual and 8: {Cold} placed air change an es. Checke ext due 4	airs: Com FAR 43.9, 1~80/56 filter {B, d baffles. ed and co 02 or filte d operatio	02 TTE: 597 spleted Annual inspection this Appendix D. Performed cylinder) 2~ 80/58) 3~ 80/57) 4~ A8103-1}. Cleaned gap spark Check magneto timing. Dress mplied with Airworthy er removal, see report .Lubed shal and leak checks, all checks N INSPECTED IN WAS DETERMINED TO BE IN	
_ 3498105IA					the second of the second secon	
			and the same of th			
		1 1				
H						
					er fan 'n de skriver oan de skriver fan de skriver De skriver	
<u> </u>						
:					<u>.</u>	
	100 mm m	4	in the second		Aven	- Marie Company of the Company of th

						•
**************************************	1			1		3
			 	 		
		<u> </u>	ļ			
					:	
	_	-	 			
				1		
				ļ		
	1	†	†			4 /
	 	 				
		ŀ				
				-		
	 	 	 	<u> </u>		
		1				
	1					
	 	ļ	<u> </u>	<u> </u>		
				[
		I Total				
	 	ļ				
	<u></u>					
			l			
	 	<u></u>	ļ			
2000-1-00	-					
	ļ					
					,	

Date	Total Time		Last Overhaul		Engine Service and Maintenance Record Installations, Inspections, Airworthiness Directives, Special Inspections,		
	Hrs.	Min.	Hrs.	Min.	Modifications and Service Bulletins		
		0.7 AF	www.n	orthwoods	aviation Maintenance, LLCaviation-maintenance-ilc.com 715 538-3026 1597.6 Engine: TTIS: Unknown TSMOH: 465.2		
I certify that thi Inspection Chec #6 80/71. Checi CH48110-1. Ch checked on the	s Engine sk List. Cl muffler, ecked ma ground an	has been heck AD carb inli gneto to ad detern	inspected compliant jet screen. congine tir mined to l	d In Accordance. Cylind Changed oming. Clea be in an ai	dance With an Annual inspection per Cessna 182 Service Manual for compression #1 80/70, #2 80/71, #3 80/79, #4 80/70, #5 80/68 bil 12 qts 15W50 Aeroshell, replaced oil filter with new uned gapped rotated spark plugs. Aircraft was test run/leak irworthy condition.		
Philip Jankowsk	i Chu	bo .	20	suhul			
					Aviation Maintenance, LLC.		
			www.i	northwood	Is-aviation-maintenance-llc.com 715 538-3026		
October 25, 20	17 Tach	477.3	AFTT: 3	892.5 Ho	obbs: 11617.9 Engine: TTIS: Unknown TSMOH: 484.5		
nistons remove	of all into	ice and c	NUMBER OF STREET	IVES PROBE			
honed all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new.	ders, replaced a ad all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	and all seats and valves, replaced all exhaust valve guides with new, w PN: SA539467, replaced all piston rings with ring sets PN: PN: SA470-T2, installed two missing push-rod tube washers PN: PN: SA642917-1, replaced intake boot expander with new PN: DN: Serviced engine with Phillips 20W50 mineral oil, replaced oil O-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in. A&P2818147		
boned all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a ad all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, a S34609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
honed all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
honed all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
honed all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
honed all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
honed all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, a 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, r 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, r 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		
boned all cylin SA4000-SC2, r 534609, replace 0752016-7, inst filter with new, the ground. No	ders, replaced a red all indu- alled new All work thwoods	aced all all gasker action ai v shock i perform Aviation	piston pin ts with ga- ir hoses wi mount PN ned per Co n Mainten	s with new sket sets P ith new PN : 19534-20 ontinental sance LLC	w PN: SA539467, replaced all piston rings with ring sets PN: "N: SA470-T2, installed two missing push-rod tube washers PN: N: SA642917-1, replaced intake boot expander with new PN: 0. Serviced engine with Phillips 20W50 mineral oil, replaced oil 0-470 Overhaul Manual. Aircraft was test run and leak checked on resumes no responsibility for cylinder break in.		

				rterial	nce Record
Avtech				rectives,	Special Inspections,
Fleming-Mason Ai 606-742-2084 a	rport (FGX) 70	79 Airport Rd. 1	faysville, KY 41056		
Engine Entry N52	san.	The state of the s			
TCM 0470R-42 S/ Performed the foll	N 466802 Date	: 5-21-14 Tach	302 TTE: 507		
date, utilizing Ces	ena Senire Man	nice/ repairs: Co	mpleted Annual inspection	this	
- companion test is	marker outer an		STORPETRUIK D. PRITOFFERD CO.	-Cond-	
80/56) 5~ 80/58)	6~ 80/56). Rep	placed air filter (96) 2~ 80/58) 3~ 80/57) 4 BA8103-1). Cleaned gap s	nast.	
nron inspect spins	mer maint blade.	- Charles College	a Creex magneto timino i	Drace	
- Directives to date	AD06.12.33		complied with Airworthy		
satisfactory, I CER	TIEV THAT THIS	ENGINE WAS	ordinal and leak checks, all c	hecks	
ACCORDANCE WIT	H AN ANNUAL I	NSPECTION AN	EEN INSPECTED IN WAS DETERMINED TO BE		
AIRWORTHY COND 3498105IA	ITION.		DETERMINED TO BE	- 114	
1	_	-			
-					
				-	
-				The state of the s	
1				- A	
_					
		Northwood	Aviation Maintenance, L	1C	
	9	www.northwo	ds-aviation-maintenance-	Ilc com	
May 24, 2015 1			715 538-3026		
May 24, 2015 1					
	Tach: 346.3 AF	FTT: 3761.3 E	715 538-3026 ngine: TTIS: Unknown TS	SMOH: 353.2	82
- I certify that thi	Tach: 346.3 AF	FTT: 3761.3 E	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An	SMOH: 353.2 mual inspection per Cessna 1	
I certify that the Service Manual	Tach: 346.3 AF is Engine has b I Inspection Ch	FTT: 3761.3 E	715 538-3026 ngine: TTIS: Unknown TS in Accordance With an An k AD compliance. Cylinde	SMOH: 353.2	80/67,
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replace	PTT: 3761.3 E been inspected in neck List. Chec #6 80/68. Check d oil filter with	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an Ar k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke	SMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Change d magneto to engine timing a	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replace	PTT: 3761.3 E been inspected in neck List. Chec #6 80/68. Check d oil filter with	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an Ar k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke	SMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Change d magneto to engine timing a	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped	FTT: 3761.3 E been inspected in eck List. Check #6 80/68. Check doil filter with I spark plugs. A	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak of	SMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2 i en, engine oil screen. Change	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen L/H magneto. C determined to	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in neck List. Chec #6 80/68. Chec doil filter with a spark plugs. A porthy condition	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylind k muffler, carb inlet scree new CH48110-1. Checke circraft was test run/leak co.	SMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Change d magneto to engine timing a	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen L/H magneto. C determined to	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in neck List. Chec #6 80/68. Chec doil filter with a spark plugs. A porthy condition	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylind k muffler, carb inlet scree new CH48110-1. Checke circraft was test run/leak co.	SMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Change d magneto to engine timing a	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen L/H magneto. C determined to	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in neck List. Chec #6 80/68. Chec doil filter with a spark plugs. A porthy condition	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylind k muffler, carb inlet scree new CH48110-1. Checke circraft was test run/leak co.	SMOH: 353.2 mual inspection per Cessna 1: er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in the ceck List. Check Heek List. Check Heek 80/68. Check doil filter with a spark plugs. For thy condition	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak compliance.	SMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2 8 en, engine oil screen. Changes d magneto to engine timing a checked on the ground and	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen L/H magneto. C determined to	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in the ceck List. Check List. Check 16 80/68. Check do oil filter with a spark plugs. For thy condition of Links. Northwood:	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak compliance.	sMOH: 353.2 mual inspection per Cessna I: er compression #1 80/65, #2 s m, engine oil screen. Changes d magneto to engine timing a checked on the ground and	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen L/H magneto. C determined to	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in the ceck List. Check List. Check 16 80/68. Check do oil filter with a spark plugs. For thy condition of Links. Northwood:	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak compliance. Aviation Maintenance, LLC ds-aviation-maintenance-llc	sMOH: 353.2 mual inspection per Cessna I: er compression #1 80/65, #2 s m, engine oil screen. Changes d magneto to engine timing a checked on the ground and	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aen L/H magneto. C determined to	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in the ceck List. Check List. Check 16 80/68. Check do oil filter with a spark plugs. For thy condition of Links. Northwood:	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak compliance.	sMOH: 353.2 mual inspection per Cessna 1: er compression #1 80/65, #2 s m, engine oil screen. Changes d magneto to engine timing a checked on the ground and	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo	peen inspected in the leck List. Check 16 80/68. Check doil filter with a spark plugs. For thy condition of the leck List. Northwoods www.northwoods www.northwoods	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak compliance. Aviation Maintenance, LLC ds-aviation-maintenance-llc	sMOH: 353.2 mual inspection per Cessna 1 er compression #1 80/65, #2.3 en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	80/67, d oil 12
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwood ki Plage Check: 410.1 AFT	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the condition of the central www.northwoods www.northwoods.	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak compliance. Aviation Maintenance, LLC ds-aviation-maintenance-llc. 715 538-3026	amual inspection per Cessna II er compression #1 80/65, #2 in, engine oil screen. Changed d magneto to engine timing a checked on the ground and	80/67, d oil 12 djusted
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsl	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwood ki Physical ch: 410.1 AFT	peen inspected in the control of the	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak con- linear	amual inspection per Cessna I: er compression #1 80/65, #2 8 en, engine oil screen. Changes d magneto to engine timing a checked on the ground and	Manual
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsl May 16, 2016 Ta	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Phip ch: 410.1 AFT	peen inspected in the control of the	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke direraft was test run/leak com- line Aviation Maintenance, LLC ds-aviation-maintenance-llc 715 538-3026 : 1547.5 Engine: TTIS: Univerdance With an Annual inspender compression #1 8070.	amual inspection per Cessna II er compression #1 80/65, #2 8 en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankows! May 16, 2016 Tall certify that this E Inspection Check I #6 80/68. Check m	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced be in an airwo ki Place ch: 410.1 AFT ingine has been in List, Check AD on uffler, carb inlet	peen inspected in the control of the	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke chircraft was test run/leak co a. Aviation Maintenance, LLC ds-aviation-maintenance-llc 715 538-3026 1547.5 Engine: TTIS: Un ordance With an Annual insender compression #1 80/70, d oil 12 qts 15W50 Aeroshel	amual inspection per Cessna 1: er compression #1 80/65, #2 sen, engine oil screen. Changed magneto to engine timing a checked on the ground and A&P2818147IA A&P2818147IA A&P2818147IA	Manual 5 80/67 xhaust
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Phillip Jankowsi May 16, 2016 Tall I certify that this E Inspection Check I #6 80/68. Check m CH48110-1. Check	rach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replace Cleaned gapped be in an airwo ki Phys ch: 410.1 AFT ingine has been it List. Check AD couffler, carb inlet cod magneto to e	peen inspected in the ceck List. Check List. Check M6 80/68. Check doil filter with a spark plugs. A porthy condition of the	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak compliance. Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, d oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and A&P2818147IA Com known TSMOH: 417.0 pection per Cessna 182 Service 1 #2 80/70, #3 80/30, #4 80/68, #: III, replaced oil filter with new III, replaced oil filter with new III, replaced oil filter with new III. replaced oil filter with new	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Phillip Jankowsi May 16, 2016 Tall I certify that this E Inspection Check I #6 80/68. Check m CH48110-1. Check	rach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replace Cleaned gapped be in an airwo ki Phys ch: 410.1 AFT ingine has been it List. Check AD couffler, carb inlet cod magneto to e	peen inspected in the ceck List. Check List. Check M6 80/68. Check doil filter with a spark plugs. A porthy condition of the	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak compliance. Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, d oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and A&P2818147IA Com known TSMOH: 417.0 pection per Cessna 182 Service 1 #2 80/70, #3 80/30, #4 80/68, #: III, replaced oil filter with new III, replaced oil filter with new III, replaced oil filter with new III. replaced oil filter with new	Manual 5 80/67 xxhaust 0-SC2.
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Ta I certify that this E Inspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack wi	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak compliance. Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, d oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I	amual inspection per Cessna 1: er compression #1 80/65, #2 sen, engine oil screen. Changed magneto to engine timing a checked on the ground and A&P2818147IA A&P2818147IA A&P2818147IA	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Phillip Jankowsi May 16, 2016 Tall I certify that this E Inspection Check I #6 80/68. Check m CH48110-1. Check	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Tall certify that this Elinspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack will determined to be in	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and A&P2818147IA Com known TSMOH: 417.0 pection per Cessna 182 Service 1 #2 80/70, #3 80/30, #4 80/68, #: III, replaced oil filter with new III, replaced oil filter with new III, replaced oil filter with new III. replaced oil filter with new	Manual 5 80/67 xxhaust 0-SC2.
I certify that thi Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Ta I certify that this E Inspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack wi	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Tall certify that this Elinspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack will determined to be in	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Tall certify that this Elinspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack will determined to be in	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Tall certify that this Elinspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack will determined to be in	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual 5 80/67 xxhaust 0-SC2.
I certify that this Service Manual #3 80/62, #4 80 qts 15W50 Aer L/H magneto. C determined to Philip Jankowsi May 16, 2016 Tall certify that this Elinspection Check I #6 80/68. Check m CH48110-1. Check valve guide SA636 #3 exhaust stack will determined to be in	Tach: 346.3 AF is Engine has b I Inspection Ch 0/70, #5 80/67, oshell, replaced Cleaned gapped be in an airwo ki Play ch: 410.1 AFT ingine has been in List. Check AD on uffler, carb inlet cod magneto to e 6242, grounded in ith new Aerospa	peen inspected in the ceck List. Check List. Check M6 80/68. Check do oil filter with a spark plugs. For thy condition of the condition of the condition of the compliance. Cylin screen. Change ingine. Cleaned intake and exhause welding Job in the condition of t	715 538-3026 ngine: TTIS: Unknown TS n Accordance With an An k AD compliance. Cylinde k muffler, carb inlet scree new CH48110-1. Checke discraft was test run/leak con- linear test and test and test Aviation Maintenance, LLC ds-aviation-maintenance-lic 715 538-3026 : 1547.5 Engine: TTIS: Un ordance With an Annual insunder compression #1 80/70, 1 oil 12 qts 15W50 Aeroshel gapped rotated spark plugs. I st valves/sents, honed cylind order 88841. Aircraft was test	amual inspection per Cessna 1 er compression #1 80/65, #2 s en, engine oil screen. Changed d magneto to engine timing a checked on the ground and	Manual 5 80/67 xxhaust 0-SC2