



	N759	27	
ingine Record General Information			
prial 467165	INENTAL Model	0-470-4	
prial 467165		Type Certificate	
his engine is currently installed in airc	raft		
Vinimum Octane Fuel	Oil Grade: Summer	Winter	
Vagneto Time 24° BTC	Point Setting	Firing Order	
şark Plug Gap	<u>viel</u>		
Imple of the recommended overhaul a	Control of the contro	ours	

19 9 8	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7-21	2010,5	14	M 104	6,3 Engine TOTAL TIME 2010.5
			1.32	A Committee of the second of t
		Engin	e Rem	oved FROM AIRCHAFT AND MAYOR OVERHAULED.
-	ALL ST	eeL	PHATS	MAGNAFLYXED. CHANKSHAFT YLTRASOVICALLY
	tested	La Ch	ANKSHA	FT Polished, countERWeighTS Rebushed,
100				ANDREAD SISE . CHMShAFT BECONDITIONED.
	STARTE	R Ad	APTER	overhauled, PROPELLER GOVERNOR
	overt	AULE	do IN	STALLED 6 NEW CYLINDER ASSEMBLIES.
		ENgi	we As	sembled with the Following New PARTS.
100	ALL	SEAL.	SIGASI	ets, hoses - MAIN BEARINGS - ROD BEARINGS-
	Rod I	0175	+ NY	TS - CHANK GEAR DOLTS - CAM GEAR BOLTS -
				See Next Page>



RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
> "BA	DUGT	FORH	y ARd '
		di anti-	
Hydra	Lie	LIFTE	RS - PISTON PINS - DIL PRESS RELIEF
VALV	e & 54	BING	SHAFT-DIL BY PASS VALUE SPRING-
oil	FILT	P-M	SHAFT-DIL BY PASS VALUE SPRING- AG drive CUSHIDNS - MAGNETO'S - IGNITION
hAR	NESS	- Sp	ARK PLUGS-TACH drive housing.
2 4 1 1 1	CON	Bods	Bebushed, Bocken ABMS Rebusheda
oil C	ooLen	FLUS	hed + tested. Comphied with ADNO
97-	26-17	by u	ATRASONIEHLLY TESTING CHANKSHAFT. End
1.1227.7	18		andrew Sarrell
			A+P 1938121
The second second	The state of		

DATE 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
88	2010.5			Installed engine. Installed new vocumpying
				and probe Reduced Alternator drive belt
		1.34	(A) 2	Repaired engine buffle seals serviced
1111				engine with 12 gps teroshed will
	22	y dis	> VIIIV	Replaced oil filter Run-in engine
	Lize s	RN 1-0	1 4 (8)	adjusted of pressure up defects
		ادرات الما الما	Virginizati	Noted. Date & BUST. (L) (R)
		Lavia	ANNE	I certify that this AC Eng. has been
			1.2.9	inspected in accordance with a structure inspection & has been found airworth.
	Ĭ	417		Sig. Feet
		4		Cert. #



RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2027.1	8/10	11 82	Plenoved Coul, Romoved Ryhi Macj Installed 1
1066.3	A.	and the second	Browned Couly Removed Ryhi Ming Installed M. Ming PN6310, 5N 98091417 IAU SLICK INST. Ground Fan OPS CKELSund Reinstalled Coul
Su -0	The same	Cul	Ground ran ups exedquet Reinstalled Coul
BOTA		(- 1 N - 5 - 7	The maintenance identified above has been inspected and the item
	111/	1.21.20	is approved for return to service. Details are on file at this repair
A Comment	N. C.		station under work order # 100456 Date: 10-13-48
februaries	THE STATE	NATIONAL DESCRIPTION	Signed by: for Knox Air, line CRS # RE4R489M Aloos, TN 37701
AP-13	1 Versient	MELLIN	
100	21	Wy 4	SAN THE RESIDENCE OF THE PROPERTY OF THE PROPE

1996	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
0-21-98	2034.4			Clarge Oil a/ Aeroshell 80w & Justalles
				New filter CH48110 cot open old filter
				Leaks extraced
		12 (40) 70		1 = P414176609 Toler William
			- 4	The maintenance identified above has been inspected and the item
				station under work order # 190491 . Date: 10-21-98
				Know-Air, Inc. CRS & REAR489M Alcoa, TN 3770)

DA

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2096.2	85.7	2096.2	GENERAL SERVICE + INSP. DRAINES OIL,
Sun d	3-47	doi: Oppos	REMOVES, INSP. REPLACED OILFILTER SERVICE
1.00	Maria V	1	WIZETS, Als100 JOIL, INSP. EXHAUST,
			HOSES, ACCESSORIES + ENg. MOUNTS. TIMES
			MAGS. Compression CK. 80/15 74 75 73 74 76
	3/113		ALL KNOWN AB'S C/W SEEKIST AT REAR OF LOG.
Alexander	personal little	.d.L.	RANENG, NO LEAKS NOTES,
			I CERIFIFY THAT THIS ENG. HAS BEEN INSP.
	t shill	mr OAI	IAW AN ANNUAL/100 HR CHECKLIST FERFARK
VEAR			AND WAS FOUND TO BE IN AN AIRWORTHY
		1	CONDITION.
			Charles Cheliton Art 412985607



19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9/5/90	9	i.	r je zela i	
17.			Pate 9-5	ervice and Inspection. Drained oil, cleaned screens,
3.6	ca - A	n	eplaced of	ill filter, serviced with 12 gts Aenoshall lan
4	and the		hecked f	or leaks. Checked engine mount, controls, hoses, exhaust
		1 77		sories. Cleaned and gapped spark plugs. Timed mags.
	1		Compress	prop for condition, dressed and painted prop. Functionally
		Ç	hecked	ingine. Complied with A.D. See A.D. Compliance hit
- 1	2,10		certify th	at this aircraft has been inspected in accordance with
1000	h cala - I	' .)ંદ	ANNI	AL)100 Hour checklist per FAR 43.D and was determined to be
	1 1		Airwor	Hay condition. William E. Humphrey Al 411365897
				WM & Hand
-			· · · · · · · · · · · · · · · · · · ·	

DATE 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				(Smontzo.o)
				DATE 15 SEP 2000 TACH 2830.5
		4	10	GENERAL SERVICE AND INSPECTION. DRAINED OIL, CLEANED SCREEKS,
				REPLACED OIL FILTER, SERVICED WITH 12 QTS. AFROSKELL 80
				CHECKED FOR LEAKS. CHECKED ENGINE MOUNT, CONTROLS, HOSES, EXHAUST
			14	AND ACCESSORIES. CLEANED AND GAPPED SPARK PLUGS. TIMED MAGS.
		-		COMPRESSION CHECK /80. 75 70 72 72 72 72 75
				CHECKED PROP FOR CONDITION, DRESSED AND PAINTED PROP. FUNCTIONALLY
				CHECKED ENGINE. COMPLIED WITH A.D. SEE 45 AT BREACH
				I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH
				ANANNUAL 100 HOUR CHECKLIST PER FAR 43.D AND WAS DETERMINED TO BE
				IN AN AIRWORTHY CONDITION.
				CHARLES C. JOHNSTON JR.
			, y	A&P/IA 412985607
				Males Chilatony

7			ced	
OTO	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
\$/00	2140	2146.5	6.2	TO QUE ZO FIVO - 198 - FMQ - DW- AG - GM - LOS CARTER
1/0/02	2146.5	21508	4,3	LEB NH -> MEN WYA (40-50 Kunds alg) CARTER
1/11	2150.8	2153.1	2.3	042 am from MGN -> TYS
1/9	2153.1	21544	1,1	LOCAL TILS BC LITE STAYSON BUSHON
1/15	7154.4	ZI 55.B	1.4	LOCAL ILS BELITE HAD TO USE MIKE TO THUS MIT
23/01	7.155.8	2156.0	0.20	MAINT / Jung START PLAT NEW BACK
-13/01	2156.0	2402	4,20	TYS-VALUESTA- WE OAK FL - YH- KISSAUNE FLA TO CARTER
2/19/61	2160.2	161.0	0.83	dage posses Kissenne - TAMPA - CARTOL
7/18/0	7161.0	2/65.	4.13	TAMEA - VARIOUSTA - TUS.
2/1/01	2165.1	2167.9	2.87	15- AD2- T-15- Bald to weather Alon 12 hers
5/4/01	2167.1	21731	6.03	TYL-TLH-TYS CLOTO
6/9/0	2173.2	- 2174.7	, 1,10	FTYL-Byson lity-TV-TYL OASA 1993

20)	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9/01	2743	2/752	0.99	TYS - TYS
9/01	2175,2	2176.1	Ø.9°	TYS - T1/5
	2186,6	2187,6	, , 4	735
1				
41	2187,3	2194.1	6.8	TYS-CCO-CMH-TYS FUSHEE/DAVIS
19	2220,5		216	Mys Fe Tys
1 3/		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Fry And Add Asserted to the London Control of the C
			1	
	li i			
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

1993

RECORDING TACH TIME	G TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2 2224			PLUGS CLEINED: GOPPED DEL + FALTER
			CHANCED Shell 40 as oneralled
			1 Pour A Suffer Leating
			I CERTIFY THAT THIS ENGINE + PROP
			ANUL AMUNDO
			IS IN AN AIRWORTHY CONDITION. AP 1615099 IA
	Hall !	1 7 1	
	السيسينا		© ASA 199



19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	Inspected of Drained the filter and a was remove follows: #1 the throttle Installed a Tom E. At For: Technology 2701	engine and e engine of dded 7 qu ed and ser 68/80, #2 rod end v	il and inspectants of Aeros at to G&N Air 264/80, #3 7 with a new rokett BA-8103 A&P1987294 ace	Tach Hours 2282.4 TTSMOH 271.9 accordance with a 100-hour inspection per Continental Service Instruction checklist. Ited the oil filter for foreign contamination-none found. Installed a new CH48110 oil shell 80W A.D. oil. Number #3 cylinder was found to have very low compression so it ircraft for repair then reinstalled on return. Compression check results were as 18/80, #4 64/80, #5 64/80 and #6 64/80. Checked engine timing to magnetos. Replaced d end. Replaced the fasteners on the air inlet duct to connect to the carburetor air box. B-1 air induction filter. Bi-weekly A.D. listing checked through 2003-20.
				interdential control
				Noting of decided three
1				
ASA 1993			-	

T	RECORDING FACH FIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-9	-04	TAZH	2347.	2 REPLATE CRANKSHAFT SEAL
				PIN 641250 REPLAZE PROP. "O" RING
			4/1-	PIN A 1633.3 TORQUE PROP. gRd. RUN
				This o. K. Supple the REPLAZE
				ALEL ZLAMP ON OIL dipHSTIZH,
				Wagnet Style
				18 2 8 413 76 300 1
				BIRZRAFT FECH FNZ
				WORK ORDER # 4029
				© ASA

CS CamScanner

ASA 1993	RECORDING TODAY'S FLIGHT TIME IN SERVICE TOTAL TIME IN SERVICE TOTAL TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)								
	TT: 2363.4 Tach: 2363.4 Hobbs: 1066.3 N759ZT S/N 18266395 Cessna 182Q SWOH 352.9 McGhee Tyson Airport Engine Model: 467165 Engine S/N: 0-470-U TTSMOH: 352.9 TTSN: 2363.4 Chris Carter, Gabriel Fushee, John Myers & Dennis & Sally Bushman Engine Entry Aircraft Technicians, Inc. McGhee Tyson Airport 2285 Alcoa Hwy P.O. Box 1026 Alcoa, TN 37701 (865) 681-4553								
	R&R new brackett air filter element P/N RA8103-1.* Drained oil, removed old oil filter, cut open filter & checked for metal. No metal noted. Installed, torqued, and saftied new filter P/N CH48110 and added 11 qts of 80W Aeroshell oil.* Engine compressions: 1) 62/80 2) 64/80 3) 72/80 4) 60/80 5) 68/80 6) 62/80 * I certify that this engine has been inspected IAW Annual / 100 Hour Inspection Procedures and was determined to be in Airworthy Condition. Aircraft Technicians, Inc. Work Order # 4177 as provided to owner/operator provides information regarding the work performed and is on file. FOR: Aircraft Technicians, Inc. William D. Burchfiel IA# 2860491 11/04/04								

DATE 19—	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	//2006 66.3 Tach: 251			Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026
	United Aero			Alcoa, TN. 37701 (865) 681-4553 #1 Engine Entry
einstalle	engine oil. F ed drain plug engine.	Removed, with gask	cut and ins et MS35776	spected oil filter. Install, torqued and saftied new filter P/N CH48110-1. 69-11.Serviced engine with 11 QTS of Aeroshell 15W50 oil. Ran and leak
ertify that thi	s aircraft/engine/app	liance identified	above was repaire	ed in accordance with FAR's and/or Manufacturer's instructions as applicable and is returned to service as
gards to work	k performed only. Air			r # 5757 as provided to owner/operator provides information regarding the work performed and is on file.
FOR: Aircra	ft Technicians, Inc.	PIVIO	Fellman A&P# 303	M530 IA
		, Onb	Cilillati Adi # 505	7000 IA

DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
TSN: 25 S/N: 46	2/1/2006 Hobb 550.1 TSO: 539 7165 Continen er: United Aero	.9 tial 0-470-l		Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553
oil. Rer Ground certify that Aircraft Tec	noved, inspect I run leak che this engine has been	cted and r ck good. inspected IAW Order # 5860 as	eplaced oil f Adjusted al	pression are: 1) 65/80, 2) 54/80, 3) 61/80, 4) 68/80. 5) 67/80, 6) 65/80. Drained filter with new CH48110-1. Serviced engine with 11 Qts of Aeroshell 80W oil. Iternator belts as needed, torqued and saftied. procedures and was determined to be in Airworthy Condition. operator provides information regarding the work performed and is on file.

DATE .	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endo	spections, Tests, Repairs and Alterations rsed with Name, Rating and Certificate Number of Technician or Repair ges for other specific entries.)
N: 2550. N: 781449	2006 Hobbs: 1 1 TSO: 751.2 9 McCauley C United Aero			Prop Ent	Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553
rify that this raft Technicia	prop has been inspe	r # 5869 as pro	al Inspection proced		
)			
					© As

DATE 19——	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Hobbs: N759ZT	/9/2007 1066.3 Tach: 「Model Cessn er: United Aer	a 182Q S/	N: 18266395	Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553 Engine Entry
Aerosh certify that egards to w	this aircraft/engine/	appliance ideni Aircraft Techn	n leak check lified above was repa	aired in accordance with FAR's and/or Manufacturer's instructions as applicable and is returned to service as der # 6327 as provided to owner/operator provides information regarding the work performed and is on file.
				©ASA 1

19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	그 전쟁 내려면 가장 하는 것으로 가장 하는 것이 되었다. 그 그는 그 그리고 있다면서 바다 이번 없었다.	tions, Tests, Repairs and Alterations with Name, Rating and Certificate Number of Technician or Repair or other specific entries.)
Hobbs N759Z	8/14/2007 s: 1066.3 ZT Model Cess mer: United A		5/N: 1826639	Prop En	Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553
I certify th	nat this aircraft/engin	ne/appliance ide	ntified above was	repaired in accordance with FAR's and/or	Manufacturer's instructions as applicable and is returned to service as
regards to	o work performed or Aircraft Technicians	nly. Aircraft Tech		<i></i>	ator provides information regarding the work performed and is on file.
regards to		nly. Aircraft Tech	micians, Inc. Word	<i></i>	

CS CamScanner

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alter Entries must be endorsed with Name, Rating and Certificate Num Facility. (See back pages for other specific entries.)
H	M	11-30-07 1066 3 2675.3 665.2	Continental 0-470-1 Peg No N759ZT Ser No:
			Horizon Avionics, Inc.
	2361 Air	port Highway	v. #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701
52 no mi ve	W an 100 erformed 2/80 #4: metal neral oi erificati	Hr Inspect AD verifica 68/80 #5: found. Inst 1. R&R oil on. AD96-1 filter wit	ENGINE LOG ENTRY tion this date IAW Horizon Avionics Inc. Inspection Guide tion. Performed compression test, #1: 64/80, #2: 42/80, #3 68/80, #6: 66/80. Drained oil & remove filter, cut open tall new CH48110-1 filter and added 12 qts Aeroshell 80 sump, p/n; 539937 & gasket, p/n; 655546 with new. C/W AD 2-22 c/w by visual inspection. no defects noted R&R the new BA8103-1. R&R #2&3 cylinders after C/H by G&N Ran A/C ops & leak check good.
Ap No	certify proved F M1306.	that this	MAINTENANCE RELEASE Engine has been inspected IAW an 100 Hr Inspection and is To Service. Pertinent Details Are On File Under Work Order Cert. No: 2822398 Date 4/30/7 For Horizon Avionics, Inc.

19	The second secon	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technicia Facility. (See back pages for other specific entries.)
		11-30-0 1066 3 2675.3 0:876.4 : 2675.3	7	McCauley C2A34C204 Peg. No: N759ZT Ser. No: Horizon Avionics, Inc.
	2361	Airport Hig	hway #3	Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701
	 I certif	y that thi For Retur	is Propell rn To Ser	Ran aircraft ops & leak check good MAINTENANCE RELEASE ler has been inspected IAW an 100 Hr Inspection and is rvice. Pertinent Details Are On File Under Work Order Cert. No: 2622598 Date: 1//30/7 For Horizon Avionics, Inc.
2/3			Tauld of A I	

ate: 5/9/2008	Aircraft Technicians, Inc.
ach: 2469.8 - INCORRECT	2285 Airport Highway
759ZT Model Cessna 182Q S/N: 18266395	P. O. Box 1026
ustomer: United Aero	Alcoa, TN. 37701 (865) 681-4553
	#1 Engine Entry
,,,,,,,	pint of cam guard per owner request. Ground run and leak check good
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	accordance with FAR's and/or Manufacturer's instructions as applicable and is returned to service as 016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70	016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	016 as provided to owner/operator provides information regarding the work performed and is on file.
gards to work performed only. Aircraft Technicians, Inc. Work Order # 70 FOR: Aircraft Technicians, Inc.	016 as provided to owner/operator provides information regarding the work performed and is on file.



DATE RECORDING TODAY'S FLIGHT TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)					
	19	TACH	and the second s	TIME IN	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair

Date: 12/22/2008

Hobbs: 1066.3 Tach: 2723.8 TT: 2723.8 TSM6H 7/3,3 Quality People N759ZT Model Cessna 182Q S/N: 18266395

Customer: United Aero

Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553

#1 Engine Entry

Performed Annual Inspection. Drained engine oil, removed, inspected and replaced oil filter with new P/N CH48110-1. Serviced engine with 12 ats Aeroshell 80W, Removed, serviced and reinstalled spark plug per annual. Compressions are: #1 70/80, #2 62/80, #3 70/80, #4 66/80, #5 70/80, #6 72/80 Adjusted idle mixture. Adjusted oil pressure. Adjusted prop governor. Retourque throttle rod end jam nut reinstalled and saftied Installed missing screws in #2 cyl baffle. Installed protective wrap P/N SWP-314 around starter cable and Secured with RTV silicone. Repositioned mixture control cable and adel clamps to prevent chaffing. Installed protective spiral wrap to Carb heat cable and secured with RTV to prevent further chaffing. Adjusted Mixture control cable. Repositioned oil temperature probe cable to prevent chaffing. Re-secured right induction tube clamp. Removed and replaced Crankcase breather adel clamps with new MS21919WDG12 ADEL. Removed and replaced mainfold crossover tube clamp with new clamp. Secured prop gov control cable as required. Secured magneto p-leads as required. Repositioned alt vac cable and cable clamps as required. Re-secured Carb air temp wiring as required. Removed and replaced carb heat scat hose ADEL Clamp with new MS21919WDG-20.

I certify that this ENGINE has been inspected IAW ANNUAL Inspection procedures and was determined to be in Airworthy Condition.

Aircraft Technicians, Inc. Work Order #,7277 as provided to owner/operator provides information regarding the work performed and is on file.

FOR: Aircraft Technicians, Inc.

Jeremy Webster A&P# 2616233IA

@ ASA 199

Date: 12/22/2008 Hobbs: 1066.3 Tach: 2723.8 TT: 2723.8 N759ZT Model Cessna 182Q S/N: 18266395 Customer: United Aero FOR: Aircraft Technicians, Inc.



Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553

#1 Prop Entry


Performed Annual Inspection Dressed prop blades. Installed two new prop spinner forward bulkhead spacers P/N 0752620-3 in addition to original spacers. Re Painted Propeller tips and installed new decals.

I certify that this Propeller has been inspected IAW ANNUAL Inspection procedures and was determined to be in Airworthy Condition.

Aircraft Technicians, Inc. Work Order #7277 as provided to owner/operator provides information regarding the work performed and is on file.

Jeremy Webster A&P# 2616233

	© ASA 1993



19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE		 Tests, Repairs and Alterations ame, Rating and Certificate Number of Technician or Repair r specific entries.)
Date: 4/2] 3/2010 7.8 Tach: 275	84		people mance	Aircraft Technicians, Inc. 2285 Airport Highway
	Model Cessna		l: 18266395	Quality People Quality Performance	P. O. Box 1026

#1 Engine Entry

Alcoa, TN. 37701 (865) 681-4553

C/W Annual Inspection. Drained engine oil, removed inspected and replaced filter with new CH48110-1, no debris found. Torqued and saftied filter, serviced with 12 quarts of Aeroshell 80W, leak check good. Compressions are as follows: 1) 62/80 2) 65/80 3) 65/80 4) 65/80 5) 62/80 6) 68/80 Removed, inspected, tested spark plugs. Tested #2 upper ignition lead tests good, coated bare area with high heat RTV to prevent chaffing.

certify that this engine has been inspected IAW Annual Inspection procedures and was determined to be in Airworthy Condition.

Aircraft Technicians, Inc. Work Order # 7811 as provided to owner/operator provides information regarding the work performed and is on file.

FOR: Aircraft Technicians, Inc.

Customer: United Aero

Jeremy J Webster AP2616233IA

E	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE		ns, Tests, Repairs and Alterations Name, Rating and Certificate Number of Technician or Repair ner specific entries.)
obs: 59Z	28/2010 78.0 Tach: 279 Model Cessn ner: United Aer	a 182Q S/		Quality People Quality Performance	Aircraft Technicians, Inc. 2285 Airport Highway P. O. Box 1026 Alcoa, TN. 37701 (865) 681-4553
				#1 Engine Entry	
que	ed and saftied	new filte	r AA48110. S	il removed cut open and insp Serviced engine with 11 quar	ected oil filter element no debris found. Installed ts Aeroshell 100W. Placed 1 quart in baggage.
que eins tify th	ed and saftied talled engine nat this aircraft/engine	I new filte cowling. e/appliance ider y. Aircraft Tech	r AA48110. S Ops check g	il removed cut open and insp Serviced engine with 11 quar ood. paired in accordance with FAR's and/or Manuf Order # 7971 as provided to owner/operator pro	ected oil filter element no debris found. Installed
rque eins rtify th	ed and saftied talled engine nat this aircraft/engine o work performed onl	I new filte cowling. e/appliance ider y. Aircraft Tech	r AA48110. S Ops check g ntified above was re pricians, Inc. Work	il removed cut open and insp Serviced engine with 11 quar ood. paired in accordance with FAR's and/or Manuf Order # 7971 as provided to owner/operator pro	pected oil filter element no debris found. Installed ts Aeroshell 100W. Placed 1 quart in baggage.
rque eins ertify th ards to	ed and saftied talled engine nat this aircraft/engine o work performed onl	I new filte cowling. e/appliance ider y. Aircraft Tech	r AA48110. S Ops check g ntified above was re pricians, Inc. Work	il removed cut open and insp Serviced engine with 11 quar ood. paired in accordance with FAR's and/or Manuf Order # 7971 as provided to owner/operator pro	pected oil filter element no debris found. Installed ts Aeroshell 100W. Placed 1 quart in baggage.

OASA 1993

Date 8-13-00 Hobbs 113-3 Tach: 2832.3 Horizon Avionics, Inc. 2361 Airport Highway, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 LOG ENTRY Drained oil and cut open filter: no metal noted Installed new CH48110-1 torqued and saftied Serviced 12 qts. Phillips 20W-50 Ground ran engine leak and ops check good MAINTENANCE RELEASE I certify that this Airframe/Appliance has been repaired and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No M2159 Signed: AMAINTENANCE RELEASE. Cert No: 263344. Date 7/360	9	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Rep Facility. (See back pages for other specific entries.)
2361 Airport Highway, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 LOG ENTRY Drained oil and cut open filter: no metal noted Installed new CH40110-1 torqued and saftied Serviced 12 qts. Phillips 20W-50 Ground ran engine leak and ops check good MAINTENANCE RELEASE I certify that this Airframe Appliance has been repaired and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No M2159			Hobbs	113 3	
Drained oil and cut open filter: no metal noted Installed new CH42110-1 torqued and saftied Serviced 12 qts. Phillips 20W-50 Ground ran engine leak and ops check good MAINTENANCE RELEASE I certify that this Airframe Appliance has been repaired and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No M2159					
Drained oil and cut open filter: no metal noted Installed new CH42110-1 torqued and saftied Serviced 12 qts. Phillips 20W-50 Ground ran engine leak and ops check good MAINTENANCE RELEASE I certify that this Airframe Appliance has been repaired and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No M2159			2361 A	irport Highw	
I certify that this Airframe Appliance has been repaired and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No M2159			and saft.	ied Servic	open filter: no metal noted Installed new CH48110-1 torqued
Signed: Bill Cert No: 26257 AF Date 7/3/N			I certify Return To	that this Service. F	s Airframe/Appliance has been repaired and is Approved For
			Signed:	pish	For Horizon Avionics, Inc

Date: 3-21-2011 HM 168 0 Tach 2885 3 Prop TSO:1086.4 Prop TT: 2885.3 Horizon Avionics, Inc. 2361 Airport Highway, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 PROP LOG ENTRY Performed AD verification thru biweekly 2011-05. Ran aircraft ops & leak check MAINTENANCE RELEASE I certify that this Propeller has been inspected IAW an 100 Hr Inspection and 1s Approved For Return To Service. Pertinent Details Are On File Under Work Order	HM 168 0 Tach 2885 3 Prop TSO:1086.4 Prop TT: 2885.3 HOrizon Avionics, Inc. 2361 Airport Highway, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 PROP LOG ENTRY Performed AD verification thru biweekly 2011-05. Ran aircraft ops & leak check MAINTENANCE RELEASE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repa Entries must be endorsed with Name, Rating and Facility. (See back pages for other specific entries	Certificate Number of Technician or Repai
2361 Airport Highway, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 PROP LOG ENTRY C.W an 100 Hr Inspection this date IAW Horizon Avionics Inc Inspection Guide Performed AD verification thru biweekly 2011-05. Ran aircraft ops & leak check good. MAINTENANCE RELEASE I certify that this Propeller has been inspected IAW an 100 Hr Inspection and is Approved For Return To Service. Pertinent Details are Cm File Under Work Order.	2361 Airport Highway, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 PROP LOG ENTRY C.W an 100 Hr Inspection this date IAW Horizon Avionics Inc Inspection Guide Performed AD verification thru biweekly 2011-05. Ran aircraft ops & leak check good. MAINTENANCE RELEASE I certify that this Propeller has been inspected IAW an 100 Hr Inspection and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No. M2358.	HM Tach Prop TS	168.0 2885.3 SO:1086.4		Reg No	N759ZT
good. MAINTENANCE RELEASE I certify that this Propeller has been inspected IAW an 100 Hr Inspection and is Approved For Return To Service. Pertinent Details Are On File Under Work Order	I certify that this Propeller has been inspected IAW an 100 Hr Inspection and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No. M2358.	C/W an	100 Hr I	ighway, #3, A	PROP LOG ENTRY Olis date TAW Horizon Aviening Inc. Lagran	
	No. M2358,	good. I certi	fy that t	this Propell	MAINTENANCE RELEASE er has been inspected TAW an 100 Hr Inspe	& leak check

THE	SERVICE	Entries must be endorsed with Name, Rati	ing and Certificate Number of Technicis								
	Date 3/21/20 Tach 2885.3 HM: 168.0 Eng. TSO. 1086.4	11	TCM 0-470-U Peg No N759ZT Ser No 467165								
		Horizon Avionics, Inc.									
	2361 Airport Hig	hway, #3. Alcoa, TN 37701. Tel: (865) 98	0-7858 Fax: (865) 980-7701								
	Performed AD veri 64/80, #2: 66/80 reinstall #3 cyli with new, S2334-3 Installed new CH48	ENGINE LOG ENTRY spection this date IAW Horizon Avio fication thru biweekly 11-05. Perf . #3: 38/80. #4: 62/80. #5: 62/ nder after repair by G&N Aircraft . Drained oil and remove filter - 8110-1 filter and serviced with 12 of the element with new. p/n BA8103-1.	ormed compression test. #1 80, #6 64/80 Remove and on WO: 67602. R&R CHT probe cut open, no metal found qts Phillips 20W50. Replaced								
	I certify that the Approved For Return No: M2358	MAINTENANCE RELEASE is Engine has been inspected IAW a on To Service Pertinent Details An	an 100 Hr Inspection and is re On File Under Work Order Date: 3/21/11								
	Signed. Je-	For Horizon Avionics, Inc.	Date of The								

RECORDING FACH FIME	FLIGHT TIN	TAL ME IN RVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technic Facility. (See back pages for other specific entries.)
	Hobbs:	05-10-10 189.9 2905.1	Aircraft Cessna 1820 Peg No N759ZT Ser No 18266395
			Horizon Avionics, Inc.
	2361 Airp	ort Highw	yay, #3, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701
	and saftied	d. Service	LOG ENTRY open filter; no metal noted. Installed new CH48110-1 torqued ced 12 qts. Phillips 20W-50 and 1 btl Camgaurd. Ground ran s check good.
	I certify Return To S Signed:	that this ervice. I	MAINTENANCE RELEASE s Airframe/Appliance has been repaired and is approved For Pertinent Details Are On File Under Work Order No. M2411 Cert. No: 262359/AP Date 5/10/1/ For Horizon Avionics, Inc.
		1	

9	RECORDING TACH. TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs (See back pages for other specific entries.)
	Date Hobbs: Tach	07-05-2 223-5 2933-5		Aircraft Cessna 182Q Reg No: N759ZT Ser No: 18266395
	2361	Airport Hig		Horizon Avionics, Inc. coa. TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701
		Anporting	11way. #3. Al	
	Drained	oil and c	ut open fil	LOG ENTRY ter. no metal noted Installed new CH48110-1 torqued
	and sait	ned Serv	viced 12 qt	s. Phillips 20W-50 Ground ran engine, leak and ops
	check go	od		
	T corti	fy that t	his Airfra	MAINTENANCE RELEASE me/Appliance has been repaired and is Approved For
	Return T	o Service	. Pertinent	Details are on Fire under work Order No. Moves
	Signed A	Silliam	Hoppeni	Or Horizon Avionics Inc. Date: 7-5-201
1.41	Signed	O par service	F	For Horizon Ayionics. Inc
	37			
i	<u> </u>			
Louis de				
J	اسلى بالسياسة			
1993		1 77		
			7.	51.7

REC TAC TIMI Date: 04/13/2012

Hobbs: 300.4 Tach: 3003.5

-1204.6 WRENG ETSO:

Horizon Avionics, Inc. 5MOH 993.0.

2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

CW Annual Inspection IAW Horizon Avionics Inspection Guide. 1.)68 2.)64 3.)62 4.)38 5.)62 6.)68 all over 80PSI. Installed new AEC631397 Cylinder in #4 position. Installed 5 ea RHB32E. Drained oil and cut open filter, no metal noted. Installed new CH48110-1, Torque and safety. Serviced 12 qts Aeroshell 100 mineral oil. Installed BA8103-1. CW AD research through biweekly 2012-05. CW AD 83-10-01 no defects noted. CW AD 2011-10-09 no defects noted. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this ENGINE has been inspected IAW a Annual Inspection and was determined to be in an Airworthy condition. Pertinent Details Are On File Under Work Order No. M2643.

Cert. No: AP 2622598 IADate: 4/13/2012,

TCM 0-470-U

Reg. No: 759ZT

Ser. No: 467165

For Horizon Avionics, Inc.

NOTE: ADD 3003.5 TO TACH FOR TYAF. Date:

05/24/2012

Hobbs:

333.3

Tach:

029 2

TTM 3032.7

SMOFI 1022.2

Cessna 182Q

Reg. No: 759ZT

Ser. No: 18266395

Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C. Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

Drained oil and cut open filter: no metal noted. Installed new CH48110-1, torque and safety. Serviced 12 Qts. Phillips 20w-50. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this Airframe/Engine/Appliance has been repaired and is Approved For Return To Service With Respect to Work Preformed. Pertinent Details Are On File Under Work Order No. M2698.

Cert. No: AP2620554 Date: 5/24/12.

For Horizon Avionics, Inc.

TE

Date: Tach: 11/07/12

65.6

Hours: 374.0

TTAF 3069.1

JM64 165

Cessna

182Q

Reg. No:

N759ZT

Ser. No:

18266395

Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

Drained oil and cut open filter; no metal noted. Installed new CH48110-1 torque and saftied. Serviced 11 qts Phillips 20W50 and 1 bottle Campaurd. Bench charged and serviced Acft battery. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this Engine/Appliance has been repaired and is Approved For Return To Service. Pertinent Details Are On File Under Work Order No. M2806.

Signed: _____ Cert. No: <u>36 33 49/</u> Date: <u>// 7 /2</u> For Horizon Avionics, Inc.

Date: Hobbs: 3/11/2013

TCM 0-470-U

Reg. No: 759ZT

Ser. No: 467165

Tach:

84.8

397.0

ETSO:

WRONG 1037 Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

CW Annual Inspection IAW Horizon Avionics Inspection Guide. 1.)70 2.)64 3.)72 4.)70 5.)68 6.)70 all over 80PSI. Drained oil and cut open filter, no metal noted. Installed new CH48110-1, Torque and safety. Serviced 12 qts Phillips 20W50. Installed BA8103-1. CW AD research through biweekly 2013-04. CW AD 83-13-01 no defects noted. CW AD 2011-10-09 no defects noted. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this ENGINE has been inspected IAW a Annual Inspection and was determined to be in an Airworthy condition. Pertinent Details Are On File Under Work Order No. M2875.

Cert. No: AP 2622598 ID Date: 3/11/13

For Horizon Avionics, Inc.

chr

	9/30/13 21.3	1TAF 3064.4	Cessna Reg. No:	182Q N759ZT
Hours: 44	41.1 325-9		Ser. No:	18266395
SMOH /	113.9	Horizon Avionics, In Drive, Suite C, Alcoa, TN 37701. Tel: ((865) 980-7701
		ENGINE LOG ENTRY		(111)
		nag check per Cessna 182 POH		
found #2 bo open filter; r	ttom plug ci no metal no	nag check per Cessna 182 POH racked replaced with new RHB32 ted. Installed new CH48110-1 tord bottle cam guard . Ground ran A	E spark plug. Dra que and saftied. S	ined oil and Serviced with

	-	F
		Ī
	•	I

Date:

4/2/2014

468.1

Tach: 145.1 ETSO:

SMOH

Hobbs:

-1349.71130,7

AFIT 3,06 B.Z

TCM 0-470-U

Reg. No: 759ZT

Ser. No: 467165

Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C. Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

CW Annual Inspection IAW Horizon Avionics Inspection Guide. 1.)66 2.)64 3.)64 4.)66 5.)62 6.)62 all over 80PSI. Drained oil and cut open filter, no metal noted. Installed new CH48110-1, Torque and safety. Serviced 11 qts Phillips 20W50. Installed BA8103-1. CW AD research through biweekly 2013-04. CW AD 83-13-01 no defects noted. CW AD 2011-10-09 no defects noted. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this ENGINE has been inspected IAW a Annual Inspection and was determined to be in an Airworthy condition. Pertinent Details Are On File Under Work Order No. M3176.

Signed

Cert. No: AP 362578 TA Date: 4/2/14
For Horizon Avionics, Inc.

RECOL TACH TIME

Date:

07/15/2014

Tach: 171.8 Cessna

1820

Reg. No:

N759ZT

Ser. No:

18266395

Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

Drained oil and cut open filter; no metal noted. Installed new CH48110-1 torque and saftied. Serviced 11 qts Phillips 20W50 and 1 bottle Campaurd. CW compression check, no defects noted. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this Engine/Appliance has been repaired and is Approved For Return To Service, Pertinent Details Are On File Under Work Order No. M3287.

Signed:

Cert. No: 415318662 Date: 7/15
For Horizon Avionics, Inc.

Date:

4/23/2015

TTAF3139,9

TCM 0-470-U

Hobbs: 549.7

Reg. No: 759ZT

Tach: 216.8

Ser. No: 467165

ETSO:

12088

Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

CW Annual Inspection IAW Horizon Avionics Inspection Guide. 1.)75 2.)65 3.)65 4.)78 5.)60 6.)72 all over 80PSI. Drained oil and cut open filter, no metal noted. Installed new CH48110-1, Torque and safety. Serviced 11 qts Phillips 20W50 and camguard. Installed BA8103-1. CW AD research through biweekly 2015-08. Ground ran Acft leak and ops check good.

MAINTENANCE RELEASE

I certify that this ENGINE has been inspected IAW a 100HR Inspection and was determined to be in an Airworthy condition. Pertinent Details Are On File Under Work Order No. M3659.

Signed:

Cert. No: 19262255 V 10 Date: 4

For Horizon Avionics, Inc.

cian or

Date: Tach:	10/20/2015 257.4	Cessna 182Q Reg. No: N759ZT Ser. No: 18266395
2445 E	E. General Aviation D	Horizon Avionics, Inc. Orive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701
		ENGINE LOG ENTRY
D		
Drained saftied. S ops chec	Serviced 11 qts P	n filter; no metal noted. Installed new CH48110-1 torque hillips 20W50 and 1 bottle Camgaurd. Ground ran Acft leak
saftied. So ops check	Serviced 11 qts Plack good. that this Engine/	n filter; no metal noted. Installed new CH48110-1 torque

@ A 8

Date:

5/19/2016

Hobbs:

612.8

Tach:

274.5

ETSO:

-1479.7 1,266,5 TAF

TCM 0-470-U

Rea. No: 759ZT

Ser. No: 467165

Horizon Avionics, Inc.

2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701

ENGINE LOG ENTRY

CW 100Hr Insp I/A/W FAR 43 App D. 1.)65 2.)62 3.)62 4.)65 5.)28 6.)60. Drained oil cut open filter, no metal noted. Installed new CH48110-1, Torque and safety. Serviced 11 qts Phillips 20W50. Installed BA8103-1. R2 #5 Cyl W/P/N 649168. R2 Primer line P/N 2200001-78. Grnd run ops & leak ck good.

MAINTENANCE RELEASE

I certify that this ENGINE has been insp IAW a 100HR& was determined to be in an Airworthy condition. Pertinent Details Are On File Under Work Order No. M4071.

Signed:

For Horizon Avionics, Inc.

Model:

182Q

S/N:

18266395

N759ZT

Reg. №:

CORPORATE
FLIGHT MANAGEMENT

693 Fitzhugh Blvd. Smyrna, TN 37167 615.534.4600 Date: 27-Jan-2017

TAT: 630.2

Flight: 290.2

Engine S/N: 467165

Inspections Accomplished:

2002-Complied with Engine Annual Inspection. Ref Cessna Service Manual 2-50.

Airworthiness Directives:

-Researched ADs through 19·Dec·2016.

2017-AD 2009-19-07 — Inspect and replace EQ3 cylinders, is N/A. Engine S/N does not fall in range and no evidence of EQ3 cylinders installed. No further action required at this time.

2018-AD 2010-11-04 — Inspection and replacement of hydraulic lifters is N/A. Engine was manufactured prior to June 19, 2009 and no evidence of hydraulic lifter replacement after June 19, 2009. No further action required at this time.

2019-AD 2014-05-29 - Inspect for Superior Air Parts investment cast cylinders is N/A. No record or evidence of Superior Air Parts investment cast cylinders installed. No further action required at this time.

2020-AD 2016-16-12 – ECI Class 71 or 76 cylinder assembly failures, is N/A. No evidence or record of ECI Class 71 or 76 cylinders installed.

No further action required at this time.

Maintenance Accomplished:

2002-Complied with oil and filter change. Ref AMM 12. Cut open filter and inspected for metal. No metal noted at this time. Replaced oil filter and serviced with 11 quarts of Phillips 20W50 X/C and 1 bottle of CAMGUARD. Oil filter P/N: CH48110-1.

Complied with cylinder compression check:

Cyl Nº	1	3	5	2	4	6
PSI	68/80	56/80	78/80	55/80	68/80	56/80

- Continued on Next Page -

© A

epai

Master Orifice Reading: 42.				
2006-№ 4 cylinder compression 2011-Removed № 2 cylinder into 2015-Installed anti-heat sleeves	ith new, № 3 top spark plug. Refis 32/80. Staked valves on № 4 cake manifold heat shield, oversize around all CHT and EGT connec	eylinder and rechecked compre ed holes, installed 2 rivets, and tors. Ref AC 43.13-1B. P/N: 5	ession. Compression is now 68 d reinstalled. Ref AC 43.13-1B. 1674-001.	PVC), mark a second
I certify the Engine identified about and is approved for return to sensitive Signed: By: Thomas R. Ladd	ove was inspected in accordance vice with respect to the work performance with respect to the work performance. A&P 34514171	ormed.	n, as required by FAR 91.409(f)	(1), found to be airworthy,
	2 1		4	1
				1
				1
		the state of the s		<u> </u>
		Alexandra and the same of the	A Commence of the Commence of	1 7
		Was by	11/1/3	
	, , , , , , , , , , , , , , , , , , , ,	Log de la	of the	-

AIRCRAFT MAKE:	Cessna	AIRCRAFT REGISTRATION:	759ZT
AIRCRAFT MODEL:	182Q		297.6
SMOH:	1502.2	_ SMOH 1,289,6 Date: _	6/30/17

Completed an annual inspection on this engine in accordance with Cessna 182Q 100hr/Annual inspection guide lines and current FARs. Compressions #1)60/80, #2)60/80, #3)62/80, #4)68/80, #5)72/80, #6)64/80. Drained the oil from the crankcase and removed the oil filter. Installed a new oil filter and serviced the crankcase with Aeroshell 15W50. Cut the old oil filter open and inspected, no defects noted. Removed, cleaned, gapped, tested and reinstalled the spark plugs with new M674 gaskets. Torqued the valve cover screws to spec. Check magneto to engine timing, no defects noted. Removed and replaced the air filter. Engine run normal, no leaks noted. I certify this engine was inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

The aircraft identified above was repaired/inspected in accordance with current regulations of the Federal Aviation Administration, and was determined airworthy and approved for return to service with respect to the work performed. Details of the work are on file at this repair station under W.O. #

Signature:

GROH AVIATION, LLC

817 Airport Access Dr

A&P IA 3308388.

GREENWOOD, IN 46143 317-727-9881

		political section		
DATE 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	338.5	TT	h	
	183,5	Holls	, ,	Air Tolin ———
	15431	150		Lunken Airport Cincinnati, Ohio 513-871-8235 N759ZT 11/17/17 tach time0338.5
				removed Slick 6310 magneto on right position installed
			k	overhauled Champion #6310 S/N F-09304 and timed to engine.ok for return to service in regards to work done.
		(A)	100	Michael H. Wells A&P2099762
				- 12 11/h/l
		4		- Mille General -
	+			
		HOBBS	1	DRAINED OIJCHANGED FLUTER (48/10-2), REFLUED
12/1	3421	687.7	3390,8	46 21/21
5 ma	H 1.380	3		
A 1993	1,000			RUN, OK (1 3003856 AFP

				Air Tolin ————
TE	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Lunken Airport Cincinnati, Ohio 513-871-8235 N759ZT 1/5/18 tach time 349.7
_	TIME		SERVICE	removed starter adapter sent to signature Engines for
		-		overhaul WO#E7473 P/N635050A4.reinstalled after overhaul
				using new gasket.installed new P/N94110-40 engine mount
				rubbers, using new MS9276-13 lock tabs on mount bolts.
		and the second		reinstalled exhaust system using new exhaust gaskets.
				ground run checked operation,ok fro return to service in
				regards to work done. Michael H. Wells A&P2099762
				much fills
				Mun Kille
-				
1		Heim	N/ 14 BERRY	
_			Marie Bayers	
+				
\perp				
+				

DATE 19	TOTAL TIME IN SERVICE	Reference of FAA Form ACA-3	Major Repairs and Maj 337 by Date, or to the Work	or Alterations To Order by Number and the Approving Agency
	Mar	ch 2, 2018 TA	CH: 357.0	
	Insta	alled ElectroAi	r EIS-61000-1M in	place of the left magneto see FAA 337 dated
	this	date. Existing	mag will fire all the	e top spark plugs and the electronic ignition
	— syste	em will fire the	e special high-energ	gy plugs (EARHB32E) (6) in the lower cylinder
	spar	k plugs holes.	Other components	s are:
	Syste	em harness P/	N EA-6000 S/N	N 17-480
	Ignit	ion Wires	P/N EA-4195 (3	3) S/N 17-442
$-\dagger$	— Sparl	c Plugs	P/N EARHB32E	(6)
	(***)	•	P/N EA-7000	
	•		P/N EA-5000	S/N 17-485-001
	MTH		P/N EA-10000	S/N 17-384-003
- 1	– Coil P	ack	P/N EA-8000	S/N 17-486-001
		h Panel	P/N EA-13000	S/N 17-387
		Hardware Kit		(cont)

1993

TOTAL TIME IN SERVICE	Reference of Major Repairs and Major Alterations To FAA Form ACA-337 by Date, or to the Work Order by Number and the Approving Agency
EA	A-418-CR-6 Spark Plug Hardware Kit
EA	A-10000 MTH MTH Hardware Kit (in place of magneto)
EA	A-8000 Coil Pack Hardware Kit
EA	4-13000 Hardware Package - Switch Kit
Ele	ectrical checks OK. System operational checks OK. Update to AFM part of aircraft
	cords.
	structions for Continued Airworthiness are contained in ICA EIS-41000, "EIS-
	000 Instructions for Continued Airworthiness" dated 06/23/2014 which has
	en added to the aircraft records.
He	enry Rosche III
	aP 3166523
AC	21 3100323

19	TOTAL TIME IN SERVICE	Reference of Major Repairs and Major Alterations To FAA Form ACA-337 by Date, or to the Work Order by Number and the Approving Agency
x4	0366.8	REMEDEN EHGIVE FOR T.D.I.
IMA		to check for pres Present
47 - 6		mul 1/ /ll NO 2099762
		province gives
	Į.	

© ASA 1993



E	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance
20.	-98		97-26-17 YLTRASONIC TEST CRANKSHAFT Andrew Sevell
_			
_			
			© ASA 1993

