AIRCRAFT TECHNICAL RECORD

Section 3. ENGINE LOG



ENGINE DATA

1.	Make	Austro Engine
2.	Model	EY-C
3.	Specification	E0008/EN
4.	Manufacturer's Serial Number	E4-C-00455
5.	Date of Manufacture	March 2018
6.	Aircraft Inspection Cycle	FAR 43 Appx. D/100hr

Section 3A: Engine Service and Maintenance Log

	TIME RUN	TIME SINCE OVERHAUL	C	CLES	DESCRIPTION OF WORK PERFORME
DATE	HOURS min	HOURS mi	Sub Total	TOTAL	(INSPECTION, REPAIRS, REPLACEMENT)
ROUGHT _	Hoome				
ORWARD	Registration: Airframe Total T Engine RH SN:	ne E4-C, S/N: E4-C 42.N334, RIGHT Time Engine broug U software installed ine and documentat C's incorporated, nor applicable Airworth nplied with. ID Bi-weekly check er to Austro MM E4 pection/exchange in xt inspection due: 10	p.o.t. oRGAI AC Serial Ni Work Order Engine RH 1 00455, insta pht forward: 3 1 VC33_2_05 1 on inspected found. 1 ones Direct 1 one found. 1 ones Direct 1 ones Dire	illed on Aircraft DA 31.08 hrs 5_21 5 for Major Mod's a tives, Service Bu 3-13 revision for comp	nd/or lletins inent
		EMBRY-	RIDD	LE	A/C TOTAL TIME: 97.8
	I certify that thi inspected in acc was found to be Time in Service Took engine of oil. Inspected Operational ch The aircraft, ai current regulat	is RIGHT ENGINE-I cordance with an Annie e in an airworthy cond e: 97.8 il sample. Cut & inspe- gear box oil and filter. eck good. irframe, aircraft engine ions of the Federal Av	al Inspection tion. ted old oil file Replaced fuel or appliance i iation Adminis the Repair Sta	49DA) has been and er. Changed oil & fi filter. Performed p dentified above was stration and is appro	ENG TOTAL TIME: 97.8 ENG T.S.M.O.H.: N/A TACH TIME: 97.8 PROP T.S.M.O.H.: N/A PROP TOTAL TIME: 97.8 Let, serviced engine with AeroShell Aviation Diesel 5W-30 est maint engine run-up for leak check, no leaks noted. Inspected and repaired in accordance with ed for return to service. Pertinent details order: WO # RMS 2018 04689 Date: 18 SEPT 2018 Steve Johnson ERAU 9 N3XR816N 7691
THIS PAGE TOTALS PREVIOUS TOTALS	I certify that thi inspected in accurate in Service. Took engine of oil. Inspected. Operational ch. The aircraft, ai current regulat of the repair/in. Signed:	is RIGHT ENGINE-I cordance with an Annie e in an airworthy cond e: 97.8 il sample. Cut & inspe- gear box oil and filter. eck good. irframe, aircraft engine ions of the Federal Av	al Inspection tion. ted old oil file Replaced fuel or appliance i iation Adminis the Repair Sta	er. Changed oil & fill filter. Performed p dentified above was stration and is appro-	ENG T.S.M.O.H.: N/A TACH TIME: 97.8 PROP T.S.M.O.H.: N/A PROP TOTAL TIME: 97.8 Set, serviced engine with AeroShell Aviation Diesel 5W-30 est maint engine run-up for leak check, no leaks noted. Inspected and repaired in accordance with ed for return to service. Pertinent details order: WO # RMS 2018 04689 Date: 18 SEPT 2018 Steve Johnson ERAU 9

	7	B7AG
The same of the sa	NAME/ SIGNATURE	AMEOR AMO/ACA
Diamond AIRCRAFT Diamond Diamond aircraft ind. D.O.T. APPROVED MAINTENANCE ORGANIZATION 161-93		
Registration: N649DA AC Serial Number: 42.N334 Airframe Total Time: 172.8 Work Order: SO 072010	a kg)	
Engine RH SN: E4-C-00455 Engine TT: 172.6 RH Engine NON-Routine Maintenance:		
RH Engine governor adjusted to increase RPM		
The Maintspance Describes has been performed IAW the Applicable Standard of		
NOV 2 7 2018		
	HIRCRAFT MOTOR	
rate Log Entry, See Next page!	ACA OS	NOV 2 7 2018
J J J J J J J J J J J J J J J J J J J	761.93	MUY 2 / 2010
the state of the s		
the same flows a county that the first the same of the		
		MARKET TO SERVICE
		No the state of

nd Maintenance Log

DATE	TIME RUN	TIME SINCE OVERHAUL		CY	CLES	TERRETION OF WORK TO	
1 1	HOURS min	HOURS	min	S u b Total	TOTAL	DESCRIPTION OF WORK PERFORME (INSPECTION, REPAIRS, REPLACEMENT)	
BROUGHT -							
Registration: Airfarme Total Time: Engine LH SN: Engine LH SN: Prop LH SN: Prop LH SN: RH Engine 200 hr Engin and Austro E RH Air filter re RH Engins, FN FAA Bi-Wee 2018-07-16 - 2017-01-12 - 2018-08-02 - Timing Chain	N649DA AC S 171.5 Work E4-C-00454 Engin 171.5 Engin 180211 Prop	erial Number: 4 Order: 5 er RH SN: E er RH TT: 1 RH SN: 1 IRH SN: 1 INH TT: 1 CE: Out IAW DA 42 Date: 1 Of the Flight contribution of the Flight contribution of the current reduced at 945Hrs ET Of the Flight contribution of the Current reduced at 945Hrs ET Of the Flight contribution of the Current reduced at 945Hrs ET Of the Flight contribution of the Current reduced at 945Hrs ET Of the Flight contribution of the Current reduced at 945Hrs ET Of the Flight contribution of the Current reduced at 945Hrs ET	2 N334 10 072010 2-N334 10 072010 2-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C	IM Ch 05,	RH	DIAMOND AIRCRAFT IND. D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 Registration: N649DA AC Serial Number: 42 N334 Airframe Total Time: 172.8 Work Order: 50 072010 Engine RH SN: E4-0-00455 Engine TT: 172.8 Engine NON-Routine Maintenance: RH Engine governor adjusted to increase RPM The Maintenance described has been performed IAW the Applicable Standard of NOW 2-7 2018 DIAMOND AIRCRAFT IND. D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 ACA Serial Number: 42 N334 Work Order: 50 072010 172.8 Engine RH SN: E4-0-00455 Engine TT: 172.8 DIAMOND AIRCRAFT IND. D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 AC Serial Number: 42 N334 Work Order: 50 072010 172.8 Diamond Aircraft IND. D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 AC Serial Number: 42 N334 Work Order: 50 072010 172.8 Diamond Aircraft IND. D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 AC Serial Number: 42 N334 Work Order: 50 072010 172.8 Diamond Aircraft IND. D.O.T. APPROVED MAINTENANCE ORGANIZATION161-93 Diamond Aircraft IND. Diamond Aircraft	
Date: (Tach: 2	West Texas Av 03/07/2019 215.0 gine S/N: E4P-C-					Diamond SERVICE CENTER A/C Reg.#: N649DA Right Engine TT: 215.0	

per manufacturer's removal and installation instructions. Added about 4oz. Spirax S6 GXME 75W gearbox oil per Austro service manual instructions. Re-cowled engine and returned to service only for work performed. A&P 3168048 (JD Casteel

N649AD Naror Aire 3122 Great Southwest S/N 42.N334 Right Engine S/N: E4-C-455 Parkway Grand Prairie, TX 75052 (972)988-8609 Date: Nov 12, 2019 Tach: 267.4 Engine TT: 267.4 Performed a 300hr inspection in reference to FAR Part 43 appendix (d) and Austro E4C engine maintenance manual E4.08.04 Changed the oil and filter, obtained sample for analysis, Cut open the filter for inspection, no metal noted. Added 6 ltrs. of Shell Diesel Ultra. Researched for new A.D.'s through Biweekly 2019-23. Drained gear box oil strained oil, inspected for particles, inspected magnetic plug for metal and inspected filter, replaced with new filter, next due 567.4. Added 2 liters of Spirax S6 GXME 75W gear oil. Timing chain inspection due @ 1000hr TT. I certify that this engine has been inspected in accordance with a 300 hour inspection and was determined airworthy. Steve O'Brien A&P3397718 IA

SI

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0128



Premier Aircraft Sales, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 7/23/2020 A/C TSN: 312.7 ENG TT (R): 312.7 HOBBS: 0

Right Engine Entries

- Performed 300hr Injector Cover Zonal Inspection.
- · Performed 300hr Alternator Inspection.

DATE: 7/23/2020

SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0128

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0148



Premier Aircraft Sales, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 8/17/2020 A/C TSN: 342.4 ENG TT (R): 342.4 FLIGHTTIME: 342.4

Right Engine Entries

· Pilot reported ECU A/B Fail. Downloaded data, found BPA non-latching fault. Checked WGA rigging. Cleared log and performed test flight, ops check normal.

DATE: 8/17/2020

SIGNED:

David Se

Work Order: 0148

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0165



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 9/4/2020 A/C TSN: 362.3 ENG TT (R): 362.3 HOBBS: 77.5

Right Engine Entries

- Performed 100 Hour Inspection using DA42NG AMM as a guide.
- · Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra

DATE: 9/4/2020

SIGNED: Chad Cox, License: AP3782800

Work Order: 0165

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG NO NEASDA WORK ORDER: 0152



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 12/3/2020 A/C TSN: 434.1 ENG TT (R): 434.1 FLIGHTTIME: 434.1

Right Engine Entries

- Replaced injector cover with new E4A-53-000-101
- · MSB-E4-026 Inspected engine harness

DATE: 12/3/2020

SIGNED:

Work Order: 0152

Chad Cay License: AP3782800

Printed by FRis 3 (datcomedia com)

Section 3A: Engine Service and Maintenance Log

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0223



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 12/3/2020): A/C TSN: 434.1 ENG TT (R): 434.1 HOBBS: 183.9

Right Engine Entries

- · Performed 100 Hour Inspection using DA42NG AMM as a guide.
- · Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra.

I certify this engine has been inspected IAW an Annual Inspection and was determined to be in airworthy condition.

DATE: 12/3/2020

SIGNED

David Seastead, License: AP3492477 IA

Work Order: 0223

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0267



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 2/12/2021 A/C TSN: 529.7 ENG TT (R): 529.7 HOBBS: 324.5

Right Engine Entries

- Performed 100 Hour Inspection using DA42NG AMM as a guide
- Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra
- · Inspected gearbox chip collector
- Replaced oil sump with new P/N E4A-51-000-101
- · Replaced oil baffle E4A-51-000-401

I certify this engine has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

DATE: 2/12/2021

SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0267

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0300



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 4/2/2021 A/C TSN: 619.4 ENG TT (R): 619.4 HOBBS: 461.9

Right Engine Entries

- · Performed 100 Hour Inspection using DA42NG AMM as a guide
- · Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra
- · Inspected gearbox chip collector

DATE: 4/2/2021

SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0300

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0346



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345

DATE: 6/7/2021 A/C TSN: 715.8 ENG TT (R): 715.8 HOBBS: 598.5

Right Engine Entries

DATE: 6/7/2021

- · Performed 100 Hour Inspection using DA42 AMM as a guide
- · Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra
- · Performed 300hr gearbox oil and filter replacement
- Performed 300hr injector cover zonal inspection
- · Performed 300hr alternator inspection
- Performed 600hr TVD inspection
- Performed 600hr HPP replacement, new S/N 20-08-21-02-00650.
- · Performed 600hr coolant change
- Replaced gearbox input shaft seal

I certify this engine has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

Chad Cox, License: AP3782800 IA TUTALO **PREVIOUS** TOTALS TOTALS SINCE NEW

Work Order: 0346

Printed by EBis 3 (datcomedia.com)

CARRY FORWARD to Top of Next Page





NAME/ SIGNATURE LICENCE:

AME or AMO/ACA

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0353



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562,881,5345 DATE: 6/17/2021 A/C TSN: 742.4 ENG TT (R): 742.4 HOBBS: 635.5

Right Engine Entries

Replaced BPA E4A-41-300-801

DATE: 6/17/2021

SIGNED:

David Seastead, License: AP3492477 IA

Work Order: 0353

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0392



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 7/29/2021 A/C TSN: 794.9 ENG TT (R): 794.9 HOBBS: 708.1

Right Engine Entries

Performed 100 Hour Inspection using DA42NG AMM as a guide

Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra

· Inspected gearbox chip collector

· Replaced WGA and spring clip

I certify this engine has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition

DATE: 7/29/2021

SIGNED: Chad Cox, License: AP3782800 IA

Work Order: 0392

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0410



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 9/15/2021 A/C TSN: 892.2 ENG TT (R): 892.2 FLIGHTTIME: 892.2

Right Engine Entries

MSB-E4-034 Replaced HPP spur gear with new E4A-30-000-201 S/N 2466

• MSB-E4-034/2 - Ran engine and reinspected new HPP gear

MSB-E4-035 N/A by P/N

DATE: 9/15/2021

SIGNED: Chad Cox, License: AP3782800 IA

Work Order: 0410

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL: AE300 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA WORK ORDER: 0418



Premier Aircraft Service, Inc.

3804 Falcon Way W Hangar 18S Fort Worth, TX 76106 Phone: 562.881.5345 DATE: 9/15/2021 A/C TSN: 892.2 ENG TT (R): 892.2 HOBBS: 847.8

Right Engine Entries

Performed 100 Hour Inspection using DA42NG AMM as a guide

· Changed oil and filter. Serviced engine with Aeroshell Diesel Ultra

Inspected gearbox chip collector

Replaced injectors

• MSB-E4-029/1 - installed BPA restrictor

Replaced combisensor o-ring

I certify this engine has been inspected IAW a 100 Hour Inspection and was determined to be in airworthy condition.

SIGNED:

DATE: 9/15/2021

Chad Cox, License: AP3782800 IA

Work Order: 0418

Printed by EBis 3 (datcomedia.com)

Section 3A: Engine Service and Maintenance Log Date: 12/3/2021 Diamond Fleet & Aviation services LLC DA RIPTION OF WORK PERFORMED: Make: Diamond Hobbs: 998.7 5070 S. Collins suite 205, Diamond. A/C TSN: 992.0 Model: DA42NG Arlington, TX 76018 CTION, REPAIRS, REPLACEMENT) Right engine TT: 992.0 S/N:42.N334 FLEET & AVIATION Phone: 817-575-7828 REG NO: N649DA SERVICES BROU Right engine Performed 100 hour inspection using DA42NG AMM as a guide Changed oil (serviced with aeroshell Diesel Ultra) and changed oil filter Inspected gearbox chip collector. No metal particles found Changed gearbox oil (serviced with shell Spirax S6 GXME 75W-80) Need alternator inspection at 1015.8hr Need timing chain inspection at 1000hr All AD's complied with current BI-week I certify this engine has been inspected IAW a 100 hour inspection and was determined to be in an airworthy SIGNED: auto grote condition Date: 12/3/2021 Austin Paden, A&P:4494928 DATE: 12/8/2021 ENGINE MODEL: AE300 Premier Aircraft Service, Inc. A/C TSN: 992.1 ENG TT (R): 992.1 ENGINE S/N (R): E4-C-00455 REG. NO: N649DA 3804 Falcon Way W HOBBS: 1000 Hangar 18S Fort Worth, TX 76106 WORK ORDER: 0491 Phone: 562.881.5345 **Right Engine Entries** · Performed 1000hr timing chain inspection Changed coolant G48 · Changed gearbox oil and filter · Performed injector cover 300hr zonal inspection Performed alternator 300hr inspection. Replaced brush pack ADs current to biweekly revision 2021-25 SIGNED DATE: 12/8/2021 Work Order: 0491 David Seastead, License: AP3492477 IA Printed by EBis 3 (datcomedia.com) Engine R - page 1 of 1 wo: N649DA 2022.02.14 Unscheduled Diamond Fleet & Aviation Service - 5070 S. Collins S. Suite 205 - Arlington, TX 76018 - 9012474808 AUSTRO, E4-C, S/N: E4-C-00455 February 14, 2022 N649DA SMOH: 1073.2 TACH: 1073.2 TTSN: 1073.2 Removed R/H Engine Propeller Governor P/N: P-877-16 S/N:19G913IG and replaced with overhauledserviceable Propeller Governor P/N: P-877-16 S/N: 12G111-H/G IAW current DA42NG AMM and current E4 Austro EMM. With respect to the work performed, this engine has been found in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Service under work order: N649DA 2022.02.14 Unscheduled. Austin Paden A/P 4494928 Wor Pun wo: N649DA 2022.02.28 Scheduled Diamond Fleet & Aviation Service - 5070 S. Collins S. Suite 205 - Arlington, TX 76018 - 9012474808 **N649DA** AUSTRO, E4-C, S/N: E4-C-00455 March 04, 2022 TACH: 1083.4 TTSN: 1083.4 SMOH: 1083.4 1. 100 Hour Progressive Inspection - R Engine - Performed100hr Inspection using DA42NG AMM as a guide. Removed oil filter E4A-52-000-KIT and replaced with new-serviceable oil filter P/N: E4A-52-000-KIT. Changed engine oil used (Aeroshell Diesel Ultra 5W30). Inspected gearbox oil magnetic drain plug and gearbox oil filter. With respect to the work performed, this engine has been found in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Service under

Austin Paden A/P 4494928

work order: N649DA 2022.02.28 Scheduled.

- COMPLIED WITH All CURTENT

wo: N649DA 2022.04.06 Scheduled



Engine R · page 1 of 1

NCE: ACA

Diamond Fleet & Aviation Service - 5070 S. Collins S. Suite 205 - Arlington, TX 76018 - 9012474808

N649DA

AUSTRO, E4-C, S/N: E4-C-00455

April 07, 2022

TACH: 1130.0

TTSN: 1130.0

SMOH: 1130.0

1. 50 Hour Gearbox Inspection on R/H Engine for presence of Debris - Inspection revealed no additional metal particles. IAW Diamond/Austro inspection criteria, engine is approved for continued

With respect to the work performed, this engine has been found in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Service under

work order: N649DA 2022.04.06 Schedyled.

Michael Smith A/P 3906663

wo: N649DA 2022.05.09 Scheduled



Diamond Fleet & Aviation Service · 5070 S. Collins S. Suite 205 · Arlington, TX 76018 · 9012474808

N649DA

AUSTRO, E4-C, S/N: E4-C-00455

June 01, 2022

TACH: 1160.6

TTSN: 1160.6

SMOH: 1160.6

Engine R · page 1 of 1

1. R/H 900 Hour Water Pump Inspection - Completed IAW AE300 EMM Current Revision. Next due @ 2060.6 ACTT.
2. R/H 1200 Hour Flywheel & Hub Inspection – Removed and reinstalled same-serviceable hub and

flywheel assembly. Bench test and visual inspection of flywheel & hub assembly passed IAW AE300 EMM Current Revision. Next Inspection due @ 1760.6 ACTT.

3. R/H 300 Hour Engine Inspection - Inspection completed using AE300 EMM as a guide. Removed gearbox filter (p/n E4A-70-000-806) and installed new-serviceable filter (p/n same). Next due @

 100 Hour Inspection – 100 Hour Inspection Completed IAW AE300 EMM current revision. Drained and serviced engine oil with 7qts Aeroshell Diesel Ultra 5w30, removed, inspected, and replaced engine oil filter (p/n E4A-52-000-KIT), no defects noted. Drained and serviced gearbox with 3qts Shell Spirax 75w-90 gear oil. Ground run/ops check ok. Next Due @ 1260.6 ACTT

With respect to the work performed, this engine has been found in an airworthy condition and is approved for return to service. Details of work performed are on file with Diamond Fleet & Aviation Service under work order: N649DA 2022.05.09 Scheduled

Michael Smith A/P 3906663