


# **ENGINE LOG BOOK**



**CONTINENTAL SERVICES**

**Fairhope, Alabama**

Consult the Continental web site at <http://www.continental.aero> for engine related news or announcements. The web site contains useful information for Continental engine owners, including service information and illustrated parts catalogs.

If Internet access is not available, contact our Customer Service Department at:  
1-888-826-5465 Toll free in the United States or 1-251-436-8299 for International customers

### Warranty Information

This product is covered by Continental Aerospace Technologies™ product warranty. To read or download a copy for your records, please visit the Product Warranty page on our web site at: <http://www.continental.aero/services/warranty.aspx> or scan the QR Code to the right to navigate to the page:



### Instructions for Continued Airworthiness

For complete access to the engine Instructions for Continued Airworthiness, Illustrated Parts Catalogs, Service Documents, Technical Briefs, company news, and upcoming events, please take a few moments to register the serial number of your engine on our web site: <http://www.continental.aero/services/owner-registration.aspx> or scan the QR Code to the right to navigate to the page:

### Engine Returns

Return engines for core credit with this log book to:


**Continental Aerospace Technologies**  
2039 Broad Street  
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:

**Continental Services**  
Factory Service Center  
8600 County Road 32  
Fairhope, Alabama 36532 USA

**USE ONLY FUEL CONFORMING TO ASTM D910**

**USE OF AUTOMOTIVE FUEL IS PROHIBITED**

DATE:	ENGINE MODEL:	ENGINE S/N:	ENGINE TT / SMOH
March 8, 2022	IO550N27B	689102	1665.6 / 0.0
 <b>CONTINENTAL SERVICES</b>			
<p>This is to certify that the engine described hereafter has been OVERHAULED IAW Continental Manuals M-16 (revision date of 10/21) and M-0 (08/21). This engine was disassembled, cleaned, inspected, repaired, reassembled, and tested in accordance with manufacturers current instructions. Applicable Service Bulletins and Airworthiness Directives have been complied with.</p>			
<p>This engine has been inspected in accordance with procedures listed in M-16 and M-0 and has been accepted by Continental Services in Fairhope, Alabama. I certify that this engine has been OVERHAULED as indicated above and was determined to be airworthy with respect to the work performed. Reference Work Order ES-10412</p>			
<p>COMPLIED WITH: CSB668, M87-23, M93-4, M93-8, MSB94-8D, SB04-10, SB13-6A, SB18-07, SB19-07, SB653, SB658, SB97-11, SID96-6, SID97-8.</p>			
MECHANIC:	FAA CERT # 9CER853B	AUTHORIZATION:	FAA CERT # 9CER853B
