THE OO STATE AIRCRAFT MAINTENANCE RECORD KEEPING SYSTEM

ENGINE MAINTENANCE RECORDS





ENGINE MAINTENANCE RECORDS

Log No.

Aircraft Registration No. 1134
Engine Manufacturer CONTINENTAL
Model TO 550 N
Serial No917350
Date installed on aircraft $8-26-19$





Powermaster Aircraft Engines 9027 S. Airport Way Tulsa OK 74132 918-299-0269 FAA CRS P46R287Y

Engine Overhaul Record

Date- 8-12-2019

PAE Work Order 19-0812

Engine Make- Continental

Model-IO-550N

Serial Number- 917350

Engine Total Time- 1814. 5

TSMOH- "0"

This entry certifies this engine has been overhauled to manufactures new part limits. This engine has been disassembled, cleaned, inspected and overhauled in accordance with CMI Overhaul manual M16.

The following Accessories were overhauled or replaced new at time of overhaul unless noted:

Left Magneto-	Surefly	SIM6C	337 Required
Right Magneto-	BL-500556-1	D19EA285R	CMI
Fuel Pump-	655921-3A1	B04HA306	GPFM-19-376
Fuel Controller-	653353-8A1	A04HA274	GPFM-18-376
Manifold Valve-	646433-9A1P	C04HA290	GPFM-19-376
Nozzles-	652312-12E	NA	GPFM-19-376
Oil Cooler-	654585	E06-4772-348	Eaton-111870
Governor-	C290D3R/T3	SN-041114	AAOFOK-34133

Internal Steel certified by Aircraft Specialties on WO#-255061.

Crankcase Overhauled and Certified by Divco Inc on WO# WDC-124725.

Camshaft PN-654084 installed.

New CMI Cylinders Installed, PN658595A1, SN-AC19AA786, 959, 961, 964, 978, 992.

AD's Complied With:

AD-93-16-15 Installed fuel pump drive coupling PN-653359.

AD-10-11-04 Installed 6 each 653877 and 6 each 653888, Hydraulic lifter assemblies.

Installed New Camshaft Gear PN-656818 per MSB05-8B.

Installed New Crankshaft Gear PN-656991.

The engine and accessories listed above have been inspected and overhauled in accordance with current FAA regulations and were found airworthy for return to service.

WO# 19-0812/

William R. Cunningham

Powermaster Aircraft Engines

FAA CRS P46R287Y



	DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
,					TOTALS brought forward from previous page

8/26/19 N218X CONTINENTAL IO-550-N S/N 917350 HOBBS 1814.5 TSMOH 0.0

INSTALLED ENGINE AFTER OVERHAUL BY POWERMASTER AIRCRAFT ENGINES, W/O # 19-0812. INSTALLED NEW ENGINE VIBRATION MOUNTS, ALL FIREWALL FORWARD FUEL HOSES REPLACED AT THIS TIME. SERVICED ENGINE WITH PHILLIPS 20W50 TYPE "M" OIL. GROUND RUN, IDLE SPEED AND MIXTURE SET. LEAK CHECK OK. AD'S THROUGH 2019-17 CHECKED FOR COMPLIANCE. W/O # 12212

I Certify That This <u>Engine</u> Has Been
Inspected in Accordance With A <u>N ANN Vol</u>
Inspection And Determined To Be In An Airworthy Condition
Mathem (7 Showeller AP3542093IA

•	1194.2	09/03/2019 N218X TCM 10-550-N SERIAL #917350 1820 OIL DRAINED. REMOVED AND INSPECTED FILTER. UP PHILLIPS 20W50 TYPE 'M' AND CH48108-1. GROUND R	NIT DISCARDED. SERVICED WITH
		Matthew G Showalter AP 3542093 IA	W/O #12239

11/6/19 N218X TCM IO-550-N S/N 917350 1844.3 HOBBS & TT TSMOH 29.8
OIL AND FILTER CHANGED. FILTER WAS INSPECTED FOR CONTAMINATION, NONE FOUND. SERVICED WITH PHILLIPS 20W50XC AND CH48109-1 FILTER. REMOVED AIR OIL SEPARATOR AND RETURNED BREATHER SYSTEM TO FACTORY CONFIGURATION. NO WEIGHT AND BALANCE CHANGE. REPLACED OIL DRAIN VALVE TIP O-RING P/N MS28775-011. WASH ENGINE, GROUND RUN AND LEAK CHECK OK.

World AP354209374
W/O 12257

12-12-19	1219	8 REMOVED CONCORDE BATTERY RG24-15M
,	Replaced	8 REMOVED CONCORDE BATTERY RG24-15M WITH CONCORDE RG24-15M LARD 33355501
		SUB-TOTALS this page
	144	TOTALS-Carry forward to next page

age No.	4							
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME			DF WORK PERFORMED NO. OF PERSON PERF	-	<
Mansfield Lahm H	Memorial Road, Hang	gar #528	Engine Logb	ook Entry		X	AMI	
Date: 04/05/2020		Registrat Number		Aircraft Model Number: Cirrus SR22		Aircraft Serial Number: 1134		
Vork Order: MAMI-23 Total Airframe	41	Engine Make: Co Hour Rec	corder	Engine Model Number: 10-550 Total Engine		Engine Serial 917 350 Engine Time Since		
ime: 1879.4	I magneto and replac	Time: 18	ly SIM6C magneto. Intern	Time: 1879.4	e Performed engine r	Major Overhaul: 51 3 ins to verify correct operation and the	hat no leaks	
re detected at the N OFF: SIM6C N OFF: 6C-1419 N ON: SIM6C N ON: 6C-1120	nis time All satisfact	ory with no defects	noted at this time	Mechanic: AP3371638				
— AL HE — CE FU	ERT SERVICEX NUT. GAP NTER PUNC RTHER ACT	E BULLETI BETWEEN H MARK AI ION REQUII	N 081 Rev. A. RE NUT THRUST F	ACE AND THRUST NATOR INSTALLED	FOR. INSPEC WASHER LES	TED CASTELLATED SS THAN .002.		
	,				•			
	9/1/2020 N21	8X CONTI	NENTAL MOTO	RS IO-550-N S/N 91	7350 HOBBS	& TT 1913.8 TSOH 9	9.1	
(COMPRESSIC	ON TEST RE	SULTS #1)70/80 D ROTATED. MA	#2)74/80 #3)71/80 # AGNETO TO ENGIN	4)71/80 #5)75 E TIMING CI	/80 #6)72/80. SPARK F HECKED. INDUCTION OUND RUN UP OK.	PLUGS	
		W	ITH AN ANNUA N AIRWORTHY (MATTHE	NGINE HAS BEEN L INSPECTON AND CONDITION. W G SHOWLATER A 1 ELDWAR AP 3541	WAS DETER			
	09	/23/2020 N2	18X TCM IO-5	50-N S/N 917350 H	OBBS & TT:	916.7 SMOH:102.2		
	PI	IILLIPS 20W	50 X/C AND CH	EN. REMOVED AN 148109-1. GROUND		D FILTER. SERVICED	WITH	
4		which G Hyparistopher A I	Kopkins 2216069) IA	W/O #12320			

SUB-IUIALS this page

TOTALS-Carry forward to next page

Stephen R Schming	
OIL DRAINED. SAMPLE TAKEN. REMOVED AND INSPECTED FILTER. UNIT DISCARDED. SERVICED WITH PHILLIPS 20W50 X/C AND CH48109-1. GROUND RIJN UP OK. Cha-548 & Hard. Christopher A Hopkins 2216069 IA W/O #12370 7-6-21 TACH = 13217 DRAINED. DRAINED. 216069 IA W/O #12370 7-6-21 TACH = 13217 DRAINED. DRAINED. DIA REMOVED. TASSPECTED. Filter. Service With Harilips 20 - SO And New Ch 48109 - I GEOVED. WITH Harilips 20 - SO And New Ch 48109 - I GEOVED. MORNING TO ENGINE THIN 10 CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATHEW GSHOWALTER AP 3542093 IA Method of Should be 3541093374 III - 20-21 TACH = 1355. 2 DRAINED. OIL REMOVED. TASSPECTED. FILTEL. SELVICED WITH ALLIPS 20 - SO AND New CH48109 - I fill ground Roy No. No. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
DISCARDED SERVICED WITH PHILLIPS 20W50 X/C AND CH48109-1. GROUND RUN UP OK. Charle 4 Haple. Christopher A Hopkins 2216069 IA W/O #12370 7-6-21 Tach = 13217 DRAINED OIL Removed Trispected Filter Selvice With Phillips 20 w 50 And New Ch 48/09-1 Geoond Ron OK A 18 18 18 18 18 18 18 18 18 18 18 18 18	
Christopher A Hopkins 2216069 IA W/O #12370 7-2-21 TACH = 13217 DRAINED DIL REMOVED THS PECTED FILTER SELVICE WITH IN-11/15 SOWSO AND NEW CH 48/09 - GEOONG RON OK	
10/01/2021 N218X CONTINENTAL MOTORS 10-550-N S/N 917350 HOBBS 2011.3 TSOH 196.6 TT 2011.3 COMPRESSION TEST RESULTS #1)74/80 #2)72/80 #3)71/80 #4)75/80 #5)76/80 #6)72/80. SPARK PLUGS CLEANED AND ROTATED. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA MATTHEW G SHOWALTER AP 3542093	
10/01/2021 N218X CONTINENTAL MOTORS 10-550-N S/N 917350 HOBBS 2011.3 TSOH 196.6 TT 2011.3 COMPRESSION TEST RESULTS #1)74/80 #2)72/80 #3)71/80 #4)75/80 #5)76/80 #6)72/80. SPARK PLUGS CLEANED AND ROTATED. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA MATTHEW G SHOWALTER AP 3542093	e.
10/01/2021 N218X CONTINENTAL MOTORS 10-550-N S/N 917350 HOBBS 2011.3 TSOH 196.6 TT 2011.3 COMPRESSION TEST RESULTS #1)74/80 #2)72/80 #3)71/80 #4)75/80 #5)76/80 #6)72/80. SPARK PLUGS CLEANED AND ROTATED. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA MATTHEW G SHOWALTER AP 3542093	
10/01/2021 N218X CONTINENTAL MOTORS 10-550-N S/N 917350 HOBBS 2011.3 TSOH 196.6 TT 2011.3 COMPRESSION TEST RESULTS #1)74/80 #2)72/80 #3)71/80 #4)75/80 #5)76/80 #6)72/80. SPARK PLUGS CLEANED AND ROTATED. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA MATTHEW G SHOWALTER AP 3542093	
COMPRESSION TEST RESULTS #1)74/80 #2)72/80 #3)71/80 #4)75/80 #5)76/80 #6)72/80. SPARK PLUGS CLEANED AND ROTATED. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. W/O 12427 I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA METHOD OIL REMOVED TYSPECTED FITEL SELVICES WITH PHILIPS LO WSO AND NEW CH48/109-1 Fit Ground Run OK PRINCE LOG Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airwinstallation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administral approved for return to service. Stephen R Schilling AP/IA	
CLEANED AND ROTATED. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION ELEMENT CLEANED AND SERVICED. GROUND RUN UP OK. AD'S THROUGH 2021-20 CHECKED FOR COMPLIANCE. I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA MACHEN G FLOWAL AP 2542093 IA MACHEN G FLOW	<u> </u>
I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA MATTHEW G SHOWALTER AP 3542093 MATTHEW G SHOWALTER AP 3542093 MATTHEW G SHOWALTER AP 35420	
MATTHEW G SHOWALTER AP 3542093 IA Method G Showald AR 3542093 TA III-20-21 TACH = 1355.2 - DRAILED OIL REMOVED THE PECTED FILE SELVICES WITH PHILIPS 20 WSO AND NEW CH48109-1 FILE GLOUNG RUN OK AND HEW CH48109-1 FILE Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airy installation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administration approved for return to service. Stephen R Schilling	
Serviced With Phillips 20 WSO And New CH48109-1 file Growd Ron Ok File Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airwinstallation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administration approved for return to service. Stephen R Schilling	
Serviced With Phillips 20 WSO And New CH48109-1 file Growd Ron Ok File Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airwinstallation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administration approved for return to service. Stephen R Schilling	
N218X Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airwinstallation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administration approved for return to service. Stephen R Schilling	
N218X Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airwinstallation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administration approved for return to service. Stephen R Schilling	ود
N218X Removed and replaced the SureFly p/n SIM6C s/n off 6C1120013 s/n on 6C3821014 per SureFly instructions for continued airwinstallation manual. Performed an operational check, no defects noted. The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administration approved for return to service. Stephen R Schilling	
The component listed above was repaired or inspected in accordance with current regulations of the Federal Aviation Administrapproved for return to service. Stephen R Schilling	1358.0
Stephen & Schming	ion and is
ProAv Aviation Services	ion and is
5/31/2022 N218X CONTINENTAL IO-550-N S/N 917350 HOBBS 2072.2 TSOH 257.3	330755 14/2021
OIL AND FILTER CHANGED. SAMPLE TAKEN. FILTER WAS INSPECTED FOR CONTAMINAT	330755
NONE FOUND. SERVICED WITH PHILLIPS 20W50 XC AND CH48109-1 FILTER. GROUND RU AND LEAK CHECK OK. W/O 12491 Miller G Showe No AP 354 2093 74	330755 14/2021

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
	8/18/2022 N	218X TCM I	O-550-N S/N	N 917350 HOBBS & TT 2115.1 SMOH 300.2
	FOUND. SE	RVICED WIT CHECK OK. MATTHE	H PHILLIPS W G SHOWA	A WAS INSPECTED FOR CONTAMINATION, NONE 20W50 XC AND AA48109 FILTER. GROUND RUN W/O 12518 ALTER AP 3542093 IA AR 354009374
	10/17/20	22 N218X T	CM 10-550-	N S/N 917350 HOBBS & TT 2124.7 SMOH 309.8
	PLUGS ELEME	CLEANED A' NT CLEANEI GROUND R' I CERTIFY' WITH AN A AN AIRWO	ND ROTATE D AND SERV UN UP OK. A ITHIS ENGIN NNUAL INS RTHY COND HEW G SHO	#1)70/80 #2)78/80 #3)76/80 #4)76/80 #5)77/80 #6)76/80. SPARK D. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION TICED. REPLACED LEFT EXHAUST COLLECTOR BOLT P/N AD'S THROUGH 2022-21 CHECKED FOR COMPLIANCE. W/O 12536 E HAS BEEN INSPECTED IN ACCORDANCE PECTION AND WAS DETERMINED TO BE IN DITION. WALTER AP3542093 IA J. AP3540,4937A
	OIL AN SERVIC PUSH R CONTR ALTER	D FILTER CH ED WITH PH OD SEALS P OL VALVE D NATOR DRIV F 08/21/2017.	IANGED. FII IILLIPS 20W /N SA534610 OES NOT AI E COUPLIN GROUND R	AL IO-550-N S/N 917350 HOBBS & TT 2152.3 TSOH 337.4 LTER WAS INSPECTED FOR CONTAMINATION, NONE FOUND. SOXC AND AA48109 FILTER. REPLACED #2 CYLINDER INTAKE AND 630286. CONTINENTAL SB21-03 OIL TEMPERATURE PPLY BY PART NUMBER OR LOT NUMBER. QAA ASB 021 1 G DOES NOT APPLY BY NEW ALTERNATOR INSTALLATION LUN UP OK. VALTER AP 3542093 IA W/O 12565
2-23	0.1	1 5 1		
(- \ \	CONTO	MINAT	ion F	OUND. SERVICED WITH PHILLIPS 20 W 50:
	AND	AA481	09 F.	ITER GROUND RUN US OK
			494.2	1/1 B// #3335501
			,	SUB-TOTALS this page
				TOTAL S-Carry forward to next page

*	
	/
Page No.	/

TOTAL TIME IN SERVICE TACH OR RECORDING TOTAL DESCRIPTION OF WORK PERFORMED-DATE SINCE OVERHAUL SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK TIME 11/03/2023 N218X TCM IO-550-N S/N 917350 HOBBS & TT 2231.9 TSOH 444.6 COMPRESSION TEST RESULTS #1)70/80 #2)71/80 #3)72/80 #4)76/80 #5)75/80 #6)74/80. SPARK PLUGS CLEANED, GAPPED AND ROTATED. OIL AND FILTER CHANGED. SAMPLE TAKEN. FILTER WAS INSPECTED FOR CONTAMINATION, NONE FOUND. SERVICED WITH PHILLIPS 20W50 XC AND AA48109 FILTER. MAGNETO TO ENGINE TIMING CHECKED. INDUCTION FILTER ELEMENT CLEANED, SERVICED AND RE-INSTALLED. WASHED ENGINE, GROUND RUN AND LEAK CHECK OK. AD'S THROUGH 2023-22 CHECKED FOR COMPLIANCE. W/O 12654 I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. MATTHEW G SHOWALTER AP 3542093 IA Mathew G Showell H33542093 IA **SUB-TOTALS** this page **TOTALS-**Carry forward to next page