

Maintenance Record

Instructions, Special Inspections,

Engine Service and Maintenance Record

Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins

Date	Total Time		Time Since Last Overhaul	
	Hrs.	Min.	Hrs.	Min.

Brought Forward

→

N624CP

Flight: 2089.3; Engine TT: 2089.3; Hobbs: 2325.9;

Drained engine oil, cut open and inspected oil filter. Installed new Tempest AA48108-2 oil filter and safety wire. Service engine with 7qts Phillips 20W50 oil. Lubricated engine controls and checked travels and operation. Installed new BA24 induction air filter. Installed overhauled #1 cylinder exhaust header P/N 10355-003.

Compressions: 1) 68 2) 72 3) 75 4) 67 5) 70 6) 71
Master Office: 42

I certify that this engine has been inspected I/AW an annual type inspection and was found to be in airworthy condition. AD summary checked through 2025-10.

Service Order No. 64972

Date 6/2/2025

FAA Approved Repair Station No. B2ER144J
Boshart Enterprises and Aircraft Services, Inc.
Genesee County Airport Batavia, N.Y. 14020

ENGINE

Engine Total Time: 1998.3
Flight: 1998.3

Adapter P/N: 646220A53 S/N: CAM22-239,
aircraft.

Identified above was repaired and
with current regulations of the Federal
is approved for return to service.
pair are on file at this station under

22 Dated: 4/25/24

on No. B2ER144J
ircraft Services, Inc.
Batavia, N.Y. 14020