# THE OO MAINTENANCE MAINTENANCE MAINTENANCE RECORD RECORD SYSTEM

ENGINE MAINTENANCE RECORDS

TE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	SIGNATURE	DESCRIPTION OF VE & CERTIFICATE NO	WORK PERFORMED— . OF PERSON PERFORMI	NG WORK
			TO	OTALS brought	forward from previo	ous page	
	roving Civil Aviation authority/Country:	2.		6		3. Form Tracking Number:	4
FA	AA/United States	AU'			ERTIFICATE	Invoice # 10057	
4. Orga	unization Name and Add	ress:	FAA Form 8130-3,	AIRWORTHINESS APP	ROVALTAG	5. Work Order/Contract/Invoice	-
Sign	nature Engines, Inc., 47	60 Airport Road, Cir	cinnati, Ohio 45226 Cer	tificate No. ESZR316Y		Number: E7284	
6. Item:	7. Description:		. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	Continental M	otors Engine	10-360-ES	1	360166	Overhauled	4
PARTS A 6 New F 2 Overh 1 New H 1 Overh	IGINE HAS BEEN OVERHACTURER'S SERVICE BI IN TO SERVICE. ENGINE AND ACCESSORIES REPIFICATION Steel Cylinders Lauled Slick Magnetos Harness Lauled Fuel Injection	JLLETINS COMPLIED TEST RUN PER OVER	WITH ARE A PART OF THESE	RECORDS. ALL PARTS HAV FURNISHED. THIS ENGINE 0 Hours Hours	IANUALS. A LIST OF ALL PARTS, FJ VE BEEN INSPECTED AND HAVE BE E IS AIRWORTHY FOR RETURN TO	A.A. AIRWORTHINESS DIRECTIVES AND EN DETERMINED AIRWORTHY TO SERVICE.	
13a, Cer	et of Spark Plugs rtifies the items identifie Approved design dat Non-approved design	a and are in a condition		Certifies that described in Regulations,	at unless otherwise specified in Block Block 12 was accomplished in accom-	Other regulation specified in Block 12 12, the work identified in Block 11 and dance with Title 14, Code of Federal the items are approved for return to	
13b. Aut	thorized Signature:		13c. Approval/Authorizat	service.	Signature:	14c. Approval/Certificate No.:	
						E5ZR316Y	
13d. Nar	me (Typed or Printed):		13c. Date (dd/mmm/yyyy)	14d Name (Type	ed or Printed):	14e. Date (dd/mmm/yyyy):	
It is impo Where th 1, it is ess in Block !	ortant to understand the ne user/installer perform sential that the user/inst 1.	is work in accordance aller ensures that his/	User/Ir document alone does not autor with the national regulations of her airworthiness authority act	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  ority of the country specified in Block as authority of the country specified	_
It is impo Where th 1, it is ess in Block I Statemen national r	ortant to understand the ne user/installer perform sential that the user/inst 1.	as work in accordance aller ensures that his/ a do not constitute ins	User/Ir document alone does not autor with the national regulations of her airworthiness authority act	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017	-
It is impo Where th 1, it is ess in Block I Statemen national r	ortant to understand the ne user/installer perform cential that the user/inst l. tts in Blocks 13a and 14 regulations by the user/i	as work in accordance aller ensures that his/ a do not constitute ins installer before the air	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca traft may be flown.	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where th 1, it is ess in Block I Statemen national r	ortant to understand the ne user/installer perform cential that the user/inst l. tts in Blocks 13a and 14 regulations by the user/i	as work in accordance alter ensures that his/ a do not constitute ins- installer before the air Aviators F	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca traft may be flown.	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where th 1, it is ess in Block I Statemen national r	ortant to understand the ne user/installer perform cential that the user/inst l. tts in Blocks 13a and 14 regulations by the user/i	as work in accordance aller ensures that his/ a do not constitute ins- installer before the air Aviators F Blue Ash A	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca traff may be flown.  light Center airport (KISZ)	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where th 1, it is ess in Block I Statement national r	ortant to understand the ne user/installer perform cential that the user/inst l. tts in Blocks 13a and 14 regulations by the user/i	as work in accordance alter ensures that his/ a do not constitute ins- installer before the air Aviators F Blue Ash A CRS 06	User/Ir document alone does not autor with the national regulations of her airworthiness authority acc tallation certification. In all ca craft may be flown.  light Center airport (KISZ)	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where th I, it is eas in Block I Statemen mational i	ortant to understand the se user/installer performa- tential that the user/instal.  Its in Blocks 13a and 14i regulations by the user/in- rm 8130-3 (02-14)	a do not constitute insinstaller before the air  Aviators F Blue Ash A CRS 06 (513) 9	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca traff may be flown.  light Center airport (KISZ)	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s/propel	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where th I, it is eas in Block I Statemen national r	ortant to understand the se user/installer performs the user/installer performs to the user/installer performs to the user/installer performs to the user/installer performs \$130-3 (02-14)	a do not constitute insustable before the air  Aviators F Blue Ash A CRS 06 (513) 9	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca traff may be flown.  light Center airport (KISZ) tWR853K 184-5880	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s)/propel sees, aircraft maintenance reco	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where th 1, it is ess in Block I Statemen national r	ortant to understand that en user/installer perform sential that the user/install.  Its in Blocks 13a and 14 regulations by the user/installer graduations by the user/installer graduation b	a do not constitute insinstaller before the air  Aviators F Blue Ash A CRS 06 (513) 9	User/Ir document alone does not autor with the national regulations of her airworthiness authority acc tallation certification. In all ca craft may be flown.  light Center hirport (KISZ) SWR853K 884-5880  Tach	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s)/propel sses, aircraft maintenance reconstitute authority of the saircraft maintenance reconstitutes aircraft maintenance a	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is impo Where the 1, it is east in Block I. Statemen national r FAA For	ortant to understand that he user/installer perform cential that the user/installer perform it. Its in Blocks 13a and 14d regulations by the user/irm 8130-3 (02-14)	a do not constitute insinstaller before the air  Aviators F Blue Ash A CRS 06 (513) 9	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca traff may be flown.  light Center airport (KISZ) tWR853K 184-5880	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s)/propel sees, aircraft maintenance reco	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	
It is imported by the same of	rimes N12 Times N42 Time 144 OH 0 d engine and seed engine with attor overhauler attor overhauler attor replaced viall new hoses of fuel injection sid alternator drivinew Sky Tec OF Flight Center 497	Aviators F Blue Ash A CRS 06 (513) 9  18P  4.8  O Dent to Signature rubber ed by Aerotechvith factory over from AERO A ystem IAW Mee pulley with 4ST5 starter.	User/Ir document alone does not autor with the national regulations of her airworthiness authority act tallation certification. In all ca craft may be flown.  light Center airport (KISZ) bWR853K  184-5880  Tach Eng TT Prop TT  Irre Engines for over langine mounts IAW  orerhauled unit. viation.  10. new.	Terrence McRonstaller Responsibilities matically constitute authority of an airworthiness authority cepts aircraft engine(s)/propel sees, aircraft maintenance reconstitute authority to the sees, aircraft maintenance reconstitute authority to the sees, aircraft maintenance reconstitute authority to the sees ai	to install the aircraft engine/propelle different than the airworthiness auth ller(s)/article(s) from the airworthine	08/Aug/2017  refarticle.  sority of the country specified in Block as authority of the country specified in Block as authority of the country specified infication issued in accordance with the	



#### **Aviators Flight Center Butler County Reg (KHAO)** CRS 06WR853K

<b>Current Times</b>	N1218P		OTALS bro
A/C Total Time	1471.1	Tach	1471.1
Eng TSMOH	26.3	Eng TT	1471.1
Prop TSMOH	26.3	Prop TT	1471.1
installed new CH element, no disc Aviators Flight	148108-1 filter. Cut	I engine with 8 qts 15w open used filter and e Run up and leack check R853K	xamined
W/O	514		

10/16/2017



**Duncan Latta** 

Signed

#### **Aviators Flight Center Butler County Airport (HAO) CRS 06WR853K**

Current Times	N1218P		
A/C Total Time	1571.3	Tach	1571.3
Eng TSMOH	126.5	Eng TT	1571.3
Prop TSMOH	126.5	Prop TT	1571.3
Aviators Flight W/O Duncan Latta	and check of tachor Center CRS 06WR 547 05/21/2018	853K	



#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

<b>Current Times</b>	N1218P		
A/C Total Time	1653.8	Tach	1653.8
Eng TSMOH	209	Eng TT	1653.8
Prop TSMOH	209	Prop TT	1653.8
Cleaned #1 botto Aviators Flight C W/O Duncan Latta Signed	om spark plug Center CRS 06WR853K 578 11/24/2018		



#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

<b>Current Times</b>	N1218P		
A/C Total Time	1548.4	Tach	1548.4
Eng TSMOH	103.6	Eng TT	1548.4
Prop TSMOH	103.6	Prop TT	1548.4

**Engine Annual-**

Drained oil and removed filter, filled engine with 8 qts 15w50 oil and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leack check is good.

Captured oil sample and sent for analysis.

Compression test: #1 68/80 #2 73/50 #3 65/80 #4 72/80 #5 72/80 #6 70/80.

Set Idle RPM to 620

Set magneto timing to 24 BTDC

Tightened alternator belt.

I certify this engine has been inspected IAW an ANNUAL inspection and is in an airworthy condition.

W/O

542

**Duncan Latta** 

03/29/2018



#### **Aviators Flight Center Butler County Airport** CRS 06WR853K (513) 984-5880

Current Times	N1218P		
A/C Total Time	1608.2	Tach	1608.2
Eng TSMOH	163.4	Eng TT	1608.2
Prop TSMOH	163.4	Prop TT	1608.2

Engine

Tightened connection on oil temp probe

Drained oil and removed filter, filled engine with 8qts 15w50 and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leak check is good.

Aviators Flight Center CRS 06WR853K W/O 556

**Duncan Latta** 

07/02/2018



#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

Current Times	N1218P		1	
VC Total Time	1654.4	Tach	1654.4	
Eng TSMOH	209.6	Eng TT	1654.4	
Prop TSMOH	209.6	Prop TT	1654.4	

TOTALS-Car

Cleaned, gapped and rotated spark plugs.

Drained oil and removed filter, filled engine with 8qts 15w50 and installed new CH48108-1 filter. Run up and leack check is good.

Replaced tach gen drive shaft with new.

SUB-TOTAL Aviators Flight Center CRS 06WR853K

12/12/2018 **Duncan Latta** 

Signed



#### **Aviators Flight Center Butler County Airport** CRS 06WR853K

#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

	Engine- Drained oil and	removed filter, fi	lled engine with 8 q	ts 15w50 oi
-	Prop TSMOH	298	Prop TT	1742.8
ıg	Eng TSMOH	298	Eng TT	1742.8
	A/C Total Time	1742.8	Tach	1742.8
U	<b>Current Times</b>	N1218P		

check is good .. W/O 615 **Duncan Latta** 06/17/2019 Signed

**Current Times** N1218P A/C Total Time 1691.6 Tach 1691.6 **Eng TSMOH** 246.8 Eng TT 1691.6 Prop TSMOH 246.8 Prop TT 1691.6 **Engine Annual-**

Drained oil and removed filter, filled engine with 8 qts 15w50 oil and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leack check is good.

Compression test: #1 70/80 #2 73/50 #3 68/80 #4 68/80 #5 72/80 #6 72/80.

Replaced #3 EGT probe with new.

Secured loose connection on Fuel Flow sensor wire at DAU. I certify this engine has been inspected IAW an ANNUAL inspection and is in an airworthy condition.

W/O **Duncan Latta**  608

04/11/2019

Signed



#### **Aviators Flight Center Butler County Airport** CRS 06WR853K

Current Times	N1218P		
A/C Total Time	1750.9	Tach	1750.9
Eng TSMOH	306.1	Eng TT	1750.9
Prop TSMOH	306.1	Prop TT	1750.9

Engine-

Removed Engine for repair of crank case crack

	-	
	1	
		A.K.
,	6	
	1	

#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

Prop TSMOH	306.1	Prop TT	1750.9
Eng TSMOH	306.1	Eng TT	1750.9
A/C Total Time	1750.9	Tach	1750.9
Current Times	N1218P		

Installed Engine after replacement of crank case by Airmark Overhaul Inc. IAW MM 77-00 4. A (2)

619 **Duncan Latta** 08/22/2019

L. Approv	ing Civil Aviation		3. Form Tracking Number:		
	hority/Country: A/United States	AUTHORIZED REL			47604
4 Organi	zation Name and Address AIR	FL 33309 (JL4R288M)	5. Work Order/Contract/Invoice Number: W/O: 47604		
6. Item:	7. Description:	S. Part Number:	D. Quantity: 10	Serial Number:	11. Status/Work:
001	ENGINE	10-360-ES	1/EA 3	60166	REPAIRED
ACCOR MAINT	NTINENTAL M DANCE WITH C NANCE MANUA	OTOR'S INC. ENGINE WAS REPAIREI ONTINENTAL MOTOR'S INC. OVERH AL M-O, DATED SEPTEMBER 2018. SEI R 47604. TIME SINCE MAJOR OVERHA	AUL MANUAL E FULL DETAI	M-7, DATED SEPTEM ILS OF WORK AND A.I	BER 2016 AND
		those were manufactured in conformity to:  and are in a condition for mile operation as specified in Black 12.	Certifies that	unics otherwise specified in Bloc d in Block 12 was accomplished in dations, part 43 and in respect to 0	Other regulation specified in Block 12 k 12, the work identified in Block 11 accordance with Title 14, Code of hat work, the items are approved for
13b. Aut	norized Signature:	13c. Approval/Authorization No.1	14h Authorized	Season Com	14c. Approval/Certificate No.: JL4R288M
LM Nam	(Lyped or Printed):	13c. Date (dd/matm(pyyy):	144. Name (Type WILLL	d or Printed): AM POLLARD	14c. Date (dd/mmm/yyyy): 02/AUG/2019
	The state of the s	User/Installer	r Responsibilities	Assembly the second	
Where the Block I, it specified is Statement	user/installer performs in essential that the user/ a Block L. in Blocks 13a and 14a d	he existence of this document alone does not automatically work in accordance with the national regulations of an air- installer ensures that his/her air-workinson sutherity accep- tion not constitute installation certification. In all cases, air- mater before the selected may be flown.	worthiness authority of pts aircraft engine(s)/	lifferent than the airworthiness au propeller(s)/article(s) from the airc	thority of the country specified in sorthiness authority of the country
	8130-3 (02-14)		10.31	HITCH THE	NSN: 0052-00-012-9005

_			
Pac	0	N	^
au		14	u.



## Aviators Flight Center Butler County Airport CRS 06WR853K

RIPTION OF WORK PERFORMED— TIFICATE NO. OF PERSON PERFORMING WORK

d from previous page

<b>Current Times</b>	N1218P		
A/C Total Time	1774.3	Tach	1774.3
Eng TSMOH	329.5	Eng TT	1774.3
Prop TSMOH	329.5	Prop TT	1774.3

Engine-

Adjusted fuel injection system IAW M0 6-4.10.2.2.

W/O Duncan Latta

09/12/2019

Signed\_



Aviators Flight Center Butler County Airport

CRS 06WR853K

<b>Current Times</b>	N1218P		
A/C Total Time	1787.3	Tach	1787.3
Eng TSMOH	342.5	Eng TT	1787.3
Prop TSMOH	342.5	Prop TT	1787.3

Engine

Drained oil and removed filter, cut open used filter and examined element, no discrepancies found. Filled engine with 8qts 15w50 and installed new CH48108-1 filter, run up and leak check is good.

W/O 632 Duncan Latta 09/30/2019

Signed



Aviators Flight Center
Butler County Airport
CRS 06WR853K

Prop TSMOH	377.5	Prop TT	1822.3
Eng TSMOH	377.5	Eng TT	1822.3
A/C Total Time	1822.3	Tach	1822.3
<b>Current Times</b>	N1218P		

Engine -

Removed cylinder fuel drains, cleaned and reinstalled.

W/O 64 Duncan Latta 01

01/15/2020

Signed 2

SUB-TOTALS this page

TOTALS-Carry forward to next page



#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

N1218P 1839.2 A/C Total Time 1839.2 Tach **Eng TSMOH** 1839.2 394.4 Eng TT 394.4 Prop TT 1839.2 **Prop TSMOH** 

Engine -

Drained oil and removed filter, filled engine with 8qts 15w50 and installed new CH48108-1. Cut open used filter and examined element, no discrepancies found. Run up and leak check is good. W/O

**Duncan Latta** 

658 03/09/2020

Signed



#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

N1218P **Current Times** 1847.4 A/C Total Time Tach 1847.4 402.6 **Eng TSMOH** Eng TT 1847.4 402.6 Prop TSMOH Prop TT 1847.4

**Engine Annual-**

Drained oil and removed filter, filled engine with 8 qts 15w50 oil and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leack check is good.

Compression test: #1 77/80 #2 76/50 #3 78/80 #4 77/80 #5 78/80 #6 77/80.

Cleaned and gapped spark plugs.

I certify this engine has been inspected IAW an ANNUAL inspection and is in an airworthy condition.

WO

663

**Duncan Latta** 

05/08/2020

Signed



#### **Aviators Flight Center Butler County Airport CRS 06WR853K**

**Current Times** N1218P 1902.1 Tach 1902.1 A/C Total Time **Eng TSMOH** 457.3 Eng TT 1902.1 1902.1 Prop TSMOH 457.3 Prop TT

Engine -

Drained oil and removed filter, filled engine with 8 qts 15w50 oil and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leack check is good.

W/O

683

**Duncan Latta** 

05/08/2020

Signed

TALS this page

-Carry forward to next page

DESCRIPTION OF WORK PERFORMED-TURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

bught forward from previous page

Scanned with CS CamScanner



### Avi

lators Flight Center	
utler County Airport	
CRS 06WR853K	

DESCRIPTION OF WORK PERFORMED-ATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

Current Times	N1218P		
A/C Total Time	1936.5	Tach	1936.5
Eng TSMOH	491.7	Eng TT	1936.5
Pron TSMOH	404 7	Prop TT	4020 5

Engine -

1. removed cylinders 1 and 3, replaced #3 with new and installed using new gaskets, reinstalled #1 with new gaskets.

2. Drained oil and removed filter, filled engine with 8 qts 20w50M oil and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leack check is good.

W/O Duncan Latte 42/08/2020

ought forward from previous page

Page No.



**Aviators Flight Center Butler County Airport** CRS 06WR853K

<b>Current Times</b>	N1218P		
A/C Total Time	1954.7	Tach	1954.7
Eng TSMOH	509.9	Eng TT	1954.7
Prop TSMOH	509.9	Prop TT	1954.7

**Engine Annual-**

Drained oil and removed filter, filled engine with 8 qts 15w50 oil and installed new CH48108-1 filter. Cut open used filter and examined element, no discrepancies found. Run up and leack check is good.

Compression test: #1 77/80 #2 76/50 #3 78/80 #4 77/80 #5 78/80 #6 77/80.

Cleaned and gapped spark plugs.

Replaced one spark plug with new RHM38E Tightened alternator belt


I certify this engine has been inspected IAW an ANNUAL inspection and is in an airworthy condition.

WIO

712

	00	
the Committee of the Co		SUB-TOTALS this page

TOTALS-Carry forward to next page



TE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	SIGNATU		N OF WORK PE E NO. OF PER	ERFORMED— SON PERFORMING V	VORK
E A		-63	T	OTALS brou	ght forward from	nrevious nade		
					Makas	Castinantal		
DE	Buckeye Buc	keye Aviatio	n LLC		20.00.00	Continental IO-360-ES		
May -	Leb	anon OH 45	Road Hangar 12 036		Tall:	N1218P		
	513	8146769			S/N:	360166		
Hour	s: TACH: 198	7.1 ACTT: 1	987.1 TSMOH: 54	42.3 PropTSMC	OH: 542.3			-
Repla Com Drain	aced air filter work pressions 1 20 ned oil. Added	rith BA-24 filt 278374 8 Qts Phillip		talled new filter	and leak checked	x D 100Hr inspe		
Sign	ed:		//	1	when were a second		705782IA	
Nam		Akers/				Date: _06	6/17/2022	-
	075-07-2023 (07-3	1-2023)	2-2-3			Page 1 / 1		
Service Control	MAKE: Cirrus	М	idwest Corporate	Air		/O #: 075-07-2023	and the second	
	MODEL: SR20 S/N: 1677 REG. NO:: N121 ENGINE MAKE: CONTINENTAL ENGINE MODEL ES	8P Be	00 State Route 47 Wes			DATE: 07-31-2023 A/C Tach: 2010.2 ENG TT: 2010.2 TSOH: 565.4		
	discrepancies not Blackstone oil sa #6 (76/80)] • Re I certify that this a	es  ual inspection IAI ted. Serviced wit mple for analysis esearched and co	h 8 qts 20w50 oil and A • Compressions [#1 complied with all Airworth repaired and inspected	A48108-2 filter. Wa: (77/80), #2 (78/80), hiness Directives. So	changed oil, cut open filte shed engine, leak check #3 (75/80), #4 (76/80), # ee compliance records. an ANNUAL/100 hour in	ed. Sent out 5 (75/80),		
	determined to be	in airworthy con	dition at this time.	7				
	DATE: 07-31-202		IGNED:			DER: 075-07-2023		
			im Kerns AA Cert A&P 3390695	IA	Printed by EBIS	S (EBISCloud.com)		0.000
	153-09-2023 (09-2	1-2023)				Page 1 / 1		a hardware
	MAKE: Cirrus MODEL: SR20	M	idwest Corporate			O #: 153-09-2023 OATE: 09-21-2023		
_	S/N: 1677 REG. NO:: N1218		llefontaine, OH 43311			A/C Tach: 2041.5 ENG TT: 2041.5		
	ENGINE MAKE: CONTINENTAL	12				TSOH: 596.7 Hobbs: 2562.2		
	ENGINE MODEL ES	: IO-360-				110003. 2302.2		
	ENGINE SN: 360	166						
	• Performed 50 ho	our inspection IA	W Cirrus SR22 MM and	d inspection checklis	st • Changed oil, cut op shed engine, leak checke	en filter, no ed. Sent out		
	discrepancies not	discrepancies noted. Serviced with 8 qts 20w50 oil and AA48108-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample • Researched and complied with all Airworthiness Directives. See compliance list.						<u> </u>
	discrepancies not Blackstone oil sar		repaired and increased	in accordance with	a so nour inspection and	Dellinianen eur		
	discrepancies not	aircraft has been	time.					
_	Blackstone oil sar I certify that this a	aircraft has been condition at this	time.	m		DER: 153-09-2023		
	Blackstone oil sar I certify that this a to be in airworthy	aircraft has been condition at this	time.	<u>~</u>		DER: 153-09-2023 (EBISCloud.com)		

MAKE: Cirrus MODEL: SR20 S/N: 1677 REG. NO:: N1218P ENGINE MAKE: CONTINENTAL **ENGINE MODEL: 10-360-ENGINE SN: 360166** 

Midwest Corporate Air 3100 State Route 47 West Bellefontaine, OH 43311

W/O #: 266-01-2024 DATE: 01-12-2024 A/C Tach: 2105.2 ENG TT: 2105.2 TSOH: 660.4

#### **Engine Entries**

 Performed 100 hour inspection IAW MM and inspection checklist....
 Changed oil, cut open filter, no discrepancies noted. Serviced with 8 qts 20w50 oil and AA48108-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample for analysis....
 Compressions [#1 (77/80), #2 (73/80), #3 (79/80), #4 (72/80), #5 (73/80, 6 (73/80)]... • Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with an ANNUAL/100 hour inspection and was determined to be in airworthy condition at this time

DATE: 01-12-2024

SIGNED: Tim Kerns FAA Cert A&P 3390695 IA WORK ORDER: 266-01-2024

Printed by EBIS (EBISCloud.com)

275-01-2024 (01-31-2024)

MAKE: Cirrus MODEL: SR20 S/N: 1677 REG. NO:: N1218P ENGINE MAKE: CONTINENTAL ENGINE MODEL: 10-360-

**Midwest Corporate Air** 3100 State Route 47 West Bellefontaine, OH 43311

W/O #: 275-01-2024 DATE: 01-31-2024 A/C Tach: 2119.9 ENG TT: 2119.9 TSOH: 675.1

Page 1 / 1

**ENGINE SN: 360166** 

#### **Engine Entries**

• Installed L/H Magneto overhauled by Quality Aircraft Accessories P/N 6314, S/N H-X080528. See 8130-3 form dated 8/31/2023. Installed R/H Magneto overhauled by Kelly Aero P/N 6314, S/N L-09462. See 8130-3 form dated 9/18/2023

DATE: 01-31-2024

SIGNED Tim Kerns WORK ORDER: 275-01-2024

Printed by EBIS (EBISCloud.com)

293-02-2024 (02-19-2024)

MAKE: Cirrus MODEL: SR20 S/N: 1677 REG. NO:: N1218P ENGINE MAKE: CONTINENTAL

ENGINE MODEL: 10-360-ENGINE SN: 360166

Midwest Corporate Air 3100 State Route 47 West Bellefontaine, OH 43311

FAA Cert A&P 3390695 IA

Page 1 / 1 W/O #: 293-02-2024 DATE: 02-19-2024 A/C Tach: 2141.5 ENG TT: 2141.5 TSOH: 696.7

#### **Engine Entries**

Installed new Continental Connector-Tach Drive P/N 642121-1RH. See 8130-3 form dated 8/30/2023... Installed new L/H Cirrus Muffler P/N 20560-001....Performed SID-97 Fuel Calibration.

DATE: 02-19-2024

SIGNED Tîm Kerns FAA CAN ARD 3300605 IA

WORK ORDER: 293-02-2024 Printed by EBIS (EBISCloud.com)

332-03-2024 (03-01-2024)

MAKE: Cirrus MODEL: SR20 S/N: 1677 REG. NO:: N1218P ENGINE MAKE CONTINENTAL ENGINE MODEL: 10-360Midwest Corporate Air 3100 State Route 47 West Bellefontaine, OH 43311

Page 1 / 1 W/O #: 332-03-2024 DATE: 03-01-2024 A/C Tach: 2157.4 ENG TT: 2157.4 TSOH: 712.6

#### **ENGINE SN: 360166 Engine Entries**

 Performed 50 hour inspection IAW MM and inspection checklist....
 Changed oil, cut open filter, no discrepancies noted. Serviced with 8 qts 20w50 oil and AA48110-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample.... • Researched and complied with all Ajworthiness Directives. See compliance list.

cordance with a 50 hour inspection and was determined I certify that this aircraft has been repaired and inspected in to be in airworthy condition at this time.

DATE: 03-01-2024

WORK ORDER: 332-03-2024 Printed by EBIS (EBISCloud.com)

417-05-2024 (06-11-2024) W/O #: 417-05-2024 Midwest Corporate Air DATE: 06-11-2024 3100 State Route 47 West Bellefontaine, OH 43311 MODEL: SR20 A/C Tach: 2197.4 ENG TT: 2197.4 S/N: 1677 REG. NO: N1218P ENGINE MAKE: TSOH: 752.6 CONTINENTAL ENGINE MODEL: 10-360-ENGINE SN: 360166 **Engine Entries**  Performed 100 hour inspection IAW MM and inspection checklist.... • Changed oil, cut open filter, no discrepancies noted. Serviced with 8 qts 20w50 oil and AA48110-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample for analysis.... • Compressions [#1 (70/80), #2 (68/80), #3 (70/80), #4 (64/80), #5 (70/80), (#6 (72/80)... • Researched and complied with all Airworthiness Directives. See compliance records. I certify that this aircraft has been repaired and inspected in accordance with an ANNUAL/100 hour inspection and was determined to be in airworthy condition at this time. WORK ORDER: 417-05-2024 SIGNED: DATE: 06-11-2024 Printed by EBIS (EBISCloud.com) Alvin Minzler FAA Cert A&P 3099793 563-08-2024 (08-09-2024) Page 1/1 MAKE: Cirrus MODEL: SR20 S/N: 1677 REG. NO: N1218P ENGINE MAKE: W/O #: 563-08-2024 **Midwest Corporate Air** DATE: 08-09-2024 3100 State Route 47 West A/C Tach: 2215.1 Bellefontaine, OH 43311 ENG TT: 2215.1 TSOH: 770.3 CONTINENTAL ENGINE MODEL: 10-360-**ENGINE SN: 360166 Engine Entries** · Performed ANNUAL inspection IAW Cirrus MM and inspection checklist.... · Changed oil, cut open filter, no discrepancies noted. Serviced with 8 qts 20w50 oil and AA48108-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample for analysis.... • Installed 8ea new Tempest spark plugs P/N URHM38E and 12ea new spark plug washers.... • Compressions [#1 (74/80), #2 (72/80), #3 (78/80), #4 (74/80) #5 (74/80), #6 (72/80)]... • Researched and complied with all Airworthiness Directives. See compliance records. I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time. DATE: 08-09-2024 SIGNED: WORK ORDER: 563-08-2024 Tim Kems FAA Cert A&P 3390695 IA Printed by EBIS (EBISCloud.com) 650-09-2024 (09-17-2024) Page 1 / 1 W/O #: 650-09-2024 MAKE: Cirrus MODEL: SR20 Midwest Corporate Air DATE: 09-17-2024 3100 State Route 47 West Bellefontaine, OH 43311 A/C Tach: 2266.3 S/N: 1677 REG. NO: N1218P ENGINE MAKE: ENG TT: 2266.3 TSOH: 821.5 ENGINE MODEL: 10-360-**ENGINE SN: 360166 Engine Entries**  Performed 50 hour inspection IAW Diamond MM and inspection checklist....
 Installed new tach sensor P/N T1A3-4 S/N B8428 and tach drive P/N S4212-1....
 Changed oil, cut open filter, no discrepancies noted. Serviced with 6 qts 20w50 oil and AA48108-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample.... Researched and complied with all Airworthiness Directives. See Compliance List. I certify that this aircraft has been repaired and inspected in accordance with a 50 hour inspection and was determined to be in airworthy condition at this time. WORK ORDER: 650-09-2024 DATE: 09-17-2024 SIGNED: Printed by EBIS (EBISCloud.com) Alvin Minzler FAA Cert 3099793 A&P Page 1 / 1 674-10-2024 (10-03-2024) W/O #: 674-10-2024 MAKE: Cirrus **Midwest Corporate Air** DATE: 10-03-2024 A/C Tach: 2293.2 ENG TT: 2293.2 3100 State Route 47 West Bellefontaine, OH 43311 MODEL: SR20 S/N: 1677 REG. NO: N1218P ENGINE MAKE: TSOH: 848.4 CONTINENTAL **ENGINE MODEL: 10-360-ENGINE SN: 360166 Engine Entries** • Installed new #1 Cirrus CHT sensor P/N 14880-001 WORK ORDER: 674-10-2024 DATE: 10-03-2024 SIGNED: Printed by EBIS (EBISCloud.com) Tim Kerns Cert A&P 3390695 IA una page

TOTALS-Carry forward to next page



ENGINE MAKE: CONTINENTAL **ENGINE MODEL: 10-360-**

ENGINE SN: 360166 **Engine Entries** 

Performed 100 hour inspection IAW Cirrus MM and inspection checklist....
 Changed oil, cut open filter, no discrepancies noted. Serviced with 6 qts 20w50 oil and AA48108-2 filter. Washed engine, leak checked. Sent out Blackstone oil sample for analysis....
 Installed new #1 bottom spark plug Tempest P/N URHM38E....
 Compressions [#1 (62/80), #2 (67/80), #3 (75/80), #4 (65/80) #5(69/80), #6 (67/80)]...
 Researched and complied with all Airworthiness Directives. See compliance records.

I certify that this aircraft has been repaired and inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition at this time WORK ORDER: 882-02-2025 SIGNED DATE: 02-28-2025 Printed by EBIS (EBISCloud.com) Tim Kerns FAA Cert A&P 3390695 IA SUB-TOTALS this page TOTALS-Carry forward to next page