

SSP 1872-1

652 Oliver Street Williamsport, PA 17701 U.S.A. 717/323-6181

October 1994

ENGINE LOG AND MAINTENANCE RECORD

RECORD OF	TEXTRON LYCOMING	0-360-A4A		L24027-36A	
	MAKE	MODEL		SERIAL	
FROM $\overline{\mathcal{J}_{c}}$	ine 25	19. 2008 TO		19	
DETAILING TIM	ME FROM AFTT 4282.4 73 MOH 548.3	Eng TT 3120.7	_ TO		
	73 MOH 548,3	HOURS		HOURS	

ENGINE DESCRIPTION

Mfgr. TEXTRON LYCOMING	Place Williamsport, I	PA 17701 Date
Туре	Model	Serial No.
Rated H.P.	Max. H.P.	Weight (Dry)
Rated R.P.M.	Max. R.P.M.	Oil Pressure
Bore	Stroke	Displacement Cu
Compression Ratio	Supercharger Ratio	
Reduction Gear Ratio		
Propeller Sensenich	Hub Design76EM85	5-0-60 Hub Serial No. 2.5570
Blade Design	Blade Serial No.	Blade Serial No.
Max. Hub H.P.	Max. Blade H.P.	
Pitch	Diameter	Length
Name		
Address		

	Min REPAIRS - ADJUSTMENTS - SERVICE	Number
June 25,08 7	10 Fo Tac 4282.4 Eng 17 3120	0.7 TS not 548.3(4/92) PropTSvort 313.1
Inspecto en	give ikelw Piper PA-28-180	S.M. and FOO approved checklist
change or	and Sitter CH48110-1 2825	Dear 15/50, no metal break is till
Removed cyl.	5 - 644 due to leak past	-ex-valves, replace ex-valve quite
valves pln: L	W19001, ground all seats, gra	undintake valves, honed, cheaned, assemble
and installed	When gastrets and reals,	value day last chearance ok, reting
lest mag,	dean and gap swark plas	es pressure check when of I al
strainer, dr.	essed prop, checked forg	ue of intake, exhaust, mass, prop,
spine botts,	samp, cyls, rocker covers	post run up and lack click
OK, ner la		ine, Certification on next pace Not
	Brought Forward	All Repair Data Must Bear the Endorsement of a
	Total to Date	Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

Date	Tii Hrs	me Min	REPAIRS - AD.	JUSTMENTS - SERVICE - R	EMARKS	Signature	License Number
> cleck	ed	AD.	3 thru o	8-12 no ne	w & this	lone -	
Compre	_		794	I certify that this	ensine epighas bee		
Con	pre	ssion	Test	in accordance w	ith a annual	inspection	
	-			and was determ Date 06/25/08	ined to be in airworth Total Time_4282	y condition.	
	2	3	4		+ d-Holden		¥
177	X	17	7 X	A+R52	2350755727		
80	80	. 8	30	HAP'S AIR SER 2508 AIRPORT			40
#7 =4	8	pai	and the same of th	AMES, IA 5001		B . 2-4	3
	, , ,						on the second
ered as .	ç.				4		
			Page Total		All Repair Data Must Bear	the Endorsement of a	
			Brought Forward	i	Certificated Mechanic, and	his Rating and	
			Total to Date		Certificate Number MUST I	be Snown.	


Se	rial	No.
00	141	140.

Date Hrs Min REPAIRS - ADJUSTMENTS - SERVICE - REMARKS Signature Licenter Minds Tune 24,09 Tack + TIPT 4295.68 TI Eng 311475 TSOH 542.35 (April 9) The understand Total 1255 (In plane) Turpecties and ine is all properties and in the standard Carlot and times to the standard and for the standard and according to the standard and for the standard for th				
Tune 24, 09 Tack 1TRT 4295.68 TEng 3114.75 T50H 542.35 (April 1) The unhamiliant for 1725.8 (I-pl.79) Turpocted engine is all proposed to the control of a contr	Date		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature Licens
	PAZB- PAZB- C. 11.x contan harnes halts at	anhain 180 130 100 100 100 100 100 100 100	Clamps of return time clamps and syst. Replaced worn rivets on lower Page Total Brought Forward All Repair Data Must Bear the Certificated Mechanic and him Certificated Mechanic and	ine itale piper ine itale piper t. Champed oil Pitor for metal ion testerique ion testerique crintake flaure accorrible 15" the Citer harmane Citer harmane Dog. 12. Emportion Endorsement of a

Data	Ti	me				License
Date	Hrs	Min	REPAIR	RS - ADJI	JSTMENTS	- SERVICE - REMARKS Signature Number
		С	ompres	sion T	est	in accordance with a annual inspection
		1	2	3	4	Date June 24 of Total Time 4245.68 HH
		76	76	75	71	HAP 92350 7557 AN
		80	80	80	80	HAP'S AIR SERVICE, INC. 2508 AIRPORT DR.
						AMES, IA 50010
	•					
			*			
			Page Tot Brought Total to	Forward	*	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

Carial NI-

Date Hrs.	Date 04 112 110 A/C Hrs 4308,27 -Replaced vac pump with plni-k A37317 and Sicewall to pump run up and op check ok - EN	N# 96290 POZISCE SIN: 100 Lose, post	
		to:	
	For pertinent details of this maintenance action refer Work Order(s) Signed	Hap's Air Service, Inc. Municipal Airport Ames, Iowa 50010	
	Issued in Lieu of Logbook Entr	Mechanic, and his Rating and lumber MUST be Shown.	of a





Date	Tir Hrs	me Min	REPAIRS - ADJUSTMENTS - SERVICE - RI	EMARKS	Signature	License Number
July 01	10	Tach	+ NOF 4312.72 Eng V 3131.79	TSNOH 559.39 (4/92)	Page TT 4312,72,	TS400 343.42
			Talu Piper PA28-180 S. M. and			
Silder C	481	10-1	and 8gt Dono 15/50, no metal	Sound mas dining	st, harness	ok, dean
			kplass, 190 715, pressure test			
, v			er, checkel alabed and			
		1	spine, prop mass, etc. 14			
/	7//		viel Letter muff as need		/	The sales of the s
			n up and leak shork of			
		1	l'ourdistication on next			
			Page Total	All Repair Data Must Bear	the Endorsement of a	
			Brought Forward	Certificated Mechanic, and Certificate Number MUST to	his Rating and	
			Total to Date			

	1			
Date	Ti	me		
Date	Hrs	Min	REPAIRS - ADJUSTMENTS -	7.00
				Loortify that this resine some back
	Co	mpr	ession Test	I certify that this raine appe has been inspected in accordance with a annual increase.
1	2	3	4 5 6	and was determined to be in airworthy condition
72	71	70	77 \/ \/	Data 07 0010 Tale 10 De III all Worthy condition
12	10	12		Date 07/01/10 Total Time 4/3/2.72 HRS
80	80	80	80 80 80	Kout & Howen
				14453357
				HAD'S AID SERVICE ING
				HAP'S AIR SERVICE, INC.
				2508 AIRPORT DR.
				AMES, IA 50010
			Page Total	
			Brought Forward	All Repair Data Must Bear the Endorsement of a
			Total to Date	Certificated Mechanic, and his Rating and
			10 0000	Certificate Number MUST be Shown.

_ = =	ENGINE MODEL: O-360-A4A ENGINE S/N: L24027-3 REG. NO: N9629J WORK ORDER: 0930-06-2011	Classic Aviation, Inc. 501 W 15th St Pella, IA 50219 Phone: 641-628-9393		DATE: 6/13/2011 A/C TSN: 4345.77 ENG TT: 3164.77 TSMOH: 592.37 TACH: 4345.77	License Number
_ _ _	intake and exhaust s blades of propeller. 15W50 and CH 481	n. Compression check #1 76/80, #2 7480, #3 76/80, #systems. Cleaned, gapped and rotated spark plugs and Checked all applicable AD's and updated list in aircra 10-1. Took oil sample. Cut open old filter to check force - none noted at this time.	nd re-installed with new M-674 gaskets. off records (3) Changed oil and filter w	Filed and dressed with Aeroshell	
_	DATE: 6/13/2011	SIGNED. Randall D Hunter, IA: 3445985	Work	Order: 0930-06-2011 — 3 (datcomedia.com)	
		Page Total Brought Forward Total to Date	All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST	his Rating and	a

--





Da.	ENGINE MODEL: 0-360-A4A ENGINE S/N L24027-36A REG NO N9629J WORK ORDER: 1339-06-2012		Classic Aviation, Inc. 501 W 15th St Pella, IA 50219 Phone: 641-628-9393	DATE: 6/21/2012 A/C TSN: 4375.8 ENG TT: 3194.8 TSMOH: 622.4 TACH: 4375.8	Nu
	Engine Entries				_
_	blades of propeller. Checked and filter with new CH48108-	propeller tracking. Checked all filter and 7 ats Aeroshell 15/50	0, #3 74/80, #4 76/80. Checked magneto to engoark plugs and re-installed with new M-674 gask applicable AD's and updated list in aircraft recordil and 1 bottle Cam Guard. Took oil sample. (I leaks, no leaks noted at this time.	ets. Filed and dressed	_
	I certify that this engine and prope	ller have been inspected in accordance	ce with an annual inspection and were determined to be	in ainmothy and day	
	DATE: 6/21/2012	SIGNED: Va Have	2/.	rk Order: 1339-06-2012 -	
	I 1 I	Wm. Haven Hick, IA: 3428785		Bis 3 (datcomedia.com)	
	Page Tota		All Repair Data Must Bear the	Endorsoment of a	
1	Brought Fo	orward	Contition that made bear the	Lindorsement of a	
_	Total to D		Certificated Mechanic, and his Certificate Number MUST be S	Rating and	

O-360-A4A

ENGINE S/N: L24027-36A

REG. NO: N9629J WORK ORDER: 1755-06-2013



Classic Aviation, Inc.

501 W 15th St Pella, IA 50219 Phone: 641-628-9393 DATE: 7/1/2013 A/C TSN: 4388.1 ENG TT: 3207.1 TSMOH: 634.7

TACH: 4388.1

Engine Entries

(2) Annual Inspection. Compression check #1 74/80, #2 77/80, #3 74/80, #4 77/80. Checked magneto to engine timing. Inspected intake and exhaust systems. Cleaned, gapped and rotated spark plugs and re-installed with new M-674 gaskets. Checked all applicable AD's and updated list in aircraft records.... (4) Changed oil and filter with new CH48108-1 filter and 7 qts Aeroshell 15/50 oil and 1 bottle Cam Guard. Took oil sample. Cut open old filter to check for contaminants, none found. Ran engine to check for leaks, no leaks noted at this time.

I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

DATE: 7/1/2013

SIGNED: Zhan Hall

Work Order: 1755-06-2013

Wm. Haven Hick, IA: 3428785

Printed by EBis 3 (datcomedia.com)

PROP MODEL:

76EM855-0-60

PROP S/N: 25570K

REG. NO: N9629J WORK ORDER:

1755-06-2013



Classic Aviation, Inc.

501 W 15th St Pella, IA 50219

Phone: 641-628-9393

DATE: 7/1/2013

A/C TSN: 4388.1 PROP TT:

TSPOH: 418.73

TACH: 4388.1

Prop Entries

(3) Annual Inspection. Filed and dressed blades of propeller. Checked propeller blade tracking. Checked all applicable AD's and updated list in aircraft records.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

DATE: 7/1/2013

SIGNED:

VED: Zam Haven His

Work Order: 1755-06-2013

Wm. Haven Hick, IA: 3428785

Printed by EBis 3 (datcomedia.com)

O-360-A4A

ENGINE S/N: L24027-36A

REG. NO: N9629J WORK ORDER: 2165-06-2014



Classic Aviation, Inc.

501 W 15th St Pella, IA 50219 Phone: 641-628-9393 DATE: 6/24/2014 A/C TSN: 4396 59

A/C TSN: 4396.59 ENG TT: 3215.59

> TSMOH: 643.19 TACH: 4396.59

Engine Entries

(2) Annual Inspection. Compression check #1 73/80, #2 72/80, #3 73/80, #4 73/80. Checked magneto to engine timing. Inspected intake and exhaust systems. Cleaned, gapped and rotated spark plugs and re-installed with new M-674 gaskets. Checked all applicable AD's and updated list in aircraft records.... (4) Changed oil and filter with new CH48110-1 filter and 7 qts Aeroshell 15/50 oil and 1 bottle Cam Guard. Cut open old filter to check for contaminants. Ran engine to check for leaks, no leaks noted at this time.

I certify that this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

DATE: 6/24/2014

SIGNED:

. . . .

Work Order: 2165-06-2014

Wm. Haven Hick, IA: 3428785

Printed by EBis 3 (datcomedia.com)

PROP MODEL:

76EM855-0-60

PROP S/N: 25570K

REG. NO: N9629J WORK ORDER:

2165-06-2014

Classic Aviation, Inc.

501 W 15th St

Pella, IA 50219

Phone: 641-628-9393

DATE: 6/24/2014

A/C TSN: 4396,59

PROP TT:

TSPOH: 427.22

TACH: 4396.59

Prop Entries

(3) Annual Inspection. Filed and dressed blades of propeller. Checked propeller blade tracking. Checked all applicable AD's and updated list in aircraft records.

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

DATE: 6/24/2014

SIGNED:


D: Za Haven Hell

Work Order: 2165-06-2014

Wm. Haven Hick, IA: 3428785

Printed by EBis 3 (datcomedia.com)

nse			ENGINE MODEL: O-360-A4A ENGINE S/N: L24 REG. NO: N9629, WORK ORDER: 2626-06-2015	ENGINE MODEL: 0-360-A4A ENGINE S/N: L24027-36A REG. NO: N9629J WORK ORDER: 3107-06-2016	1	Classic Aviation, Inc 501 W 15th St Pella, IA 50219 Phone: 641-628-9393	: .	DATE: 6/10/2016 A/C TSN: 4420.78 ENG TT: 3239.78 TSMOH: 667.38 TACH: 4420.78
		L	Engine Entri-	Engine Entries				ń
			(2) Annual Inspirintake and exha applicable ADs Changed oil and for contaminant	intake and exhaust systems applicable ADs and updated	Cleaned, gapped and rotate list in aircraft records (4)	75/80, #3 76/80, #4 76/80. Che ed spark plugs and re-installed of Changed oil and filter with new of for contaminants. Ran engine to	with new M-674 gaskets. (CH48110-1 filter and 7 qts.	Checked all Aeroshell 15/50
	,		I certify that this e	I certify that this engine has bee	n inspected in accordance with a	n annual inspection and was determi	ned to be in airworthy condition	n.
			DATE: 6/17/201	DATE: 6/10/2016	SIGNED: Zil	even His	Work O	rder: 3107-06-2016
					Wm. Haven Hick, IA: 3428	785	Printed by EBis 3	(datcomedia.com)
			PROP MODEL: 76EM855-0-60 PROP S/N: 25570K REG. NO: N9629J WORK ORDER: 2626-06-2015		Classic Aviat 501 W 15th St Pella, IA 50219 Phone: 641-628-93		DATE: 6/17/2015 A/C TSN 4408.62 PROP TT: TSPOH: 439.25 TACH: 4408.62	
•			Prop Entries					
			(3) Annual Inspection updated list in aircra	n. Filed and dressed blades of ift records.	f propeller. Checked propelle	er blade tracking. Checked all a	pplicable ADs and	
			I certify that this propel	ler has been inspected in accordance	ce with an annual inspection and	was determined to be in airworthy co	ondition.	
	25		DATE: 6/17/2015	SIGNED:	Haven Hill		k Order: 2626-06-2015	
				Wm. Haven Hick, IA	3428785	Printed EF	Bis 3 datcomedia com	



Date	ENGINE MODE 0-360-A4A ENGINE S/N: L2 REG NO N962 WORK ORDER: 3699-06-2017	24027-36A 9J	Classic Aviation, Inc. 501 W 15th St Pella, IA 50219 Phone: 641-628-9393	DATE: 6/19/2017 A/C TSN: 4434 05 ENG TT: 3253.05 TSMOH: 680 65 TACH: 4434.05	.icense lumber
	Engine Entr	ries			
	#2-74/80, #3-7 M-674 Gaskets Refer to AD Lis a new Champi	6/80, #4-78/80. Checked Mass. Dressed Propeller Blades sting dated Jun.2017 for curron CH48110-1 Oil Filter and	ingine/Propeller) in accordance with the Scope and Detail of 1d ion Report P/N 230-207. Performed Differential Compression agneto Timing. Cleaned, Gapped, Tested, and rotated Spark Pl and checked tracking. Researched AD's and updated AD List rent AD Status (3) Drained Oil and removed Oil Filter to che Serviced Engine with 7Qts. Aeroshell 15W/50 Oil and 16 oz.	Check as follows: #1-78/80, ugs reinstalling with new ting in Aircraft records.	
	_	P/N 359-2D0072 Primer Hos	UNG DEUR HUMPO - (A) RANISCAA NIAICA EURAR MALIANA CIAAAA	P/N MS21919WDG14	
	(11) Replaced	P/N 359-2D0072 Primer Hos	se Assy.	P/N MS21919WDG14	
	(11) Replaced	P/N 359-2D0072 Primer Hosengine and propeller have been in SIGNED:	se Assy. inspected in accordance with an annual inspection and were determined.	d to be in airworthy condition.	
	(11) Replaced I certify that this e	P/N 359-2D0072 Primer Hosengine and propeller have been in SIGNED:	se Assy. inspected in accordance with an annual inspection and were determined.	P/N MS21919WDG14	

/2017 40 55 40 55
2017
4.4 4.4


Page Total


Total to Date


Brought Forward


All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.


License Number




















O-360-A4A

ENGINE S/N: L24027-36A

REG. NO: N9629J

WORK ORDER:

5418-06-2020



Classic Aviation, Inc.

501 W 15th St Pella, IA 50219

Phone: 641-628-9393

DATE: 7/1/2020

A/C TSN: 4468.23

ENG TT: 3287.23

TSMOH: 714.83

TACH: 4468.23

Engine Entries

(2) Annual Inspection. Compression check #1 75/80, #2 76/80, #3 78/80, #4 76/80. Checked magneto to engine timing. Inspected intake and exhaust systems. Cleaned, gapped and rotated spark plugs and re-installed with new M-674 gaskets. Filed and dressed blades of propeller. Checked all applicable AD's on engine and propeller and updated list in aircraft records.... (3) Changed oil and filter with new CH48110-1 filter and 8 qts Phillips 20W/50. Cut open old filter to check for contaminants, none found. Ran engine to check for leaks, no leaks noted at this time.

I certify that this engine and propeller have been inspected in accordance with an annual inspection and were determined to be in airworthy condition.

DATE: 7/1/2020


SIGNED:

Stals M

Work Order: 5418-06-2020

Shane Vande Voort, IA: 3362480

Printed by EBis 3 (datcomedia.com)



O-360-A4A

ENGINE S/N: L24027-36A

REG. NO: N9629J WORK ORDER:

5977-06-2021



Classic Aviation, Inc.

501 W 15th St Pella, IA 50219

Phone: 641-628-9393

DATE: 7/9/2021

A/C TSN: 4482.96 ENG TT: 3301.96

TSMOH: 729.56

TACH: 4482.96

Engine Entries

(2) Annual Inspection. Compression check #1 75/80, #2 75/80, #3 77/80, #4 75/80. Checked magneto to engine timing. Inspected intake and exhaust systems. Cleaned, gapped and rotated spark plugs and re-installed with new M-674 gaskets. Filed and dressed blades of propeller. Checked all applicable AD's on engine and propeller and updated list in aircraft records.... (4) Changed oil and filter with new CH48110-1 filter and 8 qts Phillips 20W/50. Cut open old filter to check for contaminants, none found. Ran engine to check for leaks, no leaks noted at this time.... (6) Sealed Cyl# 2 and 3 oil return fittings with Loctite 592 performed leak check, no issues found at this time... (7) Replaced Cyl# 3 and 4 Rocker Cover Gaskets with Real Gaskets P/N RG-75906 Gaskets.

I certify that this engine and propeller have been inspected in accordance with an annual inspection and were determined to be in airworthy condition.

DATE: 7/9/2021

SIGNED:

.

Work Order: 5977-06-2021

O-360-A4A

ENGINE S/N: L24027-36A

REG. NO: N9629J WORK ORDER:

6541-06-2022



Classic Aviation, Inc.

501 W 15th St Pella, IA 50219

Phone: 641-628-9393

DATE: 7/23/2022

A/C TSN: 4500.38

ENG TT: 3319.38 TSMOH: 746.98

TACH: 4500.38

Engine Entries

(2) Annual Inspection. Compression check #1 74/80, #2 74/80, #3 76/80, #4 73/80. Checked magneto to engine timing. Inspected intake and exhaust systems. Cleaned, gapped and rotated spark plugs and re-installed with new M-674 gaskets. Filed and dressed blades of propeller. Checked all applicable AD's on engine and propeller and updated list in aircraft records.... (3) Changed oil and filter with new CH48110-1 filter and 8 qts Phillips 20W/50. Cut open old filter to check for contaminants, none found. Ran engine to check for leaks, no leaks noted at this time.

I certify that this engine and propeller have been inspected in accordance with an annual inspection and were determined to be in airworthy condition.

DATE: 7/23/2022

SIGNED:


& 4/2 df


Work Order: 6541-06-2022

Shane Vande Voort, IA: 3362480

Printed by EBis 3 (datcomedia.com)

Date	Tir Hrs	me Min	REPAIRS - ADJUSTMENTS - SERVICE - RI	EMARKS •	Signature	License Number
		ENG THE AIRCOAIRWORD SIGN Drain	PA28-180 CHANDLER MUN 28-3786 CHANDI	LER, AZ HOE 732-9118 TAC TOT ED IN ACCORDANCE WITH CURRENT FEDERAL AI AILS OF THE REPAIR ARE ON FILE AT THIS AGEN AUTH.	59515 BBS XXXXX CH 4533.89 CAL XXXXX R REGULATIONS AND WAS FOUND CY.	
			Page Total Brought Forward	All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST	his Rating and	
			Total to Date	Certificate Number MOST	DO OTTOWN.	





Date	Tir	ne						
Date	Hrs	Min	REPAIRS - ADJ	USTMENTS - SERVICE -	REMARKS		Signature	
	REG MOD	NO EL	N9629J PA28-180	CHANDLER AV		DATE	12/14/22	
	s/n		28-3786 XXXXXX	CHANDLER MUNIC CHANDLER (480) 732	R, AZ .	WO# HOBBS TACH	59565 XXXXX 4541.21	
	THE AIR AIRWOR	S/N CRAFT AND/ THY FOR RE	OR COMPONENT IDENTIFIED AS TURN TO SERVICE ON THE DAY	BOVE WAS REPAIRED AND INSPECTED IN A ESTATED ABOVE. DEPTIMENT DETAILS O		MOMAT	12222	_
			w T /wil	1006 with new terminal b		Allun NO '	2307335 A&P	
								T
					T			-
			Page Total		All Repair Da	ta Must Bear t	he Endorsement of a	
			Brought Forward Total to Date	2 , 1 1	Certificated M	flechanic, and h Imber MUST be	nis Rating and	

ire	lies				ENGINE LOG	Se	erial No.	
	License Number	Date	Tin Hrs	ne Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	recula :	Signature	License Number
		M S E E TH AND S	IGNAT	OD AND/OR RETURE Gine C	PA28-180 CHANDLER MUNICIPAL 28-3786 CHANDLER, AZ XXXXXX (480) 732-9118 XXXXXX COMPONENT IDENTIFIED ABOVE WAS RETAINED AND INSPECTED IN ACCORDANCE WITH CURRENT FED IN TO SERVICE ON THE PAIR ARE ON FILE AT THE	TH. NO.2	2307335 A&P	
f a					Page Total Brought Forward Total to Date All Repair C Certificated Certificate	Data Must E I Mechanic, Number MU	Bear the Endorsement and his Rating and JST be Shown.	of a

Date		ne	REPAIRS - A	ADJUSTMENTS - SERVICE - R	FMARKS		Signature		License Number
	Hrs	Min	TEL ALIO						
	EG N		N9629J PA28-180	CHANDLER AVIATION CHANDLER MUNICIPA		DATE WO#	$\frac{03/21/23}{60145}$		
	/N		28-3786	CHANDLER, A		HOBBS	XXXXX	. –	
	NG M		XXXXXXX	(480) 732-91	.18	TACH	4571.8		
— TI	IE AIRCRAF	TAND/OR (OR RETUR	COMPONENT IDENTIFIED AND TO SERVICE ON THE DAT	BOVE WAS REPAIRED AND INSPECTED IN ACCORD	ANCE WITH CURRENT EPAIR ARE ON FILE A	TOTAL T FEDERAL AIR REGULA T THIS AGENCY.	ATIONS AND WAS FOUND		
S	IGNA'	TURE	Voul	se v	A	WTH. NO.2	2307335 A&P		
a	nd re-s	afety (oil filler tube. Gr	oil filter and install new. Servi round run and leak check sat	ce engine wi isfactory.	ith /qts of A/S	S 15W50. Tighten	_	
								ormania na karan d	
			Page Total		All Repair	Data Must B	ear the Endorseme	nt of a	
			Brought Forw	ard	Certificate	ed Mechanic,	and his Rating and ST be Shown.		
			Total to Date		Certificate	e iquiliber ivio.			

	T				Octiai 140.
Date	Hrs	me Min	REPAIRS - ADJUSTM	IENTS - SERVICE - REMARKS	Signature
	REG MOD S/N ENG	S NO DEL MOD	N9629J PA28-180 28-3786 XXXXXX	CHANDLER AVIATION INC LANDLER MUNICIPAL CHANDLER, AZ HOBB (480) 732-9118 TACH	03/21/23 60145 S XXXXX 4571.8
	SIG Repla	NATU	NOR COMPONENT IDENTIFIED ABOVE WAS ETURN TO SERVICE ON THE DATE STATE RE Stomer provided fuel ho	TOTA S REPAIRE D'AID AND REPETIN ACCORDANCE WITH CURRENT FEDERAL AIR RE D'ABOVE DE REPAIR ARE ON FILE AT THIS AGENCY. AUTH. No ses (reference Midstate Aerospace Inc & Strate - No discrepancies noted.	L XXXXX LGULATIONS AND WAS FOUND
			Page Total Brought Forward Total to Date	All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST	the Endorsement of a his Rating and

wo: 2023-2462



Sawyer MX, LLC - 14700 North Airport Drive, Suite 117 - Scottsdale, Arizona 85260 - (480) 922-5341

N9629J Lycoming, O&VO-360, S/N: L24027-36A

July 07, 2023

Engine fuel primer inop. Primer system was troubleshot, found two fuel primer plunger o-rings leaking. Removed and installed two new plunger o-rings, P/N: MS29513-012. Ops check good. All work performed in reference to Piper PA-28-180 AMM.

Jose Bandin Cert: A&P 3496042 Sign:

- 1 & ail

Date	REG NO	N9629J	CHANDLER AVIATION INC	DATE	09/18/23	Lic
	MODEL	PA-28-180	CHANDLER MUNICIPAL	WO#	60389	Nu
	s/N	28-3786	CHANDLER, AZ	HOBBS	XXXXXX	
	ENG MOD	0360A4A	(480) 732-9118	TACH	4586.8	_
	ENG S/N	L24027-36A		SMOH	833.4	_
	THE AIRCRAFT AND/OR AIRWORTHY FOR RETU	R COMPONENT IDENTIFIED ABOURN TO SERVICE ON ON THE DAY	IVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE A	FEDERAL AIR REGUL T THIS FACILITY.	ATIONS AND WAS FOUND	
	SIGNATURE	E/X/NC	AUTH.	NO.4719	954 A&P	_
	Drain engine	oil and collect sa	mple for analysis. Remove oil filter and o	ut open for v	visual inspection -	
	No defects no	oted Install oil filt	er and service engine with 7qts of A/S 15	W50 oil Cle	an gan tost and	
	140 delects in	rea, motan on mit	ci dila service engine with rats of 700 10	THOU OIL. OIC	all, yap, lest allu	
	rotate spark p	olugs, reinstall wit	th new gaskets. Perform cylinder compr	ession tests	: #1-78/80, #2-	_
	rotate spark p 74/80, #3-75/8	olugs, reinstall wit 30, and #4-78/80. In	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si	ession tests icone gaske	: #1-78/80, #2- ts on cylinders #1	_
	rotate spark p 74/80, #3-75/8 & #2. Wash ar	olugs, reinstall wit 0, and #4-78/80. In nd de-grease engi	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si ine, lube controls. Ground run and leak t	ession tests icone gaske est satisfact	: #1-78/80, #2- ts on cylinders #1 orv. I certify that	_
	rotate spark p 74/80, #3-75/8 & #2. Wash ar this engine ha	olugs, reinstall wit 0, and #4-78/80. In nd de-grease engi as been inspected	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si	ession tests icone gaske est satisfact	: #1-78/80, #2- ts on cylinders #1 orv. I certify that	
	rotate spark p 74/80, #3-75/8 & #2. Wash ar	olugs, reinstall wit 0, and #4-78/80. In nd de-grease engi as been inspected	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si ine, lube controls. Ground run and leak t	ession tests icone gaske est satisfact	: #1-78/80, #2- ts on cylinders #1 orv. I certify that	
	rotate spark p 74/80, #3-75/8 & #2. Wash ar this engine ha	olugs, reinstall wit 0, and #4-78/80. In nd de-grease engi as been inspected	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si ine, lube controls. Ground run and leak t	ession tests icone gaske est satisfact	: #1-78/80, #2- ts on cylinders #1 orv. I certify that	
	rotate spark p 74/80, #3-75/8 & #2. Wash ar this engine ha airworthy con	olugs, reinstall wit 80, and #4-78/80. In 1d de-grease engins 1d been inspected 1dition.	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si ine, lube controls. Ground run and leak t	ession tests icone gaske est satisfact	: #1-78/80, #2- ts on cylinders #1 orv. I certify that	
	rotate spark p 74/80, #3-75/8 & #2. Wash ar this engine ha airworthy con	olugs, reinstall wit 0, and #4-78/80. In nd de-grease engines as been inspected idition.	th new gaskets. Perform cylinder compressed new crankshaft seal. Install new sine, lube controls. Ground run and leak the in accordance with a 100hr Inspection and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls. Ground run and leak the interval of the seal. Install new sine, lube controls are seal. Instal	ession tests icone gaske est satisfact and was dete	ts on cylinders #1 ory. I certify that ermined to be in	
	rotate spark p 74/80, #3-75/8 & #2. Wash ar this engine ha airworthy con	olugs, reinstall wit 80, and #4-78/80. In 1d de-grease engins 1d been inspected 1dition.	th new gaskets. Perform cylinder compr nstall new crankshaft seal. Install new si ine, lube controls. Ground run and leak t d in accordance with a 100hr Inspection a	ession tests icone gaske est satisfact and was dete	ts on cylinders #1 ory. I certify that ermined to be in	

Flite Instruments and Avionics

4927 E. Falcon Drive

Mesa, AZ 85215

CRS# 6FIR926C

480-516-0308

	,		S/N	Ta\dh/Hobb
9629	Prope	1928/80	3786	

I certify that the Static, Altimeter and transponder tests, including date a correspondence required by § 91.411 & 91.413, have been performent and found to comply with 14 CFR part 43, appendix E & F. Altitude;

Work performed by:


med by:

Inspected by: ___

Date: ZV/L

Work Order# _____

wo: MO_1714		AcroMeph	Engine Squawk · page 1 of 1
	Aeromech · 6799 N Glen Harbo	or Blvd · Glendale, AZ 85307 · 6238	8779334
N9629J TACH: 4705.8	38		May 29, 2024
Phillips 100AW AA48110-2 - T	e oil replaced oil filter with new, oil san / using Piper M/M and standard main empest Oil Filter, Installed P/N AAOA led (8) P/N 08-13850-1 - Phillips 100A	tenance practices. Leak and o P-PPD - Advanced Oil Analys	ops check good. Installed P/N
	the work performed, this engine squaresco A&P4813355	wk is approved for return to ser	rvice.
	Page Total Brought Forward	Certificated Mechan	t Bear the Endorsement of a ic, and his Rating and
	Total to Date	Certificate Number I	MUST be Shown.



Date	Hrs Min	REPAIRS - ADJUST	TMENTS - SERVICE - REMARKS		Signature	Licen Numb
	REG NO	N9629J	CHANDLER AVIATION INC	DATE	06/18/24	_
	MODEL	PA-28-180	CHANDLER MUNICIPAL	WO#	70169	
	s/n	28-3786	CHANDLER, AZ	HOBBS	XXXXX	
	ENG MOD	0360A4A	(480) 732-9118	TACH	4722.67	
	ENG S/N	L24027-36A		SMOH	XXXXXX	
	THE AIRCRAFT AND/ AIRWORTHY FOR RE	OR COMPONENT IDENTIFIED ABOTURN TO SERVICE ON THE DATE	OYEWAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE A	FEDERAL AIR REGU T THIS AGENCY.	LATIONS AND WAS FOUND	
	SIGNATUR		/ /		954 A&P	_
	Install new cr	ankshaft seal. Ops a	nd leak check satisfactory.			
	- 					
		ge Total	All Repair Data Mo	ist Rear the	Endoron	
	Bro	ge Total ought Forward	All Repair Data Mc Certificated Mecha Certificate Number	nic, and his	Rating and	

Serial No.	
------------	--

Date	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
		SWAZAVIATION		

ENGINE MAINTENANCE ENTRY

Model: Lycoming O-360-A4A Serial Number: N9629J

Tach Time: 4636.72

1. Drained engine oil, removed oil filter, cut open filter, no abnormalities found, installed new oil filter, serviced engine with 7qts of Phillips XC 20W-50

All work done IAW Piper PA28-180 AMM and Lycoming O-360-A4A overhaul manual. This aircraft is returned to service only for the work described above ------ End ----- End -----

Print Name: Zachary Spisak Signature:

Cert#: AP3970228IA Date: 2/2/2024

. 1				
		Page Total	All Repair Data Must Bear the Endorsement of a	
T		Brought Forward	Certificated Mechanic, and his Rating and	
		Total to Date	Certificate Number MUST be Shown.	