










## AD Compliance Report

Airframe - Cirrus - SR22 3405  
 Engine - Continental Motors - IO-550-N 692109  
 Propeller - Hartzell - PHC-J3Y1F NJ41B  
 Appliance - Magnetos - TCM (formerly Bendix) S-600 series L/H:D16FA043R  
 R/H:D16FA045R


| AD #                   | Subject  | Date and Hours at Compliance | Recurring Yes/No  | Next Due Date/Hours |
|------------------------|--|------------------------------|---|---------------------|
| 2001-25-03             | Detect and replace understrength rivets in the elevator and rudder                 |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22   | <b>Category:</b>             | Airframe  |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22   | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 12/17/2001   | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A  | <b>Authorized Sign.:</b>     |    |                     |
| <b>Superseded By:</b>  | N/A  |                              |   |                     |
| <b>Compliance:</b>     | N/A BY S/N   |                              |   |                     |
| <b>Notes:</b>          |  |                              |   |                     |
| 2002-05-05             | Limit the chance of failure of the CAPS activation system                          |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22   | <b>Category:</b>             | Airframe  |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22   | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 03/19/2002   | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A  | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | 2002-24-08   |                              |   |                     |
| <b>Compliance:</b>     | SUPERSEDED   |                              |   |                     |
| <b>Notes:</b>          |  |                              |   |                     |
| 2002-21-02             | Prevent loss of the self-locking retaining nut on the roll and yaw trim cartridges |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22   | <b>Category:</b>             | Airframe  |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22   | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 11/08/2002   | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A  | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A  |                              |   |                     |
| <b>Compliance:</b>     | N/A BY S/N   |                              |   |                     |
| <b>Notes:</b>          |  |                              |   |                     |
| 2002-24-08             | Prevent failure of the CAPS activation system in an emergency situation            |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22   | <b>Category:</b>             | Airframe  |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22   | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 01/24/2003   | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | 2002-05-05   | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A  |                              |   |                     |
| <b>Compliance:</b>     | N/A BY S/N   |                              |   |                     |
| <b>Notes:</b>          |  |                              |   |                     |

| AD #                   | Subject   | N770MM | Date and Hours at Compliance | Recurring Yes/No  | Next Due Date/Hours |
|------------------------|---|--------|------------------------------|---|---------------------|
| 2005-17-19             | Prevent the crew seats from folding forward during emergency landing    |        |                              | No  | 10/31/2017          |
| <b>Description:</b>    | Airframe - Cirrus - SR22  |        |                              |   |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22  |        | <b>Category:</b>             | Airframe  |                     |
| <b>Effective Date:</b> | 10/13/2005  |        | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Supersedes:</b>     | N/A   |        | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Superseded By:</b>  | 2006-19-10  |        | <b>Authorized Sign.:</b>     |    |                     |
| <b>Compliance:</b>     | SUPERSEDED  |        |                              |   |                     |
| <b>Notes:</b>          |   |        |                              |   |                     |
| 2006-07-06             | To detect, correct, and prevent damage to the fuel line and wire        |        |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22  |        |                              |   |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22  |        | <b>Category:</b>             | Airframe  |                     |
| <b>Effective Date:</b> | 05/11/2006  |        | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Supersedes:</b>     | N/A   |        | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Superseded By:</b>  | N/A   |        | <b>Authorized Sign.:</b>     |    |                     |
| <b>Compliance:</b>     | N/A BY S/N  |        |                              |   |                     |
| <b>Notes:</b>          |   |        |                              |   |                     |
| 2006-19-10             | To prevent the crew seats from folding forward during emergency landing |        |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22  |        |                              |   |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22  |        | <b>Category:</b>             | Airframe  |                     |
| <b>Effective Date:</b> | 10/24/2006  |        | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Supersedes:</b>     | 2005-17-19  |        | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Superseded By:</b>  | N/A   |        | <b>Authorized Sign.:</b>     |  |                     |
| <b>Compliance:</b>     | N/A BY S/N  |        |                              |   |                     |
| <b>Notes:</b>          |   |        |                              |   |                     |
| 2006-21-03             | Prevent overheating damage to the brake caliper piston O-ring seals     |        |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22  |        |                              |   |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22  |        | <b>Category:</b>             | Airframe  |                     |
| <b>Effective Date:</b> | 11/17/2006  |        | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Supersedes:</b>     | N/A   |        | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Superseded By:</b>  | N/A   |        | <b>Authorized Sign.:</b>     |  |                     |
| <b>Compliance:</b>     | N/A BY S/N  |        |                              |   |                     |
| <b>Notes:</b>          |   |        |                              |   |                     |
| 2007-14-03             | To correct pick-up collar support fasteners of the CAPS                 |        |                              | No  |                     |
| <b>Description:</b>    | Airframe - Cirrus - SR22  |        |                              |   |                     |
| <b>Component:</b>      | Airframe - Cirrus - SR22  |        | <b>Category:</b>             | Airframe  |                     |
| <b>Effective Date:</b> | 08/16/2007  |        | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Supersedes:</b>     | N/A   |        | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Superseded By:</b>  | N/A   |        | <b>Authorized Sign.:</b>     |  |                     |
| <b>Compliance:</b>     | N/A BY S/N  |        |                              |   |                     |
| <b>Notes:</b>          |   |        |                              |   |                     |

**2007-24-13** To prevent moisture from accumulating along the wing shear web where it may freeze in certain conditions

**Date and Hours at Compliance:** \_\_\_\_\_  
**Recurring Yes/No:** No  
**Next Due Date/Hours:** \_\_\_\_\_


**Description:** Airframe - Cirrus - SR22  
**Component:** Airframe - Cirrus - SR22  
**Effective Date:** 12/04/2007  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Category:** Airframe  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 

**2008-03-16** To prevent the possibility of jamming of the rudder-aileron interconnect system

**Date and Hours at Compliance:** \_\_\_\_\_  
**Recurring Yes/No:** No  
**Next Due Date/Hours:** \_\_\_\_\_


**Description:** Airframe - Cirrus - SR22  
**Component:** Airframe - Cirrus - SR22  
**Effective Date:** 03/11/2008  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Category:** Airframe  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 

**2008-14-13** To prevent in-flight failure of the cabin door

**Date and Hours at Compliance:** \_\_\_\_\_  
**Recurring Yes/No:** No  
**Next Due Date/Hours:** \_\_\_\_\_


**Description:** Airframe - Cirrus - SR22  
**Component:** Airframe - Cirrus - SR22  
**Effective Date:** 08/14/2008  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Category:** Airframe  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 

**2009-26-01** To detect and correct anti-ice fluid distribution lines with improperly installed compression fittings

**Date and Hours at Compliance:** \_\_\_\_\_  
**Recurring Yes/No:** No  
**Next Due Date/Hours:** \_\_\_\_\_


**Description:** Airframe - Cirrus - SR22  
**Component:** Airframe - Cirrus - SR22  
**Effective Date:** 12/21/2009  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Category:** Airframe  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 


**73-07-04** Bendix Magnetos

**Date and Hours at Compliance:** \_\_\_\_\_  
**Recurring Yes/No:** No  
**Next Due Date/Hours:** \_\_\_\_\_


**Description:** Airframe - Cirrus - SR22  
**Component:** Airframe - Cirrus - SR22  
**Effective Date:** 10/11/1973  
**Supersedes:** N/A  
**Superseded By:** 94-01-03 R2  
**Compliance:** SUPERSEDED  
**Notes:**

**Category:** Airframe  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 


**94-01-03 R2** Teledyne/Bendix magnetos  
**Description:** Appliance - Magnetos - TCM (formerly Bendix) S-600 series  
**Component:** Appliance - Magnetos - TCM (formerly Bendix) S-600 series  
**Effective Date:** 06/28/1995  
**Supersedes:** 73-07-04  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Date and Hours at Compliance:**  
**Recurring Yes/No:** No  
**Next Due Date/Hours:**  
**Category:** Appliance  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 


**88-03-06** Oil filter  
**Description:** Engine - Continental Motors - IO-550-N  
**Component:** Engine - Continental Motors - IO-550-N  
**Effective Date:** 02/05/1988  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A by P/N  
**Notes:**

**Date and Hours at Compliance:**  
**Recurring Yes/No:** No  
**Next Due Date/Hours:**  
**Category:** Engine  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 


**91-19-03** Champion oil filter  
**Description:** Engine - Continental Motors - IO-550-N  
**Component:** Engine - Continental Motors - IO-550-N  
**Effective Date:** 09/29/1991  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY DATE OF MANUFACTURE  
**Notes:**

**Date and Hours at Compliance:**  
**Recurring Yes/No:** No  
**Next Due Date/Hours:**  
**Category:** Engine  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 

**93-08-17** Incorrect oil pick-up tube  
**Description:** Engine - Continental Motors - IO-550-N  
**Component:** Engine - Continental Motors - IO-550-N  
**Effective Date:** 08/23/1993  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Date and Hours at Compliance:**  
**Recurring Yes/No:** No  
**Next Due Date/Hours:**  
**Category:** Engine  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 

**93-10-02** Cylinder valve retainer  
**Description:** Engine - Continental Motors - IO-550-N  
**Component:** Engine - Continental Motors - IO-550-N  
**Effective Date:** 05/17/1993  
**Supersedes:** N/A  
**Superseded By:** N/A  
**Compliance:** N/A BY S/N  
**Notes:**

**Date and Hours at Compliance:**  
**Recurring Yes/No:** No  
**Next Due Date/Hours:**  
**Category:** Engine  
**Mechanic name:** Daniel P Monahan  
**Certificate #:** AP32484081A  
**Authorized Sign.:** 

N770MM


10/31/2017

| AD #                   | Subject   | Date and Hours at Compliance | Recurring Yes/No  | Next Due Date/Hours |
|------------------------|---|------------------------------|---|---------------------|
| PL99-09-17             | Crankshaft failure                                |                              | No  |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N            | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N            | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | Upon Receipt                                      | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |    |                     |
| <b>Superseded By:</b>  | 99-19-01  |                              |   |                     |
| <b>Compliance:</b>     | SUPERSEDED  |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 99-19-01               | Crankshaft failure                                |                              | No  |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N            | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N            | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 09/30/1999  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | PL99-09-17  | <b>Authorized Sign.:</b>     |    |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A BY DATE OF MANUFACTURE                        |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| PL2000-08-51           | Crankshaft connecting rod journal fracture        |                              | Yes   |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N            | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N            | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | Upon Receipt                                      | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | 2000-23-21  |                              |   |                     |
| <b>Compliance:</b>     | SUPERSEDED  |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2000-23-21             | Fracture of the crankshaft connecting rod journal |                              | No  |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N            | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N            | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 12/12/2000  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | PL2000-08-51                                      | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A BY DATE OF MANUFACTURE                        |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2004-08-10             | Prevent loss of engine power                      |                              | No  |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N            | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N            | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 05/05/2004  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A NOT INSTALLED                                 |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |

at Compliance Yes/No Date/Hours  
No

2007-16-10 To prevent the turbine rotor from separating from the shaft of the turbocharger due to a machining defect in the turbocharger compressor


Description: Engine - Continental Motors - IO-550-N  
Component: Engine - Continental Motors - IO-550-N  
Effective Date: 08/23/2007  
Supersedes: N/A  
Superseded By: N/A  
Compliance: N/A BY TURBOCHARGER S/N  
Notes:

Category: Engine  
Mechanic name: Daniel P Monahan  
Certificate #: AP32484081A  
Authorized Sign.: 

2009-16-03 To prevent the separation of the cylinder head

Yes


Description: Engine - Continental Motors - IO-550-N  
Component: Engine - Continental Motors - IO-550-N  
Effective Date: 09/09/2009  
Supersedes: N/A  
Superseded By: 2014-05-29  
Compliance: SUPERSEDED  
Notes:

Category: Engine  
Mechanic name: Daniel P Monahan  
Certificate #: AP32484081A  
Authorized Sign.: 

2009-24-52 To address rapid wear on the face of hydraulic lifters

Yes


Description: Engine - Continental Motors - IO-550-N  
Component: Engine - Continental Motors - IO-550-N  
Effective Date: Upon Receipt  
Supersedes: 2009-24-51  
Superseded By: 2010-11-04  
Compliance: SUPERSEDED  
Notes:

Category: Engine  
Mechanic name: Daniel P Monahan  
Certificate #: AP32484081A  
Authorized Sign.: 

2010-11-04 To prevent excessive hydraulic lifter wear

Yes


Description: Engine - Continental Motors - IO-550-N  
Component: Engine - Continental Motors - IO-550-N  
Effective Date: 06/16/2010  
Supersedes: 2009-24-52  
Superseded By: N/A  
Compliance: N/A NO LIFTERS HAVE BEEN REPLACED AFTER JUNE 2008  
Notes:






Category: Engine  
Mechanic name: Daniel P Monahan  
Certificate #: AP32484081A  
Authorized Sign.: 

2011-25-51 To address fractures in starter adapter shaft gears

No






Description: Engine - Continental Motors - IO-550-N  
Component: Engine - Continental Motors - IO-550-N  
Effective Date: 12/28/2011  
Supersedes: N/A  
Superseded By: 2012-10-13  
Compliance: SUPERSEDED  
Notes:

Category: Engine  
Mechanic name: Daniel P Monahan  
Certificate #: AP32484081A  
Authorized Sign.: 

| AD #                   | Subject   | Date and Hours at Compliance | Recurring Yes/No  | Next Due Date/Hours |
|------------------------|---|------------------------------|---|---------------------|
| 2012-03-06             | To prevent an in-flight shutdown due to a failed fuel servo diaphragm |                              |   | 10/31/2017          |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N                                |                              | Yes   |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N                                | <b>Category:</b>             |   | Engine              |
| <b>Effective Date:</b> | 02/24/2012  | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Supersedes:</b>     | 2011-15-10  | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Superseded By:</b>  | N/A   | <b>Authorized Sign.:</b>     |    |                     |
| <b>Compliance:</b>     | N/A NOT INSTALLED   |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2012-10-13             | To prevent starter adapter gear shaft failure                         |                              | Yes   |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N                                | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N                                | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 6/8/2012  | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Supersedes:</b>     | 2011-25-51  | <b>Authorized Sign.:</b>     |    |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A BY HOURS ON STARTER DRIVE   |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2014-05-29             | Superior Air Parts Investment Cast Cylinder Assemblies                |                              | Yes   |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N                                | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N                                | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 04/25/2014  | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Supersedes:</b>     | 2009-16-03  | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A NOT INSTALLED   |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2016-16-12             | ECI Class 71 or Class 76 Cylinder Assembly Failures                   | 10/03/2016<br>FLT:1168.9     | No  |                     |
| <b>Description:</b>    | Engine - Continental Motors - IO-550-N                                | <b>Category:</b>             | Engine  |                     |
| <b>Component:</b>      | Engine - Continental Motors - IO-550-N                                | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 09/15/2016  | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A NOT INSTALLED   |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 77-12-06 R2            | Prop blade  |                              | Yes   |                     |
| <b>Description:</b>    | Propeller - Hartzell - PHC-J3Y1F                                      | <b>Category:</b>             | Propeller   |                     |
| <b>Component:</b>      | Propeller - Hartzell - PHC-J3Y1F                                      | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 11/10/1977  | <b>Certificate #:</b>        | AP32484081A   |                     |
| <b>Supersedes:</b>     | 70-16-03, 73-10-03, 74-15-02, 75-07-05                                | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | 2002-09-08  |                              |   |                     |
| <b>Compliance:</b>     | SUPERSEDED  |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |

N770MM

10/31/2017

| AD #                   | Subject   | Date and Hours at Compliance | Recurring Yes/No  | Next Due Date/Hours |
|------------------------|---|------------------------------|---|---------------------|
| 2001-07-03             | CORRECTION - Prevent propeller failure of the propellers returned to service by BASCO   |                              | No  |                     |
| <b>Description:</b>    | Propeller - Hartzell - PHC-J3Y1F  | <b>Category:</b>             | Propeller   |                     |
| <b>Component:</b>      | Propeller - Hartzell - PHC-J3Y1F  | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 06/04/2001  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |    |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A BY S/N  |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2002-09-08             | Prevent failure of the propeller blade from fatigue cracks                              |                              | No  |                     |
| <b>Description:</b>    | Propeller - Hartzell - PHC-J3Y1F  | <b>Category:</b>             | Propeller   |                     |
| <b>Component:</b>      | Propeller - Hartzell - PHC-J3Y1F  | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 06/13/2002  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | 77-12-06 R2   | <b>Authorized Sign.:</b>     |    |                     |
| <b>Superseded By:</b>  | 2007-26-09  |                              |   |                     |
| <b>Compliance:</b>     | SUPERSEDED  |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2003-13-17             | Maintenance by T&W Propellers Inc.  |                              | No  |                     |
| <b>Description:</b>    | Propeller - Hartzell - PHC-J3Y1F  | <b>Category:</b>             | Propeller   |                     |
| <b>Component:</b>      | Propeller - Hartzell - PHC-J3Y1F  | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 7/18/2003   | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A NOT WORKED ON BY T7W PRPOELLER SERVICES   |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2005-14-11             | Maintenance by Southern California Propeller Service                                    |                              | No  |                     |
| <b>Description:</b>    | Propeller - Hartzell - PHC-J3Y1F  | <b>Category:</b>             | Propeller   |                     |
| <b>Component:</b>      | Propeller - Hartzell - PHC-J3Y1F  | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 08/17/2005  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | N/A   | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A NOT WORKED ON BY SoCal SERVICES   |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |
| 2007-26-09             | To prevent failure of the propeller blade from fatigue cracks in the blade shank radius |                              | No  |                     |
| <b>Description:</b>    | Propeller - Hartzell - PHC-J3Y1F  | <b>Category:</b>             | Propeller   |                     |
| <b>Component:</b>      | Propeller - Hartzell - PHC-J3Y1F  | <b>Mechanic name:</b>        | Daniel P Monahan  |                     |
| <b>Effective Date:</b> | 01/30/2008  | <b>Certificate #:</b>        | AP3248408IA   |                     |
| <b>Supersedes:</b>     | 2002-09-08  | <b>Authorized Sign.:</b>     |  |                     |
| <b>Superseded By:</b>  | N/A   |                              |   |                     |
| <b>Compliance:</b>     | N/A BY BLADE S/N  |                              |   |                     |
| <b>Notes:</b>          |   |                              |   |                     |