

N65TY Maintenance Status as of 9-13-2018 and 1398 flight hours

Next annual due by 10/01/2019

50 hour oil change due at 1448 flight time or 04/1/2019

300 hour fuel injector nozzle cleaning due 1699 flight time

500 hr magneto inspection due at 1613 flight time

24 month IFR recertification due by 8/1/2020

5 year oxygen bottle hydrostatic test was due 06/30/2014, but may be deferred until empty. Bottle cannot be refilled until after a new 5 year test is performed.

ELT batteries due by 12/1/2025

TKS filter 24 month expiration 8/31/2019

Alternator 2 batteries expiration 8/31/2019

Main battery 3 year recommended replacement 07/31/2019

CAPS reefing line cutters replacement due by 04/30/2023

CAPS parachute overhaul due by 08/31/2025

Spare parts:

Oil filter PN 48108-1, or 48109-1 (long version)

Air filter PN BA-24

Brake linings PN 066-10500, or RA66-105

Alternator 2 batteries PN NP7-12T

Service Bulletins

Compliance Date / Hobbs

AUTO FLIGHT

SB2X-22-06

Autopilot Disconnect

Apr. 09, 2007

Orig

Optional

0002 - 2042

Excluding: 2037

SB2X-22-03R1

Avidyne® Flight Director Installation

Feb. 22, 2006

Rev 1

Optional

0435 and subsequent.

COMMUNICATIONS

SB2X-23-05R1

Garmin GDL 88 UAT/ADS-B Transceiver Installation

Feb. 26, 2018

Rev 1

Optional

0002 - 4434

SB2X-23-04

Optional Modifications to Dissipate P-Static

Jun. 16, 2015

Orig

Optional

0002 - 2437

Excluding: 2334, 2420

DOORS

SB2X-52-08R2

Catcher/Diverter and Gas Strut Rod End Replacement

Apr. 22, 2016

Rev 2

Mandatory

0002 - 4317

Excluding: 4311

SB2X-52-07R4

Cabin Door Rod End Replacement

Jan. 24, 2008

Rev 4

Mandatory

0795 - 2912

Compliance Date / Hobbs

Airframe Log entry 07/02/2016 Hobbs 1,112.4

Airframe Log entry 05/28/2008 Hobbs 397.7

Service Bulletins

Compliance Date / Hobbs

AUTO FLIGHT

SB2X-22-06

Autopilot Disconnect

Apr. 09, 2007

Orig

Optional

0002 - 2042

Excluding: 2037

SB2X-22-03R1

Avidyne® Flight Director Installation

Feb. 22, 2006

Rev 1

Optional

0435 and subsequent.

COMMUNICATIONS

SB2X-23-05R1

Garmin GDL 88 UAT/ADS-B Transceiver Installation

Feb. 26, 2018

Rev 1

Optional

0002 - 4434

SB2X-23-04

Optional Modifications to Dissipate P-Static

Jun. 16, 2015

Orig

Optional

0002 - 2437

Excluding: 2334, 2420

DOORS

Compliance Date / Hobbs

SB2X-52-08R2

Catcher/Diverter and Gas Strut Rod End Replacement

Apr. 22, 2016

Rev 2

Mandatory

0002 - 4317

Excluding: 4311

SB2X-52-07R4

Cabin Door Rod End Replacement

Jan. 24, 2008

Rev 4

Mandatory

0795 - 2912

Airframe Log entry 05/28/2008 Hobbs 397.7

Airframe Log entry 07/02/2016 Hobbs 1,112.4

Excluding: 0796, 0797, 0798, 0799, 0800, 0801, 0802, 0803, 0804, 0806, 0806,
0807, 0808, 0809, 0810, 0811, 0812, 0813, 0814, 0815, 0816, 0817, 0818, 0819

ELECTRICAL POWER

SB2X-24-09

TVS Fuse Installation

Feb. 21, 2011

Orig

Recommended

0002 - 2979

Compliance Date / Hobbs

Airframe logbook date: 06/06/2012 Hobbs 619.7

SB2X-24-06

SR22 Wiring and Alternator Inspection

Sep. 08, 2006

Orig

Recommended

0002 - 2003

Excluding: 1602, 1840

Compliance Date / Hobbs

Airframe logbook date: 06/06/2012 Hobbs 619.7

ENGINE INDICATING

SB2X-77-04R1

MAP / Oil Pressure Sensor Replacement

May. 08, 2013

Rev 1

Recommended

0002 - 3849

SB2X-77-02R2

Engine Sensor Modification

Jun. 16, 2009

Rev 2

Optional

0002 - 1662

Excluding: 1602, 1644

SB22-77-01R4

Avidyne Engine Instrument Kit

Feb. 22, 2006

Rev 4

Optional

0002 and subsequent.

ENVIRONMENTAL SYSTEMS

No results found in this category.

EQUIPMENT & FURNISHINGS

SB2X-25-18

Installation of the Artex ME406 Emergency Locator

Aug. 16, 2007

Orig

Optional
0002 and subsequent.

SB2X-25-19

Inflatable Restraint Harness Inspection

May. 24, 2007

Orig

Recommended

0795 - 2407

SB2X-25-14

Crew Seat Inflatable Restraint Installation

Aug. 25, 2006

Orig

Optional

0795 - 1519

Excluding: 0796, 0797, 0798, 0799, 0800, 0801, 0802, 0803, 0804, 0805, 0806,
0807, 0808, 0809, 0810, 0811, 0812, 0813, 0814, 0815, 0816, 0817, 0818, 0819,

SB2X-25-17R1

Crew Seat Break-Over Pin Replacement

Jan. 20, 2006

Rev 1

Mandatory

0002 - 1727

Compliance Date / Hobbs

Airframe Logbook 08/03/2007 Hobbs 333.2

EXHAUST

No results found in this category.

FLIGHT CONTROLS

SB2X-27-17

Electronic Flap Relay Installation

Jun. 03, 2013

Orig

Optional

0002 - 3881

SB2X-27-10R2

Rudder Pedal Extension

Feb. 25, 2013

Rev 2

Optional

0119 and subsequent.

SB2X-27-16R2

Modification to Prevent Possible Asymmetric Flap
and Flap Actuator

Jan. 23, 2013

Rev 2

Mandatory

0002 - 3766

Compliance Date / Hobbs

Airframe logbook 06/06/2012 619.7

SB2X-27-15

Stall Horn Replacement

May. 12, 2009

Orig

Optional
0002 and subsequent.

SB2X-27-14R3

Rudder-Aileron Interconnect Modification

Oct. 10, 2007

Rev 3

Mandatory

0002 - 2437

Excluding: 2334, 2420

Compliance Date / Hobbs

Airframe logbook 05/28/2008 397.7

SB2X-27-12R1

Flight Control System Freeplay

Oct. 28, 2005

Rev 1

Optional

0002 - 1564

FUEL

SB2X-28-12R1

Electric Fuel Pump Inspection

Aug. 19, 2015

Rev 1

Mandatory

0002 - 4225

Excluding: 4222, 4224

Compliance Date / Hobbs

Airframe logbook dated 07/02/16 Hobbs 1,112.4

Note: Electric Boost Pump Replaced 07/16/16

SB2X-28-05R2

Hot Climate Start

Sep. 18, 2006

Rev 2

SB2X-32-14R2

Main Landing Gear Fairing Modification for Inspection

Apr. 24, 2015

Rev 2

Mandatory

0002 - 1727

Compliance Date / Hobbs

Airframe logbook

SB2X-32-14R1 Complied 08/03/20017 Hobbs 333.7

SB2X-32-19R3

Nose Landing Gear Assembly Inspection and

Jun. 28, 2012

Rev 3

Mandatory

0002 - 3612

Compliance Date / Hobbs

Airframe Logbook 06/23/2010 Hobbs 524.3

SB2X-71-12R2

SR22 Induction Duct Support Bracket Removal

Sep. 07, 2006

Rev 2

Mandatory

0686 - 1818

Compliance Date / Hobbs

Airframe logbook 08/03/2007 Hobbs 333.2

SB2X-61-03

Compliance Date / Hobbs

Propeller Hub Torque Inspection

Aug. 22, 2005

Orig

Mandatory

1307 - 1537

Propeller Logbook Date 09/26/2007 Hobbs 337.4

SB2X-61-02R1

Propeller Spinner Assembly Torque Inspection

Aug. 22, 2005

Rev 1

Mandatory

0975 - 1519

Compliance Date / Hobbs

Propeller Logbook Date 09/26/2007 Hobbs 337.4

SPECIAL PURPOSE EQUIPMENT

SB2X-95-23R1

CAPS Aft Grain Replacement

Apr. 06, 2018

Rev 1

Mandatory

0821 - 4336

SB2X-95-22R2

CAPS Aft Grain Replacement

Apr. 06, 2018

Rev 2

Mandatory

0002 - 3914

SB2X-95-24R1

CAPS Rocket Shelf Ground Wire

Nov. 06, 2017

Rev 1

Mandatory

0002 - 4523

SB2X-95-18R4

CAPS Rocket Motor Assembly Replacement

Aug. 31, 2017

Rev 4

Mandatory

0821 and subsequent.

SBA2X-95-10R3

CAPS Pick-up Collar Support Replacement

Mar. 28, 2013

Rev 3

Mandatory

0002 - 2437

Compliance Date / Hobbs

Airframe Logbook 05/28/2008 Hobbs 397.7

SB2X-95-13

CAPS Strap Inspection And Grommet Installation

Nov. 30, 2010

Orig

Mandatory

0002 - 2380

SB2X-95-12

CAPS CMM Line Cutters Rigging Illustration Error

Apr. 09, 2010

Orig

Mandatory

0002 and subsequent.

SB2X-95-11R1

Aft Tie Down Ballast Installation

Jul. 02, 2008

Rev 1

Optional

0820 and subsequent.

SB2X-95-09R1

CAPS Strap Abrasion Inspection

Apr. 10, 2007

Rev 1

Mandatory

0002 - 2250

STABILIZERS

SB2X-55-12R1

Upper Rudder Hinge Replacement

Aug. 17, 2016

Rev 1

Optional

0002 - 4145

Excluding: 4131

STANDARD PRACTICES-STRUCTURES

SB2X-51-03

Flap Hinge Edge Protective Tape Installation

Aug. 12, 2008

Orig

Optional

0002 - 2437

Excluding: 2334, 2420

TIME LIMITS & MAINTENANCE CHECKS

SB2X-05-02

Induction Duct Flapper Bolt Replacement Interval

Jun. 26, 2012

Orig

Mandatory

0686 and subsequent.

Compliance Date / Hobbs

Airframe logbook date 06/25/2013 Hobbs 676.1

SB2X-05-01

Overhaul and Replacement Schedule - Brake

Assembly O-Ring Replacement Interval

Mar. 11, 2009

Orig

Optional

0002 - 3450

Compliance Date / Hobbs

Airframe logbook date 06/21/2010 Hoobs 529.3

WINGS

SB2X-57-07R1

Aft Wing Attach Fitting Torque Inspection

Dec. 13, 2005

Rev 1

Mandatory

1300 - 1519

Excluding: 1500

Compliance Date / Hobbs

Airframe logbook date 08/03/2007 Hobbs 333.2

SB2X-57-06R1

Flap Hinge Fairing Replacement

Oct. 06, 2005

Rev 1

Optional

0002 - 1519

Compliance Date / Hobbs

Airframe logbook date 08/03/2007 Hobbs 333.2

Airworthiness Directive Compliance Record

AIRCRAFT RECORDS - DO NOT DESTROY engine

Company
Manufacturer TELEDYNE CONTINENTAL MOTORS
Model IO-550 SERIES
Location Center
Serial # 917692
TSMOH
Total Time 1112.4

07-04-19 R1	05/07/07	SUPERIOR AIR PARTS, INC. CAST CYLINDER ASSEMBLIES/	
Method of Compliance	N/A		
SB #		Date	Next Due
Signature			Cert. #
07-16-10	08/23/07	TURBOCHARGER COMPRESSOR ROTOR/	
Method of Compliance	N/A		
SB #		Date	Next Due
Signature			Cert. #
*09-19-07	10/07/09	EQ3 CYLINDER HEAD ASSEMBLIES/	
Method of Compliance	N/A		
SB #		Date	Next Due
Signature			Cert. #
10-11-04	06/16/10	HYDRAULIC VALVE LIFTERS/	
Method of Compliance	N/A		
SB #		Date	Next Due
Signature			Cert. #
12-03-06	02/24/12	AFS FUEL SERVO DIAPHRAGM/	
Method of Compliance	C/W by inspection		
SB #		Date	Next Due
Signature			Cert. #
12-10-13	06/08/12	STARTER ADAPTER SHAFT GEAR/	
Method of Compliance	N/A		
SB #		Date	Next Due
Signature			Cert. #
*14-05-29	04/25/14	SUPERIOR AIR PARTS INVESTMENT CAST CYLINDER ASSEMBLIES/	
Method of Compliance	N/A		
SB #		Date	Next Due
Signature			Cert. #

Prepared by J. Masters 2802663IA Date July 2, 2016

Airworthiness Directive Compliance Record

AIRCRAFT RECORDS - DO NOT DESTROY **airframe**

Company
Manufacturer CIRRUS DESIGN CORPORATION
Model SR22
Tail # N65TY
Serial # 1452
Current Time 1112.4
Total Time
A/C Cert. Date

06-07-06	05/11/06	FUEL LINE AND WIRING HARNESS IN CONSOLE/
Method of Compliance	P/C/W	
SB #		
Signature		
	Date	Next Due Cert. #
06-19-10	10/24/06	CREW SEAT BREAK-OVER BOLT AND RECLINE LOCKS/
Method of Compliance	P/C/W	
SB #		
Signature		
	Date	Next Due Cert. #
06-21-03	11/17/06	POH, BRAKE CALIPER OVERHEATING DAMAGE/
Method of Compliance	P/C/W	
SB #		
Signature		
	Date	Next Due Cert. #
07-14-03	08/16/07	PARACHUTE SYSTEM PICK-UP COLLAR SUPPORT AND SCREWS/
Method of Compliance	P/C/W	
SB #		
Signature		
	Date	Next Due Cert. #
07-24-13	12/04/07	WING TIP TO WING STRUCTURE INTERFACE MOISTURE ACCUMULATION/
Method of Compliance	N/A	
SB #		
Signature		
	Date	Next Due Cert. #
08-03-16	03/11/08	RUDDER-AILERON INTERCONNECT RIGGING/
Method of Compliance	P/C/W	
SB #		
Signature		
	Date	Next Due Cert. #
08-14-13	08/14/08	CABIN DOOR ROD ENDS AND HINGE PIN/
Method of Compliance	P/C/W	
SB #		
Signature		
	Date	Next Due Cert. #
09-26-01	12/21/09	ANTI-ICE FLUID DISTRIBUTION LINE COMPRESSION FITTINGS/
Method of Compliance	N/A	
SB #		
Signature		
	Date	Next Due Cert. #

Prepared by Tim Masters 2802603JA Date JULY 2, 2016

Airworthiness Directive Compliance Record

AIRCRAFT RECORDS - DO NOT DESTROY **propeller**

Company
Manufacturer HARTZELL
Model PHC-J3Y SERIES
Location Front
Tail # N65TY
Serial # FP3628B
Blade
TSMOH
Total Time 1112.4

05-14-11	08/17/05	MAINTENANCE AND REPAIR BY SOUTHERN CALIFORNIA
PROPELLER SERVICE/		
Method of Compliance	N/A	
SB #		Date
Signature		Next Due Cert. #
07-26-09	01/30/08	PLACARD, PROPELLER BLADE SHANK REWORK/
Method of Compliance	N/A	
SB #		Date
Signature		Next Due Cert. #
*08-13-28	07/17/08	PROPELLER HUB LUBRICATION HOLES/
Method of Compliance	N/A	
SB #		Date
Signature		Next Due Cert. #

Prepared by Tim Whiter 2802663DA Date July 2 2016

APPLIANCE AIRWORTHINESS DIRECTIVE COMPLIANCE RECORD

MAGNETO SERIES SC & S 20

MODEL NUMBER S6RSC-25
SERIAL NUMBER D05D7031
PART NUMBER 10-500556-1
WORK ORDER NUMBER 3038 RESEARCH DATE 06-09

DATE, SIGNATURE & CRT. #

~~74-06-02~~ 12/24/74 9-20, S-200, S-1200 SERIES MAGNETOS
METHOD OF COMPLIANCE: INSPECT AND REPAIR I/A/W
SERVICE BULLETIN SB556B *M/A by Model*

~~82-11-01~~ 06/28/82 S-1200 DISTRIBUTOR BLOCK AND BUSHINGS
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
SERVICE BULLETIN SB613 *M/A by Model*

~~82-28-01~~ 06/14/83 VARIOUS MODELS IMPULSER COUPLINGS
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
SERVICE BULLETIN SB623 *OK*

~~84-01-03 R2~~ 06/28/95 S-20, S-200 S-600, S-1200
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
MANDATORY SERVICE BULLETIN MSB644 *M/A by Model*

~~84-06-02~~ 03/09/94 SC-20, SC-200, S-1200
SEE AD TEXT FOR ADDITIONAL MODELS
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
CRITICAL SERVICE BULLETIN CSB641, CSB94-1, SB517
new style capacitor installed *OK*

~~MSB 645, SB639~~
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
MANDATORY SERVICE BULLETIN MSB645, SB639 *OK*
RECURRING INSPECTION REQUIRED
X DIMENSION LEFT PAWL .038"; RIGHT PAWL .040"
NEXT DUE 100 HRS 200 HRS

AD 2002-12-06 JUL 19, 2006 IMPULSER COUPLING ASSEMBLIES
MUST BE APPROVED BY INSTALLING AUTHORITY TO COMPLY WITH
MAKE AND MODEL OF ENGINE

Monitor 2006/2004

CSB 665 REGARDING CAPACITOR 10-400615
COMPLIED WITH. INSTALLING AUTHORITY TO INSTALL
UP LEAD & TORQUE NUT 15-17 IN POUNDS.
MAKE LOG ENTRY IN ENGINE & AIRFRAME LOG BOOK
STATING COMPLIANCE WITH THIS BULLETIN

OK
06-10-09
268866817

APPLIANCES AIRWORTHINESS DIRECTIVE COMPLIANCE RECORD

MAGNETO SERIES SC & S 20

MODEL NUMBER 56RSC-25

SERIAL NUMBER 0050A027

PART NUMBER 10-500556-1

WORK ORDER NUMBER 3037

RESEARCH DATE 06-09

DATE, SIGNATURE & CERT. #

~~74-06-02~~ 12/24/74 S-20, S-200, S-1200 SERIES MAGNETOS
METHOD OF COMPLIANCE: INSPECT AND REPAIR I/A/W
SERVICE BULLETIN SB556B

NA by P/N

~~82-13-01~~ 06/28/82 S-1200 DISTRIBUTOR BLOCK AND BUSHINGS
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
SERVICE BULLETIN SB613

NA by Model

~~82-24-01~~ 06/14/83 VARIOUS MODELS IMPULSE COUPLINGS
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
SERVICE BULLETIN SB623

ok

~~94-01-03 R2~~ 06/28/95 S-20, S-200 S-600, S-1200
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
MANDATORY SERVICE BULLETIN MSB644

NA by S/N

~~94-06-02~~ 03/03/94 SC-20, SC-200, S-1200
SEE AD TEXT FOR ADDITIONAL MODELS
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
CRITICAL SERVICE BULLETIN CSB641, CSB94-1, SB517

NA

new style capacitor installed

~~MSB 645, SB639~~
METHOD OF COMPLIANCE: INSPECT & REPAIR I/A/W
MANDATORY SERVICE BULLETIN MSB645, SB639

ok

RECURRING INSPECTION REQUIRED
X DIMENSION LEFT PAWL .036 "; RIGHT PAWL .038 "
NEXT DUE 100 Hrs

AD 2002-12-06 JUL 19, 2005 IMPULSE COUPLING ASSEMBLIES
MUST BE APPROVED BY INSTALLING AUTHORITY TO COMPLY WITH
MAKE AND MODEL OF ENGINE

Master 306/2004

CSB 665 REGARDING CAPACITOR 10-400615
COMPLIED WITH. INSTALLING AUTHORITY TO INSTALL
"P" LEAD & TORQUE NUT 15-17 IN POUNDS.
MAKE LOG ENTRY IN ENGINE & AIRFRAME LOG BOOK
STATING COMPLIANCE WITH THIS BULLETIN

*50-01-90
C18092880817
06-10-09
[Signature]*