







## AD Compliance Report

AD #	Subject	Date and Hours at Compliance	Recurring Yes/No	Next Due Date/Hours
77-12-06 R2	Prop blade		Yes	Superseded.
<b>Description:</b>	Propeller - Hartzell - PHC-J3YF-1			
<b>Component:</b>	Propeller - Hartzell - PHC-J3YF-1	<b>Category:</b>	Propeller	
<b>Effective Date:</b>	11/10/1977	<b>Mechanic name:</b>	Greg Herrmann	
<b>Supersedes:</b>	70-16-03, 73-10-03, 74-15-02, 75-07-05	<b>Certificate #:</b>	AP406901563IA	
<b>Superseded By:</b>	2002-09-08	<b>Authorized Sign.:</b>		
<b>Compliance:</b>	Superseded.			
<b>Notes:</b>				
89-22-05	Propeller hub failure		Yes	Superseded.
<b>Description:</b>	Propeller - Hartzell - PHC-J3YF-1			
<b>Component:</b>	Propeller - Hartzell - PHC-J3YF-1	<b>Category:</b>	Propeller	
<b>Effective Date:</b>	Upon receipt	<b>Mechanic name:</b>	Greg Herrmann	
<b>Supersedes:</b>	N/A	<b>Certificate #:</b>	AP406901563IA	
<b>Superseded By:</b>	93-16-14	<b>Authorized Sign.:</b>		
<b>Compliance:</b>	Superseded.			
<b>Notes:</b>				
93-16-14	Prop hub cracks		Yes	Superseded.
<b>Description:</b>	Propeller - Hartzell - PHC-J3YF-1			
<b>Component:</b>	Propeller - Hartzell - PHC-J3YF-1	<b>Category:</b>	Propeller	
<b>Effective Date:</b>	08/18/1993	<b>Mechanic name:</b>	Greg Herrmann	
<b>Supersedes:</b>	89-22-05	<b>Certificate #:</b>	AP406901563IA	
<b>Superseded By:</b>	94-17-13	<b>Authorized Sign.:</b>		
<b>Compliance:</b>	Superseded.			
<b>Notes:</b>				
94-17-13	Prop hub failure		Yes	N/A
<b>Description:</b>	Propeller - Hartzell - PHC-J3YF-1			
<b>Component:</b>	Propeller - Hartzell - PHC-J3YF-1	<b>Category:</b>	Propeller	
<b>Effective Date:</b>	09/15/1994	<b>Mechanic name:</b>	Greg Herrmann	
<b>Supersedes:</b>	93-16-14	<b>Certificate #:</b>	AP406901563IA	
<b>Superseded By:</b>	N/A	<b>Authorized Sign.:</b>		
<b>Compliance:</b>	N/A by Serial Number.			
<b>Notes:</b>				
2001-07-03	CORRECTION - Prevent propeller failure of the propellers returned to service by BASCO		No	
<b>Description:</b>	Propeller - Hartzell - PHC-J3YF-1			
<b>Component:</b>	Propeller - Hartzell - PHC-J3YF-1	<b>Category:</b>	Propeller	
<b>Effective Date:</b>	06/04/2001	<b>Mechanic name:</b>	Greg Herrmann	
<b>Supersedes:</b>	N/A	<b>Certificate #:</b>	AP406901563IA	
<b>Superseded By:</b>	N/A	<b>Authorized Sign.:</b>		
<b>Compliance:</b>	N/a not returned to service by BASCO.			
<b>Notes:</b>				




AD # 2002-09-08  
 Description: Propeller - Hartzell - PHC-J3YF-1  
 Component: Propeller - Hartzell - PHC-J3YF-1  
 Effective Date: 06/13/2002  
 Superseded: 77-12-06 R2  
 Superseded By: 2007-26-09  
 Compliance: Superseded.

Date and Hours at Compliance  
 Recurring Yes/No: No  
 Category: Propeller  
 Mechanic name: Greg Herrmann  
 Certificate #: AP4069015631A  
 Authorized Sign.: 


2005-14-11  
 Notes: Prevent blade failure that could result in separation of a propeller blade

Description: Propeller - Hartzell - PHC-J3YF-1  
 Component: Propeller - Hartzell - PHC-J3YF-1  
 Effective Date: 08/17/2005  
 Supersedes: N/A  
 Superseded By: N/A  
 Compliance: N/A prop not returned to service by Southern California Propeller Service.

Category: Propeller  
 Mechanic name: Greg Herrmann  
 Certificate #: AP4069015631A  
 Authorized Sign.: 


2007-26-09  
 Notes: To prevent failure of the propeller blade from fatigue cracks in the blade shank radius

Description: Propeller - Hartzell - PHC-J3YF-1  
 Component: Propeller - Hartzell - PHC-J3YF-1  
 Effective Date: 01/30/2008  
 Supersedes: 2002-09-08  
 Superseded By: N/A  
 Compliance: N/A by date of manufacture.

Category: Propeller  
 Mechanic name: Greg Herrmann  
 Certificate #: AP4069015631A  
 Authorized Sign.: 


2008-13-28  
 Notes: To prevent failure of the propeller hub

Description: Propeller - Hartzell - PHC-J3YF-1  
 Component: Propeller - Hartzell - PHC-J3YF-1  
 Effective Date: 07/17/2008  
 Supersedes: N/A  
 Superseded By: N/A  
 Compliance: N/A by Model.

Category: Propeller  
 Mechanic name: Greg Herrmann  
 Certificate #: AP4069015631A  
 Authorized Sign.: 

011-25-51  
 Notes: To address fractures in starter adapter shaft gears

Description: Engine - Continental Motors - TSIO-550-K  
 Component: Engine - Continental Motors - TSIO-550-K  
 Effective Date: 12/28/2011  
 Supersedes: N/A  
 Superseded By: 2012-10-13  
 Compliance: Superseded.

Category: Engine  
 Mechanic name: Greg Herrmann  
 Certificate #: AP4069015631A  
 Authorized Sign.: 



**Subject**  
 To require inspection and modification of the air box flange welds and slots and installation of induction system air box seals

**Date and Hours at Compliance**  
 8/17/11 flight: 94.4

**Recurring Yes/No**  
 No

**Next Due Date/Hours**

AD #

2012-01-11

**Description:** Airframe - Cirrus - SR22T  
**Component:** Airframe - Cirrus - SR22T


**Effective Date:** 2/29/2012  
**Supersedes:** N/A

**Superseded By:** N/A

**Compliance:** PCW by compliance with SB2X-71-17

**Category:**  
**Mechanic name:**  
**Certificate #:**  
**Authorized Sign.:**

**Airframe**  
 Greg Herrmann  
 AP4069015631A




**Notes:**  
 2012-03-06 To prevent an in-flight shutdown due to a failed fuel servo diaphragm

Yes N/A

**Description:** Engine - Continental Motors - TSIO-550-K  
**Component:** Engine - Continental Motors - TSIO-550-K  
**Effective Date:** 02/24/2012  
**Supersedes:** 2011-15-10  
**Superseded By:** N/A

**Category:**  
**Mechanic name:**  
**Certificate #:**  
**Authorized Sign.:**

**Engine**  
 Greg Herrmann  
 AP4069015631A



**Compliance:** N/A Fuel servo not overhauled or manufactured by AVStar fuel Systems


2-10-13 To prevent starter adapter gear shaft failure

Yes N/A

**Description:** Engine - Continental Motors - TSIO-550-K  
**Component:** Engine - Continental Motors - TSIO-550-K  
**Effective Date:** 6/8/2012  
**Supersedes:** 2011-25-51  
**Superseded By:** N/A

**Category:**  
**Mechanic name:**  
**Certificate #:**  
**Authorized Sign.:**

**Engine**  
 Greg Herrmann  
 AP4069015631A



**Compliance:** N/A by date of manufacture.



**Cirrus SR22T Maintenance Tracking**

Component Installation History		AC SIN:	AC REG#	AC MFG DATE:	ATA	AC TOTAL TIME:	344.2	FHM:	344.2	DATE:	9/16/2014
AC TT, TC, or Date component installed on aircraft.	REVISION 0 Hrs, Cyc, or Mo. expended at time of installation.	0066 N88BA 12/23/2010	ITEM/REQUIREMENT	PART NUMBER	SERIAL NUMBER	344.2	344.2	344.2	344.2	REMARKS	AMM 12137-001 Release B
						LIMITS	EXPENDED	REMAIN.	DUE		
3/28/2014	Annual Inspection	5		N/A	N/A	12	6	6	3/28/2015		
323.5	50 Hour Oil Change/ Inspection	5		N/A	N/A	50	20.7	29.3	373.5		REFER TO CHAPTER 12
323.5	100 HOUR LUBRICATION ITEMS	12		N/A	N/A	100	20.7	79.3	423.5		REFER TO CHAPTER 12
254.7	200 HOUR LUBRICATION ITEMS	12		N/A	N/A	200	89.5	110.5	454.7		REFER TO CHAPTER 12
254.7	300 HOUR LUBRICATION ITEMS	12		N/A	N/A	300	89.5	210.5	554.7		REFER TO CHAPTER 12
0.0	500 HOUR LUBRICATION ITEMS	12		N/A	N/A	500	344.2	155.8	500.0		500 HOUR OR 5 YEARS
12/23/2010	5 YEAR LUBRICATION ITEMS	12		N/A	N/A	60	MO	15	2000.0		
0.0	ALTERNATOR #1 OVERHAUL	12		N/A	N/A	2000	HRS	344.2	1655.8		
71.8	ALTERNATOR #2 OVERHAUL	24				500	HRS	272.4	227.6		571.8
0.0	BATTERY #1 SERIAL W/ CONCORDE BATTERY	24				1800	HRS	344.2	1455.8		1800.0
12/23/2010	BATTERY #2	24		50979-001		36	MO.	45	-9		12/22/2013
254.7	ELT BATTERY REPLACEMENT	25		N/A		500	HRS	89.5	410.5		754.7
2/1/2013	ELT INSP - COMPLY WITH FAR 91.207(d)	25		N/A		24	MO.	19	5		2/1/2015
3/28/2014	ELT REMOTE CONTROL PANEL BATTERY	25		N/A		SEE BATT.					REPLACE BATTERY ON OR BEFORE
12/23/2010	EMA CONTROLLER, AAIR	25		20902-001		12	MO	6	6		3/28/2015
5/1/2010	INFLATABLE RESTRAINT-PILOT SEAT INFLATOR ASSEMBLY	25		20902-002		96	MO	45	51		12/21/2018
6/3/2010	INFLATABLE RESTRAINT-CO-PILOT SEAT INFLATOR ASSEMBLY	25		20902-002		48	MO		N/A		
6/3/2010	COCKPIT FIRE EXTINGUISHER INSPECTION	25				84	MO	52.569857	31		4/29/2017
3/28/2014	COCKPIT FIRE EXTINGUISHER REPLACEMENT	26				108	MO	51	57		6/1/2019
12/23/2010	FUEL SYSTEM BOOST PUMP	26				108	MO	51	57		6/1/2019
12/23/2010	GASCOLATOR SEALS	28				12	MO	6	6		3/28/2015
12/23/2010	FUEL SYSTEM DRAIN VALVE SEALS	28				144	MO	45	99		12/20/2022
12/23/2010	ICE PROTECTION SYSTEM FILTER	30				120	MO	45	75		12/20/2020
0.0	ANTI ICE PROP BOOT - HARTZELL	30									On Condition
12/23/2010	CARBON MONOXIDE DETECTOR	31									On Condition
0.0											SERIALS W/
12/23/2010											855.8
0.0											2056
12/23/2010											12/22/2012
0.0											2055.8
12/23/2010											12/21/2016
0.0											12/21/2017



Component Installation History  
 REVISION 0  
 Hrs, Cyc, or Mo.  
 expended at  
 time of installation.

### Cirrus SR22T Maintenance Tracking

A/C S/N:	0066	A/C REG#	N88BA	A/C MFG DATE:	12/23/2010	A/C TOTAL TIME:	344.2	FHM:	344.2	DATE:	9/16/2014
ITEM/REQUIREMENT	0666	TOTAL TIME NEXT INSPECTION DUE	344.2	PART NUMBER	SERIAL NUMBER	LIMITS	EXPENDED	REMAIN.	DUE	REMARKS	
ATA	ITEM/REQUIREMENT	PART NUMBER	SERIAL NUMBER	LIMITS	EXPENDED	REMAIN.	DUE	REMARKS			
32	FLEXIBLE BRAKE SYSTEM LINES		N/A	60	MO	45	15	12/22/2015	On Condition		
32	OLEO STRUTS RUBBER ELEMENTS			2000	HRS	344.2	1655.8	2000.0	REFER TO TECHNOMETRA CMM FOR CIRRUS NILG SHOCK ABSORBER		
32	BRAKE ASSEMBLY O-RINGS		N/A	60	MO	45	15	12/22/2015	SERIALS 1005-2030 AFTER SB2X-05-01		
34	FAR 91.411 RE-CERTIFY #1 SYSTEM	N/A	N/A	24	MO	19	5	2/1/2015			
34	FAR 91.411 RE-CERTIFY #2 SYSTEM	N/A	N/A	24	MO	19	5	2/1/2015			
34	FAR 91.413 RE-CERTIFY #1 SYSTEM	N/A	N/A	24	MO	19	5	2/1/2015			
34	FAR 91.413 RE-CERTIFY #2 SYSTEM	N/A	N/A	24	MO	19	5	2/1/2015			
35	OXYGEN BOTTLE ASSEMBLY		N/A	180	MO	49	131	8/28/2025	SEE ICA FOR PRECISE FLIGHT STC SA1708SE		
51	AIRFRAME STRUCTURE		N/A	12000	HRS	344.2	11655.8	12000			
61	PROPELLER OVERHAUL	PHC-J3Y1F-1N		500	HRS	344.2	155.8	500.0	SEE HARTZELL SB 61M OR MCCAULEY SB 137B FOR LIMITS		
61	PROPELLER GOVERNOR OVERHAUL			72	MO	45	27	12/21/2016	SEE WOODWARD SB 33580F OR MCCAULEY SB 137		
71	FLEXIBLE OIL SYSTEM LINES		N/A	2400	HRS	344.2	2055.8	2400.0	On Condition		
71	FLEXIBLE FUEL LINES		N/A	45	MO	45			On Condition		
71	FLEXIBLE VENT LINES		N/A	45	MO	45			On Condition		
71	INDUCTION AIR FILTER - SERIALS 22T-0001 & SUB			500	HRS	344.2	155.8	156			
71	INDUCTION AIR FILTER - SERIALS 22T-0001 & SUB			36	MO	45	-9	12/22/2013			
72	ENG OIL FILTER REPLACEMENT		N/A	50	HRS	20.7	29.3	373.5	REFER TO TCM SIL 98-9		
72	ENGINE OVERHAUL	TSIO50K1B		2000	HRS	344.2	1655.8	2000.0			
73	ENG FUEL NOZZLES CLEAN/FLOW/CHECK		N/A	300	HRS	20.7	279.3	623.5	SEE TCM SB 643B		
74	LEFT MAGNETO			48	MO	45	3	12/22/2014			
74	RIGHT MAGNETO			500	HRS	344.2	155.8	500.0	SEE TCM SB 643B		
74	MAGNETO FILTER			48	MO	45	3	12/22/2014			
95	CAPS ROCKET MOTOR			500	HRS	344.2	155.8	500.0	SEE TCM SB 643B		
95	CAPS PARACHUTE			48	MO	45	3	12/22/2014			
95	CAPS PYROTECHNIC LINE CUTTERS			500	HRS	344.2	155.8	500.0	On Condition		
MISC.	CHECK POH/AFM FOR CURRENT REVISION STATUS										