

HARTZELL

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3YF-1RF

PROPELLER S/N FP 8122B

LOGBOOK # \_\_\_\_\_

PROPELLER MAINTENANCE RECORD

Position OWE

PITCH RANGE

Propeller Model PHC-13YF-1RF

High/Feather \_\_\_\_\_

Propeller S/N FP8122B

Start Lock \_\_\_\_\_

Blade Design F7392-1

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 L32337

No. 2 L32331

Aircraft Manufacturer Civens Corp.

No. 3 L32330

Aircraft Model SR 20

No. 4 \_\_\_\_\_

S/N 2230

No. 5 \_\_\_\_\_

Registration N585TC

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

# Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell


PHC-J3YF-1RF/F7392-1

s/n:FP8122B

N585TC

8-19-13 Hobbs:121.7hrs Prop Total Time:98.6hrs Completed a 100hr inspection in accordance with Chapter 05-20 Cirrus SR22 inspection checklist this date. Serviced Hub with Aeroshell #6 lubricant. AD's checked thru FAA Bi -Weekly 2013-16. No AD 's due at this time.

I certify this Propeller has been inspected in accordance with a 100hr inspection and was determined to be in Airworthy condition at this time.

  
Bryan M Wood A&P3216290

# Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell


PHC-J3YF-1RF/F7392-1

s/n:FP8122B


N585TC

12-27-13 Hobbs:246.4hrs Prop Total Time:200.9hrs Completed a 100hr inspection in accordance with Chapter 05-20 Cirrus SR22 inspection checklist this date. Serviced Hub with Aeroshell #6 lubricant. AD's checked thru FAA Bi -Weekly 2013-25. No AD 's due at this time.

I certify this Propeller has been inspected in accordance with a 100hr inspection and was determined to be in Airworthy condition at this time.


  
Bryan M Wood A&P3216290

Propeller has been inspected in accordance with a 100hr inspection and was determined to be in Airworthy condition at this time.

  
Bryan M Wood A&P3216290

3-24-2014 Hobbs:367.3 Prop Total Time 301.0

I certify that a 100hr inspection has been performed on this propeller in accordance with FAR part 43 appendix D. and Cirrus check list this date. Serviced hub with Aero shell #6 lub. AD's researched thru FAA Bi-weekly 2014 and no propeller AD's due at this time. Propeller returned to service.

  
A/P/I/A 3057515  
William F Sepuch

Date	Propeller		A/C Hrs
	TSN	TSO	

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.



6/6/2014  
4375 NE 48<sup>TH</sup> AVE  
GAINESVILLE, FL 32609

N 585TC PROP  
MAKE: HARTZELL  
MODEL: PHC-J3YRF-1RF  
S/N:  
TACH: TT 400  
W/O#:

I certify this propeller has been inspected in accordance with a 100 hr inspection and was found to be in an airworthy condition.

R Scott Lambert AP 3300566 IA

9/12/14	REPAIR = 500.0	CLW 100 HR INSPECTION
		PROP FOUND TO BE AIRWORTHY
		AP 3300566

11/20/2014 N585TC mod PHC-J3YRF-1RF Engine hours 601.2

I certify that this propeller has been inspected in accordance with a 100 hour inspection using Cirrus procedures and was found to be in a condition for safe operation. No current ADs

Dressed leading edge of prop

JOHN CARMEN  
A&P 2844678

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		



3/24/2015  
4375 NE 48<sup>TH</sup> AVE  
GAINESVILLE, FL 32609

N PROP N585TC  
MAKE: HARTZELL  
MODEL: PHCY-3RF-1  
S/N:  
TACH: TT 702.2  
W/O#:

1) Lubricated and inspected prop per Hartzell manual

I certify this propeller has been inspected in accordance with a 100 hr inspection and was found to be in an airworthy condition.

R Scott Lambert AP 3300566 IA


## Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell PHC-J3YF-1RF/F7392-1

s/n:FP8122B

N585TC

6-23-15 Hobbs:946.9hrs Prop Total Time:774.6hrs Completed an Annual inspection in accordance with Chapter 05-20 Cirrus SR20 inspection checklist this date. AD's checked thru FAA Bi-Weekly 2015-12. No AD's due at this time. Serviced Hub with Aeroshell #6 lubricant.

I certify this Propeller has been inspected in accordance with an Annual inspection and was determined to be in Airworthy condition at this time.

Liam Mullane A&P2807974IA

9/23/15	873.2	I certify this propeller has been inspected IAW a 100hr inspection has been found airworthy and returned to service AP 3585304IA

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections
------	----------------------	------------	--



11/19/2015  
4701 N.E. 40th TERRACE  
GAINESVILLE, FL 32609

N: 585TC PROP  
MAKEHARTZELL  
MODEL: PHC-J3YF-1  
S/N: FP 8122B  
ACTT 971.9  
W/O#:

1) Inspected and serviced prop PER Hartzell manual 145 and cirrus SR20 manual

I certify propeller has been inspected in accordance with a 100 hour inspection in accordance with FAR 43 appendix (d) using the manufacture checklist and current Federal Air Regulations as guidelines. This propeller was found to be in an airworthy condition and is approved for return to service.

R Scott Lambert  
A&P 3300566

3/14/2016	1071.8	Lubricated with AS66, Blended minor nicks from blades (dressed) inspected thru 100hr inspection found to be airworthy. For Thisse AP 3585304JA
-----------	--------	--

			July 01 2016 N585TC tach 1164.4
			Dressed leading edge of prop
			Greased with Aeroshell #6
			I certify that this aircraft propeller has been inspected in accordance with an annual inspection using Cirrus MM and checklist and was found to be airworthy. → 100hr.
			No current Ads, or time limit items
			John Carmer. A&P IA #2844678





