

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-JME-1RE/F9 6932FB

PROPELLER S/N FP4492B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model PHC-J34E-1RE/F7693DFB

High/Feather _____

Propeller S/N EP 4492B

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 K 34514

Aircraft Manufacturer Cirrus

No. 2 K 34513

Aircraft Model SR22

No. 3 K 34497

S/N 1871

No. 4 _____

Registration N 212SR

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
3-8-06	1	N/A	1	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 11 dated Dec/04 Section: 61-00-15 on <u>3-8-06</u> (DATE). The location of the Weight(s) are <u>310</u> (DATE). And are <u>D-1</u> gram(s). <u>310</u> degree.</p> <p><i>John M. Moran</i> (MFE 218) (Sign/Stamp) Cirrus Design Corporation, PC 338CE</p> <p>PROF MODEL: PWC-310 PWC-310-100 REG. NO. 2125R WORK ORDER: 2538-02-2006</p> <p>Cirrus Design Factory Service Center Repair Station No. 125282001 4011 Taylor Lane Duluth, MN 55811 Phone: 218-726-1181</p> <p>DATE: 10/4/2006 SIGNED: <i>[Signature]</i> Name: Gary Krohmer Certified Repair Station No. 24280001 Work Order: 2538-02-2006 Printed by EBis 3 (datcomedia.com)</p>

				<p>PROF MODEL: PWC-310-100 PWC-310-100 REG. NO. 2125R WORK ORDER: 2693-03-2007</p> <p>Commander Aero, Inc. Repair Station No. G401-4766 18375 Brighton Pike Marietta, Ohio 43042 USA Phone: 688-81-6585</p> <p>DATE: 3/26/2007 SIGNED: <i>[Signature]</i> Name: Gary Krohmer Certified Repair Station No. G401-4766 Work Order: 2693-03-2007 Printed by EBis 3 (datcomedia.com)</p>
				<p>PROF MODEL: PWC-310-100 PWC-310-100 REG. NO. 2125R WORK ORDER: 27440-03-2006</p> <p>Commander Aero, Inc. Repair Station No. G401-4766 18375 Brighton Pike Marietta, Ohio 43042 USA Phone: 688-81-6585</p> <p>DATE: 4/6/2006 SIGNED: <i>[Signature]</i> Name: Gary Krohmer Certified Repair Station No. G401-4766 Work Order: 27440-03-2006 Printed by EBis 3 (datcomedia.com)</p>

PremAir
 5400 Airport Dr. Charlotte, NC 28208 (704) 359-5230

Date: 8-4-06 N212SR TT: 205.1 WO# 06-8140 Propeller
 for Hobbs - 241.2

1. C/W 200 hour inspection IAW Cirrus MM #13773-001, Sept 15, 2004

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repairs are on file at this agency under Work Order No. 06-8140
 Date: 8-6-06

Signed: *[Signature]*
 Details of other work accomplished on file at the repair station under work order 06-8140 Dated: 8-6-06
 Signed: *[Signature]* for

PremAir Aviation Services
 CRS # R40R890N
 5400 Airport
 Charlotte, NC 28208

Date



4510 Airport Rd.
Cincinnati, OH 45226
(513) 821-1200




N212SR Date: 3/23/2012 **Propeller Flight: 594.3 TSN: 594.3**

Inspected propeller I/A/W an Annual inspection per Cirrus SR22 AMM rev. B2 Chapter 5-20 and Hartzell POM no.145 rev 3 jul/06. The following work was accomplished at this time:

1. Lubricated propeller
2. Dressed blades

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 4069015631A 



4510 Airport Rd.
Cincinnati, OH 45226
(513) 821-1200




N212SR Date: 4/11/2013 **Propeller Flight: 638.8 TSN: 638.8**

Inspected propeller I/A/W an Annual inspection per Cirrus SR22 AMM rev. B2 Chapter 5-20 and Hartzell POM no.145 rev 3 jul/06. The following work was accomplished at this time:

1. Lubricated propeller
2. Dressed blades

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 4069015631A 



4510 Airport Rd.
Cincinnati, OH 45226
(513) 821-1200




N212SR Date: 4/8/2014 **Propeller Flight: 638.8 TSN: 638.8**

Inspected propeller I/A/W an Annual inspection per Cirrus SR22 AMM rev. B2 Chapter 5-20 and Hartzell POM no.145 rev 3 jul/06. The following work was accomplished at this time:

1. Lubricated propeller
2. Dressed blades

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 4069015631A 



4510 Airport Rd.
Cincinnati, OH 45226
(513) 821-1200




N212SR Date: 4/6/2015 **Propeller Flight: 645.9 TSN: 645.9**

Inspected propeller I/A/W an Annual inspection per Cirrus SR22 AMM rev. B5 Chapter 5-20 and Hartzell POM no.145 rev 3 jul/06. The following work was accomplished at this time:

1. Lubricated propeller

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 4069015631A 

Date



4510 Airport Rd.
Cincinnati OH 45226
(513) 321-1200



N212SR **Date:** 4/22/2016 **Propeller Flight:** 646.1 **TSN:** 646.1

Inspected propeller I/A/W an **Annual** inspection per Cirrus SR22 AMM rev. B5 Chapter 5-20 and Hartzell POM no.145 rev 3 jul/06. The following work was accomplished at this time:

1. Lubricated propeller

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 406901563IA



4510 Airport Rd.
Cincinnati OH 45226
(513) 321-1200



N212SR **Date:** 4/17/2017 **Propeller Flight:** 646.7 **TSN:** 646.7

Inspected propeller I/A/W an **Annual** inspection per Cirrus SR22 AMM rev. B5 Chapter 5-20 and Hartzell POM no.145 rev 3 jul/06. The following work was accomplished at this time:

1. Lubricated propeller

I certify that this propeller has been inspected and repaired in accordance with current regulations of the FAA and is approved for return to service.

Greg Herrmann 406901563IA