HARTZELL

## PROPELLER LOGBOOK

PROPELLER MODEL PHC - J3 YF - IRF

PROPELLER S/N FP 2087 B

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

## PROPELLER MAINTENANCE RECORD

PITCH RANGE
High/Feather
Start Lock
Low
Reverse
Aircraft ManufacturerCIRRUS
Aircraft Model SR 20
S/N_ 1299
Registration N 77 ZX

Description of all operations pertaining to Airworthiness Directives, Propeller A/C Date Service Documents, Overhaul, Major or Minor Repair, and Inspections. Hrs TSN TSO ARAPAHOE AERO 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 S/N: FP2087B N77ZX Hartzell PHC-J3YF-1RF 06 February 2004 Hobbs: 0181.8 Propeller Total Time: 0181.8 100 Hour Inspection for Annual completed this date using the Cirrus SR20 inspection form as a guide. Inspected propeller blades and hub. Dressed blade leading edges. Painted blade faces. AD 2003-13-17 (T & W overhaul) N/A by propeller maintenance history. AD's checked through bi-weekly 2004-01. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. END. all Well L. John Wells A&P523116767 w/o 20371 ARAPAHOE AERO 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 S/N: FP2087B PHC-J3YF-1RF N77ZX Hartzell Hobbs: 0354.2 Propeller Total Time: 0354.2 25 February 2005 Propeller Calendar Time In Service 2 Years / 0 Months 100 Hour Inspection for Annual completed this date using the Cirrus SR20 inspection form as a guide. Inspected propeller blades and hub. Dressed blade leading edges. Painted blade faces. AD's checked through bi-weekly 2005-02. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. END. w/o: 21699 / 21700 L. John Wells A&P523116767 ARAPAHOE AERO 12760 EAST CONTROL TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 N77ZX Hartzell PHC-J3YF-1RF S/N: FP2087B 10 February 2006 Hobbs: 0494.9 Propeller Total Time: 0494.9 Propeller Calendar Time In Service 3 Years / 0 Months 100 Hour Inspection for Annual completed this date using the Cirrus SR20 inspection form as a guide. Inspected propeller blades and hub. Dressed blade leading edges. Painted blade faces. Hartzell AD 2005-14-11 (Southern California Propeller Service) N/A by maintenance history. AD's checked through biweekly 2006-02. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. END. L. John Wells A&P523116767 w/o 23049 March 9, 2007 N77ZX Erie Municipal Airport S/N 1299 395 Airport Drive HM: 612.1 Erie. CO 80516 1. Performed a 100hr inspection of propeller for annual of N77ZX in accordance with FAR 43 appdx D and a checklist. I certify this propeller has been inspected iaw a 100hr inspection and determined to be in airworthy condition. END-Terrill Shafer

IA2860279

N77ZX	7, 2008		Erie Municipal Airport	
S/N 1299 HM: 784		Vector A	395 Airport Drive	
1. Perfor	med a 100hr inspection of p	propeller for annual of N77ZX in accordance waspected law a 100hr inspection and determined	with FAR 43 appdx D and a check I to be in airworthy condition.	list.
		END	12011	,
+		5		
			Terrill Shafer IA2860279	
	Date: 4/02/2009; Aircr	raft: N77ZX; Type: SINGLE ENGINE;	S/N: 1299;	
	357559, Time: 968.1; I	me: 968.1; Engine - Type: TCM, IO36 Prop - Type: PHC-J3YF-1RF, S/N: FP	0ES6, S/N: 2087B, Time:	
	Painted backs flat blac	d greased hub. Dressed nicks out of		
	N77ZX Hobbs indicate propeller has been ins	es 968.1 Hours this Date 4/2/2009. I opected in accordance with an annual/	100 hour	
-	conformity checked the		on. AD	
-	Aero Clinic, Inc. PO Box 1626	Gregory Langham A&P458476877IA		
	Seminole, Tx. 79360 (432) 758-6455	Dugley bougham		
			W 0 0400	
	N77ZX Date: 5/4/2010	HOBBS: 1081.0	W.O. 8163 SMOH: 1081.0	
	Date: 5/4/2010	TT: 1081.0	SMOH: 1081.0	
	Date: 5/4/2010		SMOH: 1081.0	
	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 10the inspection and has b	TT: 1081.0  and spinner assembly. Lubed propeller with A  ASE  the aircraft's annual inspection, this propeller has been in the propeller has been i	smoH: 1081.0  eroshell 6 grease.	
	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 100hr inspection and has b under the work order numb	and spinner assembly. Lubed propeller with A ASE.  The aircraft's annual inspection, this propeller has been in the aircraft to be in airworthy condition. Pertinent details a beer stated above.  NORTHS  NOR	smoh: 1081.0  eroshell 6 grease.  spected in accordance with a are on file at the Repair Station  iTAR JET, Inc.  JRATE WAY  LA, MONTANA 59808	
	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 10the inspection and has b	and spinner assembly. Lubed propeller with A ASE.  The aircraft's annual inspection, this propeller has been in been found to be in airworshy condition. Pertinent details to ber stated above.  NORTHS 1 CORPO	smoh: 1081.0  eroshell 6 grease.  espected in accordance with a are on file at the Repair Station  ETAR JET, Inc.  DRATE WAY  LA, MONTANA 59808	
PROP	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 100hr inspection and has b under the work order numb	and spinner assembly. Lubed propeller with A ASE  The aircraft's annual inspection, this propeller has been in the stated above.  NORTHS  NORTHS  1 CORPC  MISSOUR (800) 735  CRS. NT	smoh: 1081.0  eroshell 6 grease.  espected in accordance with a are on file at the Repair Station  ETAR JET, Inc.  DRATE WAY  LA, MONTANA 59808	2011
PHG-J PROP REG. I WORK	Inspected propeller a  MAINTENANCE RELE. I certify that, at the time of 100hr inspection and has bunder the work order numb  (Signature)  MODEL: 3YF-1RF SN: FP2087B NO: N77ZX CORDER:	and spinner assembly. Lubed propeller with A ASE  The aircraft's annual inspection, this propeller has been in the propeller has been in the been stated above.  NORTHS  NORTHS  1 CORPO  MISSOU  (800) 735	smoh: 1081.0  eroshell 6 grease.  spected in accordance with a are on file at the Repair Station STAR JET, Inc.  DRATE WAY  LA, MONTANA 59808  L4476  BR983G	21.4 24.4
PHC-J PROP REG. I WORK 1883-0	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 100hr inspection and has b under the work order numb  (Signature)  MODEL: 3YF-1RF SNE FP2087B NO: N77ZX	and spinner assembly. Lubed propeller with A ASE.  The aircraft's annual inspection, this propeller has been in the aircraft to be in airworthy condition. Pertinent details of the stated above.  NORTHS  NORTHS  LOGRO  MISSOU  (800) 735  CRS. NT  Houston Aviation Center, LLC  12888 Hwy 6 S Ste 113  Sugar Land, TX 77498	smoh: 1081.0  eroshell 6 grease.  spected in accordance with a are on file at the Repair Station  ETAR JET, Inc.  DRATE WAY  LA, MONTANA 59808  LA476  BR983G  DATE: 7/1/2  A/C TSN: 11  PROP IT: 11	21.4 24.4
PHC-J PROP REG. WORK 1883-0 Prop Compi	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 100hr inspection and has b under the work order numb  (Signature)  MODEL: 3YF-1RF SNk FP2087B NO: N77ZX (ORDER: 34-2011  Entries eted an Annual Inspection this date F g edges. Inspected and lubricated pr	and spinner assembly. Lubed propeller with A ASE.  The aircraft's annual inspection, this propeller has been in the aircraft to be in airworthy condition. Pertinent details of the stated above.  NORTHS  NORTHS  LOGRO  MISSOU  (800) 735  CRS. NT  Houston Aviation Center, LLC  12888 Hwy 6 S Ste 113  Sugar Land, TX 77498	smoh: 1081.0  eroshell 6 grease.  spected in accordance with a are on file at the Repair Station  ETAR JET, Inc.  RATE WAY  LA, MONTANA 59808  4476  BR983G  DATE: 7/1/2  A/C TSN: 11  PROP TT: 11  HOBBS: 11	21.4 24.4 21.4
PHC-J PROP REG : WORH 1883-C Prop Compil leading inspec	Inspected propeller a  MAINTENANCE RELE I certify that, at the time of 100hr inspection and has b under the work order numb  (Signature)  MODEL: 3YF-1RF SNk FP2087B NO: N77ZX (ORDER: 34-2011  Entries eted an Annual Inspection this date F g edges. Inspected and lubricated pr	ASE The aircraft's annual inspection, this propeller has been in seen found to be in airworthy condition. Pertinent details a beer stated above.  NORTHS 1 CORPO MISSOU (800) 735 CRS. NT  Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 Phone: 281-494-5800  Ref. CDC SR20 AMM 5-20 and Propeller Owner's Manual No. opeller hub. Checked blade track. Checked AD's thru BW 20	smoh: 1081.0  eroshell 6 grease.  spected in accordance with a are on file at the Repair Station  ETAR JET, Inc.  RATE WAY  LA, MONTANA 59808  4476  BR983G  DATE: 7/1/2  A/C TSN: 11  PROP TT: 11  HOBBS: 11	21.4 24.4 21.4
PHC-J PROP REG : WORK 1883-0 Prop Compi leading inspec Mainte	MAINTENANCE RELE I certify that, at the time of 100hr inspection and has be under the work order numb  (Signature)  MODEL: 3YF-1RF SNk FP2087B NO: N772X CORDER: 04-2011  Entries eted an Annual Inspection this date for godges. Inspected and lubricated pried in accordance with an Annual Inspection Release increase and inspection on N772X  mance Release increase and inspection on N772X  mance Release increase and inspection on N772X	ASE The aircraft's annual inspection, this propeller has been in seen found to be in airworthy condition. Pertinent details a beer stated above.  NORTHS 1 CORPO MISSOU (800) 735 CRS. NT  Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 Phone: 281-494-5800  Ref. CDC SR20 AMM 5-20 and Propeller Owner's Manual No. opeller hub. Checked blade track. Checked AD's thru BW 20	smoh: 1081.0  eroshell 6 grease.  spected in accordance with a are on file at the Repair Station  ETAR JET, Inc.  DRATE WAY  LA, MONTANA 59808  14476  BR983G  DATE: 7/1/2  A/C TSN: 11  PROP TT: 11  HOBBS: 11	21.4 24.4 21.4

ate	Propeller SN TSC	PROP MODEL: PHC_ISYF_1RF PROP SIN: FP20878 REG. NO: N77ZX  White is a superficient of the content of the conten	C DATE: 8/2/2012 A/C TSN: 1214.5 PROP TT: 1214.5 HOBBS: 1214.5
		WORK ORDER Phone: 281-494-5800 2377-04-2012	
		Prop Entries	
		Completed an Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Own leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked inspected in accordance with an Annual Inspection and	AD's thru BW 2012-14 I certify that this Propeller has been
		Maintenance Refease	
		The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance and was found Airworthy for return to service. Pertinent details of the repair are on file at 2377-04-2012.	to with current requirements of the Federal Aviation Regulations at Houston Aviation Center, LLC under Work Order No.
-		DATE: 8/2/2012 SIGNED: Philip L Zwahr, A&P: 2685619	Work Order: 2377-04-2012
		Philip L Zwahr, A&P: 2685619 JA	Printed by EBis 3 (datcomedia.com)
		PROP MODEL: PHC-J3YF-1RF PROP SR: FP2087B REG. NO: N77ZX WORK ORDER:  PROP MODEL: PHOUSTON Aviation Center, LL: 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800	DATE: 9/25/2013 A/C TSN: 1273.4 PROP TT: 1273.4 HOBBS: 1273.4
		3065-08-2013	
		Prop Entries  Completed an Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Own leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked inspected in accordance with an Annual Inspection and was determined to be in Annual	AD's thru BW 2013-19 I certify that this Propeller has been
			my conducts.
		Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance and was found Airworthy for return to service. Pertinent details of the repair are on file at 3065-08-2013.	a with current requirements of the Federal Aviation Regulations at Houston Aviation Center, LLC under Work Order No.
		DATE: 9/25/2013 SIGNED: Philip Sugal	Work Order: 3065-08-2013
		Philip L Zwahr, A&P: 2685619 IA	Printed by EBis 3 (datcomedia.com)
	•		
	•		
	•	O United Assisting Center III C	
		PROP MODEL: PHC-J3YF-1RF PHC-J3YF-1RF PHC-J3YF-1RF 12888 May 6 S SM 113	DATE: 9/29/2014 A/C TSN: 1323.1 PROP TT: 1323.1
		REG. NO: N77ZX Sugar Land, TX 77498 USA	DATE: 9/29/2014 AC TSN 1323.1
		REG. NO: N77ZX Sugar Land, TX 77498 USA	DATE: 9/29/2014 A/C TSN: 1323.1 PROP TT: 1323.1
		PROP SIN 1920878 REG. NO. N77ZX WORK ORDER: 3560-09-2014  Prop Entries	DATE: 9/29/2014 AC TSN 1323.1 PROP TT 1323.1 HOBBS: 1323.1
		PROP SIN FP20878  REG. NO: N77ZX  WORK ORDER: 3560-09-2014	DATE: 9/29/2014 AC TSN: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1
		PROP SN: PF20878 REG. NO: N772X WORK ORDER: 3560-09-2014 Prop Entries Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release	DATE: 9/29/2014 A/C TSN: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1 HOBBS: 1323.1  From the BW 2014-18 I certify that this Propeller has a in Airworthy condition.
		PROP SN: FP2087B REG. NO: N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checken inspected in accordance with a 100 HR/Annual Inspection and was determined to be	DATE: 9/29/2014 AC TSN: 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  r Owner's Manual No. 115N. Inspected and dressed propeller sked AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.
		PROP SN: P20878 REG. NO: N772X WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N772X was repaired and/or inspected in accordance and was found Airworthy for return to service. Pertinent details of the repair are on file at h	DATE: 9/29/2014 AC TSN 1323.1 PROP TT 1323.1 PROP TT 1323.1 HOBBS: 1323.1  r Owner's Manuel No. 115N. Inspected and dressed propeller fixed AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.
		REG. NO: N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade leading edges. Inspected and lubricated propeller hub. Checked blade track. Checked in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance and was found Airworthy for return to service. Pertinent details of the repair are on file at H 3560-09-2014.	DATE: 9/29/2014 AC TSN: 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  of Owner's Manuel No. 115N. Inspected and dressed propeller clied AD's thru BW 2014-18 I certify that this Propeller has a in Airworthy condition.  with current requirements of the Federal Aviation Regulations Houston Aviation Center, LLC under Work Order No.
		REG. NO. N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade loading edges. Inspected and lubricated propeller hub. Checked blade track. Check been inspected in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance vand was found Airworthy for return to service. Pertinent details of the repair are on file at F 3560-09-2014.  DATE: 9/29/2014  SIGNED:	DATE: 9/29/2014 AC TSN 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  r Owner's Manuel No. 115N. Inspected and dressed propeller ked AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.  with current requirements of the Federal Aviation Regulations Houston Aviation Center, LLC under Work Order No.  Work Order: 3560-09-2014
		REG. NO. N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade loading edges. Inspected and lubricated propeller hub. Checked blade track. Check been inspected in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance vand was found Airworthy for return to service. Pertinent details of the repair are on file at F 3560-09-2014.  DATE: 9/29/2014  SIGNED:	DATE: 9/29/2014 AC TSN 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  r Owner's Manuel No. 115N. Inspected and dressed propeller ked AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.  with current requirements of the Federal Aviation Regulations Houston Aviation Center, LLC under Work Order No.  Work Order: 3560-09-2014
		REG. NO. N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade loading edges. Inspected and lubricated propeller hub. Checked blade track. Check been inspected in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance vand was found Airworthy for return to service. Pertinent details of the repair are on file at F 3560-09-2014.  DATE: 9/29/2014  SIGNED:	DATE: 9/29/2014 AC TSN 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  r Owner's Manuel No. 115N. Inspected and dressed propeller ked AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.  with current requirements of the Federal Aviation Regulations Houston Aviation Center, LLC under Work Order No.  Work Order: 3560-09-2014
		REG. NO. N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade loading edges. Inspected and lubricated propeller hub. Checked blade track. Check been inspected in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance vand was found Airworthy for return to service. Pertinent details of the repair are on file at F 3560-09-2014.  DATE: 9/29/2014  SIGNED:	DATE: 9/29/2014 AC TSN 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  r Owner's Manuel No. 115N. Inspected and dressed propeller ked AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.  with current requirements of the Federal Aviation Regulations Houston Aviation Center, LLC under Work Order No.  Work Order: 3560-09-2014
		REG. NO. N77ZX WORK ORDER: 3560-09-2014  Prop Entries  Completed a 100 HR/Annual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller blade loading edges. Inspected and lubricated propeller hub. Checked blade track. Check been inspected in accordance with a 100 HR/Annual Inspection and was determined to be Maintenance Release  The aircraft and/or component(s) on N77ZX was repaired and/or inspected in accordance vand was found Airworthy for return to service. Pertinent details of the repair are on file at F 3560-09-2014.  DATE: 9/29/2014  SIGNED:	DATE: 9/29/2014 AC TSN: 1323.1 PROP TT: 1323.1 PROP TT: 1323.1 HOBBS: 1323.1  FOwner's Manuel No. 115N. Inspected and dressed propeller sked AD's thru BW 2014-18 I certify that this Propeller has e in Airworthy condition.  with current requirements of the Federal Aviation Regulations Houston Aviation Center, LLC under Work Order No.  Work Order: 3560-09-2014

te	Propeller TSN TSC	A/C Hrs		aining to Airworthiness Directives, ijor or Minor Repair, and Inspections.	
	PROP M PHC-J3Y PROP S/ REG. NO	F-1RF N: FP2087B	Houston Aviation Center, LLC  12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA	DATE 10/12/2015 AIC TSN: 1355.5 PROP TT: 1355.5 HOBBS: 1355.5	
+	WORK 0 4084-09-	RDER:	Phone: 281-494-5800		
+	Prop E	4 - 400 HB/Ann	ual Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's	Manual No. 115N. Inspected and dressed propeller	
+	blade for	tion adopt fair	pocted and lubricated propoller hub. Checked blade track. Checked ADs eith an Annual Inspection and was determined to be in Airworthy condition	THE BAY SO 12-51 I county didn may a rob time count	
4		nce Release			
	The aircreand was f	ound Airworthy	ment(s) on N77ZX was repaired and/or inspected in accordance with curre for return to service. Pertinent details of the repair are on file at Houston A	ant requirements of the Federal Aviation Regulations Aviation Center, LLC under Work Order No.	
		0/12/2015	SIGNED: Plublind	Work Order: 4084-09-2015	
	UATE.	G122010	Philip L Zwahr, A&P: 2685619 M	Printed by EBis 3 (datcomedia.com)	
+					
	PROP MODE		Houston Aviation Center, LLC	DATE: 11/11/2016	
	PROP MODE PHG-J3YF-1F PROP SIN F REG. NO: N7 WORK ORDE	F P2087B 7ZX	Houston Aviation Center, LLC  12888 Hwy 6 S Sie 113 Sugar Land, TX 77498 USA Phone 281-464-5800	DATE: 11/11/2016 A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2	
	PHC-J3YF-1F PROP S/N: FI REG. NO: N7 WORK ORDE 4644-10-2016	F P2087B 7ZX R:	12888 Hwy 6 S Sie 113 Sugar Land, TX 77498 USA	A/C TSN: 1404.2 PROP TT: 1404.2	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016 Prop Entr Completed a blade leading	P2087B P2087B PZX R: ies ioo HR/Annuel I edges. Inspect	12888 Hwy 6 S Sie 113 Sugar Land, TX 77498 USA	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  HOBBS: 1404.2	
	PHC-J3YF-1F PROP SIN FI REG. NO. N7 WORK ORDE 4644-10-2016  Prop Entr Completed a blade leading been inspecte  Maintenance The aircraft ai	P 22087B 72X R: Inspect of in accordance Release Addor component Anworthy for re	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Maried and lubricated propeller hub. Checked blade track. Checked ADs thru	AVC TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2 HOBBS: 1404.2  nual No. 115N. Inspected and dressed propeller BW 2016-22 I certify that this Propeller has condition.	
	PHC-J3YF-1F PROP SiN FI REG. NO. N. T WORK ORDE 4644-10-2016  Prop Entr Completed a blade leading been inspecte  Maintenance The aircraft at and was found	EF 2087B 72X R: ies 100 HR/Annual 1 edges inspect d in accordance Release adlor component Anworthy for re	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-484-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Maried and lubricated propeller hub. Checked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy  (s) on N77ZX was recaired and/or inspected in accordance with current of	AVC TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2 HOBBS: 1404.2  nual No. 115N. Inspected and dressed propeller BW 2016-22 I certify that this Propeller has condition.	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr Completed a blade leading been inspecte  Maintenance The aircraft ai and was found 4644-10-2016	EF 2087B 72X R: ies 100 HR/Annual 1 edges inspect d in accordance Release adlor component Anworthy for re	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-464-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Mailed and lubricated propeller hub. Checked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy  (s) on N77ZX was repaired and/or inspected in accordance with current return to service. Pertinent details of the repair are on file at Houston Aviat	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propeller BW 2016-22 I certify that this Propeller has condition.  But 2016-22 I certify that this Propeller has lion Center, LLC under Work Order No.  Work Order: 4644-10-2016 Printed by EBis 3 (datcomedia.com)	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr Completed a blade leading been inspecte  Maintenance The aircraft ai and was found 4644-10-2016	EF 2087B 72X R: ies 100 HR/Annual 1 edges inspect d in accordance Release adlor component Anworthy for re	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-464-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Market and subricated propeller hub. Checked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy  (s) on N77ZX was repaired and/or inspected in accordance with current return to service. Pertinent details of the repair are on file at Houston Aviation.	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propeller BW 2016-22 I certify that this Propeller has condition.  equirements of the Federal Aviation Regulations ion Center, LLC under Work Order No.  Work Order: 4644-10-2016	
	PHC-J3YF-1F PROP SN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr Completed a blade leading been inspecte  Maintenance The aircraft ai and was found 4644-10-2016  DATE: 11/1  PROF PHC- PROF REG. WOR	ies  ios  ios  ios  ios  ios  ios  ios	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-464-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Market and subricated propeller hub. Checked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy  (s) on N77ZX was repaired and/or inspected in accordance with current return to service. Pertinent details of the repair are on file at Houston Aviation.	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propeller BW 2016-22 I certify that this Propeller has condition.  But 2016-22 I certify that this Propeller has lion Center, LLC under Work Order No.  Work Order: 4644-10-2016 Printed by EBis 3 (datcomedia.com)	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr  Completed a blade leading been inspecte  Maintenance  The aircraft ar and was found 4644-10-2016  DATE: 11/1  PROF PHC- PROF REG. WOR 5096	IF 2087B 72X R: Instance Insta	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Mailed and lubricated propeller hub. Chacked blade track, Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Ann	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propeller BW 2016-22 I certify that this Propeller has condition.  Requirements of the Federal Aviation Regulations ion Certer, LLC under Work Order No.  Work Order: 4644-10-2016  Printed by EBis 3 (datcomedia.com)  DATE: 12/18/2017 A/C TSN: 1441.3 PROP TT: 1441.3	
	PHC-J3YF-1F PROP SIN F REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr  Completed a blade leading been inspecte  Maintenance  The aircraft ai and was found 4644-10-2016  DATE: 11/1  PROF PHC- PROF REG. WOR 5096  Proj	P2087B 72X R  ies  100 HR/Annuel ledges. Inspected in accordance Release ridior component Anworthy for re 1/2016  MODEL 13YF-1RF SN: FP2087B NO: N77ZX K ORDER 11-2017 Entries	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Mailed and lubricated propeller hub. Chacked blade track, Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Ann	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propellor BW 2016-22 I certify that this Propeller has condition.  Requirements of the Federal Aviation Regulations lion Center, LLC under Work Order No.  Work Order: 4644-10-2016 Printed by EBis 3 (datcomedia.com)  DATE: 12/18/2017 A/C T8N: 1441.3 PROP TT: 1441.3 HOBBS: 1441.3	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr  Completed a blade leading been inspecte  Maintenance  The aircraft ar and was found 4644-10-2016  DATE: 11/1  PROF PHC- PROF REG. WOR 5096- Proj Loerti	P2087B 72X R  ies  100 HR/Annuel ledges. Inspected in accordance Release ridior component Anworthy for re 1/2016  MODEL 13YF-1RF SN: FP2087B NO: N77ZX K ORDER 11-2017 Entries	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Mailed and lubricated propeller hub. Chacked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy (s) on N77ZX was repaired and/or inspected in accordance with current refurn to service. Pertinent details of the repair are on file at Houston Aviation SIGNED:  Found Hussain, A&P. 320486 FIA  Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800	A/C TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propellor BW 2016-22 I certify that this Propeller has condition.  Requirements of the Federal Aviation Regulations lion Center, LLC under Work Order No.  Work Order: 4644-10-2016 Printed by EBis 3 (datcomedia.com)  DATE: 12/18/2017 A/C T8N: 1441.3 PROP TT: 1441.3 HOBBS: 1441.3	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr  Completed a blade leading been inspecte  Maintenance  The aircraft ai and was found 4644-10-2016  DATE: 11/1  PROF PHC- PROF REG. WORK S096  Proj  Loetii  The a and was and was and was The a	ies  ios  ios  ios  ios  ios  ios  ios	12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Mailed and lubricated propeller hub. Chacked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy with a 100 HR/Annual Inspection and was determined to be in Airworthy (s) on N77ZX was repaired and/or inspected in accordance with current refurn to service. Pertinent details of the repair are on file at Houston Aviation SIGNED:  Found Hussain, A&P. 320486 FIA  Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800	AVC TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propeller IBW 2016-22 I certify that this Propeller has requirements of the Federal Aviation Regulations ion Center, LLC under Work Order No.  Work Order: 4644-10-2016  Printed by EBis 3 (datcomedia.com)  DATE: 12/18/2017 AVC T8N: 1441.3 HOBBS: 1441.3  determined to be in Airworthy condition.	
	PHC-J3YF-1F PROP SIN FI REG. NO. N.7 WORK ORDE 4644-10-2016  Prop Entr  Completed a blade leading been inspecte  Maintenance  The aircraft ar and was found 4644-10-2016  DATE: 11/1  PROF PHC- PROF REG. WOR 5096  Prog Loeri  Mainty The a and w 5008-	P 22087B 72X R. 100 HR/Annual 1 edges. Inspect of in accordance Release addor component Aniworthy for relative to the second of	12888 Hwy 6 S Ste 113 Sugar Land, TX 77496 USA Phone: 281-464-5800  Inspection this date Ref. CDC SR20 AMM 5-20 and Propeller Owner's Maried and lubricated propellier hub. Checked blade track. Checked ADs thru with a 100 HR/Annual Inspection and was determined to be in Airworthy  (s) on N77ZX was repaired and/or inspected in accordance with current neum to service. Pertinent details of the repair are on file at Houston Aviation to service. Pertinent details of the repair are on file at Houston Aviation SIGNED:  Found Hussain, A&P. 320486 LIA  Houston Aviation Center, LLC 12888 Hwy 6 S Set 113 Sugar Land, TX 77498 USA Phone: 281-494-5800  er has been inspected in accordance with a 100 HR/Annual Inspection and was ponentist on N77ZX was repaired and/or inspected in accordance with current re-	AVC TSN: 1404.2 PROP TT: 1404.2 HOBBS: 1404.2  Inual No. 115N. Inspected and dressed propeller IBW 2016-22 I certify that this Propeller has requirements of the Federal Aviation Regulations ion Center, LLC under Work Order No.  Work Order: 4644-10-2016  Printed by EBis 3 (datcomedia.com)  DATE: 12/18/2017 AVC T8N: 1441.3 HOBBS: 1441.3  determined to be in Airworthy condition.	

## END OF N77ZX Propeller Log January 2018