# AIRCRAFT TECHNICAL LOGS

Section 4. PROPELLER

### The United States of America Department of Transportation

Federal Aviation Administration Washington, D.C.

Nov E395275

### Export Certificate of Airworthiness

This certifies that the product	identified below and more particularly described in Specification (s) of
the Federal Aviation Administration	
has been examined and as of the	date of this certificate, is considered airworthy in accordance with a
comprehensive and detailed airworts	riness code of the United States Government, and is in compliance with
those special requirements of the	importing country filed with the United States Government, except
as noted below. This certificate in	no way allests to compliance with any agreements or contracts between
	it constitute authority to operate an aircraft.

Product:

Aircraft Propeller

Manufacturer.

Hartzell Propeller Inc.

Model:

HC-C2YR-1BF/F7495S

Levial No.

CH38129B

New X Newly Overhauled |

Used Direraft [

Country to which exported:

Canada

Exceptions:

NONE

Jeff Guillon


Jeff . Quillen, DOA-100082-CE

Signature of Authorized Representative

April 15, 2004

Hartzell Propeller Inc. (PC-10)

District Office or Designee Number



<sup>&</sup>lt;sup>1</sup> For complete aircraft, list applicable specification or Type Certificate Data Sheet numbers for the aircraft, engine, and propeller.

Applicable specifications or Type Certificate Data Sheet, if not attached to this export certificate, will have been forwarded to the appropriate governmental office of the importing country.

# PROPELLER LOG

1.	Make _	HAMA ZEEC			
2.	Model	HC-CZYR-1BF			
3.	Specification No.	P-920			
4.	Date of Manufacture				
5.	Hub Serial No.	CH38/29B			
6.	Blades				
	(a) Design No.				
	(b) Blade Serial Nos.				

1.1

### PROPELLER SERVICE AND

#### MAINTENANCE RECORD

							THE THANGE REGORD				
DATE	TIME		TOTA SINCE O	VERHAU MIN.	NOTE: USE BOTH PAGES AND AS M.	ONS, INSPECTIONS, ANY LINES AS REQUIRED FOR COMPLETE	REPAIRS, ADJUSTMENTS, MODIFICATIONS ENTRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS,	SIGNATURE	LICENCE		
BROUGHT FORWARD	HRS.	MIN.	6-	0		ERWARD	40.38% AS PER SICNO, SADIESOCH	Now	DA Q 13		
2 1001 201				V	MODERN AERO, INC. 14801 PIONEER TRAIL EDEN PRAIRIE, MN 55347 952-941-2595				Q 13		
			N388J	P	DATE: 11/4/04	HOBBS: 95.9 PTT: 95.9					
	COMPLETED ANNUAL INSPECTION ON THIS DATE. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. REFERENCE MODERN AERO W/O # 32969										
	KEN R FISCHBACH A&P/IA 504925029 Km. R Freshland					R Fiedlah					
			Date.	01-06-2	Channel Islands Aviation 305 Durlay Avenue Camarillo, CA 93010 FAA Repair Station DDER146D JP Model: Hartzell HC-C2YR-1BF 005 Hobbs 170.7 T.T. 170.7	Ser. #. CH38129B					
	Performed 200 Hour Inspection in accordance with Diamond DA40 maintenance checklist.  Dressed and painted blades.  All pertinent data on file under WO 12653.  I certify that the above work was accomplished, inspected, found in airworthy condition and approved for return to										
					REPAIR STATION #DDER146D Authorized Inspector						
					\(\text{\tint{\text{\tin}\text{\ti}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\tint{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}\\ \tint{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tex{\tex						
TOTAL TURN					CARRIED FORWARD						
TOTAL THIS PAGE											

	TIME RUN	TOTAL TIME		INSTALLATIONS, INSPECTIONS, NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE	
DATE	HRS. MIN.	HRS.	MIN.	NOTE: USE BOTA FACE	0
BROUGHT	-			Diamond	
	DONE TSN.	304	.4	2005 S/N: 40 388 Ren: N388 ID	
e 16,205	PROP 12.		-	W/O RO-05-167 Prop S/N: CH38129B PROP ISN: 304.4 HRS	
				50 HR Inspection carried out I.A.W. Diamond Aircraft DA 40 current Maintenance	
				Manual Chapter 05-20-00	
				Propeller Static R.F.M. adjusted. Prop Spinner Assy. P/N C-3532-4P S/N: Al0331 Removed. Serviceable Spinner Assy. S/N. A.J-0582 Installed.	
				- described above has been performed in accordance with the	
				applicable standards of airworthiness.  DIAMOND AIRCRAFT INDUSTRIES D.O.T. APPROVAL #164-93	
				a comment	
				Signature Lic or Stamp RO6	
			-		
				Kim Davidson Aviation, Inc. DATE: 19 December, 2008 AIC TSN: 559.7	
	PROP MODEL: HC-CZYR-18F/F/ PROP S/N: CH38	7495S 5129B	The same	PROP TT 559.7	
	REG NO 388JP WORK ORDER			Pages 2017 Alport Avenue TACH: 559.7 2017 Alport Avenue TACH:	
	Prop Entries				
			as been insp	pected in accordance with with an Annual inspection I.A.W. FAR Part ed to be in AIRWORTHY CONDITION	
			en determin	ed to be all All World III of the III	
	Maintenance R	telease		and inspected in accordance with the	
	The aircraft, air current mainter	frame, engine, p nance rules of th	propeller, or ap ne Federal Avia	pliance identified above was repaired and inspected in accordance with the aton Administration and is APPROVED FOR RETURN TO SERVICE	
	Pertinent detail	Is of the repair ar	re on file at thi	s repair station under Work Order No. 12302, Dated 19 December, 2008.	
	DATE: 19 Dece	2000 ambas 2000	SIGNED	RAGGE Work Order: 12302	
	DATE 19 Deck	stillogi, 2000	Brian Davids	on Printed by EBis 3 (datcomedia.com)	
			Certified Rep	pair Station No. YYKR678L	
					I
	_				
	_				
				1 of 1	
				1 of 1	
				10f1	
ory 02, 2010			QualiTe	ch Aviation. Inc.	
ory 02, 2010			- Make: I	ch Aviation, inc. Diamond - Model: DA-40 - S/N: 40.388	
ry 02, 2010	Propel	ller: Hartzel	- Make: I I HC-C2YF	ch Aviation, Inc. Diamond - Model: DA-40 - S/N: 40.388  X-1BF - Propeller S/N: CH38139B	
iry 02, 2010	Propel	ller: Hartzel	- Make: I I HC-C2YF Total Tin	ch Aviation, inc. Diamond - Model: DA-40 - S/N: 40.388	
	Propel	ller: Hartzel - Airframe	- Make: I I HC-C2YF Total Tin	ch Aviation, Inc. Diamond - Model: DA-40 - S/N: 40.388  **IBF - Propeller S/N: CH38129B  **E89.0 - Propeller Total Time: 689.0	
	Propel Tach: 689.0 og Aeroshell #6 grea	lier: Hartzel - Airframe	- Make: I I HC-C2YF Total Tin 100 Ho	ch Aviation, Inc. Diamond - Model: DA-40 - S/N: 40.388 R-1BF - Propeller S/N: CH38129B se: 689.0 - Propeller Total Time: 689.0 ur Inspection	
ted propeller usin 9-22-03, dated N	Propel Tach: 689.0 g Aeroshell #6 great ovember 12, 2009,	ller: Hartzel - Airframe ase. does not ap	- Make: I I HC-C2YF e Total Tin 100 Ho	ch Aviation, Inc. Diamond - Model: DA-40 - S/N: 40,388 R-1BF - Propeller S/N: CH38129B Bic: 689.0 - Propeller Total Time: 689.0 ur Inspection  propeller serial number suffix letter "B". No further action required.	
ted propeller usin 9-22-03, dated N	Propel Tach: 689.0 g Aeroshell #6 great ovember 12, 2009,	ller: Hartzel - Airframe ase. does not ap	- Make: I I HC-C2YF Total Tin 100 Hor oply due to	ch Aviation, Inc. Diamond - Model: DA 40 - S/N: 40.388 C-15 - Fropeller S/N: CH38129B Diamond - Propeller Total Time: 689.0 Diamond - Model: DA 40 - S/N: 40.388 C-16 - Grant	
ted propeller usin	Propel Tach: 689.0 g Aeroshell #6 great ovember 12, 2009,	ller: Hartzel - Airframe ase. does not ap inspected i	- Make: I I HC-C2YF Total Tim 100 Hos	ch Aviation, inc. Diamond - Model: DA-40 - S/N: 40.388  ##################################	
ted propeller usin 9-22-03, dated N	Propel Tach: 689.0 g Aeroshell #6 great ovember 12, 2009,	ller: Hartzel - Airframe ase. does not ap inspected i	- Make: I I HC-C2YF Total Tim 100 Hos	ch Aviation, Inc. Diamond - Model: DA 40 - S/N: 40.388 C-15 - Fropeller S/N: CH38129B Diamond - Propeller Total Time: 689.0 Diamond - Model: DA 40 - S/N: 40.388 C-16 - Grant	

REPAIRS. ADJUSTMENTS, MODIFICATIONS HES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS. certify this PROPELLER os been inspected in accordance with an 100 HR / annual inspection has been inspected in accordance with an 100 HR /-annual Inspection and has been determined to be in nd has been determined to be in alrworthy / unairworthy condition. WES WRIGHT A&P / IA 2994045 rworthy / unairworthy condition. ES WRIGHT ASP / 15 2994045 Wer Nr W Date 3/7/2012 a Wight 100 2/24/201 a/cT.T. 957.6 ENGINE TOTAL DIE: 845.5 ENGINE TACH 768,1 HRS GalaxyFBO Prop 100hr Inspection 10013 Military Dr.

1. I certify that this prop has been inspected in accordance with the 100 hour inspection and was determined to be in airworthy condition.

The aircraft/component identified above was maintained or altered in accordance with current regulations of the Foderal Aviation Administration and is approved for return to service for the work performed. All disrupted systems were restored and functionally tested in accordance with might instructions.

Date:

Mar 4, 2013

Authorized Signature:

Tach# 913.4

ACTT# 913.4

Authorized Sign

Prop time: 875

Rvan Gengerke A&P/IA 3538675

Model No: HC-C2YR-1BF

Serial No: CH38129B

General Aviation Services 5260 Central Pkwy. Hangar 14

Conroe, TX 77303

Propeller Annual Logbook Entry Model: HC-C2YR-1BF Make: Hartzell

Serial: CH38129B

Hobbs# 1040.0

Registration: N388JP Make: Diamond Model: DA-40 Serial: 40.388

ompleted a 100HR inspection in accordance with FAR 43, Appendix D and approved maintenance/ rvice manual.

Removed spinner, checked condition of backing plate, spinner, and propeller. All satisfactory.

Checked security and propeller blade condition and reinstalled spinner.

No new/outstanding Ads this date per Navigator V ATP Compliance program, latest revision 5-30-14.

I certify that this Propeller has been inspected in accordance with a 100HR inspection and was found be in an airworthy condition. This Propeller is approved for return to service with respect to work

rformed this date.

Date: 06-13-2014

Gregory J. Evans JR A&P 3023363 IA

MAXIMUM HOURS BETWEEN OVERHAULS\_\_\_\_ OR LIFE

TOTAL FROM PREVIOUS SUMMARY

## PROPELLER SERVICE AND

DATE	TIME	RUN	TOTAL TIME SINCE OVERHAUL		INSTALLATIONS, INSPECTIONS, NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE		
DATE	HRS.	MIN.	HRS.	MIN.	Transfer this Alway		
witha and h	n 100 H as been thy/u	R / and determination	in acco nual ins nined to thy con / IA 2	be in dition.	has been inspected in accordance with an 100 HR / annual inspection and has been determined to be in airworthy / finairworthy common. WES WRIGHT A&P / IA 29.949AS		
	a/c	r.T. 19	66.5	-	a/cT.T. uni		
I certify the has been instructed with an 100 and has been airworthy / WES WRIG	pected IR / and n determinative HT A&P	in acconual instituted to the correct of the correc	rdance pection be in idition.				