

Propeller Inspection Work Order
Palm Beach Aircraft Propeller, Inc.

F.A.A. L104R349M - EASA 145.5271

Date: Jun 13, 2017 Work Order No. 19223 Propeller Mfg. HARTZELL
Invoice Number: 10178 Model in: PHC-J3YF-1N OUT: PHC-J3YF-1N
Customer: Southeast Aero Services, Inc. Hub Serial# in: FP6417B OUT: FP6417B
385 Hawkeye View Lane Authorized by: _____
St. Augustine, FL 32095 Auth. Date: _____
Phone Number: 800-692-2091 Purchase Order # N1223A Tail # N1223A

Aircraft Model: SR-22 Engine Model: IO-550N TT: 963.5
Special Instructions: NEEDS BY 6-21-2017 TSO: 963.5
TKS SYSTEM INSTALLED

Incoming Preliminary Inspection by: CR
Tear Down JG Parts Missing NA
General Appearance Fair Visual Damage/Accident NA

Service Info Complied With: Propeller was: Overhaul
I/A/W Mfg. Spec. Manual # 113B, REV 44 S/17
SB complied with: 306R4,319, 374 Components Identified were: Overhaul

SL complied with: 154, 177, 206R22, 217, 244, 267, 268R1, 278, 282R12, 293R1, 348, 353, 354,
As per mandatory Service Information: HC-SL-61-61Y REV. 10
From installation date, next OHC Due: 2400 HRS/72 MO.

Components Identified were: _____ Overhaul _____
in accordance with current FAA regulations
and were found AIRWORTHY for return to service. Pertinent
details of the work performed are on file at this agency.

AD complied with: _____ Approved for Service: _____
NA _____ Michael F. O'Neill Jul 18, 2017

