

PROPELLER LOGBOOK

PROPELLER MODEL PHC-534/F-IN

LOGBOOK #____

	480 000 00 Part (900) 10 10 10 10 10 10 10 10 10 10 10 10 10
inspected. Removed (1) N7605CI N7605CB blade serial number A935 and inspected propeller. All work 113B-R42, 135F-R26, 159-R52, 202 Hartzell Service Letter HC-SL-61-30 # 25. See the airworthiness lim	ided TSO Not Provided led. Reassembled, lubricated, static balanced, and 3 blade serial number B0818 and installed (1) new 59. Overhauled, assembled, lubricated, static balanced, was performed in accordance with Hartzell manuals 2A (Vol. 1-R52, Vol. 6-R34, Vol. 7-R41, Vol. 11-R36), 11. For serial numbers and times reference attached Form hitations section of Hartzell Owner manual 145 for extinent details of the work performed are on file at this





Midwest Aircraft Refinishing 11038 Hwy 37 Bld A Box 8 Hibbing, MN 55746 (218)404-0314 Cirrus Design Corp SR22T 13 July 2016 N877EM 22T-1217 Hobbs- 78.6 FLT- 60.8 Propeller Entry

Removed propeller for blister in blade, and sent to Hartzell for repair. Re-installed this propeller (J1122B) IAW SR22 AMM CH 61. Ops and leak check good.

	Ross W. F	lobillard		A&P # 3353760 Signature
		12 7 7		
, 8 , 5				
4.5			V6)	
			100	

	Propeller TSN TSO	A/C Hrs	Description of all operation Service Documents, Over	ons pertaining to Airworth haul, Major or Minor Rep	hiness Directive pair, and Inspec	tions.	
	i c	RRUS	Leading the Busin	TER> ness of Aviation	PROPELL RECORD E		
t	Registration	N77EM	Cutter Aviation S	an Antonio Inc.	Flt hour meter	96.9	
t	Model No. SR22T		Cutter Aviation San Antonio, Inc. 367 Sandau Rd.		Propeller TT	96.9	
r	Serial No.	erial No. 1217 San Antonio, Texas 78216					
r	Prop Model	PHC-J3Y1F-1N	Phone (210) 384-3388	PAGE 1 OF 1			
_	Prop S/N NJ1122B		CRS U71				
	SCHEI 2. LUBRI 3. PERFO	DULED INSPECTION F CATED PROPELLER I ORMED GROUND RUI A 100 HOUR INSPEC		SULTS. ED ON THIS PROPELLER I	IN ACCORDANCE PPROVED FOR F er: 11M-4055	E WITH FA	
1	- 47 1 1 1 1 1		Authorized Signature:	The Kingle	Tom	Bierschwa	
1	Date: 2/	15/2017	olgitatoro.	Sinterior who was in the first and a second of the second	and the same		





Chuck's Aircraft, LLC.

6200 Aviation Dr. AC101 Austin Executive Airport Pflugerville, TX 78660 Phone: 512-610-3111 DATE: 2/22/2018 A/C TSN: 142.8 PROP TT: 142.8 TSPOH: FLIGHTTIME: 142.8

Prop Entries

PROP S/N: NJ1122B REG. NO: 877EM WORK ORDER: 2555

PROP MODEL: PHC-J3Y1F-1N

Inspected blades, hub, spinner, backplate, checked TKS nozzle alignment, and lubricated hub.

Technicians Who Worked On The Items Listed Above: Same of the wingle or solding of

Jessy Parsons

This propeller has been inspected in accordance with a 100-hour inspection and is approved for fourn to service.

SIGNED: DATE: 2/22/2018 Robert McBride, Jr., IA: 2710158

Work Order: 2555

Printed by EBis 3 (datcomedia.com)

Date	Propeller TSN TSO	A/C Hrs		of all operations pertaining ments, Overhaul, Major
s	ALPHA APR	Genter	en en senten en en en en en en	
i aju pjer er		center.com	costs freezensing, and the same of	
	417-623-	-3113		
550	9 Dennis Weaver Dr.,	Webb City, M	IO 64870	
PHC-J3Y1I Shop Orde	/2019; Aircraft: N877EM; Tyl F-1N, S/N: NJ1122B, Time: , r #: 19-1576, Closed: 3/05/2	269.6 mg 2019		
Inspection Dressed pr		as guides.		
I certify an	checked thru 3-5-2019. No no Annual Inspection was comp opeller is in an airworthy con	oleted in accordance	e with current FARs	
service.	letails of the repair are on file	¥ 5.		
	Shop Order listed above.	at this repair of		
Signed:	Urchail P. Blake	uy Date_	3-5-2019	
	•			