

N-347CP

HARTZELL

~~PROPELLER LOGBOOK~~

PROPELLER MODEL PHC-J34F-1W

PROPELLER S/N FP6731B

Closed

Set Log

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model PHC-339F-1N

Propeller S/N FP6731B

Blade Design A7605B

Blade S/N's

No. 1 A1904

No. 2 A1896

No. 3 A1905

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus Design

Aircraft Model SR22

S/N 3044

Registration N347CP

PROP MODEL:
PHC-J3YF-1N
PROP S/N: FP6371B
REG. NO: 347CP
WORK ORDER:
3306-11-2009



Twin Cities Aviation, Inc.

8891 Airport Rd #A-2
Blaine, Minnesota 55449 USA
Phone: 763-784-9165

DATE: 11/24/2009
A/C TSN: 12
PROP TT: 12
FLIGHTTIME: 12

Prop Entries

C/W a annual Propeller inspection IAW Cirrus SR 22 MM and IG. AD's researched to date. See AD listing for pertinent details. All Cirrus SB's researched to date. Ground run, ops and leak check satisfactory. I certify that I have inspected this propeller IAW a annual inspection and it was determined to be airworthy with respect to work performed at this date and time. The following discrepancies were addressed:

The aircraft, airframe, engine, propeller, or appliance above was repaired and / or inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

DATE: 11/24/2009

SIGNED:

Work Order: 3306-11-2009

Andrew Bougetz, IA: 2656245 1 of 1

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1N
PROP S/N: FP6731B
REG NO: 347CP
WORK ORDER:
13564-04-2010



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y
4514 Taylor Circle
Duluth, MN 55811
Phone: 218- 788-3438

DATE: 4/22/2010
A/C TSN: 129.4
PROP TT: 129.4
FLIGHTTIME: 104.6

Prop Entries

(24) Performed 100 Hour inspection of propeller IAW CDC AMM 5-20 and Hartzell MM 61-00-45.... (25) Lubricated propeller hub IAW Hartzell Owners Manual section Maintenance Practices.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 4/22/2010

SIGNED:

Work Order: 13564-04-2010

Nick Lacoursiere
Certified Repair Station No. YD5R855Y

Printed by EBis 3 (datcomedia.com)

PROP MODEL
PHC-J3YF-1N
PROP S/N FP6731B
REG NO 347CP
WORK ORDER
14586-12-2011



Cirrus Design Factory Service Center

Repair Station No. YD5R855Y
4514 Taylor Circle
Duluth, MN 55811
Phone 218- 788-3438

DATE 12/30/2011
A/C TSN. 498 6
PROP TT. 498 6
HOBBS 597

Prop Entries

- (5) Flight meter 498 6 - Performed propeller Annual/100HR inspection IAW cirrus mm chapter 5-20 and 5-30.
- (8) Researched ADs through bi-weekly issue 2011-26. all ADs are in compliance at this time.
- (17) Lubricated propeller hub IAW Hartzell Owners Manual section Maintenance Practices.
- (19) Conditioned propeller boots IAW standard maintenance practices.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 12/30/2011

SIGNED:

Joseph Sullivan
Certified Repair Station No. YD5R855Y

Work Order: 14586-12-2011

Printed by EBis 3 (datcomedia.com)



Travel Express Aviation Maintenance, Inc.
DuPage Airport, West Chicago, IL 60185

Aircraft: N347CP Date: 1/17/2013 Invoice: 4589

TT A/F: 810.4 FLT HOBBS: 692.0 TT PROP: 810.4

This propeller has been given an annual inspection in accordance with the aircraft manufacturer's instructions and the propeller manufacturer's instructions.

The current status of applicable ADs was researched through 2012-26.

I certify that this PROPELLER has been inspected in accordance with an annual inspection, and was determined to be in AIRWORTHY condition.

A handwritten signature in black ink, appearing to read "Sean Blumenschein", is written over a horizontal line.

Sean Blumenschein, AP 3331960 IA

End

**A/C
Hrs**

**Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.**

PROP MODEL:
PHC-J3YF-1N
PROP S/N: FP6731B
REG. NO: 347CP
WORK ORDER:
15377-06-2013

Cirrus Design Factory Service Center

Repair Station No. YD5R855Y
4961 Airport Road
Duluth, MN 55811
Phone: 218-788-3438

DATE: 8/15/2013
A/C TSN: 788.9
PROP TT: 788.9
FLIGHTTIME: 788.9


Prop Entries

- (4) (Flight Time 798.9) Performed propeller annual inspection IAW CDC AMM 05-20, Scheduled Maintenance.
- (27) Lubricated propeller hub IAW CDC AMM 61-10 and Hartzell Owner's Manual, Maintenance Practices.
- (52) Researched propeller AD's through FAA Bi-weekly 2013-12. All AD's are in compliance at this time.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 8/15/2013

SIGNED:



Dan Trampush
Certified Repair Station No. YD5R855Y

Work Order: 15377-06-2013

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: N347CP
WORK ORDER:
1148-09-2014



Lone Mountain Aircraft Maintenance

2460 Greentree Road
Hangar 12
Lebanon, Ohio 45036
Phone: 888-566-3686

DATE: 9/11/2014
A/C TSN: 1201.8
PROP TT:
HOBBS: 1027.7

Prop Entries

(3) Propeller Annual Inspection... Complied with the Propeller annual inspection in accordance with the manufacturers maintenance manual. Serviced hub with Aeroshell #6 grease. Dressed blades as needed.

This propeller has been inspected in accordance with a 100/annual inspection in accordance with the manufacturers maintenance manual and current FAA regulations and has been determined to be in an airworthy condition. END

DATE: 9/11/2014

SIGNED


Tony McBe, IA: 3248287

Work Order: 1148-09-2014

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: N347CP
WORK ORDER:
1300-07-2015

Lone Mountain Aircraft Maintenance

2460 Greentree Road
Hangar 12
Lebanon, Ohio 45036
Phone: 888-566-3686

DATE: 7/13/2015
A/C TSN: 1173.4
PROP TT:
HOBBS: 1369.2

Prop Entries

(3) Prop RPM needs adjusted up 20 RPM.... Adjusted prop RPM up to maintain 2700 RPM.

DATE: 7/13/2015

SIGNED:

Ryan Yenger, IA: 3669633

Work Order: 1300-07-2015

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO: N347CP
WORK ORDER:
1299-07-2015

Lone Mountain Aircraft Maintenance

2460 Greentree Road
Hangar 12
Lebanon, Ohio 45036
Phone: 888-566-3686

DATE: 7/8/2015
A/C TSN: 1171.2
PROP TT:
HOBBS: 1365.9

Prop Entries

(2) Prop RPM higher than 2700 RPM on takeoff.... Adjusted Propeller governor stop screw to maintain 2700 RPM on takeoff.

DATE: 7/8/2015

SIGNED:

Ryan Yenger, IA: 3669633

Work Order: 1299-07-2015

Printed by EBis 3 (datcomedia.com)

