

HARTZELL

**PROPELLER
OWNER'S MANUAL**



HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J33F-1RF

PROPELLER S/N FP6196B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position 1

PITCH RANGE

Propeller Model PHC-J32F-1BF

High/Feather _____

Propeller S/N FP 6196B

Start Lock _____

Blade Design F7693DFB

Low _____

Blade S/N's

Reverse _____

No. 1 K 61198

No. 2 K 61201

Aircraft Manufacturer Cirrus Design

No. 3 K 61200

Aircraft Model TR22

No. 4 _____

S/N 2793

No. 5 _____

Registration N397SR N627PW

No. 6 _____

Spinner Assembly Part No. _____

Seller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
N/A	11	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 13 dated Aug./06 Section: 61-00-15 on <u>10-18-07</u> (DATE) The location of the Weight(s) are _____ degree And are _____ gram(s).</p> <p>_____ (Sign/Stamp) Cirrus Design Corporation, PC 338CE</p>

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP6196B
REG NO: 397SR
WORK ORDER:
10322-11-2007

Cirrus Design Factory Service Center

Repair Station No. YD5R855Y
4515 Taylor Circle
Duluth, MN 55811
Phone: 218- 788-3101

DATE: 11/29/2007
A/C TSN: 7
PROP TT: 7
HOBBS: 7


Prop Entries

(7) Burished out nick in trailing edge of propeller blade and touched up paint IAW Hartzel maintenance manual.

I have reviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, propeller, or appliance identified was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and is approved for return to service. Pertinent details of repair are on file at this Certified Repair Station CRS YD5R855Y.

DATE: 11/29/2007

SIGNED:



Steven LaMourea
Certified Repair Station No. YD5R855Y

Work Order: 10322-11-2007

Printed by EBis 3 (datcomedia.com)

AvDyne AeroServices, LLC

MAKE: Cirrus

MODEL: SR22

SERIAL NO.: 2793

REGISTRATION NO.: N627PW

DATE: 12-23-08

WORKORDER: 08-12-002

TOTAL TIME: 207.0

TAC TIME: 146.8

- 1) Completed Annual inspection on Propeller in accordance with FAR 43, appendix "D".
- 2) Completed Cirrus 200 hr inspection items per Cirrus SR22 Maintenance Manual.
- 3) AD's researched thru ATP Navigator V, dated 12-23-08

END

This aircraft and or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at agency under Work Order No.: 08-12-002

Date: 12-23-08

Signed: _____

For AvDyne AeroServices LLC CRS #Y7NR985Y

Date	Propeller TSN TSO	A/C Hrs	Description of all op Service Documents, C
------	----------------------	------------	---



330 Aviation Way
Frederick, MD 21701
301-662-8156
CRS LC1R291K

Date: 12/20/2011; Aircraft: N627PW; Tach: 430.6; Total Time: 586.3
Shop Order #: S05-11-60752

Prop log entry

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

John
C. John Colaluca for Landmark Aviation CRS LC1R291K



330 Aviation Way
Frederick, MD 21701
301-662-8156
CRS LC1R291K

Date: 1/02/2013; Aircraft: N627PW; Tach: 562.1
Shop Order #: S05-12-61324

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

John
C. John Colaluca for Landmark Aviation CRS LC1R291K



330 Aviation Way
Frederick, MD 21701
301-662-8156
CRS LC1R291K

Date: 1/24/2014; Aircraft: N627PW; Tach: 634.0
Shop Order #: S05-14-61488
Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

John
C. John Colaluca for Landmark Aviation CRS LC1R291K



330 Aviation Way
Frederick, MD 21701
301-662-8156
CRS LC1R291K

Date: 2/03/2015; Aircraft: N627PW; Hobbs: 906.5; Tach: 685.2
Shop Order #: S05-15-61500

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

John
C. John Colaluca for Landmark Aviation CRS LC1R291K



330 Aviation Way
 Frederick, MD 21701
 301-662-8156
 CRS LC1R291K

Date: 3/02/2016; Aircraft: N627PW; Hobbs: 992.7; Total Time: 992.7

Shop Order #: S05-16-62650

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

C. John Colaluca for Landmark Aviation CRS LC1R291K



SIGNATURE
TECHNICAIR™
Aircraft Maintenance
A BBA Aviation company

330 Aviation Way
 Frederick, MD 21701
 301-662-8156
 CRS LC1R291K

Date: 4/07/2017; Aircraft: N627PW; Hobbs: 1095.2; Tach: 840.1

Shop Order #: S05-17-62836

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

C. John Colaluca for Signature Technicair CRS LC1R291K



SIGNATURE
TECHNICAIR™
Aircraft Maintenance
A BBA Aviation company

330 Aviation Way
 Frederick, MD 21701
 301-662-8156
 CRS LC1R291K

Date: 5/22/2018; Aircraft: N627PW; Hobbs: 1174.1

Shop Order #: S05-18-63140

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

C. John Colaluca for Signature Technicair CRS LC1R291K



SIGNATURE
TECHNICAIR™
Aircraft Maintenance
A BBA Aviation company

330 Aviation Way
 Frederick, MD 21701
 301-662-8156
 CRS LC1R291K

Date: 5/16/2019; Aircraft: N627PW; Hobbs: 1241.4; Tach: 951.0

Shop Order #: S05-19-63459

Dressed and painted prop. I certify that this prop has been inspected in accordance with a 100 hour inspection and has been approved for return to service.

C. John Colaluca for Signature Technicair CRS LC1R291K

**Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.**

Date

**Propeller
TSN TSO**

**A/C
Hrs**

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP6196B
REG. NO: N627PW
WORK ORDER:
8098-05-2021

ADVANCED Fly Advanced

Repair Station No. 5T2R901C
530 Airport Rd.
Lititz, PA 17543
Phone: 717-735-5179

DATE: 6/3/2021
A/C TSN: 1062.9
PROP TT: 1062.9
HOBBS: 1365.5

Prop Entries

Annual Propeller Inspection completed IAW FAR 91.409 and the requirements outlined in FAR 43 App. D. with reference to the Cirrus AMM check list ch 5-20. Cleaned and dressed blades. Serviced hub. All ADs current through 2021-11... AD 2020-19-06 McCauley Prop Governor Idler Gear Bearing Inspection Not Applicable by Prop Governor S/N: 070941 installed IAW McCauley ASB273C

I certify that this PROPELLER has been inspected IAW an Annual Inspection and was found to be in Airworthy condition.

DATE: 6/3/2021

SIGNED:

Joshua J. Ferry
Certified Repair Station No. 5T2R901C

Work Order: 8098-05-2021

Printed by EBis 3 (datcomedia.com)