

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J33F-18F1F76930EB

PROPELLER S/N FP41694B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model PHC-SMF-1RE/F7693DFB

Propeller S/N FP 41814B

Blade Design F7693DFB

Blade S/N's

No. 1 K 37694

No. 2 K 37697

No. 3 K 37846

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____



Reverse _____

Aircraft Manufacturer Cirrus Design

Aircraft Model SR22

S/N 1978

Registration N313SR

Date	Propeller		AC Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
5-11-06	.0	N/A	.1	<p>I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 11 dated Dec/04 Section: 61-00-15 on <u>5-11-06</u> (DATE). The location of the Weight(s) are <u>N/R</u> degree And are <u>N/R</u> grams).</p> <p> (Sign/Stamp) Cirrus Design Corporation, PC 338CE</p> <p></p>

PROP MODEL:
PROP S/N:
REG. NO: 313SR
WORK ORDER: 6730



Lincoln Park Aviation
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 11/9/2006
A/C TSN:
PROP TT:
HOBBS: 128.9

Prop Entries


(3) ANNUAL/PROP -Inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 11/9/2006

SIGNED:

Frank R Galella



Inspector 2

Work Order: 6730

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
 PROP S/N:
 REG. NO: 313SR
 WORK ORDER: 6806



Lincoln Park Aviation

425 Beaverbrook Road
 Lincoln Park, NJ 07035
 Phone: 973-633-0450

DATE: 12/15/2006
 AC TSN: 124.4
 PROP TT: 168.3
 HOBBS: 168.3

Prop Entries

(1) DRESS AND BLEND PROPELLER AS REQUIRED.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 12/15/2006

SIGNED:

Inspector 2

Work Order: 6806

Frank R Galella

Printed by EBis 3 (datcomedia.com)

01/26/07	—	DRESS AND BLENDED PROPELLER AS REQUIRED	
TACNTIME	160.6	PERFORMED SONR INSPECTION I/A/W SR22	
PROP TOTAL TIME		MAINTENANCE MANUAL. DETERMINED TO BE	
	160.6	IN AIRWORTHY CONDITION END <i>Mill</i> ^{AJP} 91523901	
ENG TOTAL TIME	160.6	GLASS COCKPIT AVIATION	

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	---

North East Aero

97 Hangar RD Montgomery NY, 12549 (845) 457-1184

Cirrus Design SR22 N313SR S/N 1978

27, April 2007

Hartzell PHC-J3YF-1RF

Hobbs Time: 262.1

Air Switch Hobbs: 193.7

S/N: FP4694B

1. Completed Annual Inspection IAW Cirrus Design 100hr/Annual Inspection checklist..
2. Lubricated propeller as required.
3. Dressed blades as required.
4. Inspected spinner with no defects noted.
5. Complied with all outstanding AD's as required.

*I certify this Propeller was inspected in accordance with
an Annual Inspection and found to be in an airworthy condition.*

Robert C. Betzler A&P31668811A




Prop Log Entry

50 Hour Service


**N313SR; Serial # 1978
Prop TTSN: 243.5**

**Airframe TT: 243.5
Tach Time: 243.5**

**Engine TTSN: 243.5
Date: JULY 23, 2007**

Filed, painted, lubricated and Dressed prop. END

.Name:



A&P Certificate # 3245675

NO FURTHER ENTRIES SEE ADLOG SYSTEM

WERY GOTTSHAM 567452582 CFI/1